

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 3, 2025

Progress Estimate Number 13	Contract ID 240517-F05 Prime Raineri Construction, LLC dba Rainer Contractor Construction	Pay Period March 16, Original Control Start 2025 Amount Pay Period April 1, 2025 Amount End April 1, 2025 Amount Current Control Amount	\$1,155,735.45 rder \$39,073.65
-----------------------------------	---	---	------------------------------------

Original Comp	letion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amou	nt Complete
April 4, 2025			Reviewed and Approved at the Cen	tral Office Controllers Office Level by	ramses1
April 3, 2025		Reviewed and Appro	oved (and should be considered Dra	nft) at the Resident Engineer Level by	wolkt1
April 3, 2025		Generated and	Approved (and should be considere	d Draft) at the Project Office Level by	litzam
Approval Date					By User

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
June 30, 2026	June 30, 2026		99.88%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date	June 26, 2024	June 26, 2024	
Awarded Date	June 5, 2024	June 5, 2024	
Letting Date	May 17, 2024	May 17, 2024	
Notice to Proceed Date	July 8, 2024	July 8, 2024	
Open to Traffic Date			
Work Began Date	September 17, 2024	September 17, 2024	

Contract Total Pa	ay For Estimate No. 13			
		This Estimate	Previous	To Date
240517-F05				
	Total Posted Items Pay	\$241,940.02	\$951,377.74	\$1,193,317.76
	Gross Item Adjustments	\$18,442.36	(\$24,031.83)	(\$5,589.47)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·	-	\$927,345.91	\$1,187,728.29
Contract Total Pa	avable This Estimate:	\$260 382 38		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6P3510B	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$97,408.300	0.05	\$4,870.42
	0060	6081012	TRUNCATED DOMES	SQFT	\$22.000	-0.25	(\$5.50
	0110	6089902	MISC.CONCRETE CURB RAMP	EA	\$2,722.170	1	\$2,722.17
	0160	6169901	MISC.TRAFFIC CONTROL	LS	\$35,553.600	0.25	\$8,888.40
	0180	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$37.800	399	\$15,082.20
	0190	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	EA	\$302.400	148	\$44,755.20
	0200	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	EA	\$113.400	133	\$15,082.20
	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$3.020	2,255	\$6,810.10
	0220	6207001	PAVEMENT MARKING REMOVAL	LF	\$2.270	391	\$887.57
	0230	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	LS	\$12,096.000	1	\$12,096.00
	0250	8031000A	TURF TYPE TALL FESCUE SODDING	SQYD	\$16.200	159	\$2,575.80
	0290	9022708	POST, SIGNAL 8 FT.	EA	\$1,399.680	2	\$2,799.36
	0300	9025020	CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE	LF	\$16.200	70	\$1,134.00
	0310	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$29.700	72	\$2,138.40
	0320	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	LF	\$91.030	35	\$3,186.05

Revision 3/23/2023 Page 1 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 3, 2025

Progress Estimate Number	Contract ID	240517-F05	Pay Period Start	March 16, 2025	Original Contract Amount	\$1,155,735.45
13	Prime Contractor	Raineri Construction, LLC dba Raineri Construction	Pay Period End	April 1, 2025	Net Change Order Amount	\$39,073.65
					Current Contract Amount	\$1,194,809.10

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6P3510B	0330	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	LF	\$146.880	57	\$8,372.16
	0340	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	LF	\$149.040	100	\$14,904.00
	0350	9028308	CABLE, 16 AWG 2 CONDUCTOR	LF	\$1.620	3,250	\$5,265.00
	0360	9028500	CABLE, LOOP DETECTOR, IN DUCT	LF	\$7.560	3,290	\$24,872.40
	0390	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING WITH VERBAL WALK MESSAGE	EA	\$1,274.400	28	\$35,683.20
	0400	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	EA	\$788.400	4	\$3,153.60
	0410	9029902	MISC.LED BLANKOUT SIGN	EA	\$6,424.920	2	\$12,849.84
	0420	9029902	MISC.PEDESTRIAN PUSHBUTTON EXTENSION	EA	\$294.840	1	\$294.84
	0430	9029902	MISC.PEDESTRIAN PUSHBUTTON STANCHION, 4 FT	EA	\$1,051.920	1	\$1,051.92
	0450	9031010	CONCRETE FOOTINGS, EMBEDDED	CUYD	\$1,870.850	4	\$7,483.40
	0460	9031280	2.5 IN. PSST POST - 12 GA.	LF	\$54.840	17	\$932.28
	0470	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	EA	\$357.370	1	\$357.37
	0480	9035069A	SHF-FLAT SHEET FLUORESCENT	SQFT	\$38.120	97	\$3,697.64
Project J6F	P3510B - T	otal					\$241,940.02
Overall - T	otal						\$241,940.02

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
P3510B	0070	6 IN. CONCRETE MEDIAN STRIP	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',317.23000 - 317.23000, 'is applied (if non-zero).	60.7	\$317.23	\$19,255.86
	0100	CONCRETE SIDEWALK, 7 IN.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',165.21000 - 165.21000, 'is applied (if non-zero).	7	\$165.21	\$1,156.47
	0110	MISC.	Overrun			-1	\$2,722.17	(\$2,722.17)
	0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun			-1	\$37.80	(\$37.80
	0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-399	\$37.80	(\$15,082.20
	0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.	399	\$37.80	\$15,082.20
	0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material			-148	\$302.40	(\$44,755.20
	0190	PREFORMED THERMOPLASTIC	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	148	\$302.40	\$44,755.20

Revision 3/23/2023 Page 2 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 3, 2025

Progress Estimate Number	Contract ID	240517-F05	Pay Period Start	March 16, 2025	Original Contract Amount	\$1,155,735.45
13	Prime Contractor	Raineri Construction, LLC dba Raineri Construction	Pay Period End	April 1, 2025	Net Change Order Amount	\$39,073.65
					Current Contract Amount	\$1,194,809.10

No. Type									
WHITE MIDBLOCK			Item Description		Adjustment	Comments		Adjustment	Adjustment amount
PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	J6P3510B					overridding Payment Estimate Exception 2 on			
THERMOPLASTIC Adjustment (0070) due to user litzam overridding Payment Estimate ltem Adjustment (0090) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate ltem Adjustment (0010) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 9 on the Current Payment Estimate Exception 9 on the Current Payment Estimate		0200	THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE	Material			-133	\$113.40	(\$15,082.20)
WATERBORNE PAVEMENT MARKING PAINT. TYPE L BEADS		0200	THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE	Material		generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment Estimate Exception 3 on	133	\$113.40	\$15,082.20
WATERBORNE PAVEMENT MARKING PAINT. TYPE L BEADS		0210	WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Overrun			-76	\$3.02	(\$229.52)
WATERBORNE PAVEMENT, TYPE BEADS		0210	WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material			-2,255	\$3.02	(\$6,810.10)
Day		0210	WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material		generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 4 on	2,255	\$3.02	\$6,810.10
generated Material Payment Estimate Item Adjustment (0010) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate. O390 MISC. Overrun O430 MISC. Overrun O440 Overrun O440 Overrun O440 Overrun O440 Overrun O440 MISC. Overru		0370	BASE, CONCRETE	Material			-0.9	\$43,338.24	(\$39,004.42)
0430 MISC. Overrun -1 \$1,051.92 (\$1,051.92 0440 MISC. Overrun Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3345.84000 - 3345.84000, 'is applied (if non-zero). 1 \$3,345.84 \$3,345.84 0460 2.5 IN. PSST POST - 12 GA. Material —17 \$54.84 (\$932.28 0460 2.5 IN. PSST POST - 12 GA. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. 17 \$54.84 \$932.28 0480 SHF-FLAT SHEET FLUORESCENT Material —97 \$38.12 (\$3,697.64 0480 SHF-FLAT SHEET FLUORESCENT Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate. 97 \$38.12 \$3,697.64		0370	BASE, CONCRETE	Material		generated Material Payment Estimate Item Adjustment (0010) due to user litzam overridding Payment Estimate Exception 6 on	0.9	\$43,338.24	\$39,004.42
Output		0390	MISC.	Overrun			-1	\$1,274.40	(\$1,274.40)
adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3345.84000, 'is applied (if non-zero). 0460 2.5 IN. PSST POST - 12 GA. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. 0480 SHF-FLAT SHEET FLUORESCENT Material This adjustment offsets the original system-generated Material Payment Estimate. 0480 SHF-FLAT SHEET FLUORESCENT Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate.		0430	MISC.	Overrun			-1	\$1,051.92	(\$1,051.92)
D460 2.5 IN. PSST POST - 12 GA. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. D480 SHF-FLAT SHEET FLUORESCENT D480 SHF-FLAT SHEET FLUORESCENT Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate. D480 SHF-FLAT SHEET FLUORESCENT Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate.		0440	MISC.	Overrun		adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3345.84000 - 3345.84000, 'is	1	\$3,345.84	\$3,345.84
generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. O480 SHF-FLAT SHEET FLUORESCENT O480 SHF-FLAT SHEET FLUORESCENT Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate.		0460	2.5 IN. PSST POST - 12 GA.	Material			-17	\$54.84	(\$932.28)
FLUORESCENT 0480 SHF-FLAT SHEET FLUORESCENT FLUORESCENT Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate.		0460	2.5 IN. PSST POST - 12 GA.	Material		generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 8 on	17	\$54.84	\$932.28
FLUORESCENT generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate.		0480		Material			-97	\$38.12	(\$3,697.64)
Total \$18,442.36		0480		Material		generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on	97	\$38.12	\$3,697.64
	Total								\$18,442.36

Revision 3/23/2023 Page 3 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6P3510B	FAS S503(95)	ADA and signal improvements	Various	ST LOUIS	at various locations in t	he St. Louis District	
Γotals by Jo	b Numbers	•					
J6P3510B		Item Pay tem Adjustmen	ts <mark>Gross Ite</mark>	m Pay	This Estimate \$241,940.02 \$18,442.36 \$260,382.38	Previous \$951,377.74 (\$24,031.83) \$927,345.91	To Date \$1,193,317.76 (\$5,589.47) \$1,187,728.29
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 3/23/2023 Page 4 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 6200015, Project Item Line Number 0180, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Pavement markings were just installed, and the inspector is working on the Sample ID.	litzam	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 6200036, Project Item Line Number 0190, Material Set 620003696, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Pavement markings were just installed, and the inspector is working on the Sample ID.	litzam	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 6200042, Project Item Line Number 0200, Material Set 620004296, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Pavement markings were just installed, and the inspector is working on the Sample ID.	litzam	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Pavement markings were just installed, and the inspector is working on the Sample ID.	litzam	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Pavement markings were just installed, and the inspector is working on the Sample ID.	litzam	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 9029100, Project Item Line Number 0370, Material Set 902910096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with the contractor and there testing company, TSI along with MoDOT Materials to report the remaining quantities.	litzam	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 9029100, Project Item Line Number 0370, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with the contractor and there testing company, TSI along with MoDOT Materials to report the remaining quantities.	litzam	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 9031280, Project Item Line Number 0460, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Working with the contractor and MoDOT Materials to report the remaining quantities.	litzam	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3510B, Item 9035069A, Project Item Line Number 0480, Material Set 9035069A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Working with the contractor and MoDOT Materials to report the remaining quantities.	litzam	Overridden
Estimate Exception Type: Item Overrun: Contract 240517-F05, Contract Project J6P3510B, Project Item Line Number 0110, Contract Line Item Number 0110, Item 6089902, Minor Item.	This item is on final change order 008 and should be completed by the next estimate.	litzam	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240517-F05, Contract Project J6P3510B, Project Item Line Number 0180, Contract Line Item Number 0180, Item 6200015, Minor Item.	This item is on final change order 008 and should be completed by the next estimate.	litzam	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240517-F05, Contract Project J6P3510B, Project Item Line Number 0210, Contract Line Item Number 0210, Item 6205902A, Minor Item.	This item is on final change order 008 and should be completed by the next estimate.	litzam	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240517-F05, Contract Project J6P3510B, Project Item Line Number 0390, Contract Line Item Number 0390, Item 9029902, Minor Item.	This item is on final change order 008 and should be completed by the next estimate.	litzam	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240517-F05, Contract Project J6P3510B, Project Item Line Number 0430, Contract Line Item Number 0430, Item 9029902, Minor Item.	This item is on final change order 008 and should be completed by the next estimate.	litzam	Acknowledged

Revision 3/23/2023 Page 5 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	s are ba Line No.	Item Code	port Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	S Gener Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
240517-F05	J6P3510B	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	Qty 1.00	\$97,408.30	\$97,408.30
		0001	0020	2079909	MISC.LINEAR GRADING, CLASS 2 - MODIFIED	21.00	0.00	21.00	STA	21.00	\$1,345.14	\$28,247.94
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,734.00	124.60	1,858.60	SQYD	1,858.60	\$11.30	\$21,002.18
		0001	0040	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT.	718.10	125.00	843.10	SQYD	843.10	\$104.56	\$88,154.54
		0001	0050	6039902	JOINTS) WATER	2.00	0.00	2.00	EA	2.00	\$275.00	\$550.00
		0001	0060	6081012	TRUNCATED DOMES	878.00	-129.00	749.00	SQFT	749.00	\$22.00	\$16,478.00
		0001	0070	6083006	6 IN. CONCRETE MEDIAN STRIP	19.60	49.80	69.40	SQYD	69.40	\$317.23	\$22,015.76
		0001	0080	6085008	PAVED APPROACH, 8 IN.	392.60	64.70	457.30	SQYD	457.30	\$91.83	\$41,993.86
		0001	0090	6086004	CONCRETE SIDEWALK, 4 IN.	394.80	-52.20	342.60	SQYD	342.60	\$148.38	\$50,834.99
		0001	0100	6086007	CONCRETE SIDEWALK, 7 IN.	165.90	7.00	172.90	SQYD	172.90	\$165.21	\$28,564.81
		0001	0110	6089902	MISC.CONCRETE CURB RAMP	27.00	-2.00	25.00	EA	26.00	\$2,722.17	\$70,776.42
		0001	0120	6089902	MISC.CONCRETE CURB RAMP - DECORATIVE CONCRETE	45.00	1.00	46.00	EA	46.00	\$2,970.38	\$136,637.48
		0001	0130	6089905	MISC.CONCRETE SIDEWALK, 4 IN DECORATIVE CONCRETE	43.00	-9.00	34.00	SQYD	34.00	\$257.97	\$8,770.98
		0001	0140	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	13.00	17.50	30.50	LF	30.50	\$742.67	\$22,651.44
		0001	0150	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	26.00	157.00	183.00	LF	183.00	\$88.68	\$16,228.44
		0001	0160	6169901	MISC.TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$35.553.60	\$35,553,60
		0001	0170	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$191,959.54	\$0.00
		0001	0171	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$180,971.54	\$180,971.54
		0001	0180	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	398.00	0.00	398.00	LF	399.00	\$37.80	\$15,082.20
		0001	0190	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	148.00	0.00	148.00	EA	148.00	\$302.40	\$44,755.20
		0001	0200	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	133.00	0.00	133.00	EA	133.00	\$113.40	\$15,082.20
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,179.00	0.00	2,179.00	LF	2,255.00	\$3.02	\$6,810.10
		0001	0220	6207001	PAVEMENT MARKING REMOVAL	3,130.00	0.00	3,130.00	LF	391.00	\$2.27	\$887.57
		0001	0230	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	1.00	\$12,096.00	\$12,096.00
		0001	0240	6229903	MISC.SIDEWALK EDGE GRINDING	38.00	-20.50	17.50	LF	17.50	\$89.27	\$1,562.22
		0001	0250	8031000A	TURF TYPE TALL FESCUE SODDING	484.00	0.00	484.00	SQYD	484.00	\$16.20	\$7,840.80
		0001	0260	8061007A	CURB INLET CHECK	31.00	-31.00	0.00	EA	0.00	\$135.00	\$0.00
		0001	0270	8061016	SEDIMENT REMOVAL	19.00	-19.00	0.00	CUYD	0.00	\$95.87	\$0.00
		0001	0280	8061019	SILT FENCE	1,738.00	-1,738.00	0.00	LF	0.00	\$5.40	\$0.00
		0030	0290	9022708	POST, SIGNAL 8 FT.	2.00	0.00	2.00	EA	2.00	\$1,399.68	\$2,799.36
		0030	0300	9025020	CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE	70.00	0.00	70.00	LF	70.00	\$16.20	\$1,134.00
		0030	0310	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	84.00	0.00	84.00	LF	84.00	\$29.70	\$2,494.80
		0030	0320	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	35.00	0.00	35.00	LF	35.00	\$91.03	\$3,186.05
		0030	0330	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	64.00	0.00	64.00	LF	64.00	\$146.88	\$9,400.32
		0030	0340	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	100.00	0.00	100.00	LF	100.00	\$149.04	\$14,904.00
		0030	0350	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,250.00	0.00	3,250.00	LF	3,250.00	\$1.62	\$5,265.00
		0030	0360	9028500	CABLE, LOOP DETECTOR, IN DUCT	3,290.00	0.00	3,290.00	LF	3,290.00	\$7.56	\$24,872.40
		0030	0370	9029100	BASE, CONCRETE	0.90	0.00	0.90	CUYD	0.90	\$43,338.24	\$39,004.42
		0030	0380	9029902	MISC.ADJUST PULL BOX TO GRADE	1.00	1.00	2.00	EA	2.00	\$995.76	\$1,991.52
		0030	0390	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING WITH VERBAL WALK MESSAGE	27.00	0.00	27.00	EA	28.00	\$1,274.40	\$35,683.20
		0030	0400	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	4.00	0.00	4.00	EA	4.00	\$788.40	\$3,153.60
		0030	0410	9029902	MISC.LED BLANKOUT SIGN	2.00	0.00	2.00	EA	2.00	\$6,424.92	\$12,849.84
		0030	0420	9029902	MISC.PEDESTRIAN PUSHBUTTON EXTENSION	3.00	0.00	3.00	EA	1.00	\$294.84	\$294.84
		0030	0430	9029902	MISC.PEDESTRIAN PUSHBUTTON STANCHION, 4 FT	16.00	0.00	16.00	EA	17.00	\$1,051.92	\$17,882.64
		0030	0440	9029902	MISC.REMOVE AND REPLACE CONC. PULL BOX	2.00	0.00	2.00	EA	2.00	\$3,345.84	\$6,691.68
Revision 3/23/20	222				W/PREFORMED CLASS 2 PULL BOX							Page 6 of 18

Page 6 of 18 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240517-F05	J6P3510B	0040	0450	9031010	CONCRETE FOOTINGS, EMBEDDED	4.00	0.00	4.00	CUYD	4.00	\$1,870.85	\$7,483.40
		0040	0460	9031280	2.5 IN. PSST POST - 12 GA.	17.00	0.00	17.00	LF	17.00	\$54.84	\$932.28
		0040	0470	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	1.00	0.00	1.00	EA	1.00	\$357.37	\$357.37
		0040	0480	9035069A	SHF-FLAT SHEET FLUORESCENT	90.00	7.00	97.00	SQFT	97.00	\$38.12	\$3,697.64
		0040	0490	9039902	MISC.REMOVE AND RELOCATE EXISTING GROUND MOUNTED SIGN	11.00	0.00	11.00	EA	11.00	\$1,016.02	\$11,176.22
		0001	5001	6189901	MISC.Misc. Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$10,988.00	\$10,988.00
		0001	5002	6169902	MISC.Misc. ADA Compliant Barricades	0.00	8.00	8.00	EA	8.00	\$236.25	\$1,890.00
		0030	5003	9016110	PULL BOX, PREFORMED CLASS 1	0.00	1.00	1.00	EA	1.00	\$1,828.54	\$1,828.54
		0001	5004	6042020	ADJUSTING BASIN OR INLET	0.00	2.00	2.00	EA	2.00	\$1,200.00	\$2,400.00
	Project J6I	23510B - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,193,317.68
240517-F05 Ove	rall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$1,193,317.68

Page 7 of 18 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6P3510B

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	3/27/25	4/2/25	0.05	LS		Various sites				
0060	6081012	TRUNCATED DOMES	3/25/25	3/25/25	-0.25	SQFT	Various					Rounding Error
0110	6089902	MISC. CONCRETE	3/27/25	4/2/25	1.00	EA	Imperial Main	12+05				Landing pad, missed on prior estimate
0160	6169901	MISC.	3/27/25	4/2/25	0.25	LS		Various sites				
0180	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	3/27/25	4/2/25	305.00	LF	Various sites					
			4/1/25	4/3/25	94.00	LF	Jennings Station					1 Extra Midblock at Jennings Station 12+30 left turn lane on to I-70
0190	6200036	PREF THERMO PVMT MARK, 30" WHT MIDBL	3/27/25	4/2/25	110.00	EA	Various sites					
			4/1/25	4/3/25	38.00	EA	Jennings Station					
0200	6200042	PREF THERMO PVMT MARK, YIELD TRIAN	3/27/25	4/2/25	81.00	EA		Various sites				
			4/1/25	4/3/25	52.00	EA	Jennings Station					
0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	3/27/25	4/2/25	2,108.00	LF	Various Sites					
			4/1/25	4/3/25	147.00	LF	Jennings Station					
0220	6207001	PAVEMENT MARKING REMOVAL	3/27/25	4/2/25	57.00	LF	Various Sites					
			4/1/25	4/3/25	334.00	LF	Jennings Station					
0230	6209901	MISC. PAVEMENT MARKINGS	3/28/25	4/2/25	1.00	LS		Various sites				
0250	8031000A	TURF TYPE TALL FESCUE SODDING	3/27/25	4/2/25	159.00	SQYD	Various sites					
0290	9022708	POST, SIGNAL 8 FT.	3/27/25	4/2/25	2.00	EA	Elm					
0300	9025020	CONDUIT, 1 IN., LOOP DETECTOR WITH TRACE	3/27/25	4/2/25	70.00	LF	Vogel Rd					
0310	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	3/27/25	4/2/25	72.00	LF	Various Sites					
0320	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	3/27/25	4/2/25	35.00	LF	Various locations					
0330	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	3/27/25	4/2/25	57.00	LF	Various Sites					
0340	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	3/27/25	4/2/25	100.00	LF	Various sites					
0350	9028308	CABLE, 16 AWG 2 CONDUCTOR	3/27/25	4/2/25	3,250.00	LF	Various Sites					
0360	9028500	CABLE, LOOP DETECTOR, IN DUCT	3/27/25	4/2/25	3,290.00	LF	Vogel Rd					
0390	9029902	MISC.	3/27/25	4/2/25	27.00	EA	Various sites					
			3/31/25	4/2/25	1.00	EA	Imperial Main					
0400	9029902	MISC.	3/27/25	4/2/25	4.00	EA	Elm					
0410	9029902	MISC.	3/27/25	4/2/25	2.00	EA	Elm					
0420	9029902	MISC.	3/27/25	4/2/25	1.00	EA	Vogel Rd 231+50 RT	231+50	RT			Extension added to make pushbutton ADA compliant. S change order for reason
0430	9029902	MISC.	3/31/25	4/2/25	1.00	EA	Imperial Main					
0450	9031010	CONCRETE FOOTINGS, EMBEDDED	3/27/25	4/2/25	4.00	CUYD	Various sites for pushbutton bases					
0460	9031280	2.5 IN. PSST POST - 12 GA.	3/27/25	4/2/25	17.00	LF	Vogel Rd					
0470	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	3/27/25	4/2/25	1.00	EA	Vogel Rd					
0480	9035069A	SHF-FLAT SHEET FLUORESCENT	3/27/25	4/2/25	97.00	SQFT	Elm, Imperial, Vogel.					6.93 overrun from yield sign at Imperial Main. Missing upon arival and agreed to in change order

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 8 of 18



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J6P3510B	0030	TYPE 5 AGGREGATE FOR BASE	Material		2	Oct 1, 2024	SYSTEM	\$3,350.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
					2	Oct 1, 2024	SYSTEM	(\$3,350.45)																				
					3	Oct 16, 2024	SYSTEM	\$4,817.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user claspc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
					3	Oct 16, 2024	SYSTEM	(\$4,817.19)																				
				- Total				\$0.00																				
			Material - Tota	ıl				\$0.00																				
			Price FUEL		2	Oct 1, 2024	SYSTEM	(\$8.94)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					3	Oct 16, 2024	SYSTEM	(\$4.42)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					4	Nov 4, 2024	SYSTEM	(\$18.10)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					4	Nov 4, 2024	SYSTEM	(\$7.34)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					5	Nov 18, 2024	SYSTEM	(\$3.45)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					6	Dec 2, 2024	SYSTEM	(\$9.99)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					7	Dec 16, 2024	SYSTEM	(\$7.52)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					8	Jan 3, 2025	SYSTEM	(\$4.85)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					9	Feb 3, 2025	SYSTEM	(\$0.88)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
											10	Feb 18, 2025	SYSTEM	(\$0.75)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					11	Mar 3, 2025	SYSTEM	(\$0.11)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					12	Mar 17, 2025	SYSTEM	(\$2.29)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
				- Total				(\$68.64)																				
			Price FUEL - 1	Γotal				(\$68.64)																				
	0030 -	Total						(\$68.64)																				
	0040	CONCRETE PAVEMENT (10	Material		2	Oct 1, 2024	SYSTEM	(\$31,002.04)																				
		IN. NON- REINFORCED						3	Oct 16, 2024	SYSTEM	\$31,002.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user claspc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					3	Oct 16, 2024	SYSTEM	(\$31,002.04)																				
					4	Nov 4, 2024	SYSTEM	\$73,348.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user claspc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
							4	Nov 4, 2024	SYSTEM	(\$73,348.84)																		
					5	5									5									5	Nov 18, 2024	SYSTEM	\$73,348.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.
																			5	5			5	Nov 18, 2024	SYSTEM	(\$73,348.84)		
									6	6	6	6	6	6	6	6	6	6	Dec 2, 2024	SYSTEM	\$88,154.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.						
						6	Dec 2, 2024	SYSTEM	(\$88,154.54)																			
					7	Dec 16, 2024	SYSTEM	\$88,154.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3510B	0040	CONCRETE PAVEMENT (10	Material		7	Dec 16, 2024	SYSTEM	(\$88,154.54)	
		IN. NON- REINFORCED			8	Jan 3, 2025	SYSTEM	\$88,154.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jan 3, 2025	SYSTEM	(\$88,154.54)	
					9	Feb 3, 2025	SYSTEM	\$88,154.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Feb 3, 2025	SYSTEM	(\$88,154.54)	
					10	Feb 18, 2025	SYSTEM	\$88,154.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Feb 18, 2025	SYSTEM	(\$88,154.54)	
					11	Mar 3, 2025	SYSTEM	\$88,154.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Mar 3, 2025	SYSTEM	(\$88,154.54)	
				- Total				(\$31,002.04)	
			Material - Tota	ıl				(\$31,002.04)	
			MaterialCredit		3	Oct 16, 2024	SYSTEM	\$31,002.04	
				- Total				\$31,002.04	
			MaterialCredit	- Total				\$31,002.04	
			Overrun	Overrun	6	Dec 2, 2024	SYSTEM	(\$13,043.27)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Dec 16, 2024	SYSTEM	\$13,043.27	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',104.34616 - 104.56000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
			Price FUEL		2	Oct 1, 2024	SYSTEM	(\$42.91)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Nov 4,	SYSTEM	(\$30.94)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
						2024		(ψου.οτ)	, , , , , , , , , , , , , , , , , , , ,
					4	2024 Nov 4, 2024	SYSTEM	(\$35.25)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Nov 4,	SYSTEM SYSTEM		
				- Total		Nov 4, 2024 Dec 2,		(\$35.25)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Price FUEL - 1			Nov 4, 2024 Dec 2,		(\$35.25) (\$30.28)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0040 -	- Total	Price FUEL - 1			Nov 4, 2024 Dec 2,		(\$35.25) (\$30.28) (\$139.38)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0040 -	-Total WATER - UTILITY ITEM	Price FUEL - 1			Nov 4, 2024 Dec 2,		(\$35.25) (\$30.28) (\$139.38)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		WATER -			6	Nov 4, 2024 Dec 2, 2024	SYSTEM	(\$35.25) (\$30.28) (\$139.38) (\$139.38) (\$139.38)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		WATER -			2	Nov 4, 2024 Dec 2, 2024 Oct 1, 2024 Oct 16,	SYSTEM	(\$35.25) (\$30.28) (\$139.38) (\$139.38) (\$139.38) (\$275.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user claspc1 overridding Payment
		WATER -			2 3	Nov 4, 2024 Dec 2, 2024 Oct 1, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM	(\$35.25) (\$30.28) (\$139.38) (\$139.38) (\$139.38) (\$275.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user claspc1 overridding Payment
		WATER -			2 3 3	Nov 4, 2024 Dec 2, 2024 Oct 1, 2024 Oct 16, 2024 Nov 4,	SYSTEM SYSTEM SYSTEM	(\$35.25) (\$30.28) (\$139.38) (\$139.38) (\$139.38) (\$275.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user claspc1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user claspc1 overridding Payment
		WATER -			2 3 3 4	Nov 4, 2024 Dec 2, 2024 Oct 1, 2024 Oct 16, 2024 Nov 4, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$35.25) (\$30.28) (\$139.38) (\$139.38) (\$139.38) (\$275.00) (\$275.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user claspc1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user claspc1 overridding Payment



18-05-100 18-0	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks															
UTILITY (TEM		20	2 coc.ipiioii		Adjustment				7 1110 1111	. Gunano															
State Color Total Color Colo	J6P3510B	0050		Material		6		SYSTEM	\$550.00	Estimate Item Adjustment (0006) due to user litzam overridding Payment															
Material Teal Material Teal Material Teal Material Teal 175.50						6		SYSTEM	(\$550.00)																
Material Credit 3					- Total				(\$275.00)																
				Material - Tota	1				(\$275.00)																
				MaterialCredit		3		SYSTEM	\$275.00																
					- Total				\$275.00																
1				MaterialCredit	- Total				\$275.00																
DOMES		0050 -	· Total						\$0.00																
2024 A		0060		Material		3		SYSTEM	\$902.00	Estimate Item Adjustment (0007) due to user claspc1 overridding Payment															
2024 System Statuse Exception 4 on the current Payment Estimate Statuse St						3		SYSTEM	(\$902.00)																
Source						4		SYSTEM	\$4,004.00	Estimate Item Adjustment (0019) due to user claspc1 overridding Payment															
						4		SYSTEM	(\$4,004.00)																
2024 6											5		SYSTEM	\$5,461.50	Estimate Item Adjustment (0006) due to user litzam overridding Payment										
2024 Estimate Item Adjustment (0007) due to user litzam overridding Payment Estimate Exception 4 on the current Payment Estimate.							5		SYSTEM	(\$5,461.50)															
2024 7 Dec 16, SYSTEM \$8,585.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 7 Dec 16, 2024 \$0.00						6		SYSTEM	\$6,341.50	Estimate Item Adjustment (0007) due to user litzam overridding Payment															
2024 Estimate Item Adjustment (0005) due to user litzam overridding Payment Estimate.						6		SYSTEM	(\$6,341.50)																
Approach Barbar Concern Conc						7		SYSTEM	\$8,585.50	Estimate Item Adjustment (0005) due to user litzam overridding Payment															
Material - Total \$0.00						7		SYSTEM	(\$8,585.50)																
1					- Total				\$0.00																
Overrun Overrun Overrun 11				Material - Tota	ı				\$0.00																
2025 12 Mar 17, 2025 13 Apr 3, 2025 2025 2025 2026 2025 2025 2026 2025 2025 2025 2025 2025 2026		0060 -	· Total						\$0.00																
12 Mar 17, SYSTEM (\$13,545.72) 13 Apr 3, 2025 13 Apr 3, 2025 14 Nov 4, 2024 15 Nov 18, SYSTEM (\$19,255.86) 19,255.86 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',317.23000 - 317.23000, 'is applied (if non-zero). 1000 100		0070	CONCRETE	Overrun	Overrun	11		SYSTEM	(\$5,710.14)																
Overrun - Total Overru						12		SYSTEM	(\$13,545.72)																
Overrun - Total So.00 PAVED APPROACH, 8 IN. Oct 16, 2024 SYSTEM \$11,919.53 Oct 16, 2024 Finis adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. Oct 16, 2024 Nov 4, SYSTEM \$34,656.64 Nov 4, 2024 Nov 4, 2024 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user claspc1 overridding Payment Estimate Item Adjustment (0020) due to user claspc1 overridding Payment Estimate Exception 5 on the current Payment Estimate. Nov 4, 2024 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. Nov 4, 2024 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment						13		SYSTEM	\$19,255.86	previous payment estimates. Price Adjustments of ',317.23000 - 317.23000, 'is															
Overrun - Total S0.00 PAVED APPROACH, 8 IN. Material 3 Oct 16, 2024 SYSTEM \$11,919.53 Cot 16, 2024 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 3 Oct 16, SYSTEM (\$11,919.53) 4 Nov 4, 2024 Nov 4, 2024 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user claspc1 overridding Payment Estimate Item Adjustment (0020) due to user claspc1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Nov 4, 2024 SYSTEM (\$34,656.64) Nov 18, SYSTEM \$34,656.64 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 5 Nov 18, SYSTEM \$34,656.64 Estimate Item Adjustment (0007) due to user itizam overridding Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment					Overrun - T	otal			\$0.00																
O080 PAVED APPROACH, 8 IN. 3 Oct 16, 2024 SYSTEM \$11,919.53 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user claspc1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 3 Oct 16, 2024 SYSTEM (\$11,919.53) 4 Nov 4, 2024 SYSTEM \$34,656.64 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user claspc1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Nov 4, 2024 SYSTEM (\$34,656.64) 5 Nov 18, 2024 SYSTEM \$34,656.64 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 5 Nov 18, 2024 SYSTEM \$34,656.64 Estimate Item Adjustment (0007) due to user litzam overridding Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment				Overrun - Tota																					
PAVED APPROACH, 8 IN. Material APPROACH, 8 IN. APPROACH, 8 IN		0070 -	· Total																						
2024 4 Nov 4, 2024 SYSTEM \$34,656.64 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user claspc1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Nov 4, 2024 SYSTEM (\$34,656.64) 5 Nov 18, 2024 \$34,656.64 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment			APPROACH, 8	Material		3		SYSTEM	\$11,919.53	Estimate Item Adjustment (0009) due to user claspc1 overridding Payment															
Estimate Item Adjustment (0020) due to user claspc1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Nov 4, 2024 5 Nov 18, SYSTEM \$34,656.64 2024 5 SYSTEM \$34,656.64 Estimate Item Adjustment (0020) due to user claspc1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment																				3	3		SYSTEM	(\$11,919.53)	
4 Nov 4, 2024 SYSTEM (\$34,656.64) 5 Nov 18, 2024 SYSTEM \$34,656.64 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment								4		SYSTEM	\$34,656.64	Estimate Item Adjustment (0020) due to user claspc1 overridding Payment													
2024 Estimate Item Adjustment (0007) due to user litzam overridding Payment					4		SYSTEM	(\$34,656.64)																	
						5		SYSTEM	\$34,656.64	Estimate Item Adjustment (0007) due to user litzam overridding Payment															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3510B	0080	PAVED APPROACH, 8	Material	3.	5	Nov 18, 2024	SYSTEM	(\$34,656.64)	
		IN.			6	Dec 2, 2024	SYSTEM	\$41,993.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Dec 2, 2024	SYSTEM	(\$41,993.86)	
					7	Dec 16, 2024	SYSTEM	\$41,993.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Dec 16, 2024	SYSTEM	(\$41,993.86)	
					8	Jan 3, 2025	SYSTEM	\$41,993.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jan 3, 2025	SYSTEM	(\$41,993.86)	
					9	Feb 3, 2025	SYSTEM	\$41,993.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Feb 3, 2025	SYSTEM	(\$41,993.86)	
					10	Feb 18, 2025	SYSTEM	\$41,993.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Feb 18, 2025	SYSTEM	(\$41,993.86)	
					11	Mar 3, 2025	SYSTEM	\$41,993.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Mar 3, 2025	SYSTEM	(\$41,993.86)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun	6	Dec 2, 2024	SYSTEM	(\$5,929.87)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Dec 16, 2024	SYSTEM	\$5,929.87	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',91.65178 - 91.83000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
			Price FUEL		3	Oct 16, 2024	SYSTEM	(\$17.68)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Nov 4, 2024	SYSTEM	(\$18.63)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Nov 4, 2024	SYSTEM	(\$15.09)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Dec 2, 2024	SYSTEM	(\$14.24)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$65.64)	
			Price FUEL - 1	Γotal				(\$65.64)	
	0080 -	Total						(\$65.64)	
	0100	CONCRETE SIDEWALK, 7	Overrun	Overrun	12	Mar 17, 2025	SYSTEM	(\$1,156.47)	
		IN.			13	Apr 3, 2025	SYSTEM	\$1,156.47	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',165.21000 - 165.21000, 'is applied (if non-zero).
				Overrue T	otal			\$0.00	applied (ii noti-zero).
			O	Overrun - T	otai				
			Overrun - Tota	al				\$0.00	
	0100 -							\$0.00	
	0110	MISC. CONCRETE	Material		8	Jan 3, 2025	SYSTEM	\$35,388.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3510B	0110	MISC. CONCRETE	Material		8	Jan 3, 2025	SYSTEM	(\$35,388.21)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
			Overrun	Overrun	13	Apr 3, 2025	SYSTEM	(\$2,722.17)	
				Overrun - T	otal			(\$2,722.17)	
			Overrun - Tota	al				(\$2,722.17)	
	0110 -	Total						(\$2,722.17)	
	0120	MISC. CONCRETE	Overrun	Overrun	6	Dec 2, 2024	SYSTEM	(\$2,970.38)	
					7	Dec 16, 2024	SYSTEM	\$2,970.38	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2970.38000 - 2970.38000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota					\$0.00	
	0120 -	Total						\$0.00	
	0140	CONCRETE CURB (6 IN.	Overrun	Overrun	8	Jan 3, 2025	SYSTEM	(\$12,996.73)	
		HEIGHT AND UNDER)			9	Feb 3, 2025	SYSTEM	\$12,996.73	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',742.67000 - 742.67000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0140 -	Total						\$0.00	
	0150	INTEGRAL CURB (6 IN.	Material		2	Oct 1, 2024	SYSTEM	(\$1,507.56)	
		HEIGHT AND UNDER)			3	Oct 16, 2024	SYSTEM	\$1,507.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user claspc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Oct 16, 2024	SYSTEM	(\$1,507.56)	
				- Total				(\$1,507.56)	
			Material - Tota	al				(\$1,507.56)	
			MaterialCredit		3	Oct 16, 2024	SYSTEM	\$1,507.56	
				- Total				\$1,507.56	
			MaterialCredit	t - Total				\$1,507.56	
			Overrun	Overrun		Nov 4, 2024	SYSTEM	(\$3,015.12)	
					6	Dec 2, 2024	SYSTEM	(\$1,596.24)	
					7	Dec 16, 2024	SYSTEM	\$4,611.36	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',88.68000 - 88.68000, 'is applied (if non-zero).
					8	Jan 3, 2025	SYSTEM	(\$8,601.96)	
					9	Feb 3, 2025	SYSTEM	\$7,892.52	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',88.68000 - 88.68000, 'is applied (if non-zero).
					11	Mar 3, 2025	SYSTEM	\$709.44	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',88.68000 - 88.68000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
		Total						\$0.00	
	0150 -	Total							
	0150 -	MISC.	Material		7	Dec 16, 2024	SYSTEM	\$26,665.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3510B	0160	MISC.	Material	- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0160 -	Total						\$0.00	
	0180	PREF THERMO PVMT MARK, 24 IN WHIT	Material		13	Apr 3, 2025	SYSTEM	\$15,082.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Apr 3, 2025	SYSTEM	(\$15,082.20)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
			Overrun	Overrun	13	Apr 3, 2025	SYSTEM	(\$37.80)	
				Overrun - T	otal			(\$37.80)	
			Overrun - Tota	al				(\$37.80)	
	0180 -	Total						(\$37.80)	
	0190	PREF THERMO PVMT MARK, 30" WHT MIDBL	Material		13	Apr 3, 2025	SYSTEM	\$44,755.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Apr 3, 2025	SYSTEM	(\$44,755.20)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0190 -	Total						\$0.00	
	0200	PREF THERMO PVMT MARK, YIELD TRIAN	Material		13	Apr 3, 2025	SYSTEM	\$15,082.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Apr 3, 2025	SYSTEM	(\$15,082.20)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0200 -	Total		<u>"</u>				\$0.00	
	0210	6 IN. WHITE HIGH BUILD WATERBORNE	Material		13	Apr 3, 2025	SYSTEM	\$6,810.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 4 on the current Payment Estimate.
		PAINT			13	Apr 3, 2025	SYSTEM	(\$6,810.10)	,
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun	13	Apr 3, 2025	SYSTEM	(\$229.52)	
				Overrun - T	otal			(\$229.52)	
			Overrun - Tota					(\$229.52)	
	0210 -	Total						(\$229.52)	
	0370	BASE, CONCRETE	Material		9	Feb 3, 2025	SYSTEM	\$39,004.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Feb 3, 2025	SYSTEM	(\$39,004.42)	
					10	Feb 18, 2025	SYSTEM	\$39,004.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Feb 18, 2025	SYSTEM	(\$39,004.42)	
					11	Mar 3, 2025	SYSTEM	\$39,004.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Mar 3, 2025	SYSTEM	(\$39,004.42)	
					12	Mar 17, 2025	SYSTEM	\$39,004.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3510B	0370	BASE, CONCRETE	Material		12	Mar 17, 2025	SYSTEM	(\$39,004.42)	
					13	Apr 3, 2025	SYSTEM	\$39,004.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Apr 3, 2025	SYSTEM	(\$39,004.42)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0370 -	· Total						\$0.00	
	0380	MISC.	Material		4	Nov 4, 2024	SYSTEM	\$995.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user claspc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Nov 4, 2024	SYSTEM	(\$995.76)	
					5	Nov 18, 2024	SYSTEM	\$995.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Nov 18, 2024	SYSTEM	(\$995.76)	
					6	Dec 2, 2024	SYSTEM	\$995.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user litzam overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Dec 2, 2024	SYSTEM	(\$995.76)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0380 -	· Total		nateriai - Totai				\$0.00	
	0390	MISC.	Overrun	Overrun	13	Apr 3, 2025	SYSTEM	(\$1,274.40)	
				Overrun - To	otal			(\$1,274.40)	
				Overrun - Total					
			Overrun - Tot					(\$1,274.40)	
	0390 -	· Total	Overrun - Tot	al					
	0390 - 0430	Total MISC.	Overrun - Tot	al	3	Oct 16, 2024	SYSTEM	(\$1,274.40)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				al	3		SYSTEM	(\$1,274.40) (\$1,274.40)	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment
				al		2024 Oct 16,		(\$1,274.40) (\$1,274.40) \$1,051.92	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment
				al	3	2024 Oct 16, 2024 Nov 4,	SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92)	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment
				al	3	2024 Oct 16, 2024 Nov 4, 2024	SYSTEM SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92) \$1,051.92	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment
				al	3 4	2024 Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18,	SYSTEM SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92) \$1,051.92 (\$1,051.92)	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment
				al	3 4 4 5	2024 Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92) \$1,051.92 (\$1,051.92) \$2,103.84	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment
				al	3 4 4 5 5	2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92) \$1,051.92 (\$1,051.92) \$2,103.84	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment
				al	3 4 4 5 5 6 6	2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92) \$1,051.92 (\$1,051.92) \$2,103.84 (\$2,103.84)	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment
				al	3 4 4 5 5 6 6 6	2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92) \$1,051.92 (\$1,051.92) \$2,103.84 (\$2,103.84) \$9,467.28	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.
				al	3 4 4 5 5 6 6 7 7	2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 16, 2024 Dec 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92) (\$1,051.92) (\$2,103.84) (\$2,103.84) (\$9,467.28) (\$9,467.28)	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.
				al	3 4 4 5 5 6 6 7 7	2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 16, 2024 Dec 16, 2024 Jan 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,274.40) (\$1,274.40) \$1,051.92 (\$1,051.92) (\$1,051.92) (\$2,103.84) (\$2,103.84) (\$9,467.28) (\$9,467.28)	Estimate Item Adjustment (0012) due to user claspc1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user claspc1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.



Property										
Patronic Exception on the current Payment Estimate. Patronic Exception of the current Payment Estimate. Patronic Exception of the current Payment Estimate. Patronic Payment Estimate. Patronic Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment Patronic Payment Payment Payment Patronic Payment Payme	Project	Line	Description		Adjustment				Amount	Remarks
10 Feb 18, 2015 SYSTEM ST157.112 This adjustment offices the original system-generated Material Payment Control of the current Payment (MOS) due to user illumo overridding Payment (Similar Man Adjustment) (MOS) due to user illumo overridding Payment (Similar Man Adjustment) (MOS) due to user illumo overridding Payment (Similar Man Adjustment) (MOS) due to user illumo overridding Payment (Similar Man Adjustment) (MOS) due to user illumo overridding Payment (Similar Man Adjustment) (MOS) due to user illumo overridding Payment) (Similar Man Adjustment) (MOS) due to user illumo overridding Payment) (Similar Man Adjustment) (MOS) due to user illumo overridding Payment) (Similar Man Adjustment) (MOS) due to user illumo overridding Payment) (Similar Man Adjustment) (MOS) due to user illumo overridding Payment) (Similar Man Adjustment) (MOS) due to user disease) (MOS) du	J6P3510B	0430	MISC.	Material			2025			
2025						9		SYSTEM	(\$9,467.28)	
1						10		SYSTEM	\$11,571.12	Estimate Item Adjustment (0005) due to user litzam overridding Payment
2025 Editinde Item Adjustment (CODT) due to user fitzam overridding Payment Editinate Exception 3 on the outrient Payment Editinate.						10		SYSTEM	(\$11,571.12)	
-Total						11		SYSTEM	\$11,571.12	Estimate Item Adjustment (0007) due to user litzam overridding Payment
Material - Total						11		SYSTEM	(\$11,571.12)	
Material - Total					- Total				\$0.00	
Overrun Total Overrun				Material - Tota						
Overrun - Total						13		SYSTEM		
Misc. Material					Overrun - T	otal	2020		(\$1,051.92)	
MISC. Material				Overrun - Tota	al				(\$1,051.92)	
MISC. Material		0430 -	· Total						(\$1,051.92)	
		0440	MISC.	Material		4		SYSTEM	\$3,345.84	Estimate Item Adjustment (0023) due to user claspc1 overridding Payment
2024 SySTEM S3,345.84						4		SYSTEM	(\$3,345.84)	
2024 6						5		SYSTEM	\$3,345.84	Estimate Item Adjustment (0010) due to user litzam overridding Payment
2024 Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate Payment Estimate Exception 9 on the current Payment Estimate Payment Estimate Item Adjustment (0012) due to user litzam overridding Payment Estimate Item Adjustment (0012) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Item Adjustment (0008) due to user litzam overridding Payment Item Adjustment (0008) due to user litzam overridding Payment Item Adjustment (0008) due to user litzam overridding Payment Item Adjustment Item Adjustments of installed quantity on all previous payment estimates, Price Adjustments of installed quantity on all previous payment estimates, Price Adjustments of installed quantity on all previous payment estimates, Price Adjustments of installed quantity on all previous payment estimates, Price Adjustments of installed quantity on all previous payment estimates. Price Adjustment of installed quantity on all previous payment estimates. Price Adjustment of installed quantity on all previous payment estimates. Price Adjustment of installed quantity on all pr						5		SYSTEM	(\$3,345.84)	
2024 2025 2025						6		SYSTEM	\$3,345.84	Estimate Item Adjustment (0015) due to user litzam overridding Payment
Substitute Sub						6		SYSTEM	(\$3,345.84)	
8 Jan 3, 2025 SYSTEM \$3,345.84 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. 8 Jan 3, 2025 SYSTEM (\$3,345.84) 9 Feb 3, 2025 SYSTEM \$3,345.84 17 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate I						7		SYSTEM	\$3,345.84	Estimate Item Adjustment (0012) due to user litzam overridding Payment
Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. 8 Jan 3, 2025 9 Feb 3, 2025 9 Feb 3, 2025 9 Feb 3, 2025 1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate. 9 Feb 3, 2025 1 SySTEM (\$3,345.84) 2025 1 SySTEM (\$3,345.84) 2025 1 Material - Total Overrun Overrun Overrun Overrun Overrun Overrun Overrun - Total Overrun - Total So.00 Overrun - Total Overrun - Total Overrun - Total So.00 Overrun - Total Overrun - Total So.00 Overrun - Total Overrun - Total So.00 Overrun - Total So.00 Overrun - Total So.00 Overrun - Total So.00 Overrun - Total						7		SYSTEM	(\$3,345.84)	
2025 9						8		SYSTEM	\$3,345.84	Estimate Item Adjustment (0008) due to user litzam overridding Payment
System S						8		SYSTEM	(\$3,345.84)	
Comparison of the content of the c						9		SYSTEM	\$3,345.84	Estimate Item Adjustment (0008) due to user litzam overridding Payment
Material - Total						9		SYSTEM	(\$3,345.84)	
Overrun					- Total				\$0.00	
2025 13 Apr 3, 2025 13 Apr 3, 2025 SYSTEM \$3,345.84 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3345.84000 - 3345.84000, 'is applied (if non-zero). Overrun - Total \$0.00 Overrun - Total \$0.00 0440 - Total \$0.00 0460 2.5 IN. PSST POST - 12 GA. Apr 3, 2025 SYSTEM \$932.28 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment				Material - Tota	ıl				\$0.00	
Overrun - Total So.00 Editional System-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment				Overrun	Overrun	12		SYSTEM	(\$3,345.84)	
Overrun - Total \$0.00 0440 - Total \$0.00 0460						13		SYSTEM	\$3,345.84	previous payment estimates. Price Adjustments of ',3345.84000 - 3345.84000,
Overrun - Total S0.00 0440 - Total \$0.00 0460 2.5 IN. PSST POST - 12 GA. Apr 3, SYSTEM \$932.28 POST - 12 GA. S0.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment					Overrun - T	otal			\$0.00	
0440 - Total\$0.0004602.5 IN. PSST POST - 12 GA.Material13 Apr 3, 2VSTEM 2025\$932.28This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment				Overrun - Tota					\$0.00	
0460 2.5 IN. PSST Material 13 Apr 3, SYSTEM \$932.28 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment		0440	Total							
Estudate exception & on the current estudate			2.5 IN. PSST	Material		13		SYSTEM		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3510B	0460	2.5 IN. PSST POST - 12 GA.	Material		13	Apr 3, 2025	SYSTEM	(\$932.28)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0460 - Total							\$0.00	
	0480	SHF-FLAT SHEET FLUORESCENT	Material		13	Apr 3, 2025	SYSTEM	\$3,697.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 9 on the current Payment Estimate.
					13	Apr 3, 2025	SYSTEM	(\$3,697.64)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0480 -	Total						\$0.00	
	5003	PULL BOX, PREFORMED CLASS 1	Material		7	Dec 16, 2024	SYSTEM	\$1,828.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user litzam overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Dec 16, 2024	SYSTEM	(\$1,828.54)	
					8	Jan 3, 2025	SYSTEM	\$1,828.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jan 3, 2025	SYSTEM	(\$1,828.54)	
					9	Feb 3, 2025	SYSTEM	\$1,828.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Feb 3, 2025	SYSTEM	(\$1,828.54)	
					10	Feb 18, 2025	SYSTEM	\$1,828.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Feb 18, 2025	SYSTEM	(\$1,828.54)	
					11	Mar 3, 2025	SYSTEM	\$1,828.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Mar 3, 2025	SYSTEM	(\$1,828.54)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5003 -	Total						\$0.00	
J6P3510B -	6P3510B - Total								
Overall - To	verall - Total							(\$5,589.47)	

MoDOT

Contract Adjustments for Contract - 240517-F05

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 18 of 18