

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 2, 2025

Progress Estimate 5	Number	Contract ID Prime Contractor	240517-F11 Kelpe Contracti		Pay Period Start Pay Period End	March 16 April 1, 2	,	Original Contract Amount Net Change Order Amount Current Contract Amount	\$472,091.33 \$0.00 \$472,091.33		
Approval Date									By User		
April 2, 2025			Generated and A	Approved	(and should be cor	nsidered D	raft) at	the Project Office Level by	ashtoa1		
April 2, 2025	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by dunnj1										
April 4, 2025	Reviewed and Approved at the Central Office Controllers Office Level by ramses1										
Original Completion Date Current Completion Date Actual Completion Date % of Current Contract Am									unt Complete		
March 31, 202	5	March 3	1, 2025					91.24%			
	Contract	Informational Date	es		Miles	tones					
Date Description	Original	Completion Date	Current Comple	tion Date	No Milestones E	Exist for Co	ontract				
Acceptance Date											
Awarded Date	June 5, 2	024	June 5, 2024								
Letting Date	May 17, 2	2024	May 17, 2024								
Notice to Proceed Date	July 8, 20)24	July 8, 2024								
Open to Traffic Date											

Contract Total Pay For	r Estimate No. 5			
		This Estimate	Previous	To Date
240517-F11				
	Total Posted Items Pay	\$168,388.26	\$262,351.39	\$430,739.65
	Gross Item Adjustments	(\$9,734.50)	\$0.00	(\$9,734.50)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$262,351.39	\$421,005.15
Contract Total Payable	e This Estimate:	\$158,653.76		

January 27, 2025

Items Paid This Estimate Period

Work Began Date

January 27, 2025

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JSL0093	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$12,951.950	0.1	\$1,295.20
	0030	2031000	CLASS A EXCAVATION	CUYD	\$89.170	260	\$23,184.20
	0040	2036000	COMPACTING EMBANKMENT	CUYD	\$215.910	26	\$5,613.66
	0070	2063500	CULVERT CLEANOUT	EA	\$7,316.030	2	\$14,632.06
	0800	2069901	MISC.DEWATERING	LS	\$7,890.210	0.5	\$3,945.11
	0110	6071012A	CHAIN-LINK FENCE (60 IN.)	LF	\$73.250	306	\$22,414.50
	0120	6071040	DRIVE GATE (CHAIN-LINK)	EA	\$3,094.000	2	\$6,188.00
	0130	6085007	PAVED APPROACH, 7 IN.	SQYD	\$324.230	28	\$9,078.44
	0140	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$226.960	12	\$2,723.52
	0150	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$26.710	247.27	\$6,604.58
	0160	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$88.070	247.27	\$21,777.07
	0180	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	EA	\$3,094.000	1	\$3,094.00
	0190	6149902	MISC.GRATES AND BEARING PLATES (1 FT. X 7 FT. 7 IN.)	EA	\$2,952.000	0.5	\$1,476.00
	0200	6149902	MISC.GRATES AND BEARING PLATES (5 FT. X 7 FT. 7 IN.)	EA	\$6,188.000	1.5	\$9,282.00
	0210	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$7,890.210	0.5	\$3,945.11
	0250	7034041	CLASS B-1 CONCRETE (CULVERTS)	CUYD	\$1,540.920	7.8	\$12,019.18
	0260	7061030	REINFORCING STEEL (CULVERTS)	LB	\$14.550	820	\$11,931.00

Revision 3/23/2023 Page 1 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 2, 2025

Progress Estimate Number	Contract ID	240517-F11	•	,	Original Contract Amount	
5	Prime Contractor	Kelpe Contracting, Inc.	Pay Period End	April 1, 2025	Net Change Order Amount	
					Current Contract Amount	\$472,091.33

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JSL0093	0290	8025006	MULCHING	ACRE	\$1,125.930	0.2	\$225.19
	0300	8051000A	SEEDING - COOL SEASON GRASSES	ACRE	\$4,323.560	1.2	\$5,188.27
	0320	8061016	SEDIMENT REMOVAL	CUYD	\$290.090	13	\$3,771.17
Project JSL0	093 - Total						\$168,388.26
Overall - Tot	al						\$168,388.26

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
SL0093	0130	PAVED APPROACH, 7 IN.	Material			-28	\$324.23	(\$9,078.44)
	0130	PAVED APPROACH, 7 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user ashtoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	28	\$324.23	\$9,078.44
	0140	CONCRETE SIDEWALK, 4 IN.	Material			-12	\$226.96	(\$2,723.52)
	0140	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user ashtoa1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	12	\$226.96	\$2,723.52
	0150	FURNISHING TYPE 2 ROCK BLANKET	Overrun			-84.81	\$26.71	(\$2,265.28)
	0160	PLACING TYPE 2 ROCK BLANKET	Overrun			-84.81	\$88.07	(\$7,469.22)
	0250	CLASS B-1 CONCRETE (CULVERTS)	Material			-18.3	\$1,540.92	(\$28,198.84)
	0250	CLASS B-1 CONCRETE (CULVERTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user ashtoa1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	18.3	\$1,540.92	\$28,198.84
	0280	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material			-11	\$589.22	(\$6,481.42)
	0280	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user ashtoa1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	11	\$589.22	\$6,481.42
	0300	SEEDING - COOL SEASON GRASSES	Material			-1.2	\$4,323.56	(\$5,188.27)
	0300	SEEDING - COOL SEASON GRASSES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user ashtoa1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1.2	\$4,323.56	\$5,188.27
	0310	ROCK DITCH CHECK	Material			-20	\$218.49	(\$4,369.80)
	0310	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user ashtoa1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	20	\$218.49	\$4,369.80
otal								(\$9,734.50)

Revision 3/23/2023 Page 2 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work				
JSL0093	FAF-364-1 (51)	Drainage improvement	364	ST LOUIS	at northeast corner of Bennington in Maryland Heights					

Revision 3/23/2023 Page 3 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSL0093, Item 6085007, Project Item Line Number 0130, Material Set 608500796, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Waiting on PAL Cert to be entered in	ashtoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0093, Item 6085007, Project Item Line Number 0130, Material Set 608500796, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL Cert to be entered in	ashtoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0093, Item 6086004, Project Item Line Number 0140, Material Set 608600496, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Underrun, waiting on change order	ashtoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0093, Item 6086004, Project Item Line Number 0140, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on PAL to be entered in	ashtoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0093, Item 7034041, Project Item Line Number 0250, Material Set 703404196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on PAL to be entered in	ashtoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0093, Item 7311053, Project Item Line Number 0280, Material Set 731105396, Material 1033DIRCPK - Precast Conc Drop Inlet, Acceptance Action Generic 1033DIRCPK is insufficient.	Waiting on DPRO APQC test	ashtoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0093, Item 8051000A, Project Item Line Number 0300, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Need to enter in a tag cert, LBLA	ashtoa1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0093, Item 8061005, Project Item Line Number 0310, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Underrun, must do change order	ashtoa1	Overridden
Estimate Exception Type: Item Overrun: Contract 240517-F11, Contract Project JSL0093, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6113020, Minor Item.	Overrun, must do change order	ashtoa1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240517-F11, Contract Project JSL0093, Project Item Line Number 0160, Contract Line Item Number 0160, Item 6113040, Minor Item.	Overrun, must do change order	ashtoa1	Acknowledged

Revision 3/23/2023 Page 4 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240517-F11	JSL0093	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$12,385.19	\$12,385.19
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$12,951.95	\$12,951.95
		0001	0030	2031000	CLASS A EXCAVATION	523.00	0.00	523.00	CUYD	523.00	\$89.17	\$46,635.91
		0001	0040	2036000	COMPACTING EMBANKMENT	26.00	0.00	26.00	CUYD	26.00	\$215.91	\$5,613.66
		0001	0050	2063000	CLASS 3 EXCAVATION	49.00	0.00	49.00	CUYD	49.00	\$135.97	\$6,662.53
		0001	0060	2063300	CLASS 4 EXCAVATION	30.00	0.00	30.00	CUYD	30.00	\$213.45	\$6,403.50
		0001	0070	2063500	CULVERT CLEANOUT	2.00	0.00	2.00	EA	2.00	\$7,316.03	\$14,632.06
		0001	0800	2069901	MISC.DEWATERING	1.00	0.00	1.00	LS	1.00	\$7,890.21	\$7,890.21
		0001	0090	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	48.00	0.00	48.00	SQYD	48.00	\$122.80	\$5,894.40
		0001	0100	3105002	GRAVEL (A) OR CRUSHED STONE (B)	12.00	0.00	12.00	TONS	12.00	\$311.58	\$3,738.96
		0001	0110	6071012A	CHAIN-LINK FENCE (60 IN.)	306.00	0.00	306.00	LF	306.00	\$73.25	\$22,414.50
		0001	0120	6071040	DRIVE GATE (CHAIN-LINK)	2.00	0.00	2.00	EA	2.00	\$3,094.00	\$6,188.00
		0001	0130	6085007	PAVED APPROACH, 7 IN.	28.00	0.00	28.00	SQYD	28.00	\$324.23	\$9,078.44
		0001	0140	6086004	CONCRETE SIDEWALK, 4 IN.	20.00	0.00	20.00	SQYD	12.00	\$226.96	\$2,723.52
		0001	0150	6113020	FURNISHING TYPE 2 ROCK BLANKET	548.00	0.00	548.00	CUYD	632.81	\$26.71	\$16,902.36
		0001	0160	6113040	PLACING TYPE 2 ROCK BLANKET	548.00	0.00	548.00	CUYD	632.81	\$88.07	\$55,731.58
		0001	0170	6119905	MISC.PERMANENT EROSION CONTROL MAT	4,809.00	0.00	4,809.00	SQYD	4,809.00	\$3.22	\$15,484.98
		0001	0180	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR $$ 1524 MM X 914 MM)	1.00	0.00	1.00	EA	1.00	\$3,094.00	\$3,094.00
		0001	0190	6149902	MISC.GRATES AND BEARING PLATES (1 FT. X 7 FT. 7 IN.)	2.00	0.00	2.00	EA	2.00	\$2,952.00	\$5,904.00
		0001	0200	6149902	MISC.GRATES AND BEARING PLATES (5 FT. X 7 FT. 7 IN.)	6.00	0.00	6.00	EA	6.00	\$6,188.00	\$37,128.00
		0001	0210	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$7,890.21	\$7,890.21
		0001	0220	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$5,622.00	\$5,622.00
		0001	0230	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	822.00	0.00	822.00	SQYD	822.00	\$14.09	\$11,581.98
		0001	0240	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$7,500.00	\$7,500.00
		0001	0250	7034041	CLASS B-1 CONCRETE (CULVERTS)	18.30	0.00	18.30	CUYD	18.30	\$1,540.92	\$28,198.84
		0001	0260	7061030	REINFORCING STEEL (CULVERTS)	2,820.00	0.00	2,820.00	LB	2,820.00	\$14.55	\$41,031.00
		0001	0270	7250348A	48 IN. PIPE GROUP B	20.00	0.00	20.00	LF	20.00	\$473.80	\$9,476.00
		0001	0280	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	11.00	0.00	11.00	FT	11.00	\$589.22	\$6,481.42
		0001	0290	8025006	MULCHING	0.20	0.00	0.20	ACRE	0.20	\$1,125.93	\$225.19
		0001	0300	8051000A	SEEDING - COOL SEASON GRASSES	1.20	0.00	1.20	ACRE	1.20	\$4,323.56	\$5,188.27
		0001	0310	8061005	ROCK DITCH CHECK	40.00	0.00	40.00	LF	27.00	\$218.49	\$5,899.23
		0001	0320	8061016	SEDIMENT REMOVAL	13.00	0.00	13.00	CUYD	13.00	\$290.09	\$3,771.17
		0001	0330	8061019	SILT FENCE	1,024.00	0.00	1,024.00	LF	700.00	\$2.78	\$1,946.00
		0030	0340	9029902	MISC.POTHOLING UTILITY FACILITIES	20.00	0.00	20.00	EA	0.00	\$2,200.00	\$0.00
					Date as of Report Generated Date							\$432,269.05
240517-F11 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$432,269.05

Revision 3/23/2023 Page 5 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JSL0093

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2022010	REMOVAL OF IMPROVEMENTS	3/26/25	4/2/25	0.10	LS	Northeast corner of 364 and Bennington	8+55		9+97		Includes the curb and part of the rock blanket
0030	2031000	CLASS A EXCAVATION	3/26/25	4/2/25	260.00	CUYD	Northeast corner of 364 and Bennington	7+00		8+69		
0040	2036000	COMPACTING EMBANKMENT	3/26/25	4/2/25	26.00	CUYD	Northeast corner of 364 and Bennington	8+26				Around the inlet
0070	2063500	CULVERT CLEANOUT	3/26/25	4/2/25	2.00	EA	Northeast corner of 364 and Bennington	8+55				Cleaned out the box and 48" circular culvert
0800	2069901	MISC.	3/26/25	4/2/25	0.50	LS	Northeast corner of 364 and Bennington	7+55		8+55		
0110	6071012A	CHAIN-LINK FENCE (60 IN.)	4/1/25	4/2/25	306.00	LF	Northeast corner of 364 and Bennington	7+54		9+60		Posts were installed on 3/31, Fence on 4/1
0120	6071040	DRIVE GATE (CHAIN-LINK)	4/1/25	4/2/25	2.00	EA	Northeast corner of 364 and Bennington	8+92		9+83		Both gates installed today
0130	6085007	PAVED APPROACH, 7 IN.	3/26/25	4/2/25	28.00	SQYD	Northeast corner of 364 and Bennington	325+20.4				26'x5.2'+21'x5' Approach was made shorter than what is called for on the plans due to gate only being 15' wide. The quantity includes the two curbs along the sides of the approach and the curb that the contractor had to replace/pour parallel to the strong
0140	6086004	CONCRETE SIDEWALK, 4 IN.	3/26/25	4/2/25	12.00	SQYD	Northeast corner of 364 and Bennington on Bennington	325+20.4				Measured quantity is 8.333/sdx2 multiplied by 1.44. The measured quantity of eidernality os dievensive was increased by 44% to account for increased costs to the contractor. Contractor poured all sidewalk as 7" instead of 4" as called for on the plans, and laid down dirt and seeded around the approach. MOOT feels that maintenance vehicles may accidentally drive onto the sidewalk thus the increased depth is beneficial to us. NOTE: No inspector was on the site at the time of the pour to tell them to pour or not pour it 7" thick.
0150	6113020	FURNISHING TYPE 2 ROCK BLANKET	3/26/25	4/2/25	239.43	CUYD	Northeast corner of 364 and Bennington	7+54		8+75		Rock blanket for the north side of the channel, around the culvert including wingwall on the south side, and rock going up to the culvert.
			4/1/25	4/2/25	7.84	CUYD	Northeast corner of 364 and Bennington	8+74				4-8" rock placed around the inlet and behind the culvert to act as erosion control. Significant erosion was occurring in these two areas.
0160	6113040	PLACING TYPE 2 ROCK BLANKET	3/26/25	4/2/25	239.43	CUYD	Northeast corner of 364 and Bennington	7+54		8+75		Rock blanket for the north side of the channel, around the culvert including wingwall on the south side, and rock going up to the culvert.
			4/1/25	4/2/25	7.84	CUYD	Northeast corner of 364 and Bennington	8+74				4-8" rock placed around the inlet and behind the culvert t act as erosion control. Significant erosion was occurring in these two areas.
0180	6141024	GRATES AND BEARING PLATES (5 FT X 3 FT)	3/26/25	4/2/25	1.00	EA	Northeast corner of 364 and Bennington					Grate goes on top of the drop inlet
0190	6149902	MISC. DRAINAGE FITTINGS	3/26/25	4/2/25	0.50	EA	Northeast corner of 364 and Bennington	8+55				Grates go on top of the culvert extension walls
0200	6149902	MISC. DRAINAGE FITTINGS	3/26/25	4/2/25	1.50	EA	Northeast corner of 364 and Bennington	8+55				Grates go on top of the culvert extension walls
0210	6169901	MISC.	3/26/25	4/2/25	0.50	LS	Northeast corner of 364 and Bennington					Final, 2nd, half of the traffic control
0250	7034041	CLASS B-1 CONCRETE (CULVERTS)	3/26/25	4/2/25	7.80	CUYD	Northeast corner of 364 and Bennington	8+55				Used for the culvert
0260	7061030	REINFORCING STEEL (CULVERTS)	3/26/25	4/2/25	820.00	LB	Northeast corner of 364 and Bennington	8+55				Used for the culvert
0290	8025006	MULCHING	3/26/25	4/2/25	0.20	ACRE	Northeast corner of 364 and Bennington	7+00		9+97		
0300	8051000A	000A SEEDING - COOL SEASON GRASSES 3/26/25 4/2/25 1.20 ACRE Northeast corner of 364 and Bennington 0+36 9+50		Seeding for under the erosion control mat, around the culvert, and behind the drop inlet								
0320	8061016	SEDIMENT REMOVAL	3/26/25	4/2/25	13.00	CUYD	Northeast corner of 364 and Bennington	7+55				Sediment and wood debris removed from the rock check dams. All debris/sediment was removed when the contractor took out the rock check dams

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 6 of 9



Line Item Adjustments by Estimate

Contract ID: 240517-F11

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
SL0093	0130	PAVED APPROACH, 7 IN.	Material		5	Apr 2, 2025	SYSTEM	\$9,078.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ashtoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					5	Apr 2, 2025	SYSTEM	(\$9,078.44)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0130 -	· Total						\$0.00				
	0140	CONCRETE SIDEWALK, 4 IN.	Material		5	Apr 2, 2025	SYSTEM	\$2,723.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ashtoa1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					5	Apr 2, 2025	SYSTEM	(\$2,723.52)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0140 -	· Total						\$0.00				
			Overs	0	-	Amr C	CVCTC					
	0150	FURNISHING TYPE 2 ROCK BLANKET	Overrun	Overrun		Apr 2, 2025	SYSTEM	(\$2,265.28)				
				Overrun - T	otal			(\$2,265.28)				
			Overrun - T	otal				(\$2,265.28)				
	0150 -	Total						(\$2,265.28)				
	0160	PLACING TYPE 2 ROCK	ACING Overrun Overrun 5 Apr 2, SYSTEM (\$7,469.22)									
		BLANKET		Overrun - T	otal			(\$7,469.22)				
			Overrun - To	otal				(\$7,469.22)				
	0160 -	Total										
								(\$7,469.22)				
	0170	MISC. EMBANKMENT PROTECTION	Material		4	Mar 17, 2025	SYSTEM	\$15,484.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ashtoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					4	Mar 17, 2025	SYSTEM	(\$15,484.98)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0170 -	Total						\$0.00				
	0230	0 PERMANENT EROSION CONTROL	230 PERMANENT EROSION	PERMANENT EROSION CONTROL	EROSION CONTROL	Material		3	Mar 3, 2025	SYSTEM	\$5,636.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ashtoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		CLOTEXTILE			3	Mar 3, 2025	SYSTEM	(\$5,636.00)				
					4	Mar 17, 2025	SYSTEM	\$11,581.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ashtoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					4	Mar 17, 2025	SYSTEM	(\$11,581.98)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0230 -	Total						\$0.00				
	0250	CLASS B-1 CONCRETE	Material		4	Mar 17, 2025	SYSTEM	\$16,179.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ashtoa1 overridding Payment			
		(CULVERTS)			4		SYSTEM	(\$16.470.00)	Estimate item Adjustment (0003) due to user ashiba i overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					Mar 17, 2025		(\$16,179.66)					
					5	Apr 2, 2025	SYSTEM	\$28,198.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ashtoa1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
					5	Apr 2, 2025	SYSTEM	(\$28,198.84)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				



Line Item Adjustments by Estimate

Contract ID: 240517-F11

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
ISL0093	0250 -	Total						\$0.00				
	0280	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		4	Mar 17, 2025	SYSTEM	\$6,481.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ashtoa1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
		FIX3FI			4	Mar 17, 2025	SYSTEM	(\$6,481.42)				
						5	Apr 2, 2025	SYSTEM	\$6,481.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ashtoa1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
							5	Apr 2, 2025	SYSTEM	(\$6,481.42)		
				- Total				\$0.00				
			Material - To	al - Total				\$0.00				
	0280 -	Total						\$0.00				
	0300	COOL	SEASON	COOL SEASON	Material		5	Apr 2, 2025	SYSTEM	\$5,188.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ashtoa1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					5	Apr 2, 2025	SYSTEM	(\$5,188.27)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0300 -	Total						\$0.00				
	0310	ROCK DITCH CHECK				Material		4	Mar 17, 2025	SYSTEM	\$4,369.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ashtoa1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Mar 17, 2025	SYSTEM	(\$4,369.80)				
					5	Apr 2, 2025	SYSTEM	\$4,369.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ashtoa1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					5	Apr 2, 2025	SYSTEM	(\$4,369.80)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0310 -	Total						\$0.00				
SL0093	- Total							(\$9,734.50)				
Overall -	Total						(\$9,734.50)					

MoDOT

Contract Adjustments for Contract - 240517-F11

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 9 of 9