

Missouri Department of Transportation Contractor's Pay Estimate Summary

July 8, 2024

Pay Estimate Created Date: October 16, 2024

Progress Estimate 6	Number	Contract ID Prime Contractor	240517-H06 r Gerstner Electric		y Period Start y Period End			Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,532,103.21 \$0.00 \$1,532,103.21			
Approval Date									By User			
October 16, 2024	tober 16, 2024 Generated and Approved (and should be considered Draft) at the Project Office Leve											
October 16, 2024		Resident Engineer Level by	plottk1									
October 17, 2024	ober 17, 2024 Reviewed and Approved at the Central Office Controllers Office Leve											
Original Complet	ion Date	Current Con	npletion Date	Actu	ial Completion	Date	9/	6 of Current Contract Amoun	t Complete			
December 1, 2	2025	Decembe	er 1, 2025					35.88%				
	Contrac	t Informational Dat	es		Mil	estones						
Date Description	Original	Completion Date	Current Completi	ion Date	No Milestone	s Exist for	Contract					
Acceptance Date												
Awarded Date	June 5, 2	2024	June 5, 2024									
Letting Date	May 17,	2024	May 17, 2024									

Contract Total Pay	y For Estimate No. 6			
		This Estimate	Previous	To Date
240517-H06				
	Total Posted Items Pay	\$100,518.75	\$449,140.86	\$549,659.61
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$449,140.86	\$549,659.61
Contract Total Pay	yable This Estimate:	\$100,518.75		

Items Paid This Estimate Period

Notice to Proceed Date July 8, 2024

Open to Traffic Date
Work Began Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JSE0099	0110	9108810	PULL BOX, PREFORMED CLASS 1	EA	\$1,615.000	2	\$3,230.00
	0120	9108811	PULL BOX, PREFORMED CLASS 2	EA	\$1,845.000	18	\$33,210.00
	0190	9109903	MISC.CONDUIT, 2 IN., HDPE, IN TRENCH	LF	\$9.250	5,470	\$50,597.50
Project JSE009	9 - Total						\$87,037.50
JSE0121	0400	9109903	MISC.CONDUIT, 2 IN., HDPE, DIRECTIONAL DRILLED	LF	\$15.000	750	\$11,250.00
	0410	9109903	MISC.CONDUIT, 2 IN., HDPE, IN TRENCH	LF	\$8.750	255	\$2,231.25
Project JSE012	1 - Total						\$13,481.25
Overall - Total							\$100,518.75

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item /	Adjustr	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSE0099	0020	CONSTRUCTION SIGNS	Material			-80	\$5.00	(\$400.00)
	0020	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user kirchp1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	80	\$5.00	\$400.00
	0110	PULL BOX, PREFORMED CLASS 1	Material			-2	\$1,615.00	(\$3,230.00)

Revision 3/23/2023 Page 1 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2024

Progress Estimate Number	Contract ID		•	,	Original Contract Amount	. , ,
6	Prime Contractor	Gerstner Electric, Inc.	Pay Period End	October 15, 2024	Net Change Order Amount	\$0.00
0					Current Contract Amount	\$1,532,103.21

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSE0099	0110	PULL BOX, PREFORMED CLASS 1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	2	\$1,615.00	\$3,230.00
	0120	PULL BOX, PREFORMED CLASS 2	Material			-42	\$1,845.00	(\$77,490.00)
	0120	PULL BOX, PREFORMED CLASS 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	42	\$1,845.00	\$77,490.00
	0180	MISC.	Material			-1,440	\$22.00	(\$31,680.00)
	0180	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1,440	\$22.00	\$31,680.00
	0190	MISC.	Material			-23,407	\$9.25	(\$216,514.75)
	0190	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user kirchp1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	23,407	\$9.25	\$216,514.75
JSE0121	0340	PULL BOX, PREFORMED CLASS 2	Material			-13	\$1,845.00	(\$23,985.00)
	0340	PULL BOX, PREFORMED CLASS 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user kirchp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	13	\$1,845.00	\$23,985.00
	0400	MISC.	Material			-2,040	\$15.00	(\$30,600.00)
	0400	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user kirchp1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	2,040	\$15.00	\$30,600.00
	0410	MISC.	Material			-11,775	\$8.75	(\$103,031.25)
	0410	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user kirchp1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	11,775	\$8.75	\$103,031.25
Total								\$0.00

Revision 3/23/2023 Page 2 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Con	tract Project Information					
			1		Con	tract Project information					
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work					
JSE0099	FAF 67-3 (145)	ITS maintenance	32, 67, 72	ST FRANCOIS	at various locations along Routes 32, 67 and 72						
JSE0121	FAF-32-3 (28)	ITS maintenance	60,61,51,67,72,I-55	CAPE GIRARDEAU	at various locations along Routes 60, 61, 51, 67, 72 and I-55						
Γotals by J	Job Numbe	rs									
JSE0099		d Item Pay Item Adjustme	ents Gross Item Pay	This Estir \$87,037.5 \$0.00 \$87,037.5	50	Previous \$277,277.25 \$0.00 \$277,277.25		To Date \$364,314.75 \$0.00 \$364,314.75			
				\$0.00 \$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00 \$0.00			
JSE0121		d Item Pay Item Adjustme	ents Gross Item Pay	This Estir \$13,481.2 \$0.00 \$13,481. 2	25	Previous \$171,863.61 \$0.00 \$171,863.61		To Date \$185,344.86 \$0.00 \$185,344.86			
				\$0.00 \$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00 \$0.00			

Revision 3/23/2023 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSE0099, Item 6161005, Project Item Line Number 0020, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	kirchp1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0099, Item 9108810, Project Item Line Number 0110, Material Set 910881096, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	No Remark was entered by Engineer	kirchp1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0099, Item 9108811, Project Item Line Number 0120, Material Set 910881196, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	No Remark was entered by Engineer	kirchp1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0121, Item 9108811, Project Item Line Number 0340, Material Set 910881196, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	No Remark was entered by Engineer	kirchp1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0099, Item 9109903, Project Item Line Number 0180, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	No Remark was entered by Engineer	kirchp1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0099, Item 9109903, Project Item Line Number 0190, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	No Remark was entered by Engineer	kirchp1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0121, Item 9109903, Project Item Line Number 0400, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	No Remark was entered by Engineer	kirchp1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSE0121, Item 9109903, Project Item Line Number 0410, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	No Remark was entered by Engineer	kirchp1	Overridden

Revision 3/23/2023 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q					Report Generated date and can differ from the posted am	ount at the	e time th	e Estimate v	was Ger	erated.			
Contract	Project	Category	Line	Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED	

	Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
	240517-H06	JSE0099	0001	0010	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	0.00	\$2,500.00	\$0.00
			0001	0020	6161005	CONSTRUCTION SIGNS	819.00	0.00	819.00	SQFT	80.00	\$5.00	\$400.00
			0001	0030	6161025	CHANNELIZER (TRIM LINE)	150.00	0.00	150.00	EA	0.00	\$15.00	\$0.00
			0001	0040	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	0.00	\$125.00	\$0.00
			0001	0050	6161033	DIRECTIONAL INDICATOR BARRICADE	28.00	0.00	28.00	EA	0.00	\$25.00	\$0.00
			0001	0060	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.00
			0001	0070	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$35,000.00	\$35,000.00
			0030	0080	9029902	MISC.INSTALL ETHERNET SWITCH AND POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$545.00	\$0.00
			0050	0090	9108208	CABLE, 8 AWG, 1 CONDUCTOR, POWER	900.00	0.00	900.00	LF	0.00	\$2.00	\$0.00
			0050	0100	9108408	WIRE, 8 AWG, BARE NEUTRAL	300.00	0.00	300.00	LF	0.00	\$1.50	\$0.00
			0050	0110	9108810	PULL BOX, PREFORMED CLASS 1	2.00	0.00	2.00	EA	2.00	\$1,615.00	\$3,230.00
			0050	0120	9108811	PULL BOX, PREFORMED CLASS 2	46.00	0.00	46.00	EA	42.00	\$1,845.00	\$77,490.00
			0050	0130	9109902	MISC.CCTV BATTERY BACKUP, POLE MOUNTED	1.00	0.00	1.00	EA	0.00	\$7,850.00	\$0.00
0000 0190 0190902 MISCINSTALL CCTV CONCRETE POLE 1.00 0.00 1.00 EA 0.00 \$8,000 0.00			0050	0140	9109902	MISC.CCTV CAMERA TERMINAL CABINET, POLE MOUNTED	1.00	0.00	1.00	EA	0.00	\$4,725.00	\$0.00
0000			0050	0150	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$1,155.00	\$0.00
			0050	0160	9109902	MISC.INSTALL CCTV CONCRETE POLE	1.00	0.00	1.00	EA	0.00	\$9,100.00	\$0.00
			0050	0170	9109902	MISC.MODIFY EXISTING POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$525.00	\$0.00
			0050	0180	9109903	MISC.CONDUIT, 2 IN., HDPE, DIRECTIONAL DRILLED	1,440.00	0.00	1,440.00	LF	1,440.00	\$22.00	\$31,680.00
			0050	0190	9109903	MISC.CONDUIT, 2 IN., HDPE, IN TRENCH	24,660.00	0.00	24,660.00	LF	23,407.00	\$9.25	\$216,514.75
Project JSE0939 - Total Value Posted to Date as of Report Generated Date			0050	0200	9109903	MISC.CONDUIT, 2 IN., HDPE, ON STRUCTURE	460.00	0.00	460.00	LF	0.00	\$20.00	\$0.00
USEO121 0001 0220 6123001 TRUCK MOUNTED ATTENUATOR (TMA) 1.00 0.00 1.00 LS 0.00 \$2,500.00 \$0.0			0050	0210	9109903	MISC.FIBER OPTIC CABLE, 24-FIBER SINGLE MODE	29,040.00	0.00	29,040.00	LF	0.00	\$2.50	\$0.00
0001 0230 6161036 CONSTRUCTION SIGNS 819.00 0.00 819.00 SOFT 0.00 \$5.00 \$0.00		Project JS	SE0099 - To	otal Value	Posted to	Date as of Report Generated Date							\$364,314.75
0001 0240 6161025 CHANNELIZER (TRIM LINE) 150.00 0.00 150.00 EA 0.00 \$15.00 \$0.0		JSE0121	0001	0220	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	0.00	\$2,500.00	\$0.00
001 025 616130 TYPE III MOVEABLE BARRICADE 6.00 0.00 6.00 EA 0.00 \$125.00 \$0.00			0001	0230	6161005	CONSTRUCTION SIGNS	819.00	0.00	819.00	SQFT	0.00	\$5.00	\$0.00
0001 0260 6161033 DIRECTIONAL INDICATOR BARRICADE 28.00 0.00 28.00 EA 0.00 \$25.00 \$0.00			0001	0240	6161025	CHANNELIZER (TRIM LINE)	150.00	0.00	150.00	EA	0.00	\$15.00	\$0.00
0001 0270 6161040 FLASHING ARROW PANEL 2.00 0.00 2.00 EA 0.00 \$250.00 \$0			0001	0250	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	0.00	\$125.00	\$0.00
0001 0280 6181000 MOBILIZATION 1.00 0.00 1.00 LS 0.50 \$55,457.21 \$27,728.80			0001	0260	6161033	DIRECTIONAL INDICATOR BARRICADE	28.00	0.00	28.00	EA	0.00	\$25.00	\$0.00
0330 0290 9029902 MISC.INSTALL ETHERNET SWITCH AND POWER SUPPLY 8.00 0.00 8.00 EA 0.00 \$545.00 \$0.00 0050 0300 9108208 CABLE, 8 AWG, 1 CONDUCTOR, POWER 113.40.00 0.00 11,340.00 LF 0.00 \$1.60 \$0.00 0050 0310 9108208 CABLE, 8 AWG, BARE NEUTRAL 3,780.00 0.00 3,780.00 LF 0.00 \$1.50 \$0.00 0050 0310 9108208 WIRE, 8 AWG, BARE NEUTRAL 3,780.00 0.00 3,780.00 LF 0.00 \$1.50 \$0.00 0050 0320 910821 POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE. 1.00 0.00 1.00 EA 0.00 \$6,570.00 \$0.00 0050 0330 9108810 PULL BOX, PREFORMED CLASS 1 15.00 0.00 15.00 EA 0.00 \$1,815.00 \$0.00 0050 0340 9108811 PULL BOX, PREFORMED CLASS 2 74.00 0.00 74.00 EA 13.00 \$1,845.00 \$23,985.00 0050 0350 9109902 MISC.CCTV BATTERY BACKUP, POLE MOUNTED 10.00 0.00 10.00 EA 0.00 \$7,850.00 \$0.00 0050 0350 9109902 MISC.CCTV CAMERA TERMINAL CABINET, POLE MOUNTED 10.00 0.00 10.00 EA 0.00 \$4,725.00 \$0.00 0050 0350 9109902 MISC.INSTALL CCTV CAMERA ASSEMBLY 10.00 0.00 10.00 EA 0.00 \$1,150.00 \$0.00 0050 0350 9109902 MISC.INSTALL CCTV CAMERA ASSEMBLY 10.00 0.00 10.00 EA 0.00 \$1,150.00 \$0.00 0050 0350 9109902 MISC.INSTALL CCTV CAMERA SSEMBLY 10.00 0.00 10.00 EA 0.00 \$1,150.00 \$0.00 0050 0350 9109902 MISC.INSTALL CCTV CONCRETE POLE 10.00 0.00 10.00 EA 0.00 \$1,150.00 \$0.00 0050 0350 9109902 MISC.INSTALL CCTV CONCRETE POLE 10.00 0.00 10.00 EA 0.00 \$1,150.00 \$0.00 0050 0350 9109902 MISC.INSTALL CCTV CONCRETE POLE 10.00 0.00 10.00 EA 0.00 \$1,150.00 \$0.00 0050 0350 9109902 MISC.CONDUIT, 2 IN, HDPE, DIRECTIONAL DRILLED 6,460.00 0.00 6,460.00 LF 2,040.00 \$150.00 \$30,600.00 0050 0400 9109903 MISC.CONDUIT, 2 IN, HDPE, DIRECTIONAL DRILLED 6,460.00 0.00 460.00 LF 11,775.00 \$8.75 \$103,031.25 0050 0420 9109903 MISC.CONDUIT, 2 IN, HDPE, DIRECTIONAL DRILLED 6,460.00 0.00 460.00 LF 11,775.00 \$8.75 \$103,031.25 0050 0420 9109903 MISC.CONDUIT, 2 IN, HDPE, DIRECTIONAL DRILLED 6,460.00 0.00 460.00 LF 0.00 \$0.00			0001	0270	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.00
0050 0300 9108208 CABLE, 8 AWG, 1 CONDUCTOR, POWER 11,340.00 0.00 11,340.00 LF 0.00 \$1.60 \$0.00 0.00 0.00 0.00 0.00 0.00 0.00			0001	0280	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$55,457.21	\$27,728.60
0050 0310 9108408 WIRE, 8 AWG, BARE NEUTRAL 3,780.00 0.00 3,780.00 LF 0.00 \$1.50 \$0.00 \$0.00 \$0.00 \$1.50 \$0.50 \$1.50 \$0.50 \$1.50 \$0.50 \$1.50 \$0.50 \$1.50 \$0.50 \$1.50 \$0.50 \$1.50 \$0.50 \$1.			0030	0290	9029902	MISC.INSTALL ETHERNET SWITCH AND POWER SUPPLY	8.00	0.00	8.00	EA	0.00	\$545.00	\$0.00
0050 0320 9108621 POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, 1.00 0.00 1.00 EA 0.00 \$6,570.00 \$0.00			0050	0300	9108208	CABLE, 8 AWG, 1 CONDUCTOR, POWER	11,340.00	0.00	11,340.00	LF	0.00	\$1.60	\$0.00
ITS			0050	0310	9108408	WIRE, 8 AWG, BARE NEUTRAL	3,780.00	0.00	3,780.00	LF	0.00	\$1.50	\$0.00
0050 0330 9108810 PULL BOX, PREFORMED CLASS 1 15.00 0.00 15.00 EA 0.00 \$1,615.00 \$0.00			0050	0320	9108621		1.00	0.00	1.00	EA	0.00	\$6,570.00	\$0.00
0050 0350 9109902 MISC.CCTV BATTERY BACKUP, POLE MOUNTED 10.00 0.00 10.00 EA 0.00 \$7,850.00 \$0.00 0050 0360 9109902 MISC.CCTV CAMERA TERMINAL CABINET, POLE MOUNTED 10.00 0.00 10.00 EA 0.00 \$4,725.00 \$0.00 0050 0370 9109902 MISC.INSTALL CCTV CAMERA ASSEMBLY 10.00 0.00 10.00 EA 0.00 \$1,150.00 \$0.00 0050 0380 9109902 MISC.INSTALL CCTV CONCRETE POLE 10.00 0.00 10.00 EA 0.00 \$9,100.00 \$0.00 0050 0390 9109902 MISC.MODIFY EXISTING POWER SUPPLY 9.00 0.00 9.00 EA 0.00 \$525.00 \$0.00 0050 0400 9109903 MISC.CONDUIT, 2 IN., HDPE, DIRECTIONAL DRILLED 6,460.00 0.00 6,460.00 LF 2,040.00 \$15.00 \$30,600.00 0050 0410 9109903 MISC.CONDUIT, 2 IN., HDPE, IN TRENCH 32,310.00 0.00 32,310.00 LF 11,775.00 \$8.75 \$103,031.25 0050 0420 9109903 MISC.CONDUIT, 2 IN., HDPE, ON STRUCTURE 460.00 0.00 460.00 LF 0.00 \$20.00 \$0.00 \$0.00 0050 0430 9109903 MISC.FIBER OPTIC CABLE, 24-FIBER SINGLE MODE 41,390.00 0.00 41,390.00 LF 0.00 \$3.55 \$0.00 \$0.00 \$15,00 \$3.55 \$0.00 \$0.00 \$0.00 \$15,00 \$3.55 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$15,00 \$3.55 \$0.00 \$0			0050	0330	9108810	PULL BOX, PREFORMED CLASS 1	15.00	0.00	15.00	EA	0.00	\$1,615.00	\$0.00
0050 0360 9109902 MISC.CCTV CAMERA TERMINAL CABINET, POLE MOUNTED 10.00 0.00 10.00 EA 0.00 \$4,725.00 \$0.00 \$			0050	0340	9108811	PULL BOX, PREFORMED CLASS 2	74.00	0.00	74.00	EA	13.00	\$1,845.00	\$23,985.00
0050 0370 9109902 MISC.INSTALL CCTV CAMERA ASSEMBLY 10.00 0.00 10.00 EA 0.00 \$1,150.00 \$0.			0050	0350	9109902	MISC.CCTV BATTERY BACKUP, POLE MOUNTED	10.00	0.00	10.00	EA	0.00	\$7,850.00	\$0.00
0050 0380 9109902 MISC.INSTALL CCTV CONCRETE POLE 10.00 0.00 10.00 EA 0.00 \$9,100.00 \$0.00			0050	0360	9109902	MISC.CCTV CAMERA TERMINAL CABINET, POLE MOUNTED	10.00	0.00	10.00	EA	0.00	\$4,725.00	\$0.00
0050 0390 9109902 MISC.MODIFY EXISTING POWER SUPPLY 9.00 0.00 9.00 EA 0.00 \$525.00 \$0.00 \$0.00 0050 0400 9109903 MISC.CONDUIT, 2 IN., HDPE, DIRECTIONAL DRILLED 6,460.00 0.00 6,460.00 LF 2,040.00 \$15.00 \$30,600.00 0050 0410 9109903 MISC.CONDUIT, 2 IN., HDPE, IN TRENCH 32,310.00 0.00 32,310.00 LF 11,775.00 \$8.75 \$103,031.25 0050 0420 9109903 MISC.CONDUIT, 2 IN., HDPE, ON STRUCTURE 460.00 0.00 460.00 LF 0.00 \$20.00 \$0.00 0050 0430 9109903 MISC.FIBER OPTIC CABLE, 24-FIBER SINGLE MODE 41,390.00 0.00 41,390.00 LF 0.00 \$3.55 \$0.00 0050 0430 9109903 MISC.FIBER OPTIC CABLE, 24-FIBER SINGLE MODE 41,390.00 0.00 41,390.00 LF 0.00 \$3.55 \$0.00 0050 0450 050 050 050 050 050 050 050			0050	0370	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$1,150.00	\$0.00
0050 0400 9109903 MISC.CONDUIT, 2 IN., HDPE, DIRECTIONAL DRILLED 6,460.00 0.00 6,460.00 LF 2,040.00 \$15.00 \$30,600.00 0050 0410 9109903 MISC.CONDUIT, 2 IN., HDPE, IN TRENCH 32,310.00 0.00 32,310.00 LF 11,775.00 \$8.75 \$103,031.25 0050 0420 9109903 MISC.CONDUIT, 2 IN., HDPE, ON STRUCTURE 460.00 0.00 460.00 LF 0.00 \$20.00 \$0.00 0050 0430 9109903 MISC.FIBER OPTIC CABLE, 24-FIBER SINGLE MODE 41,390.00 0.00 41,390.00 LF 0.00 \$3.55 \$0.00 Project JSE0121 - Total Value Posted to Date as of Report Generated Date \$185,344.86			0050	0380	9109902	MISC.INSTALL CCTV CONCRETE POLE	10.00	0.00	10.00	EA	0.00	\$9,100.00	\$0.00
0050 0410 9109903 MISC.CONDUIT, 2 IN., HDPE, IN TRENCH 32,310.00 0.00 32,310.00 LF 11,775.00 \$8.75 \$103,031.25 \$0050 0420 9109903 MISC.CONDUIT, 2 IN., HDPE, ON STRUCTURE 460.00 0.00 460.00 LF 0.00 \$20.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$10,000 \$0.0			0050	0390	9109902	MISC.MODIFY EXISTING POWER SUPPLY	9.00	0.00	9.00	EA	0.00	\$525.00	\$0.00
0050 0420 9109903 MISC.CONDUIT, 2 IN., HDPE, ON STRUCTURE 460.00 0.00 460.00 LF 0.00 \$20.00 \$0.0			0050	0400	9109903	MISC.CONDUIT, 2 IN., HDPE, DIRECTIONAL DRILLED	6,460.00	0.00	6,460.00	LF	2,040.00	\$15.00	\$30,600.00
0050 0430 9109903 MISC.FIBER OPTIC CABLE, 24-FIBER SINGLE MODE 41,390.00 0.00 41,390.00 LF 0.00 \$3.55 \$0.00 Project JSE0121 - Total Value Posted to Date as of Report Generated Date \$185,344.86			0050	0410	9109903	MISC.CONDUIT, 2 IN., HDPE, IN TRENCH	32,310.00	0.00	32,310.00	LF	11,775.00	\$8.75	\$103,031.25
Project JSE0121 - Total Value Posted to Date as of Report Generated Date \$185,344.86			0050	0420	9109903	MISC.CONDUIT, 2 IN., HDPE, ON STRUCTURE	460.00	0.00	460.00	LF	0.00	\$20.00	\$0.00
			0050	0430	9109903	MISC.FIBER OPTIC CABLE, 24-FIBER SINGLE MODE	41,390.00	0.00	41,390.00	LF	0.00	\$3.55	\$0.00
		Project JS	SE0121 - To	otal Value	Posted to	Date as of Report Generated Date							\$185,344.86
40517-H06 Overall - Total Value Posted to Date as of Report Generated Date \$549,659.60 vision 3/23/2023 Page 5 of 10			Value Post	ted to Dat	te as of Rep	port Generated Date							\$549,659.60



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

$\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Project: JSE0099

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0110	9108810	PULL BOX, PREFORMED CLASS 1	10/2/24	10/16/24	1.00	EA	Site 3- St. Genevieve, St. Genevieve County	5.302 Hwy 32				Pull Box 12
				10/16/24	1.00	EA	Site 3- St. Genevieve, St. Genevieve County	5.342 Hwy 32				Pull Box 11
0120	9108811	PULL BOX, PREFORMED CLASS 2	9/30/24	10/16/24	1.00	EA	Site 3, St. Genevieve, St. Genevieve County	5.322 Hwy 32				Pull Box 10
				10/16/24	1.00	EA	Site 3, St. Genevieve, St. Genevieve County	5.340 Hwy 32				Pull Box 9
				10/16/24	1.00		Site 3, St. Genevieve, St. Genevieve County	5.540 Hwy 32				Pull Box 5
				10/16/24	1.00		Site 3, St. Genevieve, St. Genevieve County	5.543 Hwy 32				Pull Box 4
			10/1/24	10/16/24	1.00	EA	Site 3, St. Genevieve, St. Genevieve County	150.319 I55				Pull Box 6
				10/16/24	1.00	EA	Site 3, St. Genevieve, St. Genevieve County	150.321 I55				Pull Box 8
				10/16/24	1.00		Site 3, St. Genevieve, St. Genevieve County	5.724 Hwy 32				Pull Box 3
				10/16/24	1.00		Site 3, St. Genevieve, St. Genevieve County	6.083 Hwy 32				Pull Box 1
			10/7/24	10/16/24	1.00		Site 1- Leadington, St. Francois County PB 7	90.944 Hwy 67				
				10/16/24	1.00		Site 1-Leadington, St. Francois County PB 4	90.599 Hwy 67				
			10/8/24	10/16/24	1.00		Site 1- Leadington, St. Francois County PB 3	90.416 Hwy 67				
				10/16/24	1.00		Site 1- Leadington, St. Francois County PB 5	90.803 Hwy 67				
			10/9/24	10/16/24	1.00		Site 1- Leadington, St. Francois County Hwy 32	3.782 Hwy 32				
				10/16/24	1.00		Site 1- Leadington, St. Francois County PB 13	91.743 Hwy 67				
				10/16/24	1.00		Site 1- Leadington, St. Francois County PB 15	3.771 Hwy 32				
			10/10/24	10/16/24	1.00		Site 1- Leadington, St. Francois County PB 11	91.444 Hwy 67				
				10/16/24	1.00		Site 1- Leadington, St. Francois County PB 8	91.279 Hwy 67				
				10/16/24	1.00		Site 1- Leadington, St. Francois County PB 9	91.279 Hwy 67				
0190	9109903	MISC. ITS		10/16/24	200.00		Site 1, Leadington, St. Francois County PB 4 to PB 5					
				10/16/24	260.00		Site 1-Leadington, St. Francois County between PB 4 and PB 5					
			10/2/24	10/16/24	1,900.00		Site 1- Leadington, St. Francois County Pull Box 12 to Pull Box 14					
				10/16/24	400.00		Site 1-Leadington, St. Francois County Pull Box 4 to Pull Box 5					
			10/7/24	10/16/24	210.00		Site 1- Leadington, St. Francois County PB 3 to PB 4					
			40/0/5	10/16/24	500.00		Site 1- Leadington, St. Francois County PB 6 to PB 7					
				10/16/24	650.00		Site 1- Leadington, St. Francois County between PB 8 and PB 9					
				10/16/24	700.00		Site 1- Leadington, St. Francois County between PB 11 and PB 12					
			10/9/24	10/16/24	650.00	LF	Site 1- Leadington, St. Francois County PB 10 to PB 11					

Project: JSE0121

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0400	9109903	MISC. ITS	10/1/24	10/11/24	120.00	LF	Route 61 Southbound, Cape Girardeau County	286.942	RT	286.942	LT	Drilled conduit from Pull Box 1 to Pull Box 2
				10/11/24	150.00	LF	Route 61 Southbound, Cape Girardeau County	286.942	LT	286.967	LT	Drilled conduit from Pull Box 2 to Pull Box 3
			10/2/24	10/11/24	20.00	LF	Route 61 Southbound, Cape Girardeau County	286.97	LT			Conduit drilled from Pull Box 4 to existing Pull Box
			10/7/24	10/11/24	80.00	LF	Route 72 Westbound, Cape Girardeau County, Site #2A	3.516	RT	3.502	RT	Conduit drilled from CCTV Pole to Existing Pull Box
				10/11/24	110.00	LF	Route 72 Westbound, Cape Girardeau County, Site #2A	3.516	LT	3.516	RT	Conduit drilled from Pull Box 2 to Pul Box 3
			10/8/24	10/16/24	30.00	LF	MO 25 Northbound, Southwest corner of MO 25 and MO 72	91.174	LT	91.17	LT	Conduit drilled from Pull Box 1 to Pull Box 2
				10/16/24	120.00	LF	MO 25 Northbound, Southeast corner of MO 25 and MO 61 to Southwest corner of MO 25 and MO 72	91.085	RT	91.17	LT	Conduit drilled from Pull Box 4 to Existing Pull Box near Pull Box 2
				10/16/24	120.00	LF	MO 25 Northbound, Southwest corner of MO 25 and MO 72 to Southeast corner of MO 25 and MO 61	91.17	LT	91.085	RT	Conduit drilled from Pull Box 2 to Pull Box 3
0410	9109903	MISC. ITS	10/7/24	10/11/24	110.00	LF	Route 61 Northbound, Cape Girardeau County, Site #2C	113.607	RT	113.627	RT	conduit trenched from Pull Box 2 to Pull Box 1
				10/11/24	110.00	LF	Route 61 Northbound, Cape Girardeau County, Site #2C	113.627	RT	113.607	RT	conduit trenched from CCTV Pole to Existing Pull Box
			10/8/24	10/16/24	35.00	LF	MO 25 Northbound, Southwest corner of MO 25 and MO 72	91.174	LT	91.17	RT	Conduit trenched from Pull Box 1 to Pull Box 2

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 6 of 10



Line Item Adjustments by Estimate

Contract ID: 240517-H06

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
99	0020	CONSTRUCTION SIGNS	Material		2	Aug 16, 2024	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$400.00)	
					3	Sep 3, 2024	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$400.00)	
					4	Sep 16, 2024	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$400.00)	
					5	Oct 1, 2024	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$400.00)	
					6	Oct 16, 2024	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kirchp1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$400.00)	
				- Total				\$0.00	
			Material - To	[otal				\$0.00	
	0020 -	Total						\$0.00	
•	0110	PULL BOX, PREFORMED CLASS 1	Material		6	Oct 16, 2024	SYSTEM	\$3,230.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$3,230.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0110 -	Total) - Total						
		PULL BOX, PREFORMED CLASS 2							
1	0120	PREFORMED	Material		3	Sep 3, 2024	SYSTEM	\$16,605.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	0120	PREFORMED	Material		3		SYSTEM	\$16,605.00 (\$16,605.00)	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment
	0120	PREFORMED	Material			2024 Sep 3,			Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
	0120	PREFORMED	Material		3	2024 Sep 3, 2024 Sep 16,	SYSTEM	(\$16,605.00)	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment
	0120	PREFORMED	Material		3	2024 Sep 3, 2024 Sep 16, 2024 Sep 16,	SYSTEM SYSTEM	(\$16,605.00) \$42,435.00	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment
	0120	PREFORMED	Material		3 4	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM	(\$16,605.00) \$42,435.00 (\$42,435.00)	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment
	0120	PREFORMED	Material		3 4 4 5	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$16,605.00) \$42,435.00 (\$42,435.00) \$44,280.00	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
	0120	PREFORMED	Material		3 4 4 5	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1, 2024 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$16,605.00) \$42,435.00 (\$42,435.00) \$44,280.00	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment
	0120	PREFORMED	Material	- Total	3 4 4 5 5 6	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$16,605.00) \$42,435.00 (\$42,435.00) \$44,280.00 (\$44,280.00) \$77,490.00	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment
	0120	PREFORMED	Material Material - To		3 4 4 5 5 6	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$16,605.00) \$42,435.00 (\$42,435.00) \$44,280.00 (\$44,280.00) \$77,490.00	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment
	0120	PREFORMED CLASS 2			3 4 4 5 5 6	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$16,605.00) \$42,435.00 (\$42,435.00) \$44,280.00 (\$44,280.00) \$77,490.00 (\$77,490.00)	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment
		PREFORMED CLASS 2	Material - To		3 4 4 5 5 6	2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$16,605.00) \$42,435.00 (\$42,435.00) \$44,280.00 (\$44,280.00) \$77,490.00 (\$77,490.00) \$0.00	Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment Estimate Item Adjustment (0003) due to user kirchp1 overridding Payment



Line Item Adjustments by Estimate

Contract ID: 240517-H06

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSE0099	0180	MISC. ITS	Material - To		2	Aug 16, 2024	SYSTEM	\$26,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$26,400.00)	
					3	Sep 3, 2024	SYSTEM	\$32,670.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$32,670.00)	
					4	Sep 16, 2024	SYSTEM	\$31,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kirchp1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$31,680.00)	
				- Total	5	Oct 1, 2024	SYSTEM	\$31,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$31,680.00)	
					6	Oct 16, 2024	SYSTEM	\$31,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kirchp1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$31,680.00)	
								\$0.00	
				otal				\$0.00	
			Overrun	Overrun	3	Sep 3, 2024	SYSTEM	(\$990.00)	
					4	Sep 16, 2024	SYSTEM	\$990.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',22.00000 - 22.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T		otal			\$0.00 \$0.00	
	0180 -	Total	Overrun - T		otal				
	0180 -	Total MISC. ITS	Overrun - T		otal	Aug 2, 2024	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
							SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment
					1	2024 Aug 2,		\$0.00 \$0.00 \$5,550.00	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment
					1	Aug 2, 2024 Aug 16,	SYSTEM	\$0.00 \$0.00 \$5,550.00 (\$5,550.00)	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment
					1 2	Aug 2, 2024 Aug 16, 2024 Aug 16,	SYSTEM	\$0.00 \$0.00 \$5,550.00 (\$5,550.00) \$104,155.00	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment
					1 2 2	Aug 2, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3,	SYSTEM SYSTEM	\$0.00 \$0.00 \$5,550.00 (\$5,550.00) \$104,155.00 (\$104,155.00)	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment
					1 2 2 3	Aug 2, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,550.00 (\$5,550.00) \$104,155.00 (\$104,155.00) \$159,812.25	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment
					1 2 2 3 3	2024 Aug 2, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,550.00 (\$5,550.00) \$104,155.00 (\$104,155.00) \$159,812.25 (\$159,812.25)	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kirchp1 overridding Payment Estimate Item Adjustment (0005) due to user kirchp1 overridding Payment
					1 1 2 2 3 3 3 4	2024 Aug 2, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,550.00 (\$5,550.00) \$104,155.00 (\$104,155.00) \$159,812.25 (\$159,812.25) \$164,344.75	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kirchp1 overridding Payment Estimate Item Adjustment (0005) due to user kirchp1 overridding Payment
					1 1 2 2 3 3 4 4 4	2024 Aug 2, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,550.00 (\$5,550.00) \$104,155.00 (\$104,155.00) \$159,812.25 (\$159,812.25) \$164,344.75	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kirchp1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.
					1 1 2 2 3 3 4 4 5 5	2024 Aug 2, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,550.00 (\$5,550.00) \$104,155.00 (\$104,155.00) \$159,812.25 (\$159,812.25) \$164,344.75 (\$164,344.75) \$165,917.25	Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kirchp1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.



Line Item Adjustments by Estimate

Contract ID: 240517-H06

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSE0099	0190	MISC. ITS	Material	- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
JSE0099 -	Total							\$0.00	
JSE0121	0340	PULL BOX, PREFORMED CLASS 2	Material		5	Oct 1, 2024	SYSTEM	\$23,985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$23,985.00)	
					6	Oct 16, 2024	SYSTEM	\$23,985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kirchp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$23,985.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0340 -	Total						\$0.00	
	0400	MISC. ITS	Material		4	Sep 16, 2024	SYSTEM	\$16,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kirchp1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$16,950.00)	
					5	Oct 1, 2024	SYSTEM	\$19,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$19,350.00)	
					6	Oct 16, 2024	SYSTEM	\$30,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kirchp1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$30,600.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0400 -	Total						\$0.00	
	0410	MISC. ITS	Material		4	Sep 16, 2024	SYSTEM	\$35,428.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kirchp1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$35,428.75)	
					5	Oct 1, 2024	SYSTEM	\$100,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$100,800.00)	
					6	Oct 16, 2024	SYSTEM	\$103,031.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kirchp1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$103,031.25)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0410 -	Total						\$0.00	
JSE0121 -	Total							\$0.00	
Overall -	Γotal							\$0.00	

MoDOT

Contract Adjustments for Contract - 240517-H06

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 10 of 10