

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 18, 2025

		<u> </u>						
Progress Estimate Number 9			17-H08 Electric, Inc.	Pay Perio		August 2, 2025 August 15, 2025	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,510,875.3 \$0.0 \$1,510,875.3
Approval Date								By User
August 18, 2025			Generated	d and Approve	ed (and sl	nould be considered	d Draft) at the Project Office Level by	thomar1
August 18, 2025		ft) at the Resident Engineer Level by	stottt1					
August 20, 2025		tral Office Controllers Office Level by	ramses1					
Original Completion	on Date	Current Co	% of Current Contract Amour	nt Complete				
November 1, 2	025	Novem	ber 1, 2025				70.24%	
	Co	ontract Informat	ional Dates				Milestones	
Date Description	Original Co	ompletion Date	Current Com	pletion Date		No Miles	tones Exist for Contract	
Acceptance Date								
Awarded Date	June 5, 202	14	June 5, 2024					
Letting Date	May 17, 202	24	May 17, 2024					
Notice to Proceed Date	July 8, 2024	1	July 8, 2024					
Work Began Date	April 10, 20	25	April 10, 2025	5				

Contract Total Pay	y For Estimate No. 9			
		This Estimate	Previous	To Date
240517-H08				
	Total Posted Items Pay	\$134,353.35	\$926,859.93	\$1,061,213.28
	Gross Item Adjustments	(\$1,125.00)	(\$12,450.00)	(\$13,575.00)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$914,409.93	\$1,047,638.28
<b>Contract Total Pay</b>	yable This Estimate:	\$133,228.35		

Project	Line	Item	Item Description	Unit	Unit Price	Current Installed	Current Installed
Number	Number	Code				Qty	Amount
SE0169	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$20,000.000	0.300	\$6,000.0
	0050	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$35,000.000	0.100	\$3,500.00
	0060	8025006	MULCHING	ACRE	\$5,000.000	0.150	\$750.00
	0800	8051000A	SEEDING - COOL SEASON GRASSES	ACRE	\$2,500.000	0.150	\$375.00
	0120	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	EA	\$3,123.000	6	\$18,738.00
	0130	9011115	BRACKET ARM, 15 FT. OR 4.6 M	EA	\$1,211.000	6	\$7,266.00
	0140	9011313	LUMINAIRE, LED-C	EA	\$373.000	9	\$3,357.00
	0150	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	EA	\$9,750.000	1	\$9,750.00
	0160	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	LF	\$19.000	39	\$741.00
	0170	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	LF	\$30.000	22	\$660.00
	0180	9014003	CONDUIT, 3 IN. RIGID, PUSHED	LF	\$30.000	765	\$22,950.00
	0190	9015010	TRENCHING TYPE I	LF	\$10.000	2,185	\$21,850.00
	0200	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$1,232.000	9	\$11,088.00
	0210	9016112	PULL BOX, PREFORMED CLASS 3	EA	\$2,303.000	1	\$2,303.00
	0220	9017002	CABLE, 2 AWG 1 CONDUCTOR	LF	\$3.750	153	\$573.75
	0230	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	LF	\$0.980	720	\$705.60
	0250	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	LF	\$4.600	3,130	\$14,398.00
	0260	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	EA	\$1,558.000	6	\$9,348.00
roject JSE0	169 - Total						\$134,353.35

Revision 5/29/2025 Page 1 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 18, 2025

Progress Estimate Number 9

Contract ID 240517-H08 Koch Electric, Inc. Pay Period Start Pay Period End Pay Peri

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSE0169	0060	MULCHING	Material			-1.31000	\$5,000.00	(\$6,550.00)
	0060	MULCHING	MaterialCredit			1.16000	\$5,000.00	\$5,800.00
	0070	TURF TYPE TALL FESCUE SODDING	Material			-25	\$150.00	(\$3,750.00)
	0070	TURF TYPE TALL FESCUE SODDING	MaterialCredit			25	\$150.00	\$3,750.00
	0800	SEEDING - COOL SEASON GRASSES	Material			-1.31000	\$2,500.00	(\$3,275.00)
	0800	SEEDING - COOL SEASON GRASSES	MaterialCredit			1.16000	\$2,500.00	\$2,900.00
Total								(\$1,125.00)

Revision 5/29/2025 Page 2 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	ontract Project Informa	tion
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
JSE0169	FAS S705(28)	Lighting improvements	60, 63, 67, PP	BUTLER	at various locations in th	e Southeast District	
Totals b	y Job Nu	umbers					
JSE0169		d Item Pay Item Adjustme		tem Pay	This Estimate \$134,353.35 (\$1,125.00) \$133,228.35	Previous \$926,859.93 (\$12,450.00) \$914,409.93	To Date \$1,061,213.28 (\$13,575.00) <b>\$1,047,638.28</b>
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 5/29/2025 Page 3 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSE0169, Item 8025006, Project Item Line Number 0060, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Have not received the certification from contractor.	thomar1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project JSE0169, Item 8031000A, Project Item Line Number 0070, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is insufficient.	Have not received the certification from contractor.	thomar1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project JSE0169, Item 8051000A, Project Item Line Number 0080, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Have not received the certification from contractor.	thomar1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project JSE0169, Item 8051000A, Project Item Line Number 0080, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Have not received the certification from contractor.	thomar1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project JSE0169, Item 8051000A, Project Item Line Number 0080, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Have not received the certification from contractor.	thomar1	Acknowledged

Revision 5/29/2025 Page 4 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ntract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0517-	JSE0169	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.70	\$20,000.00	\$14,000.00
18		0001	0020	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.00
		0001	0030	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$65,000.00	\$48,750.00
		0001	0040	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$50,000.00	\$50,000.00
		0001	0050	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.80	\$35,000.00	\$28,000.00
		0001	0060	8025006	MULCHING	1.70	0.00	1.70	ACRE	1.31	\$5,000.00	\$6,550.00
		0001	0070	8031000A	TURF TYPE TALL FESCUE SODDING	25.00	0.00	25.00	SQYD	25.00	\$150.00	\$3,750.00
		0001	0800	8051000A	SEEDING - COOL SEASON GRASSES	1.70	0.00	1.70	ACRE	1.31	\$2,500.00	\$3,275.00
		0001	0090	8061005	ROCK DITCH CHECK	500.00	0.00	500.00	LF	0.00	\$10.00	\$0.00
		0001	0100	8061019	SILT FENCE	1,000.00	0.00	1,000.00	LF	0.00	\$4.50	\$0.00
		0020	0110	9011010	RELOCATED POLE	1.00	0.00	1.00	EA	1.00	\$5,500.00	\$5,500.00
		0020	0120	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	76.00	0.00	76.00	EA	49.00	\$3,123.00	\$153,027.00
		0020	0130	9011115	BRACKET ARM, 15 FT. OR 4.6 M	76.00	0.00	76.00	EA	49.00	\$1,211.00	\$59,339.00
		0020	0140	9011313	LUMINAIRE, LED-C	96.00	0.00	96.00	EA	71.00	\$373.00	\$26,483.00
		0020	0150	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	17.00	0.00	17.00	EA	14.00	\$9,750.00	\$136,500.00
		0020	0160	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	666.00	0.00	666.00	LF	526.00	\$19.00	\$9,994.00
		0020	0170	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	645.00	0.00	645.00	LF	478.00	\$30.00	\$14,340.00
		0020	0180	9014003	CONDUIT, 3 IN. RIGID, PUSHED	5,610.00	0.00	5,610.00	LF	4,470.00	\$30.00	\$134,100.00
		0020	0190	9015010	TRENCHING TYPE I	10,336.00	0.00	10,336.00	LF	4,761.00	\$10.00	\$47,610.00
		0020	0200	9016110	PULL BOX, PREFORMED CLASS 1	67.00	0.00	67.00	EA	52.00	\$1,232.00	\$64,064.00
		0020	0210	9016112	PULL BOX, PREFORMED CLASS 3	19.00	0.00	19.00	EA	16.00	\$2,303.00	\$36,848.00
		0020	0220	9017002	CABLE, 2 AWG 1 CONDUCTOR	2,750.00	0.00	2,750.00	LF	2,130.00	\$3.75	\$7,987.50
		0020	0230	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	8,910.00	0.00	8,910.00	LF	5,761.00	\$0.98	\$5,645.78
		0020	0240	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	5,760.00	0.00	5,760.00	LF	0.00	\$5.40	\$0.00
		0020	0250	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	12,990.00	0.00	12,990.00	LF	9,650.00	\$4.60	\$44,390.00
		0020	0260	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	77.00	0.00	77.00	EA	50.00	\$1,558.00	\$77,900.00
		0020	0270	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	5.00	0.00	5.00	EA	3.00	\$17,720.00	\$53,160.00
	Project JS	SE0169 - To	tal Value	Posted to E	Date as of Report Generated Date							\$1,061,213.28
0517-H	08 Overall	- Total Val	ue Poste	d to Date as	of Report Generated Date							\$1,061,213.28

Revision 5/29/2025 Page 5 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JSE0169

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
010	2022010	REMOVAL OF IMPROVEMENTS	8/14/25	8/14/25	1	0.30	LS	Locations 21-27	0		0		
050	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	8/14/25	8/14/25	1	0.10	LS	Paid up to location 28	0		0		
060	8025006	MULCHING	8/7/25	8/11/25	1	0.15	ACRE	Location 27	0		0		
080	8051000A	SEEDING - COOL SEASON GRASSES	8/7/25	8/11/25	1	0.15	ACRE	Location 27	0		0		
120	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	8/7/25	8/11/25	1	1.00	EA	Location 27 (P-27A)	0		0		
				8/11/25	2	1.00		Location 27 (P-27B)	0		0		
				8/11/25	3	1.00	EA	Location 27 (P-27C)	0		0		
				8/11/25	4	1.00		Location 27 (P-27D)	0		0		
				8/11/25	5	1.00		Location 27 (P-27E)	0		0		
				8/11/25	6	1.00		Location 27 (P-27F)	0		0		
130	9011115	BRACKET ARM, 15 FT. OR 4.6 M	8/7/25	8/11/25	1	1.00		Location 27 (P-27A)	0		0		
				8/11/25	2	1.00		Location 27 (P-27B)	0		0		
				8/11/25	3	1.00		Location 27 (P-27C)	0		0		
				8/11/25 8/11/25	5	1.00		Location 27 (P-27D)	0		0		
				8/11/25	6	1.00		Location 27 (P-27E) Location 27 (P-27F)	0		0		
140	9011313	LUMINAIRE, LED-C	8/7/25	8/11/25	1	1.00		Location 27 (P-27F) Location 27 (P-27A)	0		0		
140	9011313	LOWINAIRE, LED-C	0///23	8/11/25	2	1.00		Location 27 (P-27A)	0		0		
				8/11/25	3	1.00		Location 27 (P-27C)	0		0		
				8/11/25	4	1.00		Location 27 (P-27D)	0		0		
				8/11/25	5	1.00		Location 27 (P-27E)	0		0		
				8/11/25	6	1.00		Location 27 (P-27F)	0		0		
				8/11/25	7	1.00		Location 26 (P-26A)	0		0		
				8/11/25	8	1.00		Location 26 (P-26B)	0		0		
				8/11/25	9	1.00		Location 26 (P-26C)	0		0		
150	9012230	BASE MOUNTED CONTROL STATION	8/14/25	8/14/25	1	1.00		Location 28	0		0		
160	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH		8/14/25	1	39.00		Location 28 (P Supply Exist to CONT)	0		0		
170	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	8/14/25	8/14/25	1	22.00	LF	Location 28 (CONT to PB-28A)	0		0		
180	9014003	CONDUIT, 3 IN. RIGID, PUSHED		8/11/25	1	94.00		Location 27 (PB-27A to PB-27B)	0		0		
				8/11/25	2	188.00	LF	Location 27 (PB-27B to PB-27D)	0		0		
				8/11/25	3	112.00	LF	Location 27 (PB-27D to PB-27E)	0		0		
			8/14/25	8/14/25	1	88.00	LF	Location 28 (PB-28A to PB-28B)	0		0		
				8/14/25	2	129.00	LF	Location 28 (PB-28C to PB-28E)	0		0		
				8/14/25	3	154.00	LF	Location 28 (PB-28E to PB-28F)	0		0		
190	9015010	TRENCHING TYPE I	8/7/25	8/11/25	1	23.00	LF	Location 27 (PB-27A toP-27A)	0		0		
				8/11/25	2	501.00	LF	Location 27 (PB-27B to P-27C)	0		0		
				8/11/25	3	43.00	LF	Location 27 (PB-27D to P-27D)	0		0		
				8/11/25	4	505.00	LF	Location 27 (PB-27E to P-27F)	0		0		
			8/14/25	8/14/25	1	28.00	LF	Location 28 (PB-28A to P-28A)	0		0		
				8/14/25	2	539.00	LF	Location 28 (PB-28B to P-28C)	0		0		
				8/14/25	3	66.00	LF	Location 28 (PB-28E to P-28D)	0		0		
				8/14/25	4	480.00	LF	Location 28 (PB-28F to P-28F)	0		0		
200	9016110	PULL BOX, PREFORMED CLASS 1	8/7/25	8/11/25	1	1.00	EA	Location 27 (PB-27D)	0		0		
				8/11/25	2	1.00	EA	Location 27 (PB-27E)	0		0		
				8/11/25	3	1.00	EA	Location 27 (PB-27F)	0		0		
			8/14/25	8/14/25	1	1.00	EA	Location 28 (PB-28B)	0		0		
				8/14/25	2	1.00	EA	Location 28 (PB-28C)	0		0		
				8/14/25	3	1.00		Location 28 (PB-28D)	0		0		
				8/14/25	4	1.00		Location 28 (PB-28E)	0		0		
				8/14/25	5	1.00		Location 28 (PB-28F)	0		0		
				8/14/25	6	1.00		Location 28 (PB-28G)	0		0		
210		PULL BOX, PREFORMED CLASS 3		8/14/25	1	1.00		Location 28 (PB-28A)	0		0		
220		CABLE, 2 AWG 1 CONDUCTOR		8/14/25		153.00		Location 28 (P Supply existing	0		0		
230	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE	8/7/25	8/11/25	1			Location 27 (P-27A)	0		0		
				8/11/25	2			Location 27 (P-27B)	0		0		
				8/11/25	3			Location 27 (P-27C)	0		0		
				8/11/25	4			Location 27 (P-27D)	0		0		
				8/11/25	5			Location 27 (P-27E)	0		0		
250	0017407	CARLE CONDUIT 1 IN 2 CONDUCTORS	0/7/05	8/11/25	6			Location 27 (P-27F)	0		0		
υU	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	8/7/25	8/11/25	1			Location 27 (PB-27A to P-27C)	0		0		
				8/11/25	2			Location 27 (PB-27B to P-27D)	0		0		
			9/4 4 IOF	8/11/25 8/14/25	3			Location 27 (PB-27D to P-27F)  Location 28 (CONT to PB-28A)	0		0		
			0/14/25	8/14/25	1 2			Location 28 (CON1 to PB-28A)  Location 28 (PB-28A to P-28A)	0		0		
				8/14/25 8/14/25	3	665.00 211.00		Location 28 (PB-28A to P-28C)	0		0		
					4			Location 28 (PB-28C to P-28D)	0				
260	0018245	POLE FOUNDATION (45 FT. OR 13.5 M	8/7/25	8/14/25	5			Location 28 (PB-28E to P-28F)			0		
260	9018245	TOLE TOURDATION (45 FT. OK 13.5 M	8/7/25	8/11/25 8/11/25	1 2	1.00		Location 27 (P-27A)	0		0		
				8/11/25	3	1.00		Location 27 (P-27B)	0		0		
					4			Location 27 (P-27C)	0		0		
				8/11/25		1.00		Location 27 (P-27D)	0		0		
				8/11/25	5	1.00		Location 27 (P-27E)					

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 6 of 12



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
JSE0169	0030	MISC.	Material	Туро	1	Apr 16, 2025	SYSTEM	(\$13,000.00)							
					1	Apr 16, 2025	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					2	May 1, 2025	SYSTEM	(\$13,000.00)							
					2	May 1, 2025	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
				- Total				\$0.00							
			Material - Tota	ıl				\$0.00							
	0030 -	- Total						\$0.00							
	0060	MULCHING	Material		2	May 1, 2025	SYSTEM	(\$3,300.00)							
					2	May 1, 2025	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
						3	May 15, 2025	SYSTEM	(\$3,800.00)						
						4	Jun 2, 2025	SYSTEM	(\$4,050.00)						
								5	Jun 16, 2025	SYSTEM	(\$4,550.00)				
							6	Jul 1, 2025	SYSTEM	(\$4,750.00)					
						7	Jul 16, 2025	SYSTEM	(\$5,250.00)						
					8	Aug 4, 2025	SYSTEM	(\$5,800.00)							
					9	Aug 18, 2025	SYSTEM	(\$6,550.00)							
				- Total				(\$34,750.00)							
			Material - Tota	ıl				(\$34,750.00)							
			MaterialCredit		4	Jun 2, 2025	SYSTEM	\$3,800.00							
					5	Jun 16, 2025	SYSTEM	\$4,050.00							
					6	Jul 1, 2025	SYSTEM	\$4,550.00							
					7	Jul 16, 2025	SYSTEM	\$4,750.00							
					8	Aug 4, 2025	SYSTEM	\$5,250.00							
					9	Aug 18, 2025	SYSTEM	\$5,800.00							
				- Total				\$28,200.00							
			MaterialCredit	t - Total				\$28,200.00							
	0060 -	- Total						(\$6,550.00)							
	0070	TURF TYPE TALL FESCUE	Material		4	Jun 2, 2025	SYSTEM	(\$3,750.00)							
		SODDING			5	Jun 16, 2025	SYSTEM	(\$3,750.00)							
					6	Jul 1, 2025	SYSTEM	(\$3,750.00)							
					7	Jul 16, 2025	SYSTEM	(\$3,750.00)							
					8	Aug 4, 2025	SYSTEM	(\$3,750.00)							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
JSE0169	0070	TURF TYPE TALL FESCUE	Material	- Total				(\$22,500.00)							
		SODDING	Material - Tota					(\$22,500.00)							
			MaterialCredit		5	Jun 16, 2025	SYSTEM	\$3,750.00							
					6	Jul 1, 2025	SYSTEM	\$3,750.00							
					7	Jul 16, 2025	SYSTEM	\$3,750.00							
					8	Aug 4, 2025	SYSTEM	\$3,750.00							
					9	Aug 18, 2025	SYSTEM	\$3,750.00							
				- Total				\$18,750.00							
			MaterialCredit	- Total				\$18,750.00							
	0070 -				_			(\$3,750.00)							
	0800	SEEDING - COOL SEASON	Material		2	May 1, 2025	SYSTEM	(\$1,650.00)							
		GRASSES			2	May 1, 2025	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thomar1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					3	May 15, 2025	SYSTEM	(\$1,900.00)							
					4	Jun 2, 2025	SYSTEM	(\$2,025.00)							
							5	Jun 16, 2025	SYSTEM	(\$2,275.00)					
											6	Jul 1, 2025	SYSTEM	(\$2,375.00)	
								7	Jul 16, 2025	SYSTEM	(\$2,625.00)				
								8	Aug 4, 2025	SYSTEM	(\$2,900.00)				
					9	Aug 18, 2025	SYSTEM	(\$3,275.00)							
			Material - Tota	- Total				(\$17,375.00)							
			Material - Tota	<u> </u>	4	Jun 2, 2025	SYSTEM	(\$17,375.00) \$1,900.00							
					5	Jun 16, 2025	SYSTEM	\$2,025.00							
					6	Jul 1, 2025	SYSTEM	\$2,275.00							
					7	Jul 16, 2025	SYSTEM	\$2,375.00							
					8	Aug 4, 2025	SYSTEM	\$2,625.00							
					9	Aug 18, 2025	SYSTEM	\$2,900.00							
				- Total				\$14,100.00							
			MaterialCredit	- Total				\$14,100.00							
	0080 -	Total						(\$3,275.00)							
	0120	LIGHTING POLE, 45 FT. OR 13.5 M,	Material		2	May 1, 2025	SYSTEM	(\$28,107.00)							
		TYPE AT			2	May 1, 2025	SYSTEM	\$28,107.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
				- Total				\$0.00							
			Material - Tota					\$0.00							
	0120 -	Total						\$0.00							



JSEP169   0130   BACKET   ARA 1.5 FT   ARA	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
APAY, 15 FT.   2026   2   May 1, 5YSTEM   510,890.00   Table adjustment officials the original system-generated Miderial Payment Estimate Exception 6 on the current Payment Estimate.   10,000	JSF0169	0130	BRACKET						(\$10.899.00)	
California Bear Applications (1997)   See   Se	0020.00	0.00	ARM, 15 FT.	matorial			2025		,	
Material   Total						2		SYSTEM	\$10,899.00	Estimate Item Adjustment (0006) due to user thomar1 overridding Payment
1930   Total									\$0.00	
UNINVAIRE				Material - Tota	ıl					
LED-C								0) (0==1.4		
Part		0140		Material			2025			
Material   Total						2		SYSTEM	\$3,357.00	Estimate Item Adjustment (0007) due to user thomar1 overridding Payment
1					- Total				\$0.00	
DISC   DAGE				Material - Tota	ıl					
MOUNTED CONTROL STATION		0140 -								
1		0150	MOUNTED	Material		1		SYSTEM	(\$9,750.00)	
2025   2						1		SYSTEM	\$9,750.00	Estimate Item Adjustment (0002) due to user thomar1 overridding Payment
Substitute   Sub						2		SYSTEM	(\$19,500.00)	
Material - Total						2		SYSTEM	\$19,500.00	Estimate Item Adjustment (0008) due to user thomar1 overridding Payment
Name					- Total				\$0.00	
O160   CONDUIT, 2   N. RIGID, IN TRENCH										
NR RIGID, IN TRENCH   2025   2 May 1, 2VSTEM   \$209.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.   2025   2 May 1, 2VSTEM   2000		0150 -	Total						\$0.00	
2 May 1, 2025 SYSTEM \$209.00 This adjustment foffsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  1		0160	IN. RIGID, IN	Material		2		SYSTEM	(\$209.00)	
Material - Total						2		SYSTEM	\$209.00	Estimate Item Adjustment (0009) due to user thomar1 overridding Payment
Naterial - Total   Summer								\$0.00		
1				Material - Tota	ıl				\$0.00	
IN. RIGID, IN TRENCH    Apr 16, 2025   1		0160 -	Total						\$0.00	
Apr 16, 2025   SYSTEM   Sy00.00   This adjustment offsets the original system-generated Material Payment Estimate Estimate Item Adjustment (0003) due to user thomarf overridding Payment Estimate Exception 3 on the current Payment Estimate.		0170	IN. RIGID, IN	Material		1		SYSTEM	(\$900.00)	
2025  2 May 1, 2025  2 May 1, 530.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user thomar1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  **So.00**  **Material - Total**  **So.00**  **ONDUIT, 3 IN. RIGID, PUSHED**  **In. RI			TRENCH			1		SYSTEM	\$900.00	Estimate Item Adjustment (0003) due to user thomar1 overridding Payment
Estimate Item Adjustment (0010) due to user thomar1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  **So.00**  **Material - Total**  **So.00**  **OnDUIT, 3 IN. RIGID, PUSHED**  **In Apr 16, 2025**  *In Apr 16, 2025						2		SYSTEM	(\$1,530.00)	
Material - Total   \$0.00						2		SYSTEM	\$1,530.00	Estimate Item Adjustment (0010) due to user thomar1 overridding Payment
Solution									\$0.00	
O180 CONDUIT, 3 IN, RIGID, PUSHED  Material  1				Material - Tota	ıl				\$0.00	
IN. RIGID, PUSHED  2025  1 Apr 16, 2025  2025  1 Apr 16, 2025  2 May 1, 2025  3 SYSTEM \$31,500.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.  3 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user thomar1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		0170 -							\$0.00	
1 Apr 16, 2025 SYSTEM \$18,720.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  2 May 1, 2025 SYSTEM \$31,500.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user thomar1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		0180	IN. RIGID,	Material		1		SYSTEM	(\$18,720.00)	
2 May 1, 2025  2 May 1, 2025  31,500.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user thomar1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			OOIILD			1		SYSTEM	\$18,720.00	Estimate Item Adjustment (0004) due to user thomar1 overridding Payment
2025 Estimate Item Adjustment (0011) due to user thomar1 overridding Payment Estimate Exception 14 on the current Payment Estimate.						2		SYSTEM	(\$31,500.00)	
- Total \$0.00						2		SYSTEM	\$31,500.00	Estimate Item Adjustment (0011) due to user thomar1 overridding Payment
					- Total				\$0.00	



ect I	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
169 0		CONDUIT, 3 IN. RIGID, PUSHED	Material - Tota	ıl				\$0.00	
0	0180 -	Total						\$0.00	
0		PULL BOX, PREFORMED	Material		2	May 1, 2025	SYSTEM	(\$14,784.00)	
		CLASS 1			2	May 1, 2025	SYSTEM	\$14,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user thomar1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
0	0200 -	Total						\$0.00	
0		PULL BOX, PREFORMED CLASS 3	Material		2	May 1, 2025	SYSTEM	(\$4,606.00)	
		02.000			2	May 1, 2025	SYSTEM	\$4,606.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user thomar1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
0	0210 -	Total						\$0.00	
0		CABLE, 2 AWG 1 CONDUCTOR	Material		2	May 1, 2025	SYSTEM	(\$821.25)	
		CONDUCTOR			2	May 1, 2025	SYSTEM	\$821.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
0	AWC	Total						\$0.00	
0		AWG 1	AWG 1 CONDUCTOR,	Material		2	May 1, 2025	SYSTEM	(\$1,058.40)
					2	May 1, 2025	SYSTEM	\$1,058.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user thomar1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
								\$0.00	
			Material - Tota					\$0.00	
0	0230 -	Total						\$0.00	
0		CABLE- CONDUIT, 1 IN., 2	Material		2	May 1, 2025	SYSTEM	(\$2,815.20)	
		CONDUCTORS			2 May 1, SYSTEM 2025		SYSTEM	\$2,815.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user thomar1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
0	0250 -	Total						\$0.00	
0		FOUNDATION	Material		2	May 1, 2025	SYSTEM	(\$14,022.00)	
		(45 FT. OR 13.5 M			2	May 1, 2025	SYSTEM	\$14,022.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user thomar1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				- Total					
				_					
			Material - Tota	ıl				\$0.00	
0	0260 -	Total	Material - Tota	ı				\$0.00 \$0.00	
	0270	POWER SUPPLY	Material - Tota	1	1	Apr 16, 2025	SYSTEM	<b>\$0.00</b> (\$17,720.00)	
	0270	POWER			1		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	0270	POWER SUPPLY ASSEMBLY, TYPE 2,				2025 Apr 16,		<b>\$0.00</b> (\$17,720.00)	Estimate Item Adjustment (0005) due to user thomar1 overridding Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSE0169	0270	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120	Material			2025			Estimate Item Adjustment (0017) due to user thomar1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
	0270 - Total							\$0.00	
JSE0169 - Total							(\$13,575.00)		
Overall - Total							(\$13,575.00)		

# MoDOT

## Contract Adjustments for Contract - 240517-H08

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 12 of 12