

# Missouri Department of Transportation Contractor's Pay Estimate Summary

#### Pay Estimate Created Date: August 4, 2025

•	-								
Progress Estimate Number 7	Contract ID Prime Contractor		.0920-D04 nristensen Construction Co.		Pay Period Start Pay Period End	July 16, 2025 August 1, 20	)25 <b>N</b>	Original Contract Amount let Change Order Amount Current Contract Amount	\$7,356,465.30 \$42,219.00 \$7,398,684.30
Approval Date									By User
August 4, 2025					Generated and Approved	(and should be c	considered	Draft) at the Project Office Level by	koenib2
August 4, 2025				Rev	viewed and Approved (and	should be consid	dered Draft	) at the Resident Engineer Level by	stokez1
August 6, 2025					Reviewed	and Approved a	t the Centra	al Office Controllers Office Level by	ramses1
Original Comp	Original Completion Date Current Completion Date				Actual Completion Date % of Current Contract Amount Compl				
November	1, 2025		November 1, 2025	51.29%					
		Contrac	t Informational Dates					Milestones	
Date Description	Original Completio	n Date	<b>Current Completion Date</b>			No Milesto	ones Exist t	for Contract	
Acceptance Date									
Awarded Date	October 2, 2024		October 2, 2024						
Letting Date September 20, 2024 September 20, 2024									
Notice to Proceed Date	November 4, 2024	November 4, 2024							
Work Began Date									

<b>Contract Total Pay</b>	For Estimate No. 7			
		This Estimate	Previous	To Date
240920-D04				
	Total Posted Items Pay	\$261,639.98	\$3,533,267.62	\$3,794,907.60
	Gross Item Adjustments	\$1,774.89	\$1,237.14	\$3,012.03
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$3,534,504.76	\$3,797,919.63
<b>Contract Total Pays</b>	able This Estimate:	\$263,414.87		

Contract	Total Payable This Estimate:	\$263,414


Items Paid Th	his Estimate	Period					
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JCD0029	0010	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$37.000	217.850	\$8,060.45
	0020	4071005	TACK COAT	GAL	\$2.450	5,096	\$12,485.20
	0041	6181000	MOBILIZATION	LS	\$110,434.870	0.250	\$27,608.72
	0090	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.020	77,743.800	\$1,554.88
	0130	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$84.000	1,888.180	\$158,607.12
	5006	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	STA	\$16.500	710.500	\$11,723.25
	5007	6181000	MOBILIZATION	LS	\$17,295.810	1	\$17,295.81
Project JCD	0029 - Total						\$237,335.43
JCD0050	0200	4071005	TACK COAT	GAL	\$2.450	-3,789	(\$9,283.05)
	0210	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	EA	\$2,200.000	2	\$4,400.00
	0231	6181000	MOBILIZATION	LS	\$63,874.730	0.250	\$15,968.68
Project JCD	0050 - Total						\$11,085.63
JCD0149	0585	6069902	MISC.GUARDRAIL POST IN CONCRETE	EA	\$300.430	44	\$13,218.92
Project JCD	0149 - Total						\$13,218.92
Overall - To	tal						\$261,639.98

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item A	Adjustr	nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JCD0029	0010	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user koenib2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	922.46000	\$37.00	\$34,131.02
	0010	GRAVEL (A) OR CRUSHED STONE (B)	Material			-922.46000	\$37.00	(\$34,131.02)
	0020	TACK COAT	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user koenib2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	15,179	\$2.45	\$37,188.55
	0020	TACK COAT	Material			-15,179	\$2.45	(\$37,188.55)
	0080	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.	135,670.44000	\$0.22	\$29,847.50
	0080	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-135,670.44000	\$0.22	(\$29,847.50)

Revision 5/29/2025 Page 1 of 19





#### Pay Estimate Created Date: August 4, 2025

Estimate	gress Numb 7	Contract ID per Prime Contractor	240920-D0- Christenser	4 n Construction	Pay Period Start Pay Period End	July 16, 2025 August 1, 2025	Original Contr Net Change O Current Contr	rder Amount		\$7,356,465.30 \$42,219.00 \$7,398,684.30
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Con	nments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JCD0029	0090	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original sys Estimate Item Adjustment (0004) due t Estimate Exception 23 on the current F	o user koenib2 overridd		173,832.20000	\$0.02	\$3,476.64
	0090	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material					-173,832.20000	\$0.02	(\$3,476.64)
	0130	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		This adjustment offsets the original sys Estimate Item Adjustment (0005) due I Estimate Exception 6 on the current Pa	o user koenib2 overridd		3,505.61000	\$84.00	\$294,471.24
	0130	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material					-3,505.61000	\$84.00	(\$294,471.24
	0130	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	AC Price Index Adjustment based on ti spreadsheet. Spreadsheet placed on e http://eprojects/Docs/CD0029/240920- D04_JCD0029_JCD0050_JCD0149_E	eProjects:				\$1,774.89
	5004	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original sys Estimate Item Adjustment (0020) due t Estimate Exception 12 on the current f	o user koenib2 overridd		4	\$2,200.00	\$8,800.00
	5004	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material					-4	\$2,200.00	(\$8,800.00)
JCD0050	0180	SHAPING SLOPES, CLASS	Material		This adjustment offsets the original sys Estimate Item Adjustment (0014) due t Estimate Exception 2 on the current Pa	o user koenib2 overridd		13.52000	\$1,420.96	\$19,211.38
	0180	SHAPING SLOPES, CLASS	Material					-13.52000	\$1,420.96	(\$19,211.38
	0190	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	Material		This adjustment offsets the original sys Estimate Item Adjustment (0015) due t Estimate Exception 5 on the current Pa	o user koenib2 overridd		227.25000	\$37.00	\$8,408.25
	0190	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	Material		·			-227.25000	\$37.00	(\$8,408.25)
	0200	TACK COAT	Material		This adjustment offsets the original sys Estimate Item Adjustment (0022) due t Estimate Exception 9 on the current Pa	o user koenib2 overridd		2,990	\$2.45	\$7,325.50
	0200	TACK COAT	Material					-2,990	\$2.45	(\$7,325.50)
	0210	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original sys Estimate Item Adjustment (0016) due t Estimate Exception 14 on the current F	o user koenib2 overridd		2	\$2,200.00	\$4,400.00
	0210	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material					-2	\$2,200.00	(\$4,400.00)
	0320	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original systemate Item Adjustment (0017) due to Estimate Exception 21 on the current F	o user koenib2 overridd		61,142	\$0.20	\$12,228.40
	0320	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material					-61,142	\$0.20	(\$12,228.40)
	0330	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original sys Estimate Item Adjustment (0018) due t Estimate Exception 27 on the current F	o user koenib2 overridd		58,509	\$0.04	\$2,340.36
	0330	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material					-58,509	\$0.04	(\$2,340.36)
	0380	MGS GUARDRAIL	Material		This adjustment offsets the original sys Estimate Item Adjustment (0019) due t Estimate Exception 11 on the current F	o user koenib2 overridd		700	\$32.04	\$22,428.00
	0380	MGS GUARDRAIL	Material					-700	\$32.04	(\$22,428.00)
JCD0149	0440	SHAPING SLOPES, CLASS	Material		This adjustment offsets the original sys Estimate Item Adjustment (0006) due t Estimate Exception 1 on the current Pa	to user koenib2 overridd	Payment ing Payment	12	\$1,425.34	\$17,104.08
	0440	SHAPING SLOPES, CLASS	Material					-12	\$1,425.34	(\$17,104.08)

Revision 5/29/2025 Page 2 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary

#### Pay Estimate Created Date: August 4, 2025

Prog Estimate	gress Numb 7	Contract ID  Prime Contractor	240920-D04 Christenser	4 Construction	Pay Period Start Pay Period End	July 16, 2025 August 1, 2025	Original Contr Net Change Or Current Contra	der Amount		\$7,356,465.3 \$42,219.0 \$7,398,684.3
Project umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Com	nments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
D0149		III								
	0450	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original sys Estimate Item Adjustment (0007) due t Estimate Exception 4 on the current Pa	o user koenib2 overrido		425	\$45.00	\$19,125.00
	0450	GRAVEL (A) OR CRUSHED STONE (B)	Material					-425	\$45.00	(\$19,125.00
	0470	TACK COAT	Material		This adjustment offsets the original sys Estimate Item Adjustment (0008) due t Estimate Exception 8 on the current Pa	o user koenib2 overrido	Payment ing Payment	5,858	\$2.45	\$14,352.10
	0470	TACK COAT	Material					-5,858	\$2.45	(\$14,352.10
	0500	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original sys Estimate Item Adjustment (0009) due t Estimate Exception 15 on the current F	o user koenib2 overrido		48	\$40.00	\$1,920.00
	0500	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material					-48	\$40.00	(\$1,920.00
	0510	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original sys Estimate Item Adjustment (0010) due t Estimate Exception 16 on the current F	o user koenib2 overrido		1	\$400.00	\$400.00
	0510	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material					-1	\$400.00	(\$400.00
	0520	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original sys Estimate Item Adjustment (0011) due t Estimate Exception 19 on the current F	o user koenib2 overrido		96,800	\$0.21	\$20,328.00
	0520	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material					-96,800	\$0.21	(\$20,328.00
	0530	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original sys Estimate Item Adjustment (0012) due t Estimate Exception 25 on the current F	o user koenib2 overrido		84,138	\$0.03	\$2,524.14
	0530	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material					-84,138	\$0.03	(\$2,524.14
	0560	MGS GUARDRAIL	Material		This adjustment offsets the original sys Estimate Item Adjustment (0013) due t Estimate Exception 10 on the current F	o user koenib2 overrido		300	\$33.95	\$10,185.00
	0560	MGS GUARDRAIL	Material					-300	\$33.95	(\$10,185.00
	5005	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original sys Estimate Item Adjustment (0021) due t Estimate Exception 13 on the current F	o user koenib2 overrido		2	\$2,200.00	\$4,400.00
	5005	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material					-2	\$2,200.00	(\$4,400.00
tal										\$1,774.89

Revision 5/29/2025 Page 3 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	ontract Project Information	n			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
JCD0029	FAS- S403 (038)	Coldmill and resurface	J, F, H, M, RA	CALLAWAY			oute J to Westminster Ave in Fulton, RA from Route J to end of state mair	on Route H from Route J to Route 54, on nt.		
JCD0050	FAS-403 (037)	Resurface	WW, N	BOONE	on Route WW from Route 63 to Route J in Millersburg and on Route N from Route 163 to end of state maintenance in Easley					
JCD0149	FAS S403(89)	Coldmill and resurface	Z	CALLAWAY	on Route Z from Fulto	n to I-70				
Totals b	y Job Nu	ımbers								
JCD0029		l Item Pay Item Adjustmo		Item Pay	This Estimate \$237,335.43 \$1,774.89 \$239,110.32	Previous \$1,892,443.82 (\$1,534.04) \$1,890,909.78	To Date \$2,129,779.25 \$240.85 \$2,130,020.10			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
JCD0050		l Item Pay Item Adjustmo		Item Pay	This Estimate \$11,085.63 \$0.00 \$11,085.63	Previous \$606,237.37 (\$1,550.56) \$604,686.81	To Date \$617,323.00 (\$1,550.56) \$615,772.44			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
JCD0149		l Item Pay Item Adjustmo		Item Pay	This Estimate \$13,218.92 \$0.00 <b>\$13,218.92</b>	Previous \$1,034,586.43 \$4,321.74 \$1,038,908.17	<b>To Date</b> \$1,047,805.35 \$4,321.74 <b>\$1,052,127.09</b>			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 5/29/2025 Page 4 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period  Exceptions / Discrepancies	Explanation	Entered	Status
		Ву	
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 2153000, Project Item Line Number 0440, Material Set 215300096, Material 3304AGBS - Aggregate Base JSP, Acceptance Action Generic 3304AGBS is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 2153000, Project Item Line Number 0180, Material Set 215300096, Material 3304AGBS - Aggregate Base JSP, Acceptance Action Generic 3304AGBS is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0029, Item 3105002, Project Item Line Number 0010, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 3105002, Project Item Line Number 0450, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 3107002, Project Item Line Number 0190, Material Set 310700296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0029, Item 4020520, Project Item Line Number 0130, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0029, Item 4071005, Project Item Line Number 0020, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 4071005, Project Item Line Number 0470, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 4071005, Project Item Line Number 0200, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 6061060, Project Item Line Number 0560, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 6061060, Project Item Line Number 0380, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0029, Item 6161098A, Project Item Line Number 5004, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 6161098A, Project Item Line Number 5005, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 6161098A, Project Item Line Number 0210, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 6200015, Project Item Line Number 0500, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 6200021, Project Item Line Number 0510, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0029, Item 6206000C, Project Item Line Number 0080, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0029, Item 6206000C, Project Item Line Number 0080, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 6206000C, Project Item Line Number 0520, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 6206000C, Project Item Line Number 0520, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 6206000C, Project Item Line Number 0320, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 6206000C, Project Item Line Number 0320, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0029, Item 6206001C, Project Item Line Number 0090, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0029, Item 6206001C, Project Item Line Number 0090, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne	Working with contractor and materials to resolve.	koenib2	Overridden

Revision 5/29/2025 Page 5 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.			
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 6206001C, Project Item Line Number 0530, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0149, Item 6206001C, Project Item Line Number 0530, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 6206001C, Project Item Line Number 0330, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Insufficient Materials: Project JCD0050, Item 6206001C, Project Item Line Number 0330, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Working with contractor and materials to resolve.	koenib2	Overridden
Estimate Exception Type: Item Overrun: Contract 240920-D04, Contract Project JCD0149, Project Item Line Number 0500, Contract Line Item Number 0500, Item 6200015, Minor Item.	Working on change order for overrun.	koenib2	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240920-D04, Contract Project JCD0029, Project Item Line Number 0140, Contract Line Item Number 0140, Item 4020520, Minor Item.	Working on change order for overrun.	koenib2	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240920-D04, Contract Project JCD0029, Project Item Line Number 0150, Contract Line Item Number 0150, Item 4020520, Minor Item.	Working on change order for overrun.	koenib2	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240920-D04, Contract Project JCD0149, Project Item Line Number 0540, Contract Line Item Number 0540, Item 6221001, Minor Item.	Working on change order for overrun.	koenib2	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240920-D04, Contract Project JCD0050, Project Item Line Number 0420, Contract Line Item Number 0420, Item 4020520, Minor Item.	Working on change order for overrun.	koenib2	Acknowledged

Revision 5/29/2025 Page 6 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
0920-	JCD0029	0001	0010	3105002	GRAVEL (A) OR CRUSHED STONE (B)	2,520.00	0.00	2,520.00	TONS	922.46	\$37.00	\$34,131.
4		0001	0020	4071005	TACK COAT	51,490.00	0.00	51,490.00	GAL	15,179.00	\$2.45	\$37,188.
		0001	0030	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$31,000.00	\$15,500.
		0001	0040	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$130,000.00	\$0.
		0001	0041	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$110,434.87	\$110,434.
		0001	0050	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	11.00	0.00	11.00	LF	0.00	\$35.00	\$0.
		0001	0060	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	6.00	0.00	6.00	EA	0.00	\$350.00	\$0.
		0001	0070	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	5.00	0.00	5.00	EA	0.00	\$250.00	\$0.
		0001	0800	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	474,376.00	0.00	474,376.00	LF	135,670.44	\$0.22	\$29,847.
		0001	0090	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	477,354.00	0.00	477,354.00	LF	173,832.20	\$0.02	\$3,476
		0001	0100	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,301.00	0.00	1,301.00	SQYD	1,301.00	\$10.00	\$13,010
		0001	0110	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,246.00	0.00	4,246.00	SQYD	2,205.26	\$12.00	\$26,463
		0050	0120	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	26,345.00	0.00	26,345.00	TONS	0.00	\$79.50	\$0
		0051	0130	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	10,968.00	0.00	10,968.00	TONS	9,505.61	\$84.00	\$798,471
		0052	0140	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	5,650.00	0.00	5,650.00	TONS	5,757.50	\$83.00	\$477,872
		0053	0150	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	6,126.00	0.00	6,126.00	TONS	6,261.90	\$84.00	\$525,999
		0054	0160	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	85.00	0.00	85.00	TONS	0.00	\$84.00	\$0
		0001	5001	6189901	MISC.Adjusted Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$19,565.13	\$19,56
		0001	5004	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	0.00	4.00	4.00	EA	4.00	\$2,200.00	\$8,80
		0001	5006	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	0.00	710.50	710.50	STA	710.50	\$16.50	\$11,72
		0001	5007	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$17,295.81	\$17,295
	Project JO		otal Value	Posted to D	ate as of Report Generated Date							\$2,129,779
	JCD0050	0001	0170	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00				
			0110	LULLUTO		1.00	0.00	1.00	LS	0.31	\$9,914.05	\$3,07
		0001	0180	2153000	SHAPING SLOPES, CLASS III	20.40	0.00	20.40	100F	13.52	\$9,914.05 \$1,420.96	
		0001										\$19,21
		0001	0180	2153000	SHAPING SLOPES, CLASS III	20.40	0.00	20.40	100F	13.52	\$1,420.96	\$19,21 \$8,40
		0001 0001 0001	0180 0190	2153000 3107002	SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	20.40 855.00	0.00	20.40 855.00	100F TONS	13.52 227.25	\$1,420.96 \$37.00	\$19,21 \$8,40 \$7,32
		0001 0001 0001	0180 0190 0200	2153000 3107002 4071005	SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C) TACK COAT CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	20.40 855.00 17,803.00	0.00 0.00 0.00	20.40 855.00 17,803.00	100F TONS GAL	13.52 227.25 2,990.00	\$1,420.96 \$37.00 \$2.45	\$19,21 \$8,40 \$7,32 \$4,40
		0001 0001 0001 0001 0001	0180 0190 0200 0210	2153000 3107002 4071005 6161098A	SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C) TACK COAT CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	20.40 855.00 17,803.00 2.00	0.00 0.00 0.00 0.00	20.40 855.00 17,803.00 2.00	100F TONS GAL EA	13.52 227.25 2,990.00 2.00	\$1,420.96 \$37.00 \$2.45 \$2,200.00	\$19,21 \$8,40 \$7,32 \$4,40
		0001 0001 0001 0001 0001 0001	0180 0190 0200 0210	2153000 3107002 4071005 6161098A 6169901	SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C) TACK COAT CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL MOBILIZATION MOBILIZATION	20.40 855.00 17,803.00 2.00	0.00 0.00 0.00 0.00	20.40 855.00 17,803.00 2.00	100F TONS GAL EA LS LS	13.52 227.25 2,990.00 2.00 0.50	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40
		0001 0001 0001 0001 0001 0001	0180 0190 0200 0210 0220 0230 0231 0240	2153000 3107002 4071005 6161098A 6169901 6181000 6200009	SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C) TACK COAT CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL MOBILIZATION MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	20.40 855.00 17,803.00 2.00 1.00 1.00 0.00	0.00 0.00 0.00 0.00 0.00 -1.00 1.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00	100F TONS GAL EA LS LS LS LS	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015	SHAPING SLOPES, CLASS III  GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)  TACK COAT  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL  MOBILIZATION  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	20.40 855.00 17,803.00 2.00 1.00 1.00 0.00 132.00	0.00 0.00 0.00 0.00 -1.00 1.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00	100F TONS GAL EA LS LS LS LS LF	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$ \$63,87
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200018	SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C) TACK COAT CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL MOBILIZATION MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	20.40 855.00 17,803.00 2.00 1.00 0.00 132.00 86.00	0.00 0.00 0.00 0.00 -1.00 1.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00	100F TONS GAL EA LS LS LS LF LF	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$18.00	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$ \$63,87 \$
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200018 6200021	SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C) TACK COAT CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL MOBILIZATION MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	20.40 855.00 17,803.00 2.00 1.00 1.00 0.00 132.00 86.00 620.00	0.00 0.00 0.00 0.00 -1.00 1.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 620.00	TONS GAL EA LS LS LS LF LF LF	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00 0.00	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$18.00 \$18.00	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$ \$63,87 \$
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200018 6200021 6200024	SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C) TACK COAT CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL MOBILIZATION MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELTINGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	20.40 855.00 17,803.00 2.00 1.00 0.00 132.00 86.00 620.00 22.00	0.00 0.00 0.00 0.00 0.00 -1.00 1.00 0.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 620.00 22.00	TONS GAL LS LS LS LF LF LF LF EA	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00 0.00 0.00	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$18.00 \$260.00	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$ \$63,87 \$ \$
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260 0270 0280	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200018 6200021 6200024 6200027	SHAPING SLOPES, CLASS III  GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)  TACK COAT  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL  MOBILIZATION  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	20.40 855.00 17,803.00 2.00 1.00 1.00 0.00 132.00 86.00 22.00 2.00	0.00 0.00 0.00 0.00 0.00 1.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 620.00 22.00	TONS GAL LS LS LS LF LF LF EA EA	13.52 227.25 2,990.00 0.50 0.00 1.00 0.00 0.00 0.00	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$18.00 \$24.00 \$260.00	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$ \$63,87 \$ \$ \$
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260 0270 0280	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200018 6200021 6200024 6200027 6200036	SHAPING SLOPES, CLASS III  GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)  TACK COAT  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL  MOBILIZATION  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STRAITATT  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	20.40 855.00 17,803.00 2.00 1.00 0.00 132.00 86.00 22.00 2.00 2.00	0.00 0.00 0.00 0.00 0.00 1.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 22.00 2.00 2.00	100F TONS GAL EA LS LS LS LF LF EA EA	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00 0.00 0.00 0.00	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$18.00 \$24.00 \$260.00 \$520.00	\$19,21 \$8,40 \$7,32 \$4,40 \$63,87 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260 0270 0280 0290 0300	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200018 6200024 6200027 6200036 6200042	SHAPING SLOPES, CLASS III  GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)  TACK COAT  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL  MOBILIZATION  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STRILT/RT  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	20.40 855.00 17,803.00 2.00 1.00 0.00 132.00 86.00 22.00 2.00 2.00 20.00	0.00 0.00 0.00 0.00 1.00 0.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 22.00 2.00 2.00 20.00	100F TONS GAL LS LS LS LF LF EA EA EA	13.52 227.25 2,990.00 0.50 0.00 1.00 0.00 0.00 0.00 0.00	\$1,420,96 \$37.00 \$2,45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$18.00 \$260.00 \$260.00 \$190.00	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$ \$63,87 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260 0270 0280 0300 0310	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200018 6200024 6200027 6200036 6200042 620000C	SHAPING SLOPES, CLASS III  GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)  TACK COAT  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL  MOBILIZATION  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT  PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 20 IN WHITE MIDBLOCK  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 10 IN WHITE MIDBLOCK  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	20.40 855.00 17,803.00 2.00 1.00 0.00 132.00 86.00 22.00 2.00 2.00 78.00	0.00 0.00 0.00 0.00 1.00 0.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 22.00 2.00 2.00 2.00 78.00	100F TONS GAL EA LS LS LS LF LF EA EA EA EA	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00 0.00 0.00 0.00 0	\$1,420.96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$18.00 \$24.00 \$260.00 \$520.00 \$190.00 \$22.50	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$ \$63,87 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260 0270 0280 0300 0310 0320	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200024 6200024 6200027 6200036 6200042 6206000C 6206001C	SHAPING SLOPES, CLASS III  GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)  TACK COAT  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL  MOBILIZATION  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELTOWN THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELTOWN THERMOPLASTIC PAVEMENT MARKING, 25 IN. YELTOWN THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, OMBINATION STR/LT/RT  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LIME TRIANGLES  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	20.40 855.00 17,803.00 2.00 1.00 0.00 132.00 86.00 22.00 2.00 20.00 78.00 156,968.00	0.00 0.00 0.00 0.00 1.00 0.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 22.00 2.00 20.00 78.00 156,968.00	100F TONS GAL LS LS LS LF LF LF LF LF LA EA EA EA LC LF LF LF LF LF	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00 0.00 0.00 0.00 0	\$1,420,96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$24.00 \$18.00 \$260.00 \$190.00 \$20.00 \$0.20 \$0.04	\$19,21 \$8,40 \$7,32 \$4,40 \$6,40 \$ \$63,87 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
		0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260 0270 0280 0300 0310 0320	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200018 6200024 6200024 6200027 6200036 6200042 6206000C 6206001C 6206001C	SHAPING SLOPES, CLASS III  GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)  TACK COAT  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL  MOBILIZATION  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STRULT/RT  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	20.40 855.00 17,803.00 2.00 1.00 1.00 0.00 132.00 86.00 22.00 2.00 2.00 20.00 78.00 156,968.00 163,309.00	0.00 0.00 0.00 0.00 1.00 0.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 620.00 2.00 2.00 2.00 78.00 156,968.00 163,309.00	TONS GAL LS LS LS LF LF LF LF LF LA EA LA EA LF	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00 0.00 0.00 0.00 0	\$1,420.96 \$37.00 \$2,45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$18.00 \$260.00 \$260.00 \$190.00 \$22.50 \$0.20	\$19,21 \$8,40i \$7,32; \$4,40i \$63,87; \$i \$i \$i \$i \$i \$i \$i \$i \$i \$i \$i \$i \$i
		0001 0001 0001 0001 0001 0001 0001 000	0180 0190 0200 0210 0220 0230 0231 0240 0250 0260 0270 0280 0300 0310 0320	2153000 3107002 4071005 6161098A 6169901 6181000 6200009 6200015 6200024 6200024 6200027 6200036 6200042 6206000C 6206001C	SHAPING SLOPES, CLASS III  GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)  TACK COAT  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL  MOBILIZATION  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW  PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STRULT/RT  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK  PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	20.40 855.00 17,803.00 2.00 1.00 0.00 132.00 86.00 22.00 2.00 20.00 78.00 156,968.00	0.00 0.00 0.00 0.00 1.00 0.00 0.00 0.00	20.40 855.00 17,803.00 2.00 1.00 0.00 1.00 132.00 86.00 22.00 2.00 20.00 78.00 156,968.00	100F TONS GAL LS LS LS LF LF LF LF LF LA EA EA EA LC LF LF LF LF LF	13.52 227.25 2,990.00 2.00 0.50 0.00 1.00 0.00 0.00 0.00 0.00 0	\$1,420,96 \$37.00 \$2.45 \$2,200.00 \$12,815.00 \$75,000.00 \$63,874.73 \$6.00 \$24.00 \$18.00 \$260.00 \$190.00 \$20.00 \$0.20 \$0.04	\$3,07: \$19,21: \$6,40: \$7,32: \$4,40: \$63,87: \$1 \$1 \$1 \$1 \$2,34: \$1 \$2,34:

Revision 5/29/2025 Page 7 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10920-	JCD0050	0010	0380	6061060	MGS GUARDRAIL	1,337.50	0.00	1,337.50	LF	700.00	\$32.04	\$22,428.0
04		0010	0390	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$4,244.63	\$16,978.5
		0010	0400	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10.00	0.00	10.00	EA	8.00	\$3,430.83	\$27,446.6
		0050	0410	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	9,987.50	0.00	9,987.50	TONS	0.00	\$84.00	\$0.0
		0051	0420	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	4,712.20	0.00	4,712.20	TONS	4,783.34	\$85.00	\$406,583.9
		0001	5002	6189901	MISC.Adjusted Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$11,125.27	\$11,125.2
	Project JC	CD0050 - To	tal Value	Posted to D	ate as of Report Generated Date							\$617,323.
	JCD0149	0001	0430	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$8,261.71	\$8,261.7
		0001	0440	2153000	SHAPING SLOPES, CLASS III	12.00	0.00	12.00	100F	12.00	\$1,425.34	\$17,104.0
		0001	0450	3105002	GRAVEL (A) OR CRUSHED STONE (B)	540.00	0.00	540.00	TONS	425.00	\$45.00	\$19,125.0
		0001	0460	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	9,301.90	0.00	9,301.90	TONS	9,284.10	\$85.00	\$789,148.5
		0001	0470	4071005	TACK COAT	11,074.00	0.00	11,074.00	GAL	5,858.00	\$2.45	\$14,352.
		0001	0480	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$9,665.00	\$9,181.
		0001	0490	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$50,000.00	\$0.
		0001	0491	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$42,327.40	\$42,327.
		0001	0500	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	24.00	0.00	24.00	LF	48.00	\$40.00	\$1,920.
		0001	0510	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$400.00	\$400.
		0001	0520	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	102,781.00	0.00	102,781.00	LF	96,800.00	\$0.21	\$20,328.
		0001	0530	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	102,781.00	0.00	102,781.00	LF	84,138.00	\$0.03	\$2,524
		0001	0540	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	839.00	0.00	839.00	SQYD	1,131.00	\$12.50	\$14,137.
		0001	0550	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,140.00	0.00	1,140.00	SQYD	1,101.40	\$14.00	\$15,419.
		0010	0560	6061060	MGS GUARDRAIL	300.00	0.00	300.00	LF	300.00	\$33.95	\$10,185
		0010	0570	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	8.00	\$3,831.55	\$30,652
		0010	0580	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	8.00	\$3,430.83	\$27,446
		0010	0585	6069902	MISC.GUARDRAIL POST IN CONCRETE	44.00	0.00	44.00	EA	44.00	\$300.43	\$13,218
		0030	0590	9029902	MISC.6'x30' LOOP DETECTOR	2.00	0.00	2.00	EA	0.00	\$2,900.00	\$0
		0001	5003	6189901	MISC.Adjusted Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$7,672.60	\$7,672
		0001	5005	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	0.00	2.00	2.00	EA	2.00	\$2,200.00	\$4,400
	Project JC	D0149 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,047,805
0920-D	004 Overall	- Total Val	ue Poste	d to Date as	of Report Generated Date							\$3,794,907

Revision 5/29/2025 Page 8 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JCD0029

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	3105002	GRAVEL (A) OR CRUSHED STONE (B)	7/17/25	8/1/25	1	217.85	TONS	Route F	Entrances		Entrances		
0020	4071005	TACK COAT	7/16/25	8/1/25	1	1,307.00	GAL	Route F (eastbound lane)	3.706 E		0.002 E		
			7/30/25	7/30/25	1	3,789.00	GAL	Route H					Fixing error. Moving tack used on Route H from line 0200 (error) to line 0020 (correct). This amounts to 3789 gallons of tack.
0041	6181000	MOBILIZATION	7/31/25	8/4/25	1	0.25	LS	Routes J, F, H, M, RA					Per Sec 618, the final 25% of mobilization will be paid once 30% of the original contract is earned. As of this pay period, 38% has been earned.
0090	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	7/29/25	8/4/25	1	77,743.80	LF	Route F					Payment is for 80% of yellow stripe placed on Route F. Remaining 20% will be paid once retro results have been received.
0130	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	7/16/25	8/1/25	1	1,888.18	TONS	Route F (eastbound lane)	3.706 E		0.002 E		
5006	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	7/31/25	8/4/25	1	710.50	STA	Route F					
5007	6181000	MOBILIZATION	7/31/25	8/4/25	1	1.00	LS	Route F					Mobilization to perform rumble strip work on Route F

Project: JCD0050

0,000.													
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0200	4071005	TACK COAT	7/30/25	7/30/25	1	-3,789.00	GAL	Route H					Fixing error. Moving tack used on Route H from line 0200 (error) to line 0020 (correct). This amounts to 3789 gallons of tack.
0210	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	7/31/25	8/4/25	1	2.00	EA	Route N					
0231	6181000	MOBILIZATION	7/31/25	8/4/25	1	0.25	LS	Routes WW, N					Per Sec 618, the final 25% of mobilization will be paid once 30% of the original contract is earned. As of this pay period, 38% has been earned.

Project: JCD0149

Line Number	Item Code	Description			Posting Sequence No.			Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0585	6069902	MISC. GUARDRAIL ITEM	7/31/25	8/4/25	1	44.00	EA	Route F Bridge Guardrail					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 9 of 19



ct	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	LIIIG	Description	Type	Adjustment Type	Number	Date	By	Amount	IVIIIains
)29	0010	GRAVEL (A) OR CRUSHED STONE	Material		4	Jun 16, 2025	SYSTEM	(\$14,249.07)	
		(B)			4	Jun 16, 2025	SYSTEM	\$14,249.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user koenib2 overridding Payment Estimate Exception 3 on th current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$26,070.57)	
					5	Jul 1, 2025	SYSTEM	\$26,070.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user koenib2 overridding Payment Estimate Exception 3 on th current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$26,070.57)	
					6	Jul 16, 2025	SYSTEM	\$26,070.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user koenib2 overridding Payment Estimate Exception 3 on th current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$34,131.02)	
					7	Aug 4, 2025	SYSTEM	\$34,131.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user koenib2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0010 -	Total						\$0.00	
	0020	TACK COAT	Material		3	Jun 3, 2025	SYSTEM	(\$7,577.85)	
					3	Jun 3, 2025	SYSTEM	\$7,577.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schaua1 overridding Payment Estimate Exception 4 on tourrent Payment Estimate.
					4	Jun 16, 2025	SYSTEM	(\$10,885.35)	
					4	Jun 16, 2025	SYSTEM	\$10,885.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user koenib2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$10,885.35)	
					5	Jul 1, 2025	SYSTEM	\$10,885.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user koenib2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$24,703.35)	
					6	Jul 16, 2025	SYSTEM	\$24,703.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user koenib2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$37,188.55)	
					7	Aug 4, 2025	SYSTEM	\$37,188.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user koenib2 overridding Payment Estimate Exception 7 on tourrent Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0020 -	4 IN. WHITE WATERBORNE	Material		5	Jul 1, 2025	SYSTEM	<b>\$0.00</b> (\$17,818.90)	
		PAVEMENT MARKING			5	Jul 1, 2025	SYSTEM	\$17,818.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user koenib2 overridding Payment Estimate Exception 13 on current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$29,847.50)	
					6	Jul 16,	SYSTEM	\$29,847.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user koenib2 overridding Payment Estimate Exception 16 on
					6	2025			current Payment Estimate.
					7	2025 Aug 4, 2025	SYSTEM	(\$29,847.50)	
						Aug 4,	SYSTEM	(\$29,847.50) \$29,847.50	current Payment Éstimate.  This adjustment offsets the original system-generated Material Payment Estimate Item
				- Total	7	Aug 4, 2025 Aug 4,		, , , ,	current Payment Éstimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user koenib2 overridding Payment Estimate Exception 17 on
			Material - To		7	Aug 4, 2025 Aug 4,		\$29,847.50	current Payment Éstimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user koenib2 overridding Payment Estimate Exception 17 on



et L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
29 0	0090	4 IN. YELLOW WATERBORNE	Material		5	Jul 1, 2025	SYSTEM	(\$982.84)	
		PAVEMENT MARKING			5	Jul 1, 2025	SYSTEM	\$982.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user koenib2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$1,921.77)	
					6	Jul 16, 2025	SYSTEM	\$1,921.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user koenib2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$3,476.64)	
					7	Aug 4, 2025	SYSTEM	\$3,476.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user koenib2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
0	090 -	Total						\$0.00	
0	0130	BITUMINOUS PAVEMENT MIXTURE	Material		6	Jul 16, 2025	SYSTEM	(\$639,864.12)	
		PG64-22 (SUR			6	Jul 16, 2025	SYSTEM	\$639,864.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user koenib2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$294,471.24)	
					7	Aug 4, 2025	SYSTEM	\$294,471.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user koenib2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	6	Jul 16, 2025	koenib2	\$7,160.38	AC Index price adjustment. Supporting documentation placed on eProjects: http://eprojects/Docs/CD0029/240920-D04_JCD0029_JCD0050_JCD0149_Estimate_0006_0130_0420_AC_Adjustment.pdf
					7	Aug 4, 2025	koenib2	\$1,774.89	AC Price Index Adjustment based on the AC Price Index Adjustment spreadsheet. Spreadsheet placed on eProjects: http://eprojects/Docs/CD0029/240920-D04_JCD0029_JCD0050_JCD0149_Estimate_0007_0130_AC_Adjustment.pdf
				ACAD - Tota	al			\$8,935.27	
			Other Item /	Adjustment -	Total			\$8,935.27	
0	)130 -	Total						\$8,935.27	
0	0140	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Other Item Adjustment	ACAD	5	Jul 1, 2025	koenib2	\$5,757.45	AC Price Index Adjustment based on the AC Price Index Adjustment spreadsheet.  Spreadsheet placed in eProjects: http://eprojects/Docs/CD0029/240920- D04_JCD0029_JCD0050_JCD0149_Estimate_0005_0140_0460_AC_Adjustment.pdf
		. 661 22 (661)		ACAD - Tota	al			\$5,757.45	
				Adjustment -				\$5,757.45	
			Overrun	Overrun	5	Jul 1, 2025	SYSTEM	(\$8,922.50)	
				Overrun - T	otal			(\$8,922.50)	
			Overrun - T	otal				(\$8,922.50)	
	)140 -		O.I. II					(\$3,165.05)	
0	0150	BITUMINOUS PAVEMENT MIXTURE	Other Item Adjustment	ACAD	3	Jun 3, 2025	schaua1	\$3,895.60	AC Price Adjustment for period 5/15/2025-6/1/2025 Line 0150 - 4,144.25 tons - 4.7% AC SL25-18 Mix ID
		PG64-22 (SUR			4	Jun 16, 2025	koenib2	\$1,990.63	AC Price Index Adjustment based on the AC Price Index Adjustment spreadsheet.  Spreadsheet placed in eprojects: http://eprojects/Docs/CD0029/240920- D04_JCD0029_JCD0050_JCD0149_Estimate_0004_0150_0420_0460_AC_Adjustment.pd
				ACAD - Tota	al			\$5,886.23	
			Other Item /	Adjustment -	Total			\$5,886.23	
			Overrun	Overrun	4	Jun 16, 2025	SYSTEM	(\$11,415.60)	
				Overrun - T	otal			(\$11,415.60)	
			Overrun - T	otal				(\$11,415.60)	
0	)150 -	Total						(\$5,529.37)	
5	5004	CHANGEABLE MESSAGE SIGN WITHOUT	Material		6	Jul 16, 2025	SYSTEM	(\$8,800.00)	
		COMMUNICATION INTERFACE, CONTRACTOR			6	Jul 16, 2025	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user koenib2 overridding Payment Estimate Exception 12 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0029	5004	FURNISHED / RETAINED	Material		7	Aug 4, 2025	SYSTEM	(\$8,800.00)	
					7	Aug 4, 2025	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user koenib2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5004 -	Total						\$0.00	
JCD0029 - 1								\$240.85	
JCD0050	0180	SHAPING SLOPES, CLASS	Material		2	May 16, 2025	SYSTEM	(\$5,158.08)	
		III			2	May 16, 2025	SYSTEM	\$5,158.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user koenib2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jun 3, 2025	SYSTEM	(\$10,500.89)	
					3	Jun 3, 2025	SYSTEM	\$10,500.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Jun 16, 2025	SYSTEM	(\$10,500.89)	
					4	Jun 16, 2025	SYSTEM	\$10,500.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user koenib2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$10,500.89)	
					5	Jul 1, 2025	SYSTEM	\$10,500.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user koenib2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$19,211.38)	
					6	Jul 16, 2025	SYSTEM	\$19,211.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user koenib2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$19,211.38)	
					7	Aug 4, 2025	SYSTEM	\$19,211.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user koenib2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
1	0180 -	Total						\$0.00	
,	0190	GRAVEL (A) OR CRUSHED STONE	Material		3	Jun 3, 2025	SYSTEM	(\$8,408.25)	
		(B) OR CHAT			3	Jun 3, 2025	SYSTEM	\$8,408.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schaua1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jun 16, 2025	SYSTEM	(\$8,408.25)	
					4	Jun 16, 2025	SYSTEM	\$8,408.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user koenib2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$8,408.25)	
					5	Jul 1, 2025	SYSTEM	\$8,408.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user koenib2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$8,408.25)	
					6	Jul 16, 2025	SYSTEM	\$8,408.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user koenib2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$8,408.25)	
					7	Aug 4, 2025	SYSTEM	\$8,408.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user koenib2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0050	0190 -	- Total						\$0.00	
	0200	TACK COAT	Material		3	Jun 3, 2025	SYSTEM	(\$7,149.10)	
					3	Jun 3, 2025	SYSTEM	\$7,149.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Jun 16, 2025	SYSTEM	(\$7,271.60)	
					4	Jun 16, 2025	SYSTEM	\$7,271.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user koenib2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$16,554.65)	
					5	Jul 1, 2025	SYSTEM	\$16,554.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$16,608.55)	•
					6	Jul 16, 2025	SYSTEM	\$16,608.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user koenib2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$7,325.50)	
					7	Aug 4, 2025	SYSTEM	\$7,325.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user koenib2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0200 -				-		OVOTEN	\$0.00	
	0210	CHANGEABLE MESSAGE SIGN WITHOUT	Material		7	Aug 4, 2025	SYSTEM	(\$4,400.00)	
		COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /			7	Aug 4, 2025	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user koenib2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		RETAINED	Metarial T	- Total				\$0.00	
	0210 -	Total	Material - To	otai				\$0.00	
								\$0.00	
	0320	4 IN. WHITE	Material		5	Jul 1,	SYSTEM	<b>\$0.00</b> (\$12,228.40)	
			Material		5	Jul 1, 2025 Jul 1, 2025	SYSTEM SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the
		4 IN. WHITE WATERBORNE PAVEMENT	Material			2025 Jul 1, 2025 Jul 16,		(\$12,228.40)	
		4 IN. WHITE WATERBORNE PAVEMENT	Material		5	2025 Jul 1, 2025	SYSTEM	(\$12,228.40) \$12,228.40	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the
		4 IN. WHITE WATERBORNE PAVEMENT	Material		5	Jul 16, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40)	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item
		4 IN. WHITE WATERBORNE PAVEMENT	Material		5 6	Jul 16, 2025 Jul 16, 2025 Jul 16, 2025	SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the
		4 IN. WHITE WATERBORNE PAVEMENT	Material	- Total	5 6 6 7	Jul 16, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 (\$12,228.40)	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 21 on the
		4 IN. WHITE WATERBORNE PAVEMENT	Material  Material - To		5 6 6 7	Jul 16, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 (\$12,228.40)	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 21 on the
	0320	4 IN. WHITE WATERBORNE PAVEMENT			5 6 6 7	Jul 16, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 21 on the
	0320	4 IN. WHITE WATERBORNE PAVEMENT MARKING  - Total  4 IN. YELLOW WATERBORNE			5 6 6 7	Jul 16, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 \$0.00	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 21 on the
	0320	4 IN. WHITE WATERBORNE PAVEMENT MARKING  Total  4 IN. YELLOW	Material - To		5 6 6 7 7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 \$0.00 \$0.00	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 21 on the
	0320	4 IN. WHITE WATERBORNE PAVEMENT MARKING  Total  4 IN. YELLOW WATERBORNE PAVEMENT	Material - To		5 6 6 7 7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 \$0.00 \$0.00 \$0.00 (\$2,340.36)	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user koenib2 overridding Payment Estimate Exception 23 on the
	0320	4 IN. WHITE WATERBORNE PAVEMENT MARKING  Total  4 IN. YELLOW WATERBORNE PAVEMENT	Material - To		5 6 6 7 7 5 5	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 1, 2025 Jul 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 \$0.00 \$0.00 \$0.00 \$2,340.36	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user koenib2 overridding Payment Estimate Exception 23 on the
	0320	4 IN. WHITE WATERBORNE PAVEMENT MARKING  Total  4 IN. YELLOW WATERBORNE PAVEMENT	Material - To		5 6 6 7 7 5 5 6	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Jul 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 (\$12,228.40) \$12,228.40 \$0.00 \$0.00 \$0.00 \$2,340.36 (\$2,340.36)	Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user koenib2 overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user koenib2 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user koenib2 overridding Payment Estimate Exception 26 on the



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0050	0330	4 IN. YELLOW WATERBORNE	Material						current Payment Estimate.
		PAVEMENT MARKING		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0330 -						0)/07514	\$0.00	
	0380	MGS GUARDRAIL	Material		2	May 16, 2025		(\$5,206.50)	This adjustment offrate the original gustom generated Material Doument Estimate Item
					2	May 16, 2025	SYSTEM	\$5,206.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user koenib2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Jun 3, 2025	SYSTEM	(\$10,813.50)	
					3	Jun 3, 2025	SYSTEM	\$10,813.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schaua1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Jun 16, 2025	SYSTEM	(\$10,813.50)	
					4	Jun 16, 2025	SYSTEM	\$10,813.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user koenib2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$10,813.50)	
					5	Jul 1, 2025	SYSTEM	\$10,813.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user koenib2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$22,428.00)	
					6	Jul 16, 2025	SYSTEM	\$22,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user koenib2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$22,428.00)	
					7	Aug 4, 2025	SYSTEM	\$22,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user koenib2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0380 -							\$0.00	
	0390	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Material		2	2025	SYSTEM	(\$8,489.26)	
		, , ,			2	May 16, 2025	SYSTEM	\$8,489.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user koenib2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	<b>0390</b> -	TYPE A	Material		2		SYSTEM	<b>\$0.00</b> (\$6,861.66)	
		CRASHWORTHY END TERMINAL (MASH)			2	2025 May 16, 2025	SYSTEM	\$6,861.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user koenib2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0400 -	Total						\$0.00	
	0420	BITUMINOUS PAVEMENT MIXTURE	Other Item Adjustment	ACAD	3	Jun 3, 2025	schaua1	\$4,375.61	AC Price Adjustment for period 5/15/2025-6/1/2025 Line 0420 - 4,654.9 tons - 4.7% AC SL25-18 Mix ID
		PG64-22 (SUR			4	Jun 16, 2025	koenib2	\$91.64	AC Price Index Adjustment based on the AC Price Index Adjustment spreadsheet.  Spreadsheet placed in eprojects: http://eprojects/Docs/CD0029/240920- D04 JCD0029 JCD0050 JCD0149 Estimate 0004 0150 0420 0460 AC Adjustment.pdf
					6	Jul 16, 2025	koenib2	\$29.09	AC Index price adjustment. Supporting documentation placed on eProjects: http://eprojects/Docs/CD0029/240920-D04 JCD0029 JCD0050 JCD0149 Estimate 0006 0130 0420 AC Adjustment.pdf
				ACAD - Tot	al			\$4,496.34	DUN JODUUZA JODUUSU JODU 149 ESIIIIRIR 0000 0 130 0420 AC Adjusiment par
			Other Item	Adjustment -				\$4,496.34	
			Overrun	Overrun	4	Jun 16, 2025	SYSTEM	(\$3,416.15)	
					6	Jul 16,	SYSTEM	(\$2,630.75)	



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	0420	BITUMINOUS	Overrun	Overrun		2025			
		PAVEMENT MIXTURE		Overrun - T	otal			(\$6,046.90)	
		PG64-22 (SUR	Overrun - T	otal				(\$6,046.90)	
	0420 -	Total						(\$1,550.56)	
	Total	OLIADINO			0	1 0	OVOTEM	(\$1,550.56)	
0149	0440	SHAPING SLOPES, CLASS III	Material		3	Jun 3, 2025 Jun 3,	SYSTEM	(\$8,552.04)	This adjustment offsets the original system-generated Material Payment Estimate Item
					4	2025 Jun 16,	SYSTEM	(\$8,552.04)	Adjustment (0002) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	2025 Jun 16, 2025	SYSTEM	\$8,552.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user koenib2 overridding Payment Estimate Exception 1 on the
					5	Jul 1, 2025	SYSTEM	(\$17,104.08)	current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	\$17,104.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user koenib2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$17,104.08)	
					6	Jul 16, 2025	SYSTEM	\$17,104.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user koenib2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$17,104.08)	
					7	Aug 4, 2025	SYSTEM	\$17,104.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user koenib2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
	0440 -	Total	Material - To	otal				\$0.00 \$0.00	
	0450	GRAVEL (A) OR	Material		5	Jul 1,	SYSTEM	(\$19,125.00)	
	0.00	CRUSHED STONE (B)	, material		5	2025 Jul 1, 2025	SYSTEM	\$19,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user koenib2 overridding Payment Estimate Exception 4 on the
					6	Jul 16, 2025	SYSTEM	(\$19,125.00)	current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	\$19,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user koenib2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$19,125.00)	Contract dynamics.
					7	Aug 4, 2025	SYSTEM	\$19,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user koenib2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0450 -	Total						\$0.00	
	0460	BITUMINOUS PAVEMENT MIXTURE	Material		4	Jun 16, 2025 Jun 16,	SYSTEM	(\$499,154.00) \$499,154.00	This adjustment offsets the original system-generated Material Payment Estimate Item
		PG64-22 (SUR			7	2025	OTOTEM		Adjustment (0005) due to user koenib2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			Material - To	- Total				\$0.00 \$0.00	
			Other Item Adjustment	ACAD	4	Jun 16, 2025	koenib2	\$5,520.06	AC Price Index Adjustment based on the AC Price Index Adjustment spreadsheet.  Spreadsheet placed in eprojects: http://eprojects/Docs/CD0029/240920- D04 JCD0029 JCD0050 JCD0149 Estimate 0004 0150 0420 0460 AC Adjustment.pc
					5	Jul 1, 2025	koenib2	\$3,411.68	AC Price Index Adjustment based on the AC Price Index Adjustment spreadsheet.  Spreadsheet placed in eProjects: http://eprojects/Docs/CD0029/240920- D04 JCD0029 JCD0050 JCD0149 Estimate 0005 0140 0460 AC Adjustment.pdf
				ACAD - Tot	al			\$8,931.74	
			Other Item	ACAD - Tot Adjustment -				\$8,931.74 \$8,931.74	504_5050025_0650005_0650145_234111415_0005_0140_5405_46_48_50



ct I	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
49 (	0470	TACK COAT	Material	Туре	4	Jun 16,	SYSTEM	(\$9,657.90)	
10	5-17-0	77.01.007.11	Waterial			2025	CICILIN	(ψο,οοι .οο)	
					4	Jun 16, 2025	SYSTEM	\$9,657.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user koenib2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$14,352.10)	
					5	Jul 1, 2025	SYSTEM	\$14,352.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user koenib2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$14,352.10)	
					6	Jul 16, 2025	SYSTEM	\$14,352.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user koenib2 overridding Payment Estimate Exception 8 on th current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$14,352.10)	
					7	Aug 4, 2025	SYSTEM	\$14,352.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user koenib2 overridding Payment Estimate Exception 8 on th current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
C	0470 -	Total						\$0.00	
C		PREF THERMO PVMT MARK, 24	Material		5	Jul 1, 2025	SYSTEM	(\$1,920.00)	
		IN WHIT			5	Jul 1, 2025	SYSTEM	\$1,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user koenib2 overridding Payment Estimate Exception 11 on current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$1,920.00)	
					6	Jul 16, 2025	SYSTEM	\$1,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user koenib2 overridding Payment Estimate Exception 14 on current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$1,920.00)	
					7	Aug 4, 2025	SYSTEM	\$1,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user koenib2 overridding Payment Estimate Exception 15 on current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	5	Jul 1, 2025	SYSTEM	(\$960.00)	
				Overrun - T	otal			(\$960.00)	
			Overrun - T	otal				(\$960.00)	
	0 <b>500 -</b> 0510	PREF THERMO	Material		5	Jul 1,	SYSTEM	(\$960.00) (\$400.00)	
		PVMT MARK, LT/RT ARROW			5	Jul 1, 2025	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user koenib2 overridding Payment Estimate Exception 12 on current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$400.00)	SOLITOR COMMITTEE STATE COMMIT
					6	Jul 16, 2025	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user koenib2 overridding Payment Estimate Exception 15 on current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$400.00)	•
					7	Aug 4, 2025	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user koenib2 overridding Payment Estimate Exception 16 on current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
C	0510 -	Total						\$0.00	
C		4 IN. WHITE WATERBORNE	Material		5	Jul 1, 2025	SYSTEM	(\$20,328.00)	
		PAVEMENT MARKING			5	Jul 1, 2025	SYSTEM	\$20,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user koenib2 overridding Payment Estimate Exception 15 on tourrent Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0149	0520	4 IN. WHITE WATERBORNE	Material		6	Jul 16, 2025	SYSTEM	(\$20,328.00)	
		PAVEMENT MARKING			6	Jul 16, 2025	SYSTEM	\$20,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user koenib2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$20,328.00)	
					7	Aug 4, 2025	SYSTEM	\$20,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user koenib2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				- Total				\$0.00	current aymon Lamate.
			Material - To	otal				\$0.00	
	0520 -	- Total						\$0.00	
	0530	4 IN. YELLOW WATERBORNE	Material		5	Jul 1, 2025	SYSTEM	(\$2,524.14)	
		PAVEMENT MARKING			5	Jul 1, 2025	SYSTEM	\$2,524.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user koenib2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$2,524.14)	
					6	Jul 16, 2025	SYSTEM	\$2,524.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user koenib2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$2,524.14)	
					7	Aug 4, 2025	SYSTEM	\$2,524.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user koenib2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0530 -	- Total						\$0.00	
	0540	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	4	Jun 16, 2025	SYSTEM	(\$3,650.00)	
		KEW OF SOKE.		Overrun - T	otal			(\$3,650.00)	
			Overrun - T	otal				(\$3,650.00)	
	0540 -		Matarial		2	lum 0	CVCTEM	(\$3,650.00)	
	0560	MGS GUARDRAIL	Material		3	Jun 3, 2025	SYSTEM	(\$5,092.50)	
					3	Jun 3, 2025	SYSTEM	\$5,092.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schaua1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Jun 16, 2025	SYSTEM	(\$5,092.50)	
					4	Jun 16, 2025	SYSTEM	\$5,092.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user koenib2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$10,185.00)	
					5	Jul 1, 2025	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user koenib2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$10,185.00)	
					6	Jul 16, 2025	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user koenib2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Aug 4,	SYSTEM	(\$10,185.00)	
						2025			
					7	2025 Aug 4, 2025	SYSTEM	\$10,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user koenib2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total		Aug 4,	SYSTEM	\$10,185.00 \$0.00	Adjustment (0013) due to user koenib2 overridding Payment Estimate Exception 10 on the
			Material - To			Aug 4,	SYSTEM		Adjustment (0013) due to user koenib2 overridding Payment Estimate Exception 10 on the
	0560 -	- Total	Material - To			Aug 4,	SYSTEM	\$0.00	Adjustment (0013) due to user koenib2 overridding Payment Estimate Exception 10 on the
	<b>0560</b> - 5005	-Total  CHANGEABLE  MESSAGE SIGN WITHOUT	Material - To			Aug 4,	SYSTEM	\$0.00 \$0.00	Adjustment (0013) due to user koenib2 overridding Payment Estimate Exception 10 on the

Aug 7, 2025



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JCD0149	5005	CONTRACTOR	Material						current Payment Estimate.
		FURNISHED / RETAINED			7	Aug 4, 2025	SYSTEM	(\$4,400.00)	
					7	Aug 4, 2025	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user koenib2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5005 -	Total						\$0.00	
JCD0149	Total							\$4,321.74	
Overall - 1	otal							\$3,012.03	

# MoDOT

### Contract Adjustments for Contract - 240920-D04

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 19 of 19