	ate Number Prime Contractor Capita 6		118-C04 Pay Period Start tal Paving & Construction, LLC Pay Period End			June 16, 2025 June 30, 2025	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,247,663.35 \$0.00 \$1,247,663.35
Approval Date								By User
July 1, 2025			Generated and	Approve	d (and should be con	sidered Draft) a	t the Project Office Level by	jamesc2
July 1, 2025			Reviewed and Appr	oved (an	d should be consider	ed Draft) at the	Resident Engineer Level by	ilesb1
July 3, 2025				Reviewe	d and Approved at th	ne Central Office	e Controllers Office Level by	ramses1
Original Completion	on Date C	Current Co	ompletion Date	Act	ual Completion Dat	te %	of Current Contract Amount	Complete
November 1, 20	025	Novem	ber 1, 2025				32.63%	
	Contrac	t Informat	ional Dates				Milestones	
Date Description	Original Comple	tion Date	Current Completi	on Date	No	Milestones Ex	st for Contract	
Acceptance Date								
Awarded Date	November 8, 2024	4	November 8, 2024					
Letting Date	October 18, 2024		October 18, 2024					
Notice to Proceed Date	December 9, 2024	4	December 9, 2024					
Work Began Date	May 12, 2025		May 12, 2025					

## Contract Total Pay For Estimate No. 6

Contract Total Payable This E	stimate:	\$172,262.60			
			<mark>\$264,616.36</mark>	\$436,878.96	
Other C	ontract Adjustments	\$0.00	\$0.00	\$0.00	
Liquidat	ed Damage	\$0.00	\$0.00	\$0.00	
Disince	ntive	\$0.00	\$0.00	\$0.00	
Incentiv	e	\$0.00	\$0.00	\$0.00	
Gross I	em Adjustments	\$0.00	\$29,793.20	\$29,793.20	
Total Po	osted Items Pay	\$172,262.60	\$234,823.16	\$407,085.76	
241018-C04					
		This Estimate	Previous	To Date	

## Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JKR0090	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$18,760.900	1	\$18,760.90
	0050	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	100F	\$210.150	3	\$630.45
	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$21.750	399	\$8,678.25
	0100	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$97.000	399	\$38,703.00
	0140	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	SQYD	\$1.000	58	\$58.00
	0390	9020213	SIGNAL HEAD, TYPE 3S	EA	\$1,074.000	3	\$3,222.00
	0400	9020513	SIGNAL HEAD, TYPE 3B	EA	\$1,314.000	1	\$1,314.00
	0410	9020514	SIGNAL HEAD, TYPE 4B	EA	\$1,468.000	4	\$5,872.00
	0420	9020833	SH-FLAT SHEET - SIGNAL SIGN	SQFT	\$40.000	46	\$1,840.00
	0430	9020834	SIGNAL SIGN, MOUNTING HARDWARE	EA	\$354.000	6	\$2,124.00
	0440	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	EA	\$395.000	1	\$395.00
	0450	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	EA	\$14,640.000	1	\$14,640.00
	0460	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	EA	\$24,227.000	1	\$24,227.00
	0470	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	LF	\$35.000	13	\$455.00
	0540	9029100	BASE, CONCRETE	CUYD	\$1,450.000	3.300	\$4,785.00
	0550	9109902	MISC.VIDEO DETECTION SYSTEM	EA	\$46,558.000	1	\$46,558.00
Project JKR	0090 - Total						\$172,262.60
Overall - Tot	al						\$172,262.60

No Contract Adjustments Exist on Contract



Estimate	gress e Numb 6	Contract ID er Prime Contractor	241018-C04 Capital Paving &	Construction,	Pay Period Start LLC Pay Period End		Original Contract Net Change Orde Current Contract	er Amount	\$1,247,663.3 \$0.0 \$1,247,663.3
ine Item /	Adjustn	nents This Estimate							
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comme	nts	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JKR0090	0070	TYPE 5 AGGREGATE F BASE (6 IN. THICK)	OR Material		This adjustment offsets th generated Material Payme Adjustment (0001) due to overridding Payment Estir the current Payment Estin	ent Estimate Iten user grayw1 nate Exception 1	1	\$21.75	\$8,678.25
	0070	TYPE 5 AGGREGATE F BASE (6 IN. THICK)	OR Material				-399	\$21.75	(\$8,678.25
		CONCRETE PAVEMEN 1/2 IN. NON-REINFORC 15 FT. JOINTS)			This adjustment offsets th generated Material Payme Adjustment (0002) due to overridding Payment Estir the current Payment Estin	ent Estimate Iten user grayw1 nate Exception 3	1	\$97.00	\$38,703.00
		CONCRETE PAVEMEN 1/2 IN. NON-REINFORC 15 FT. JOINTS)					-399	\$97.00	(\$38,703.00
		FURNISHING AND PLA CONCRETE MATERIAL FULL DEPTH PAVEMEI REPAIR	FOR		This adjustment offsets th generated Material Payme Adjustment (0003) due to overridding Payment Estir the current Payment Estin	ent Estimate Iten user grayw1 nate Exception 4	1	\$217.70	\$181,418.12
		FURNISHING AND PLA CONCRETE MATERIAL FULL DEPTH PAVEMEI REPAIR	FOR				-833.34000	\$217.70	(\$181,418.12
		DOWEL BAR (DRILLING FURNISHING AND INSTALLATION) FOR F DEPTH PAVEMENT RE	ULL		This adjustment offsets th generated Material Payme Adjustment (0004) due to overridding Payment Estir the current Payment Estin	ent Estimate Iten user grayw1 nate Exception 5	1	\$4.95	\$3,118.50
		DOWEL BAR (DRILLING FURNISHING AND INSTALLATION) FOR F DEPTH PAVEMENT RE	ULL				-630	\$4.95	(\$3,118.50)
		TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR F DEPTH PAVEMENT RE (TYPE L JOINTS)			This adjustment offsets th generated Material Payme Adjustment (0005) due to overridding Payment Estir the current Payment Estin	ent Estimate Iten user grayw1 nate Exception 7	1	\$2.55	\$382.50
		TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR F DEPTH PAVEMENT RE (TYPE L JOINTS)					-150	\$2.55	(\$382.50)
	0180	CONSTRUCTION SIGN	S Material		This adjustment offsets th generated Material Payme Adjustment (0006) due to overridding Payment Estir the current Payment Estin	ent Estimate Iten user grayw1 nate Exception 9	1	\$7.00	\$1,764.00
	0180	CONSTRUCTION SIGN	S Material				-252	\$7.00	(\$1,764.00
		CHANGEABLE MESSA SIGN WITH COMMUNICATION INTERFACE, CONTRAC FURNISHED / RETAINE	CTOR		This adjustment offsets th generated Material Payme Adjustment (0007) due to overridding Payment Estir on the current Payment Est	ent Estimate Iten user grayw1 nate Exception 1	1	\$2,750.00	\$5,500.00
		CHANGEABLE MESSA SIGN WITH COMMUNICATION INTERFACE, CONTRAC FURNISHED / RETAINE	CTOR				-2	\$2,750.00	(\$5,500.00
	0340	SILT FENCE	Material		This adjustment offsets th	e original system	1- 300	\$4.80	\$1,440.00



Estimat	gress e Numl 6		018-C04 bital Paving & C	Construction,			er Amount	\$1,247,663.3 \$0.0 \$1,247,663.3
Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
<r0090< td=""><td></td><td></td><td></td><td></td><td>generated Material Payment Estimate Item Adjustment (0008) due to user grayw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.</td><td></td><td></td><td></td></r0090<>					generated Material Payment Estimate Item Adjustment (0008) due to user grayw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
	0340	SILT FENCE	Material			-300	\$4.80	(\$1,440.00)
	0390	SIGNAL HEAD, TYPE 3S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user grayw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	3	\$1,074.00	\$3,222.00
	0390	SIGNAL HEAD, TYPE 3S	Material			-3	\$1,074.00	(\$3,222.00)
	0400	SIGNAL HEAD, TYPE 3B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user grayw1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	1	\$1,314.00	\$1,314.00
	0400	SIGNAL HEAD, TYPE 3B	Material			-1	\$1,314.00	(\$1,314.00)
	0410	SIGNAL HEAD, TYPE 4B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user grayw1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	4	\$1,468.00	\$5,872.00
	0410	SIGNAL HEAD, TYPE 4B	Material			-4	\$1,468.00	(\$5,872.00)
	0440	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user grayw1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	1	\$395.00	\$395.00
	0440	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	Material			-1	\$395.00	(\$395.00)
	0450	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user grayw1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$14,640.00	\$14,640.00
	0450	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	Material			-1	\$14,640.00	(\$14,640.00)
	0460	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user grayw1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1	\$24,227.00	\$24,227.00
	0460	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material			-1	\$24,227.00	(\$24,227.00)
	0500	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user grayw1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	50	\$1.65	\$82.50
	0500	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material			-50	\$1.65	(\$82.50)
	0510	CABLE, 12 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user grayw1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	70	\$1.40	\$98.00
	0510	CABLE, 12 AWG 2 CONDUCTOR	Material			-70	\$1.40	(\$98.00)



Prog Estimate	gress e Numb 6	Contract ID ber Prime Contractor	241018-C04 Capital Paving & (	Construction,		iginal Contrac t Change Orde rrent Contract	er Amount	\$1,247,663.35 \$0.00 \$1,247,663.35
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JKR0090	0520	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user grayw1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	1,100	\$1.85	\$2,035.00
	0520	CABLE, 16 AWG 7 CONDUCTOR	Material			-1,100	\$1.85	(\$2,035.00)
	0550	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user grayw1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1	\$46,558.00	\$46,558.00
	0550	MISC.	Material			-1	\$46,558.00	(\$46,558.00)
Total								\$0.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Con	tract Project Inform	nation
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
JKR0090	FAS - S303(092)	Coldmill, resurface and add right turn lane	23	JOHNSON	from Route 50 to Route E	סט	
Totals b	y Job Nu	mbers					
JKR0090		Item Pay tem Adjustme		Item Pay	This Estimate \$172,262.60 \$0.00 <b>\$172,262.60</b>	Previous \$234,823.16 \$29,793.20 <b>\$264,616.36</b>	To Date \$407,085.76 \$29,793.20 \$436,878.96
					\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) mis Estimate renou Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 3040506, Project Item Line Number 0070, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 3040506, Project Item Line Number 0070, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 5021332, Project Item Line Number 0100, Material Set 502133296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 6131010, Project Item Line Number 0120, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 6131015, Project Item Line Number 0160, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 6131015, Project Item Line Number 0160, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 6131018, Project Item Line Number 0170, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 6131018, Project Item Line Number 0170, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 6161005, Project Item Line Number 0180, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 6161099, Project Item Line Number 0210, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 8061019, Project Item Line Number 0340, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9020213, Project Item Line Number 0390, Material Set 902021396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9020513, Project Item Line Number 0400, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9020514, Project Item Line Number 0410, Material Set 902051496, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9022651, Project Item Line Number 0440, Material Set 9022651, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9023140, Project Item Line Number 0450, Material Set 902314096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9024283, Project Item Line Number 0460, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9028208, Project Item Line Number 0500, Material Set 902820896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9028302, Project Item Line Number 0510, Material Set 902830296, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9028311, Project Item Line Number 0520, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Test needs entered.	grayw1	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0090, Item 9109902, Project Item Line Number 0550, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Test needs entered.	grayw1	Overridden



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241018-	JKR0090	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$18,760.90	\$18,760.9
C04		0001	0020	2031000	CLASS A EXCAVATION	108.00	0.00	108.00	CUYD	0.00	\$21.85	\$0.0
		0001	0030	2035500	EMBANKMENT IN PLACE	250.00	0.00	250.00	CUYD	0.00	\$33.35	\$0.0
		0001	0040	2036000	COMPACTING EMBANKMENT	359.00	0.00	359.00	CUYD	0.00	\$2.35	\$0.0
		0001	0050	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	3.00	0.00	3.00	100F	3.00	\$210.15	\$630.4
		0001	0060	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	0.00	\$700.00	\$0.0
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	399.00	0.00	399.00	SQYD	399.00	\$21.75	\$8,678.2
		0001	0080	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	4,844.20	0.00	4,844.20	TONS	0.00	\$102.65	\$0.0
		0001	0090	4071005	TACK COAT	4,386.00	0.00	4,386.00	GAL	0.00	\$2.66	\$0.0
		0001	0100	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	399.00	0.00	399.00	SQYD	399.00	\$97.00	\$38,703.0
		0001	0110	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	0.00	\$2,500.00	\$0.0
		0001	0120	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,012.00	0.00	1,012.00	SQYD	833.34	\$217.70	\$181,418.
		0001	0130	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	101.00	0.00	101.00	SQYD	0.00	\$1.00	\$0.0
		0001	0140	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	101.00	0.00	101.00	SQYD	58.00	\$1.00	\$58.0
		0001	0150	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,849.00	0.00	1,849.00	LF	1,144.00	\$1.45	\$1,658.
		0001	0160	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	693.00	0.00	693.00	EA	630.00	\$4.95	\$3,118.
		0001	0170	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	150.00	0.00	150.00	EA	150.00	\$2.55	\$382.
		0001	0180	6161005		814.00	0.00	814.00	SQFT	252.00	\$7.00	\$1,764.0
		0001	0190	6161025		100.00	0.00	100.00	EA	0.00	\$18.00	\$0.0
		0001	0200	6161040		2.00	0.00	2.00	EA	0.00	\$550.00	\$0.1
			0210	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,750.00	\$5,500.
		0001	0220	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$108,542.95	\$27,135.
		0001	0230	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.
		0001	0240	6191000	PAVEMENT EDGE TREATMENT	287.00	0.00	287.00	LF	0.00	\$6.00	\$0.
		0001	0250	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	153.00	0.00	153.00	LF	0.00	\$25.00	\$0.0
		0001	0260	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	212.00	0.00	212.00	LF	0.00	\$25.00	\$0.
		0001	0270	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	13.00	0.00	13.00	EA	0.00	\$300.00	\$0.0
		0001	0280		4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	19,259.00	0.00	19,259.00	LF	0.00	\$0.25	\$0.1
		0001	0290	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,065.00	0.00	21,065.00	LF	0.00	\$0.31	\$0.
		0001	0300	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	43,861.00	0.00	43,861.00	SQYD	0.00	\$2.03	\$0.
		0001	0310			152.60	0.00	152.60	STA	0.00	\$16.51 \$6,000.00	\$0.
		0001	0320 0330	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING SEEDING - COOL SEASON GRASSES	1.00	0.00	1.00	LS ACRE	0.00	\$8,500.00	\$0. \$0.
		0001	0340	8061019	SILT FENCE	300.00	0.00	300.00	LF	300.00	\$8,500.00	\$0.1
		0001	0340	8064132	TYPE 1B EROSION CONTROL BLANKET	320.00	0.00	320.00	SQYD	0.00	\$4.00	\$1,440.0
		0010	0360	6061060	MGS GUARDRAIL	100.00	0.00	100.00	LF	0.00	\$23.00	\$0.
		0010	0370	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	8.00	0.00	8.00	EA	0.00	\$3,307.00	\$0.
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	0.00	\$2,850.00	\$0.1
		0030	0390	9020213	SIGNAL HEAD, TYPE 3S	3.00	0.00	3.00	EA	3.00	\$1,074.00	\$3,222.
		0030	0400	9020513	SIGNAL HEAD, TYPE 3B	1.00	0.00	1.00	EA	1.00	\$1,314.00	\$1,314.
		0030	0410	9020514	SIGNAL HEAD, TYPE 4B	4.00	0.00	4.00	EA	4.00	\$1,468.00	\$5,872.
		0030	0420	9020833	SH-FLAT SHEET - SIGNAL SIGN	46.00	0.00	46.00	SQFT	46.00	\$40.00	\$1,840.
		0030	0430	9020834	SIGNAL SIGN, MOUNTING HARDWARE	6.00	0.00	6.00	EA	6.00	\$354.00	\$2,124.
		0030	0440	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	1.00	0.00	1.00	EA	1.00	\$395.00	\$395.
		0030	0450	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	1.00	0.00	1.00	EA	1.00	\$14,640.00	\$14,640.
		0030	0460	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00	\$24,227.00	\$24,227.
		0030	0470	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	13.00	0.00	13.00	LF	13.00	\$35.00	\$455.
		0030	0480	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	95.00	0.00	95.00	LF	95.00	\$28.00	\$2,660.
		0030	0490	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	131.00	0.00	131.00	LF	131.00	\$30.00	\$3,930.
		0030	0500	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	50.00	0.00	50.00	LF	50.00	\$1.65	\$82.5

## Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241018-	JKR0090	0030	0510	9028302	CABLE, 12 AWG 2 CONDUCTOR	70.00	0.00	70.00	LF	70.00	\$1.40	\$98.00
C04		0030	0520	9028311	CABLE, 16 AWG 7 CONDUCTOR	1,100.00	0.00	1,100.00	LF	1,100.00	\$1.85	\$2,035.00
		0030	0530	9028810	PULL BOX, PREFORMED CLASS 1	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0030	0540	9029100	BASE, CONCRETE	3.30	0.00	3.30	CUYD	3.30	\$1,450.00	\$4,785.00
		0030	0550	9109902	MISC.VIDEO DETECTION SYSTEM	1.00	0.00	1.00	EA	1.00	\$46,558.00	\$46,558.00
		0040	0560	9039902	MISC.RELOCATION OF EXISTING SIGN	2.00	0.00	2.00	EA	0.00	\$357.00	\$0.00
	Project Jł	(R0090 - To	otal Value	Posted to I	Date as of Report Generated Date							\$407,085.76
241018-C	04 Overall	- Total Val	ue Poste	d to Date as	of Report Generated Date							\$407,085.76



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

roject:	JKR0090	1										
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location From Stationu Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	6/20/25	6/30/25	1	1.00	LS	31.734		33.697		
0050	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	6/16/25	6/30/25	1	3.00	100F	31.734		33.697		
0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	6/16/25	6/30/25	1	399.00	SQYE	31.734		33.697		
0100	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINF,	6/20/25	6/30/25	1	399.00	SQYE	31.734		33.697		
0140	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	6/20/25	6/30/25	1	58.00	SQYE	31.734		33.697		
0390	9020213	SIGNAL HEAD, TYPE 3S	6/23/25	6/30/25	1	3.00	EA	0		1		
0400	9020513	SIGNAL HEAD, TYPE 3B	6/23/25	6/30/25	1	1.00	EA	0		1		
0410	9020514	SIGNAL HEAD, TYPE 4B	6/23/25	6/30/25	1	4.00	EA	0		1		
0420	9020833	SH-FLAT SHEET - SIGNAL SIGN	6/23/25	6/30/25	1	46.00	SQFT	0		1		
0430	9020834	SIGNAL SIGN, MOUNTING HARDWARE	6/23/25	6/30/25	1	6.00	EA	0		1		
0440	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	6/23/25	6/30/25	1	1.00	EA	0		1		
0450	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	6/23/25	6/30/25	1	1.00	EA	0		1		
0460	9024283	CONTROLLER ASSEMBLY HOUSING,	6/23/25	6/30/25	1	1.00	EA	0		1		
0470	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	6/23/25	6/30/25	1	13.00	LF	0		1		
0540	9029100	BASE, CONCRETE	6/23/25	6/30/25	1	3.30	CUYE	0		1		
0550	9109902	MISC. ITS	6/23/25	6/30/25	1	1.00	EA	0		1		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025



Jul 4, 2025

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0090	0070	TYPE 5 AGGREGATE	Material		6	Jun 30, 2025	SYSTEM	(\$8,678.25)	
		FOR BASE (6 IN. THICK)			6	Jun 30, 2025	SYSTEM	\$8,678.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0070 -							\$0.00	
	0100	CONCRETE PAVEMENT (8 1/2 IN. NON-REINF,	Material		6	Jun 30, 2025	SYSTEM	(\$38,703.00)	
					6	Jun 30, 2025	SYSTEM	\$38,703.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0100 -	Total						\$0.00	
	0120	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		4	Jun 2, 2025	SYSTEM	(\$83,307.26)	
					4	Jun 2, 2025	SYSTEM	\$83,307.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$181,418.12)	
					5	Jun 16, 2025	SYSTEM	\$181,418.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 30, 2025	SYSTEM	(\$181,418.12)	
					6	Jun 30, 2025	SYSTEM	\$181,418.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -	Total						\$0.00	
	0160	DOWEL BAR (DRILLING, FURNISHING AND	Material		4	Jun 2, 2025	SYSTEM	(\$841.50)	
	0160	(DRILLING,	Material		4		SYSTEM SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	0160	(DRILLING, FURNISHING AND	Material			2025 Jun 2,		(\$841.50)	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment
	0160	(DRILLING, FURNISHING AND	Material		4	2025 Jun 2, 2025 Jun 16,	SYSTEM	(\$841.50) \$841.50	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment
	0160	(DRILLING, FURNISHING AND	Material		4	2025 Jun 2, 2025 Jun 16, 2025 Jun 16,	SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50)	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment
	0160	(DRILLING, FURNISHING AND	Material		4 5 5	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30,	SYSTEM SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50) \$3,118.50	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment
	0160	(DRILLING, FURNISHING AND	Material	- Total	4 5 5 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50) \$3,118.50 (\$3,118.50)	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment
	0160	(DRILLING, FURNISHING AND	Material Material - To		4 5 5 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50) \$3,118.50 (\$3,118.50) \$3,118.50	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment
	0160 0160 -	(DRILLING, FURNISHING AND INST			4 5 5 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50) \$3,118.50 (\$3,118.50) \$3,118.50 \$0.00	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment
	0160 -	(DRILLING, FURNISHING AND INST Total TIE BAR (DRILL, FURN & INSTAL)			4 5 5 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50) \$3,118.50 (\$3,118.50) \$3,118.50 \$0.00	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment
	0160 -	(DRILLING, FURNISHING AND INST	Material - To		4 5 6 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jun 30, 2025 Jun 30, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50) \$3,118.50 (\$3,118.50) \$3,118.50 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment
	0160 -	(DRILLING, FURNISHING AND INST Total TIE BAR (DRILL, FURN & INSTAL)	Material - To		4 5 5 6 6 4	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jun 30, 2025 Jun 2, 2025 Jun 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50) \$3,118.50 (\$3,118.50) \$3,118.50 \$0.00 \$0.00 \$0.00 (\$198.90)	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	0160 -	(DRILLING, FURNISHING AND INST Total TIE BAR (DRILL, FURN & INSTAL)	Material - To		4 5 5 6 6 6 4 4	2025 Jun 2, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jun 30, 2025 Jun 2, 2025 Jun 2, 2025 Jun 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$841.50) \$841.50 (\$3,118.50) \$3,118.50 (\$3,118.50) \$3,118.50 \$0.00 \$0.00 \$0.00 \$0.00 \$198.90 \$198.90	Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Jul 4, 2025

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
R0090	0170	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		6	2025 Jun 30, 2025	SYSTEM	\$382.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment
				- Total				\$0.00	Estimate Exception 7 on the current Payment Estimate.
			Material - To	tal				\$0.00	
	0170 -	Total						\$0.00	
	0180	CONSTRUCTION SIGNS	Material		3	May 16, 2025	SYSTEM	(\$1,764.00)	
					3	May 16, 2025	SYSTEM	\$1,764.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 2, 2025	SYSTEM	(\$1,764.00)	
					4	Jun 2, 2025	SYSTEM	\$1,764.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$1,764.00)	
					5	Jun 16, 2025	SYSTEM	\$1,764.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user grayw1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Jun 30, 2025	SYSTEM	(\$1,764.00)	
					6	Jun 30, 2025	SYSTEM	\$1,764.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user grayw1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0180 -	Total						\$0.00	
		CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR	Material		2	May 1, 2025	SYSTEM	(\$5,500.00)	
		INTERFACE, CONTRACTOR			2	May 1, 2025	SYSTEM	\$5,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		INTERFACE,			2 3		SYSTEM SYSTEM	\$5,500.00 (\$5,500.00)	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment
		INTERFACE, CONTRACTOR FURNISHED /				2025 May 16,			Estimate Item Adjustment (0001) due to user grayw1 overridding Payment
		INTERFACE, CONTRACTOR FURNISHED /			3	2025 May 16, 2025 May 16,	SYSTEM	(\$5,500.00)	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment
		INTERFACE, CONTRACTOR FURNISHED /			3	2025 May 16, 2025 May 16, 2025 Jun 2,	SYSTEM SYSTEM	(\$5,500.00) \$5,500.00	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment
		INTERFACE, CONTRACTOR FURNISHED /			3 3 4	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2,	SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00 (\$5,500.00)	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment
		INTERFACE, CONTRACTOR FURNISHED /			3 3 4 4	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment
		INTERFACE, CONTRACTOR FURNISHED /			3 3 4 4 5	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00 (\$5,500.00)	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate.
		INTERFACE, CONTRACTOR FURNISHED /			3 3 4 4 5 5	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate.
		INTERFACE, CONTRACTOR FURNISHED /		- Total	3 3 4 4 5 5 5 6	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00 (\$5,500.00)	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material - To		3 3 4 4 5 5 5 6	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00) (\$5,500.00) \$5,500.00) (\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	0210 -	INTERFACE, CONTRACTOR FURNISHED / RETAINED			3 3 4 4 5 5 5 6 6	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00) (\$5,500.00) (\$5,500.00) (\$5,500.00) (\$5,500.00) (\$5,500.00) (\$5,500.00) \$5,500.00 (\$0.00	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material - To Material		3 3 4 4 5 5 6 6 6	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jun 30, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00 (\$5,500.00) \$5,500.00 \$0.00 \$0.00 \$0.00 \$0.00 (\$1,440.00)	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		INTERFACE, CONTRACTOR FURNISHED / RETAINED			3 3 4 4 5 5 5 6 6	2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jun 30, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,500.00) \$5,500.00) (\$5,500.00) (\$5,500.00) (\$5,500.00) (\$5,500.00) (\$5,500.00) (\$5,500.00) \$5,500.00 (\$0.00	Estimate Item Adjustment (0001) due to user grayw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grayw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user grayw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.



Jul 4, 2025

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
090	0340	SILT FENCE	Material			2025			
					6	Jun 30, 2025	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user grayw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0340 - Total							\$0.00	
	0360	MGS GUARDRAIL	Construction Stockpile STMI		3	May 16, 2025	SYSTEM	\$1,230.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,230.00	
			Construction	Stockpile S	TMI - Tota	I		\$1,230.00	
	0360 -							\$1,230.00	
	0370	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Construction Stockpile STMI	Tetal	3	May 16, 2025	SYSTEM	\$13,608.80	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$13,608.80	
			Construction	Stockpile S	TMI - Tota	I		\$13,608.80	
	0370 -		0.1.1		0		OVOTEN	\$13,608.80	
	0380	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI	- Total	3	May 16, 2025	SYSTEM	\$14,954.40	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)	Construction	Stockpile S				\$14,954.40	
	0290	Total	Construction	I Stockpile S	rivii - Tota				
	0380 - 0390	SIGNAL HEAD, TYPE 3S	Material		6	Jun 30, 2025	SYSTEM	<b>\$14,954.40</b> (\$3,222.00)	
					6	Jun 30, 2025	SYSTEM	\$3,222.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user grayw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0390 - Total							\$0.00	
	0400	SIGNAL HEAD, TYPE 3B	Material		6	Jun 30, 2025	SYSTEM	(\$1,314.00)	
					6	Jun 30, 2025	SYSTEM	\$1,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user grayw1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0400 -	Total						\$0.00	
		SIGNAL HEAD, TYPE 4B	Material		6	Jun 30, 2025	SYSTEM	(\$5,872.00)	
					6	Jun 30, 2025	SYSTEM	\$5,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user grayw1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0410 -	Total						\$0.00	
	0440	LUMINAIRE LED- A, 120 VOLT COMPATIBLE	Material		6	Jun 30, 2025	SYSTEM	(\$395.00)	
					6	Jun 30, 2025	SYSTEM	\$395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user grayw1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0440 -	Total						\$0.00	
	0450		FT. ARM OR		6	Jun 30, 2025	SYSTEM	(\$14,640.00)	
					6	Jun 30, 2025	SYSTEM	\$14,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user grayw1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



roject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
rojeci	LINE	Description	Туре	Adjustment Type		Date	By	Amount	Reindriks
R0090	0450	POST, TYPE CL, 40 FT. ARM OR	Material	- Total				\$0.00	
		12.2 M ARM	Material - To	tal				\$0.00	
	0450	Total							
	0460	CONTROLLER ASSEMBLY HOUSING,	Material		6	Jun 30, 2025	SYSTEM	(\$24,227.00)	
					6	Jun 30, 2025	SYSTEM	\$24,227.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user grayw1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0460 -	Total						\$0.00	
	0500	CABLE, 8 AWG 1 CONDUCTOR,	Material		3	May 16, 2025	SYSTEM	(\$82.50)	
		POWER			3	May 16, 2025	SYSTEM	\$82.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user grayw1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jun 2, 2025	SYSTEM	(\$82.50)	
					4	Jun 2, 2025	SYSTEM	\$82.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user grayw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$82.50)	
					5	Jun 16, 2025	SYSTEM	\$82.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user grayw1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Jun 30, 2025	SYSTEM	(\$82.50)	
					6	Jun 30, 2025	SYSTEM	\$82.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user grayw1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0500 -	Total						\$0.00	
	0510	CABLE, 12 AWG 2 CONDUCTOR	Material		3	May 16, 2025	SYSTEM	(\$98.00)	
					3	May 16, 2025	SYSTEM	\$98.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user grayw1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Jun 2, 2025	SYSTEM	(\$98.00)	
					4	Jun 2, 2025	SYSTEM	\$98.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user grayw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$98.00)	
					5	Jun 16, 2025	SYSTEM	\$98.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user grayw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Jun 30, 2025	SYSTEM	(\$98.00)	
					6	Jun 30, 2025	SYSTEM	\$98.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user grayw1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0510 -	Total						\$0.00	
	0520	CABLE, 16 AWG 7 CONDUCTOR	Material		3	May 16, 2025	SYSTEM	(\$2,035.00)	
					3	May 16, 2025	SYSTEM	\$2,035.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user grayw1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Jun 2,	SYSTEM	(\$2,035.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0090	0520	CABLE, 16 AWG 7 CONDUCTOR	Material			2025			
					4	Jun 2, 2025	SYSTEM	\$2,035.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user grayw1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$2,035.00)	
					5	Jun 16, 2025	SYSTEM	\$2,035.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user grayw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Jun 30, 2025	SYSTEM	(\$2,035.00)	
					6	Jun 30, 2025	SYSTEM	\$2,035.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user grayw1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
	0520 -	Total						\$0.00	
	0550	MISC. ITS	Material		6	Jun 30, 2025	SYSTEM	(\$46,558.00)	
					6	Jun 30, 2025	SYSTEM	\$46,558.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user grayw1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				- Total				\$0.00	
		Material - Total							
	0550 - Total							\$0.00	
JKR0090	KR0090 - Total								
Overall -	Total						\$29,793.20		



There are no contract adjustments to display for this contract.