

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 18, 2025

| Progress Estimate Number 9 | Contract ID Prime Contract | | 241018-C05 r Superior Bowen Asphalt Company, LLC | | | August 2, 2025 August 15, 2025 | Original Contract Amount Net Change Order Amount Current Contract Amount | \$7,723,606.90 (\$698,813.56) \$7,024,793.34 | | |
|----------------------------------|-------------------------------|-------------|---|------------|----------------------|--|--|--|--|--|
| Approval Date | | | | | | | | By User | | |
| August 18, 2025 | | | Generated and | Approved | d (and should be cor | nsidered Draft) at | the Project Office Level by | doggea1 | | |
| August 18, 2025 | | | Reviewed and Appr | roved (and | d should be conside | red Draft) at the F | esident Engineer Level by | sandis1 | | |
| August 20, 2025 | | | | Reviewe | d and Approved at t | he Central Office | Controllers Office Level by | ramses1 | | |
| Original Completion Date Current | | | Completion Date Actual Completion | | | Date % of Current Contract Amount Complete | | | | |
| November 1, 2 | 025 | Noven | ember 1, 2025 | | | | 88.45% | | | |
| | Conti | act Informa | tional Dates | | | | Milestones | | | |
| Date Description | Original Comp | letion Date | Current Completio | n Date | No | Milestones Exist | for Contract | | | |
| Acceptance Date | | | | | | | | | | |
| Awarded Date | November 8, 20 | 024 | November 8, 2024 | | | | | | | |
| Letting Date | October 18, 202 | 24 | October 18, 2024 | | | | | | | |
| Notice to Proceed Date | December 9, 20 | 024 | December 9, 2024 | | | | | | | |
| Work Began Date | | | | | | | | | | |

| Contract Total Pa | ay For Estimate No. 9 | | | |
|-------------------|----------------------------|---------------|----------------|----------------|
| | | This Estimate | Previous | To Date |
| 241018-C05 | | | | |
| | Total Posted Items Pay | \$35,071.20 | \$6,178,257.70 | \$6,213,328.90 |
| | Gross Item Adjustments | (\$2,380.18) | (\$256,241.67) | (\$258,621.85) |
| | Incentive | \$0.00 | \$0.00 | \$0.00 |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 |
| | • | | \$5,922,016.03 | \$5,954,707.05 |
| Contract Total Pa | avable This Estimate: | \$32,691,02 | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|---|------|---------------|--------------------------|-----------------------------|
| JKU0018 | 0180 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | LF | \$24.000 | 94 | \$2,256.00 |
| | 0190 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | EA | \$350.000 | 6 | \$2,100.00 |
| | 0220 | 6200036 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | EA | \$300.000 | 17 | \$5,100.00 |
| | 0230 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | LF | \$0.260 | 34,984.500 | \$9,095.97 |
| | 0240 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | LF | \$0.260 | 33,205 | \$8,633.30 |
| | 0250 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | LF | \$0.500 | 10,574 | \$5,287.00 |
| | 0300 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | STA | \$26.530 | 97.962 | \$2,598.93 |

 Project JKU0018 - Total
 \$35,071.20

 Overall - Total
 \$35,071.20

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| | | ments This Estimate | | | | | | |
|-------------------|-------------|---------------------|--------------------|----------------------------------|---|------------------------|---------------------------------------|-------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| JKU0018 | 0030 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user doggea1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 19,155 | \$3.75 | \$71,831.25 |
| | 0030 | MISC. | Material | | | -19,155 | \$3.75 | (\$71,831.25) |
| | 0180 | PREFORMED | Material | | This adjustment offsets the original system- | 153 | \$24.00 | \$3,672.00 |

Revision 5/29/2025 Page 1 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 18, 2025

Progress Contract ID 241018-C05 Pay Period Start August 2, 2025 Original Contract Amount \$7,723,606.90 Pay Period End August 15, 2025 Prime Contract Amount 9,7024,793.34

| | | | | | Surrent Contract | | \$7,024,793.34 |
|--------------------|--|--------------------------|----------------------------------|--|------------------------|---------------------------------------|-------------------|
| ect Line per No | | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| 8 | THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | | | generated Material Payment Estimate Item Adjustment (0002) due to user doggea1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | |
| 018 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | | -153 | \$24.00 | (\$3,672.00) |
| 019 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user doggea1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | 8 | \$350.00 | \$2,800.00 |
| 019 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Material | | | -8 | \$350.00 | (\$2,800.00) |
| 020 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user doggea1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | 1 | \$350.00 | \$350.00 |
| 020 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | Material | | | -1 | \$350.00 | (\$350.00) |
| 021 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user doggea1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | 3 | \$450.00 | \$1,350.00 |
| 021 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT | Material | | | -3 | \$450.00 | (\$1,350.00) |
| 022 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user doggea1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | 34 | \$300.00 | \$10,200.00 |
| 022 | 0 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | Material | | | -34 | \$300.00 | (\$10,200.00) |
| 023 | 0 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user doggea1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | 34,984.50000 | \$0.26 | \$9,095.97 |
| 023 | 0 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | | -34,984.50000 | \$0.26 | (\$9,095.97) |
| 023 | 0 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Other Item Adjustment | Other | This line item adjustment is created to withhold 10%. Awaiting retro reflectivity results. | | | (\$909.60) |
| 024 | 0 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user doggea1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | 33,205 | \$0.26 | \$8,633.30 |
| | | | | | -33,205 | \$0.26 | (\$8,633.30) |

Revision 5/29/2025 Page 2 of 24

\$9,000.00

\$300.00

30



0600 PREFORMED

THERMOPLASTIC
PAVEMENT MARKING, 30 IN

Missouri Department of Transportation Contractor's Pay Estimate Summary

| Estimate | gress e Numl 9 | | 18-C05 rior Bowen As | sphalt Compa | iny, LLC Pay Period End August 15, 2025 | Original Contrac Net Change Orde Current Contract | er Amount | \$7,723,606.90 (\$698,813.56 \$7,024,793.34 |
|-------------------|----------------------|--|--------------------------|----------------------------------|--|---|---------------------------------------|---|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| JKU0018 | | WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | | | | | | |
| | 0240 | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Other Item Adjustment | Other | This line item adjustment is created to withhold 10%. Awaiting retro reflectivity results. | | | (\$863.30) |
| | 0250 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user doggea1 overridding Payment Estimate Exception 25 on the current Payment Estimate. | 10,574 | \$0.50 | \$5,287.00 |
| | 0250 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | | -10,574 | \$0.50 | (\$5,287.00) |
| | 0250 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Other Item Adjustment | Other | This line item adjustment is created to withhold 10%. Awaiting retro reflectivity results. | | | (\$528.70) |
| | 0300 | BITUMINOUS SHOULDER RUMBLE STRIP | Overrun | | | -2.96200 | \$26.53 | (\$78.58) |
| JKU0029 | 0390 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user doggea1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 11,731.54000 | \$3.25 | \$38,127.51 |
| | 0390 | MISC. | Material | | | -11,731.54000 | \$3.25 | (\$38,127.51) |
| | 0400 | CONCRETE PAVEMENT (10 IN. NON-REINF) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user doggea1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 4.60000 | \$103.45 | \$475.87 |
| | 0400 | CONCRETE PAVEMENT (10 IN. NON-REINF) | Material | | | -4.60000 | \$103.45 | (\$475.87 |
| | 0430 | INTEGRAL CURB TYPE M | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user doggea1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | 7 | \$94.15 | \$659.05 |
| | 0430 | INTEGRAL CURB TYPE M | Material | | | -7 | \$94.15 | (\$659.05) |
| | 0490 | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user doggea1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | 1 | \$1,437.50 | \$1,437.50 |
| | 0490 | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | Material | | | -1 | \$1,437.50 | (\$1,437.50) |
| | 0580 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user doggea1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | 673 | \$24.00 | \$16,152.00 |
| | 0580 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | | -673 | \$24.00 | (\$16,152.00) |
| | | | | | | | | |

Revision 5/29/2025 Page 3 of 24

Material

This adjustment offsets the original systemgenerated Material Payment Estimate Item Adjustment (0016) due to user doggea1



Missouri Department of Transportation Contractor's Pay Estimate Summary

| | | | 18-C05 rior Bowen As | sphalt Compa | Pay Period Start August 2, 2025 iny, LLC Pay Period End August 15, 2025 | Original Contract Net Change Orde Current Contract | er Amount | \$7,723,606.90 (\$698,813.56 \$7,024,793.34 |
|---------------|-------------|---|-------------------------|----------------------------------|--|--|---------------------------------------|---|
| oject mber | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J0029 | | WHITE MIDBLOCK | | | overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | |
| | 0600 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | Material | | | -30 | \$300.00 | (\$9,000.00 |
| | 0610 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user doggea1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | 41 | \$85.00 | \$3,485.00 |
| | 0610 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES | Material | | | -41 | \$85.00 | (\$3,485.00 |
| | 0620 | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user doggea1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | 24,977 | \$0.26 | \$6,494.02 |
| | 0620 | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | | -24,977 | \$0.26 | (\$6,494.02 |
| | 0630 | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user doggea1 overridding Payment Estimate Exception 23 on the current Payment Estimate. | 17,721 | \$0.26 | \$4,607.46 |
| | 0630 | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | | -17,721 | \$0.26 | (\$4,607.46 |
| | 0640 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user doggea1 overridding Payment Estimate Exception 27 on the current Payment Estimate. | 6,280 | \$0.50 | \$3,140.00 |
| | 0640 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | | -6,280 | \$0.50 | (\$3,140.00 |
| | 0650 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user doggea1 overridding Payment Estimate Exception 29 on the current Payment Estimate. | 1,437 | \$0.12 | \$172.44 |
| | 0650 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -1,437 | \$0.12 | (\$172.44 |
| | 0660 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user doggea1 overridding Payment Estimate Exception 31 on the current Payment Estimate. | 1,358 | \$0.12 | \$162.96 |
| | 0660 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -1,358 | \$0.12 | (\$162.96) |
| | 0670 | 8 IN. WHITE STANDARD WATERBORNE PAVEMENT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item | 619 | \$0.35 | \$216.65 |

Revision 5/29/2025 Page 4 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 18, 2025

| Prog Estimate | gress e Numl 9 | | 118-C05 erior Bowen As | sphalt Compa | any, LLC Pay Period End August 15, 2025 | Original Contrac Net Change Orde Current Contract | r Amount | \$7,723,606.90 (\$698,813.56) \$7,024,793.34 |
|-------------------|----------------------|---|--|--------------|--|---|---------------------------------------|--|
| Project Number | Line No. | Item Description | Adjustment Type Other Item Adjustment Type | | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| JKU0029 | | MARKING PAINT, TYPE P BEADS | | | Adjustment (0023) due to user doggea1 overridding Payment Estimate Exception 33 on the current Payment Estimate. | | | |
| | 0670 | 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -619 | \$0.35 | (\$216.65) |
| | 0740 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user doggea1 overridding Payment Estimate Exception 36 on the current Payment Estimate. | 6 | \$5,500.00 | \$33,000.00 |
| | 0740 | MISC. | Material | | | -6 | \$5,500.00 | (\$33,000.00) |
| Total | | | | | | | | (\$2,380.18) |

Revision 5/29/2025 Page 5 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | Co | ontract Project Informa | ition | | | | | |
|-------------------|---|---|-------|------------|---|--|---|--|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work | | | | | |
| JKU0018 | IS-35-1 (296) | Coldmill and resurface | I-35 | JACKSON | from I-70 to Kansas state | om I-70 to Kansas state line | | | | | | |
| JKU0029 | IS-670-1 (160) | Coldmill and resurface | I-670 | JACKSON | from the Belleview Overp | n the Belleview Overpass to Troost Avenue | | | | | | |
| Totals b | y Job N | umbers | | | | | | | | | | |
| JKU0018 | Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive | | | s Item Pay | This Estimate \$35,071.20 (\$2,380.18) \$32,691.02 \$0.00 | Previous \$4,238,949.08 (\$236,236,96) \$4,002,712.12 \$0.00 | To Date \$4,274,020.28 (\$238,617.14) \$4,035,403.14 \$0.00 | | | | | |
| | Liquid | centive dated Damages Contract Adju | | . | \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 | | | | | |
| JKU0029 | | d Item Pay Item Adjustm | | s Item Pay | This Estimate \$0.00 \$0.00 \$0.00 | Previous \$1,939,308.62 (\$20,004.71) \$1,919,303.91 | To Date \$1,939,308.62 (\$20,004.71) \$1,919,303.91 | | | | | |
| | Liquid | tive centive dated Damages Contract Adju | | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | | | | |

Revision 5/29/2025 Page 6 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|---|---|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 4079912, Project Item Line Number 0030, Material Set 407991296, Material 1015EASS1VH - Emulsified Asphalt - Non-Tracking Tack, Acceptance Action Generic AspEmulsion is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 4079912, Project Item Line Number 0390, Material Set 407991296, Material 1015EASS1VH - Emulsified Asphalt - Non-Tracking Tack, Acceptance Action Generic AspEmulsion is insufficient. | This exception will be removed once 28day compressive strength testing results are uploaded. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 5021110, Project Item Line Number 0400, Material Set 502111096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient. | This exception will be removed once 28day compressive strength testing results are uploaded. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 5021110, Project Item Line Number 0400, Material Set 502111096, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient. | This exception will be removed once 28day compressive strength testing results are uploaded. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 5021110, Project Item Line Number 0400, Material Set 502111096, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | This exception will be removed once 28day compressive strength testing results are uploaded. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 5021110, Project Item Line Number 0400, Material Set 502111096, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient. | This exception will be removed once 28day compressive strength testing results are uploaded. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6092013, Project Item Line Number 0430, Material Set 609201396, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient. | This exception will be removed once 28day compressive strength testing results are uploaded. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6141121, Project Item Line Number 0490, Material Set 614112196, Material 0614DFGTCV - Curved Vane Grate and Frame, Acceptance Action Generic 0614DFGTCV is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6200015, Project Item Line Number 0180, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6200015, Project Item Line Number 0580, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6200021, Project Item Line Number 0190, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6200024, Project Item Line Number 0200, Material Set 620002496, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6200027, Project Item Line Number 0210, Material Set 620002796, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6200036, Project Item Line Number 0220, Material Set 620003696, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6200036, Project Item Line Number 0600, Material Set 620003696, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6200042, Project Item Line Number 0610, Material Set 620004296, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6205902A, Project Item Line Number 0230, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6205902A, Project Item Line Number 0230, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6205902A, Project Item Line Number 0620, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6205902A, Project Item Line Number 0620, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6205903A, Project Item Line Number 0240, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | No Remark was entered by Engineer | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6205903A, Project Item Line Number 0240, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6205903A, Project Item Line Number 0630, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6205903A, Project Item Line Number 0630, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |

Revision 5/29/2025 Page 7 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|--|---|---------------|--------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient. | | | |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6205906A, Project Item Line Number 0250, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0018, Item 6205906A, Project Item Line Number 0250, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6205906A, Project Item Line Number 0640, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6205906A, Project Item Line Number 0640, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6206000C, Project Item Line Number 0650, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6206000C, Project Item Line Number 0650, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6206001C, Project Item Line Number 0660, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6206001C, Project Item Line Number 0660, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6206108A, Project Item Line Number 0670, Material Set 6206108A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6206108A, Project Item Line Number 0670, Material Set 6206108A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 6206108A, Project Item Line Number 0670, Material Set 6206108A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0029, Item 9029902, Project Item Line Number 0740, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. | This exception will be removed once the contractor has submitted certifications for this line item. | doggea1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0018, Project Item Line Number 0300, Contract Line Item Number 0300, Item 6261000A, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0029, Project Item Line Number 0610, Contract Line Item Number 0610, Item 6200042, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0029, Project Item Line Number 0650, Contract Line Item Number 0650, Item 6206000C, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0029, Project Item Line Number 0660, Contract Line Item Number 0660, Item 6206001C, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0029, Project Item Line Number 0670, Contract Line Item Number 0670, Item 6206108A, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0029, Project Item Line Number 0740, Contract Line Item Number 0740, Item 9029902, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0018, Project Item Line Number 0020, Contract Line Item Number 0020, Item 4030132, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0029, Project Item Line Number 0370, Contract Line Item Number 0370, Item 4030009, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 241018-C05, Contract Project JKU0029, Project Item Line Number 0730, Contract Line Item Number 0730, Item 6221001, Minor Item. | Item will appear on change order. | doggea1 | Acknowledged |

Revision 5/29/2025 Page 8 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Project No. | Category | Line No. | Item Code | on Report Generated date and can differ from the posts Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|----------------|--------------|-------------|----------------------|--|------------------------|------------------------|------------------------------|------|------------------------------------|------------------|--|
| JKU0018 | 0001 | 0010 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | 6,122.20 | -200.29 | 5,921.91 | TONS | 2,139.98 | \$128.75 | \$275,522.4 |
| | 0001 | 0020 | 4030132 | ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX) | 16,079.70 | -452.53 | 15,627.17 | TONS | 17,346.50 | \$146.75 | \$2,545,598.8 |
| | 0001 | 0030 | 4079912 | MISC.BONDED ASPHALTIC CONCRETE PAVEMENT | 27,086.00 | -795.87 | 26,290.13 | GAL | 19,155.00 | \$3.75 | \$71,831. |
| | 0001 | 0040 | 6131010 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | 80.00 | 54.70 | 134.70 | SQYD | 134.70 | \$680.70 | \$91,690.2 |
| | 0001 | 0050 | 6131012 | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) | 8.00 | -8.00 | 0.00 | SQYD | 0.00 | \$1.00 | \$0. |
| | 0001 | 0060 | 6131013 | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) | 8.00 | -8.00 | 0.00 | SQYD | 0.00 | \$1.00 | \$0. |
| | 0001 | 0070 | 6131014 | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) | 360.00 | 226.00 | 586.00 | LF | 586.00 | \$1.45 | \$849. |
| | 0001 | 0800 | 6131015 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | 200.00 | -5.00 | 195.00 | EA | 195.00 | \$4.85 | \$945. |
| | 0001 | 0090 | 6161005 | CONSTRUCTION SIGNS | 2,233.00 | 0.00 | 2,233.00 | SQFT | 1,328.00 | \$5.50 | \$7,304. |
| | | 0100 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$50.00 | \$0. |
| | 0001 | 0110 | 6161025 | CHANNELIZER (TRIM-LINE) | 1,000.00 | 0.00 | 1,000.00 | EA | 536.00 | \$15.00 | \$8,040 |
| | | 0120 | 6161030 | TYPE 3 MOVEABLE BARRICADE | 40.00 | 0.00 | 40.00 | EA | 12.00 | \$100.00 | \$1,200 |
| | 0001 | 0130 | 6161033 | DIRECTION INDICATOR BARRICADE | 250.00 | 0.00 | 250.00 | EA | 0.00 | \$30.00 | \$0. |
| | 0001 | 0140 | 6161040 | FLASHING ARROW PANEL | 16.00 | 0.00 | 16.00 | EA | 11.00 | \$600.00 | \$6,600 |
| | 0001 | 0150 | 6161055 | SEQUENTIAL FLASHING WARNING LIGHT | 225.00 | 0.00 | 225.00 | EA | 0.00 | \$40.00 | \$0. |
| | 0001 | 0160 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED | 16.00 | 0.00 | 16.00 | EA | 15.00 | \$1,800.00 | \$27,000. |
| | 0001 | 0170 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 0.88 | \$575,000.00 | \$503,700. |
| | 0001 | 0180 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 248.00 | 0.00 | 248.00 | LF | 153.00 | \$24.00 | \$3,672. |
| | 0001 | 0190 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$350.00 | \$2,800. |
| | 0001 | 0200 | 6200024 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$350.00 | \$350. |
| | 0001 | 0210 | 6200027 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$450.00 | \$1,350. |
| | 0001 | 0220 | 6200036 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | 39.00 | 0.00 | 39.00 | EA | 34.00 | \$300.00 | \$10,200.0 |
| | 0001 | 0230 | 6205902A 6205903A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT | 56,176.00 40,151.00 | -885.00 -530.00 | 55,291.00 39,621.00 | LF | 34,984.50 | \$0.26 \$0.26 | \$9,095.9 \$8,633.3 |
| | 0001 | 0250 | 6205906A | MARKING PAINT, TYPE L BEADS 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT | 14,112.00 | -442.00 | 13,670.00 | LF | 10,574.00 | \$0.50 | \$5,287. |
| | 0001 | 0260 | 6206000C | MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING | 247.00 | 0.00 | 247.00 | LF | 0.00 | \$0.12 | \$0. |
| | 0001 | 0270 | 6206001C | PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT | 1,869.00 | 0.00 | 1,869.00 | LF | 0.00 | \$0.12 | \$0. |
| | 0001 | 0280 | 6207001 | MARKING PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL | 13,469.00 | 0.00 | 13,469.00 | LF | 0.00 | \$1.00 | \$0. |
| | 0001 | 0290 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 135,427.00 | -3,979.36 | 131,447.64 | SQYD | 83,163.70 | \$5.50 | \$457,400 |
| | 0001 | 0300 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 95.00 | 0.00 | 95.00 | STA | 97.96 | \$26.53 | \$2,598. |
| | 0070 | 0310 | 2161501 | REMOVAL OF ASPHALT WEARING SURFACE | 12,547.00 | 0.00 | 12,547.00 | SQFT | 12,547.00 | \$6.75 | \$84,692. |
| | 0070 | 0320 | 4031050 | OPTIONAL ASPHALTIC CONCRETE WEARING SURFACE (BRIDGES) | 1,394.00 | 0.00 | 1,394.00 | SQYD | 1,394.00 | \$85.00 | \$118,490 |
| | 0070 | 0330 | 7111001 | WATERPROOFING MEMBRANE | 1,394.00 | 0.00 | 1,394.00 | SQYD | 741.25 | \$39.35 | \$29,168 |
| Project . | IKU0018 - To | otal Value | Posted to D | ate as of Report Generated Date | | | | | | | \$4,274,020 |
| JKU0029 | 0001 | 0340 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$3,889.50 | \$3,889. |
| | 0001 | 0350 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 5.00 | 0.00 | 5.00 | SQYD | 0.00 | \$19.35 | \$0. |
| | 0001 | 0360 | 4011211 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2) | 1,657.00 | -225.10 | 1,431.90 | TONS | 1,069.12 | \$125.00 | \$133,640. |
| | 0001 | 0370 | 4030009 | ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095BSM MIX) | 13,320.00 | -3,990.36 | 9,329.64 | TONS | 9,433.30 | \$128.00 | \$1,207,462 |
| | 0001 | 0380 | 4071005 | TACK COAT | 262.00 | 0.00 | 262.00 | GAL | 0.00 | \$3.25 | \$0. |
| | 0001 | 0390 | 4079912 | MISC.BONDED APSHALTIC CONCRETE PAVEMENT | 19,872.00 | -5,153.70 | 14,718.30 | GAL | 11,731.54 | \$3.25 | \$38,127 |
| | 0001 | 0400 | 5021110 | CONCRETE PAVEMENT (10 IN. NON-REINF) | 4.60 | 0.00 | 4.60 | SQYD | 4.60 | \$103.45 | \$475. |
| | 0001 | 0410 | 6042020 | ADJUSTING BASIN OR INLET | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$658.90 | \$658. |
| | 0001 | 0420 | 6049902 | MISC.DROP INLET CLEANOUT | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$358.90 | \$358. |
| | 0001 | 0420 | 6092013 | INTEGRAL CURB TYPE M | 7.00 | 0.00 | 7.00 | LF | 7.00 | \$94.15 | \$659 |
| | 0001 | 0440 | 6131010 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL | 56.00 | 53.30 | 109.30 | SQYD | 109.30 | \$612.95 | \$66,995 |
| | | 0-7-0 | 3101010 | DEPTH PAVEMENT REPAIR | 30.00 | 55.50 | 103.30 | 2010 | 103.30 | ψυ12.33 | ψ00,393 |
| | 0001 | 0450 | 6131012 | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) | 6.00 | -6.00 | 0.00 | SQYD | 0.00 | \$1.00 | \$0. |
| | 0001 | 0460 | 6131013 | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) | 6.00 | -6.00 | 0.00 | SQYD | 0.00 | \$1.00 | \$0.0 |
| | 0001 | | | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER | 252.00 | 238.00 | 490.00 | LF | 490.00 | | |

Revision 5/29/2025 Page 9 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| ntract D | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------|----------------|---------------------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 018- | JKU0029 | | | | AND INTERNAL SAW CUTS) | | | | | | | |
| 5 | | 0001 | 0480 | 6131015 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | 140.00 | -10.00 | 130.00 | EA | 130.00 | \$4.85 | \$630.50 |
| | | 0001 | 0490 | 6141121 | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,437.50 | \$1,437.50 |
| | | 0001 | 0500 | 6161005 | CONSTRUCTION SIGNS | 2,928.00 | 0.00 | 2,928.00 | SQFT | 1,054.00 | \$5.50 | \$5,797.00 |
| | | 0001 | 0510 | 6161025 | CHANNELIZER (TRIM-LINE) | 1,028.00 | 0.00 | 1,028.00 | EA | 393.00 | \$15.00 | \$5,895.0 |
| | | 0001 | 0520 | 6161030 | TYPE 3 MOVEABLE BARRICADE | 35.00 | 0.00 | 35.00 | EA | 31.00 | \$100.00 | \$3,100.0 |
| | | 0001 | 0530 | 6161033 | DIRECTION INDICATOR BARRICADE | 237.00 | 0.00 | 237.00 | EA | 0.00 | \$30.00 | \$0.0 |
| | | 0001 | 0540 | 6161040 | FLASHING ARROW PANEL | 17.00 | 0.00 | 17.00 | EA | 6.00 | \$850.00 | \$5,100.0 |
| | | 0001 | 0550 | 6161055 | SEQUENTIAL FLASHING WARNING LIGHT | 237.00 | 0.00 | 237.00 | EA | 0.00 | \$40.00 | \$0.0 |
| | | 0001 | 0560 | 6161099 | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$1,800.00 | \$0.0 |
| | | 0001 | 0570 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$150,000.00 | \$150,000.0 |
| | | 0001 | 0580 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 1,231.00 | -93.30 | 1,137.70 | LF | 673.00 | \$24.00 | \$16,152.0 |
| | | 0001 | 0590 | 6200018 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW | 754.00 | -58.10 | 695.90 | LF | 0.00 | \$24.00 | \$0.0 |
| | | 0001 | 0600 | 6200036 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | 41.00 | 0.00 | 41.00 | EA | 30.00 | \$300.00 | \$9,000.0 |
| | | 0001 | 0610 | 6200042 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES | 32.00 | 0.00 | 32.00 | EA | 41.00 | \$85.00 | \$3,485.0 |
| | | 0001 | 0620 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 42,299.00 | -6,893.30 | 35,405.70 | LF | 24,977.00 | \$0.26 | \$6,494.0 |
| | | 0001 | 0630 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 29,711.00 | -4,513.30 | 25,197.70 | LF | 17,721.00 | \$0.26 | \$4,607.4 |
| | | 0001 | 0640 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 8,409.00 | -1,879.20 | 6,529.80 | LF | 6,280.00 | \$0.50 | \$3,140.0 |
| | | 0001 | 0650 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 887.00 | 0.00 | 887.00 | LF | 1,437.00 | \$0.12 | \$172.4 |
| | | 0001 | 0660 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 1,316.00 | 0.00 | 1,316.00 | LF | 1,358.00 | \$0.12 | \$162.9 |
| | | 0001 | 0670 | 6206108A | 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 462.00 | 0.00 | 462.00 | LF | 619.00 | \$0.35 | \$216.6 |
| | | 0001 | 0680 | 6207001 | PAVEMENT MARKING REMOVAL | 95.00 | 0.00 | 95.00 | LF | 95.00 | \$1.00 | \$95.0 |
| | | 0001 | 0690 | 6207002 | PAVEMENT MARKING REMOVAL (SYMBOLS) | 21.00 | 0.00 | 21.00 | EA | 21.00 | \$50.00 | \$1,050.0 |
| | | 0001 | 0700 | 6209902 | MISC.INTERSTATE SHIELD PAVEMENT MARKINGS | 5.00 | -5.00 | 0.00 | EA | 0.00 | \$2,500.00 | \$0.0 |
| | | 0001 | 0710 | 6209902 | MISC.LANE REDUCTION ARROWS | 6.00 | -3.00 | 3.00 | EA | 0.00 | \$750.00 | \$0.0 |
| | | 0001 | 0720 | 6209902 | MISC.WORDS "NORTH" & "SOUTH" | 3.00 | -3.00 | 0.00 | EA | 0.00 | \$750.00 | \$0.0 |
| | | 0001 | 0730 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 101,976.00 | -25,768.51 | 76,207.49 | SQYD | 76,977.20 | \$3.00 | \$230,931.6 |
| | | 0030 | 0740 | 9029902 | MISC.LOOP DETECTOR | 3.00 | 0.00 | 3.00 | EA | 6.00 | \$5,500.00 | \$33,000.0 |
| | | 0001 | 5001 | 6269901 | MISC.BITUMINOUS SHOULDER RUMBLE STRIP | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$5,863.42 | \$5,863.4 |
| | Project Jr | KU0029 - <u>T</u> o | otal Value | Posted to E | Date as of Report Generated Date | | | | | | | \$1,939,308.6 |
| 018-C | 05 Overall | - Total Val | ue Poste | d to Date as | of Report Generated Date | | | | | | | \$6,213,328.8 |

Revision 5/29/2025 Page 10 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JKU0018

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Posting Sequence No. | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|---|-------------|-------------------------|----------------------------|--------------------|-------|--|---------------------------------|---------------------|-------------------------------|---------------------|--|
| 0180 | 6200015 | PREF THERMO PVMT MARK, 24 IN WHIT | 8/7/25 | 8/18/25 | 1 | 20.00 | LF | I-35 N to 14th St ramp | | | | | 2 10' Stop Bars at the end of the I-25 N to 14th St ramp |
| | | | 8/12/25 | 8/18/25 | 1 | 74.00 | LF | I-35 S ramp to 12th St and I-670 W to I-35 N gore | | | | | Chevrons placed on gores of the I-35 S to 12th St ramp (51') and I-670 W to I-35 N gore (23') |
| 0190 | 6200021 | PREF THERMO PVMT MARK, LT/RT ARROW | 8/7/25 | 8/18/25 | 1 | 6.00 | EA | I-35 N ramp to 12th St and 12th St before off-ramp to I-35 S | | | | | 2 Right Arrows on I-35 N ramp to 12th St 2 Left Arrows on I-35 N ramp to 12th St 2 Right Arrows on 12th St |
| 0220 | 6200036 | PREF THERMO PVMT MARK, 30" WHT MIDBL | 8/7/25 | 8/18/25 | 1 | 12.00 | EA | I-35 NB/SB ramps on and off of 12th st | | | | | 6 Mid Blocks on I-35 N to 12th St 6 Mid Blocks on 12th St to I-35 S |
| | | | 8/12/25 | 8/18/25 | 1 | 5.00 | EA | I-35 S on-ramp from Broadway | | | | | Mid blocks installed on the cross walk of Broadway Blvd to I-35 S ramp |
| 230 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT | 8/12/25 | 8/18/25 | 1 | 20,882.00 | LF | I-35 SB Mainline and Ramps | | | | | Various 6" White striping across I-35 SB and ramps |
| | | MARKING PAINT, TYPE L BEADS | 8/13/25 | 8/18/25 | 1 | 2,863.00 | LF | I-35 SB Mainline and Ramps | | | | | 6" White pavement marking used on I-35 SB |
| | | | 8/15/25 | 8/18/25 | 1 | 11,239.50 | LF | I-35 NB Mainline and Ramps | | | | | update of measurements taken for pavement marking or I-35 NB |
| 1240 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 8/12/25 | 8/18/25 | 1 | 17,418.00 | LF | I-35 SB Mainline and Ramps | | | | | Various 6" Yellow Striping across I-35 SB Mainline and Ramps |
| | | | 8/13/25 | 8/18/25 | 1 | 1,367.00 | LF | I-35 S Mainline and ramps | | | | | 6" Yellow Striping on I-35 SB |
| | | | 8/15/25 | 8/18/25 | 1 | 14,420.00 | LF | I-35 NB Mainline and Ramps | | | | | update of measurements taken for pavement marking or I-35 NB |
| 1250 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 8/12/25 | 8/18/25 | 1 | 1,623.00 | LF | I-35 SB Mainline and Ramps | | | | | Various 12" White striping across I-35 SB Mainline and Ramps |
| | | | 8/13/25 | 8/18/25 | 1 | 4,130.00 | LF | I-35 SB Mainline and Ramps | | | | | 12" White striping on gores |
| | | | 8/15/25 | 8/18/25 | 1 | 4,821.00 | LF | I-35 NB Mainline and Ramps | | | | | update of measurements taken for pavement marking or I-35 NB |
| 300 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 8/4/25 | 8/18/25 | 1 | 97.96 | STA | I-35 NB & SB Inside and Outside Shoulders | | | | | Rumble Strips installed from L0232 to state line on SB and state line to A1704 on NB |

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 11 of 24



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks | | | | | |
|----------|--------|--------------------------|--------------------------|--------------------|--------|-----------------|-----------------|------------------|--|---|-----------------|--------|----------------|--|
| 1 10,000 | LIIIO | Возоприон | Туре | Adjustment Type | Number | Date | Ву | 7 anount | romano | | | | | |
| JKU0018 | 0010 | BIT. PAVEMENT MIXTURE | Other Item Adjustment | ACAD | 5 | Jun 16, 2025 | mcclon1 | \$104.91 | This line item adjustment is being made to pay for the AC price adjustment for the June 2025 First Estimate Period. | | | | | |
| | | PG64-22 (BP-1) | | | 6 | Jul 1, 2025 | mcclon1 | \$168.47 | This line Item adjustment is being made to pay for the AC price adjustment for the June Second Estimate Period for 6/22/2025 | | | | | |
| | | | | | 8 | Aug 5, 2025 | mcclon1 | \$471.31 | This line Item adjustment is being made to pay for the AC price adjustment for the July Second Estimate Period for 7/22/2025 | | | | | |
| | | | | | 8 | Aug 5, 2025 | mcclon1 | \$559.93 | This line Item adjustment is being made to pay for the AC price adjustment for the July Second Estimate Period for 7/23/2025 | | | | | |
| | | | | | 8 | Aug 5, 2025 | mcclon1 | \$535.75 | This line Item adjustment is being made to pay for the AC price adjustment for the July Second Estimate Period for 7/28/2025 | | | | | |
| | | | | ACAD - Tota | al | | | \$1,840.37 | | | | | | |
| | | | Other Item | Adjustment - | Total | | | \$1,840.37 | | | | | | |
| | 0010 - | Total | | | | | | \$1,840.37 | | | | | | |
| | 0020 | ASPHALTIC CONCRETE | Material | | 6 | Jul 1, 2025 | SYSTEM | (\$1,294,467.08) | | | | | | |
| | | MIXTURE PG 76-22 (SP1 | | | 6 | Jul 1, 2025 | SYSTEM | \$1,294,467.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | |
| | | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$2,273,273.43) | | | | | |
| | | | | | | | | | | 7 | Jul 16, 2025 | SYSTEM | \$2,273,273.43 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | | | | | | | | 8 | Aug 5, 2025 | SYSTEM |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$2,545,598.88 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | |
| | | | Other Item Adjustment | ACAD | 5 | Jun 16, 2025 | mcclon1 | \$2,002.14 | This line item adjustment is being made to pay for the AC price adjustment for the June 2025 First Estimate Period. | | | | | |
| | | | , , | | 6 | Jul 1, 2025 | mcclon1 | \$1,568.79 | This line Item adjustment is being made to pay for the AC price adjustment for the June Second Estimate Period for 6/21/2025 | | | | | |
| | | | | | 6 | Jul 1, 2025 | mcclon1 | \$940.53 | This line Item adjustment is being made to pay for the AC price adjustment for the June Second Estimate Period for 6/23/2025 | | | | | |
| | | | | | 6 | Jul 1, 2025 | mcclon1 | \$836.76 | This line Item adjustment is being made to pay for the AC price adjustment for the June Second Estimate Period for 6/24/2025 | | | | | |
| | | | | | 6 | Jul 1, 2025 | mcclon1 | \$588.33 | This line Item adjustment is being made to pay for the AC price adjustment for the June Second Estimate Period for 6/25/2025 | | | | | |
| | | | | | 6 | Jul 1, 2025 | mcclon1 | \$808.68 | This line Item adjustment is being made to pay for the AC price adjustment for the June Second Estimate Period for 6/30/2025 | | | | | |
| | | | | | 7 | Jul 16, 2025 | mcclon1 | \$842.23 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/01/2025 | | | | | |
| | | | | | 7 | Jul 16, 2025 | mcclon1 | \$942.84 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/02/2025 | | | | | |
| | | | | | 7 | Jul 16, 2025 | mcclon1 | \$447.39 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/07/2025 | | | | | |
| | | | | | 7 | Jul 16, 2025 | mcclon1 | \$829.52 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/08/2025 | | | | | |
| | | | | | 7 | Jul 16, 2025 | mcclon1 | \$920.29 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/09/2025 | | | | | |
| | | | | | | 7 | Jul 16, 2025 | mcclon1 | \$943.49 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/10/2025 | | | | |
| | | | | | 7 | Jul 16, 2025 | mcclon1 | \$75.87 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/12/2025 | | | | | |
| | | | | | 7 | Jul 16, 2025 | mcclon1 | \$734.47 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/14/2025 | | | | | |
| | | | | | 8 | Aug 5, 2025 | mcclon1 | \$793.97 | This line Item adjustment is being made to pay for the AC price adjustment for the July Second Estimate Period for 7/16/2025 | | | | | |
| | | | | | 8 | Aug 5, 2025 | mcclon1 | \$801.94 | This line Item adjustment is being made to pay for the AC price adjustment for the July Second Estimate Period for 7/17/2025 | | | | | |
| | | | | ACAD - Tota | al | | | \$14,077.24 | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| JKU0018 | 0020 | ASPHALTIC | Other Item | Adjustment - | Total | | | \$14,077.24 | |
| | | CONCRETE MIXTURE PG 76-22 (SP1 | Overrun | Overrun | 8 | Aug 5, 2025 | SYSTEM | (\$252,311.68) | |
| | | | | Overrun - T | otal | | | (\$252,311.68) | |
| | | | Overrun - T | otal | | | | (\$252,311.68) | |
| | 0020 - | Total | | | | | | (\$238,234.44) | |
| | 0030 | MISC. | Material | | 5 | Jun 16, 2025 | SYSTEM | (\$3,093.75) | |
| | | | | | 5 | Jun 16, 2025 | SYSTEM | \$3,093.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$23,531.25) | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | \$23,531.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$55,016.25) | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$55,016.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$71,831.25) | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$71,831.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$71,831.25) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$71,831.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user doggea1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0030 - | Total | | | | | | \$0.00 | |
| | 0040 | FURN & PLACE CONC MATL FOR FULL DEPTH | Material | | 3 | May 16, 2025 | SYSTEM | (\$91,690.29) | |
| | | FOLL DEFIN | | | 3 | May 16, 2025 | SYSTEM | \$91,690.29 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | Overrun | Overrun | 3 | May 16, 2025 | SYSTEM | (\$37,234.29) | |
| | | | | | 4 | Jun 2, 2025 | SYSTEM | \$37,234.29 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',680.70000 - 680.70000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - T | otal | | | | \$0.00 | |
| | 0040 - | Total | | | | | | \$0.00 | |
| | 0070 | FULL DEPTH PAVEMENT | Overrun | Overrun | 3 | May 16, 2025 | SYSTEM | (\$327.70) | |
| | | REPAIR SAW CUT (FOR | | | 4 | Jun 2, 2025 | SYSTEM | \$327.70 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). |
| | | | | Overrun - To | otal | | | \$0.00 | |
| | | | Overrun - T | | | | | \$0.00 | |
| | 0070 - | Total | | | | | | \$0.00 | |
| | | CHANGEABLE MESSAGE SIGN WITHOUT | Material | | 2 | May 2, 2025 | SYSTEM | (\$27,000.00) | |
| | | COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / | | | 2 | May 2, 2025 | SYSTEM | \$27,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---------|---|---------------------------------------|--------------------------|--------------------|--------|-----------------|---------|--------------|---|
| | | | Туре | Adjustment Type | Number | Date | Ву | | |
| JKU0018 | 0160 | RETAINED | Material | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | Other Item Adjustment | MDPA | 2 | May 2, 2025 | mcclon1 | (\$2,700.00) | This item adjustment is to with hold 10% of the installed quantity. This item adjustment will be removed once the necessary material certifications has been submitted. |
| | | | | MDPA - Tota | al | | | (\$2,700.00) | |
| | | | | OTHR | 5 | Jun 16, 2025 | mcclon1 | \$2,700.00 | This item adjustment is to remove the 10% with-holding created on 02/02/2025. |
| | | | | OTHR - Tota | al | | | \$2,700.00 | |
| | | | Other Item | Adjustment - | Total | | | \$0.00 | |
| | 0160 | Total | | | | | | \$0.00 | |
| | 0180 | PREF THERMO PVMT MARK, 24 | Material | | 8 | Aug 5, 2025 | SYSTEM | (\$1,416.00) | |
| | | IN WHIT | | | 8 | Aug 5, 2025 | SYSTEM | \$1,416.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$3,672.00) | Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$3,672.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user doggea1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | 0180 - Total 0190 PREF THERMO PVMT MARK, LT/RT ARROW | Material - T | otal | | | | \$0.00 | | |
| | | Total | | | | | | \$0.00 | |
| | | PREF THERMO PVMT MARK, | Material | | 8 | Aug 5, 2025 | SYSTEM | (\$700.00) | |
| | | PVMT MARK, | | | 8 | Aug 5, 2025 | SYSTEM | \$700.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$2,800.00) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$2,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user doggea1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0190 - | Total | | | | | | \$0.00 | |
| | 0200 | PREF THERMO PVMT MRKG, STRIAGHT | Material | | 8 | Aug 5, 2025 | SYSTEM | (\$350.00) | |
| | | ARROW | | | 8 | Aug 5, 2025 | SYSTEM | \$350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$350.00) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user doggea1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0200 - | Total | | | | | | \$0.00 | |
| | 0210 | PREF THERMO PVMT MARKING, | Material | | 8 | Aug 5, 2025 | SYSTEM | (\$1,350.00) | |
| | | COMBO | | | 8 | Aug 5, 2025 | SYSTEM | \$1,350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$1,350.00) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$1,350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user doggea1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | | | | | | | |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---------|--|--|--|--------------------|--------|-----------------|-----------------|---------------|---|
| | | | Туре | Adjustment Type | Number | Date | Ву | | |
| JKU0018 | 0210 - | - Total | | | | | | \$0.00 | |
| | 0220 | PREF THERMO PVMT MARK, 30" WHT MIDBL | Material | | 8 | Aug 5, 2025 | SYSTEM | (\$5,100.00) | |
| | | WITT WILDSE | | | 8 | Aug 5, 2025 | SYSTEM | \$5,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$10,200.00) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$10,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user doggea1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0220 | - Total | | | | | | \$0.00 | |
| | 0230 | 6 IN. WHITE HIGH BUILD | Material | | 9 | Aug 18, 2025 | SYSTEM | (\$9,095.97) | |
| | | WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | | | 9 | Aug 18, 2025 | SYSTEM | \$9,095.97 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user doggea1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | 0230 - Total 0240 6 IN. YELLOW HIGH BUILD WATERBORNE | | Material - T | otal | | | | \$0.00 | |
| | | | Other Item Adjustment | OTHR | 9 | Aug 18, 2025 | doggea1 | (\$909.60) | This line item adjustment is created to withhold 10%. Awaiting retro reflectivity results. |
| | | | | OTHR - Total | | | | (\$909.60) | |
| | | | Other Item | Adjustment - | Total | | | (\$909.60) | |
| | | - Total | | | | | | (\$909.60) | |
| | | 6 IN. YELLOW HIGH BUILD | 6 IN. YELLOW HIGH BUILD WATERBORNE | Material | | 9 | Aug 18, 2025 | SYSTEM | (\$8,633.30) |
| | | HIGH BUILD | | | 9 | Aug 18, 2025 | SYSTEM | \$8,633.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user doggea1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | Other Item Adjustment | OTHR | 9 | Aug 18, 2025 | doggea1 | (\$863.30) | This line item adjustment is created to withhold 10%. Awaiting retro reflectivity results. |
| | | | | OTHR - Tota | al | | | (\$863.30) | |
| | | | Other Item | Adjustment - | Total | | | (\$863.30) | |
| | 0240 - | - Total | | | | | | (\$863.30) | |
| | 0250 | 12 IN. WHITE HIGH BUILD WATERBORNE | Material | | 9 | Aug 18, 2025 | SYSTEM | (\$5,287.00) | |
| | | PAVEMENT MARKING PAINT, TYPE L BEADS | | | 9 | Aug 18, 2025 | SYSTEM | \$5,287.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user doggea1 overridding Payment Estimate Exception 25 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | Other Item Adjustment | OTHR | 9 | Aug 18, 2025 | doggea1 | (\$528.70) | This line item adjustment is created to withhold 10%. Awaiting retro reflectivity results. |
| | | | | OTHR - Tota | al | | | (\$528.70) | |
| | | | Other Item | Adjustment - | Total | | | (\$528.70) | |
| | 0250 | - Total | | | | | | (\$528.70) | |
| | 0300 | BITUMINOUS SHOULDER RUMBLE STRIP | Overrun | Overrun | 9 | Aug 18, 2025 | SYSTEM | (\$78.58) | |
| | | | | Overrun - T | otal | | | (\$78.58) | |
| | | | Overrun - T | otal | | | | (\$78.58) | |
| | 0300 | - Total | | | | | | (\$78.58) | |
| | 0300 - | OPTIONAL ASPHALTIC CONCRETE | Other Item Adjustment | ACAD | 6 | Jul 1, 2025 | mcclon1 | \$91.73 | This line Item adjustment is being made to pay for the AC price adjustment for the June Second Estimate Period for 6/29/2025 |
| | | WEARING SURFACE (BRIDGES) | | | 7 | Jul 16, 2025 | mcclon1 | \$65.38 | This line Item adjustment is being made to pay for the AC price adjustment for the July First Estimate Period for 7/12/2025 |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|---------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|------------------|--|
| JKU0018 | 0320 | OPTIONAL ASPHALTIC CONCRETE | Other Item Adjustment | ACAD - Tota | al | | | \$157.11 | |
| | | WEARING SURFACE (BRIDGES) | Other Item | Adjustment - | Total | | | \$157.11 | |
| | 0320 - | Total | | | | | | \$157.11 | |
| JKU0018 | - Total | | | | | | | (\$238,617.14) | |
| JKU0029 | 0360 | BIT. PAVEMENT MIXTURE PG64-22 (BP-2) | Other Item Adjustment | ACAD | 5 | Jun 16, 2025 | mcclon1 | \$1,445.17 | This line item adjustment is being made to pay for the AC price adjustment for the May 2025 Second Estimate Period. |
| | | FG04-22 (BF-2) | | ACAD - Tota | al | | | \$1,445.17 | |
| | | | Other Item | Adjustment - | Total | | | \$1,445.17 | |
| | 0360 - | Total | | | | | | \$1,445.17 | |
| | 0370 | ASPH. CONC. MIXTURE PG 76-22 | Material | | 4 | Jun 2, 2025 | SYSTEM | (\$1,207,462.40) | |
| | | (SP095BSM) | | | 4 | Jun 2, 2025 | SYSTEM | \$1,207,462.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | Other Item Adjustment | ACAD | 5 | Jun 16, 2025 | mcclon1 | \$11,518.72 | This line item adjustment is being made to pay for the AC price adjustment for the May 2025 First & Second Estimate Periods. |
| | | | | ACAD - Tota | al | | | \$11,518.72 | |
| | | | Other Item | Adjustment - | Total | | | \$11,518.72 | |
| | | | Overrun | Overrun | 8 | Aug 5, 2025 | SYSTEM | (\$13,268.48) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | Overrun - T | otal | | | (\$13,268.48) | |
| | | | Overrun - T | otal | | | | (\$13,268.48) | |
| | 0370 - | Total | | | | | | (\$1,749.76) | |
| | 0390 | MISC. | Material | | 3 | May 16, 2025 | SYSTEM | (\$18,135.00) | |
| | | | | | 3 | May 16, 2025 | SYSTEM | \$18,135.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 4 | Jun 2, 2025 | SYSTEM | (\$38,127.50) | |
| | | | | | 4 | Jun 2, 2025 | SYSTEM | \$38,127.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 5 | Jun 16, 2025 | SYSTEM | (\$38,127.50) | |
| | | | | | 5 | Jun 16, 2025 | SYSTEM | \$38,127.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$38,127.51) | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | \$38,127.51 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$38,127.51) | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$38,127.51 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$38,127.51) | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$38,127.51 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$38,127.51) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$38,127.51 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user doggea1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | |
|---------|--------|--------------------------|-----------------------------|-----------------------------|----------------|-----------------|----------------|------------|--|---|---|----------------|--------|----------|--|--------|--|
| JKU0029 | 0390 | MISC. | Material | - Total | | | | \$0.00 | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | |
| | 0390 - | | | | | | 01/0==1 | \$0.00 | | | | | | | | | |
| | 0400 | CONCRETE PAVEMENT (10 | Material | | 3 | May 16, 2025 | SYSTEM | (\$475.87) | | | | | | | | | |
| | | IN. NON-REINF) | | | 3 | May 16, 2025 | SYSTEM | \$475.87 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | | | | | |
| | | | | | 4 | Jun 2, 2025 | SYSTEM | (\$475.87) | | | | | | | | | |
| | | | | | 4 | Jun 2, 2025 | SYSTEM | \$475.87 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | | | | | |
| | | | | | 5 | Jun 16, 2025 | SYSTEM | (\$475.87) | | | | | | | | | |
| | | | | | 5 | Jun 16, 2025 | SYSTEM | \$475.87 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$475.87) | | | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | \$475.87 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$475.87) | | | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$475.87 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | |
| | | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$475.87) | | | | | | | | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$475.87 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mcclon1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$475.87) | | | | | | | | | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$475.87 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user doggea1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | |
| | 0400 - | Total | | | | | | \$0.00 | | | | | | | | | |
| | 0430 | INTEGRAL CURB TYPE M | Material | | 3 | May 16, 2025 | SYSTEM | (\$659.05) | | | | | | | | | |
| | | | | | 3 | May 16, 2025 | SYSTEM | \$659.05 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | | | |
| | | | | | 4 | Jun 2, 2025 | SYSTEM | (\$659.05) | | | | | | | | | |
| | | | | | | | | | | | 4 | Jun 2, 2025 | SYSTEM | \$659.05 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | |
| | | | | | 5 | Jun 16, 2025 | SYSTEM | (\$659.05) | | | | | | | | | |
| | | | | | | | | 6 | 5 6 6 | 6 | 6 | 6 | | | 5 Jun 16, SYSTEM \$659.05 This adjust Estimate It | | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | | | | | | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$659.05) |
| | | | | | | | | | | | | | | | | | 6 |
| | | | 7 Jul 16, SYSTEM (\$659.05) | | | | | | | | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$659.05 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | |



| - | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---------|--------------------|--|--------------|--------------------|----------------------------|---|--|--|--|
| | | | Туре | Adjustment Type | Number | Date | Ву | | |
| JKU0029 | 0430 | INTEGRAL CURB TYPE M | Material | | 8 | Aug 5, 2025 | SYSTEM | (\$659.05) | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$659.05 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$659.05) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$659.05 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user doggea1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0430 | - Total | | | | | | \$0.00 | |
| | 0440 | FURN & PLACE CONC MATL FOR | Material | | 3 | May 16, 2025 | SYSTEM | (\$66,995.44) | |
| | | FULL DEPTH | | | 3 | May 16, 2025 | SYSTEM | \$66,995.44 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | Overrun | Overrun | 3 | May 16, 2025 | SYSTEM | (\$32,670.24) | |
| | | | | | 4 | Jun 2, 2025 | SYSTEM | \$32,670.24 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',612.95000 - 612.95000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | Overrun - T | otal | | | | \$0.00 | | |
| | 0440 | ULL DEPTH | | | | | | \$0.00 | |
| | 0470 | Total FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR | Overrun | Overrun | 3 | May 16, 2025 | SYSTEM | (\$345.10) | |
| | | | | | | | | | |
| | | (FOR | | | 4 | Jun 2, 2025 | SYSTEM | \$345.10 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). |
| | | (FOR | | Overrun - T | | | SYSTEM | \$345.10 \$0.00 | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is |
| | | , | Overrun - T | | | | SYSTEM | \$0.00 \$0.00 | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is |
| | 0470 | - Total | | | otal | 2025 | | \$0.00 \$0.00 \$0.00 | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is |
| | 0470 - 0490 | Total CURVED VANE GRATE AND | Overrun - T | | | | SYSTEM | \$0.00 \$0.00 | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is |
| | | -Total CURVED VANE | | | otal | 2025 May 16, | | \$0.00 \$0.00 \$0.00 | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | otal 3 | May 16, 2025 May 16, | SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | 3 3 | May 16, 2025 May 16, 2025 Jun 2, | SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) \$1,437.50 | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | 3 3 4 | May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, | SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) \$1,437.50 | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | 3 3 4 4 | 2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 16, | SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) \$1,437.50 (\$1,437.50) | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | 3 3 4 4 | 2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 | SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) \$1,437.50 (\$1,437.50) (\$1,437.50) | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | 3 3 4 4 5 | 2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 11, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) \$1,437.50 (\$1,437.50) \$1,437.50 (\$1,437.50) | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | 3 3 4 4 5 5 | 2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) \$1,437.50 (\$1,437.50) \$1,437.50 (\$1,437.50) | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | 3 3 4 4 5 6 6 | 2025 May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025 Jul 16, 4025 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) \$1,437.50 (\$1,437.50) \$1,437.50 (\$1,437.50) \$1,437.50 | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. |
| | | -Total CURVED VANE GRATE AND FRAME(4 FT. X 2 | | | 3 3 4 4 5 6 6 7 | May 16, 2025 May 16, 2025 Jun 2, 2025 Jun 16, 2025 Jul 14, 2025 Jul 14, 2025 Jul 16, 2025 Jul 16, 2025 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 (\$1,437.50) \$1,437.50 (\$1,437.50) \$1,437.50 (\$1,437.50) \$1,437.50 (\$1,437.50) | previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. |



| Project | Line | Description | Adjustment | Other Adjustment | Est. Number | Created Date | Created | Amount | Remarks | | | | | | | | | | | |
|---------|------|---|---------------|---------------------|----------------|-----------------|--------------------------------------|---------------|---|-------------|-----|-----------------|----------------|--------------|-----------------|---|----------------|---|---|---|
| | | | Туре | Type | Number | | Ву | | | | | | | | | | | | | |
| JKU0029 | 0490 | CURVED VANE GRATE AND FRAME(4 FT. X 2 | Material | | | 2025 | | | Estimate Item Adjustment (0013) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | |
| | | FT FT | | | 9 | Aug 18, 2025 | SYSTEM | (\$1,437.50) | | | | | | | | | | | | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$1,437.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user doggea1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | | |
| | 0490 | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 0580 | PREF THERMO PVMT MARK, 24 | Material | | 5 | Jun 16, 2025 | SYSTEM | (\$16,152.00) | | | | | | | | | | | | |
| | | IN WHIT | | | 5 | Jun 16, 2025 | SYSTEM | \$16,152.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$16,152.00) | | | | | | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | \$16,152.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$16,152.00) | | | | | | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$16,152.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$16,152.00) | | | | | | | | | | | | |
| | | | | | | | | | | | | 8 | Aug 5, 2025 | SYSTEM | \$16,152.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mcclon1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | |
| | | | | | | | | | | | | | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$16,152.00) |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$16,152.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user doggea1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | Estimate Exception to on the current rayment Estimate. | | | | | | | | | | | |
| | | | Material - To | | | | | \$0.00 | | | | | | | | | | | | |
| | 0580 | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 0600 | PREF THERMO PVMT MARK, 30" | Material | | 5 | Jun 16, 2025 | SYSTEM | (\$9,000.00) | | | | | | | | | | | | |
| | | WHT MIDBL | | | 5 | Jun 16, 2025 | SYSTEM | \$9,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$9,000.00) | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 6 | Jul 1, 2025 | SYSTEM | \$9,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$9,000.00) | • | | | | | | | | | | | |
| | | | 7 8 8 | | | | | | | | | | | 7 | Jul 16, 2025 | SYSTEM | \$9,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | |
| | | | | | | : | 8 Aug 5, SYSTEM (\$9,000.00) 2025 | | | | | | | | | | | | | |
| | | | | | | | | | 9 | 8 9 9 | 9 9 | | | | | 8 | 8 | 8 Aug 5, 2025 \$9,000.00 This adjustment offsets the original system Estimate Item Adjustment (0015) due to use the stimate Item Adjustment (0015) due to use the | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | |
| | | | | | | | | | | | | Aug 18, 2025 | SYSTEM | (\$9,000.00) | | | | | | |
| | | | | | | | | | | | | | | | 9 | Aug 18, 2025 | SYSTEM | \$9,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user doggea1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|-------------------|--|---|--|--|
| JKU0029 | 0600 - | - Total | | | | | | \$0.00 | |
| | 0610 | PREF THERMO PVMT MARK, | Material | | 5 | Jun 16, 2025 | SYSTEM | (\$3,485.00) | |
| | | YIELD TRIAN | | | 5 | Jun 16, 2025 | SYSTEM | \$3,485.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$3,485.00) | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | \$3,485.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$3,485.00) | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$3,485.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$3,485.00) | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$3,485.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user mcclon1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$3,485.00) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$3,485.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user doggea1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | Overrun | Overrun | 5 | Jun 16, 2025 | SYSTEM | (\$765.00) | |
| | | | | Overrun - T | otal | | | (\$765.00) | |
| | | | Overrun - T | otal | | | | (\$765.00) | |
| | 0610 - | - Total | | | | | | (\$765.00) | |
| | 0620 | 6 IN. WHITE HIGH BUILD WATERBORNE | Material | | 5 | Jun 16, 2025 | SYSTEM | (\$3,764.28) | |
| | | | | | | | | | |
| | | PAVEMENT MARKING PAINT, TYPE L BEADS | | | 5 | Jun 16, 2025 | SYSTEM | \$3,764.28 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | PAVEMENT MARKING PAINT, | | | 5 | | SYSTEM | \$3,764.28 (\$3,764.28) | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment |
| | | PAVEMENT MARKING PAINT, | | | | 2025 Jul 1, | | | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment |
| | | PAVEMENT MARKING PAINT, | | | 6 | 2025 Jul 1, 2025 Jul 1, | SYSTEM | (\$3,764.28) | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment |
| | | PAVEMENT MARKING PAINT, | | | 6 | 2025 Jul 1, 2025 Jul 1, 2025 Jul 16, | SYSTEM | (\$3,764.28) \$3,764.28 | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment |
| | | PAVEMENT MARKING PAINT, | | | 6 6 7 | 2025 Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, | SYSTEM SYSTEM SYSTEM | (\$3,764.28) \$3,764.28 (\$6,494.02) | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment |
| | | PAVEMENT MARKING PAINT, | | | 6 6 7 7 | 2025 Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 5, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$3,764.28) \$3,764.28 (\$6,494.02) \$6,494.02 | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment |
| | | PAVEMENT MARKING PAINT, | | | 6 6 7 7 8 8 | 2025 Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 5, 2025 Aug 5, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$3,764.28) \$3,764.28 (\$6,494.02) \$6,494.02 | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment |
| | | PAVEMENT MARKING PAINT, | | | 6 6 7 7 8 8 8 8 | 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 5, 2025 Aug 5, 2025 Aug 18, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$3,764.28) \$3,764.28 (\$6,494.02) \$6,494.02 (\$6,494.02) | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment |
| | | PAVEMENT MARKING PAINT, | | - Total | 6 6 7 7 8 8 8 9 9 | 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 5, 2025 Aug 5, 2025 Aug 18, Aug 18, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$3,764.28) \$3,764.28 (\$6,494.02) \$6,494.02 (\$6,494.02) (\$6,494.02) | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. |
| | | PAVEMENT MARKING PAINT, | Material - T | | 6 6 7 7 8 8 8 9 9 | 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 5, 2025 Aug 5, 2025 Aug 18, Aug 18, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$3,764.28) \$3,764.28 (\$6,494.02) \$6,494.02 (\$6,494.02) \$6,494.02 (\$6,494.02) | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. |
| | 0620 - | PAVEMENT MARKING PAINT, | Material - T | | 6 6 7 7 8 8 8 9 9 | 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 5, 2025 Aug 5, 2025 Aug 18, Aug 18, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$3,764.28) \$3,764.28 (\$6,494.02) \$6,494.02 (\$6,494.02) \$6,494.02 \$6,494.02 \$6,494.02 | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. |
| | | PAVEMENT MARKING PAINT, TYPE L BEADS | Material - T | | 6 6 7 7 8 8 8 9 9 | 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 5, 2025 Aug 5, 2025 Aug 18, Aug 18, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$3,764.28) \$3,764.28 (\$6,494.02) \$6,494.02 (\$6,494.02) \$6,494.02 \$6,494.02 \$0.00 | Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcclon1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|--------------|---|--|--|---|-----------------|--------|------------|---|
| JKU0029 | 0630 | MARKING PAINT, TYPE L BEADS | Material | | | 2025 | | | Estimate Item Adjustment (0011) due to user mcclon1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$2,922.66) | | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | \$2,922.66 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mcclon1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$4,607.46) | | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$4,607.46 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mcclon1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$4,607.46) | | | | | | | | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$4,607.46 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user mcclon1 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$4,607.46) | | | | | | | | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$4,607.46 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user doggea1 overridding Payment Estimate Exception 23 on the current Payment Estimate. | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | |
| | 0630 - | Total | | | | | | \$0.00 | | | | | | | | |
| | 0640 | 12 IN. WHITE HIGH BUILD | Material | | 5 | Jun 16, 2025 | SYSTEM | (\$2,283.50) | | | | | | | | |
| | | | | | 5 | Jun 16, 2025 | SYSTEM | \$2,283.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mcclon1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$2,283.50) | | | | | | | | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | \$2,283.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mcclon1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | | | | | |
| | | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$3,140.00) | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$3,140.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mcclon1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | | | | | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$3,140.00) | | | | | | | | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$3,140.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user mcclon1 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | | | | | | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$3,140.00) | | | | | | | | |
| | | | | | | | | | | | | 9 | Aug 18, 2025 | SYSTEM | \$3,140.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user doggea1 overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | |
| | 0640 - | | | | _ | | 211 | \$0.00 | | | | | | | | |
| | 0650 | 4 IN. WHITE WATERBORNE PAVEMENT | Material | | 5 | Jun 16, 2025 | SYSTEM | (\$172.44) | | | | | | | | |
| | | MARKING | | | 5 | Jun 16, 2025 | SYSTEM | \$172.44 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mcclon1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | |
| | | | | 6 | | Jul 1, 2025 | SYSTEM | (\$172.44) | | | | | | | | |
| | | | | | | Jul 1, 2025 | SYSTEM | \$172.44 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mcclon1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | | | | | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$172.44) | | | | | | | | |



| Majoritary Maj | | | | | | | | | | |
|--|---------|--------|------------------------|-----------------|-----------------|------|--------|--------|------------|---|
| WALTERSONNE | Project | Line | Description | | Adjustment | | | | Amount | Remarks |
| S | JKU0029 | 0650 | WATERBORNE PAVEMENT | Material | | 7 | | SYSTEM | \$172.44 | Estimate Item Adjustment (0013) due to user mcclon1 overridding Payment |
| 2025 System Sys | | | | | | 8 | | SYSTEM | (\$172.44) | |
| 2025 0 Aug 10, SYSTEM S172.44 This adjustment officets the original system-generated Material Payment Estimate Exemption 29 on the current Payment Estimate Estimate Exemption 20 on the current Payment Estimate Estimate Exemption 20 on the current Payment Estimate Estimate Exemption 29 on the current Payment Estimate Estimate Estimate Exemption 29 on the current Payment Estimate Estimate Estimate Exemption 29 on the current Payment Estimate Estimate Estimate Exemption 29 on the current Payment Estimate Estimate Exemption 29 on the current Payment Estimate Estimate Estimate Exemption 29 on the current Payment Estimate Estimate Estimate Exemption 29 on the current Payment Estimate Estimate Estimate Exemption 29 on the current Payment Estimate Estima | | | | | | 8 | | SYSTEM | \$172.44 | Estimate Item Adjustment (0020) due to user mcclon1 overridding Payment |
| Part | | | | | | 9 | | SYSTEM | (\$172.44) | |
| National - Total South | | | | | | 9 | | SYSTEM | \$172.44 | Estimate Item Adjustment (0021) due to user doggea1 overridding Payment |
| Material - Total | | | | | Total | | | | \$0.00 | Estimate Exception 20 on the surrout rayment Estimate. |
| Overnum | | | | | | | | | | |
| | | | | | | 5 | lup 16 | CVCTEM | | |
| | | | | Overrun | Overruit | 5 | | STSTEM | (\$66.00) | |
| | | | | | Overrun - Total | | | | (\$66.00) | |
| Material Material | | | | Overrun - Total | | | | | (\$66.00) | |
| WATERBORNE PAVEMENT | | 0650 - | Total | | | | | | (\$66.00) | |
| MARKING | | 0660 | WATERBORNE PAVEMENT | Material | | 5 | | SYSTEM | (\$81.48) | |
| 2025 SYSTEM S81.48 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user modorn overridding Payment Estimate Exception 21 on the current Payment Estimate Exception 21 on the current Payment Estimate Exception 21 on the current Payment Estimate Estimate Exception 21 on the current Payment Estimate Estimate Estimate Exception 21 on the current Payment Estimate Estimate Estimate Exception 21 on the current Payment Estimate Estimate Estimate Exception 21 on the current Payment Estimate Estimate Exception 21 on the current Payment Estimate Estimate Estimate Exception 22 on the current Payment Estimate Estimate Exception 23 on the current Payment Estimate Exception 25 on the current Payment Estimate Exception 26 on the current Payment Estimate Exception 27 on the current Payment Estimate Exception 28 on the current Payment Estimate Exception 29 on the current Payment Estimate Exception 29 on the current Payment Estimate Exception 31 on the current Payment Estimate Exception 32 o | | | | | | 5 | | SYSTEM | \$81.48 | Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment |
| 2025 SYSTEM Stamate Item Adjustment (0014) due to user motion overriding Payment Estimate Exception 21 on the current Payment Estimate Exception 22 on the current Payment Estimate Item Adjustment (012) due to user moderal overridding Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment (012) due to user moderal overridding Payment Estimate Exception 22 on the current Payment Estimate Item Adjustment (012) due to user moderal overridding Payment Estimate Exception 22 on the current Payment Estimate Item Adjustment (012) due to user moderal overridding Payment Estimate Exception 22 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate Exception 31 on the current Payment Estimate Exception 31 on the current Payment Estimate Estimate Exception 31 on the current Payment Estimate Exception 31 on the current Payment Estimate Estimate Exception 31 on the current Payment Estimate Estimate Exception 32 on the current Payment Estimate Es | | | | | | 6 | | SYSTEM | (\$81.48) | |
| 2025 7 | | | | | | 6 | | SYSTEM | \$81.48 | Estimate Item Adjustment (0014) due to user mcclon1 overridding Payment |
| 2025 Estimate Item Adjustment (0015) due to user moclon1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | 7 | | SYSTEM | (\$162.96) | |
| 2025 | | | | | | 7 | | SYSTEM | \$162.96 | Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment |
| 2025 Estimate Item Adjustment (0021) due to user moclon1 overridding Payment Estimate Exception 26 on the current Payment Estimate. | | | | | | 8 | | SYSTEM | (\$162.96) | |
| 2025 9 | | | | | | 8 | | SYSTEM | \$162.96 | Estimate Item Adjustment (0021) due to user mcclon1 overridding Payment |
| Comparison of | | | | | | 9 | | SYSTEM | (\$162.96) | |
| Material - Total | | | | | | 9 | | SYSTEM | \$162.96 | Estimate Item Adjustment (0022) due to user doggea1 overridding Payment |
| Overrun Overrun 7 | | | | | - Total | | | | \$0.00 | |
| Overrun - Total (\$5.04) | | | | Material - To | otal | | | | \$0.00 | |
| 10660 - Total | | | | Overrun | Overrun | 7 | | SYSTEM | (\$5.04) | |
| Control Cont | | | | | Overrun - T | otal | | | (\$5.04) | |
| SYSTEM S | | | | Overrun - Total | | | | | (\$5.04) | |
| WATERBORNE PAVEMENT MARKING 5 Jun 16, 2025 5 Jun 16, 2025 5 Jun 16, 2025 6 Jul 1, 2025 6 Jul 1, 2025 6 Jul 1, 2025 6 Jul 1, 2025 7 Jul 16, SYSTEM \$216.65 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. This adjustment (0017) due to user mcclon1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment Estimate Exception 23 on the current Payment Estimate. | | 0660 - | otal | | | | | | (\$5.04) | |
| MARKING 5 Jun 16, 2025 8216.65 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 6 Jul 1, 2025 6 Jul 1, SYSTEM 8216.65 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment Estimate Exception 23 on the current Payment Estimate. 7 Jul 16, SYSTEM (\$216.65) | | 0670 | WATERBORNE PAVEMENT | Material | | | | SYSTEM | (\$216.65) | |
| 2025 6 Jul 1, 2025 \$216.65 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment Estimate Exception 23 on the current Payment Estimate. 7 Jul 16, SYSTEM (\$216.65) | | | | | | 5 | | SYSTEM | \$216.65 | Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment |
| 2025 Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment Estimate Exception 23 on the current Payment Estimate. 7 Jul 16, SYSTEM (\$216.65) | | | | | | 6 | | SYSTEM | (\$216.65) | |
| | | | | | | 6 | | SYSTEM | \$216.65 | Estimate Item Adjustment (0015) due to user mcclon1 overridding Payment |
| | | | | | | 7 | | SYSTEM | (\$216.65) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|---------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------------------------|---|
| JKU0029 | 0670 | 8 IN. WHITE WATERBORNE PAVEMENT MARKING | Material | - Total | 7 | Jul 16, 2025 | SYSTEM | \$216.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user mcclon1 overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$216.65) | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$216.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user mcclon1 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$216.65) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$216.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user doggea1 overridding Payment Estimate Exception 33 on the current Payment Estimate. |
| | | | | | | | | \$0.00 | |
| | | | Material - T | | | | | \$0.00 | |
| | | | Overrun | Overrun | 5 | Jun 16, 2025 | SYSTEM | (\$54.95) | |
| | | | | Overrun - T | otal | | | (\$54.95) | |
| | | | Overrun - T | | | | | (\$54.95) | |
| | 0670 | Total | | Overruin - Total | | | | | |
| | | COLDMILLING BIT. PAVT FOR REM OF SURF. | Overrun | Overrun | 8 | Aug 5, 2025 | SYSTEM | (\$54.95) (\$2,309.13) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | Overrun - T | otal | | | (\$2,309.13) | |
| | | | Overrun - T | Overrun - Total | | | | (\$2,309.13) | |
| | 0730 | Total | | | | | | (\$2,309.13) | |
| | 0740 | MISC. | Material | | 5 | Jun 16, 2025 | SYSTEM | (\$33,000.00) | |
| | | | | | 5 | Jun 16, 2025 | SYSTEM | \$33,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user mcclon1 overridding Payment Estimate Exception 25 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | (\$33,000.00) | |
| | | | | | 6 | Jul 1, 2025 | SYSTEM | \$33,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user mcclon1 overridding Payment Estimate Exception 26 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | (\$33,000.00) | |
| | | | | | 7 | Jul 16, 2025 | SYSTEM | \$33,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mcclon1 overridding Payment Estimate Exception 26 on the current Payment Estimate. |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | (\$33,000.00) | |
| | | | | | 8 | Aug 5, 2025 | SYSTEM | \$33,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user mcclon1 overridding Payment Estimate Exception 31 on the current Payment Estimate. |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | (\$33,000.00) | |
| | | | | | 9 | Aug 18, 2025 | SYSTEM | \$33,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user doggea1 overridding Payment Estimate Exception 36 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | | | Overrun | Overrun | 5 | Jun 16, 2025 | SYSTEM | (\$16,500.00) | |
| | | | | Overrun - Total | | | | (\$16,500.00) | |
| | | | Overrun - T | Overrun - Total | | | | | |
| | 0740 | Total | | | | | | (\$16,500.00) | |
| JKU0029 | - Total | | | | | | | (\$20,004.71) | |
| Overall - | Total | | | | | | | (\$258,621.85) | |
| | | | | | | | | . , , | |

MoDOT

Contract Adjustments for Contract - 241018-C05

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 24 of 24