

Pay Estimate Created Date: April 2, 2025

Progress Estimate N 4	umber	Contract ID Prime Contractor	241018-C13 Concrete Strateg		Pay Period Start Pay Period End			Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,081,739.00 \$15,219.75 \$2,096,958.75
Approval Date									By User
April 2, 2025			Generated and A	Approved (	(and should be cor	sidered	Draft) at	the Project Office Level by	sandis1
April 2, 2025		Re	eviewed and Appro	ved (and	should be consider	red Draf	t) at the F	Resident Engineer Level by	sandis1
April 4, 2025		Controllers Office Level by	s Office Level by ramses1						
Original Completion	n Date	Current Con	oletion Date Actual Completion Date % of C			of Current Contract Amoun	t Complete		
June 1, 2025		June 1	2025			50.16%			
	Contract	Informational Dat	tes		Miles	tones			
Date Description	Original	Completion Date	Current Comple	tion Date	No Milestones E	xist for	Contract		
Acceptance Date									
Awarded Date	Novembe	er 8, 2024	November 8, 202	4					
Letting Date	October	18, 2024	October 18, 2024						
Notice to Proceed Date	Decembe	er 9, 2024	December 9, 202	4					
Open to Traffic Date									

Contract Total Pay F	For Estimate No. 4				
		This Estimate	Previous	To Date	
241018-C13					
	Total Posted Items Pay	\$325,220.75	\$726,571.40	\$1,051,792.15	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$726,571.40	\$1,051,792.15	
<b>Contract Total Paya</b>	ble This Estimate:	\$325,220.75			

## Items Paid This Estimate Period

Work Began Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JKU0410	0020	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 2	EA	\$55,200.000	1	\$55,200.00
	0050	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 5	EA	\$49,350.000	-1	(\$49,350.00
	0270	2169902	MISC.REMOVAL OF DIAPHRAGM	EA	\$3,400.000	2	\$6,800.00
	0280	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	LB	\$25.000	488	\$12,200.00
	0290	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	LS	\$66,000.000	1	\$66,000.00
	0300	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	LS	\$9,900.000	1	\$9,900.00
	0310	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	LS	\$3,300.000	1	\$3,300.00
	0320	7125112	FINISH FIELD COAT (SYSTEM G)	LS	\$3,300.000	1	\$3,300.00
	0340	7129901	MISC.HEAT STRAIGHTENING	LS	\$83,500.000	1	\$83,500.00
	0350	7129901	MISC.NON-DESTRUCTIVE TESTING	LS	\$1.000	1	\$1.00
	0660	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	LS	\$72,200.000	0.5	\$36,100.00
	0670	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	LS	\$10,850.000	1	\$10,850.00
	0680	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	LS	\$3,600.000	1	\$3,600.00
	0690	7125112	FINISH FIELD COAT (SYSTEM G)	LS	\$3,600.000	1	\$3,600.00
	0700	7129901	MISC.GRIND SURFACE DEFORMITIES	LS	\$10,500.000	1	\$10,500.00
	0730	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	LS	\$62,400.000	0.5	\$31,200.00

Revision 3/23/2023 Page 1 of 14



Pay Estimate Created Date: April 2, 2025

Progress Estimate Number	Contract ID				Original Contract Amount	
4	Prime Contractor	Concrete Strategies, LLC	Pay Period End	April 1, 2025	Net Change Order Amount	\$15,219.75
					Current Contract Amount	\$2,096,958.75

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JKU0410	0740	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	LS	\$9,300.000	1	\$9,300.00
	0750	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	LS	\$3,100.000	1	\$3,100.00
	0760	7125112	FINISH FIELD COAT (SYSTEM G)	LS	\$3,100.000	1	\$3,100.00
	0770	7129901	MISC.GRIND SURFACE DEFORMITIES	LS	\$7,800.000	1	\$7,800.00
	5001	6169902	MISC.Misc. Temp traffic Control Bridge Location 8	EA	\$6,168.750	1	\$6,168.75
	5002	6169902	MISC.Misc Traffic Control Location 2	EA	\$9,051.000	1	\$9,051.00
Project JKU0	410 - Total						\$325,220.75
Overall - Tota	ı						\$325,220.75

### **Contract Adjustments This Estimate**

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
Varibei	140.		Турс	Туре		Quantity	Unit Price	amount
KU0410	0290	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material			-1	\$66,000.00	(\$66,000.00)
	0290	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1	\$66,000.00	\$66,000.00
	0300	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material			-1	\$9,900.00	(\$9,900.00)
	0300	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1	\$9,900.00	\$9,900.00
	0310	INTERMEDIATE FIELD COAT (SYSTEM G)	Material			-1	\$3,300.00	(\$3,300.00)
	0310	INTERMEDIATE FIELD COAT (SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$3,300.00	\$3,300.00
	0320	FINISH FIELD COAT (SYSTEM G)	Material			-1	\$3,300.00	(\$3,300.00
	0320	FINISH FIELD COAT (SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	1	\$3,300.00	\$3,300.00
	0380	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material			-1	\$35,700.00	(\$35,700.00)
	0380	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1	\$35,700.00	\$35,700.00
0	0390	FIELD APPLICATION OF INORGANIC ZINC PRIMER			-1	\$5,350.00	(\$5,350.00)	
	0390	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user kennec2	1	\$5,350.00	\$5,350.00

Revision 3/23/2023 Page 2 of 14



Pay Estimate Created Date: April 2, 2025

Progress Estimate Number
4

Contract ID 241018-C13 Pay Period Start March 16, 2025 Original Contract Amount \$2,081,739.00 Pay Period End April 1, 2025 Original Contract Amount \$15,219.75 Current Contract Amount \$2,081,739.00 \$15,219.75 \$15,21

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
KU0410					overridding Payment Estimate Exception 6 on the current Payment Estimate.			
	0400	INTERMEDIATE FIELD COAT (SYSTEM G)	Material			-1	\$1,800.00	(\$1,800.00)
	0400	INTERMEDIATE FIELD COAT (SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	1	\$1,800.00	\$1,800.00
	0410	FINISH FIELD COAT (SYSTEM G)	Material			-1	\$1,800.00	(\$1,800.00)
	0410	FINISH FIELD COAT (SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	1	\$1,800.00	\$1,800.00
	0660	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material			-1	\$72,200.00	(\$72,200.00)
	0660	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1	\$72,200.00	\$72,200.00
	0670	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material			-1	\$10,850.00	(\$10,850.00)
	0670	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1	\$10,850.00	\$10,850.00
	0680	INTERMEDIATE FIELD COAT (SYSTEM G)	Material			-1	\$3,600.00	(\$3,600.00)
	0680	INTERMEDIATE FIELD COAT (SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.	1	\$3,600.00	\$3,600.00
	0690	FINISH FIELD COAT (SYSTEM G)	Material			-1	\$3,600.00	(\$3,600.00)
	0690	FINISH FIELD COAT (SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.	1	\$3,600.00	\$3,600.00
	0730	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material			-1	\$62,400.00	(\$62,400.00)
	0730			generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 4 on	1	\$62,400.00	\$62,400.00	
	0740	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material				\$9,300.00	(\$9,300.00)
	0740	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 8 on	1	\$9,300.00	\$9,300.00

Revision 3/23/2023 Page 3 of 14



Pay Estimate Created Date: April 2, 2025

	Contract ID	241018-C13		-, -	Original Contract Amount	, , ,
4	Prime Contractor	Concrete Strategies, LLC	Pay Period End	April 1, 2025	Net Change Order Amount	\$15,219.75
4					<b>Current Contract Amount</b>	\$2,096,958.75

							in Contidot	ναιισαιιτ ψε	2,000,000.70
Project Number	Line No.	Item Descri	otion	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JKU0410						the current Payment Estimate.			
	0750	INTERMEDI COAT (S	ATE FIELD SYSTEM G)	Material			-1	\$3,100.00	(\$3,100.00)
	0750	INTERMEDI COAT (S	ATE FIELD SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	1	\$3,100.00	\$3,100.00
	0760		ELD COAT SYSTEM G)	Material			-1	\$3,100.00	(\$3,100.00)
	0760		ELD COAT SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user kennec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$3,100.00	\$3,100.00
Total									\$0.00

Revision 3/23/2023 Page 4 of 14



					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
JKU0410	FAS S304(46)	9 Bridge rehabilitations	Various	JACKSON	at various locations in	the urban Kansas City Distri	ct
Totals by J	lob Numbe	rs					
JKU0410					This Estimate	Previous	To Date
	Poste	d Item Pay			\$325,220.75	\$726,571.40	\$1,051,792.15
		d Item Pay Item Adjustme			\$325,220.75 \$0.00	\$726,571.40 \$0.00	\$1,051,792.15 \$0.00
			nts Gross It	em Pay			\$1,051,792.15
		Item Adjustme		em Pay	\$0.00	\$0.00	\$1,051,792.15 \$0.00
	Gross	Item Adjustme		em Pay	\$0.00 <b>\$325,220.75</b>	\$0.00 <b>\$726,571.40</b>	\$1,051,792.15 \$0.00 <b>\$1,051,792.15</b>
	Gross Incent Disinc	Item Adjustme		em Pay	\$0.00 <b>\$325,220.75</b> \$0.00	\$0.00 <b>\$726,571.40</b> \$0.00	\$1,051,792.15 \$0.00 <b>\$1,051,792.15</b> \$0.00

Revision 3/23/2023 Page 5 of 14



## **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Feriou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125100, Project Item Line Number 0290, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125100, Project Item Line Number 0380, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125100, Project Item Line Number 0660, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125100, Project Item Line Number 0730, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125110, Project Item Line Number 0300, Material Set 712511096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125110, Project Item Line Number 0390, Material Set 712511096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125110, Project Item Line Number 0670, Material Set 712511096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125110, Project Item Line Number 0740, Material Set 712511096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125111, Project Item Line Number 0310, Material Set 712511196, Material 1045PTEP - High Solids Epoxy System G Intrmdte Coat, Acceptance Action Generic 1045PTEP is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125111, Project Item Line Number 0400, Material Set 712511196, Material 1045PTEP - High Solids Epoxy System G Intrmdte Coat, Acceptance Action Generic 1045PTEP is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125111, Project Item Line Number 0680, Material Set 712511196, Material 1045PTEP - High Solids Epoxy System G Intrmdte Coat, Acceptance Action Generic 1045PTEP is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125111, Project Item Line Number 0750, Material Set 712511196, Material 1045PTEP - High Solids Epoxy System G Intrmdte Coat, Acceptance Action Generic 1045PTEP is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125112, Project Item Line Number 0320, Material Set 712511296, Material 1045PTAP - Polyurethane System G Finish Coating, Acceptance Action Generic 1045PTAP is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125112, Project Item Line Number 0410, Material Set 712511296, Material 1045PTAP - Polyurethane System G Finish Coating, Acceptance Action Generic 1045PTAP is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125112, Project Item Line Number 0690, Material Set 712511296, Material 1045PTAP - Polyurethane System G Finish Coating, Acceptance Action Generic 1045PTAP is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKU0410, Item 7125112, Project Item Line Number 0760, Material Set 712511296, Material 1045PTAP - Polyurethane System G Finish Coating, Acceptance Action Generic 1045PTAP is insufficient.	Sample record has been created, need to tie to this line item.	kennec2	Overridden

Revision 3/23/2023 Page 6 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241018-C13	JKU0410	0001	0010	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 1	1.00	0.00	1.00	EA	0.00	\$52,100.00	\$0.00
		0001	0020	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 2	1.00	0.00	1.00	EA	1.00	\$55,200.00	\$55,200.00
		0001	0030	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 3	1.00	0.00	1.00	EA	1.00	\$48,400.00	\$48,400.00
		0001	0040	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 4	1.00	0.00	1.00	EA	0.00	\$61,750.00	\$0.00
		0001	0050	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 5	1.00	0.00	1.00	EA	0.00	\$49,350.00	\$0.00
		0001	0060	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 6	1.00	0.00	1.00	EA	0.00	\$48,200.00	\$0.00
		0001	0070	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 7	1.00	0.00	1.00	EA	0.00	\$10,150.00	\$0.00
		0001	0080	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.86	\$240,600.00	\$207,878.40
		0001	0082	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 8	1.00	0.00	1.00	EA	1.00	\$58,200.00	\$58,200.00
		0001	0084	6169902	MISC.TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 9	1.00	0.00	1.00	EA	1.00	\$52,850.00	\$52,850.00
		0070	0090	2169902	MISC.REMOVAL OF DIAPHRAGM	2.00	0.00	2.00	EA	0.00	\$2,300.00	\$0.00
		0070	0100	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	520.00	0.00	520.00	LB	0.00	\$24.00	\$0.00
		0070	0110	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$43,000.00	\$0.00
		0070	0120	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$6,450.00	\$0.00
		0070	0130	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$2,150.00	\$0.00
		0070	0140	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$2,150.00	\$0.00
		0070	0150	7129901	MISC.GRIND SURFACE DEFORMITIES	1.00	0.00	1.00	LS	0.00	\$10,300.00	\$0.00
		0070	0160	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	0.00	\$72,500.00	\$0.00
		0070	0170	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0071	0180	2169902	MISC.REMOVAL OF DIAPHRAGM	4.00	0.00	4.00	EA	0.00	\$3,400.00	\$0.00
		0071	0190	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	1,020.00	0.00	1,020.00	LB	0.00	\$33.00	\$0.00
		****	0200	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL	1.00	0.00	1.00	LS	0.00	\$115,000.00	\$0.00
		0071	0210	7125110	STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$17,250.00	\$0.00
		0071	0220	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$5,750.00	\$0.00
		0071	0230	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$5,750.00	\$0.00
		0071	0240	7129901	MISC.GRIND SURFACE DEFORMITIES	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.00
		0071	0250	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	0.00	\$61,500.00	\$0.00
		0071	0260	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0072	0270	2169902	MISC.REMOVAL OF DIAPHRAGM	2.00	0.00	2.00	EA	2.00	\$3,400.00	\$6,800.00
		0072	0280	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	650.00	0.00	650.00	LB	488.00	\$25.00	\$12,200.00
		0072	0290	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	1.00	\$66,000.00	\$66,000.00
		0072	0300	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	1.00	\$9,900.00	\$9,900.00
		0072	0310	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$3,300.00	\$3,300.00
		0072	0320	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$3,300.00	\$3,300.00
		0072	0330	7129901	MISC.GRIND SURFACE DEFORMITIES	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.00
		0072	0340	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	1.00	\$83,500.00	\$83,500.00
		0072	0350	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.00
		0073	0360	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	0.00	\$550.00	\$0.00
		0073	0370	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$455.00	\$0.00
		0073	0380	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL	1.00	0.00	1.00	LS	1.00	\$35,700.00	\$35,700.00
		0073	0390	7125110	STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	1.00	\$5,350.00	\$5,350.00
		0073	0400	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$1,800.00	\$1,800.00
		0073	0410	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$1,800.00	\$1,800.00
		0073	0420	7129901	MISC.GRIND SURFACE DEFORMITIES	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.00

Revision 3/23/2023 Page 7 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted an Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241018-C13	JKU0410	0073	0430	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	1.00	\$39,500.00	\$39,500.00
		0073	0440	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.00
		0074	0450	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$39,300.00	\$0.00
		0074	0460	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$5,900.00	\$0.00
		0074	0470	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$1,950.00	\$0.00
		0074	0480	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$1,950.00	\$0.00
		0074	0490	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	0.00	\$25,500.00	\$0.00
		0074	0500	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0075	0510	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$41,900.00	\$0.00
		0075	0520	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$6,300.00	\$0.00
		0075	0530	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$2,100.00	\$0.00
		0075	0540	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$2,100.00	\$0.00
		0075	0550	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	0.00	\$29,000.00	\$0.00
		0075	0560	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0076	0570	2169902	MISC.REMOVAL OF DIAPHRAGM	15.00	0.00	15.00	EA	0.00	\$3,500.00	\$0.00
		0076	0580	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$84,700.00	\$0.00
		0076	0590	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$12,250.00	\$0.00
		0076	0600	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$4,100.00	\$0.00
		0076	0610	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$4,100.00	\$0.00
		0076	0620	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	0.00	\$25,500.00	\$0.00
		0076	0630	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0077	0640	2169902	MISC.REMOVAL OF DIAPHRAGM	1.00	0.00	1.00	EA	1.00	\$4,200.00	\$4,200.00
		0077	0650	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	280.00	0.00	280.00	LB	280.00	\$33.00	\$9,240.00
		0077	0660	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL	1.00	0.00	1.00	LS	1.00	\$72,200.00	\$72,200.00
		0077	0670	7125110	STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	1.00	\$10,850.00	\$10,850.00
		0077	0680	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$3,600.00	\$3,600.00
		0077	0690	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$3,600.00	\$3,600.00
		0077	0700	7129901	MISC.GRIND SURFACE DEFORMITIES	1.00	0.00	1.00	LS	1.00	\$10,500.00	\$10,500.00
		0077	0710	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	1.00	\$83,500.00	\$83,500.00
			0710	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.00
		0077										
		0078	0730		SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	1.00	\$62,400.00	\$62,400.00
		0078	0740	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	1.00	\$9,300.00	\$9,300.00
		0078	0750	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$3,100.00	\$3,100.00
		0078	0760	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$3,100.00	\$3,100.00
		0078	0770	7129901	MISC.GRIND SURFACE DEFORMITIES	1.00	0.00	1.00	LS	1.00	\$7,800.00	\$7,800.00
		0078	0780	7129901	MISC.HEAT STRAIGHTENING	1.00	0.00	1.00	LS	1.00	\$61,500.00	\$61,500.00
		0078	0790	7129901	MISC.NON-DESTRUCTIVE TESTING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.00
		0077	5001	6169902	MISC.Misc. Temp traffic Control Bridge Location 8	0.00	1.00	1.00	EA	1.00	\$6,168.75	\$6,168.75
		0072	5002	6169902	MISC.Misc Traffic Control Location 2	0.00	1.00	1.00	EA	1.00	\$9,051.00	\$9,051.00
		0078	5003	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	0.00	0.00	0.00	LB	0.00	\$0.00	\$0.00
		0001	5004	6169902	MISC.MISC. TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 1	0.00	0.00	0.00	EA	0.00	\$0.00	\$0.00
		0001	5005	6169902	MISC. MISC. TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 4	0.00	0.00	0.00	EA	0.00	\$0.00	\$0.00
		0001	5006	6169902	MISC.MISC. TEMPORARY TRAFFIC CONTROL BRIDGE LOCATION 5/6	0.00	0.00	0.00	EA	0.00	\$0.00	\$0.00
	Project J	(U0410 - T	otal Value	e Posted to	Date as of Report Generated Date							\$1,051,792.15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

140to. 1 ootou Q	adminio	aria valac	o alo b	acca ciri	toport Concreted date and earl affer from the posted and	iount at a	io unito u	io Louinato	Wao Co	noratoa.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241018-C13 Ove	rall - Total	Value Post	ed to Dat	e as of Rep	port Generated Date							\$1,051,792.15

Revision 3/23/2023 Page 9 of 14



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: JKI I0410

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	6169902	MISC. TRAFFIC CONTROL DEVICES	3/28/25	4/2/25	1.00	EA	Blue Ridge and MO 350	+		+		
0050	6169902	MISC. TRAFFIC CONTROL DEVICES	3/28/25	4/2/25	-1.00	EA		+		+		Payment was intended for line 0020.
0270	2169902	MISC. REMOVALS	3/28/25	4/2/25	2.00	EA	Bridge L0126 Blue Ridge over MO 350	6.43		6.43		
0280	7121000	FAB. STRUCT. CARBON STEEL (MISC)	3/28/25	4/2/25	488.00	LB	Bridge L0126 Blue Ridge over MO 350	6.43		6.43		Diaphragms fabricated and delivered on site as to shop drawings, diaphragms were too small to fit opening between girders, being refabricated.
0290	7125100	SURFACE PREPARATION FOR RECOATING STRUC	3/28/25	4/2/25	1.00	LS	Blue ridge surface prep for heat straightening	+		+		
0300	7125110	FIELD APPLICATION OF INORGANIC ZINC	3/28/25	4/2/25	1.00	LS	Bridge L0126 Blue Ridge over MO 350	6.43		6.43		
0310	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	3/28/25	4/2/25	1.00	LS	Bridge L0126 Blue Ridge over MO 350	6.43		6.43		
0320	7125112	FINISH FIELD COAT (SYSTEM G)	3/28/25	4/2/25	1.00	LS	Bridge L0126 Blue Ridge over MO 350	6.43		6.43		
0340	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	3/17/25	3/31/25	1.00	LS	Bridge L0126					Contractor on site: ISI. Judd and 3-ironworkers on site completing the heat straightening on girders #8 and #9 addressed critical issues on girder #8 and #9 marked b Terracon while performing the mag-test.
0350	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	3/17/25	3/31/25	1.00	LS	Bridge L0126					Terracon (Mike) in site on Thursday, March 13, - 11:00 and GBAVasile observed NDT may-lest on girdref &8#9. Chris of MoDOT was on site as well. Critical issu were addressed and repairs on Saturday, 3/14. Magtesting completed.  GBAVasile
0660	7125100	SURFACE PREPARATION FOR RECOATING STRUC	3/28/25	3/31/25	0.50	LS	Bridge A 3344 NB US-169 Outer Road @ Cookingham Road.					Completed 03/27/2025
0670	7125110	FIELD APPLICATION OF INORGANIC ZINC	3/28/25	3/31/25	1.00	LS	Bridge A 3344 NB US-169 Outer Road					Completed 3/27/2025.
0680	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	3/28/25	3/31/25	1.00	LS	Bridge A 3344 NB US-169 Outer Road					Completed 100%
0690	7125112	FINISH FIELD COAT (SYSTEM G)	3/28/25	3/31/25	1.00	LS	Bridge A 3344 NB US-169 @ Cookingham Road.					Completed 3/27/25 100%.
0700	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	3/17/25	3/31/25	0.50	LS	A3344					Completed EB/WB inside lanes only.
			3/28/25	3/31/25	0.50	LS	Bridge A 3344 NB US-169 @ Cookingham Road					Completed 3/27/25 100%.
0730	7125100	SURFACE PREPARATION FOR RECOATING STRUC	3/28/25	3/31/25	0.50	LS	Bridge A 3345 Main NB US-169 @ Cookingham Road.					Complete on 03/27/25 100%.
0740	7125110	FIELD APPLICATION OF INORGANIC ZINC	3/28/25	3/31/25	1.00	LS	Bridge A 3345 Main NB US-169 @ Cookingham Road.					Completed 03/27/25 100%.
0750	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	3/28/25	3/31/25	1.00	LS	Bridge A 3345 Main NB US-169 @ Cookingham Road.					Completed 03/27/25 100%.
0760	7125112	FINISH FIELD COAT (SYSTEM G)	3/28/25	3/31/25	1.00	LS	Bridge A 3345 Main NB US-169 @ Cookingham Road.					Completed 03/27/25 100%.
0770	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	3/28/25	3/31/25	1.00	LS	Bridge A 3345 Main NB US-169 @ Cookingham Road.					Completed 03/27/25 100%.
5001	6169902	MISC. TRAFFIC CONTROL DEVICES	3/28/25	4/2/25	1.00	EA	US-169 and Cookingham Drive	14.933		14.933		Additional traffic control costs
5002	6169902	MISC. TRAFFIC CONTROL DEVICES	3/28/25	4/2/25	1.00	EA	Blue Ridge and MO 350	6.43		6.43		Additional traffic control costs

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 10 of 14



## Line Item Adjustments by Estimate

Contract ID: 241018-C13

Type Adjustment Number Date By Type	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks			
PREPARATION   PROCESTING   2005   Estimate Exception 1 on the outrant Physmeth Estimate.   Estimate Exception 1 on the outrant Physmeth Estimate.   Estimate Exception 1 on the outrant Physmeth Estimate.	,		,		Adjustment	Number	Date	Ву					
A	KU0410	0290	PREPARATION FOR	Material		4		SYSTEM	\$66,000.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment			
Material - Total						4		SYSTEM	(\$66,000.00)				
Material   FELD   Material   Apr 2   SYSTEM   \$9,000   This adjustment offices the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.   Feld					- Total				\$0.00				
PROPERTY   Property				Material - To	otal				\$0.00				
APPLICATION   CFINORGANIC   2025		0290 -	Total						\$0.00				
A		0300	APPLICATION OF INORGANIC	Material		4		SYSTEM	\$9,900.00	Estimate Item Adjustment (0002) due to user kennec2 overridding Payment			
Material - Total			ZINC			4		SYSTEM	(\$9,900.00)				
					- Total				\$0.00				
Material - Total   Apr 2, SYSTEM   S3,300.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 1 on t				Material - To	otal				\$0.00				
FIELD COAT (SYSTEM G)		0300 -	Total						\$0.00				
2025   SUBSTACE   Material - Total   Substantial Exception 1 on the current Payment Estimate   Substantial Exception 1 on the current Payment Estimate   Substantial Exception 2 on the current Payment Estimate   Substantial Exception 2 on the current Payment Estimate   Substantial Exception 3 on the current Payment Estimate   Substantial Exception 4 on the curr		0310	FIELD COAT	Material		4		SYSTEM	\$3,300.00	Estimate Item Adjustment (0003) due to user kennec2 overridding Payment			
State						4		SYSTEM	(\$3,300.00)				
State					- Total				\$0.00				
Signature   Content				Material - To	otal				\$0.00				
COAT (SYSTEM S)		0310 -	Total						\$0.00				
2025   Sundant   Sundant		0320	COAT	Material		4		SYSTEM	\$3,300.00	Estimate Item Adjustment (0004) due to user kennec2 overridding Payment			
Material - Total						4		SYSTEM	(\$3,300.00)				
SURFACE   PREPARATION   FOR RECOATING   STRUC					- Total				\$0.00				
Surface   PREPARATION   FOR RECOATING STRUC				Material - To	otal				\$0.00				
PREPARATION FOR RECOATING STRUC		0320 -	Total						\$0.00				
2		0380	PREPARATION FOR RECOATING	Material		2		SYSTEM	\$35,700.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment			
2025   Sestimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.						2		SYSTEM	(\$35,700.00)				
2025									3		SYSTEM	\$35,700.00	Estimate Item Adjustment (0001) due to user kennec2 overridding Payment
2025   SYSTEM   S35,700.00						3		SYSTEM	(\$35,700.00)				
Total  S0.00    Material - Total   \$0.00						4		SYSTEM	\$35,700.00	Estimate Item Adjustment (0005) due to user kennec2 overridding Payment			
Solid National State   Solid National State						4		SYSTEM	(\$35,700.00)				
Solution   Solution					- Total			\$0.00					
Day				Material - To	otal				\$0.00				
APPLICATION OF INORGANIC ZINC  2025 Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.  2 Mar 3, 2025 SYSTEM (\$5,350.00)  3 Mar 17, 2025 SYSTEM \$5,350.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.  3 Mar 17, 2025 SYSTEM (\$5,350.00)		0380 -	Total						\$0.00				
2 Mar 3, 2025 SYSTEM (\$5,350.00)  3 Mar 17, 2025 SYSTEM \$5,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.  3 Mar 17, 2025 SYSTEM (\$5,350.00)		0390	APPLICATION OF INORGANIC	Material		2		SYSTEM	\$5,350.00	Estimate Item Adjustment (0002) due to user kennec2 overridding Payment			
2025 Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.  3 Mar 17, 2025 (\$5,350.00)			ZING			2		SYSTEM	(\$5,350.00)				
2025						3		SYSTEM	\$5,350.00	Estimate Item Adjustment (0002) due to user kennec2 overridding Payment			
4 Apr 2, SYSTEM \$5,350.00 This adjustment offsets the original system-generated Material Payment						3		SYSTEM	(\$5,350.00)				
						4	Apr 2,	SYSTEM	\$5,350.00	This adjustment offsets the original system-generated Material Payment			



## Line Item Adjustments by Estimate

Contract ID: 241018-C13

oject	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J0410	0390	FIELD APPLICATION	Material	Туре		2025			Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		OF INORGANIC ZINC			4	Apr 2, 2025	SYSTEM	(\$5,350.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0390 -	Total						\$0.00	
	0400	INTERMEDIATE FIELD COAT (SYSTEM G)	Material		3	Mar 17, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Mar 17, 2025	SYSTEM	(\$1,800.00)	
					4	Apr 2, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Apr 2, 2025	SYSTEM	(\$1,800.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0400 -	Total						\$0.00	
	0410	FINISH FIELD COAT (SYSTEM G)	Material		3	Mar 17, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		(0.0.2			3	Mar 17, 2025	SYSTEM	(\$1,800.00)	
					4	Apr 2, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					4	Apr 2, 2025	SYSTEM	(\$1,800.00)	
				- Total	Total			\$0.00	
			Material - To	tal				\$0.00	
	0410 -	Total						\$0.00	
	0660	SURFACE PREPARATION FOR RECOATING STRUC	Material		2	Mar 3, 2025	SYSTEM	\$36,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Mar 3, 2025	SYSTEM	(\$36,100.00)	
					3	Mar 17, 2025	SYSTEM	\$36,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Mar 17, 2025	SYSTEM	(\$36,100.00)	
					4	Apr 2, 2025	SYSTEM	\$72,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Apr 2, 2025	SYSTEM	(\$72,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0660 -	Total						\$0.00	
	0670	FIELD APPLICATION OF INORGANIC	Material		4	Apr 2, 2025	SYSTEM	\$10,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		ZINC			4	Apr 2, 2025	SYSTEM	(\$10,850.00)	
				- Total				\$0.00	
			Material - To	terial - Total					
	0670 -	Total						\$0.00	



## Line Item Adjustments by Estimate

Contract ID: 241018-C13

NUMBER   Color   Col	Project	Line	Description	Adjustment Type	Other	Est.	Created Date	Created By	Amount	Remarks
A				Туре		Number	Date	Бу		
Total   Material   Total   So   So	JKU0410	0680	(SYSTEM G)	Material						Estimate Exception 11 on the current Payment Estimate.
Material   Total						4		SYSTEM	(\$3,600.00)	
0500   TNUSH RELD   Maketal					- Total				\$0.00	
PRINCE PRICE   Material				Material - To	otal				\$0.00	
COAT		0680 -	Total						\$0.00	
Total		0690	COAT	Material		4		SYSTEM	\$3,600.00	Estimate Item Adjustment (0012) due to user kennec2 overridding Payment
Material - Total   So 00   SURFACE   Material - Total   So 00   SURFACE   PEEPARATION   PEEPARATIO						4		SYSTEM	(\$3,600.00)	
SURFACE   PREPARATION   PROPARATION   PROP					- Total				\$0.00	
0730   SURPICE   PREPARATION   PREPARATION				Material - To	otal				\$0.00	
PREPARATION   FOR   PREPARATION   PREPARAT		0690 -	Total						\$0.00	
STRUC		0730	PREPARATION FOR	Material		2		SYSTEM	\$31,200.00	Estimate Item Adjustment (0004) due to user kennec2 overridding Payment
2025   SySTEM   S31,200.00   Set user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate Exception 6 on						2		SYSTEM	(\$31,200.00)	
						3		SYSTEM	\$31,200.00	Estimate Item Adjustment (0006) due to user kennec2 overridding Payment
2025   SYSTEM   Similar   Item Aglustment (0013) due to user kennec2 overridding Payment   Estimate   Estimate   Exception 4 on the current Payment Estimate.						3		SYSTEM	(\$31,200.00)	
2025   So.00   Material - Total   So.00     So.00     So.00     So.00     So.00     So.00     So.00     So.00     So.00     So.00						4		SYSTEM	\$62,400.00	Estimate Item Adjustment (0013) due to user kennec2 overridding Payment
Material - Total   \$0.00						4		SYSTEM	(\$62,400.00)	
10740					- Total				\$0.00	
				Material - To	otal				\$0.00	
APPLICATION OF INORGANIC ZINC   2025   Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.   2025   SYSTEM (\$9,300.00)     2000   2000     2000		0730 -	Total						\$0.00	
Apr 2, 2025   SYSTEM   (\$9,300.00)		0740	APPLICATION OF INORGANIC	Material		4		SYSTEM	\$9,300.00	Estimate Item Adjustment (0014) due to user kennec2 overridding Payment
Material - Total   S0.00								SYSTEM	(\$9,300.00)	
10740 - Total   10750   INTERMEDIATE					- Total				\$0.00	
O750   INTERMEDIATE   FIELD COAT (SYSTEM G)				Material - To	rial - Total					
FIELD COAT (SYSTEM G)		0740 -	Total						\$0.00	
Total   \$0.00		0750	FIELD COAT	Material		4		SYSTEM	\$3,100.00	Estimate Item Adjustment (0015) due to user kennec2 overridding Payment
Material - Total   \$0.00						4		SYSTEM	(\$3,100.00)	
O750 - Total   S0.00					- Total				\$0.00	
O760   FINISH FIELD   COAT (SYSTEM G)   Material   Apr 2, 2025   SYSTEM   \$3,100.00   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kennec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.   Apr 2, 2025   SYSTEM (\$3,100.00)				Material - To	otal				\$0.00	
COAT (SYSTEM G)		0750 -	Total						\$0.00	
2025   S		0760	COAT	Material		4		SYSTEM	\$3,100.00	Estimate Item Adjustment (0016) due to user kennec2 overridding Payment
Material - Total \$0.00  0760 - Total \$0.00  JKU0410 - Total \$0.00						4		SYSTEM	(\$3,100.00)	
0760 - Total     \$0.00       JKU0410 - Total     \$0.00					- Total				\$0.00	
JKU0410 - Total \$0.00				Material - To	erial - Total					
		0760 -	Total						\$0.00	
Overall - Total \$0.00	JKU0410	- Total							\$0.00	
	Overall -	Total							\$0.00	

## MoDOT

## Contract Adjustments for Contract - 241018-C13

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 14 of 14