

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 17, 2025

Progress Estimate Number	Contract ID	241018-S01	Pay Period Start	April 2, 2025	Original Contract Amount	\$1,676,182.10
5	Prime Contractor	Plattin Creek Excavating, LLC dba PCX Construction, LLC	Pay Period End	April 15, 2025	Net Change Order Amount	(\$7,638.10)
					Current Contract Amount	\$1,668,544.00

Approval Date					By User
April 17, 2025		Generated and	Approved (and should be considere	d Draft) at the Project Office Level by	collie1
April 17, 2025		Reviewed and Appro	oved (and should be considered Dra	ft) at the Resident Engineer Level by	wilkem1
April 18, 2025			Reviewed and Approved at the Cen	tral Office Controllers Office Level by	ramses1
Original Comp	letion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amou	nt Complete
March 31	2025	March 31, 2025		79.79%	

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	November 8, 2024	November 8, 2024	
Letting Date	October 18, 2024	October 18, 2024	
Notice to Proceed Date	December 9, 2024	December 9, 2024	
Open to Traffic Date			
Work Began Date			

Contract Total P	ay For Estimate No. 5			
		This Estimate	Previous	To Date
241018-S01				
	Total Posted Items Pay	\$288,362.00	\$1,043,032.00	\$1,331,394.00
	Gross Item Adjustments	\$12,000.00	(\$12,000.00)	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	(\$1,500.00)	(\$1,500.00)
	Other Contract Adjustments	\$11,300.00	(\$9,800.00)	\$1,500.00
	·		\$1,019,732.00	\$1,331,394.00
Contract Total P	avable This Estimate:	\$311,662,00		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JST0071	0090	6189901	MISC.MOBILIZATION FOR BRIDGE NO A1700	LS	\$215,000.000	0.5	\$107,500.00
	0200	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	SQFT	\$228.000	4	\$912.00
	0210	7034204	CLASS B-2 CONCRETE (SUPERSTRUCTURE ON STEEL)	CUYD	\$28,600.000	1.4	\$40,040.00
	0220	7061070	MECHANICAL BAR SPLICE	EA	\$100.000	78	\$7,800.00
	0230	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$3.000	420	\$1,260.00
	0270	7129902	MISC.STRUCTURAL STEEL - BOLTED SPLICE REPAIR LOCATION NO. 1	EA	\$94,800.000	0.75	\$71,100.00
	0290	7129903	MISC.DEFECT REMOVAL FOR BRIDGE NO. A1700	LF	\$26,600.000	1.5	\$39,900.00
	0300	7129903	MISC.WELD INSPECTION FOR BRIDGE NO. A1700	LF	\$400.000	5	\$2,000.00
	0310	7129903	MISC.WELD REPAIR FOR BRIDGE NO. A1700	LF	\$11,900.000	1.5	\$17,850.00
Project JST	0071 - Total						\$288,362.00
Overall - To	tal						\$288,362.00

Contract Adjustments This Estimate

Contract Adjustment ID	Adj Type	Entered By	Comments	Time Units	Rate	Amount
6895	RUCOther Contract Adjustment		LD's Road User Cost from April 1st			\$9,800.00
6896		collie1	LD's Administration Cost from April 1st			\$1,500.00

Revision 3/23/2023 Page 1 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 17, 2025

Progress Estimate Number	Contract ID	241018-S01	Pay Period Start	April 2, 2025	Original Contract Amount	\$1,676,182.10
5	Prime Contractor	Plattin Creek Excavating, LLC dba PCX Construction, LLC	Pay Period End	April 15, 2025	Net Change Order Amount	(\$7,638.10)
					Current Contract Amount	\$1,668,544.00

			30					Current Cor Amount	ntract	\$1,668,544.00
Contract	Adjustn	ment ID	Adj Type	Entere	ed By	Comments	Time Units	Rate	A	Amount
Overall -	Total									\$11,300.00
na Itam	Adiust			ed in the Ince	entive, Disino	centive, Liquidated Da	mages or Other Contra	ıct Adjustmer	nts	
ne item	Aujust	ments ini	s Estimate						,	
Project Number	Line No.	Ite	m Description	Adjustment Type	Other Item Adjustment Type	Com	nments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JST0071	0030	INTERFA	GEABLE MESSAGE SIGN WITHOUT COMMUNICATION ICE, CONTRACTOR IED, CONTRACTOR RETAINED	Overrun		adjustments fo previous p	sed on averaged overrur r installed quantity on al ayment estimates. Price .00000 - 3000.00000, 'is applied (if non-zero)		\$3,000.00	\$12,000.00
	0210		SS B-2 CONCRETE ERSTRUCTURE ON STEEL)	Material				-1.4	\$28,600.00	(\$40,040.00
	0210		SS B-2 CONCRETE ERSTRUCTURE ON STEEL)	Material		generated Material Adjustment ((overridding Payment	sets the original system- I Payment Estimate Item 2002) due to user collie1 Estimate Exception 1 or rrent Payment Estimate.		\$28,600.00	\$40,040.00
	0240		ACE PREPARATION FOR RECOATING TRUCTURAL STEEL	Material				-0.6	\$55,000.00	(\$33,000.00
	0240		ACE PREPARATION FOR RECOATING FRUCTURAL STEEL	Material		generated Material Adjustment ((overridding Payment	sets the original system- I Payment Estimate Item 2003) due to user collie1 Estimate Exception 4 or rrent Payment Estimate.		\$55,000.00	\$33,000.00
	0250		D APPLICATION OF ANIC ZINC PRIMER	Material				-0.5	\$5,000.00	(\$2,500.00
	0250		D APPLICATION OF ANIC ZINC PRIMER	Material		generated Material Adjustment ((overridding Payment	sets the original system- I Payment Estimate Item 2004) due to user collie1 Estimate Exception 7 or rrent Payment Estimate		\$5,000.00	\$2,500.00
	0320		ACE PREPARATION FOR RECOATING TRUCTURAL STEEL	Material				-1	\$45,000.00	(\$45,000.00
	0320		ACE PREPARATION FOR RECOATING FRUCTURAL STEEL	Material		generated Material Adjustment (0 overridding Payment	sets the original system- I Payment Estimate Item 2005) due to user collie1 Estimate Exception 5 or rrent Payment Estimate.		\$45,000.00	\$45,000.00
	0330		D APPLICATION OF ANIC ZINC PRIMER	Material				-1	\$5,000.00	(\$5,000.00
	0330		D APPLICATION OF ANIC ZINC PRIMER	Material		generated Material Adjustment ((overridding Payment	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			\$5,000.00
	0340		MISC.	Material				-1	\$5,000.00	(\$5,000.00
	0340		MISC.	Material		generated Material Adjustment ((overridding Paymer	sets the original system- I Payment Estimate Item 0007) due to user collie1 It Estimate Exception 10 rrent Payment Estimate.		\$5,000.00	\$5,000.00
	0380	SURFA	ACE PREPARATION FOR RECOATING	Material				-1	\$50,000.00	(\$50,000.00)

Revision 3/23/2023 Page 2 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 17, 2025

Progress Estimate Number	Contract ID	241018-S01	Pay Period Start	April 2, 2025	Original Contract Amount	\$1,676,182.10
5	Prime Contractor	Plattin Creek Excavating, LLC dba PCX Construction, LLC	Pay Period End	April 15, 2025	Net Change Order Amount	(\$7,638.10)
					Current Contract Amount	\$1,668,544.00

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JST0071		STRUCTURAL STEEL						
	0380	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$50,000.00	\$50,000.00
	0390	FIELD APPLICATION OF ORGANIC ZINC PRIMER	Material			-1	\$5,000.00	(\$5,000.00)
	0390	FIELD APPLICATION OF ORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$5,000.00	\$5,000.00
	0400	MISC.	Material			-1	\$5,000.00	(\$5,000.00)
	0400	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	1	\$5,000.00	\$5,000.00
Total								\$12,000.00

Revision 3/23/2023 Page 3 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
JST0071		Bridge rehabilitations	I-64, I-55, I-70	ST LOUIS	Bridge A15011/A1502 over Daniel Boone Expressway, Bridge A1700 about 3.6 miles southeast of Route 84 over the Mississippi River, bridge A3292 from about 1.4 miles southeast of Route 94 over the Missouri River

JST0071 Posted Item Pay \$288,362.00 \$1,043,032.00 \$1,331,394.00 \$12,000.00 \$12,000.00 \$0.00 \$1,331,394.00 \$1,000.00	otals by Job Numbe	ls hy loh Numhars								
Posted Item Pay \$288,362.00 \$1,043,032.00 \$1,331,394.00 Gross Item Adjustments \$12,000.00 (\$12,000.00) \$0.00 Gross Item Pay \$300,362.00 \$1,031,032.00 \$1,331,394.00 Incentive \$0.00 \$0.00 \$0.00	otalo by cob Hullibe	010								
Gross Item Adjustments \$12,000.00 (\$12,000.00) \$0.00 Gross Item Pay \$300,362.00 \$1,031,032.00 \$1,331,394.00 Incentive \$0.00 \$0.00 \$0.00	JST0071		This Estimate	Previous	To Date					
Incentive \$0.00 \$0.00 \$0.00										
		Gross Item Pay	\$300,362.00	\$1,031,032.00	\$1,331,394.00					
	Incent	ntive	\$0.00	\$0.00	\$0.00					
Disincentive \$0.00 \$0.00 \$0.00	Disino	centive	\$0.00	\$0.00	\$0.00					
Liquidated Damages \$0.00 (\$1,500.00) (\$1,500.00)	Liquid	dated Damages	\$0.00	(\$1,500.00)	(\$1,500.00)					
Other Contract Adjustments \$11,300.00 (\$9,800.00) \$1,500.00	Other	r Contract Adjustments	\$11,300.00	(\$9,800.00)	\$1,500.00					

Revision 3/23/2023 Page 4 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7034204, Project Item Line Number 0210, Material Set 703420496, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7034204, Project Item Line Number 0210, Material Set 703420496, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7034204, Project Item Line Number 0210, Material Set 703420496, Material 1036RSEMBS - Mechanical Bar Splice for Reinf Steel Epoxy @, Acceptance Action Generic ReinforcingMisc is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7125100, Project Item Line Number 0240, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7125100, Project Item Line Number 0320, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7125100, Project Item Line Number 0380, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7125109, Project Item Line Number 0250, Material Set 7125109, Material 1045PTOZ - High Solids Organic Zinc Paint, Acceptance Action Generic 1045PTOZ is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7125109, Project Item Line Number 0330, Material Set 7125109, Material 1045PTOZ - High Solids Organic Zinc Paint, Acceptance Action Generic 1045PTOZ is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7125109, Project Item Line Number 0390, Material Set 7125109, Material 1045PTOZ - High Solids Organic Zinc Paint, Acceptance Action Generic 1045PTOZ is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7129901, Project Item Line Number 0340, Material Set 7129901, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	materials issue to be resolved	collie1	Overridden
Estimate Exception Type: Insufficient Materials: Project JST0071, Item 7129901, Project Item Line Number 0400, Material Set 7129901, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	materials issue to be resolved	collie1	Overridden

Revision 3/23/2023 Page 5 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Value	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at th	e time the	Estimate wa	as Gene	rated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241018-S01	JST0071	0001	0010	6122040	WORK ZONE CRASH CUSHION (NARROW)	1.00	0.00	1.00	EA	1.00	\$6,250.00	\$6,250.00
		0001	0020	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	1.00	\$21,000.00	\$21,000.00
		0001	0030	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	4.00	8.00	EA	8.00	\$3,000.00	\$24,000.00
		0001	0040	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL FOR BRIDGE A1501	1.00	0.00	1.00	LS	0.50	\$50,700.00	\$25,350.00
		0001	0050	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL FOR BRIDGE A1700	1.00	0.00	1.00	LS	0.75	\$87,200.00	\$65,400.00
		0001	0060	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL FOR BRIDGE A3292	1.00	0.00	1.00	LS	0.50	\$52,900.00	\$26,450.00
		0001	0070	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	230.00	0.00	230.00	LF	230.00	\$54.40	\$12,512.00
		0001	0080	6189901	MISC.MOBILIZATION FOR BRIDGE A3292	1.00	0.00	1.00	LS	0.25	\$94,000.00	\$23,500.00
		0001	0090	6189901	MISC.MOBILIZATION FOR BRIDGE NO A1700	1.00	0.00	1.00	LS	1.00	\$215,000.00	\$215,000.00
		0001	0100	6189901	MISC.MOBILIZATION FOR BRIDGE NO. A1501	1.00	0.00	1.00	LS	1.00	\$66,900.00	\$66,900.00
		0001	0110	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,905.00	-1,905.00	0.00	LF	0.00	\$2.25	\$0.00
		0001	0120	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	1,275.00	-1,275.00	0.00	LF	0.00	\$2.25	\$0.00
		0001	0130	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,275.00	-1,275.00	0.00	LF	0.00	\$3.00	\$0.00
		0001	0140	6207001	PAVEMENT MARKING REMOVAL	5,093.00	-5,093.00	0.00	LF	0.00	\$1.70	\$0.00
		0070	0150	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$40,000.00	\$0.00
		0070	0160	7125109	FIELD APPLICATION OF ORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0070	0170	7125115	FINISHED FIELD COAT (SYSTEM I)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0070	0180	7129903	MISC.WELD INSPECTION FOR BRIDGE NO. A3292	6.00	0.00	6.00	LF	6.00	\$500.00	\$3,000.00
		0070	0190	7129903	MISC.WELD REPAIR	2.00	0.00	2.00	LF	0.00	\$40,200.00	\$0.00
		0071	0200	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	49.00	0.00	49.00	SQFT	49.00	\$228.00	\$11,172.00
		0071	0210	7034204	CLASS B-2 CONCRETE (SUPERSTRUCTURE ON STEEL)	1.40	0.00	1.40	CUYD	1.40	\$28,600.00	\$40,040.00
		0071	0220	7061070	MECHANICAL BAR SPLICE	78.00	0.00	78.00	EA	78.00	\$100.00	\$7,800.00
		0071	0230	7101000	REINFORCING STEEL (EPOXY COATED)	420.00	0.00	420.00	LB	420.00	\$3.00	\$1,260.00
		0071	0240	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.60	\$55,000.00	\$33,000.00
		0071	0250	7125109	FIELD APPLICATION OF ORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.50	\$5,000.00	\$2,500.00
		0071	0260	7129901	MISC.FINISH FIELD COAT FOR BRIDGE NO. A1700	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0071	0270	7129902	MISC.STRUCTURAL STEEL - BOLTED SPLICE REPAIR LOCATION NO. 1	1.00	0.00	1.00	EA	1.00	\$94,800.00	\$94,800.00
		0071	0280	7129902	MISC.STRUCTURAL STEEL - BOLTED SPLICE REPAIR LOCATION NO. 2	1.00	0.00	1.00	EA	1.00	\$94,800.00	\$94,800.00
		0071	0290	7129903	MISC.DEFECT REMOVAL FOR BRIDGE NO. A1700	2.00	0.00	2.00	LF	1.50	\$26,600.00	\$39,900.00
		0071	0300	7129903	MISC.WELD INSPECTION FOR BRIDGE NO. A1700	10.00	0.00	10.00	LF	5.00	\$400.00	\$2,000.00
		0071	0310	7129903	MISC.WELD REPAIR FOR BRIDGE NO. A1700	3.00	0.00	3.00	LF	1.50	\$11,900.00	\$17,850.00
		0072	0320	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	1.00	\$45,000.00	\$45,000.00
		0072	0330	7125109	FIELD APPLICATION OF ORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0072	0340	7129901	MISC.FINISH FIELD COAT FOR BRIDGE NO. A15019	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0072	0350	7129902	MISC.DEFECT REMOVAL FOR BRIDGE NO. A15019	2.00	0.00	2.00	EA	2.00	\$20,300.00	\$40,600.00
		0072	0360	7129902	MISC.LONGITUDINAL STIFFENER RETROFIT	6.00	0.00	6.00	EA	6.00	\$15.500.00	\$93,000.00
		0072	0370	7129902	MISC.WELD INSPECTION FOR BRIDGE NO. A15019	6.00	0.00	6.00	EA	6.00	\$500.00	\$3,000.00
		0072	0380	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	1.00	\$50,000.00	\$50,000.00
		0073	0390	7125109	FIELD APPLICATION OF ORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0073	0400	7129901	MISC.FINISH FIELD COAT FOR BRIDGE NO. A15020	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0073	0410	7129902	MISC.DEFECT REMOVAL FOR BRIDGE NO. A15020	3.00	0.00	3.00	EA	3.00	\$17,100.00	\$51,300.00
		0073	0420	7129902	MISC.LONGITUDINAL STIFFENER RETROFIT	12.00	0.00	12.00	EA	12.00	\$13,100.00	\$157,200.00

Revision 3/23/2023 Page 6 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241018-S01	JST0071	0073	0440	7129902	MISC.WELD INSPECTION FOR BRIDGE NO. A15020	15.00	0.00	15.00	EA	15.00	\$500.00	\$7,500.00
Project JST0071 - Total Value Posted to Date as of Report Generated Date											\$1,331,394.00	
241018-S01 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$1,331,394.00

Revision 3/23/2023 Page 7 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JST0071

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0090	6189901	MISC.	4/15/25	4/17/25	0.50	LS		0		0		
0200	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	4/15/25	4/17/25	4.00	SQFT		0		0		
0210	7034204	CLASS B-2 CONCRETE (SUPSTR ON	4/15/25	4/17/25	1.40	CUYD		0		0		
0220	7061070	MECHANICAL BAR SPLICE	4/15/25	4/17/25	78.00	EA		0		0		
0230	7101000	REINFORCING STEEL (EPOXY COATED)	4/15/25	4/17/25	420.00	LB		0		0		
0270	7129902	MISC.	4/15/25	4/17/25	0.75	EA	per Lynn	0		0		
0290	7129903	MISC. STRUCTURAL STEEL CONSTRUCTION	4/15/25	4/17/25	1.50	LF		0		0		
0300	7129903	MISC. STRUCTURAL STEEL CONSTRUCTION	4/15/25	4/17/25	5.00	LF		0		0		
0310	7129903	MISC. STRUCTURAL STEEL CONSTRUCTION	4/15/25	4/17/25	1.50	LF		0		0		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 8 of 12



Line Item Adjustments by Estimate

Contract ID: 241018-S01

JETION Line Description Majorithms										
379071 0030 CAS WON Notice	Project	Line	Description	Adjustment Type	Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
CONTENT	JST0071	0030	COMMUNICATION	Material	Турс	1		SYSTEM	\$24,000.00	Estimate Item Adjustment (0002) due to user collie1 overridding Payment
Total						1		SYSTEM	(\$24,000.00)	Estimate Exception 1 on the current Payment Estimate.
Material - Total					Total		2020		\$0.00	
Oversign										
						4	F-1- 40	OVOTEM		
Part				Overrun	Overrun		2025			Usit wise board on account of the board of t
1						5		STSTEW	φ12,000.00	previous payment estimates. Price Adjustments of ',3000.00000 - 3000.00000,
					Overrun - T	- Total			\$0.00	
Misc. Material				Overrun - T	otal				\$0.00	
2025 Estimate Item Adjustment (0003) due to user collect overridding Payment Estimate.		0030 -	- Total						\$0.00	
1-Total 1-To		0050	MISC.	Material		1		SYSTEM	\$43,600.00	Estimate Item Adjustment (0003) due to user collie1 overridding Payment
Material - Total						1		SYSTEM	(\$43,600.00)	
					- Total				\$0.00	
CLASS B-2 CONCRETE SUPSTRO Material				Material - T	otal				\$0.00	
CONCRETE (SUPSTRON 2025 5		0050 -	- Total						\$0.00	
2025 SO		0210	CONCRETE	Material		5		SYSTEM	\$40,040.00	Estimate Item Adjustment (0002) due to user collie1 overridding Payment
						5		SYSTEM	(\$40,040.00)	
Material Apr 2, SySTEM S3,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate Estimate Estimate Exception 7 on the current Payment Estimate Estimate Exception 7 on the current Payment Estimate Estimate Exception 7 on the current Payment Estimate Estimate Estimate Exception 9 on the current Payment Estimate Estimat					- Total				\$0.00	
SURFACE PREPARATION FOR RECOATING PREPARATION POR RECOATING Por RE									Ψ0.00	
PREPARATION FOR RECOATING STRUC				Material - T	otal					
4		0210 -	- Total	Material - T	otal				\$0.00	
Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. Summarie Sum			SURFACE PREPARATION FOR RECOATING		otal	4		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment
Comparison of			SURFACE PREPARATION FOR RECOATING		otal		2025 Apr 2,		\$0.00 \$0.00 \$33,000.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment
Material - Total S0.00			SURFACE PREPARATION FOR RECOATING		otal	4	2025 Apr 2, 2025 Apr 17,	SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00)	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment
O250 FIELD Material 4 Apr 2, SYSTEM \$2,500.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 4 Apr 2, SYSTEM \$2,500.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 5 Apr 17, SYSTEM \$0.00			SURFACE PREPARATION FOR RECOATING		otal	5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17,	SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment
Description Pield Application of Organic Zinc Page			SURFACE PREPARATION FOR RECOATING			5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17,	SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
APPLICATION OF ORGANIC ZINC Apr 2, 2025 SYSTEM (\$2,500.00)			SURFACE PREPARATION FOR RECOATING	Material	- Total	5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17,	SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00)	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
2025 Apr 17, 2025 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Total So.00 Material - Total Surface PREPARATION FOR RECOATING STRUC Support System System Support System Sys		0240	SURFACE PREPARATION FOR RECOATING STRUC	Material	- Total	5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17,	SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00) \$0.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
2025 Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 5 Apr 17, 2025 SYSTEM (\$2,500.00) - Total \$0.00 Material - Total \$0.00 0250 - Total \$0.00 0250 - Total \$0.00 0250 - Total \$0.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		0240	SURFACE PREPARATION FOR RECOATING STRUC - Total FIELD APPLICATION OF	Material Material - T	- Total	5 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment
2025 - Total S0.00 Material - Total \$0.00 0250 - Total SURFACE PREPARATION FOR RECOATING STRUC STRUC SURFACE PREPARATION FOR RECOATING STRUC		0240	SURFACE PREPARATION FOR RECOATING STRUC - Total FIELD APPLICATION OF	Material Material - T	- Total	5 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 2, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00) \$0.00 \$0.00 \$2,500.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment
Material - Total \$0.00		0240	SURFACE PREPARATION FOR RECOATING STRUC - Total FIELD APPLICATION OF	Material Material - T	- Total	5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00) \$0.00 \$0.00 \$2,500.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment
0320 SURFACE PREPARATION FOR RECOATING STRUC \$0.00 SURFACE PREPARATION FOR RECOATING STRUC \$0.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		0240	SURFACE PREPARATION FOR RECOATING STRUC - Total FIELD APPLICATION OF	Material Material - T	- Total	4 5 5 4 4 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00) \$0.00 \$0.00 \$2,500.00 (\$2,500.00)	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment
O320 SURFACE PREPARATION FOR RECOATING STRUC SURFACE PREPARATION FOR RECOATING STRUC Apr 2, SYSTEM \$45,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		0240	SURFACE PREPARATION FOR RECOATING STRUC - Total FIELD APPLICATION OF	Material Material - T	- Total otal	4 5 5 4 4 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$33,000.00) (\$33,000.00) \$33,000.00) \$0.00 \$0.00 \$2,500.00) (\$2,500.00) (\$2,500.00)	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment
PREPARATION FOR RECOATING STRUC PREPARATION STRUC STRUC Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		0240	SURFACE PREPARATION FOR RECOATING STRUC - Total FIELD APPLICATION OF	Material - T	- Total otal - Total	4 5 5 4 4 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00) \$0.00 \$0.00 \$2,500.00 (\$2,500.00) \$2,500.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment
STRUC		0240 0240 0250	SURFACE PREPARATION FOR RECOATING STRUC - Total FIELD APPLICATION OF ORGANIC ZINC	Material - T	- Total otal - Total	4 5 5 4 4 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00) \$0.00 \$0.00 \$2,500.00 (\$2,500.00) \$2,500.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment
		0240 - 0250 -	SURFACE PREPARATION FOR RECOATING STRUC - Total - Total - Total - Total SURFACE PREPARATION	Material - T Material - T	- Total otal - Total	4 5 5 4 4 5 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$33,000.00 (\$33,000.00) \$33,000.00 (\$33,000.00) \$0.00 \$0.00 \$2,500.00 (\$2,500.00) \$2,500.00 \$0.00 \$0.00	Estimate Item Adjustment (0001) due to user collie1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user collie1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.



Line Item Adjustments by Estimate

Contract ID: 241018-S01

	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
71 0320		Material			2025			
	PREPARATION FOR RECOATING STRUC			5	Apr 17, 2025	SYSTEM	\$45,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Apr 17, 2025	SYSTEM	(\$45,000.00)	
			- Total			\$0.00		
		Material - To	otal				\$0.00	
032) - Total						\$0.00	
0330	APPLICATION OF ORGANIC ZINC	Material		4	Apr 2, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user collie1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	Apr 2, 2025	SYSTEM	(\$5,000.00)	
				5	Apr 17, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	Apr 17, 2025	SYSTEM	(\$5,000.00)	
			- Total				\$0.00	
		Material - Total					\$0.00	
033) - Total						\$0.00	
0340	MISC. STRUCTURAL STEEL CONSTRUCTION	Material		4	Apr 2, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user collie1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	CONSTRUCTION			4	Apr 2, 2025	SYSTEM	(\$5,000.00)	
				5	Apr 17, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				5	Apr 17, 2025	SYSTEM	(\$5,000.00)	
			- Total				\$0.00	
		Material - To	otal				\$0.00	
034) - Total		al - Total					
	SURFACE PREPARATION						\$0.00	
0380	PREPARATION FOR RECOATING	Material		4	Apr 2, 2025	SYSTEM	\$0.00 \$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
038	PREPARATION	Material		4		SYSTEM SYSTEM		Estimate Item Adjustment (0006) due to user collie1 overridding Payment
038	PREPARATION FOR RECOATING	Material			2025 Apr 2,		\$50,000.00	Estimate Item Adjustment (0006) due to user collie1 overridding Payment
038	PREPARATION FOR RECOATING	Material		4	2025 Apr 2, 2025 Apr 17,	SYSTEM	\$50,000.00 (\$50,000.00)	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment
038	PREPARATION FOR RECOATING	Material	- Total	5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17,	SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment
038	PREPARATION FOR RECOATING	Material - To		5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17,	SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00 (\$50,000.00)	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment
	PREPARATION FOR RECOATING			5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17,	SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00 (\$50,000.00)	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment
	PREPARATION FOR RECOATING STRUC			5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17,	SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00 (\$50,000.00) \$0.00	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment
0380	PREPARATION FOR RECOATING STRUC D - Total APPLICATION OF	Material - To		5 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00 (\$50,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment
0380	PREPARATION FOR RECOATING STRUC D - Total APPLICATION OF	Material - To		5 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 2, 2025	SYSTEM SYSTEM SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00 (\$50,000.00) \$0.00 \$0.00 \$5,000.00	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment
0380	PREPARATION FOR RECOATING STRUC D - Total APPLICATION OF	Material - To		5 4 4	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00 (\$50,000.00) \$0.00 \$0.00 \$5,000.00 (\$5,000.00)	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment
0380	PREPARATION FOR RECOATING STRUC D - Total APPLICATION OF	Material - To		4 4 4 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00) (\$50,000.00) \$0.00 \$0.00 \$5,000.00 (\$5,000.00)	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment
0380	PREPARATION FOR RECOATING STRUC D - Total APPLICATION OF	Material - To	otal - Total	4 4 4 5	2025 Apr 2, 2025 Apr 17, 2025 Apr 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$50,000.00 (\$50,000.00) \$50,000.00) (\$50,000.00) \$0.00 \$0.00 \$5,000.00 (\$5,000.00) (\$5,000.00)	Estimate Item Adjustment (0006) due to user collie1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user collie1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment Estimate Item Adjustment (0009) due to user collie1 overridding Payment





Line Item Adjustments by Estimate

Contract ID: 241018-S01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JST0071	0400	MISC. STRUCTURAL STEEL	Material		4	Apr 2, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user collie1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	CONSTRUCTION	CONSTRUCTION			4	Apr 2, 2025	SYSTEM	(\$5,000.00)	
				5	Apr 17, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user collie1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					5	Apr 17, 2025	SYSTEM	(\$5,000.00)	
				- Total				\$0.00	
	Material - Total							\$0.00	
	0400 - Total								
JST0071	- Total							\$0.00	
Overall -	Total							\$0.00	



Contract Adjustments for Contract - 241018-S01

Estimate Number	Project	Adjustment Type	Other Adjustment Type	Adjustment Amount	Adjustment Percentage by Project	Created Date	Created By	Comments
4	JST0071	Liquidated Damage		(\$1,500.00)	100	Apr 2, 2025	collie1	Liquidated Damages assessed Estimate Period: March 15 – April 1 Administrative Costs – 1 day = \$1500 (Days Include April 1)
		Other Contract Adjustment	RUC	(\$9,800.00)	100	Apr 2, 2025	collie1	Liquidated Damages assessed Estimate Period: March 15 – April 1 Road User Costs – 1 day = \$9800 (Days include April 1)
4 - Total					(\$11,300.00)			
5	JST0071	Other Contract Adjustment	RUC	\$9,800.00	100	Apr 17, 2025	collie1	LD's Road User Cost from April 1st
		Other Contract Adjustment		\$1,500.00	100	Apr 17, 2025	collie1	LD's Administration Cost from April 1st
5 - Total					\$11,300.00			
Overall - Total					\$0.00			

Revision 3/23/2023 Page 12 of 12