\$302,815.69



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 17, 2025

Progress Estimate Number 18	Contract ID Prime Contrac	241115 tor Millston	-F01 e Weber, LLC	Pay Period Sta Pay Period End			Original Contract Amount Net Change Order Amount Current Contract Amount	\$16,858,440.06 (\$458,531.87 \$16,399,908.19
Approval Date								By User
November 17, 2025			Generated a	nd Approved (and	should be cor	nsidered Dr	raft) at the Project Office Level by	sawyej2
November 17, 2025		F	Reviewed and A	pproved (and sho	uld be conside	red Draft) a	at the Resident Engineer Level by	amburs1
November 18, 2025				Reviewed and	Approved at the	ne Central	Office Controllers Office Level by	ramses1
Original Completion	on Date	Current Co	mpletion Date	Actual 0	ompletion Da	ite	% of Current Contract Amoun	nt Complete
May 1, 2026	3	May	1, 2026				89.83%	
	Contr	act Informati	ional Dates				Milestones	
Date Description	Original Com	pletion Date	Current Comp	oletion Date	N	o Milestone	es Exist for Contract	
Acceptance Date								
Awarded Date	December 4, 2	2024	December 4, 2	024				
Letting Date	November 15,	2024	November 15,	2024				
Notice to Proceed Date	January 6, 202	25	January 6, 202	25				
Work Began Date	March 3, 2025		March 3, 2025					

Contract Total Pa	y For Estimate No. 18			
		This Estimate	Previous	To Date
241115-F01				
	Total Posted Items Pay	\$302,815.69	\$14,429,693.85	\$14,732,509.54
	Gross Item Adjustments	\$0.00	\$211.43	\$211.43
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$14,429,905.28	\$14,732,720.97
Contract Total Pa	yable This Estimate:	\$302,815.69		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3538	0120	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$1,347.000	1	\$1,347.00
	0260	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	LF	\$208.500	470	\$97,995.00
	0300	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$7.650	300	\$2,295.00
	0370	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.900	33,000	\$29,700.00
	0400	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	LS	\$14,500.000	0.500	\$7,250.00
	0720	7040104	HALF-SOLE REPAIR	SQFT	\$139.500	25.625	\$3,574.69
	0730	7040163	CONCRETE CRACK FILLER	SQYD	\$21.400	7,110	\$152,154.00
	0870	7129901	MISC.CLEARANCE GAUGE	LS	\$34,000.000	0.250	\$8,500.00
Project J6I3538	- Total						\$302,815.69

Contract Adjustments This Estimate

Overall - Total

No Contract Adjustments Exist on Contract

Line Item	Adjust	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3538	0090	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-6,841	\$112.00	(\$766,192.00)
	0090	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	6,841	\$112.00	\$766,192.00

Revision 10/17/2025 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 17, 2025

Pro Estimat	gress te Num 18	Contract ID nber Prime Contractor	241115-F01 Millstone Weber		y Period Start November 2, 2025 y Period End November 15, 2025	Original Contract An Net Change Order A Current Contract An	mount	\$16,858,440.06 (\$458,531.87 \$16,399,908.19
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3538		FT. JOINTS)			Adjustment (0001) due to user saw overridding Payment Estimate Except the current Payment Estimate.			
	0260	CONCRETE TRAFFIC BARRIER, TYPE C	Material			-470	\$208.50	(\$97,995.00)
	0260	CONCRETE TRAFFIC BARRIER, TYPE C	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0002) due to user saw overridding Payment Estimate Except the current Payment Estimate.	até Item yej2	\$208.50	\$97,995.00
	0600	7 FT. CHANNEL POST DELINEATOR, WHITE	Material			-16	\$125.00	(\$2,000.00)
	0600	7 FT. CHANNEL POST DELINEATOR, WHITE	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0003) due to user saw overridding Payment Estimate Excoon the current Payment Estimate.	até Item yej2	\$125.00	\$2,000.00
	0750	MISC.	Material			-4	\$137.50	(\$550.00)
	0750	MISC.	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0004) due to user saw overridding Payment Estimate Except the current Payment Estimate.	até Item yej2	\$137.50	\$550.00
	0870	MISC.	Material			-1	\$34,000.00	(\$34,000.00)
	0870	MISC.	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0005) due to user saw overridding Payment Estimate Excoon the current Payment Estimate.	até Item yej2	\$34,000.00	\$34,000.00
Total								\$0.00

Revision 10/17/2025 Page 2 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Informa	ation
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6I3538	I 64-1(98)	Bridge rehabilitation and painting	I-64	ST LOUIS	for the Boone Bridge		
Totals I	by Job N	lumbers					
J6I3538		ed Item Pay s Item Adjustn		s Item Pa	This Estimate \$302,815.69 \$0.00 y \$302,815.69	Previous \$14,429,693.85 \$211.43 \$14,429,905.28	To Date \$14,732,509.54 \$211.43 \$14,732,720.97
	Liqui	ntive centive dated Damage r Contract Adji		s	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 5/29/2025 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3538, Item 5021309, Project Item Line Number 0090, Material Set 502130996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	MoDOT & GFT discussing testing frequency.	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3538, Item 5021309, Project Item Line Number 0090, Material Set 502130996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	MoDOT & GFT discussing testing frequency.	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3538, Item 6173000, Project Item Line Number 0260, Material Set 617300096, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Strength Tests & Sample Records to be completed by QA & QC.	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3538, Item 6173000, Project Item Line Number 0260, Material Set 617300096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Strength Tests & Sample Records to be completed by QA & QC.	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3538, Item 6173000, Project Item Line Number 0260, Material Set 617300096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Strength Tests & Sample Records to be completed by QA & QC.	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3538, Item 6173000, Project Item Line Number 0260, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Strength Tests & Sample Records to be completed by QA & QC.	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J613538, Item 7049904, Project Item Line Number 0750, Material Set 7049904, Material 0505CCLOSL - Bridge Deck Concrete, Low Slump, Acceptance Action Generic 0505CCLOSL is insufficient.	GFT to complete Sample Record	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J613538, Item 7049904, Project Item Line Number 0750, Material Set 7049904, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	GFT to complete Sample Record	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J613538, Item 7049904, Project Item Line Number 0750, Material Set 7049904, Material 0505CCSF - Bridge Deck Concrete, Silica Fume, Acceptance Action Generic 0505CCSF is insufficient.	GFT to complete Sample Record	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3538, Item 7129901, Project Item Line Number 0870, Material Set 7129901, Material 1045PTEP - High Solids Epoxy System G Intrmdte Coat, Acceptance Action Generic 1045PTEP is insufficient.	GFT to complete Sample Record	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3538, Item 9031256, Project Item Line Number 0600, Material Set 903125696, Material 0903HSPSUC - U-Channel Post for Highway Signing, Acceptance Action Generic 0903HSPSUC is insufficient.	GFT to complete Sample Record	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J613538, Item 9031256, Project Item Line Number 0600, Material Set 903125696, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	GFT to complete Sample Record	sawyej2	Overridden
Estimate Exception Type: Insufficient Materials: Project J613538, Item 9031256, Project Item Line Number 0600, Material Set 903125696, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	GFT to complete Sample Record	sawyej2	Overridden

Revision 5/29/2025 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	noject No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
15- J6I	13538	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$423,000.00	\$317,250.
		0001	0020	2031000	CLASS A EXCAVATION	2,961.00	0.00	2,961.00	CUYD	855.00	\$20.00	\$17,100.
		0001	0030	2035500	EMBANKMENT IN PLACE	1,422.00	0.00	1,422.00	CUYD	1,422.00	\$20.00	\$28,440.
		0001	0040	2036000	COMPACTING EMBANKMENT	1,539.00	0.00	1,539.00	CUYD	684.00	\$20.00	\$13,680.
		0001	0050	2037075	COMPACTING IN CUT	49.00	0.00	49.00	STA	49.00	\$650.00	\$31,850.
		0001	0060	2063500	CULVERT CLEANOUT	24.00	0.00	24.00	EA	5.00	\$4,233.00	\$21,165.
		0001	0070	2072000	LINEAR GRADING CLASS 2	49.00	0.00	49.00	STA	49.00	\$1,788.00	\$87,612
		0001	0800	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	13,257.00	-2,416.00	10,841.00	SQYD	10,841.00	\$18.30	\$198,390
		0001	0090	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	13,257.00	-2,416.00	10,841.00	SQYD	10,841.00	\$112.00	\$1,214,192
		0001	0100	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	7.00	0.00	7.00	EA	6.00	\$4,472.00	\$26,832
		0001	0110	6122020 6122030	REPLACEMENT SAND BARREL IMPACT ATTENUATOR (RELOCATION)	9.00	0.00	9.00	EA EA	2.00	\$1,552.00 \$1,347.00	\$2,694
		0001	0130	6122040	WORK ZONE CRASH CUSHION (NARROW)	6.00	0.00	6.00	EA	6.00	\$1,347.00	\$67,824
		0001	0140	6122041	WORK ZONE CRASH CUSHION (NARROW) (RELOCATION)	2.00	-2.00	0.00	EA	0.00	\$3,804.00	\$07,02
		0001	0150	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	1.00	\$3,500.00	\$3,500
		0001	0160	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR	139.00	-139.00	0.00	CUYD	0.00	\$1,401.00	\$(
		0001	0170	6132019	CLASS A PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	1,253.00	-1,253.00	0.00	SQYD	0.00	\$126.00	\$(
		0001	0180	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	468.00	0.00	468.00	TONS	433.70	\$96.00	\$41,63
		0001	0190	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	2,108.00	90.00	2,198.00	SQYD	2,198.00	\$33.00	\$72,53
		0001	0200	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	10.00	0.00	10.00	EA	0.00	\$1,085.00	\$
		0001	0210	6149902	MISC.INLET TOP REPLACEMENT	2.00	0.00	2.00	EA	0.00	\$8,906.00	\$
		0001	0220	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	4.00	0.00	4.00	EA	4.00	\$2,500.00	\$10,00
		0001	0230	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	20.00	-10.00	10.00	EA	10.00	\$1,000.00	\$10,00
		0001	0240	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$360,000.00	\$342,00
		0001	0250	6169902	MISC.ADA COMPLIANT TYPE III MOVABLE BARRICADE	8.00	0.00	8.00	EA	8.00	\$250.00	\$2,00
		0001	0260	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	800.00	0.00	800.00	LF	770.00	\$208.50	\$160,54
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	18,838.00	-1,682.00	17,156.00	LF	17,156.00	\$49.25	\$844,93
		0001	0280	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	125.00	50.00	175.00	LF	175.00	\$116.00	\$20,30
		0001	0290	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	425.00	-212.50	212.50	LF	212.50	\$122.00	\$25,92
		0001	0300	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	7,575.00	0.00	7,575.00	LF	3,650.00	\$7.65	\$27,92
		0001	0310	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$887,556.00	\$887,55
		0001	0320	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$
		0001	0330	6191000 6205902A	PAVEMENT EDGE TREATMENT 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	4,993.00 47,723.00	0.00	4,993.00 47,723.00	LF LF	0.00	\$2.05 \$0.28	\$
		0001	0350	6205903A	PAINT, TYPE L BEADS 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	29,294.00	0.00	29,294.00	LF	0.00	\$0.28	\$
		0001	0360	6205906A	MARKING PAINT, TYPE L BEADS 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	2,792.00	0.00	2,792.00	LF	0.00	\$1.00	\$
		0001			MARKING PAINT, TYPE L BEADS							
		0001	0370	6207001	PAVEMENT MARKING REMOVAL	203,496.00	0.00	203,496.00	LF	61,227.00	\$0.90	\$55,10
		0001	0380		TEMPORARY RAISED PAVEMENT MARKER	775.00	0.00	775.00	EA	220.00	\$10.00	\$2,20
		0001	0390	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	242,411.00	0.00	242,411.00	LF	136,073.00	\$0.70	\$95,25
		0001	0400	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.50	\$14,500.00	\$7,25
		0001	0410	6209902	MISC.INLAID PAVEMENT MARKER INSTALLATION BITUMINOUS SHOULDER RUMBLE STRIP	127.00 95.90	0.00	127.00 95.90	EA STA	0.00	\$85.00 \$129.00	\$
		0001	0430	6262000A	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	56.40	27.20	83.60	STA	0.00	\$129.00	\$
		0001	0440	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$71,200.00	\$71,20
		0001	0450	7309901	MISC.WELD DRAINAGE GRATES	1.00	0.00	1.00	LS	1.00	\$7,313.00	\$71,20
		0001	0460	8025006	MULCHING	10.00	0.00	10.00	ACRE	2.40	\$1,500.00	\$3,60
		0001	0470	8051000A	SEEDING - COOL SEASON GRASSES	5.00	0.00	5.00	ACRE	0.00	\$4,500.00	\$3,00
		0001	0480	8061003	SEDIMENT TRAP EXCAVATION	10.00	0.00	10.00	CUYD	10.00	\$55.00	\$55
		0001	0490	8061003	SEDIMENT TRAP EXCAVATION SEDIMENT TRAP ROCK	14.00	0.00	14.00	CUYD	14.00	\$90.00	\$1,26
		0001	0500	8061006	ALTERNATE DITCH CHECK	912.00	-722.00	190.00	LF	190.00	\$10.00	\$1,90
		0001	0510	8061016	SEDIMENT REMOVAL	118.00	0.00	118.00	CUYD	14.00	\$100.00	\$1,40
		0001	0520	8061017	TEMPORARY SEEDING	5.00	0.00	5.00	ACRE	2.40	\$700.00	\$1,68
						0.00	0.00	0.00		2.70	ψ. 50.00	ψ1,00

Revision 5/29/2025 Page 5 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POST To Date (See rep generated date
5- J6	613538	0010	0540	6061060	MGS GUARDRAIL	300.00	0.00	300.00	LF	0.00	\$28.00	\$
		0010	0550	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$2,400.00	\$
		0010	0560	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	0.00	\$3,800.00	\$
		0040	0570	9031010	CONCRETE FOOTINGS, EMBEDDED	1.50	0.00	1.50	CUYD	0.00	\$3,200.00	\$
		0040	0580	9031210	STRUCTURAL STEEL POSTS	520.00	0.00	520.00	LB	0.00	\$8.00	\$
		0040	0590	9031220	PIPE POSTS	550.00	0.00	550.00	LB	0.00	\$8.50	\$
		0040	0600	9031256	7 FT. CHANNEL POST DELINEATOR, WHITE	10.00	16.00	26.00	EA	16.00	\$125.00	\$2,00
		0040	0610	9031257A	7 FT. CHANNEL POST DELINEATOR, YELLOW	1.00	0.00	1.00	EA	0.00	\$125.00	
		0040	0620	9031270A	2 IN. PSST POST - 12 GA.	56.00	0.00	56.00	LF	0.00	\$34.00	
		0040	0630	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	4.00	0.00	4.00	EA	0.00	\$250.00	
		0040	0640	9035004A	SH-FLAT SHEET	50.00	0.00	50.00	SQFT	0.00	\$40.00	
		0040	0650	9039902	MISC.REMOVE AND RELOCATE EXISTING SIGN(S) TO NEW POST	6.00	0.00	6.00	EA	6.00	\$1,200.00	\$7,2
		0050	0660	9109902	MISC.CLASS 2 PULLBOX, WITH CONCRETE APRON	1.00	0.00	1.00	EA	0.00	\$6,875.00	
		0050	0670	9109902	MISC.CLASS 5 PULLBOX, WITH CONCRETE APRON	1.00	0.00	1.00	EA	0.00	\$6,875.00	
		0050	0680	9109902	MISC.CONDUIT AND CABLE ADJUSTMENTS AT PULLBOXES	4.00	0.00	4.00	EA	0.00	\$250.00	
		0050	0690	9109902	MISC.PULL BOX ADJUSTMENT	2.00	0.00	2.00	EA	0.00	\$880.00	
		0050	0700	9109903	MISC.CONDUIT REPAIR	100.00	0.00	100.00	LF	0.00	\$40.00	
		0070	0710	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	768.00	0.00	768.00	LF	768.00	\$73.25	\$56,2
		0070	0720	7040104	HALF-SOLE REPAIR	3,800.00	0.00	3,800.00	SQFT	129.00	\$139.50	\$17,9
		0070	0730	7040163	CONCRETE CRACK FILLER	14,220.00	0.00	14,220.00	SQYD	14,220.00	\$21.40	\$304,3
		0070	0740	7049902	MISC.FATIGUE CRACK REPAIRS	10.00	3.00	13.00	EA	13.00	\$3,300.00	\$42,9
		0070	0750	7049904	MISC.CONCRETE WEARING SURFACE REPAIR	2,509.00	0.00	2,509.00	SQFT	4.00	\$137.50	\$
		0070	0760	7110100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (URETHANE)	1.00	-1.00	0.00	LS	0.00	\$131,350.00	
		0070	0770	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	1.00	\$3,990,500.00	\$3,990,
		0070	0780	7125101	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM $\ensuremath{G})$	1.00	0.00	1.00	LS	1.00	\$1,273,000.00	\$1,273,0
		0070	0790	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	-1.00	0.00	LS	0.00	\$126,000.00	
		0070	0800	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$1,580,000.00	\$1,580,0
		0070	0810	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	1.00	\$1,580,000.00	\$1,580,0
		0070	0820	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	2,700.00	0.00	2,700.00	SQFT	2,700.00	\$78.00	\$210,
		0070	0830	7125201	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	70,200.00	0.00	70,200.00	SQFT	70,200.00	\$1.75	\$122,
		0070	0840	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	2,700.00	-2,700.00	0.00	SQFT	0.00	\$2.00	
		0070	0850	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	72,900.00	0.00	72,900.00	SQFT	72,900.00	\$2.00	\$145,8
		0070	0860	7125370A	FINISH FIELD COAT (SYSTEM G)	11,000.00	0.00	11,000.00	SQFT	11,000.00	\$2.00	\$22,0
		0070	0870	7129901	MISC.CLEARANCE GAUGE	1.00	0.00	1.00	LS	1.00	\$34,000.00	\$34,0
		0070	0880	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	768.00	0.00	768.00	LF	768.00	\$124.00	\$95,2
		0001	5001	6139911	MISC.MISC. PARTIAL DEPTH REPAIR CONCRETE PAVEMENT REPAIR USING FLEXIBLE, HOT POLYMER	0.00	22,206.00	22,206.00	LB	22,206.00	\$3.35	\$74,3
		0001	5002	1046002	VALUE ENGINEERING	0.00	185,456.68	185,456.68	EA	185,456.68	\$1.00	\$185,4
		0070	5003	7125109	FIELD APPLICATION OF ORGANIC ZINC PRIMER	0.00	1.00	1.00	LS	1.00	\$126,000.00	\$126,0
		0070	5004	7125209	FIELD APPLICATION OF ORGANIC ZINC PRIMER	0.00	2,700.00	2,700.00	SQFT	2,700.00	\$2.00	\$5,4
		0070	5005	7129901	MISC.FIELD WELDING	0.00	1.00	1.00	LS	1.00	\$2,597.11	\$2,5
		0070	5006	1094000	FORCE ACCOUNT	0.00	16,049.23	16,049.23	EA	16,049.23	\$1.00	\$16,0
		0001	5008	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	0.00	58.00	58.00	CUYD	58.00	\$85.00	\$4,9
		0001	5009	6096041	PLACING TYPE 1 ROCK DITCH LINER	0.00	58.00	58.00	CUYD	58.00	\$155.00	\$8,9
		0070	5011	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	0.00	1.00	1.00	LS	1.00	\$131,350.00	\$131,
		0070	5012	7049902	MISC.DRAINAGE INLET REPAIR	0.00	5,283.61	5,283.61	EA	5,283.61	\$1.00	\$5,2
		0070	5013	7049902	MISC.GRATE AND FRAME REMOVAL, DROP INLET BACKFILL	0.00	10,447.90	10,447.90	EA	10,447.90	\$1.00	\$10,4

Revision 5/29/2025 Page 6 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6l3538

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0120	6122030	IMPACT ATTENUATOR (RELOCATION)	11/10/25	11/17/25	1	1.00	EA	1-64					Payment being made of the impact attenuator relocation of sand barrel array. This array was located @ the beginning of l-64 WB TTB, that was going across the bridge. It was relocated to the beginning of the I-64 EB TTB, after the TTB was shifted from its stiffness transition
)260	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	11/15/25	11/17/25	1	470.00	LF	I-64 East Crossover	103+30		108+00		Payment being made for 470 LF of barrier wall that was placed using slip form. Remaining 30 LF will be formed/poured @ later date.
0300	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	11/10/25	11/17/25	1	220.00	LF	I-64 EB	635+80		638+00		Payment being made for TTB that was shifted at the location listed. This shift was necessary for access to the bypass, and to begin work on replacing the permanent barrier wall.
				11/17/25	2	80.00	LF	I-64 EB	107+20		108+00		Payment being made for TTB that was shifted at the location listed. This shift was necessary for slip forming the permanent barrier.
370	6207001	PAVEMENT MARKING REMOVAL	11/3/25	11/11/25	1	8,000.00	LF	I-64 WB					Payment being made for removals of Stage 1 and 2 striping, in preparation for crack sealing of the bridge dec
			11/4/25	11/14/25	1	2,000.00	LF	I-64 WB					Payment being made for removals of Stage 1 and 2 striping, in preparation for crack sealing of the bridge dec
			11/12/25	11/17/25	1	23,000.00	LF	L-64 WB					Payment being made for the remainder of removals completed for WB, so that temp striping could be applied back into normal configuation.
1400	6209901	MISC. PAVEMENT MARKINGS	11/8/25	11/17/25	1	0.50	LS	I-64 WB					Payment of 50% is being made for the completion of temporary striping I-64 WB. Remaining 50% will be paid once I-64 EB has been striped back into normal configuration.
720	7040104	HALF-SOLE REPAIR	11/4/25	11/14/25	1	2.25	SQFT	Span 6 L12					Payment being made for 3'x0.75' half-sole repair @ location listed.
				11/14/25	2	1.88	SQFT	Bent 5					Payment being made for 2.5'x0.75' half-sole repair @ location listed.
				11/14/25	3	2.00	SQFT	Bent 5					Payment being made for 1'x2' half-sole repair @ location listed.
				11/14/25	4	0.75	SQFT	Span 4 L8'					Payment being made for 0.75'x1' half-sole repair @ location listed.
				11/14/25	5	1.75	SQFT	Span 4 L8'					Payment being made for 1'x1.75' half-sole repair @ location listed.
				11/14/25	6	3.75	SQFT	Span 4 L8'					Payment being made for 1'x3.75' half-sole repair @ location listed.
				11/14/25	7	1.50	SQFT	Span 4 L8'					Payment being made for 1'x1.5' half-sole repair @ location listed.
				11/14/25	8	0.50	SQFT	Bent 4					Payment being made for .5'x1' half-sole repair @ location listed.
				11/14/25	9	2.00	SQFT	Bent 4					Payment being made for 1'x2' half-sole repair @ location listed.
				11/14/25	10	1.00	SQFT	Bent 4					Payment being made for 1'x1' half-sole repair @ location listed.
				11/14/25	11	1.50	SQFT	Bent 4					Payment being made for 1'x1.5' half-sole repair @ location listed.
				11/14/25	12	1.00	SQFT	Span 3 L12					Payment being made for 1'x1' half-sole repair @ location listed.
				11/14/25	13	1.50	SQFT	Span 3 L12					Payment being made for 1'x1.5' half-sole repair @ location listed.
				11/14/25	14	2.25	SQFT	Span 3 L12					Payment being made for .75'x3' half-sole repair @ location listed.
				11/14/25	15	2.00	SQFT	Span 3 L12					Payment being made for 2'x1' half-sole repair @ location listed.
730	7040163	CONCRETE CRACK FILLER	11/5/25	11/11/25	1	3,555.00	SQYD	I-64 WB Lane 2					Payment being made for surface preparation and crack sealer applied @ the listed location.
			11/6/25	11/11/25	1	3,555.00	SQYD	I-64 WB Lane 1					Payment being made for surface preparation and crack sealer applied @ the listed location.
1870	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	11/15/25	11/17/25	1	0.25	LS	Bridge A4017					Payment being made for the painting of the numbers and increment markings for the clearance gauge, using black paint.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 7 of 16



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3538	0090	CONCRETE PAVEMENT (9 IN.	Material		3	Apr 2, 2025	SYSTEM	(\$338,128.00)	
		NON- REINFORCED,			3	Apr 2, 2025	SYSTEM	\$338,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Apr 16, 2025	SYSTEM	(\$338,128.00)	
					4	Apr 16, 2025	SYSTEM	\$338,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lower2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 2, 2025	SYSTEM	(\$419,664.00)	
					5	May 2, 2025	SYSTEM	\$419,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	May 16, 2025	SYSTEM	(\$766,192.00)	
					6	May 16, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jun 3, 2025	SYSTEM	(\$766,192.00)	
					7	Jun 3, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jun 17, 2025	SYSTEM	(\$766,192.00)	
					8	Jun 17, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Jun 30, 2025	SYSTEM	(\$766,192.00)	
					9	Jun 30, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Jul 16, 2025	SYSTEM	(\$766,192.00)	
					10	Jul 16, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Aug 4, 2025	SYSTEM	(\$766,192.00)	
					11	Aug 4, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Aug 19, 2025	SYSTEM	(\$766,192.00)	
					12	Aug 19, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Sep 3, 2025	SYSTEM	(\$766,192.00)	
					13	Sep 3, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Sep 17, 2025	SYSTEM	(\$766,192.00)	
					14	Sep 17, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Oct 2, 2025	SYSTEM	(\$766,192.00)	
					15	Oct 2, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Oct 17,	SYSTEM	(\$766,192.00)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
38	0090	CONCRETE	Material			2025			
		PAVEMENT (9 IN. NON- REINFORCED,			16	Oct 17, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Nov 4, 2025	SYSTEM	(\$766,192.00)	
					17	Nov 4, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Nov 17, 2025	SYSTEM	(\$766,192.00)	
					18	Nov 17, 2025	SYSTEM	\$766,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sawyej2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0090 -	Total						\$0.00	
	0100	IMPACT ATTENUATOR 60	Material		3	Apr 2, 2025	SYSTEM	(\$8,944.00)	
		MPH (SAND BARREL ARRAY)			3	Apr 2, 2025	SYSTEM	\$8,944.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0100 -	Total						\$0.00	
	0150	TRUCK MOUNTED	Material		2	Mar 17, 2025	SYSTEM	(\$3,500.00)	
		ATTENUATOR (TMA)			2	Mar 17, 2025	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lower2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	Total						\$0.00	
	0180	FURN & PLACE BIT. MATL FOR CL C PARTIAL	Other Item Adjustment	ACAD	4	Apr 16, 2025	sawyej2	\$211.43	This adjustment is for the AC Index Price Adjustment.
									433.7 Tons placed this estimate period Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43
									Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5%
				ACAD - Tota				\$211.43	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT -
			Other Item	ACAD - Tota Adjustment -				\$211.43	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT -
	0180 -			Adjustment -	Total			\$211.43 \$211.43	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT -
	0180 - 0190	Total REMOVAL FOR CLASS C PARTIAL DEPTH	Other Item		Total 3	Apr 2, 2025	SYSTEM	\$211.43 \$211.43 (\$2,970.00)	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT - TranSystems" folder)
		REMOVAL FOR CLASS C		Adjustment -	Total		SYSTEM SYSTEM	\$211.43 \$211.43	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT - TranSystems" folder)
		REMOVAL FOR CLASS C PARTIAL DEPTH		Adjustment -	Total 3	2025 Apr 16,		\$211.43 \$211.43 (\$2,970.00)	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT - TranSystems" folder) Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',33.00000 - 33.00000, 'is
		REMOVAL FOR CLASS C PARTIAL DEPTH		Adjustment - Overrun Overrun - To	Total 3	2025 Apr 16,		\$211.43 \$211.43 (\$2,970.00) \$2,970.00	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT - TranSystems" folder) Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',33.00000 - 33.00000, 'is
		REMOVAL FOR CLASS C PARTIAL DEPTH PAVT REPAIR	Overrun	Adjustment - Overrun Overrun - To	Total 3	2025 Apr 16,		\$211.43 \$211.43 (\$2,970.00) \$2,970.00	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT - TranSystems" folder) Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',33.00000 - 33.00000, 'is
	0190	REMOVAL FOR CLASS C PARTIAL DEPTH PAVT REPAIR	Overrun	Adjustment - Overrun Overrun - To	Total 3	2025 Apr 16,		\$211.43 \$211.43 (\$2,970.00) \$2,970.00 \$0.00	Index @ Letting: \$493.75 Current Index: \$501.25 Index Difference: \$7.50 Virgin AC: 6.5% Total Difference = -\$211.43 (Spreadsheet located in Contractor Sharepoint within "CONSULTANT - TranSystems" folder) Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',33.00000 - 33.00000, 'is



t Line	e Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
8 022	FURNISHED / RETAINED	Material	- Total				\$0.00 \$0.00	
022	Material - Total 0220 - Total							
	0240 MISC. Material 3 Apr 2, SYSTEM						\$0.00 (\$90,000.00)	
024	Wiles.	Material			2025	OTOTEM	(ψου,σου.σο)	
				3	Apr 2, 2025	SYSTEM	\$90,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sawyej2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
		Material - T	otal				\$0.00	
	0 - Total	Matarial		40	N 47	OVOTEM	\$0.00	
026	TRAFFIC	Material		18	Nov 17, 2025	SYSTEM	(\$97,995.00)	
	BARRIER, TYPE C			18	Nov 17, 2025	SYSTEM	\$97,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
		Material - T	- Total				\$0.00	
026	0 - Total						\$0.00	
027	TEMPORARY TRAFFIC BARRIER, CONT.	Material		3	Apr 2, 2025	SYSTEM	(\$27,826.25)	
	FURN/RE			3	Apr 2, 2025	SYSTEM	\$27,826.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	Apr 16, 2025	SYSTEM	(\$707,008.38)	
				4	Apr 16, 2025	SYSTEM	\$707,008.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lower2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
		Material - To	otal				\$0.00	
		Material - To		6	May 16, 2025	SYSTEM		
			otal	6		SYSTEM	\$0.00	
			otal	11	2025 Aug 4,		\$0.00 (\$16,892.75)	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is
			otal Overrun Overrun - T	11	2025 Aug 4,		\$0.00 (\$16,892.75) \$16,892.75	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is
	0 - Total	Overrun - T	otal Overrun Overrun - T	11	2025 Aug 4, 2025	SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is
027 046		Overrun	otal Overrun Overrun - T	11 otal	2025 Aug 4,	SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero).
		Overrun - T	Overrun Overrun - T	11	2025 Aug 4, 2025	SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00)	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is
		Overrun - T	Overrun - T Overrun - T Overrun - T	11 otal	2025 Aug 4, 2025 Apr 16, 2025 Apr 16,	SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00) \$3,600.00	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment
046	0 MULCHING	Overrun - T	Overrun - T Overrun - T Overrun - T	11 otal	2025 Aug 4, 2025 Apr 16, 2025 Apr 16,	SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 (\$3,600.00) \$3,600.00 \$0.00	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment
046	MULCHING 0 - Total	Overrun - T Material Material - To	Overrun - T Overrun - T Overrun - T	11 dotal 4 d	2025 Aug 4, 2025 Apr 16, 2025 Apr 16, 2025	SYSTEM SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00) \$3,600.00 \$0.00 \$0.00	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment
046	MULCHING 0 - Total	Overrun - T	Overrun - T Overrun - T Overrun - T	11 4 4 4 3 3	2025 Aug 4, 2025 Apr 16, 2025 Apr 16, 2025 Apr 2, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00) \$0.00 \$0.00 \$0.00 (\$1,260.00)	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
046	MULCHING 0 - Total 0 SEDIMENT TRAP	Overrun - T Material Material - To	Overrun - T Overrun - T Overrun - T	11 4 4 4 3 3 3 3	Apr 16, 2025 Apr 16, 2025 Apr 2025 Apr 2, 2025 Apr 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00) \$0.00 \$0.00 \$0.00 \$1,260.00)	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
046	MULCHING 0 - Total 0 SEDIMENT TRAP	Overrun - T Material Material - To	Overrun - T Overrun - T Overrun - T	11 4 4 4 3 3	Apr 16, 2025 Apr 16, 2025 Apr 2, 2025 Apr 2, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00) \$0.00 \$0.00 \$0.00 (\$1,260.00)	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment
046	MULCHING 0 - Total 0 SEDIMENT TRAP	Overrun - T Material Material - To	Overrun - T Overrun - T Overrun - T	11 4 4 4 3 3 3 3	Apr 16, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 207 Apr 2, 2025 Apr 16, 207	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00) \$0.00 \$0.00 \$0.00 \$1,260.00)	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment
046	MULCHING 0 - Total 0 SEDIMENT TRAP	Overrun - T Material Material - To	Overrun - T Overrun - T Overrun - T	11 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Apr 16, 2025 Apr 2, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 Apr 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00) \$0.00 \$0.00 \$1,260.00) (\$1,260.00)	previous payment estimates. Price Adjustments of ',49.25000 - 49.25000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lower2 overridding Payment Estimate Item Adjustment (0005) due to user lower2 overridding Payment
046	MULCHING 0 - Total 0 SEDIMENT TRAP	Overrun - T Material Material - To	Overrun - T otal - Total - Total	11 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Apr 16, 2025 Apr 2, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 Apr 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$16,892.75) \$16,892.75 \$0.00 \$0.00 \$0.00 (\$3,600.00) \$3,600.00 \$0.00 \$1,260.00) \$1,260.00 \$1,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lower2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6I3538	0500	ALTERNATE DITCH CHECK	Material		2	Mar 17, 2025	SYSTEM	(\$1,600.00)		
					2	Mar 17, 2025	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lower2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - Total					\$0.00		
	0500 -	- Total						\$0.00		
	0520	TEMPORARY SEEDING	Material		4	Apr 16, 2025	SYSTEM	(\$1,680.00)		
					4	Apr 16, 2025	SYSTEM	\$1,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user lower2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - Total					\$0.00		
	0520 -	Total						\$0.00		
	0530	SILT FENCE	Overrun	Overrun	2	Mar 17, 2025	SYSTEM	(\$6,009.50)		
					2	Mar 17, 2025	SYSTEM	\$6,009.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user lower2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				Overrun - T	otal			\$0.00		
			Overrun - Total					\$0.00		
	0530 -	- Total						\$0.00		
	0600	7 FT. CHAN. POST DELINE., WHITE	Material		10	Jul 16, 2025	SYSTEM	(\$2,000.00)		
					10	Jul 16, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					11	Aug 4, 2025	SYSTEM	(\$2,000.00)		
					11	Aug 4, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					12	Aug 19, 2025	SYSTEM	(\$2,000.00)		
					12	Aug 19, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					13	Sep 3, 2025	SYSTEM	(\$2,000.00)		
						13	Sep 3, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					14	Sep 17, 2025	SYSTEM	(\$2,000.00)		
					14	Sep 17, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					15	Oct 2, 2025	SYSTEM	(\$2,000.00)		
					15	Oct 2, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					16	Oct 17, 2025	SYSTEM	(\$2,000.00)		
					16	Oct 17, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					17	Nov 4, 2025	SYSTEM	(\$2,000.00)		
							17	Nov 4, 2025	SYSTEM	\$2,000.00



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6I3538	0600	7 FT. CHAN. POST DELINE.,	Material		18	Nov 17, 2025	SYSTEM	(\$2,000.00)		
		WHITE			18	Nov 17, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0600 -	Total						\$0.00		
	0650	MISC.	Material		3	Apr 2, 2025	SYSTEM	(\$7,200.00)		
					3	Apr 2, 2025	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sawyej2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					4	Apr 16, 2025	SYSTEM	(\$7,200.00)		
					4	Apr 16, 2025	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user lower2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0650 -	Total						\$0.00		
	0740	MISC.	Material		2	Mar 17, 2025	SYSTEM	(\$16,500.00)		
					2	Mar 17, 2025	SYSTEM	\$16,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lower2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
				- Total				\$0.00		
		Material - Total						\$0.00		
	0740 -	Total						\$0.00		
	0750	MISC.	Material	ial	8	Jun 17, 2025	SYSTEM	(\$550.00)		
					8	Jun 17, 2025	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					9	Jun 30, 2025	SYSTEM	(\$550.00)		
					9	Jun 30, 2025	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sawyej2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					10	Jul 16, 2025	SYSTEM	(\$550.00)		
					10	Jul 16, 2025	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					11	Aug 4, 2025	SYSTEM	(\$550.00)		
						11	Aug 4, 2025	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sawyej2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Aug 19, 2025	SYSTEM	(\$550.00)		
					12	Aug 19, 2025	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					13	Sep 3, 2025	SYSTEM	(\$550.00)		
					13	Sep 3, 2025	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					14	Sep 17, 2025	SYSTEM	(\$550.00)		
					14	Sep 17, 2025	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sawyej2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	



Estimate Exception 3 on the current Payment Estimate.	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
15	3 0750	MISC.	Material	Туре	15		SYSTEM	(\$550.00)	
16					15	Oct 2,	SYSTEM	\$550.00	Estimate Item Adjustment (0003) due to user sawyej2 overridding Payme
2025 Estimate Item Agustramen (0003) due to user sawyed overridding Payment Estimate Exception 3 on the current Payment Estimate Payment Payment Estimate Payment Payment Estimate Payment Estimate Payment Payment Estimate Payment Payment Payment Estimate Payment Payment Estimate Payment Payment Payment Estimate Payment Pa					16		SYSTEM	(\$550.00)	
17					16		SYSTEM	\$550.00	Estimate Item Adjustment (0003) due to user sawyej2 overridding Payme
2025 Estimate Etem Adjustment (0003) due to user saveyez overridding Payme Estimate Exception 3 on the current Payment Estimate.					17		SYSTEM	(\$550.00)	
2025 18					17		SYSTEM	\$550.00	Estimate Item Adjustment (0003) due to user sawyej2 overridding Payme
Sectionals Estimate Estimate Estimate Estimate Estimate Exception So not be current Payment Estimate Estima					18		SYSTEM	(\$550.00)	
					18		SYSTEM	\$550.00	Estimate Item Adjustment (0004) due to user sawyej2 overridding Paymo
PROTECTIVE COATING - CONCRETE ENTS AND				- Total				\$0.00	
PROTECTIVE			Material - To	otal				\$0.00	
COATING - CONCRETE	0750 -	Total						\$0.00	
BENTS AND	0760	COATING -	Material		6		SYSTEM	(\$52,540.00)	
2025 7					6		SYSTEM	\$52,540.00	Estimate Item Adjustment (0003) due to user sawyej2 overridding Paymo
System System System Stimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 7 on the current Payment Estimate Estimate Exception 7 on the current Payment Estimate. Payment					7		SYSTEM	(\$52,540.00)	
2025 8 Jun 17, 2025 8 Jun 17, 2025					7		SYSTEM	\$52,540.00	Estimate Item Adjustment (0002) due to user sawyej2 overridding Payme
2025 Sumal tem Adjustment (0003) due to user sawyej2 overridding Payme Estimate Exception 7 on the current Payment Estimate.					8		SYSTEM	(\$52,540.00)	
2025 9 Jun 30, 2025 9 Jun 30, 2025 10 Jul 16, 2025 2025					8		SYSTEM	\$52,540.00	Estimate Item Adjustment (0003) due to user sawyej2 overridding Payme
2025 Estimate Item Adjustment (0003) due to user sawye/2 overridding Payme Estimate Exception 8 on the current Payment Estimate.					9		SYSTEM	(\$52,540.00)	
2025 10					9		SYSTEM	\$52,540.00	Estimate Item Adjustment (0003) due to user sawyej2 overridding Payme
2025 Estimate Item Adjustment (0004) due to user sawyej2 overridding Payment Estimate Exception 8 on the current Payment Estimate. Total \$0.00					10		SYSTEM	(\$105,080.00)	
Material - Total \$0.00					10		SYSTEM	\$105,080.00	Estimate Item Adjustment (0004) due to user sawyej2 overridding Payme
SURFACE PREPARATION FOR RECOATING STRUC SUBSTRUC SUBSTRUCT SUBSTR									
SURFACE PREPARATION FOR RECOATING STRUC 3			Material - To	otal					
PREPARATION FOR RECOATING STRUC 3 Apr 2, 2025 4 Apr 16, 2025 5 SYSTEM 239,430.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate testimate testimate them Adjustment (0008) due to user lower2 overridding Payment Estimate Exception 5 on the current Payment Estimate. Total So.00 Material - Total \$0.00			NA-A		0	A C	OVOTEL		
Estimate Item Adjustment (0008) due to user sawyej2 overridding Payme Estimate Exception 7 on the current Payment Estimate. 4	0//0	PREPARATION FOR RECOATING	Material			2025		,	
2025 4 Apr 16, SYSTEM \$359,145.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user lower2 overridding Paymer Estimate Exception 5 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00						2025			Estimate Item Adjustment (0008) due to user sawyej2 overridding Payme
Estimate Item Adjustment (0008) due to user lower2 overridding Paymer Estimate Exception 5 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00						2025		,	
Material - Total \$0.00					4		SYSTEM		Estimate Item Adjustment (0008) due to user lower2 overridding Paymer
0770 - Total \$0.00			Material - To	otal					



et	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	21110	Doscription	Type	Adjustment Type	Number	Date	By	7 tinount	romano
8	0870	MISC. STRUCTURAL STEEL CONSTRUCTION	Material		15	Oct 2, 2025	SYSTEM	(\$25,500.00)	
					15	Oct 2, 2025	SYSTEM	\$25,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sawyej2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					16	Oct 17, 2025	SYSTEM	(\$25,500.00)	
					16	Oct 17, 2025	SYSTEM	\$25,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sawyej2 overridding Paymen Estimate Exception 6 on the current Payment Estimate.
					17	Nov 4, 2025	SYSTEM	(\$25,500.00)	
					17	Nov 4, 2025	SYSTEM	\$25,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sawyej2 overridding Paymer Estimate Exception 6 on the current Payment Estimate.
					18	Nov 17, 2025	SYSTEM	(\$34,000.00)	
					18	Nov 17, 2025	SYSTEM	\$34,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Paymer Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	Material - Total					
	0870 -							\$0.00	
	0880	PREFORMED SILICONE OR EPDM EXP. JOINT			9	Jun 30, 2025	SYSTEM	(\$17,856.00)	
		SEAL			9	Jun 30, 2025	SYSTEM	\$17,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sawyej2 overridding Paymer Estimate Exception 9 on the current Payment Estimate.
					10	Jul 16, 2025	SYSTEM	(\$47,616.00)	
					10	Jul 16, 2025	SYSTEM	\$47,616.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Paymer Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0880 - 5003	FIELD APPLICATION OF ORGANIC ZINC	Material		3	Apr 2,	SYSTEM	\$0.00 (\$7,560.00)	
					3	2025 Apr 2, 2025	SYSTEM	\$7,560.00	This adjustment offsets the original system-generated Material Payment
									Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer
				- Total				\$0.00	
			Material - To	- Total				\$0.00 \$0.00	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer
	5003 -	Total	Material - To						Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer
	5003 - 5008	FURNISHING TYPE 1 ROCK	Material - To		9	Jun 30, 2025	SYSTEM	\$0.00	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer
		FURNISHING			9	Jun 30,	SYSTEM SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		FURNISHING TYPE 1 ROCK				Jun 30, 2025 Jun 30,		\$0.00 \$0.00 (\$4,930.00)	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment
		FURNISHING TYPE 1 ROCK			9	Jun 30, 2025 Jun 30, 2025 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$4,930.00) \$4,930.00	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		FURNISHING TYPE 1 ROCK			9	Jun 30, 2025 Jun 30, 2025 Jul 16, 2025 Jul 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,930.00) \$4,930.00 (\$4,930.00)	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment
		FURNISHING TYPE 1 ROCK			9 10 10	Jun 30, 2025 Jun 30, 2025 Jul 16, 2025 Jul 16, 2025	SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,930.00) \$4,930.00 (\$4,930.00) \$4,930.00	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
		FURNISHING TYPE 1 ROCK			9 10 10 11	Jun 30, 2025 Jun 30, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,930.00) \$4,930.00 (\$4,930.00) \$4,930.00	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment
		FURNISHING TYPE 1 ROCK		otal - Total	9 10 10 11	Jun 30, 2025 Jun 30, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,930.00) \$4,930.00 (\$4,930.00) \$4,930.00 \$4,930.00	Estimate Item Adjustment (0009) due to user sawyej2 overridding Paymer Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment Estimate Item Adjustment (0005) due to user sawyej2 overridding Payment

Nov 19, 2025



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3538	5011	PROTECTIVE COATING -	Material		11	Aug 4, 2025	SYSTEM	(\$131,350.00)	
		CONCRETE BENTS AND			11	Aug 4, 2025	SYSTEM	\$131,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sawyej2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				\$0.00	
		Material - Total						\$0.00	
	5011 -	Total					\$0.00		
J6I3538	J6l3538 - Total								
Overall -	Total						\$211.43		

MoDOT

Contract Adjustments for Contract - 241115-F01

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 16 of 16