

Pay Estimate Created Date: August 4, 2025

	Contract ID Prime Contra		241115-F03 N.B. West Contracting Company		Pay Period Start Pay Period End	August 1, 2025		Original Contra Net Change Or Current Contra	\$3	62,451.99 15,564.40 78,016.39	
Approval Date										By U	lser
August 4, 2025			Generated and	d Appr	oved (and should be	considere	ed Draft) a	at the Project O	ffice Level by		schirj1
August 4, 2025			Reviewed and App	roved	(and should be cons	idered Dr	aft) at the	Resident Engi	neer Level by		wolkt1
August 6, 2025		Reviewed and Approved at the Central Office Controllers Office Level by								ramses1	
Original Completi	n Date Current Completion Date Actual Completion Date % of Current Contract Amoun						unt Complet	e			
November 15, 2	2026	Noven	nber 15, 2026						28.52%		
	Co	ontract Informa	ational Dates					Mile	stones		
Date Description	Original Co	mpletion Date	Current Completion	Date		Date D	escription		Current	Days	Diary
Acceptance Date								Completion Date	Completion Date	Remaining	Charge Days
Awarded Date	December 4	, 2024	December 4, 2024							Milestone	
Letting Date	November 1	5, 2024	November 15, 2024				ne - JSP-		Milestone		
Notice to Proceed Date	January 6, 2	025	January 6, 2025			for A115	etion date 57 and	22, 2025	22, 2026	Complete	
Work Began Date	January 15,	2025	January 15, 2025			A1156					

Contract Total Pa	y For Estimate No. 14				
		This Estimate	Previous	To Date	
241115-F03					
	Total Posted Items Pay	\$502,181.90	\$5,823,720.54	\$6,325,902.44	
	Gross Item Adjustments	\$22,184.30	\$1,067,189.87	\$1,089,374.17	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$6,890,910.41	\$7,415,276.61	
Contract Total Pa	yable This Estimate:	\$524,366.20			

		ble This Es	·				
tems Paid	This Estir	nate Period					
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3283	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$1,687,000.000	0.045	\$75,915.00
	0020	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	STA	\$600.000	18	\$10,800.00
	0040	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$6.000	1,441.600	\$8,649.60
	0050	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$11.000	45.600	\$501.60
	0110	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	SQYD	\$140.000	424.700	\$59,458.00
	0120	5021111	CONCRETE PAVEMENT (11 INCH NON-REINFORCED)	SQYD	\$132.000	45.600	\$6,019.20
	0140	6081012	TRUNCATED DOMES	SQFT	\$30.000	60	\$1,800.00
	0150	6083006	6 IN. CONCRETE MEDIAN STRIP	SQYD	\$125.000	17.800	\$2,225.00
	0170	6085007	PAVED APPROACH, 7 IN.	SQYD	\$110.000	442.600	\$48,686.00
	0180	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$80.000	282.300	\$22,584.00
	0190	6089902	MISC.CONCRETE CURB RAMP (7 IN. THICK)	EA	\$3,320.000	6	\$19,920.00
	0200	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$18.000	137	\$2,466.00
	0210	6091052	CURB AND GUTTER TYPE B	LF	\$42.000	751	\$31,542.00
	0540	8031000A	TURF TYPE TALL FESCUE SODDING	SQYD	\$11.000	227	\$2,497.00
	0660	9015010	TRENCHING TYPE I	LF	\$4.000	76	\$304.00
	0690	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	LF	\$5.000	282	\$1,410.00
	1060	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	EA	\$18,680.000	1	\$18,680.00
	1070	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$17.000	371	\$6,307.00
	1080	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	LF	\$29.000	777	\$22,533.00
	1110	9028302	CABLE, 12 AWG 2 CONDUCTOR	LF	\$1.300	20	\$26.00
	1150	9028811	PULL BOX, PREFORMED CLASS 2	EA	\$1,785.000	4	\$7,140.00
	1160	9028812	PULL BOX, PREFORMED CLASS 3	EA	\$2,500.000	2	\$5,000.00

Revision 5/29/2025 Page 1 of 36



Pay Estimate Created Date: August 4, 2025

Estimate	gress Number 4	Contrac Prime C	t ID ontractor	241115-F03 N.B. West Contracting Company	Pay Period Start Pay Period End	July 16, 1 August 1		Original Contract Net Change Ord Current Contract	er Amount	\$21,862,451.99 \$315,564.40 \$22,178,016.39
Project Number	Line Number	Item Code		Item Description			Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3283	1170	9029100	BASE, C	ONCRETE			CUYD	\$1,575.000	27.780	\$43,753.50
	1180	9029901	MISC.TR	AFFIC SIGNAL MAINTENANCE & PI	ROGRAMMING		LS	\$24,000.000	0.050	\$1,200.00
	1190	9029902	MISC.AT	C TRAFFIC SIGNAL CONTROLLER			EA	\$5,250.000	1	\$5,250.00
	1210	9029902		MBINATION PAD MOUNTED 120V/ G CONTROLLER WITH UPS	240V POWER SUPPL	Y AND	EA	\$19,680.000	2	\$39,360.00
	1230	9029902	MISC.NE	TWORK CONNECTED SIGNAL MOI	NITOR		EA	\$1,435.000	1	\$1,435.00
	1260	9029902	MISC.SL	DISTRICT TRAFFIC SIGNAL DETEC	CTION		EA	\$39,320.000	1	\$39,320.00
	1520	6042010	ADJUSTI	NG MANHOLE			EA	\$500.000	2	\$1,000.00
	1550	7319902	MISC.RE	PLACE EXISTING CURB INLET TOP)		EA	\$1,300.000	1	\$1,300.00
	1580	7319902	MISC.RE	PLACE EXISTING GRATE INLET TO)P		EA	\$2,100.000	7	\$14,700.00
	1630	6049902	MISC.AD	JUSTING GAS VALVE TO GRADE			EA	\$50.000	2	\$100.00
	1660	6049902	MISC.AD	JUSTING WATER VALVE TO GRAD	E		EA	\$150.000	2	\$300.00
Project Je	S3283 - T	otal								\$502,181.90
Overall -	Γotal									\$502,181.90
Contract A	djustment	ts This Esti	mate							

		stments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3283	0040	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	15,601.20000	\$6.00	\$93,607.20
	0040	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-15,601.20000	\$6.00	(\$93,607.20
	0050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	792.90000	\$11.00	\$8,721.90
	0050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-792.90000	\$11.00	(\$8,721.90
	0120	CONCRETE PAVEMENT (11 INCH NON-REINFORCED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	828.40000	\$132.00	\$109,348.80
	0120	CONCRETE PAVEMENT (11 INCH NON-REINFORCED)	Material			-828.40000	\$132.00	(\$109,348.80
	0130	CONCRETE PAVEMENT (12 INCH NON-REINFORCED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	97	\$80.00	\$7,760.00
	0130	CONCRETE PAVEMENT (12 INCH NON-REINFORCED)	Material			-97	\$80.00	(\$7,760.00
	0860	POST, SIGNAL 8 FT.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$1,050.00	\$2,100.00
	0860	POST, SIGNAL 8 FT.	Material			-2	\$1,050.00	(\$2,100.00
	1060	CONTROLLER ASSEMBLY HOUSING, NEMA TS2	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$22,825.84

Revision 5/29/2025 Page 2 of 36



Pay Estimate Created Date: August 4, 2025

Estimat	gress e Num 14		41115-F03 .B. West Contrac	cting Compan	Pay Period Start y Pay Period End	July 16, 2025 August 1, 2025	Original Contract A Net Change Order A Current Contract A	Amount	\$21,862,451.99 \$315,564.40 \$22,178,016.39
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comme	ents	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3283		CONTROLLER							
	1170	BASE, CONCRETE	Material		This adjustment offsets the generated Material Paym Adjustment (0007) due to overridding Payment Est on the current Payment E	nent Estimate Iten o user schirj1 imate Exception ′	n	\$1,575.00	\$252,488.25
	1170	BASE, CONCRETE	Material				-160.31000	\$1,575.00	(\$252,488.25)
	1190	MISC.	Construction Stockpile		Payment Estimate Item A Stockpile Transaction	Adjustment gener	ated		\$85,500.00
	1230	MISC.	Construction Stockpile		Payment Estimate Item A Stockpile Transaction	Adjustment gener	ated		(\$1,169.00)
	1260	MISC.	Construction Stockpile		Payment Estimate Item A Stockpile Transaction	Adjustment gener	ated		(\$22,103.00)
	1260	MISC.	Construction Stockpile		Payment Estimate Item A Stockpile Transaction	Adjustment gener	ated		(\$17,217.86)
	1400	MISC.	Material		This adjustment offsets the generated Material Paym Adjustment (0012) due to overridding Payment Estion the current Payment E	nent Estimate Iten o user schirj1 imate Exception ′	n	\$90.00	\$360.00
	1400	MISC.	Material				-4	\$90.00	(\$360.00)
	1410	MISC.	Material		This adjustment offsets the generated Material Paym Adjustment (0013) due to overridding Payment Estion the current Payment E	nent Estimate Iten o user schirj1 imate Exception ′	n	\$38.00	\$152.00
	1410	MISC.	Material				-4	\$38.00	(\$152.00)
	1420	MISC.	Material		This adjustment offsets the generated Material Paym Adjustment (0014) due to overridding Payment Estion the current Payment E	nent Estimate Iten o user schirj1 imate Exception ′	n	\$19.00	\$76.00
	1420	MISC.	Material				-4	\$19.00	(\$76.00)
	1460	MISC.	Material		This adjustment offsets the generated Material Paym Adjustment (0015) due to overridding Payment Estion the current Payment E	nent Estimate Iten o user schirj1 imate Exception ′	n	\$425.00	\$425.00
	1460	MISC.	Material				-1	\$425.00	(\$425.00)
	1490	MISC.	Material		This adjustment offsets the generated Material Paym Adjustment (0016) due to overridding Payment Estion the current Payment E	nent Estimate Iten o user schirj1 imate Exception ′	n	\$490.00	\$490.00
	1490	MISC.	Material				-1	\$490.00	(\$490.00)
	1540	12 IN. PIPE GROUP B	Material		This adjustment offsets the generated Material Paym Adjustment (0017) due to overridding Payment Estithe current Payment Esti	nent Estimate Iten o user schirj1 imate Exception 9	n	\$153.00	\$7,038.00
	1540	12 IN. PIPE GROUP B	Material				-46	\$153.00	(\$7,038.00)
	5005	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR			This adjustment offsets the generated Material Paym Adjustment (0018) due to overridding Payment Estithe current Payment Esti	nent Estimate Iten o user schirj1 imate Exception 7	n	\$7.00	\$1,330.00
	5005	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR					-190	\$7.00	(\$1,330.00)

Revision 5/29/2025 Page 3 of 36



Pay Estimate Created Date: August 4, 2025

Estimat	gress e Numl 14		241115-F03 N.B. West Contrac	cting Compan		July 16, 2025 August 1, 2025	Original Contract A Net Change Order A Current Contract A	Amount	\$21,862,451.99 \$315,564.40 \$22,178,016.39
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comme	ents	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3283	5006	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)			This adjustment offsets the generated Material Paym Adjustment (0019) due to overridding Payment Estithe current Payment Esti	ent Estimate Item user schirj1 mate Exception 8	1	\$4.00	\$288.00
	5006	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)					-72	\$4.00	(\$288.00)
Total									\$22,184.30

Revision 5/29/2025 Page 4 of 36



					Co	ontract Project Information	n			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J6S3283 FAF 21-2(85)										
Totals I	by Job N	umbers								
J6S3283		ed Item Pay s Item Adjustme		tem Pay	This Estimate \$502,181.90 \$22,184.30 \$524,366.20	Previous \$5,823,720.54 \$1,067,189.87 \$6,890,910.41	To Date \$6,325,902.44 \$1,089,374.17 \$7,415,276.61			
	Incen Disin	tive centive			\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00			
		dated Damages · Contract Adjus	tments		\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00			

Revision 5/29/2025 Page 5 of 36



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Feriod			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 3040504, Project Item Line Number 0040, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 3040506, Project Item Line Number 0050, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 5021111, Project Item Line Number 0120, Material Set 502111196, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 5021112, Project Item Line Number 0130, Material Set 502111296, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 5021112, Project Item Line Number 0130, Material Set 502111296, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 5021112, Project Item Line Number 0130, Material Set 502111296, Material 1057JMDAEC4.12 - Dowel Assemblies Epoxy Ctd Gr40 1 1/2" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 6131015, Project Item Line Number 5005, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 6131018, Project Item Line Number 5006, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 7250312A, Project Item Line Number 1540, Material Set 7250312A96, Material 1041CPPPDW12 - Polypropylene Culv Double Wall 12", Acceptance Action Generic 1041CPPPDW12 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 9022708, Project Item Line Number 0860, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 9029100, Project Item Line Number 1170, Material Set 902910096, Material 0903HSBTZCAB - Galvanized Anchor Bolts for Highway Sign, Acceptance Action Generic 0903HSBTZCAB is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 9109902, Project Item Line Number 1400, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 9109902, Project Item Line Number 1410, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 9109902, Project Item Line Number 1420, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 9109902, Project Item Line Number 1460, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3283, Item 9109902, Project Item Line Number 1490, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Item Overrun: Contract 241115-F03, Contract Project J6S3283, Project Item Line Number 1720, Contract Line Item Number 1720, Item 7173002, Minor Item.	Waiting on Phase to to finalize the quantity.	schirj1	Acknowledged

Revision 5/29/2025 Page 6 of 36



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Po Contract ID	Project No.	Category	Line No.	Item Code	d on Report Generated date and can differ from the post	Bid Quantity	Net Change	Total Current	Unit	Generated. Total Posted	Unit Price	Total Value POSTED To Date (See report
		0004					Order	Quantity		Approved Qty		generated date)
241115- F03	J6S3283	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$1,687,000.00	\$607,320.00
		0001	0020	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	339.70	0.00	339.70	STA	101.00	\$600.00	\$60,600.00
			0030	2159910	MISC.SHAPING SLOPES, CLASS III - MODIFIED MATERIAL REQUIREMENT	49.00	0.00	49.00	100F	42.00	\$1,250.00	\$52,500.00
		0001	0040	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	36,825.00	0.00	36,825.00	SQYD	15,601.20	\$6.00	\$93,607.20
		0001	0050	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	3,683.00	0.00	3,683.00	SQYD	792.90	\$11.00	\$8,721.90
		0001	0060	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	4,125.20	0.00	4,125.20	TONS	10.10	\$100.00	\$1,010.00
		0001	0070	4019905	MISC.OPTIONAL PAVEMENT	2,764.40	0.00	2,764.40	SQYD	0.00	\$110.00	\$0.00
		0001	0800	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	295.90	0.00	295.90	TONS	0.00	\$160.00	\$0.00
			0090	4030111	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125CLP MIX)	33,293.40	0.00	33,293.40	TONS	0.00	\$122.00	\$0.00
		0001	0100	4071007	TACK COAT - NON-TRACKING	32,268.30	0.00	32,268.30	GAL	0.00	\$3.00	\$0.00
		0001	0110	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	6,181.60	0.00	6,181.60	SQYD	2,260.80	\$140.00	\$316,512.00
		0001	0120	5021111	CONCRETE PAVEMENT (11 INCH NON-REINFORCED)	918.10	0.00	918.10	SQYD	828.40	\$132.00	\$109,348.80
		0001	0130	5021112	CONCRETE PAVEMENT (12 INCH NON-REINFORCED)	1,998.60	0.00	1,998.60	SQYD	97.00	\$80.00	\$7,760.00
		0001	0140	6081012	TRUNCATED DOMES	3,383.00	0.00	3,383.00	SQFT	573.10	\$30.00	\$17,193.00
		0001	0150	6083006	6 IN. CONCRETE MEDIAN STRIP	1,486.60	0.00	1,486.60	SQYD	50.60	\$125.00	\$6,325.00
		0001	0160	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	100.00	0.00	100.00	LF	0.00	\$210.00	\$0.00
		0001	0170	6085007	PAVED APPROACH, 7 IN.	5,066.10	0.00	5,066.10	SQYD	2,103.30	\$110.00	\$231,363.00
		0001	0180	6086004	CONCRETE SIDEWALK, 4 IN.	14,990.40	0.00	14,990.40	SQYD	6,856.00	\$80.00	\$548,480.00
		0001	0190	6089902	MISC.CONCRETE CURB RAMP (7 IN. THICK)	146.00	0.00	146.00	EA	40.00	\$3,320.00	\$132,800.00
		0001	0200	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,966.00	0.00	3,966.00	LF	552.00	\$18.00	\$9,936.00
		0001	0210	6091052	CURB AND GUTTER TYPE B	21,860.00	0.00	21,860.00	LF	10,933.50	\$42.00	\$459,207.00
		0001	0220	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	395.00	0.00	395.00	LF	77.00	\$54.00	\$4,158.00
		0001	0230	6092013	INTEGRAL CURB TYPE M	54.00	0.00	54.00	LF	0.00	\$50.00	\$0.00
		0001	0240	6099902	MISC.WALK/COVER AND GUTTER	4.00	0.00	4.00	EA	0.00	\$6,500.00	\$0.00
		0001	0250	6099903	MISC.MODIFIED CONCRETE CURB & GUTTER	223.00	0.00	223.00	LF	96.00	\$48.00	\$4,608.00
		0001	0260	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$2,265.00	\$4,530.00
		0001	0270	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$732.00	\$0.00
		0001	0280	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0001	0290	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0300	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$247,930.00	\$123,965.00
		0001	0310	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	20.00	0.00	20.00	EA	6.00	\$200.00	\$1,200.00
		0001	0320	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	950.00	0.00	950.00	LF	950.00	\$31.05	\$29,497.50
		0001	0330	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	925.00	0.00	925.00	LF	0.00	\$9.13	\$0.00
		0001	0340	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$1,703,557.90	\$1,277,668.42
		0001	0350	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	8,898.00	0.00	8,898.00	LF	0.00	\$6.00	\$0.00
		0001	0360	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	7,744.00	0.00	7,744.00	LF	0.00	\$18.00	\$0.00
		0001	0370	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	507.00	0.00	507.00	LF	0.00	\$18.00	\$0.00
		0001	0380	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	270.00	0.00	270.00	EA	0.00	\$280.00	\$0.00
		0001	0390	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	7.00	0.00	7.00	EA	0.00	\$250.00	\$0.00
		0001	0400	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	11.00	0.00	11.00	EA	0.00	\$400.00	\$0.00
		0001	0410	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	210.00	0.00	210.00	EA	0.00	\$60.00	\$0.00
		0001	0420	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	103,578.00	0.00	103,578.00	LF	0.00	\$0.21	\$0.00
		0001	0430	6205902A	PAINT, TYPE L BEADS	136,049.00	0.00	136,049.00	LF	0.00	\$0.28	\$0.00
		0001	0440	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	15,691.00	0.00	15,691.00	LF	0.00	\$0.28	\$0.00
		0001	0450	6207001	PAVEMENT MARKING REMOVAL	36,360.00	0.00	36,360.00	LF	2,986.00	\$0.75	\$2,239.50
		0001	0460	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	23,129.00	0.00	23,129.00	LF	9,736.00	\$0.75	\$7,302.00
		0001	0470	6209901	MISC.PAVEMENT MARKING REMOVAL WITHIN CONCRETE SURFACES	1.00	0.00	1.00	LS	0.00	\$15,000.00	\$0.00
		0001	0480	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0001	0490	6209902	MISC.18 INCH WHITE ISLAND TUBULAR MARKER	105.00	0.00	105.00	EA	0.00	\$90.00	\$0.00
		0001	0500	6209902	MISC.18 INCH YELLOW ISLAND TUBULAR MARKER	179.00	0.00	179.00	EA	0.00	\$90.00	\$0.00

Revision 5/29/2025 Page 7 of 36



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					d on Report Generated date and can differ from the pos							
Contract	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241115- F03	J6S3283	0001	0510	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	320,972.00	0.00	320,972.00	SQYD	0.00	\$2.75	\$0.00
		0001	0520	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	64.40	0.00	64.40	STA	0.00	\$200.00	\$0.00
		0001	0530	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$62,000.00	\$31,000.00
		0001	0540	8031000A	TURF TYPE TALL FESCUE SODDING	17,632.00	0.00	17,632.00	SQYD	3,990.00	\$11.00	\$43,890.00
		0001	0550	8061006	ALTERNATE DITCH CHECK	888.00	0.00	888.00	LF	0.00	\$5.00	\$0.00
		0001	0560	8061007A	CURB INLET CHECK	217.00	0.00	217.00	EA	0.00	\$75.00	\$0.00
		0001	0570	8061016	SEDIMENT REMOVAL	453.00	0.00	453.00	CUYD	0.00	\$1.00	\$0.00
		0001	0580	8061017	TEMPORARY SEEDING	2.00	0.00	2.00	ACRE	0.00	\$3,500.00	\$0.00
		0001	0590	8061019	SILT FENCE	27,098.00	0.00	27,098.00	LF	400.00	\$0.45	\$180.00
		0010	0600	6061060	MGS GUARDRAIL	4,898.00	0.00	4,898.00	LF	4,012.50	\$27.50	\$110,343.75
		0010	0610	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	19.00	0.00	19.00	EA	11.00	\$4,200.00	\$46,200.00
		0010	0620	6061074	MGS HEIGHT AND BLOCK TRANSITION	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0010	0630	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,800.00	\$1,800.00
		0010	0640	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	24.00	0.00	24.00	EA	20.00	\$3,800.00	\$76,000.00
		0020	0650	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	97.00	0.00	97.00	LF	58.00	\$14.00	\$812.00
		0020	0660	9015010	TRENCHING TYPE I	5,255.00	0.00	5,255.00	LF	2,851.00	\$4.00	\$11,404.00
		0020	0670	9016110	PULL BOX, PREFORMED CLASS 1	46.00	0.00	46.00	EA	31.00	\$1,150.00	\$35,650.00
		0020	0680	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	3,660.00	0.00	3,660.00	LF	0.00	\$0.80	\$0.00
		0020	0690	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	5,620.00	0.00	5,620.00	LF	2,746.00	\$5.00	\$13,730.00
		0020	0700	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	55.00	0.00	55.00	EA	37.00	\$970.00	\$35,890.00
		0020	0710	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	0.00	\$1,285.00	\$0.00
		0020	0720	9019902	MISC.240 VOLT POWER SUPPLY WITH SINGLE POWER METERING, 4 LIGHTING CONTRACTORS AND PHOTOCELL LIGHTING CONNECTION	15.00	0.00	15.00	EA	2.00	\$10,500.00	\$21,000.00
		0020	0730	9019902	MISC.30 FT. TOP MOUNT LIGHTING POLE	55.00	0.00	55.00	EA	0.00	\$2,590.00	\$0.00
		0020	0740	9019902	MISC.45 FT. TOP MOUNT LIGHT POLE	4.00	0.00	4.00	EA	0.00	\$3,145.00	\$0.00
		0020	0750	9019902	MISC.TOP MOUNTED LED - A LUMINAIRE	55.00	0.00	55.00	EA	0.00	\$660.00	\$0.00
		0020	0760	9019902	MISC.TOP MOUNTED LED - B LUMINAIRE	9.00	0.00	9.00	EA	0.00	\$720.00	\$0.00
		0020	0770	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	2,963.00	0.00	2,963.00	LF	2,762.00	\$24.00	\$66,288.00
		0030	0780	9020213	SIGNAL HEAD, TYPE 3S	22.00	0.00	22.00	EA	0.00	\$940.00	\$0.00
		0030	0790	9020214	SIGNAL HEAD, TYPE 4S	1.00	0.00	1.00	EA	0.00	\$1,055.00	\$0.00
		0030	0800	9020513	SIGNAL HEAD, TYPE 3B	125.00	0.00	125.00	EA	0.00	\$1,160.00	\$0.00
		0030	0810	9020514	SIGNAL HEAD, TYPE 4B	35.00	0.00	35.00	EA	0.00	\$1,300.00	\$0.00
		0030	0820	9020515	SIGNAL HEAD, TYPE 5B	1.00	0.00	1.00	EA	0.00	\$1,850.00	\$0.00
		0030	0830	9020833	SH-FLAT SHEET - SIGNAL SIGN	964.00	0.00	964.00	SQFT	0.00	\$31.00	\$0.00
		0030	0840	9020834	SIGNAL SIGN, MOUNTING HARDWARE	103.00	0.00	103.00	EA	0.00	\$31.00	\$0.00
		0030	0850	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	9.00	0.00	9.00	EA	0.00	\$350.00	\$0.00
		0030	0860	9022708	POST, SIGNAL 8 FT.	41.00	0.00	41.00	EA	2.00	\$1,050.00	\$2,100.00
		0030	0870	9022715	POST, SIGNAL 15 FT.	2.00	0.00	2.00	EA	0.00	\$1,550.00	\$0.00
		0030	0880	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	0.00	\$9,580.00	\$0.00
		0030	0890	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$10,390.00	\$0.00
		0030	0900	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	4.00	0.00	4.00	EA	0.00	\$12,435.00	\$0.00
		0030	0910	9023145	POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$12,470.00	\$0.00
		0030	0920	9023215	POST, TYPE C, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	0.00	\$7,700.00	\$0.00
		0030	0930	9023220	POST, TYPE C, 20 FT. ARM OR 6.1 M ARM	3.00	0.00	3.00	EA	0.00	\$7,735.00	\$0.00
		0030	0940	9023225	POST, TYPE C, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	0.00	\$8,790.00	\$0.00
		0030	0950	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	6.00	0.00	6.00	EA	0.00	\$9,950.00	\$0.00
		0030	0960	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	6.00	0.00	6.00	EA	0.00	\$10,160.00	\$0.00
		0030	0970	9023240	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	11.00	0.00	11.00	EA	0.00	\$11,200.00	\$0.00
		0030	0980	9023245	POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	8.00	0.00	8.00	EA	0.00	\$11,385.00	\$0.00
		0030	0990	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	7.00	0.00	7.00	EA	0.00	\$11,855.00	\$0.00
		0030	1000	9023255	POST, TYPE C, 55 FT. ARM	2.00	0.00	2.00	EA	0.00	\$13,420.00	\$0.00
		0030	1010	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	1.00	0.00	1.00	EA	0.00	\$18,150.00	\$0.00
		0030	1020	9023345	POST, TYPE B, LONGEST ARM 45 FT. OR 13.7 M	1.00	0.00	1.00	EA	0.00	\$18,490.00	\$0.00
		0030	1030	9023350	POST, TYPE B, LONGEST ARM 50 FT. OR 15.2 M	1.00	0.00	1.00	EA	0.00	\$19,400.00	\$0.00
		0030	1040	9023440	POST, TYPE BL, LONGEST ARM 40 FT. OR 12.2 M	1.00	0.00	1.00	EA	0.00	\$19,400.00	\$0.00

Revision 5/29/2025 Page 8 of 36



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract ID	Project No.	Category	Line No.	Item Code	d on Report Generated date and can differ from the poste Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
241115-	J6S3283	0030	1060	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	21.00	0.00	21.00	EA	Qty 17.00	\$18,680.00	\$317,560.00
F03		0030	1070	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	3,647.00	0.00	3,647.00	LF	2,601.00	\$17.00	\$44,217.00
		0030	1080	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	4,523.00	0.00	4,523.00	LF	3,847.00	\$29.00	\$111,563.00
		0030	1090	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	810.00	0.00	810.00	LF	0.00	\$0.80	\$0.00
		0030	1100	9028206	CABLE, 6 AWG 1 CONDUCTOR, POWER	3,730.00	0.00	3,730.00	LF	2,320.00	\$1.75	\$4,060.00
		0030	1110	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,020.00	0.00	1,020.00	LF	20.00	\$1.30	\$26.00
		0030	1120	9028308	CABLE, 16 AWG 2 CONDUCTOR	11,500.00	0.00	11,500.00	LF	231.00	\$0.50	\$115.50
		0030	1130	9028310	CABLE, 16 AWG 5 CONDUCTOR	11,580.00	0.00	11,580.00	LF	235.00	\$1.50	\$352.50
		0030	1140	9028311	CABLE, 16 AWG 7 CONDUCTOR	42,175.00	0.00	42,175.00	LF	2,400.00	\$2.00	\$4,800.00
		0030	1150	9028811	PULL BOX, PREFORMED CLASS 2	54.00	0.00	54.00	EA	35.00	\$1,785.00	\$62,475.00
		0030	1160	9028812	PULL BOX, PREFORMED CLASS 3	16.00	0.00	16.00	EA	12.00	\$2,500.00	\$30,000.00
		0030	1170	9029100	BASE, CONCRETE	236.70	0.00	236.70	CUYD	160.31	\$1,575.00	\$252,488.25
		0030	1180	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE & PROGRAMMING	1.00	0.00	1.00	LS	0.25	\$24,000.00	\$6,000.00
		0030	1190	9029902	MISC.ATC TRAFFIC SIGNAL CONTROLLER	21.00	0.00	21.00	EA	1.00	\$5,250.00	\$5,250.00
		0030	1200	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON AND SIGNING WITH VERBAL WALK MESSAGE	68.00	0.00	68.00	EA	0.00	\$865.00	\$0.00
		0030	1210	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	21.00	0.00	21.00	EA	17.50	\$19,680.00	\$344,400.00
		0030	1220	9029902	MISC.COUTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	68.00	0.00	68.00	EA	2.00	\$730.00	\$1,460.00
			1230	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	21.00	0.00	21.00	EA	1.00	\$1,435.00	\$1,435.00
		0030	1240	9029902	MISC.PEDESTRIAN PUSH BUTTON STANCHION 4.5 FT.	2.00	0.00	2.00	EA	0.00	\$975.00	\$0.00
		0030	1250	9029902	MISC.SINGAL AHEAD SIGN WITH SOLAR	1.00	0.00	1.00	EA	0.00	\$780.00	\$0.00
		0030	1260	9029902	MISC.SL DISTRICT TRAFFIC SIGNAL DETECTION	21.00	0.00	21.00	EA LF	1.00	\$39,320.00	\$39,320.00
		0040	1270	9109903 9031270A	MISC.CCTV CAMERA CABLE 2 IN. PSST POST - 12 GA	1,760.00	0.00	1,760.00	LF	0.00	\$1.85 \$32.00	\$0.00 \$0.00
		0040	1290	9031270A 9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	1,537.00 124.00	0.00	1,537.00	EA	0.00	\$250.00	\$0.00
		0040	1300	9031271A 9035004A	SH-FLAT SHEET	37.00	0.00	37.00	SQFT	0.00	\$250.00	\$0.00
		0040	1310	9039902	MISC.BOLT DOWN SIGN BASE PLATE	26.00	0.00	26.00	EA	0.00	\$200.00	\$0.00
		0040	1320	9039902	MISC.REMOVE AND RELOCATE EXISTING SIGN	124.00	0.00	124.00	EA	0.00	\$125.00	\$0.00
		0050	1330	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	1,930.00	0.00	1,930.00	LF	114.00	\$11.00	\$1,254.00
		0050	1340	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	694.00	0.00	694.00	LF	614.00	\$22.00	\$13,508.00
		0050	1350	9108816	PULL BOX, PREFORMED CLASS 5	5.00	0.00	5.00	EA	3.00	\$3,190.00	\$9,570.00
		0050	1360	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$4,470.00	\$0.00
		0050	1370	9109901	MISC.REMOVAL OF EXISTING FIBER OPTIC CABLE	1.00	0.00	1.00	LS	0.00	\$2,100.00	\$0.00
		0050	1380	9109902	MISC.CCTV CAMERA ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$2,725.00	\$0.00
		0050	1390	9109902	MISC.CCTV EXTENSION POLE, 20 FT. METALLIC FINISH	12.00	0.00	12.00	EA	0.00	\$725.00	\$0.00
		0050	1400	9109902	MISC.FIBER OPTIC FUSION SPLICE	110.00	0.00	110.00	EA	4.00	\$90.00	\$360.00
		0050	1410	9109902	MISC.FIBER OPTIC JUMPER	72.00	0.00	72.00	EA	4.00	\$38.00	\$152.00
		0050	1420	9109902	MISC.FIBER OPTIC PIGTAIL	110.00	0.00	110.00	EA	4.00	\$19.00	\$76.00
		0050	1430	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$1,065.00	\$0.00
		0050	1440	9109902	MISC.INSTALL CONDUIT INTO EXISTING BOX	2.00	0.00	2.00	EA	0.00	\$270.00	\$0.00
		0050	1450	9109902	MISC.INSTALL MODOT FURNISHED IP ADDRESSABLE POWER STRIP	7.00	0.00	7.00	EA	0.00	\$110.00	\$0.00
		0050	1460	9109902	MISC.INSTALL OR RELOCATE EXISTING & NEW COMMUNICATION EQUIPMENT	21.00	0.00	21.00	EA	1.00	\$425.00	\$425.00
		0050	1470	9109902	MISC.REMOVE AND RELOCATE EXISTING CCTV CAMERA	7.00	0.00	7.00	EA	0.00	\$1,085.00	\$0.00
		0050	1480	9109902	MISC.REMOVE-IN-PAVEMENT WIRELESS DETECTION SYSTEM PER INTERSECTION	8.00	0.00	8.00	EA	0.00	\$1,740.00	\$0.00
		0050	1490	9109902	MISC.WALL MOUNTED INTERCONNECT CENTER	18.00	0.00	18.00	EA	1.00	\$490.00	\$490.00
		0050	1500	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	4,075.00	0.00	4,075.00	LF	0.00	\$2.20	\$0.00
		0055	1510	2063000	CLASS 3 EXCAVATION	51.00	0.00	51.00	CUYD	0.00	\$0.01	\$0.00
		0055	1520	6042010	ADJUSTING MANHOLE	53.00	0.00	53.00	EA	13.00	\$500.00	\$6,500.00
		0055	1530 1540	6042020 7250312A	ADJUSTING BASIN OR INLET	128.00	-46.00 0.00	82.00 58.00	EA LF	0.00	\$650.00 \$153.00	\$0.00
		0055	1540	7250312A 7319902	12 IN. PIPE GROUP B MISC.REPLACE EXISTING CURB INLET TOP	58.00 6.00	0.00	58.00 6.00	EA.	1.00	\$153.00 \$1,300.00	\$7,038.00 \$1,300.00
		0055	1560	7319902	MISC.REPLACE EXISTING CURB INLET TOP WITH GRATE INLET TOP	2.00	0.00	2.00	EA	0.00	\$2,100.00	\$0.00
		0055	1570	7319902	MISC.REPLACE EXISTING GRATE INLET & SIDE INTAKE TOP	8.00	0.00	8.00	EA	4.00	\$2,600.00	\$10,400.00
		0055	1580	7319902	MISC.REPLACE EXISTING GRATE INLET & SIDE INTAKE TOP	5.00	46.00	51.00	EA	45.00	\$2,000.00	\$10,400.00
		0055	1590	7319902	MISC.REPLACE EXISTING GRATE INLET TOP MISC.REPLACE EXISTING MANHOLE TOP	12.00	0.00	12.00	EA	0.00	\$1,000.00	\$94,500.00
			.000	. 0 / 0002	I D. IOL D. III O INVINITIONE TOT	12.00	0.00	12.00		0.00	ψ1,000.00	Ψ0.00

Revision 5/29/2025 Page 9 of 36



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
	J6S3283	0055	1610	7319903	MISC.MSD PCC DOUBLE STREET INLET	5.00	0.00	5.00	LF	5.00	\$1,200.00	\$6,000.00
)3		0055	1620	7319903	MISC.MSD PCC SINGLE STREET INLET - 42" BASE	5.00	0.00	5.00	LF	0.00	\$1,050.00	\$0.00
		0060	1630	6049902	MISC.ADJUSTING GAS VALVE TO GRADE	25.00	0.00	25.00	EA	5.00	\$50.00	\$250.0
		0060	1640	6049902	MISC.ADJUSTING PULL BOX TO GRADE	35.00	0.00	35.00	EA	1.00	\$500.00	\$500.0
		0060	1650	6049902	MISC.ADJUSTING TELEPHONE MANHOLE TO GRADE	18.00	0.00	18.00	EA	0.00	\$500.00	\$0.0
		0060	1660	6049902	MISC.ADJUSTING WATER VALVE TO GRADE	44.00	0.00	44.00	EA	10.00	\$150.00	\$1,500.0
		0070	1670	6239905	MISC.Epoxy Urethane Polymer Wearing Surface with Healer Sealer	2,070.00	0.00	2,070.00	SQYD	1,242.00	\$36.75	\$45,643.5
		0070	1680	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	50.00	0.00	50.00	SQFT	5.00	\$237.00	\$1,185.0
		0070	1690	7040104	HALF-SOLE REPAIR	425.00	0.00	425.00	SQFT	113.80	\$139.00	\$15,818.2
		0070	1700	7040163	CONCRETE CRACK FILLER	404.00	0.00	404.00	SQYD	250.00	\$21.00	\$5,250.0
		0070	1710	7049903	MISC.Barrier Curb Repair	5.00	0.00	5.00	LF	0.00	\$600.00	\$0.0
		0070	1720	7173002	SILICONE EXPANSION JOINT SEALANT	40.00	0.00	40.00	LF	64.00	\$19.00	\$1,216.0
		0071	1730	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	14.00	0.00	14.00	SQFT	7.00	\$400.00	\$2,800.0
		0071	1740	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,026.00	0.00	11,026.00	SQFT	6,616.00	\$22.00	\$145,552.0
		0071	1750	5031010A	BRIDGE APPROACH SLAB (MAJOR)	329.00	0.00	329.00	SQYD	0.00	\$325.00	\$0.0
		0071	1760	7033009	AESTHETIC CONCRETE STAIN	1.00	0.00	1.00	LS	0.00	\$10,200.00	\$0.0
		0071	1770	7034212	SLAB ON STEEL	1,225.00	0.00	1,225.00	SQYD	0.00	\$505.00	\$0.0
		0071	1780	7034219A	TYPE D BARRIER	329.00	0.00	329.00	LF	0.00	\$140.00	\$0.0
		0071	1790	7040101	SUBSTRUCTURE REPAIR (FORMED)	50.00	0.00	50.00	SQFT	0.00	\$168.00	\$0.0
		0071	1800	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	45.00	0.00	45.00	SQFT	0.00	\$152.00	\$0.0
		0071	1810	7061070	MECHANICAL BAR SPLICE	472.00	0.00	472.00	EA	0.00	\$60.00	\$0.
		0071	1820	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,200.00	\$0.0
		0050	5001	9109903	MISC.MoDOT ITS In-Ground Facility Relocation	0.00	370.00	370.00	LF	370.00	\$15.75	\$5,827.
		0050	5002	9109902	MISC.Relocate MoDOT ITS Pull Box	0.00	2.00	2.00	EA	2.00	\$3,547.95	\$7,095.
		0030	5003	9028500	CABLE, LOOP DETECTOR, IN DUCT	0.00	610.00	610.00	LF	610.00	\$8.50	\$5,185.0
		0001	5004	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	0.00	351.00	351.00	LF	351.00	\$9.00	\$3,159.0
		0001	5005	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	0.00	190.00	190.00	EA	190.00	\$7.00	\$1,330.
		0001	5006	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	0.00	72.00	72.00	EA	72.00	\$4.00	\$288.
		0001	5007	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	0.00	235.00	235.00	SQYD	235.00	\$300.00	\$70,500.
		0001	5008	4019901	MISC.ASPHALT PAVEMENT PATCHING	0.00	1.00	1.00	LS	1.00	\$7,723.00	\$7,723.
		0001	5009	2029905	MISC.REMOVALS REMOVAL OF IMPROVEMENTS	0.00	482.00	482.00	SQYD	0.00	\$63.00	\$0.
		0001	5010	5041000	CONCRETE APPROACH PAVEMENT	0.00	650.00	650.00	SQYD	0.00	\$180.60	\$0.0
	Duniont I	683283 - To	tal Valuo	Posted to D	Date as of Report Generated Date							\$6.325.902.

Page 10 of 36 Revision 5/29/2025



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. Project: J6S3283

	: J6S3283	December -	DWD	DWD	Destina	O th	Links	I confirm	F	0#4	т.	Offset/	0
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	7/18/25	7/22/25	- 1	0.02	LS	All across the J6S3283 Jobsite.	105+56		537+95.23		
			7/25/25	7/30/25	1	0.02	LS	All Across the J6S3283 Jobsite.	105+56		537+95.23		
			8/1/25	8/4/25	1	0.02	LS	All Across the J6S3283 Jobsite.	105+56		537+96		
0020	2079909	MISC. GRADING	7/23/25	7/29/25	1	10.00	STA	Carolynn Drive to Concord School Road right of centerline.	274+10	RT	283+70	RT	
			7/25/25	7/30/25	1	4.00	STA	@ Baptist Church Intersection	259+00	RT			
			7/31/25		1		STA	Baptist Church Grading at NE and SE corners.	259+00	LT / RT			
			8/1/25	8/4/25	1	1.00	STA	Graded Sidewalk at First Collinsville Bank.	267+00	LT	268+00	LT	
0040	3040504	TYPE 5 AGGREGATE FOR BASE	7/16/25	7/17/25	1	18.30	SQYD		274+28.61	RT	274+60	RT	
							001/10	corner of the Concord School Road Intersection.	000 15				
				7/17/25	2	79.50	SQYD	East Concord Right Turn Lane, Bottom Half. (8" Pavement)	266+45	LT	266+60	LT	
			7/17/25	7/21/25	1	66.70	SQYD	Sidewalk @ Parcel 32; Executive Office Suites LLC	268+70	LT	269+90	LT	
				7/21/25	2	5.60	SQYD	Sidewalk at the Southwest corner of Baptist Church	259+20	RT			
				7/21/25	3	25.00	SQYD	Intersection @ the old right turn lane. Top Entrance Approach for BP Gas Station; 2nd	264+83	LT			
				1721720		20.00	Ourb	Approach. (7" Approach)	204-00				
				7/21/25	4	7.80	SQYD	South of the BP Gas Station 2nd Approach. (Curb and Gutter)	265+10	LT	265+30	LT	
			7/18/25	7/22/25	1	16.10	SQYD	Northwest Corner of Concord School Rd. (Sidewalk)	273+00	RT	273+29	RT	
				7/22/25	2			Bottom Entrance Approach for Executive Office Suites,	270+17	LT			
								LLC (7" Approach)					
				7/22/25	3	24.60	SQYD	Bottom Entrance Approach for BP Gas Station, 2nd Approach (7" Approach)	264+83	LT			
				7/22/25	4	3.10	SQYD	Slump Inlet on Concord, Northwest Corner of Concord	273+20	RT			
								School Rd. (8" Pavement)					
				7/22/25	5	41.60	SQYD	Curb and Gutter for in between two BP Gas Station Approaches.	263+30	LT	264+30	LT	
			7/22/25	7/24/25	1	35.80	SQYD	Top Entrance Approach for Executive Office Suites. (7"	270+17	LT			
				7/04/0=	-	00.00	0017	Approach)	272.0-	1.7			
				7/24/25	2	20.00	SQYD	Bottom Exit Approach for Timberline Place Properties, LLC (7" Approach)	272+05	LT			
				7/24/25	3	38.30	SQYD	Southwest Corner of Baptist Church Rd. (4" Sidewalk)	259+10	RT	259+80	RT	
				7/24/25	4	44.70	SQYD	Between Baptist Church Rd heading to BP Gas Station. (Curb and Gutter)	259+15	LT	260+30	LT	
			7/23/25	7/29/25	1	22.50	SOYD	Back Half North, Half of Timberline Place Properties, LLC	272+05	LT			
			1123/23	1120120		22.30	JQID	(7" Approach)	272.03				
				7/29/25	2	19.60	SQYD	Front Half, North Half of Simko LLC Entrance. (7" Approach)	264+83	LT			
				7/29/25	3	28 50	SOYD	Front Half, North Half of Juengel Drive. (8" Concrete)	276+30	LT			
				7/29/25	4			East Concord Center Lane.	266+60	LT			
				7/29/25	5			North of the BP Gas Station 2nd Approach.	264+50	LT	264+60	LT	
			7/24/25	7/30/25	1	38.50	SQYD	North of Juengel heading towards Concord School Road.	275+80	LT	274+80	LT	
								(Curb and Gutter)					
				7/30/25	2			Back half, North half of Juengel Drive. (8" Pavement)	276+30	LT			
				7/30/25	3	53.30	SQYD	Remaining center lane of East Concord Lane. (8" Pavement)	266+60	LT			
				7/30/25	4	24.60	SQYD	Back half, North half of BP Gas Station 2nd Approach. (7"	264+82	LT			
			7/05/05	7/00/05	1	40.00	COVE	Approach)	074.00	1.7	070.00	1.7	
			//25/25	7/30/25	1	42.00	SQYD	North of Timberline Place Properties LLC Approach (Curb and Gutter)	271+90	LT	270+82	LT	
				7/30/25	2	24.40	SQYD	Back half, North half of First Collinsville Bank Approach	268+38	LT			
				7/30/25	3	22.00	SQYD	(7" Approach) Cut through crosswalks @ East Concord LT Offset (8"	266+60	LT			
				7730723	3	22.00	3010	Concrete)	200+00	LI			
				7/30/25	4	84.70	SQYD	North of the BP Gas Station 2nd Approach heading towards the 1st Approach. (4" Sidewalk)	263+35	LT	264+62	LT	
			7/28/25	7/30/25	1	10.90	SOYD	Remaining Curb and Gutter North of Timberline Plane	270+50	LT	270+78	LT	
			7720720	7700720		10.00	CQID	Properties, LLC	270.00		210110		
				7/30/25	2			Front half, North half of Juengel Drive. (8" Concrete)	276+30	LT			
				7/30/25	3	71.90	SQYD	Front half, North half of First Collinsville Bank. (7" Approach)	268+38	LT			
			7/29/25	8/3/25	1	29.30	SQYD	Back half, south half of Juengel Drive. (8" Pavement)	276+30	LT			
				8/3/25	2			Small Section of East Concord @ Right Turn Lane (8"	266+60	LT			
				0101				Pavement)					
				8/3/25	3			Front 1/2, South 1/2 of Timberline Place Properties	272+05	LT			
			7/30/25	8/3/25	1			North 1/2, back 1/2 of First Collinsville Bank Back 1/2, South 1/2 of Timberline Place Properties	270+17 272+05	LT			
			1/30/25	8/4/25	2			North 1/2, Front 1/2 of First Collinsville Bank.	272+05	LT			
				8/4/25	3			Inbound Lane of East Concord Intersection.	266+60	LT			
			7/31/25		1	48.20		South of Timberline Place Properties to Concord School	272+05	LT	273+70	LT	
								Road Intersection. (Curb and Gutter)					
				8/4/25	2			South of MJE heading to Angels Arms. (Curb and Gutter)	277+77	LT	278+40	LT	
				8/4/25	3	30.30	SQYD	South of East Concord heading to First Collinsville Bank. (Curb and Gutter)	268+38	LT	266+60	LT	
				8/4/25	4	21.00	SQYD	Front 1/2, South 1/2 of MJE Approach. (7* Approach)	277+77	LT			
				8/4/25	5	22.50	SQYD	East Concord Entrance Lane. (8" Pavement)	266+60	LT			
			8/1/25	8/4/25	1	15.00	SQYD	Back 1/2, South 1/2 of MJE Approach. (7" Approach)	277+17	LT			
				8/4/25	2	29.30	SQYD	All of the Susan Evan Approach (7" Approach)	279+82	LT			
				8/4/25	3			North of the Susan Evan Approach. (Curb and Gutter)	279+56	LT	279+82	LT	
				8/4/25	4			East Concord Entrance Lane, East Section (8" Pavement)	266+60	LT			
				8/4/25	5	52.60	SQYD	North of East Concord Approach to the 2nd BP Gas Station Approach. (4" Sidewalk)	264+82	LT	266+00	LT	
0050	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	7/29/25	8/3/25	1	45.60	SQYD	Final Lane of Baptist Church Intersection.	259+00	RT			
0110	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)		7/17/25	1			East Concord Right Turn Lane, Bottom Half.	266+45	LT	266+60	LT	
				7/22/25	1		SQYD	Slump Inlet on Concord, Northwest Corner of Concord	273+20	RT			
			7/00/0=	7/00/05		20.50	001/5	School Rd.	276.00	1.7			
			//23/25	7/29/25 7/29/25	1			Front Half, North Half of Juengel Drive.	276+30 266+60	LT			
					1			East Concord Center Lane. Back half, North half of Juengel Drive.	276+30	LT			
			7/24/25			-1.00	20010	, rectar has or eaenger brive.	210.00				
			7/24/25			53.30	SQYD	Remaining center lane of East Concord Lane.	266+60	LT			
				7/30/25 7/30/25	3			Remaining center lane of East Concord Lane. Cut through crosswalks @ East Concord LT Offset	266+60 266+60	LT LT			

Revision 6/5/2025 Page 11 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line		elow this line is supplemental to the Estimat											
Number	Item Code	Description	DWR Date	DWR Approval	Posting Sequence	Quantity Posted	Units	Location	From Station/	Offset/ Distance	To Station/	Offset/ Distance	Comments
0110	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	7/29/25	Date	No.	20.20	COVD	Back half, south half of Juengel Drive.	Log Mile 276+30	LT	Log Mile		
3110	3021100	CONCRETE FAVEMENT (6 IN. NON-REINF)	1128123	8/3/25	2			Small Section of East Concord @ Right Turn Lane	266+60	LT			
			7/30/25		1	70.30		Inbound Lane of East Concord Intersection.	266+60	LT			
			7/31/25		1			East Concord Entrance Lane.	266+60	LT			
			8/1/25	8/4/25	1	13.20	SQYD	East Concord Entrance Lane, East Section	266+60	LT			
0120	5021111	CONCRETE PAVEMENT (11 IN. NON-REINF)	7/29/25	8/3/25	1	45.60	SQYD	Final Lane of Baptist Church Intersection.	259+00	RT			
0140	6081012	TRUNCATED DOMES	7/16/25	7/17/25	1	10.00	SQFT	Curb Ramp #99, Southwest Corner of Concord School Rd. Intersection	274+28.61	RT			
			7/17/25	7/21/25	1	10.00	SQFT	Curb Ramp #78, Southwest corner of Baptist Church	259+08.57	RT			
			1111123	1121123		10.00	JUFI	Intersection.	239+06.57	KI			
				7/21/25	2	10.00	SQFT	Curb Ramp #83, Old Right Turn Lane @ Baptist Church	259+42.43				
				7/21/25	3			Curb Ramp #97, Northwest corner of Concord School Rd.	273+54.14				
				7/30/25	1			Cut through crosswalks @ East Concord LT Offset	266+60	LT			
0150	6083006	6 IN. CONCRETE MEDIAN STRIP	7/25/25	7/30/25	1	17.80	SQYD	Southwest corner of Concord School Road between ramps.	274+10	RT			
0170	6085007	PAVED APPROACH, 7 IN.	7/17/25	7/21/25	- 1	25.00	SQYD	Top Entrance Approach for BP Gas Station; 2nd	264+83	LT			
			7/10/25	7/22/25	1	14.40	eovn	Approach. Bottom Entrance Approach for Executive Office Suites,	270+17	LT			
			7710/25	1122123	· ·	14.40	OQID	LLC	270.17				
				7/22/25	2	24.60	SQYD	Bottom Entrance Approach for BP Gas Station, 2nd Approach	264+83	LT			
			7/22/25	7/24/25	1	35.80	SOYD	Top Entrance Approach for Executive Office Suites.	270+17	LT			
				7/24/25	2			Bottom Exit Approach for Timberline Place Properties,	272+05	LT			
								LLC					
			7/23/25	7/29/25	1			Back Half North, Half of Timberline Place Properties, LLC	272+05	LT			
			7/04/0=	7/29/25	2			Front Half, North Half of Simko LLC Entrance.	264+83	LT			
				7/30/25	1	24.60		Back half, North half of BP Gas Station 2nd Approach. Back half, North half of First Collinguille Bank Approach	264+82	LT			
				7/30/25 7/30/25	1	24.40 71.90		Back half, North half of First Collinsville Bank Approach Front half, North half of First Collinsville Bank.	268+38 268+38	LT			
				8/3/25	1	13.90		Front 1/2, South 1/2 of Timberline Place Properties	272+05	LT			
				8/3/25	2			North 1/2, back 1/2 of First Collinsville Bank	270+17	LT			
			7/30/25		1			Back 1/2, South 1/2 of Timberline Place Properties	272+05	LT			
				8/4/25	2	36.40	SQYD	North 1/2, Front 1/2 of First Collinsville Bank.	270+17	LT			
			7/31/25	8/4/25	1	21.00	SQYD	Front 1/2, South 1/2 of MJE Approach.	277+77	LT			
			8/1/25	8/4/25	1	15.00	SQYD	Back 1/2, South 1/2 of MJE Approach.	277+77	LT			
				8/4/25	2			All of the Susan Evan Approach	279+82	LT			
0180	6086004	CONCRETE SIDEWALK, 4 IN.	7/16/25	7/17/25	1	18.30	SQYD	Sidewalk attached to Curb Ramp #99, in the Southwest corner of the Concord School Road Intersection.	274+28.61	RT	274+60	RT	
			7/17/25	7/21/25	1	66.70	SQYD	Sidewalk @ Parcel 32; Executive Office Suites LLC	268+70	LT	269+90	LT	
				7/21/25	2	5.60	SQYD	Sidewalk at the Southwest corner of Baptist Church	259+20	RT			
								Intersection @ the old right turn lane.					
				7/22/25	1			Northwest Corner of Concord School Rd.	273+00	RT	273+29	RT	
				7/24/25	1			Southwest Corner of Baptist Church Rd. North of the BP Gas Station 2nd Approach heading	259+10 263+35	RT LT	259+80 264+62	RT LT	
			1123123	1130123	· ·	04.70	OQID	towards the 1st Approach.	203133		204.02		
			8/1/25	8/4/25	1	52.60	SQYD	North of East Concord Approach to the 2nd BP Gas Station Approach.	264+82	LT	266+00	LT	
0190	6089902	MISC. CONCRETE	7/16/25	7/17/25	1	1.00	EA	Curb Ramp #99, Southwest Corner of Concord School	274+28.61	RT			
								Rd. Intersection					
			7/17/25	7/21/25	1	1.00	EA	Curb Ramp #78, Southwest corner of Baptist Church Intersection.	259+08.57	RT			
				7/21/25	2	1.00	EA	Curb Ramp #83, Old Right Turn Lane @ Baptist Church	259+42.43	RT			
				7/21/25	3	1.00	EA	Curb Ramp #97, Northwest corner of Concord School Rd.	273+54.14	RT			
			7/28/25	7/30/25	- 1	1.00	EA	Curb Ramp #94, South of Executive Office Suites	270+30.6	LT			
			8/1/25	8/4/25	1	1.00	EA	Approach Concrete Curb Ramp #89, North of the First Collinsville	268+13.32	LT			
			8/1/25	8/4/25	1	1.00	EA	Bank Approach.	208+13.32	LI			
0200	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	7/16/25	7/17/25	1	41.00	LF	East Concord Right Turn Lane, Bottom Half.	266+45	LT	266+60	LT	
			7/18/25	7/22/25	1	10.00	LF	Slump Inlet on Concord, Northwest Corner of Concord School Rd.	273+20	RT			
			7/24/25	7/30/25	1	18.00	LF	Back half, North half of Juengel Drive.	276+30	LT			
				8/3/25	1								
						15.00	LF	Small Section of East Concord @ Right Turn Lane	266+60	LT			
			7/31/25	8/4/25	1	15.00 28.00		Small Section of East Concord @ Right Turn Lane East Concord Entrance Lane.	266+60 266+60	LT LT			
			7/31/25 8/1/25	8/4/25 8/4/25			LF						
0210	6091052	CURB AND GUTTER TYPE B	8/1/25		1	28.00	LF LF	East Concord Entrance Lane.	266+60	LT	265+30	LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25	8/4/25	1	28.00 25.00	LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station	266+60 266+60	LT LT		LT LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25	8/4/25 7/21/25 7/22/25	1 1 1	28.00 25.00 20.00 107.00	LF LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches.	266+60 266+60 265+10 263+30	LT LT LT LT	264+30	LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25 7/22/25	8/4/25 7/21/25	1 1	28.00 25.00 20.00 107.00 115.00	LF LF LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station.	266+60 266+60 265+10 263+30 259+15	LT LT LT LT LT	264+30 260+30		
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25	8/4/25 7/21/25 7/22/25 7/24/25	1 1 1 1	28.00 25.00 20.00 107.00 115.00 10.00	LF LF LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches.	266+60 266+60 265+10 263+30	LT LT LT LT	264+30 260+30	LT LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25	1 1 1 1 1	28.00 25.00 20.00 107.00 115.00 10.00	LF LF LF LF LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach.	266+60 266+60 265+10 263+30 259+15 264+50	LT LT LT LT LT LT LT LT	264+30 260+30 264+60 274+80	LT LT LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25 7/25/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25 7/30/25	1 1 1 1 1 1	28.00 25.00 20.00 107.00 115.00 10.00 99.00	LF LF LF LF LF LF LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of J	266+60 266+60 265+10 263+30 259+15 264+50 275+80	LT	264+30 260+30 264+60 274+80 270+82	LT LT LT LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25 7/25/25 7/28/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25 7/30/25 7/30/25 7/30/25	1 1 1 1 1 1 1 1	28.00 25.00 20.00 107.00 115.00 10.00 99.00 108.00 28.00	LF LF LF LF LF LF LF LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Cutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 270+50		264+30 260+30 264+60 274+80 270+82 270+78	LT LT LT LT LT LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25 7/25/25 7/28/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25 7/30/25 7/30/25	1 1 1 1 1 1 1 1 1	28.00 25.00 20.00 107.00 115.00 10.00 99.00 108.00	LF LF LF LF LF LF LF LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of J	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90	LT	264+30 260+30 264+60 274+80 270+82 270+78	LT LT LT LT LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25 7/25/25 7/28/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25 7/30/25 7/30/25 7/30/25	1 1 1 1 1 1 1 1	28.00 25.00 20.00 107.00 115.00 10.00 99.00 108.00 28.00	LF LF LF LF LF LF LF LF LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties LC Concord School	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 270+50		264+30 260+30 264+60 274+80 270+82 270+78 273+70	LT LT LT LT LT LT	
0210	6091052	CURB AND GUTTER TYPE B	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25 7/25/25 7/28/25	8/4/25 7/21/25 7/22/25 7/22/25 7/29/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 20.00 107.00 115.00 99.00 108.00 28.00 124.00 36.00 78.00	LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School Road intersection. South of Mate Heading to Angels Arms. South of Mate heading to Angels Arms.	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 270+50 272+05 277+77 266+60		264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38		
			8/1/25 7/17/25 7/18/25 7/18/25 7/22/25 7/23/25 7/24/25 7/28/25 7/31/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 2 2 3 3 1 1	28.00 25.00 20.00 107.00 115.00 99.00 108.00 28.00 124.00 36.00 78.00	LF	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School Road in Timberline Plane Properties, LLC South of MLB heading to Angels Arms. South of MLB heading to Angels Arms. South of East Concord heading to First Collinsville Bank. North of the Susan Evan Approach.	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 272+05 272+05 277+77 266+60 279+56	ш ш ш ш ш ш ш ш ш ш	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82		
0540	8031000A	TURF TYPE TALL FESCUE SODDING	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25 7/25/25 7/31/25 8/1/25 7/18/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 2 2 3 3 1 1 1 1	28.00 25.00 20.00 107.00 115.00 99.00 108.00 28.00 124.00 36.00 78.00 227.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of the BP Gas Station 2nd Approach. North of Junegel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School Road Intersection. South of Multiple Station Station South of Station Station South of Station Station South of Station Station Station Station South of Station S	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 270+50 272+05 277+77 266+60 279+56 210+53	LT L	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00	LT L	
			8/1/25 7/17/25 7/18/25 7/18/25 7/22/25 7/23/25 7/24/25 7/28/25 7/31/25	8/4/25 7/21/25 7/22/25 7/22/25 7/24/25 7/29/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 20.00 107.00 115.00 99.00 108.00 28.00 124.00 36.00 78.00 227.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Cutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School South of MIE heading to Angels Arms. South of East Concord heading to First Collinsville Bank. North of the Susan Evan Approach. South of Ms West Boneyard to St. Simon Ct. PS to PB A1 at Tesson Rise.	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 270+50 272+05 277+77 266+60 279+56 210+53 398+43	LT L	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 398+69	LT L	
0540 0660	8031000A 9015010	TURF TYPE TALL FESCUE SODDING TRENCHING TYPE I	8/1/25 7/17/25 7/18/25 7/18/25 7/22/25 7/23/25 7/28/25 7/28/25 7/31/25 8/1/25 8/1/25	8/4/25 7/21/25 7/22/25 7/22/25 7/22/25 7/29/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 107.00 115.00 10.00 99.00 28.00 124.00 36.00 78.00 227.00 49.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Cutter for in between two BP Gas Station. Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School Road Intersection. South of Wile heading to Angels Arms. South of Wile Leading to Angels Arms. South of the Susan Evan Approach. South of the Susan Evan Approach. South of the NB West Boneyard to St. Simon Ct. PS to PB A1 at Tesson Rise.	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 272+05 277+77 266+60 279+56 210+53 398+43 399+46		264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 398+69 399+84	LT L	
0540	8031000A	TURF TYPE TALL FESCUE SODDING	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25 7/25/25 7/31/25 8/1/25 7/18/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 107.00 115.00 10.00 99.00 99.00 28.00 124.00 36.00 78.00 227.00 27.00 49.00 27.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School Road Intersection. South of MLB heading to Angels Arms. South of MLB heading to Angels Arms. South of the Susan Evan Approach. South of the Susan Evan Approach. South of the Station Rise. PB A2 to A102 at Tesson Rise PS to PB A1 at Tesson Rise	266+60 266+60 265+10 263+30 259+15 264+50 277+90 270+50 272+05 277+77 266+60 279+56 210+53 398+43 399+46		264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 398+69 399+84 398+69	LT L	
0540 0660	8031000A 9015010	TURF TYPE TALL FESCUE SODDING TRENCHING TYPE I	8/1/25 7/17/25 7/18/25 7/18/25 7/22/25 7/23/25 7/28/25 7/28/25 7/31/25 8/1/25 8/1/25	8/4/25 7/21/25 7/22/25 7/22/25 7/29/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 107.00 115.00 10.00 99.00 108.00 28.00 124.00 36.00 78.00 227.00 27.00 49.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Junegel heading towards Concord School Road. North of Junegel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of MLE heading to Angels Arms. South of MLE heading to Angels Arms. South of MLE heading to Angels Arms. South of the NB West Boneyard to St. Simon Ct. PS to PB A1 at Tesson Rise. PB A2 to A102 at Tesson Rise	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 270+50 272+05 277+77 266+60 279+56 210+53 398+43 399+48	LT L	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 398+69 399+84		
0540 0660	8031000A 9015010	TURF TYPE TALL FESCUE SODDING TRENCHING TYPE I	8/1/25 7/17/25 7/18/25 7/18/25 7/22/25 7/23/25 7/28/25 7/28/25 7/31/25 8/1/25 8/1/25	8/4/25 7/21/25 7/22/25 7/24/25 7/29/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 107.00 115.00 108.00 28.00 124.00 36.00 78.00 227.00 27.00 49.00 93.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Cutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School Road Intersection. South of MaE heading to Angels Arms. South of East Concord heading to First Collinsville Bank. North of the Susan Evan Approach. South of Ba Station Rise. PB A 2 to A 102 at Tesson Rise PB A 2 to A 102 at Tesson Rise PB A 2 to A 102 at Tesson Rise	266+60 266+60 265+10 263+30 259+15 264+50 275+80 271+90 270+50 272+05 277+77 266+60 279+56 210+53 398+43 398+43 399+46 398+69	LT L	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 398+69 399+84 399+84 399+84		
0540 0660 0690	8031000A 9015010 9017407	TURF TYPE TALL FESCUE SODDING TRENCHING TYPE I CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/24/25 7/28/25 7/31/25 8/1/25 8/1/25 8/1/25	8/4/25 7/21/25 7/22/25 7/22/25 7/29/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 107.00 115.00 10.00 99.00 108.00 28.00 124.00 26.00 27.00 49.00 99.00 113.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Cutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties. LLC South of Timberline Place Properties to Concord School Road Intersection. South of MJE heading to Angels Arms. South of MJE heading to Angels Arms. South of the Suan Evan Approach. South of the Suan Evan Approach. South of the Suan Evan Approach. PS to PB A1 at Tesson Rise PB A2 to A102 at Tesson Rise A101 to PB A2 at Tesson Rise A101 to PB A2 at Tesson Rise A101 to PB A4 at Tesson Rise	266+60 266+60 265+10 263+30 259+15 264+50 271+90 270+50 272+05 277+77 266+60 279+56 210+53 398+43 399+46 399+43 399+46 399+69	LT L	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 398+69 399+84 399+84 399+84		
0540 0660	8031000A 9015010 9017407	TURF TYPE TALL FESCUE SODDING TRENCHING TYPE I CABLE-CONDUIT, 1 IN., 2 CONDUCTORS CONTROLLER ASSEMBLY HOUSING,	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/28/25 7/28/25 7/31/25 8/1/25 8/1/25	8/4/25 7/21/25 7/22/25 7/22/25 7/22/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 107.00 115.00 10.00 99.00 28.00 124.00 27.00 49.00 27.00 49.00 99.00 113.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School Road intersection. South of Mab Heading to Angels Arms. South of Mab Heading to Angels Arms. South of the Susan Evan Approach. South of the NB West Boneyard to St. Simon Ct. PS to PB A1 at Tesson Rise. PB A2 to A102 at Tesson Rise PB A2 to A102 at Tesson Rise PB A1 to PB A2 at Tesson Rise PB A1 to PB A2 at Tesson Rise PB A1 to PB A2 at Tesson Rise A101 to PB A2 at Tesson Rise Set Cabinet, Route 21 @ East Concord Rd.	266+60 266+60 265+10 263+30 259+15 264+50 270+50 272+05 277+77 266+60 279+56 210+53 398+43 399+46 398+43 399+69 398+59 266+53	UT U	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 398+69 399+84 399+84 399+84 399+84		
0540 0660 0690	8031000A 9015010 9017407	TURF TYPE TALL FESCUE SODDING TRENCHING TYPE I CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/28/25 7/28/25 7/31/25 8/1/25 8/1/25	8/4/25 7/21/25 7/22/25 7/22/25 7/29/25 7/30/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 107.00 115.00 10.00 99.00 108.00 28.00 124.00 26.00 27.00 49.00 99.00 113.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of MIE heading to Angels Arms. South of MIE heading to Angels Arms. South of East Concord heading to First Collinsville Bank. North of the Susan Evan Approach. South of the NB West Boneyard to St. Simon Ct. PS to PB A1 at Tesson Rise. PS to PB A1 at Tesson Rise PS A1 to PB A2 at Tesson Rise PS A1 to PB A2 at Tesson Rise A101 to PB A1 at Tesson Rise. Set Cabinet, Route 21 @ East Concord Rd. Controller to PB 1, Route 21 @ Northbound I-270 Ramps	266+60 266+60 265+10 263+30 259+15 264+50 271+90 270+50 272+05 277+77 266+60 279+56 210+53 398+43 399+46 399+43 399+46 399+69	UT U	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 398+69 399+84 399+84 399+84 399+84	LT	
0540 0660 0690	8031000A 9015010 9017407	TURF TYPE TALL FESCUE SODDING TRENCHING TYPE I CABLE-CONDUIT, 1 IN., 2 CONDUCTORS CONTROLLER ASSEMBLY HOUSING,	8/1/25 7/17/25 7/18/25 7/22/25 7/23/25 7/28/25 7/28/25 7/31/25 8/1/25 8/1/25	8/4/25 7/21/25 7/22/25 7/22/25 7/29/25 7/30/25 7/30/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25 8/4/25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28.00 25.00 107.00 115.00 10.00 99.00 124.00 36.00 27.00 49.00 27.00 49.00 93.00 113.00 30.00	LF L	East Concord Entrance Lane. East Concord Entrance Lane, East Section South of the BP Gas Station 2nd Approach. Curb and Gutter for in between two BP Gas Station Approaches. Between Baptist Church Rd heading to BP Gas Station. North of the BP Gas Station 2nd Approach. North of Juengel heading towards Concord School Road. North of Timberline Place Properties LLC Approach Remaining Curb and Gutter North of Timberline Plane Properties, LLC South of Timberline Place Properties to Concord School Road intersection. South of Mab Heading to Angels Arms. South of Mab Heading to Angels Arms. South of the Susan Evan Approach. South of the NB West Boneyard to St. Simon Ct. PS to PB A1 at Tesson Rise. PB A2 to A102 at Tesson Rise PB A2 to A102 at Tesson Rise PB A1 to PB A2 at Tesson Rise PB A1 to PB A2 at Tesson Rise PB A1 to PB A2 at Tesson Rise A101 to PB A2 at Tesson Rise Set Cabinet, Route 21 @ East Concord Rd.	266+60 266+60 265+10 263+30 259+15 264+50 270+50 270+50 272+05 277+77 266+60 279+56 210+53 398+43 399+46 398+43 398+49 398+69 398+59 398+69 398+69 398+69 398+69 398+69 398+69 398+69 398+69 398+59 266+53 292+57	UT U	264+30 260+30 264+60 274+80 270+82 270+78 273+70 278+40 268+38 279+82 206+00 399+84 399+84 399+84 399+84 399+84 399+84 292+69	LT L	

Revision 6/5/2025 Page 12 of 36



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1070	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	7/16/25		5	22.00		Controller to PB 1, Route 21 @ Walden Ridge Dr.	484+21	RT	484+21	RT	
			7/25/25		1		LF	PB 2 to Post 1, Route 21 @ Schuessler Road	336+61	LT	336+55	LT	
				7/30/25	2		LF	PB 2 to Post 2, Route 21 @ Schuessler Road	336+61	LT	336+71	LT	
				7/30/25	3	22.00		PB 2 to Post 3, Route 21 @ Schuessler Road	336+61	LT	336+79	LT	
				7/30/25	4		LF LF	PB 3 to Post 4, Route 21 @ Schuessler Road	337+34	LT	337+30	LT	
			7/00/05	7/30/25	5			PB 3 to Post 5, Route 21 @ Schuessler Road	337+34	LT	337+48 258+25	RT	
			7/30/25		1	23.00		PB 4 to Post 10, Route 21 @ Baptist Church Rd.	258+09 258+09	RT	258+25	RT	
			7/31/25	8/4/25	2	10.00	LF	PB 4 to Post 8, Route 21 @ Baptist Church Road. PB 4 to Post 9, Route 21 @ Baptist Church Road.	258+09	RT RT	258+10	RT	
			8/1/25	8/4/25	1		I.F.	Controller to PB 1 at Mattis Road	308+09	LT	308+27	IT	
1080	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE		7/17/25	1	61.00		PB 4 to PB 3, Route 21 @ Tesson Rise Drive / Cedar	398+87	RT	399+49	RT	
1000	3027300	CONDOTT, STIV., I GOTTED WITH TRACER WIRE	7710/23	1111123	· ·	01.00	Li	Plaza Parkway	330107	IXI	388148	IXI	
				7/17/25	2	82.00	LF	PB 1 to PB 2, Route 21 @ Suson Hills Drive	440+98	RT	441+82	RT	
				7/17/25	3	43.00	LF	PB 2 to Post 2, Route 21 @ Suson Hills Drive	441+82	RT	441+67	RT	
			7/17/25	7/21/25	1	43.00	LF	PB 1 to PB 2, Route 21 @ Schuessler Rd.	336+35	LT	336+61	LT	
			7/18/25	7/22/25	1		LF	PB 2 to PB 3, Route 21 @ Schuessler Rd.	336+61	LT	337+34	LT	
			7/22/25	7/24/25	1	102.00	LF	PB 3 to PB 4, Route 21 @ Schuessler Rd.	337+34	LT	337+60	RT	
			7/23/25	7/29/25	1	75.00	LF	PB 1 to PB 4, Route 21 @ Schuessler Road.	337+60	RT	336+83	RT	
				7/29/25	2	106.00	LF	PB 1 to PB 4, Route 21 @ Kennerly Road.	317+25	LT	317+32	RT	
			7/28/25	7/30/25	1	114.00	LF	PB 1 to PB 3, Route 21 @ Kennerly Road	317+25	LT	318+40	LT	
			7/31/25		1	81.00		PB 4 to PB 5, Route 21 @ Kennerly Road.	317+32	RT	318+13	RT	
1110	9028302	CABLE, 12 AWG 2 CONDUCTOR	7/31/25	8/4/25	1	20.00	LF	UPS to PB 1, Route 21 @ Walden Ridge Dr.	484+31	RT	484+21	RT	
1150	9028811	PULL BOX, PREFORMED CLASS 2	7/25/25	7/30/25	1	1.00	EA	Placed PB 3, Route 21 @ Schuessler Road	337+34	LT			
			7/30/25	8/4/25	1	1.00	EA	PB 2, Route 21 @ Revis Rd.	129+61	LT			
			7/31/25	8/4/25	1	1.00	EA	Placed PB 4, Route 21 @ Baptist Church Road.	258+09	RT			
			8/1/25	8/4/25	1	1.00	EA	PB 3 at East Concord.	266+18	48.9 LT			
1160	9028812	PULL BOX, PREFORMED CLASS 3	7/16/25	7/17/25	1	1.00	EA	Installed PB 1, Route 21 @ Old Tesson Ferry Rd.	377+14	LT			
			7/25/25	7/30/25	1	1.00	EA	Placed PB 1, Route 21 @ Schuessler Road	336+35	LT			
1170	9029100	BASE, CONCRETE	7/16/25	7/17/25	1	3.27	CUYD	Poured Post 6, Route 21 @ Baptist Church Road.	258+51	LT			
				7/17/25	2	3.27	CUYD	Poured Post 10, Route 21 @ Baptist Church Road.	258+25	RT			
				7/17/25	3	0.44	CUYD	Poured Post 4, Route 21 @ East Concord Road	266+60	LT			
			7/17/25	7/21/25	1	3.27	CUYD	Poured Post 6, Route 21 @ Baptist Church Rd.	258+51	LT			
				7/21/25	2	3.27	CUYD	., 0 1 1	258+25	RT			
				7/21/25	3	0.44	CUYD	Poured Post 4, Route 21 @ East Concord Rd.	266+60	LT			
			7/18/25	7/22/25	1	3.67	CUYD		266+99	RT			
			7/23/25	7/29/25	1			Poured Post 1, Route 21 @ Schuessler Road.	336+55	LT			
				7/29/25	2		CUYD		337+48	LT			
			7/24/25	7/30/25	1			Poured Post 2, Route 21 @ Schuessler Road	336+71	LT			
				7/30/25	2		CUYD	Poured Post 3, Route 21 @ Schuessler Road	336+79	LT			
				7/30/25	3	0.44		Poured Post 4, Route 21 @ Schuessler Road	337+30	LT			
				7/30/25	4		CUYD		337+45	RT			
				7/30/25	5			Poured Post 9, Route 21 @ Schuessler Road	336+84	RT			
			7/30/25		1	1.93	CUYD		129+69	LT			
1180	9029901	MISC.	7/31/25		1		LS	Across the J6S3283 Jobsite.	105+56		537+96		
1190	9029902	MISC.	7/31/25		1		EA	Route 21 @ Walden Ridge Drive.	484+00	DT			
1210	9029902	MISC.	//17/25	7/21/25	1		EA	Set Cabinet, Route 21 @ East Concord Rd.	266+47	RT LT			
1230	9029902	MISC	7/31/25	7/21/25	2		EA EA	Set Cabinet, Route 21 @ Concord School Rd.	274+29 484+00	LI			
1230	9029902	MISC.	7/31/25		1	1.00		Route 21 @ Walden Ridge Drive.	484+00				
		ADJUSTING MANHOLE			1			Route 21 @ Walden Ridge Drive.		RT			
1520	6042010	ADDOG TING WAINFIOLE	7/30/25	7/30/25	1	1.00		RT Offset of the East Concord Intersection. North 1/2, Front 1/2 of First Collinsville Bank.	266+25 270+17	LT			
1550	7319902	MISC. MANHOLES AND DROP INLETS	7/18/25		1	1.00		Northwest Corner of Concord School Road.	270+17	RT			
1580	7319902	MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS	7/18/25		1	1.00		South of the BP Gas Station 2nd Approach.	265+25	LT			
1300	1313802	MINISTRACTION AND DITTO INCETS	7/18/25		1		EA	In between two BP Gas Station Approaches.	264+00	LT			
			7/23/25		1	1.00		North of the BP Gas Station 2nd Approach.	264+55	LT			
				7/30/25	1	1.00		North of Juengel heading towards Concord School Road	275+75	LT			
			1124123	1130123	'	1.00		located in the Curb and Gutter.	213413	-1			
				7/30/25	1			North of Timberline Place Properties LLC Approach, In the Curb and Gutter	270+75	LT			
			7/30/25	8/4/25	1	1.00	EA	North 1/2, Front 1/2 of First Collinsville Bank.	269+90	LT			
			7/31/25	8/4/25	1	1.00	EA	South of East Concord Intersection located in the Curb and Gutter.	267+25	LT			
1630	6049902	MISC. DRAINAGE ITEM	7/31/25	8/4/25	1	2.00	EA	East Concord Entrance Lane.	266+60	LT			
1660	6049902	MISC. DRAINAGE ITEM	7/17/25	7/21/25	1	1.00	EA	South of the First Collinsville Bank Approach	269+00	LT			
			7/24/25	7/30/25	1	1.00	EA	Back half, North half of Juengel Drive.	276+30	LT			

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 13 of 36



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	0030	MISC. SHAPING SLOPES	Material		3	Feb 18, 2025	SYSTEM	(\$17,500.00)	
					3	Feb 18, 2025	SYSTEM	\$17,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Mar 3, 2025	SYSTEM	(\$22,500.00)	
					4	Mar 3, 2025	SYSTEM	\$22,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$40,000.00)	
					5	Mar 17, 2025	SYSTEM	\$40,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0030 -							\$0.00	
	0040	TYPE 5 AGGREGATE FOR BASE	Material		2	Feb 3, 2025	SYSTEM	(\$1,938.00)	
					2	Feb 3, 2025	SYSTEM	\$1,938.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Feb 18, 2025	SYSTEM	(\$5,787.00)	
					3	Feb 18, 2025	SYSTEM	\$5,787.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Mar 3, 2025	SYSTEM	(\$11,548.20)	
					4	Mar 3, 2025	SYSTEM	\$11,548.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$18,781.20)	
					5	Mar 17, 2025	SYSTEM	\$18,781.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$27,375.60)	
					6	Apr 2, 2025	SYSTEM	\$27,375.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$33,797.40)	
					7	Apr 16, 2025	SYSTEM	\$33,797.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$41,152.20)	
					8	May 2, 2025	SYSTEM	\$41,152.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$50,859.00)	
					9	May 16, 2025	SYSTEM	\$50,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user corrij1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Jun 2, 2025	SYSTEM	(\$60,492.00)	
					10	Jun 2, 2025	SYSTEM	\$60,492.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Jun 16, 2025	SYSTEM	(\$67,996.80)	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J6S3283	0040	TYPE 5 AGGREGATE FOR BASE	Material		11	Jun 16, 2025	SYSTEM	\$67,996.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jul 1, 2025	SYSTEM	(\$77,616.00)	
					12	Jul 1, 2025	SYSTEM	\$77,616.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$84,957.60)	
					13	Jul 16, 2025	SYSTEM	\$84,957.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$93,607.20)	
					14	Aug 4, 2025	SYSTEM	\$93,607.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0040 -	Total						\$0.00	
	0050	TYPE 5 AGGREGATE	Material		10	Jun 2, 2025	SYSTEM	(\$705.10)	
		FOR BASE (6 IN. THICK)			10	Jun 2, 2025	SYSTEM	\$705.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Jun 16, 2025	SYSTEM	(\$2,288.00)	
					11	Jun 16, 2025	SYSTEM	\$2,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Jul 1, 2025	SYSTEM	(\$4,079.90)	
					12	Jul 1, 2025	SYSTEM	\$4,079.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$8,220.30)	
					13	Jul 16, 2025	SYSTEM	\$8,220.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$8,721.90)	
					14	Aug 4, 2025	SYSTEM	\$8,721.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
	0070	T-4-1	Material - To	tal				\$0.00	
	0050 -	CONCRETE	Material		5	Mar 17,	SYSTEM	\$0.00 (\$45,024.00)	
		PAVEMENT (8 IN. NON-REINF)			5	2025 Mar 17,	SYSTEM	\$45,024.00	This adjustment offsets the original system-generated Material Payment
						2025		(444	Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$69,930.00)	
					6	Apr 2, 2025	SYSTEM	\$69,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$79,436.00)	
					7	Apr 16, 2025	SYSTEM	\$79,436.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	May 2,	SYSTEM	(\$105,882.00)	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
83	0110	CONCRETE	Material			2025			
		PAVEMENT (8 IN. NON-REINF)			8	May 2, 2025	SYSTEM	\$105,882.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$145,376.00)	
					9	May 16, 2025	SYSTEM	\$145,376.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user corrij1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Jun 2, 2025	SYSTEM	(\$172,102.00)	
					10	Jun 2, 2025	SYSTEM	\$172,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0110 -	Total						\$0.00	
	0120	CONCRETE PAVEMENT (11	Material		8	May 2, 2025	SYSTEM	(\$2,996.40)	
		IN. NON-REINF)			8	May 2, 2025	SYSTEM	\$2,996.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$4,686.00)	
					9	May 16, 2025	SYSTEM	\$4,686.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrij1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Jun 2, 2025	SYSTEM	(\$13,147.20)	
					10	Jun 2, 2025	SYSTEM	\$13,147.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Jun 16, 2025	SYSTEM	(\$32,142.00)	
					11	Jun 16, 2025	SYSTEM	\$32,142.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Jul 1, 2025	SYSTEM	(\$53,644.80)	
					12	Jul 1, 2025	SYSTEM	\$53,644.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$103,329.60)	
					13	Jul 16, 2025	SYSTEM	\$103,329.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$109,348.80)	
					14	Aug 4, 2025	SYSTEM	\$109,348.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -							\$0.00	
	0130	CONCRETE PAVEMENT (12 IN. NON-REINF)	Material		12	Jul 1, 2025	SYSTEM	(\$7,760.00)	
		()			12	Jul 1, 2025	SYSTEM	\$7,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$7,760.00)	
					13	Jul 16, 2025	SYSTEM	\$7,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	0130	CONCRETE PAVEMENT (12	Material		14	Aug 4, 2025	SYSTEM	(\$7,760.00)	
		IN. NON-REINF)			14	Aug 4, 2025	SYSTEM	\$7,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total			_		01/0==14	\$0.00	
	0140	TRUNCATED DOMES	Material		5	Mar 17, 2025	SYSTEM	(\$2,280.00)	
					5	Mar 17, 2025	SYSTEM	\$2,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$4,626.00)	
					6	Apr 2, 2025	SYSTEM	\$4,626.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$6,483.00)	
					7	Apr 16, 2025	SYSTEM	\$6,483.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$7,023.00)	
					8	May 2, 2025	SYSTEM	\$7,023.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$7,023.00)	
					9	May 16, 2025	SYSTEM	\$7,023.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user corrij1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total						\$0.00	
	0170	PAVED APPROACH, 7	Material		2	Feb 3,			
		IN				2025	SYSTEM	(\$7,854.00)	
		IN.			2		SYSTEM	\$7,854.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		IN.			3	2025 Feb 3,			Estimate Item Adjustment (0002) due to user schirj1 overridding Payment
		IN.				2025 Feb 3, 2025 Feb 18,	SYSTEM	\$7,854.00	Estimate Item Adjustment (0002) due to user schirj1 overridding Payment
		IN.			3	2025 Feb 3, 2025 Feb 18, 2025 Feb 18,	SYSTEM SYSTEM	\$7,854.00 (\$15,510.00)	Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment
		IN.			3	2025 Feb 3, 2025 Feb 18, 2025 Feb 18, 2025 Mar 3,	SYSTEM SYSTEM	\$7,854.00 (\$15,510.00) \$15,510.00	Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment
		IN.			3 3	2025 Feb 3, 2025 Feb 18, 2025 Feb 18, 2025 Mar 3, 2025 Mar 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$7,854.00 (\$15,510.00) \$15,510.00 (\$24,761.00)	Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment
		IN.			3 3 4 4	2025 Feb 3, 2025 Feb 18, 2025 Feb 18, 2025 Mar 3, 2025 Mar 17, 4025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,854.00 (\$15,510.00) \$15,510.00 (\$24,761.00) \$24,761.00	Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment
		IN.			3 3 4 4 5	2025 Feb 3, 2025 Feb 18, 2025 Feb 18, 2025 Mar 3, 2025 Mar 3, 2025 Mar 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,854.00 (\$15,510.00) \$15,510.00 (\$24,761.00) \$24,761.00 (\$33,781.00)	Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment
		IN.			3 3 4 4 5 5	2025 Feb 18, 2025 Feb 18, 2025 Feb 18, 2025 Mar 3, 2025 Mar 17, 2025 Apr 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,854.00 (\$15,510.00) \$15,510.00 (\$24,761.00) \$24,761.00 (\$33,781.00) \$33,781.00	Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment
		IN.			3 3 4 4 5 5 5 6 6	2025 Feb 18, 2025 Feb 18, 2025 Feb 18, 2025 Mar 3, 2025 Mar 17, 2025 Apr 2, 2025 Apr 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,854.00 (\$15,510.00) \$15,510.00 (\$24,761.00) \$24,761.00 (\$33,781.00) \$33,781.00 (\$69,619.00)	Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S3283	0170	PAVED	Material						Estimate Exception 6 on the current Payment Estimate.	
		APPROACH, 7 IN.			8	May 2, 2025	SYSTEM	(\$80,729.00)		
					8	May 2, 2025	SYSTEM	\$80,729.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					9	May 16, 2025	SYSTEM	(\$103,719.00)		
					9	May 16, 2025	SYSTEM	\$103,719.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user corrij1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0170	Total						\$0.00		
	0180	CONCRETE SIDEWALK, 4 IN.	Material		4	Mar 3, 2025	SYSTEM	(\$70,088.00)		
					4	Mar 3, 2025	SYSTEM	\$70,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					5	Mar 17, 2025	SYSTEM	(\$124,072.00)		
					5	Mar 17, 2025	SYSTEM	\$124,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					6	Apr 2, 2025	SYSTEM	(\$152,392.00)		
					6	Apr 2, 2025	SYSTEM	\$152,392.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					7	Apr 16, 2025	SYSTEM	(\$211,232.00)		
					7	Apr 16, 2025	SYSTEM	\$211,232.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					8	May 2, 2025	SYSTEM	(\$259,032.00)		
					8	May 2, 2025	SYSTEM	\$259,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					9	May 16, 2025	SYSTEM	(\$308,584.00)		
					9	May 16, 2025	SYSTEM	\$308,584.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user corrij1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0180 -	Total MISC.	Material		5	Mar 17.	SYSTEM	\$0.00 (\$16,600.00)		
	0.00	CONCRETE	Material			2025 Mar 17,	SYSTEM	\$16,600.00	This adjustment offsets the original system-generated Material Payment	
					5		2025			Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$36,520.00)		
					6	Apr 2, 2025	SYSTEM	\$36,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					7	Apr 16, 2025	SYSTEM	(\$49,800.00)		
					7	Apr 16, 2025	SYSTEM	\$49,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					8	May 2, 2025	SYSTEM	(\$49,800.00)		



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3283	0190	MISC. CONCRETE	Material		8	May 2, 2025	SYSTEM	\$49,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$49,800.00)	
					9	May 16, 2025	SYSTEM	\$49,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user corrij1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Jun 2, 2025	SYSTEM	(\$69,720.00)	
					10	Jun 2, 2025	SYSTEM	\$69,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0190 -	Total						\$0.00	
	0200	CONCRETE CURB (6 IN. HEIGHT AND	Material		4	Mar 3, 2025	SYSTEM	(\$306.00)	
		UNDER)			4	Mar 3, 2025	SYSTEM	\$306.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$1,746.00)	
					5	Mar 17, 2025	SYSTEM	\$1,746.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$2,160.00)	
					6	Apr 2, 2025	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$3,294.00)	
					7	Apr 16, 2025	SYSTEM	\$3,294.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$3,294.00)	
					8	May 2, 2025	SYSTEM	\$3,294.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$4,158.00)	
					9	May 16, 2025	SYSTEM	\$4,158.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user corrij1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					10	Jun 2, 2025	SYSTEM	(\$4,806.00)	
					10	Jun 2, 2025	SYSTEM	\$4,806.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0200 -							\$0.00	
	0210	CURB AND GUTTER TYPE B	Material		2	Feb 3, 2025	SYSTEM	(\$27,174.00)	This adjustment effects the original author are set of Material D
					2	Feb 3, 2025	SYSTEM	\$27,174.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Feb 18, 2025	SYSTEM	(\$88,956.00)	
					3	Feb 18, 2025	SYSTEM	\$88,956.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Mar 3,	SYSTEM	(\$88,956.00)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	0210	CURB AND GUTTER TYPE B	Material			2025			
		GUITER TIPE B			4	Mar 3, 2025	SYSTEM	\$88,956.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$102,690.00)	
					5	Mar 17, 2025	SYSTEM	\$102,690.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$164,745.00)	
					6	Apr 2, 2025	SYSTEM	\$164,745.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$191,373.00)	
					7	Apr 16, 2025	SYSTEM	\$191,373.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$227,661.00)	
					8	May 2, 2025	SYSTEM	\$227,661.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$281,064.00)	
					9	May 16, 2025	SYSTEM	\$281,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user corrij1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0210 -	- Total						\$0.00	
					_				
	0220	INTEGRAL CURB (6 IN. HEIGHT AND	Material		5	Mar 17, 2025	SYSTEM	(\$810.00)	
	0220		Material		5		SYSTEM	(\$810.00) \$810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
	0220	CURB (6 IN. HEIGHT AND	Material			2025 Mar 17,		, ,	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment
	0220	CURB (6 IN. HEIGHT AND	Material		5	2025 Mar 17, 2025 Apr 2,	SYSTEM	\$810.00	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment
	0220	CURB (6 IN. HEIGHT AND	Material		5	2025 Mar 17, 2025 Apr 2, 2025 Apr 2,	SYSTEM SYSTEM	\$810.00 (\$810.00)	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment
	0220	CURB (6 IN. HEIGHT AND	Material		5 6 6	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16,	SYSTEM SYSTEM	\$810.00 (\$810.00) \$810.00	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment
	0220	CURB (6 IN. HEIGHT AND	Material		5 6 6	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16,	SYSTEM SYSTEM SYSTEM	\$810.00 (\$810.00) \$810.00	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment
	0220	CURB (6 IN. HEIGHT AND	Material		5 6 6 7 7	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 May 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$810.00 (\$810.00) \$810.00 (\$810.00)	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment
	0220	CURB (6 IN. HEIGHT AND	Material		5 6 6 7 7 8	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$810.00 (\$810.00) \$810.00 (\$810.00) (\$810.00)	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment
	0220	CURB (6 IN. HEIGHT AND	Material		5 6 6 7 7 8 8	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00 (\$810.00)	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment
	0220	CURB (6 IN. HEIGHT AND	Material		5 6 6 7 7 8 8 8	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00 (\$810.00)	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate.
	0220	CURB (6 IN. HEIGHT AND	Material		5 6 6 7 7 8 8 8 9	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 May 16, 2025 Jun 2,	SYSTEM	\$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate.
	0220	CURB (6 IN. HEIGHT AND	Material	- Total	5 6 6 7 7 8 8 8 9 9	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 Jun 2, 2025 Jun 2,	SYSTEM	\$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00 (\$810.00)	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user corrij1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 19 on the current Payment Estimate.
	0220	CURB (6 IN. HEIGHT AND	Material - To		5 6 6 7 7 8 8 8 9 9	2025 Mar 17, 2025 Apr 2, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 Jun 2, 2025 Jun 2,	SYSTEM	\$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00 (\$810.00) \$810.00 (\$810.00)	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user corrij1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 19 on the current Payment Estimate.



	ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	283	0250		Material	, , , , , , , , , , , , , , , , , , ,	10		SYSTEM	(\$2,160.00)	
1						10		SYSTEM	\$2,160.00	Estimate Item Adjustment (0008) due to user schirj1 overridding Payment
2025 SYSTEM (\$2,190.00) Estimate Exception 7 on the current Payment Estimate Imaging Payme						11		SYSTEM	(\$2,160.00)	
12						11		SYSTEM	\$2,160.00	Estimate Item Adjustment (0004) due to user schirj1 overridding Payment
2025 SYSTEM (\$4,08.00) This adjustment offset be original system-generated Material Payment Estimate System						12		SYSTEM	(\$2,160.00)	
2025 13 2016 54 55 55 55 56 50 10 2025 20						12		SYSTEM	\$2,160.00	Estimate Item Adjustment (0005) due to user schirj1 overridding Payment
## Total ## So 00 Case - Total So 00						13		SYSTEM	(\$4,608.00)	
Material - Total So.00						13		SYSTEM	\$4,608.00	Estimate Item Adjustment (0005) due to user schirj1 overridding Payment
Ox50 - Total Ox50 MISC. Oxfortuction Stockpile Total Oxfortuction Stockpile Total Oxfortuction Oxfortuct										
MSC. PAVEMENT MARKINGS Construction A				Material - To	tal					
PAVEMENT MARKINGS								01/07=11		
Construction Stockpile Total Stockpile STMI		0490	PAVEMENT			4		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile STMI				0 1 11						
Stockpile STMI					Stockpile -		Eab 10	CVCTEM		Doument Estimate Item Adjustment generated Steelenile Transaction
Construction Stockpile STMI - Total \$5,985.00				Stockpile			2025			
Construction Stockpile STMI - Total \$5,985.00						4		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile Substitution Stockpile Substitution Stockpile Substitution Substitution Substitution Stockpile Substitution Substitution Stockpile Substitution Substitution Stockpile Substitution S				Comptunction		TMI Total				
Construction Stockpile Total Stockpile		0490	. Total	Construction	i Stockpile S	I WII - I OLA				
PAVEMENT MARKINGS				Construction		4	Mar 3	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total Construction Stockpile STMI A Mar 3, 2025 4 Mar 3, 2025 5 May 16, SYSTEM S5,101.50 Payment Estimate Item Adjustment generated Stockpile Transaction S5,101.50 D500 - Total S5,101.50 D500 - Total S5,101.50 Material 9 May 16, SYSTEM (\$23,683.00) 9 May 16, SYSTEM \$23,683.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user corril overridding Payment Estimate Exception 20 on the current Payment Estimate. - Total S0.00 D540 - Total S0.00 MGS GUARDRAIL Stockpile 3 Feb 18, SYSTEM (\$16,399.88) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile 3 Feb 18, SYSTEM (\$16,399.88) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Mar 17, SYSTEM (\$19,809.75) Payment Estimate Item Adjustment generated Stockpile Transaction		0000	PAVEMENT		- Total			0.0.2		- Symon Example North Agent Street Fire Control
Construction Stockpile STMI 2025 4 Mar 3, 2025 5 YSTEM \$5,101.50 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total StMI - Total Stockpile StMI - Tot				Construction		Fotal				
STMI 4 Mar 3, 2025 SYSTEM \$5,101.50 Payment Estimate Item Adjustment generated Stockpile Transaction - Total Construction Stockpile STMI - Total S\$10,203.00 S\$1,01.50				Construction	Стотрио			SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Total \$10,203.00						4		SYSTEM	\$5,101.50	Payment Estimate Item Adjustment generated Stockpile Transaction
Stystem Stys					- Total				\$10,203.00	
TURF TYPE TALL FESCUE SODDING Material 9				Construction	Stockpile S	TMI - Tota			\$10,203.00	
TALL FESCUE SODDING 9 May 16, 2025 9 May 16, 2025 1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user corrij1 overridding Payment Estimate Exception 20 on the current Payment Estimate. 1 Total 1 \$0.00 Material - Total		0500 -	- Total						\$5,101.50	
9		0540	TALL FESCUE	Material		9		SYSTEM	(\$23,683.00)	
Solution			SODDING			9		SYSTEM	\$23,683.00	Estimate Item Adjustment (0011) due to user corrij1 overridding Payment
\$0.00 MGS GUARDRAIL Construction Stockpile 4 Mar 3, 2025 SYSTEM (\$4,708.87) Payment Estimate Item Adjustment generated Stockpile Transaction 5 Mar 17, 2025 SYSTEM (\$19,809.75) Payment Estimate Item Adjustment generated Stockpile Transaction					- Total				\$0.00	
0600 MGS GUARDRAIL Construction Stockpile 3 Feb 18, 2025 4 Mar 3, 2025 SYSTEM (\$16,399.88) Payment Estimate Item Adjustment generated Stockpile Transaction 4 Mar 3, 2025 Mar 17, 2025 SYSTEM (\$19,809.75) Payment Estimate Item Adjustment generated Stockpile Transaction				Material - To	tal				\$0.00	
GUARDRAIL Stockpile 2025 4 Mar 3, 2025 5 Mar 17, 2025 SYSTEM (\$4,708.87) Payment Estimate Item Adjustment generated Stockpile Transaction 5 Mar 17, 2025 SYSTEM (\$19,809.75) Payment Estimate Item Adjustment generated Stockpile Transaction										
5 Mar 17, 2025 Payment Estimate Item Adjustment generated Stockpile Transaction		0600					2025		, , ,	, , , , , , , , , , , , , , , , , , ,
2025										, , ,
6 Apr 2, SYSTEM (\$4,871.25) Payment Estimate Item Adjustment generated Stockpile Transaction						5		SYSTEM	(\$19,809.75)	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	0600	MGS	Construction			2025			
		GUARDRAIL	Stockpile		8	May 2, 2025	SYSTEM	(\$6,332.63)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$52,122.38)	
			Construction	Stockpile - 1	Γotal			(\$52,122.38)	
			Construction Stockpile STMI		2	Feb 3, 2025	SYSTEM	\$63,625.02	Payment Estimate Item Adjustment generated Stockpile Transaction
			0.1111	- Total				\$63,625.02	
			Construction	Stockpile S	TMI - Tota			\$63,625.02	
	0600 -	- Total						\$11,502.64	
	0610	MGS BRIDGE APP. TRANS SEC (REG/NO	Construction Stockpile		3	Feb 18, 2025	SYSTEM	(\$6,279.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CURB)			4	Mar 3, 2025	SYSTEM	(\$2,093.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					5	Mar 17, 2025	SYSTEM	(\$6,279.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				Tetal	6	Apr 2, 2025	SYSTEM	(\$8,372.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$23,023.00)	
			Construction	Stockpile - 1				(\$23,023.00)	
			Construction Stockpile STMI		2	Feb 3, 2025	SYSTEM	\$39,767.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$39,767.00	
			Construction	Stockpile S	TMI - Tota			\$39,767.00	
	0610 -	- Total						\$16,744.00	
	0620	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile		5	Mar 17, 2025	SYSTEM	(\$660.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$660.00)	
			Construction	Stockpile - 1	Γotal			(\$660.00)	
			Construction Stockpile STMI		2	Feb 3, 2025	SYSTEM	\$660.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$660.00	
			Construction	Stockpile S	TMI - Tota			\$660.00	
	0620 -	- Total						\$0.00	
	0630	MGS END ANCHOR	Construction Stockpile		6	Apr 2, 2025	SYSTEM	(\$650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$650.00)	
			Construction	Stockpile - 1	Γotal			(\$650.00)	
			Construction Stockpile STMI		2	Feb 3, 2025	SYSTEM	\$650.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$650.00	
			Construction	Stockpile S	TMI - Tota			\$650.00	
	0630 -	- Total						\$0.00	
	0640	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		3	Feb 18, 2025	SYSTEM	(\$9,250.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			4	Mar 3, 2025	SYSTEM	(\$5,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					5	Mar 17, 2025	SYSTEM	(\$12,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Apr 2, 2025	SYSTEM	(\$5,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				Total	8	May 2, 2025	SYSTEM	(\$3,700.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$37,000.00)	
				Stockpile - 1				(\$37,000.00)	
			Construction Stockpile		2	Feb 3, 2025	SYSTEM	\$44,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
283	0640	TYPE A CRASHWORTHY	STMI	- Total				\$44,400.00	
		END TERMINAL (MASH)	Construction	Stockpile S	MI - Total			\$44,400.00	
	0640 -	Total						\$7,400.00	
	0650	CONDUIT, 2 IN. RIGID, IN	Material		7	Apr 16, 2025	SYSTEM	(\$350.00)	
		TRENCH			7	Apr 16, 2025	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$504.00)	
					8	May 2, 2025	SYSTEM	\$504.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0650 -	Total						\$0.00	
	0670	PULL BOX, PREFORMED	Material		3	Feb 18, 2025	SYSTEM	(\$6,900.00)	
		CLASS 1			3	Feb 18, 2025	SYSTEM	\$6,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Mar 3, 2025	SYSTEM	(\$10,350.00)	
					4	Mar 3, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$11,500.00)	
					5	Mar 17, 2025	SYSTEM	\$11,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$11,500.00)	
					6	Apr 2, 2025	SYSTEM	\$11,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$12,650.00)	
					7	Apr 16, 2025	SYSTEM	\$12,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$20,700.00)	
					8	May 2, 2025	SYSTEM	\$20,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0670 -							\$0.00	
	0690	CABLE- CONDUIT, 1 IN., 2	Material		10	Jun 2, 2025	SYSTEM	(\$1,850.00)	
		CONDUCTORS			10	Jun 2, 2025	SYSTEM	\$1,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0690 -	Total						\$0.00	
	0700	POLE FOUNDATION (30 FT. OR 9.0 M	Material		7	Apr 16, 2025	SYSTEM	(\$3,880.00)	
		(30 01. 0.0 191			7	Apr 16, 2025	SYSTEM	\$3,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	0700	POLE FOUNDATION	Material		8	May 2, 2025	SYSTEM	(\$26,190.00)	
		(30 FT. OR 9.0 M			8	May 2, 2025	SYSTEM	\$26,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$29,100.00)	
					9	May 16, 2025	SYSTEM	\$29,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user corrij1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Jun 2, 2025	SYSTEM	(\$29,100.00)	
					10	Jun 2, 2025	SYSTEM	\$29,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Jun 16, 2025	SYSTEM	(\$32,010.00)	
					11	Jun 16, 2025	SYSTEM	\$32,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Jul 1, 2025	SYSTEM	(\$32,010.00)	
					12	Jul 1, 2025	SYSTEM	\$32,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$35,890.00)	
					13	Jul 16, 2025	SYSTEM	\$35,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
	0700	T-4-1	Material - To	tal				\$0.00 \$0.00	
	0700 -	- i otai							
	0720	MISC. HIGHWAY	Material		9	May 16,	SYSTEM	(\$10,500.00)	
	0720	MISC. HIGHWAY LIGHTING	Material		9	May 16, 2025 May 16, 2025	SYSTEM SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate
	0720		Material			2025 May 16, 2025 Jun 2,		(\$10,500.00)	
	0720		Material		9	2025 May 16, 2025	SYSTEM	(\$10,500.00) \$10,500.00	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment
	0720		Material	- Total	9	2025 May 16, 2025 Jun 2, 2025 Jun 2,	SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00)	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment
	0720		Material Material - To		9	2025 May 16, 2025 Jun 2, 2025 Jun 2,	SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment
	0720 -	LIGHTING			9	2025 May 16, 2025 Jun 2, 2025 Jun 2,	SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment
		-Total CONDUIT, 4 IN., PUSHED WITH			9	2025 May 16, 2025 Jun 2, 2025 Jun 2,	SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00 \$0.00	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment
	0720 -	-Total CONDUIT, 4 IN.,	Material - To		9 10 10	2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025	SYSTEM SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00 \$0.00 \$0.00	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment
	0720 -	-Total CONDUIT, 4 IN., PUSHED WITH	Material - To		9 10 10 3	2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Feb 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00 \$0.00 \$0.00 \$0.00 (\$3,000.00)	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment
	0720 -	-Total CONDUIT, 4 IN., PUSHED WITH	Material - To		9 10 10 3 3 3	2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Feb 18, 2025 Feb 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00 \$0.00 \$0.00 \$3,000.00)	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment
	0720 -	-Total CONDUIT, 4 IN., PUSHED WITH	Material - To		9 10 10 3 3 4	2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Feb 18, 2025 Feb 18, 2025 Mar 3, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00 \$0.00 \$0.00 \$3,000.00) \$3,000.00	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment
	0720 -	-Total CONDUIT, 4 IN., PUSHED WITH	Material - To		9 10 10 3 3 4 4 4	2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 2, 2025 Feb 18, 2025 Mar 3, 2025 Mar 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00 \$0.00 \$0.00 \$3,000.00) \$3,000.00 (\$13,080.00) \$13,080.00	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment
	0720 -	-Total CONDUIT, 4 IN., PUSHED WITH	Material - To		9 10 10 3 3 4 4 5	2025 May 16, 2025 Jun 2, 2025 Jun 2, 2025 Feb 18, 2025 Feb 18, 2025 Mar 3, 2025 Mar 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,500.00) \$10,500.00 (\$21,000.00) \$21,000.00 \$0.00 \$0.00 \$3,000.00) \$3,000.00 (\$13,080.00) \$13,080.00 (\$17,400.00)	Estimate Item Adjustment (0013) due to user corrij1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	0770	CONDUIT, 4 IN., PUSHED WITH	Material						Estimate Exception 19 on the current Payment Estimate.
		TRACER WIRE			7	Apr 16, 2025	SYSTEM	(\$24,048.00)	
					7	Apr 16, 2025	SYSTEM	\$24,048.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$32,376.00)	
					8	May 2, 2025	SYSTEM	\$32,376.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0770	- Total						\$0.00	
	0780	SIGNAL HEAD, TYPE 3S	Construction Stockpile STMI		11	Jun 16, 2025	SYSTEM	\$10,191.09	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$10,191.09	
			Construction	Stockpile S	MI - Total			\$10,191.09	
	0780	- Total						\$10,191.09	
	0790	SIGNAL HEAD, TYPE 4S	Construction Stockpile STMI		11	Jun 16, 2025	SYSTEM	\$594.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$594.00	
			Construction	Stockpile S	MI - Total			\$594.00	
	0790	- Total						\$594.00	
	0800	SIGNAL HEAD, TYPE 3B	Construction Stockpile STMI		11	Jun 16, 2025	SYSTEM	\$86,485.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			O T WII	- Total				\$86,485.00	
			Construction	Stockpile S1	MI - Total			\$86,485.00	
	0800 -	- Total						\$86,485.00	
	0810	SIGNAL HEAD, TYPE 4B	Construction Stockpile STMI		11	Jun 16, 2025	SYSTEM	\$28,451.85	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 1 11	- Total				\$28,451.85	
	0040	- Total	Construction	Stockpile S1	IMII - Totai			\$28,451.85 \$28,451.85	
	0820	SIGNAL HEAD,	Construction		11	Jun 16,	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
	0620	TYPE 5B	Stockpile STMI	Total	11	2025	STSTEIN	\$1,163.00	rayment Estimate item Aujustinent generated Stockpile Transaction
			Construction	- Total	IMI Total			\$1,163.00 \$1,163.00	
	0820	- Total	Sonstruction	Stockpile S	-Mi - Total			\$1,163.00	
	0860	POST, SIGNAL 8 FT.	Construction Stockpile		8	May 2, 2025	SYSTEM	\$32,348.01	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$32,348.01	
			Construction	Stockpile S1	ΓΜΙ - Total			\$32,348.01	
			Material		8	May 2, 2025	SYSTEM	(\$2,100.00)	
					8	May 2, 2025	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$2,100.00)	
					9	May 16, 2025	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user corrij1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					10	Jun 2, 2025	SYSTEM	(\$2,100.00)	
					10	Jun 2, 2025	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					11	Jun 16,	SYSTEM	(\$2,100.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	0860	POST, SIGNAL 8 FT.	Material			2025			
		F1.			11	Jun 16, 2025	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Jul 1, 2025	SYSTEM	(\$2,100.00)	
					12	Jul 1, 2025	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$2,100.00)	
					13	Jul 16, 2025	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$2,100.00)	
					14	Aug 4, 2025	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0860 -	Total						\$32,348.01	
	0870	POST, SIGNAL 15 FT.	Construction Stockpile		8	May 2, 2025	SYSTEM	\$2,446.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$2,446.00	
			Construction	Stockpile S	「MI - Total			\$2,446.00	
	0870 -	Total						\$2,446.00	
	1060	CONTROLLER ASSEMBLY	Construction Stockpile		11	Jun 16, 2025	SYSTEM	(\$45,651.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
		HOUSING,			13	Jul 16, 2025	SYSTEM	(\$22,825.83)	Payment Estimate Item Adjustment generated Stockpile Transaction
					14	Aug 4, 2025	SYSTEM	(\$22,825.84)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$91,303.34)	
			Construction	Stockpile - 1	Total			(\$91,303.34)	
			Construction Stockpile		10	Jun 2, 2025	SYSTEM	\$182,606.67	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$182,606.67	
			Construction	Stockpile S1	「MI - Total			\$182,606.67	
			Material		7	Apr 16, 2025	SYSTEM	(\$112,080.00)	
					7	Apr 16, 2025	SYSTEM	\$112,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$112,080.00)	
					8	May 2, 2025	SYSTEM	\$112,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1060 -							\$91,303.33	
	1070	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		4	Mar 3, 2025	SYSTEM	(\$1,445.00)	
					4	Mar 3, 2025	SYSTEM	\$1,445.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$6,664.00)	
					5	Mar 17, 2025	SYSTEM	\$6,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.



ct	Line	Description	Adjustment	Other Adjustment	Est.	Created	Created	Amount	Remarks
22	1070	CONDUIT	Type	Type	Number	Date	Ву	(67 705 00)	
83	1070	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		6	Apr 2, 2025	SYSTEM	(\$7,735.00)	
					6	Apr 2, 2025	SYSTEM	\$7,735.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$8,109.00)	
					7	Apr 16, 2025	SYSTEM	\$8,109.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$8,619.00)	
					8	May 2, 2025	SYSTEM	\$8,619.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1070 -	Total						\$0.00	
	1080	CONDUIT, 3 IN., PUSHED WITH	Material		3	Feb 18, 2025	SYSTEM	(\$1,885.00)	
		TRACER WIRE			3	Feb 18, 2025	SYSTEM	\$1,885.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Mar 3, 2025	SYSTEM	(\$16,037.00)	
					4	Mar 3, 2025	SYSTEM	\$16,037.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$27,637.00)	
					5	Mar 17, 2025	SYSTEM	\$27,637.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$31,349.00)	
					6	Apr 2, 2025	SYSTEM	\$31,349.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$40,310.00)	
					7	Apr 16, 2025	SYSTEM	\$40,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$52,606.00)	
					8	May 2, 2025	SYSTEM	\$52,606.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1080 -							\$0.00	
	1120	CABLE, 16 AWG 2 CONDUCTOR	Material		8	May 2, 2025	SYSTEM	(\$115.50)	
					8	May 2, 2025	SYSTEM	\$115.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1120 -							\$0.00	
	1130	CABLE, 16 AWG 5 CONDUCTOR	Material		8	May 2, 2025	SYSTEM	(\$352.50)	
					8	May 2, 2025	SYSTEM	\$352.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	1130	CABLE, 16 AWG 5 CONDUCTOR	Material	- Total				\$0.00	
	1120	- Total	Material - To	tal				\$0.00 \$0.00	
			Material		3	Feb 18,	SYSTEM	(\$10,710.00)	
		PREFORMED CLASS 2				2025			
					3	Feb 18, 2025	SYSTEM	\$10,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Mar 3, 2025	SYSTEM	(\$19,635.00)	
					4	Mar 3, 2025	SYSTEM	\$19,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$23,205.00)	
					5	Mar 17, 2025	SYSTEM	\$23,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$23,205.00)	
					6	Apr 2, 2025	SYSTEM	\$23,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$23,205.00)	
					7	Apr 16, 2025	SYSTEM	\$23,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$24,990.00)	
					8	May 2, 2025	SYSTEM	\$24,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
		- Total						\$0.00 \$0.00	
	1150 1160	PULL BOX, PREFORMED	Material - To		3	Feb 18, 2025	SYSTEM	\$0.00	
		PULL BOX,			3		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		PULL BOX, PREFORMED				2025 Feb 18,		\$0.00 \$0.00 (\$5,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment
		PULL BOX, PREFORMED			3	2025 Feb 18, 2025 Mar 3,	SYSTEM	\$0.00 \$0.00 (\$5,000.00) \$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment
		PULL BOX, PREFORMED			3	2025 Feb 18, 2025 Mar 3, 2025	SYSTEM SYSTEM	\$0.00 \$0.00 (\$5,000.00) \$5,000.00 (\$10,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment
		PULL BOX, PREFORMED			3 4 4	2025 Feb 18, 2025 Mar 3, 2025 Mar 3, 2025	SYSTEM SYSTEM	\$0.00 \$0.00 (\$5,000.00) \$5,000.00 (\$10,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment
		PULL BOX, PREFORMED			3 4 4 5	2025 Feb 18, 2025 Mar 3, 2025 Mar 3, 2025 Mar 17, 2025 Mar 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$5,000.00) \$5,000.00 (\$10,000.00) (\$10,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment
		PULL BOX, PREFORMED			3 4 4 5 5	2025 Feb 18, 2025 Mar 3, 2025 Mar 3, 2025 Mar 17, 2025 Apr 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$5,000.00) \$5,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment
		PULL BOX, PREFORMED			3 4 4 5 5 6	2025 Feb 18, 2025 Mar 3, 2025 Mar 3, 2025 Mar 17, 2025 Apr 2, 2025 Apr 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$5,000.00) \$5,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) (\$10,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment
		PULL BOX, PREFORMED			3 4 4 5 5 5 6 6 6	2025 Feb 18, 2025 Mar 3, 2025 Mar 3, 2025 Mar 17, 2025 Apr 2, 2025 Apr 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$5,000.00) \$5,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment
		PULL BOX, PREFORMED			3 4 4 5 5 6 6 7 7	2025 Feb 18, 2025 Mar 3, 2025 Mar 3, 2025 Mar 17, 2025 Mar 17, 2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$5,000.00) \$5,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00) \$10,000.00 (\$10,000.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate.



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
33	1160	PULL BOX, PREFORMED	Material						Estimate Exception 35 on the current Payment Estimate.
		CLASS 3		- Total				\$0.00	
			Material - To	tal				\$0.00	
	1160 -	Total						\$0.00	
	1170	BASE, CONCRETE	Material		4	Mar 3, 2025	SYSTEM	(\$3,039.75)	
					4	Mar 3, 2025	SYSTEM	\$3,039.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Mar 17, 2025	SYSTEM	(\$10,505.25)	
					5	Mar 17, 2025	SYSTEM	\$10,505.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$20,317.50)	
					6	Apr 2, 2025	SYSTEM	\$20,317.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$46,824.75)	
					9	May 16, 2025	SYSTEM	\$46,824.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user corrij't overridding Payment Estimate Exception 25 on the current Payment Estimate.
					10	Jun 2, 2025	SYSTEM	(\$80,435.25)	
					10	Jun 2, 2025	SYSTEM	\$80,435.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Paymen Estimate Exception 20 on the current Payment Estimate.
					11	Jun 16, 2025	SYSTEM	(\$106,501.50)	
					11	Jun 16, 2025	SYSTEM	\$106,501.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Paymen Estimate Exception 11 on the current Payment Estimate.
					12	Jul 1, 2025	SYSTEM	(\$168,572.25)	
					12	Jul 1, 2025	SYSTEM	\$168,572.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Paymen Estimate Exception 19 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$208,734.75)	
					13	Jul 16, 2025	SYSTEM	\$208,734.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Paymen Estimate Exception 16 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$252,488.25)	
					14	Aug 4, 2025	SYSTEM	\$252,488.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Paymen Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1170 -							\$0.00	
	1190	MISC.	Construction Stockpile STMI		14	Aug 4, 2025	SYSTEM	\$85,500.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$85,500.00	
			Construction	1 Stockpile S	ГМI - Total			\$85,500.00	
	1190 -	Total						\$85,500.00	
	1210	MISC.	Material		4	Mar 3, 2025	SYSTEM	(\$9,840.00)	
					4	Mar 3, 2025	SYSTEM	\$9,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Mar 17,	SYSTEM	(\$19,680.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	1210	MISC.	Material			2025			
					5	Mar 17, 2025	SYSTEM	\$19,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$49,200.00)	
					6	Apr 2, 2025	SYSTEM	\$49,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$49,200.00)	
					7	Apr 16, 2025	SYSTEM	\$49,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$49,200.00)	
					8	May 2, 2025	SYSTEM	\$49,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1210 -	Total						\$0.00	
	1220	MISC.	Construction Stockpile		9	May 16, 2025	SYSTEM	\$27,540.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$27,540.00	
			Construction	Stockpile S	ΓΜΙ - Total			\$27,540.00	
			Material		8	May 2, 2025	SYSTEM	(\$1,460.00)	
					8	May 2, 2025	SYSTEM	\$1,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1220 -	Total						\$27,540.00	
	1230	MISC.	Construction Stockpile		14	Aug 4, 2025	SYSTEM	(\$1,169.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,169.00)	
			Construction	Stockpile - 1	Γotal			(\$1,169.00)	
			Construction Stockpile STMI		10	Jun 2, 2025	SYSTEM	\$24,549.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$24,549.00	
			Construction	Stockpile S	ГМI - Total			\$24,549.00	
		Total						\$23,380.00	
	1260	MISC.	Construction Stockpile		14	Aug 4, 2025	SYSTEM	(\$39,320.86)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$39,320.86)	
			Construction	Stockpile - 1	Γotal			(\$39,320.86)	
			Construction Stockpile STMI		7	Apr 16, 2025	SYSTEM	\$206,604.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTWI		9	May 16, 2025	SYSTEM	\$464,163.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$670,767.00	
			Construction	Stockpile S	ГМI - Total			\$670,767.00	
	1260 -	Total						\$631,446.14	
	1280	2 IN. PSST POST - 12 GA.	Construction Stockpile		4	Mar 3, 2025	SYSTEM	(\$15,262.41)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$15,262.41)	
			Construction	Stockpile - 1				(\$15,262.41)	
			Construction		3	Feb 18,	SYSTEM	\$15,262.41	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	20	200011741011	Туре	Adjustment Type	Number	Date	Ву	, undun	, containe
6S3283	1280	2 IN. PSST	Stockpile	, , , , , , , , , , , , , , , , , , ,		2025			
		POST - 12 GA.	STMI		4	Mar 3,	SYSTEM	\$15,262.41	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total		2025		\$30,524.82	
			Construction	Stockpile S	ΓΜΙ - Total			\$30,524.82	
	1280 -	- Total		Отосприо				\$15,262.41	
	1290	DRIVEN POST	Construction		4	Mar 3,	SYSTEM	(\$6,336.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
		ANCHOR FOR 2 IN. PSST - 12	Stockpile			2025			· · · ·
		GA.		- Total				(\$6,336.40)	
				Stockpile - 1			0.10==11	(\$6,336.40)	
			Construction Stockpile		3	Feb 18, 2025	SYSTEM	\$6,336.40	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI		4	Mar 3, 2025	SYSTEM	\$6,336.40	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$12,672.80	
			Construction	Stockpile S	ΓΜΙ - Total			\$12,672.80	
	1290 -	- Total						\$6,336.40	
	1300	SH-FLAT SHEET	Construction Stockpile		4	Mar 3, 2025	SYSTEM	(\$366.30)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$366.30)	
			Construction	Stockpile - 1	Γotal			(\$366.30)	
			Construction Stockpile		3	Feb 18, 2025	SYSTEM	\$366.30	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI		4	Mar 3, 2025	SYSTEM	\$366.30	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$732.60	
			Construction	Stockpile S	ΓΜΙ - Total			\$732.60	
	1300 -	- Total						\$366.30	
	1310	MISC.	Construction Stockpile		4	Mar 3, 2025	SYSTEM	(\$3,276.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$3,276.00)	
			Construction	Stockpile - 1	Γotal			(\$3,276.00)	
			Construction Stockpile STMI		3	Feb 18, 2025	SYSTEM	\$3,276.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII		7	Apr 16, 2025	SYSTEM	\$3,276.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$6,552.00	
			Construction	Stockpile S	ΓΜΙ - Total			\$6,552.00	
		- Total						\$3,276.00	
	1330	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Material		6	Apr 2, 2025	SYSTEM	(\$242.00)	
					6	Apr 2, 2025	SYSTEM	\$242.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Apr 2, 2025 Apr 16, 2025	SYSTEM	\$242.00 (\$605.00)	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment
						2025 Apr 16,			Estimate Item Adjustment (0022) due to user schirj1 overridding Payment
					7	2025 Apr 16, 2025 Apr 16,	SYSTEM	(\$605.00)	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment
					7	Apr 16, 2025 Apr 16, 2025 Apr 16, 2025	SYSTEM SYSTEM	(\$605.00) \$605.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment
				- Total	7 7 8	2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 2,	SYSTEM SYSTEM SYSTEM	(\$605.00) \$605.00 (\$792.00)	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment
			Material - Tol		7 7 8	2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 2,	SYSTEM SYSTEM SYSTEM	(\$605.00) \$605.00 (\$792.00) \$792.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment
	1330 -	- T otal	Material - To		7 7 8	2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 2,	SYSTEM SYSTEM SYSTEM	(\$605.00) \$605.00 (\$792.00) \$792.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3283	1340	PUSHED WITH TRACER WIRE	Material			2025			
		TRACEIT WINE			5	Mar 17, 2025	SYSTEM	\$6,292.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$6,292.00)	
					6	Apr 2, 2025	SYSTEM	\$6,292.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$9,218.00)	
					7	Apr 16, 2025	SYSTEM	\$9,218.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$9,218.00)	
					8	May 2, 2025	SYSTEM	\$9,218.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1340 -	Total						\$0.00	
	1350	PULL BOX, PREFORMED	Material		5	Mar 17, 2025	SYSTEM	(\$3,190.00)	
		CLASS 5			5	Mar 17, 2025	SYSTEM	\$3,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					6	Apr 2, 2025	SYSTEM	(\$3,190.00)	
					6	Apr 2, 2025	SYSTEM	\$3,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$3,190.00)	
					7	Apr 16, 2025	SYSTEM	\$3,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$6,380.00)	
					8	May 2, 2025	SYSTEM	\$6,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1350 -	Total MISC. ITS	Material		13	Jul 16,	SYSTEM	\$0.00 (\$360.00)	
			aronar		13	2025 Jul 16,	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment
						2025		(*****	Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$360.00)	
					14	Aug 4, 2025	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1400 -							\$0.00	
	1410	MISC. ITS	Material		13	Jul 16, 2025	SYSTEM	(\$152.00)	
					13	Jul 16, 2025	SYSTEM	\$152.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	1410	MISC. ITS	Material		14	Aug 4, 2025	SYSTEM	(\$152.00)	
					14	Aug 4, 2025	SYSTEM	\$152.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total						\$0.00	
	1420	MISC. ITS	Material		13	Jul 16, 2025	SYSTEM	(\$76.00)	
					13	Jul 16, 2025	SYSTEM	\$76.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$76.00)	
					14	Aug 4, 2025	SYSTEM	\$76.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1420 -	- Total						\$0.00	
	1460	MISC. ITS	Material		13	Jul 16, 2025	SYSTEM	(\$425.00)	
					13	Jul 16, 2025	SYSTEM	\$425.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$425.00)	
					14	Aug 4, 2025	SYSTEM	\$425.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total	Matarial		40	Int 40	OVOTEM	\$0.00	
	1490	MISC. ITS	Material		13	Jul 16, 2025	SYSTEM	(\$490.00)	
					13	Jul 16, 2025	SYSTEM	\$490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					13		SYSTEM	\$490.00 (\$490.00)	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment
						2025 Aug 4,		(\$490.00)	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment
				- Total	14	2025 Aug 4, 2025 Aug 4,	SYSTEM	(\$490.00) \$490.00	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment
			Material - To		14	2025 Aug 4, 2025 Aug 4,	SYSTEM	(\$490.00) \$490.00 \$0.00	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment
		- Total			14	2025 Aug 4, 2025 Aug 4, 2025	SYSTEM SYSTEM	(\$490.00) \$490.00 \$0.00 \$0.00	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment
		-Total 12 IN. PIPE CULVERT GROUP B	Material - To		14 14 12	2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025	SYSTEM SYSTEM SYSTEM	(\$490.00) \$490.00 \$0.00 \$0.00 \$0.00 (\$7,038.00)	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		12 IN. PIPE CULVERT			14 14 12 12	2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	(\$490.00) \$490.00 \$0.00 \$0.00 \$0.00 (\$7,038.00)	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment
		12 IN. PIPE CULVERT			14 14 12	2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM	(\$490.00) \$490.00 \$0.00 \$0.00 \$0.00 (\$7,038.00)	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment
		12 IN. PIPE CULVERT			14 14 12 12	2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 1, 2025 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$490.00) \$490.00 \$0.00 \$0.00 \$0.00 (\$7,038.00)	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment
		12 IN. PIPE CULVERT			14 14 12 12	2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$490.00) \$490.00 \$0.00 \$0.00 (\$7,038.00) \$7,038.00	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment
		12 IN. PIPE CULVERT			14 14 12 12 13 13	2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$490.00) \$490.00 \$0.00 \$0.00 (\$7,038.00) \$7,038.00 (\$7,038.00)	Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	1540	12 IN. PIPE CULVERT GROUP B	Material - To	otal				\$0.00	
	1540 -	- Total						\$0.00	
	1720	SILICONE EXPANSION JOINT SEALANT	Overrun	Overrun	13	Jul 16, 2025	SYSTEM	(\$456.00)	
				Overrun - T	otal			(\$456.00)	
			Overrun - To	otal				(\$456.00)	
		- Total						(\$456.00)	
	5001	MISC. ITS	Material		6	Apr 2, 2025	SYSTEM	(\$5,827.50)	
					6	Apr 2, 2025	SYSTEM	\$5,827.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Apr 16, 2025	SYSTEM	(\$5,827.50)	
					7	Apr 16, 2025	SYSTEM	\$5,827.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					8	May 2, 2025	SYSTEM	(\$5,827.50)	
					8	May 2, 2025	SYSTEM	\$5,827.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					9	May 16, 2025	SYSTEM	(\$5,827.50)	
					9	May 16, 2025	SYSTEM	\$5,827.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user corrij1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			otal						
	5001 -	- Total						\$0.00	
		MISC. ITS	Material		6	Apr 2, 2025	SYSTEM	\$0.00 (\$7,095.90)	
			Material		6		SYSTEM SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
			Material			2025 Apr 2,		(\$7,095.90)	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment
			Material		6	2025 Apr 2, 2025 Apr 16,	SYSTEM	(\$7,095.90) \$7,095.90	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment
			Material		7	2025 Apr 2, 2025 Apr 16, 2025 Apr 16,	SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90)	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment
			Material		6 7 7	2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2,	SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment
			Material		6 7 7 8	2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90)	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment
			Material		6 7 7 8 8 8	2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90)	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment
			Material	- Total	6 7 7 8 8 8 9	2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 2, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) (\$7,095.90)	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user corrij1 overridding Payment
			Material Material - To		6 7 7 8 8 8 9	2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 2, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 \$7,095.90	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user corrij1 overridding Payment
		MISC. ITS			6 7 7 8 8 8 9	2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 2, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 \$7,095.90	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user corrij1 overridding Payment
	5002	MISC. ITS			6 7 7 8 8 8 9 9	2025 Apr 16, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 12, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 \$0.00 \$0.00 \$0.00 (\$5,185.00)	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user corrij1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
	5002 -	MISC. ITS -Total CABLE, LOOP DETECTOR, IN	Material - To		6 7 7 8 8 8 9	2025 Apr 2, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$0.00 \$0.00	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user corrij1 overridding Payment
	5002 -	MISC. ITS -Total CABLE, LOOP DETECTOR, IN	Material - To		6 7 7 8 8 8 9 9	2025 Apr 16, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 18, 2025 May 19, 2025 May 2, 2025 May 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 \$0.00 \$0.00 \$0.00 (\$5,185.00)	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user corrij1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Item Adjustment (0034) due to user schirj1 overridding Payment Estimate Item Adjustment (0034) due to user schirj1 overridding Payment
	5002 -	MISC. ITS -Total CABLE, LOOP DETECTOR, IN	Material - To	tal - Total	6 7 7 8 8 8 9 9	2025 Apr 16, 2025 Apr 16, 2025 Apr 16, 2025 May 2, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 18, 2025 May 19, 2025 May 2, 2025 May 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 (\$7,095.90) \$7,095.90 \$0.00 \$0.00 \$0.00 \$5,185.00)	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user corrij1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Item Adjustment (0034) due to user schirj1 overridding Payment Estimate Item Adjustment (0034) due to user schirj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283	5005	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		12	Jul 1, 2025	SYSTEM	(\$1,197.00)	
					12	Jul 1, 2025	SYSTEM	\$1,197.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$1,330.00)	
					13	Jul 16, 2025	SYSTEM	\$1,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$1,330.00)	
					14	Aug 4, 2025	SYSTEM	\$1,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5005 -							\$0.00	
	5006	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		12	Jul 1, 2025	SYSTEM	(\$188.00)	
					12	Jul 1, 2025	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	Jul 16, 2025	SYSTEM	(\$288.00)	
					13	Jul 16, 2025	SYSTEM	\$288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					14	Aug 4, 2025	SYSTEM	(\$288.00)	
					14	Aug 4, 2025	SYSTEM	\$288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		6 - Total							
	5007	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		12	Jul 1, 2025	SYSTEM	(\$63,810.00)	
					12	Jul 1, 2025	SYSTEM	\$63,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total					\$0.00	
			Material - Total					\$0.00	
	5007 -	Total						\$0.00	
J6S3283 -								\$1,089,374.17	
Overall - 1	Total							\$1,089,374.17	

MoDOT

Contract Adjustments for Contract - 241115-F03

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 36 of 36