

Pay Estimate Created Date: September 2, 2025

Progress Estimate Number 10	Contract ID Prime Contractor	241115-F Pace Co	⁻ 10 nstruction Company, L		Pay Period Start Pay Period End			Original Contract Amount Net Change Order Amount Current Contract Amount	\$4,100,000.00 \$132,945.70 \$4,232,945.70
Approval Date									By User
September 2, 2025			Generated and Ap	oprove	ed (and should be	considere	d Draft) at t	the Project Office Level by	wolkt1
September 2, 2025			Reviewed and Approv	ed (an	nd should be consi	idered Dra	ft) at the R	esident Engineer Level by	wolkt1
September 4, 2025			R	eviewe	ed and Approved a	at the Cen	tral Office (Controllers Office Level by	ramses1
Original Completion	on Date C	urrent Co	ompletion Date	Ac	tual Completion	Date	% (of Current Contract Amount	Complete
October 31, 20)25	Octobe	er 31, 2025					76.62%	
	Contrac	t Informat	ional Dates					Milestones	
Date Description	Original Comple	tion Date	Current Completion	n Date		No Miles	tones Exist	for Contract	
Acceptance Date									
Awarded Date	December 4, 202	4	December 4, 2024						
Letting Date	November 15, 202	24	November 15, 2024						
Notice to Proceed Date	January 6, 2025		January 6, 2025						
Work Began Date	April 14, 2025		April 14, 2025						

Contract Total Pay	y For Estimate No. 10			
		This Estimate	Previous	To Date
241115-F10				
	Total Posted Items Pay	\$139,114.01	\$3,104,061.32	\$3,243,175.33
	Gross Item Adjustments	(\$42,409.96)	\$43,181.83	\$771.87
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$3,147,243.15	\$3,243,947.20
Contract Total Pay	yable This Estimate:	\$96,704.05		

Contract T	otal Payab	ole This Esti	mate: \$96,704.05				
Items Paid	This Estim	ate Period					
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JSL0077	0040	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED MATERIAL REQUIREMENT	100F	\$1,250.000	5.600	\$7,000.00
	0290	6181000	MOBILIZATION	LS	\$179,117.650	0.250	\$44,779.41
	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$225.000	5	\$1,125.00
	0360	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	EA	\$25.000	36	\$900.00
	0460	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN. WHITE MIDBLOCK - 10 FT.	EA	\$150.000	1	\$150.00
	0530	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$32.000	1,675	\$53,600.00
	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$4,000.000	3	\$12,000.00
	0570	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,800.000	7	\$26,600.00
Project JSI	L <mark>0077 - To</mark>	tal					\$146,154.41
JSL0080	1350	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$25.000	-53	(\$1,325.00)
	1400	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.200	-28,577	(\$5,715.40)
Project JSI	L0080 - To	tal					(\$7,040.40)
Overall - To	otal						\$139,114.01

Contract Adjustments This Estimate No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 9/2/2025 Page 1 of 34



Pay Estimate Created Date: September 2, 2025

stimat	gress e Num 10		115-F10 e Construction C	Company, LL	C Pay Period End September 1, 2025 Net	ginal Contrac : Change Orde rrent Contract	er Amount	\$4,100,000.0 \$132,945.7 \$4,232,945.7
oject imber	Line No.	Item Description		Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
L0077	0050	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-151.50000	\$3.25	(\$492.38
	0050	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	151.50000	\$3.25	\$492.38
	0100	MISC.	Material			-15,794	\$5.00	(\$78,970.00)
	0100	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	15,794	\$5.00	\$78,970.00
	0110	CONCRETE PAVEMENT (11 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-605.90000	\$145.00	(\$87,855.50)
	0110	CONCRETE PAVEMENT (11 IN. NON-REINFORCED 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	605.90000	\$145.00	\$87,855.50
	0130	TRUNCATED DOMES	Material			-163	\$25.50	(\$4,156.50)
	0130	TRUNCATED DOMES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	163	\$25.50	\$4,156.50
	0230	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR				-48.80000	\$375.00	(\$18,300.00
	0230	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	48.80000	\$375.00	\$18,300.00
	0260	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-68	\$4.90	(\$333.20)
	0260	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	68	\$4.90	\$333.20
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-11	\$25.00	(\$275.00)
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	11	\$25.00	\$275.00
	0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-11	\$225.00	(\$2,475.00)
	0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user estopn1	11	\$225.00	\$2,475.00

Revision 9/2/2025 Page 2 of 34



Pay Estimate Created Date: September 2, 2025

Estimat	gress e Numi 10		15-F10 Construction C	Company, LL	C Pay Period End September 1, 2025 N	riginal Contrac et Change Orde urrent Contract	er Amount	\$4,100,000.00 \$132,945.70 \$4,232,945.70
Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
SL0077		LEFT/RIGHT ARROW			overridding Payment Estimate Exception 13 on the current Payment Estimate.			
	0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	Material			-5	\$200.00	(\$1,000.00)
	0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	5	\$200.00	\$1,000.00
	0340	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material			-8	\$490.00	(\$3,920.00)
	0340	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	8	\$490.00	\$3,920.00
	0350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	Material			-7	\$350.00	(\$2,450.00)
	0350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	7	\$350.00	\$2,450.00
	0360	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material			-149	\$25.00	(\$3,725.00)
	0360	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	149	\$25.00	\$3,725.00
	0370	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW	Material			-3	\$350.00	(\$1,050.00)
	0370	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	3	\$350.00	\$1,050.00
	0380	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT FISH HOOK ARROW	Material			-3	\$350.00	(\$1,050.00)
	0380	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT FISH HOOK ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	3	\$350.00	\$1,050.00
	0390	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material			-11	\$350.00	(\$3,850.00)

Revision 9/2/2025 Page 3 of 34



Pay Estimate Created Date: September 2, 2025

Estimat	gress te Num 10		115-F10 e Construction	Company, LL	C Pay Period End September 1, 2025 No	riginal Contrac et Change Orde urrent Contract	er Amount	\$4,100,000.00 \$132,945.70 \$4,232,945.70
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0077		FISH HOOK ARROW						
	0390	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	11	\$350.00	\$3,850.00
	0400	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-39,449	\$0.20	(\$7,889.80)
	0400	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	39,449	\$0.20	\$7,889.80
	0425	MISC.	Material			-5	\$200.00	(\$1,000.00)
	0425	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	5	\$200.00	\$1,000.00
	0430	MISC.	Material			-5	\$200.00	(\$1,000.00)
	0430	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	5	\$200.00	\$1,000.00
	0460	MISC.	Material			-8	\$150.00	(\$1,200.00)
	0460	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	8	\$150.00	\$1,200.00
	0530	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction	d		(\$24,801.96)
	0540	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction	t		(\$5,208.00)
	0570	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction	t		(\$12,950.00)
	0710	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Material			-28	\$14.00	(\$392.00)
	0710	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user estopn1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	28	\$14.00	\$392.00
	0720	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material			-104	\$16.00	(\$1,664.00)
	0720	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	104	\$16.00	\$1,664.00
	0730	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material			-76	\$28.00	(\$2,128.00)
	0730	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	76	\$28.00	\$2,128.00

Revision 9/2/2025 Page 4 of 34



Pay Estimate Created Date: September 2, 2025

Estimat	gress e Num 10		115-F10 ce Construction	Company, LL	C Pay Period End September 1, 2025 No.	riginal Contrac et Change Orde urrent Contract	er Amount	\$4,100,000.00 \$132,945.70 \$4,232,945.70
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0077					Adjustment (0025) due to user estopn1 overridding Payment Estimate Exception 34 on the current Payment Estimate.			
	0740	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-164	\$0.65	(\$106.60)
	0740	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	164	\$0.65	\$106.60
	0800	PULL BOX, PREFORMED CLASS 2	Material			-5	\$2,070.00	(\$10,350.00)
	0800	PULL BOX, PREFORMED CLASS 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	5	\$2,070.00	\$10,350.00
	0810	PULL BOX, PREFORMED CLASS 3	Material			-2	\$2,784.00	(\$5,568.00)
	0810	PULL BOX, PREFORMED CLASS 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	2	\$2,784.00	\$5,568.00
	1060	MISC.	Material			-1	\$2,350.00	(\$2,350.00)
	1060	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	1	\$2,350.00	\$2,350.00
	1120	MISC.	Material			-102	\$27.00	(\$2,754.00)
	1120	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user estopn1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	102	\$27.00	\$2,754.00
	1130	MISC.	Material			-38	\$14.00	(\$532.00)
	1130	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	38	\$14.00	\$532.00
	1150	MISC.	Material			-1,810	\$16.50	(\$29,865.00)
	1150	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Exception 7 or the current Payment Estimate.	1,810	\$16.50	\$29,865.00
	1160	CONDUIT, 2 IN. RIGID, IN TRENCH	Material			-100	\$14.00	(\$1,400.00)
	1160	CONDUIT, 2 IN. RIGID, IN TRENCH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	100	\$14.00	\$1,400.00
Revision 9		POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	Material			-2	\$7,800.00	(\$15,600.00)

Revision 9/2/2025 Page 5 of 34



Pay Estimate Created Date: September 2, 2025

Estimat	gress e Num 10		41115-F10 ace Construction	Company, LL	C Pay Period End September 1, 2025 Ne	iginal Contrac t Change Orde rrent Contract	er Amount	\$4,100,000.00 \$132,945.70 \$4,232,945.70
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0077	1170	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	2	\$7,800.00	\$15,600.00
JSL0080	1350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-17	\$25.00	(\$425.00)
	1350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	17	\$25.00	\$425.00
	1350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',25.00000 - 25.00000, 'is applied (if non-zero).	22	\$25.00	\$550.00
	1360	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-3	\$225.00	(\$675.00)
	1360	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	3	\$225.00	\$675.00
	1380	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 WHITE, YIELD LINE TRIANGLES	Material IN			-30	\$25.00	(\$750.00)
	1380	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 WHITE, YIELD LINE TRIANGLES	Material IN		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	30	\$25.00	\$750.00
	1390	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS				-35,426	\$0.20	(\$7,085.20)
	1390	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user estopn1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	35,426	\$0.20	\$7,085.20
Total								(\$42,409.96)

Revision 9/2/2025 Page 6 of 34



					Co	ontract Project Informat	tion					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
JSL0077	FAF-109-1 (30)	Coldmill, resurface and ADA improvements	109	ST LOUIS	from Manchester Road t	Manchester Road to Wild Horse Creek Rd. in Wildwood						
JSL0080	PAS-S503 Coldmill and resurface BA ST LOUIS from Route 109 north intersection to Route 109 south intersection, near Babler State Park											
Totals I	oy Job Nu	mbers										
JSL0077	Incentive Disince Liquida	/e	Gross Ite	em Pay	This Estimate \$146,154.41 (\$42,959.96) \$103,194.45 \$0.00 \$0.00 \$0.00 \$0.00	Previous \$1,984,889.72 \$36,396.89 \$2,021,286.61 \$0.00 \$0.00 \$0.00 \$0.00	To Date \$2,131,044.13 (\$6,563.07) \$2,124,481.06 \$0.00 \$0.00 \$0.00 \$0.00					
JSL0080		Item Pay tem Adjustmen	ts <mark>Gross It</mark> e	em Pay	This Estimate (\$7,040.40) \$550.00 (\$6,490.40)	Previous \$1,119,171.60 \$6,784.94 \$1,125,956.54	To Date \$1,112,131.20 \$7,334.94 \$1,119,466.14					
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 5/29/2025 Page 7 of 34



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 3040504, Project Item Line Number 0050, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 4079912, Project Item Line Number 0100, Material Set 407991296, Material 1015EASS1VH - Emulsified Asphalt - Non-Tracking Tack, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 5021311, Project Item Line Number 0110, Material Set 502131196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 5021311, Project Item Line Number 0110, Material Set 502131196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 5021311, Project Item Line Number 0110, Material Set 502131196, Material 1057JMDBEC6.12 - Dowel Bar Epoxy Ctd Gr60 1 1/2 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 5021311, Project Item Line Number 0110, Material Set 502131196, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6069903, Project Item Line Number 1150, Material Set 606990396, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6081012, Project Item Line Number 0130, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6131010, Project Item Line Number 0230, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6131015, Project Item Line Number 0260, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200015, Project Item Line Number 1350, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200018, Project Item Line Number 0310, Material Set 620001896, Material 1048PMPFYL - Preformed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200021, Project Item Line Number 0320, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200021, Project Item Line Number 1360, Material Set 620002196, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200021, Project Item Line Number 1360, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200024, Project Item Line Number 0330, Material Set 620002496, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200027, Project Item Line Number 0340, Material Set 620002796, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200030, Project Item Line Number 0350, Material Set 620003096, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200042, Project Item Line Number 0360, Material Set 620004296, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200042, Project Item Line Number 1380, Material Set 620004296, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200042, Project Item Line Number 1380, Material Set 620004296, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200045, Project Item Line Number 0370, Material Set 6200045, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200048, Project Item Line Number 0380, Material Set 6200048, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200051, Project Item Line Number 0390, Material Set 6200051, Material 0620PMSH - Pavement Marking Performance Shape,	Working with materials to complete exception.	estopn1	Overridden

Revision 5/29/2025 Page 8 of 34



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 0620PMSH is insufficient.			
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6205901A, Project Item Line Number 0400, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6205901A, Project Item Line Number 1390, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6209902, Project Item Line Number 0425, Material Set 620990296, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6209902, Project Item Line Number 0430, Material Set 620990296, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6209902, Project Item Line Number 0460, Material Set 620990296, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9013002, Project Item Line Number 1160, Material Set 901300296, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9018612, Project Item Line Number 1170, Material Set 901861296, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9025200, Project Item Line Number 0710, Material Set 902520096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9025300, Project Item Line Number 0720, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9027300, Project Item Line Number 0730, Material Set 902730096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9028100, Project Item Line Number 0740, Material Set 902810096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9028811, Project Item Line Number 0800, Material Set 902881196, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9028812, Project Item Line Number 0810, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9109902, Project Item Line Number 1060, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9109903, Project Item Line Number 1120, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 9109903, Project Item Line Number 1130, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Item Overrun: Contract 241115-F10, Contract Project JSL0077, Project Item Line Number 0250, Contract Line Item Number 0250, Item 6131014, Minor Item.	Waiting on change order	estopn1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 241115-F10, Contract Project JSL0077, Project Item Line Number 0100, Contract Line Item Number 0100, Item 4079912, Minor Item.	Waiting for change order	estopn1	Acknowledged

Revision 5/29/2025 Page 9 of 34



Total Paid / All Items / All Estimates (Including this Estimate)

t Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POST To Date (See rep generated date)
JSL0077	0001	0010	2019919	MISC.CLEARING VEGETATION AND DEBRIS	0.20	0.00	0.20	ACRE	0.00	\$45,000.00	\$0
	0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$130,000.00	\$97,500
	0001	0030	2079909	MISC.LINEAR GRADING CLASS 2 MODIFIED	11.90	0.00	11.90	STA	0.00	\$1,400.00	\$0
	0001	0040	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED MATERIAL REQUIREMENT	19.00	0.00	19.00	100F	16.40	\$1,250.00	\$20,500
	0001	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	226.00	0.00	226.00	SQYD	151.50	\$3.25	\$49
	0001	0060	3101003	GRAVEL (A)	211.00	0.00	211.00	SQYD	0.00	\$35.00	\$
	0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	663.80	0.00	663.80	TONS	0.00	\$105.00	\$
	0001	0800	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	10,593.30	0.00	10,593.30	TONS	9,014.80	\$105.00	\$946,55
	0001	0090	4071007	TACK COAT - NON-TRACKING	615.00	0.00	615.00	GAL	0.00	\$4.25	\$
	0001	0100	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	11,794.00	0.00	11,794.00	GAL	15,794.00	\$5.00	\$78,97
	0001	0110	5021311	CONCRETE PAVEMENT (11 IN. NON-REINFORCED 15 FT. JOINTS)	818.40	-212.50	605.90	SQYD	605.90	\$145.00	\$87,85
	0001	0120	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	84.00	0.00	84.00	LF	0.00	\$82.50	5
	0001	0130	6081012	TRUNCATED DOMES	163.00	0.00	163.00	SQFT	163.00	\$25.50	\$4,1
	0001	0140	6083006	6 IN. CONCRETE MEDIAN STRIP	54.20	0.00	54.20	SQYD	0.00	\$185.00	
	0001	0150	6086004	CONCRETE SIDEWALK, 4 IN.	151.50	0.00	151.50	SQYD	151.50	\$95.00	\$14,39
	0001	0160	6089902	MISC.10 FT WIDE ADA CURB RAMP	3.00	0.00	3.00	EA	3.00	\$5,000.00	\$15,0
	0001	0170	6089902	MISC.4 IN. BOLT DOWN BOLLARD	3.00	0.00	3.00	EA	0.00	\$3,600.00	
	0001	0180	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	50.00	72.00	122.00	LF	50.00	\$120.00	\$6,0
	0001	0190	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	84.00	0.00	84.00	CUYD	84.00	\$25.00	\$2,1
	0001	0200	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	89.00	0.00	89.00	CUYD	89.00	\$25.00	\$2,2
	0001	0210	6096041	PLACING TYPE 1 ROCK DITCH LINER	84.00	0.00	84.00	CUYD	84.00	\$75.00	\$6,3
	0001	0220	6096042	PLACING TYPE 2 ROCK DITCH LINER	89.00	0.00	89.00	CUYD	89.00	\$75.00	\$6,6
	0001	0230	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	84.20	-35.40	48.80	SQYD	48.80	\$375.00	\$18,3
	0001	0240	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	74.00	-74.00	0.00	SQYD	0.00	\$20.00	
	0001	0250	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	118.00	72.00	190.00	LF	190.00	\$56.00	\$10,6
	0001	0260	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	142.00	-74.00	68.00	EA	68.00	\$4.90	\$3
	0001	0270	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,0
	0001	0280	6169901	MISC.TEMPORARY TRAFFIC CONTROL -	1.00	0.00	1.00	LS	1.00	\$22,029.00	\$22,0
	0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$179,117.65	\$179,1
	0001	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	237.00	0.00	237.00	LF	0.00	\$25.00	
	0001	0310	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	11.00	0.00	11.00	LF	11.00	\$25.00	\$2
	0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	29.00	0.00	29.00	EA	11.00	\$225.00	\$2,4
	0001	0330	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	5.00	0.00	5.00	EA	5.00	\$200.00	\$1,0
	0001	0340	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	9.00	0.00	9.00	EA	8.00	\$490.00	\$3,9
	0001	0350	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	13.00	0.00	13.00	EA	7.00	\$350.00	\$2,4
	0001	0360	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	149.00	0.00	149.00	EA	149.00	\$25.00	\$3,7
	0001	0370	6200045	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW	3.00	0.00	3.00	EA	3.00	\$350.00	\$1,0
	0001	0380	6200048	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT FISH HOOK ARROW	4.00	0.00	4.00	EA	3.00	\$350.00	\$1,0
	0001	0390	6200051	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW	12.00	0.00	12.00	EA	11.00	\$350.00	\$3,8
	0001	0400	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	50,755.00	0.00	50,755.00	LF	39,449.00	\$0.20	\$7,8
	0001	0410	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	55,594.00	0.00	55,594.00	LF	44,288.00	\$0.25	\$11,0
	0001	0420	6209901	MISC.TEMPORARY PAVEMENT MARKING	1.00	0.00	1.00	LS	0.00	\$1.00	
	0001	0425	6209902	MISC.BIKE LANE SYMBOL PREFORMED THERMOPLASTIC PAVEMENT MARKING	12.00	0.00	12.00	EA	5.00	\$200.00	\$1,0
	0001	0430	6209902	MISC.BIKE LANE ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING	12.00	0.00	12.00	EA	5.00	\$200.00	\$1,0
	0001	0440	6209902	MISC.CURB REFLECTOR	6.00	0.00	6.00	EA	0.00	\$35.00	
	0001	0450	6209902	MISC.ISLAND TUBULAR MARKER	6.00	0.00	6.00	EA	0.00	\$110.00	
	0001	0460	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING,	52.00	0.00	52.00	EA	8.00	\$150.00	\$1,2

Revision 5/29/2025 Page 10 of 34



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ole. Po	sieu Qua	nuues an	d value	s are base	d on Report Generated date and can differ from the post	ed amount	at the time	the Estimate	e was G	enerated.		
Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
41115-	JSL0077	0001	0470	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	104,442.00	0.00	104,442.00	SQYD	80,262.00	\$3.00	\$240,786.00
		0001	0480	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	516.00	0.00	516.00	SQYD	0.00	\$3.50	\$0.00
		0001	0490	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	150.00	0.00	150.00	STA	150.00	\$65.00	\$9,750.00
		0001	0500	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.00
		0001	0510	8031000A	TURF TYPE TALL FESCUE SODDING	100.00	0.00	100.00	SQYD	0.00	\$25.00	\$0.00
		0010	0520	6061060	MGS GUARDRAIL	525.00	0.00	525.00	LF	525.00	\$28.00	\$14,700.00
		0010	0530	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,588.00	0.00	2,588.00	LF	2,525.00	\$32.00	\$80,800.00
		0010	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	3.00	\$4,000.00	\$12,000.00
		0010	0550	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	3.00	0.00	3.00	EA	3.00	\$4,000.00	\$12,000.00
		0010	0560	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	3.00	\$1,800.00	\$5,400.00
		0010	0570	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	22.00	0.00	22.00	EA	19.00	\$3,800.00	\$72,200.0
		0020	0580	9019902	MISC.103W TOP MOUNTED LED-A LUMINAIRE	7.00	0.00	7.00	EA	0.00	\$500.00	\$0.0
		0030	0590	9020213	SIGNAL HEAD, TYPE 3S	5.00	0.00	5.00	EA	0.00	\$936.00	\$0.0
		0030	0600	9020513	SIGNAL HEAD, TYPE 3B	10.00	0.00	10.00	EA	0.00	\$1,186.00	\$0.0
		0030	0610	9020514	SIGNAL HEAD, TYPE 4B	5.00	0.00	5.00	EA	0.00	\$1,329.00	\$0.0
		0030	0620	9020515	SIGNAL HEAD, TYPE 5B	1.00	0.00	1.00	EA	0.00	\$1,757.00	\$0.0
		0030	0630	9020833	SH-FLAT SHEET - SIGNAL SIGN	99.00	0.00	99.00	SQFT	0.00	\$40.00	\$0.0
		0030	0640	9020834	SIGNAL SIGN, MOUNTING HARDWARE	20.00	0.00	20.00	EA	0.00	\$220.00	\$0.0
		0030	0650	9022708	POST, SIGNAL 8 FT.	2.00	0.00	2.00	EA	0.00	\$1,112.00	\$0.0
		0030	0660	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	0.00	\$9,712.00	\$0.0
		0030	0670	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	0.00	\$11,386.00	\$0.0
		0030	0680	9023145	POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$12,824.00	\$0.0
		0030	0690	9023455	POST, TYPE BL, LONGEST ARM 55 FT.	1.00	0.00	1.00	EA	0.00	\$22,872.00	\$0.0
		0030	0700	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	2.00	0.00	2.00	EA	0.00	\$20,450.00	\$0.0
		0030	0710	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	43.00	0.00	43.00	LF	28.00	\$14.00	\$392.0
		0030	0720	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	207.00	0.00	207.00	LF	104.00	\$16.00	\$1,664.0
		0030	0730	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	544.00	0.00	544.00	LF	76.00	\$28.00	\$2,128.0
		0030	0740	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	420.00	0.00	420.00	LF	164.00	\$0.65	\$106.6
		0030	0750	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	170.00	0.00	170.00	LF	0.00	\$1.85	\$0.0
		0030	0760	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,150.00	0.00	1,150.00	LF	0.00	\$2.00	\$0.0
		0030	0770	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,090.00	0.00	1,090.00	LF	0.00	\$2.00	\$0.0
		0030	0780	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,100.00	0.00	1,100.00	LF	0.00	\$2.25	\$0.0
		0030	0790	9028311	CABLE, 16 AWG 7 CONDUCTOR	4,330.00	0.00	4,330.00	LF	0.00	\$3.00	\$0.0
		0030	0800	9028811	PULL BOX, PREFORMED CLASS 2	8.00	0.00	8.00	EA	5.00	\$2,070.00	\$10,350.0
		0030	0810	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	2.00	\$2,784.00	\$5,568.0
		0030	0820	9029100	BASE, CONCRETE	22.70	0.00	22.70	CUYD	16.00	\$2,500.00	\$40,000.0
		0030	0830	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE & PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$11,200.00	\$0.0
		0030	0840	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING WITH VERBAL WALK MESSAGE	4.00	0.00	4.00	EA	0.00	\$785.00	\$0.0
		0030	0850	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING POWER SUPPLY WITH UPS	2.00	0.00	2.00	EA	0.00	\$22,000.00	\$0.0
		0030	0860	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	8.00	0.00	8.00	EA	0.00	\$669.00	\$0.0
		0030	0870	9029902	MISC.EMERGENCY VEHICLE PREEMPTION SYSTEM REINSTALLATION	2.00	0.00	2.00	EA	0.00	\$2,780.00	\$0.0
		0030	0880	9029902	MISC.EXTENSIONS FOR PUSHBUTTONS (14-IN. MAX)	3.00	0.00	3.00	EA	0.00	\$200.00	\$0.0
		0030	0890	9029902	MISC.INSTALL MODOT FURNISHED TRAFFIC SIGNAL CONTROLLER	2.00	0.00	2.00	EA	0.00	\$450.00	\$0.0
		0030	0900	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	2.00	0.00	2.00	EA	0.00	\$1,402.00	\$0.0
		0030	0910	9029902	MISC.ST LOUIS DISTRICT TRAFFIC SIGNAL DETECTION SYSTEM	2.00	0.00	2.00	EA	0.00	\$48,000.00	\$0.0
		0040	0920	9031010	CONCRETE FOOTINGS, EMBEDDED	0.40		0.40	CUYD	0.00	\$8,000.00	\$0.0
		0040	0930	9031210	STRUCTURAL STEEL POSTS	350.00		350.00	LB	0.00	\$8.00	\$0.0
		0040	0940	9031270A		223.00		223.00	LF	0.00	\$32.00	\$0.0
		0040	0950	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	17.00	0.00	17.00	EA	0.00	\$250.00	\$0.0
		0040	0960	9035004A	SH-FLAT SHEET	265.00	0.00	265.00	SQFT	0.00	\$36.00	\$0.0
		0040	0970	9035011A	ST-STRUCTURAL	72.00	0.00	72.00	SQFT	0.00	\$40.00	\$0.0
		0040	0980	9035069A	SHF-FLAT SHEET FLUORESCENT	170.00	0.00	170.00	SQFT	0.00	\$40.00	\$0.0
		0050	0990	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$450.00	\$0.0
		0050	1000	9109902	MISC.CCTV CAMERA ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$6,066.00	\$0.0
		0050	1010	9109902	MISC.FIBER OPTIC FUSION SPLICE	4.00	0.00	4.00	EA	0.00	\$120.00	\$0.0



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ract Project No.	uantities an	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
15- JSL00	77 0050	1020	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.00
	0050	1030	9109902	MISC.INSTALL MODOT FURNISHED IP ADDRESSABLE POWER STRIP	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.00
	0050	1040	9109902	MISC.INSTALL NEW CONDUIT INTO EXISTING PULL BOX	3.00	0.00	3.00	EA	3.00	\$1,200.00	\$3,600.00
	0050	1050	9109902	MISC.INSTALL OR RELOCATE EXISTING COMMUNICATIONS EQUIPMENT	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
	0050	1060	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5	1.00	0.00	1.00	EA	1.00	\$2,350.00	\$2,350.00
	0050	1070	9109902	MISC.MODOT BURIED CABLE DRIVABLE DELINEATOR	4.00	0.00	4.00	EA	0.00	\$140.00	\$0.00
	0050	1080	9109902	MISC.SM FIBER OPTIC JUMPER	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.00
	0050	1090	9109902	MISC.SM FIBER OPTIC PIGTAIL	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.00
	0050	1100	9109902	MISC.WALL-MOUNT FIBER INTERCONNECT CENTER	2.00	0.00	2.00	EA	0.00	\$1,320.00	\$0.00
	0050	1110	9109903	MISC.CCTV Camera Cable	110.00	0.00	110.00	LF	0.00	\$2.20	\$0.00
	0050	1120	9109903	MISC.CONDUIT, HDPE, DRILL, 2"	102.00	0.00	102.00	LF	102.00	\$27.00	\$2,754.00
	0050	1130	9109903	MISC.CONDUIT, HDPE, TRENCH, 2"	38.00	0.00	38.00	LF	38.00	\$14.00	\$532.00
	0050	1140	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	785.00	0.00	785.00	LF	0.00	\$2.50	\$0.00
	0051	1150	6069903	MISC.POWDER COATING GUARDRAIL (INCLUDES POSTS, END TERMINALS, END ANCHORS)	1,810.00	0.00	1,810.00	LF	1,810.00	\$16.50	\$29,865.00
	0052	1160	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	100.00	0.00	100.00	LF	100.00	\$14.00	\$1,400.00
	0052	1170	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	2.00	0.00	2.00	EA	2.00	\$7,800.00	\$15,600.0
	0052	1180	9019902	MISC.ILLUMINATED STREET NAME SIGN (LED)	8.00	0.00	8.00	EA	0.00	\$4,551.00	\$0.0
	0053	1190	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,410.00	0.00	1,410.00	LF	0.00	\$2.00	\$0.00
	0053	1200	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, CONTROLLER ENCLOSURE	2.00	0.00	2.00	EA	0.00	\$240.00	\$0.00
	0053	1210	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, PAD MOUNTED POWER SUPPLY ENCLOSURE	2.00	0.00	2.00	EA	0.00	\$240.00	\$0.00
	0053	1220	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, PEDESTAL (8')	5.00	0.00	5.00	EA	0.00	\$105.00	\$0.0
	0053	1230	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, TYPE CL POST W/ 25' MAST ARM	2.00	0.00	2.00	EA	0.00	\$693.00	\$0.0
	0053	1240	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, TYPE CL POST W/ 35' MAST ARM	3.00	0.00	3.00	EA	0.00	\$1,020.00	\$0.0
	0053	1250	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, TYPE CL POST W/ 45° MAST ARM	1.00	0.00	1.00	EA	0.00	\$1,096.80	\$0.0
	0053	1260	9029902	MISC.POWDER COATING SIGNAL EQUIPMENTM TYPE BL POST W/ 45' (LEFT ARM) AND 55' (RIGHT ARM)	1.00	0.00	1.00	EA	0.00	\$2,133.60	\$0.0
Projec	t JSL0077 - T	otal Value	Posted to D	Date as of Report Generated Date							\$2,131,044.1
JSL00		1270	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$6,000.0
	0001	1280	2159910	MISC.SHAPING SLOPES, CLASS III	7.00	0.00	7.00	100F	7.00	\$1,250.00	\$8,750.0
	0001	1290	3105003	GRAVEL (A) OR CRUSHED STONE (B)	100.00	0.00	100.00	SQYD	0.00	\$45.00	\$0.0
	0001	1300	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	6,796.00	2,055.40	8,851.40	TONS	8,851.40	600.00	\$708.112.0
	0001	1310	4074007	TACK COAT - NON-TRACKING						\$80.00	, ,
		1320	4071007 6161098A		6,249.00	-972.00	5,277.00	GAL EA	5,277.00 2.00	\$4.25	
	0001	1320	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	3.00		3.00	EA	2.00	\$4.25 \$3,000.00	\$6,000.0
	0001	1330	6161098A 6169901	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL	3.00	-972.00 0.00 0.00	3.00 1.00	EA LS	2.00	\$4.25 \$3,000.00 \$4,802.00	\$6,000.0 \$4,802.0
			6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	3.00	-972.00 0.00	3.00	EA	2.00	\$4.25 \$3,000.00	\$6,000.0 \$4,802.0 \$75,000.0
	0001	1330 1340	6161098A 6169901 6181000	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	3.00 1.00 1.00	-972.00 0.00 0.00 0.00	3.00 1.00 1.00	EA LS LS	2.00 1.00 1.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00	\$6,000.0 \$4,802.0 \$75,000.0 \$425.0
	0001	1330 1340 1350	6161098A 6169901 6181000 6200015	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING,	3.00 1.00 1.00 48.00	-972.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00	LS LS LF	2.00 1.00 1.00 17.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00	\$6,000.0 \$4,802.0 \$75,000.0 \$425.0
	0001 0001 0001	1330 1340 1350 1360	6161098A 6169901 6181000 6200015 6200021	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING,	3.00 1.00 1.00 48.00 3.00	-972.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00	LS LS LF	2.00 1.00 1.00 17.00 3.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00	\$6,000.0 \$4,802.0 \$75,000.0 \$425.0 \$675.0
	0001 0001 0001 0001 0001	1330 1340 1350 1360 1370	6161098A 6169901 6181000 6200015 6200021 6200024	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN	3.00 1.00 1.00 48.00 3.00	-972.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00	EA LS LS LF EA	2.00 1.00 1.00 17.00 3.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00	\$6,000.00 \$4,802.01 \$75,000.01 \$425.01 \$675.00
	0001 0001 0001 0001 0001 0001	1330 1340 1350 1360 1370	6161098A 6169901 6181000 6200015 6200021 6200024 6200042	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3.00 1.00 1.00 48.00 3.00 1.00	-972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00 1.00	EA LS LF EA EA	2.00 1.00 1.00 17.00 3.00 0.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00	\$22,427.2 \$6,000.0 \$4,802.0 \$75,000.0 \$425.0 \$675.0 \$7,085.2 \$0.0
	0001 0001 0001 0001 0001 0001	1330 1340 1350 1360 1370 1380 1390 1400	6161098A 6169901 6181000 6200015 6200021 6200024 6200042 6205901A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, VIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	3.00 1.00 1.00 48.00 3.00 1.00 30.00	-972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00	EA LS LF EA EA LF SQYD	2.00 1.00 1.00 17.00 3.00 0.00 30.00 35,426.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00	\$6,000.0 \$4,802.0 \$75,000.0 \$425.0 \$675.0 \$0.0 \$750.0
	0001 0001 0001 0001 0001 0001 0001	1330 1340 1350 1360 1370 1380 1390	6161098A 6169901 6181000 6200015 6200021 6200024 6200042 6205901A 6206000C	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	3.00 1.00 1.00 48.00 3.00 1.00 35,426.00 28,577.00	-972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00	EA LS LS LF EA EA LF SQYD LS	2.00 1.00 1.00 17.00 3.00 0.00 30.00 35,426.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$200.00	\$6,000.0 \$4,802.0 \$75,000.0 \$425.0 \$675.0 \$7,085.2 \$0.0 \$156,003.7
	0001 0001 0001 0001 0001 0001 0001 000	1330 1340 1350 1360 1370 1380 1390 1400	6161098A 6169901 6181000 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, VIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00 28,577.00 62,489.00	-972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00 0.00 63,675.00	EA LS LF EA EA LF SQYD	2.00 1.00 17.00 3.00 0.00 30.00 35,426.00 0.00 63,675.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$0.20 \$0.20	\$6,000.0 \$4,802.0 \$75,000.0 \$425.0 \$675.0 \$0.0 \$7,085.2 \$0.0 \$156,003.7
	0001 0001 0001 0001 0001 0001 0001 000	1330 1340 1350 1360 1370 1380 1390 1400 1410	6161098A 6169901 6181000 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001 6274000	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) CONTRACTOR FURNISHED SURVEYING AND STAKING	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00 28,577.00 62,489.00	-972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00 0.00 63,675.00	EA LS LS LF EA EA LF SQYD LS	2.00 1.00 17.00 3.00 0.00 30.00 35,426.00 0.00 63,675.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$0.20 \$0.20 \$2.45	\$6,000.0 \$4,802.0 \$75,000.0 \$425.0 \$675.0 \$0.0 \$7,085.2 \$0.0 \$156,003.7
	0001 0001 0001 0001 0001 0001 0001 000	1330 1340 1350 1360 1370 1380 1390 1400 1410 1420 1430	6161098A 6169901 6181000 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001 6274000 8051000A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) CONTRACTOR FURNISHED SURVEYING AND STAKING SEEDING - COOL SEASON GRASSES	3.00 1.00 1.00 48.00 3.00 1.00 35.426.00 28,577.00 62,489.00 1.00 0.10	-972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00 0.00 63,675.00	EA LS LS LF EA EA LF SQYD LS ACRE	2.00 1.00 17.00 3.00 0.00 30.00 35,426.00 0.00 63,675.00 1.00 0.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$0.20 \$0.20 \$1.00 \$40,000.00	\$6,000.00 \$4,802.00 \$75,000.00 \$425.00 \$675.00 \$0.00 \$7,085.20 \$0.00 \$156,003.70 \$1.00 \$0.00 \$0.00
	0001 0001 0001 0001 0001 0001 0001 000	1330 1340 1350 1360 1370 1380 1390 1400 1410 1420 1430 1440	6161098A 6169901 6181000 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001 6274000 8051000A 8061005	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, VIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) CONTRACTOR FURNISHED SURVEYING AND STAKING SEEDING - COOL SEASON GRASSES ROCK DITCH CHECK	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00 28,577.00 62,489.00 1.00 0.10 50.00	-972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 48.00 3.00 1.00 30.00 35,426.00 0.00 63,675.00 1.00 0.10 50.00	EA LS LS LF EA EA EA LF SQYD LS ACRE LF	2.00 1.00 17.00 3.00 0.00 30.00 35,426.00 0.00 63,675.00 1.00 0.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$0.20 \$0.20 \$1.00 \$40,000.00 \$55.00	\$6,000.00 \$4,802.00 \$75,000.00 \$425.00 \$675.00 \$0.00 \$7,085.20 \$0.00 \$156,003.70 \$1.00 \$0.00 \$0.00 \$0.00
	0001 0001 0001 0001 0001 0001 0001 000	1330 1340 1350 1360 1370 1380 1390 1400 1410 1420 1430 1440 1450	6161098A 6169901 6181000 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001 6274000 8051000A 8061005 8061016	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, VIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) CONTRACTOR FURNISHED SURVEYING AND STAKING SEEDING - COOL SEASON GRASSES ROCK DITCH CHECK SEDIMENT REMOVAL	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00 62,489.00 1.00 50.00 5.00	-972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	3.00 1.00 1.00 48.00 3.00 1.00 30.00 35,426.00 0.00 63,675.00 1.00 0.10 50.00 5.00	EA LS LS LF EA EA EA LF LF SQYD LS ACRE LF CUYD	2.00 1.00 17.00 3.00 0.00 30.00 35,426.00 0.00 63,675.00 1.00 0.00 0.00	\$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$0.20 \$1.00 \$40,000.00 \$55.00 \$150.00	\$6,000.00 \$4,802.00 \$75,000.00 \$425.00 \$675.00 \$750.00

Revision 5/29/2025 Page 12 of 34



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241115-	JSL0080	0010	1490	6061081	MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE)	4.00	0.00	4.00	EA	4.00	\$4,500.00	\$18,000.00
F10		0010	1500	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	16.00	0.00	16.00	EA	16.00	\$3,800.00	\$60,800.00
		0030	1510	9025020	CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE	22.00	0.00	22.00	LF	0.00	\$48.00	\$0.00
		0030	1520	9028500	CABLE, LOOP DETECTOR, IN DUCT	310.00	0.00	310.00	LF	0.00	\$7.00	\$0.00
		0030	1530	9028510	CABLE, LOOP DETECTOR, LEAD-IN	50.00	0.00	50.00	LF	0.00	\$2.00	\$0.00
		0040	1540	9031280	2.5 IN. PSST POST - 12 GA.	32.00	0.00	32.00	LF	0.00	\$36.00	\$0.00
		0040	1550	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	3.00	0.00	3.00	EA	0.00	\$300.00	\$0.00
		0040	1560	9035004A	SH-FLAT SHEET	125.00	0.00	125.00	SQFT	0.00	\$36.00	\$0.00
		0040	1570	9035069A	SHF-FLAT SHEET FLUORESCENT	9.00	0.00	9.00	SQFT	0.00	\$360.00	\$0.00
		0001	5101	6205902B	6 IN. WHITE CLASS 2 PAVEMENT MARKING PAINT (25-MIL, TYPE L BEADS)	0.00	34,850.00	34,850.00	LF	0.00	\$0.25	\$0.00
	Project J	SL0080 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,112,131.20
241115-F	10 Overall	- Total Val	ue Poste	d to Date as	of Report Generated Date							\$3,243,175.32

Revision 5/29/2025 Page 13 of 34



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JSL0077

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	2159910	MISC. SHAPING SLOPES	8/25/25	9/2/25	1	1.60	100F		187+51	rt	202+29	rt.	
			8/27/25	9/2/25	1	1.60	100F	NB RTE 109	215+90	RT	220+03	RT	
			8/28/25	9/2/25	1	0.80	100F	NB RTE 109 (SE Quad of ramp	232+18	RT	233+06	RT	
				9/2/25	2	0.80	100F	NB RTE 109 (NE Quad of Ramp)	233+71	RT	234+59	RT	
			8/29/25	9/2/25	1	0.80	100F	SB RTE 109 (SW Quad)	232+14	LT	233+04	LT	
1290	6181000	MOBILIZATION	8/19/25	8/22/25	1	0.25	LS	RTE 109	26+66.14	RT/LT	270+08	RT/LT	
320	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	8/19/25	8/22/25	1	3.00	EA	RTE 109	52+00	RT/LT	65+50	RT/LT	
				8/22/25	2	2.00	EA	RTE 109	173+50	LT	187+00	LT	
360	6200042	PREF THERMO PVMT MARK, YIELD TRIAN	8/19/25	8/22/25	1	36.00	EA	RTE 109	65+50	RT LT	79+00	RT LT	
460	6209902	MISC. PAVEMENT MARKINGS	8/19/25	8/22/25	1	1.00	EA	RTE 109	38+50	RT LT	52+00	RT LT	
530	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	8/25/25	9/2/25	1	1,362.50	LF		187+51	rt.	202+29	rt.	
			8/27/25	9/2/25	1	312.50	LF		215+90	RT	220+03	RTE	
540	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	8/28/25	9/2/25	1	1.00	EA	NB RTE 109 (SE Quad of Ramp)	232+18	RT	233+06	RT	
				9/2/25	2	1.00	EA	NB RTE 109 (NE Quad of Ramp)	233+71	RT	234+59	RT	
			8/29/25	9/2/25	1	1.00	EA	SB RTE 109 (SW Quad)	232+14	LT	233+04	LT	
570	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8/25/25	9/2/25	1	2.00	EA		187+51	rt.	202+29	rt	
			8/27/25	9/2/25	1	2.00	EA	NB RTE 109	215+90	RT	220+03	RT	
			8/28/25	9/2/25	1	1.00	EA	NB RTE 109 (SE Quad of Ramp)	232+18	RT	233+06	RT	
				9/2/25	2	1.00	EA	NB RTE 109 (NE Quad of Ramp)	233+71	RT	234+59	RT	
			8/29/25	9/2/25	1	1.00	EA	SB RTE 109 (SW Quad)	232+14	LT	233+04	LT	

Project: JSL0080

Line Number	Item Code	Description			Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance		Offset/ Distance	Comments
1350	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	8/19/25	8/22/25	1	-53.00	LF	RTE 109	2+00	RT LT			
1400	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	8/19/25	8/22/25	1	-28,577.00	LF	RTE BA	2+47	RTLT	178+00	RT LT	

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 14 of 34



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Toject	Line	Description	Туре	Adjustment Type		Date	By	Amount	Kentaks
JSL0077	0050	TYPE 5 AGGREGATE	Material		9	Aug 18, 2025	SYSTEM	(\$492.38)	
		FOR BASE			9	Aug 18, 2025	SYSTEM	\$492.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$492.38)	
					10	Sep 2, 2025	SYSTEM	\$492.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050	- Total						\$0.00	
	0090	TACK COAT - NON-TRACKING	Material		5	Jun 16, 2025	SYSTEM	(\$38,500.75)	
					5	Jun 16, 2025	SYSTEM	\$38,500.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	5	Jun 16, 2025	SYSTEM	(\$35,887.00)	
					5	Jun 16, 2025	SYSTEM	\$35,887.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0090	- Total						\$0.00	
	0100	MISC.	Material		6	Jul 1, 2025	SYSTEM	(\$78,970.00)	
					6	Jul 1, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$78,970.00)	
					7	Jul 16, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$78,970.00)	
					8	Aug 4, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$78,970.00)	
					9	Aug 18, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$78,970.00)	
					10	Sep 2, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	6	Jul 1, 2025	SYSTEM	(\$20,000.00)	
				Overrun - T	otal			(\$20,000.00)	
			Overrun - To	tal				(\$20,000.00)	
	0100	- Total						(\$20,000.00)	
	0110	CONCRETE PAVEMENT (11 IN. NON-	Material		4	Jun 2, 2025	SYSTEM	(\$64,974.50)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0110	REINFORCED	Material		4	Jun 2, 2025	SYSTEM	\$64,974.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$87,855.50)	
					5	Jun 16, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$87,855.50)	
					6	Jul 1, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$87,855.50)	
					7	Jul 16, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$87,855.50)	
					8	Aug 4, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$87,855.50)	
					9	Aug 18, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$87,855.50)	
					10	Sep 2, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
	0110 -	Total	Material - To	tal				\$0.00 \$0.00	
	0.10				9	Aug 18,	SYSTEM	(\$4,156.50)	
	0130	TRUNCATED	Material		3		STSTEIN	(φ 1, 100.00)	
	0130	TRUNCATED DOMES	Material		9	2025 Aug 18, 2025	SYSTEM	\$4,156.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	0130		Material			2025 Aug 18,		,	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment
	0130		Material		9	2025 Aug 18, 2025 Sep 2,	SYSTEM	\$4,156.50	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment
	0130		Material	- Total	9	2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM	\$4,156.50 (\$4,156.50)	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment
	0130		Material - To		9	2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM	\$4,156.50 (\$4,156.50) \$4,156.50	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment
	0130 -	DOMES	Material - To		9 10 10	2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025	SYSTEM SYSTEM SYSTEM	\$4,156.50 (\$4,156.50) \$4,156.50 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment
	0130 -	DOMES			9 10 10 4	2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$4,156.50 (\$4,156.50) \$4,156.50 \$0.00 \$0.00 \$0.00 (\$18,300.00)	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	0130 -	DOMES -Total FURN & PLACE CONC MATL FOR	Material - To		9 10 10	2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025	SYSTEM SYSTEM SYSTEM	\$4,156.50 (\$4,156.50) \$4,156.50 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment
	0130 -	DOMES -Total FURN & PLACE CONC MATL FOR	Material - To		9 10 10 4 4 5	2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Jun 2, 2025 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,156.50 (\$4,156.50) \$4,156.50 \$0.00 \$0.00 \$0.00 (\$18,300.00)	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	0130 -	DOMES -Total FURN & PLACE CONC MATL FOR	Material - To		9 10 10 4 4 4	2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Jun 2, 2025 Jun 16, 1016	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,156.50 (\$4,156.50) \$4,156.50 \$0.00 \$0.00 \$18,300.00) \$18,300.00	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment
	0130 -	DOMES -Total FURN & PLACE CONC MATL FOR	Material - To		9 10 10 4 4 5	2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Jun 2, 2025 Jun 16, 2025 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,156.50 (\$4,156.50) \$4,156.50 \$0.00 \$0.00 \$10.00 \$18,300.00) \$18,300.00	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment
	0130 -	DOMES -Total FURN & PLACE CONC MATL FOR	Material - To		9 10 10 4 4 5 5	Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,156.50 (\$4,156.50) \$4,156.50 \$0.00 \$0.00 \$0.00 (\$18,300.00) \$18,300.00 \$18,300.00	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0230	FURN & PLACE	Material			2025			
		CONC MATL FOR FULL DEPTH			7	Jul 16, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$18,300.00)	
					8	Aug 4, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$18,300.00)	
					9	Aug 18, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$18,300.00)	
					10	Sep 2, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	0230 -	Total						\$0.00	
	0250	FULL DEPTH PAVEMENT	Overrun	Overrun	4	Jun 2, 2025	SYSTEM	(\$4,032.00)	
		REPAIR SAW CUT (FOR		Overrun - T	otal			(\$4,032.00)	
			Overrun - To	tal				(\$4,032.00)	
	0250 -							(\$4,032.00)	
	0260	DOWEL BAR (DRILLING, FURNISHING AND	Material		4	Jun 2, 2025	SYSTEM	(\$215.60)	
		INST			4	Jun 2, 2025	SYSTEM	\$215.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$333.20)	
					5	Jun 16, 2025	SYSTEM	\$333.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$333.20)	
					6	Jul 1, 2025	SYSTEM	\$333.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$333.20)	
					7	Jul 16, 2025	SYSTEM	\$333.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$333.20)	
					8	Aug 4, 2025	SYSTEM	\$333.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$333.20)	
					9	Aug 18, 2025	SYSTEM	\$333.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$333.20)	
					10	Sep 2, 2025	SYSTEM	\$333.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0260	- Total		Туре				\$0.00	
JOLOUTT	0310	PREF THERMO	Material		8	Aug 4,	SYSTEM	(\$275.00)	
		PVMT MARK, 24 IN YELLOW			8	2025 Aug 4, 2025	SYSTEM	\$275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment
					9	Aug 18, 2025	SYSTEM	(\$275.00)	Estimate Exception 10 on the current Payment Estimate.
					9	Aug 18,	SYSTEM	\$275.00	This adjustment offsets the original system-generated Material Payment
						2025			Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$275.00)	
					10	Sep 2, 2025	SYSTEM	\$275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0310	- Total						\$0.00	
	0320	PREF THERMO PVMT MARK, LT/RT ARROW	Material		8	Aug 4, 2025	SYSTEM	(\$1,350.00)	
		LI/KI AKKOW			8	Aug 4, 2025	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,350.00)	
					9	Aug 18, 2025	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$2,475.00)	
					10	Sep 2, 2025	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0320	- Total	Material		0	A.u. 4	SYSTEM	\$0.00	
	0330	PREF THERMO PVMT MRKG, STRIAGHT	Material		8	Aug 4, 2025		(\$1,000.00)	
		ARROW			8	Aug 4, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,000.00)	
					9	Aug 18, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,000.00)	
					10	Sep 2, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total	Mark 111		0	A.:. 1	OVCTE::	\$0.00	
	0340	PREF THERMO PVMT MARKING, COMBO	Material		8	Aug 4, 2025	SYSTEM	(\$3,920.00)	
					8	Aug 4, 2025	SYSTEM	\$3,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$3,920.00)	
					9	Aug 18,	SYSTEM	\$3,920.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		·	Туре	Adjustment Type	Number	Date	Ву		
JSL0077	0340	PREF THERMO	Material						Estimate Exception 17 on the current Payment Estimate.
		PVMT MARKING, COMBO			10	Sep 2, 2025	SYSTEM	(\$3,920.00)	
					10	Sep 2, 2025	SYSTEM	\$3,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0340 -							\$0.00	
	0350	PREF THERMO PVMT MARK, WORD (ONLY)	Material		8	Aug 4, 2025	SYSTEM	(\$2,450.00)	
		WORD (ONET)			8	Aug 4, 2025	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$2,450.00)	
					9	Aug 18, 2025	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$2,450.00)	
					10	Sep 2, 2025	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0350 -							\$0.00	
	0360	PREF THERMO PVMT MARK, YIELD TRIAN	Material		8	Aug 4, 2025	SYSTEM	(\$2,825.00)	
					8	Aug 4, 2025	SYSTEM	\$2,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$2,825.00)	
					9	Aug 18, 2025	SYSTEM	\$2,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$3,725.00)	
					10	Sep 2, 2025	SYSTEM	\$3,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0360 -	Total						\$0.00	
	0370	PREF THERMO PVMT MARK, LT/RT FISH	Material		8	Aug 4, 2025	SYSTEM	(\$1,050.00)	
		LI/KI FION			8	Aug 4, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,050.00)	
					9	Aug 18, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,050.00)	
					10	Sep 2, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0370 -	Total						\$0.00	



t L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
7 0	0380	PREF THERMO PVMT MARK, STR	Material		8	Aug 4, 2025	SYSTEM	(\$1,050.00)	
		FISH			8	Aug 4, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,050.00)	
					9	Aug 18, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,050.00)	
					10	Sep 2, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
0	200	Total	material 10	tui					
		PREF THERMO PVMT MARK,	Material		8	Aug 4, 2025	SYSTEM	\$0.00 (\$3,850.00)	
		COMBO FISH			8	Aug 4, 2025	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$3,850.00)	Estimate Exception 22 on the current rayment Estimate.
					9	Aug 18, 2025	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Paymen Estimate Exception 24 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$3,850.00)	
					10	Sep 2, 2025	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Paymen Estimate Exception 24 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
0	390 -	Total						\$0.00	
0-	0400	4 IN. YELLOW HIGH BUILD	Material		8	Aug 4, 2025	SYSTEM	(\$7,889.80)	
		WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS			8	Aug 4, 2025	SYSTEM	\$7,889.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Paymen Estimate Exception 23 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$7,889.80)	
					9	Aug 18, 2025	SYSTEM	\$7,889.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Paymen Estimate Exception 25 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$7,889.80)	
					10	Sep 2, 2025	SYSTEM	\$7,889.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Paymen Estimate Exception 25 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0400 -	Total						\$0.00	
0	105	MISC. PAVEMENT MARKINGS	Material		8	Aug 4, 2025	SYSTEM	(\$1,000.00)	
	0425				8	Aug 4,	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Paymen
	J425					2025			Estimate Exception 27 on the current Payment Estimate.
	J425				9	2025 Aug 18, 2025	SYSTEM	(\$1,000.00)	



ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
077 (0425	MISC. PAVEMENT	Material	Туре	10	Sep 2,	SYSTEM	(\$1,000.00)	
		MARKINGS			10	2025	CVCTEM	\$1.000.00	This adjustment offsets the original system appropriate Material Daymont
					10	Sep 2, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
(0425 -							\$0.00	
(0430	MISC. PAVEMENT MARKINGS	Material		8	Aug 4, 2025	SYSTEM	(\$1,000.00)	
					8	Aug 4, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,000.00)	
					9	Aug 18, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,000.00)	
					10	Sep 2, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0430 -							\$0.00	
(0440	MISC. PAVEMENT MARKINGS	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$13.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			Occasionation	- Total	FRAIL Todal			\$13.50	
	0440 -	Total	Construction	Stockpile S	i Wii - Totai			\$13.50 \$13.50	
	0440 -	MISC. PAVEMENT	Construction		5	Jun 16,	SYSTEM	\$13.50 \$219.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		MARKINGS	Stockpile STMI	- Total		2025		\$219.00	3
			Construction		ΓΜΙ - Total			\$219.00	
(0450 -	Total						\$219.00	
(0460	MISC. PAVEMENT MARKINGS	Material		8	Aug 4, 2025	SYSTEM	(\$1,050.00)	
					8	Aug 4, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,050.00)	
					9	Aug 18, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,200.00)	
						Sep 2,	SYSTEM	\$1,200.00	The state of the s
					10	2025	STOTEM	ψ1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				- Total	10		STSTEM	\$0.00	Estimate Item Adjustment (0019) due to user estopn1 overridding Payment
			Material - Tot		10		STSTEIN		Estimate Item Adjustment (0019) due to user estopn1 overridding Payment
	0460 -							\$0.00	Estimate Item Adjustment (0019) due to user estopn1 overridding Payment
		Total MGS GUARDRAIL	Material - Tot Construction Stockpile		7		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0019) due to user estopn1 overridding Payment
			Construction		7 8	Jul 16, 2025 Aug 4, 2025	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$2,122.75) (\$606.50)	Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		7	Jul 16, 2025 Aug 4,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$2,122.75)	Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0520	MGS GUARDRAIL	Construction	Stockpile - 1	Γotal			(\$6,368.25)	
			Construction Stockpile		1	Apr 16, 2025	SYSTEM	\$6,368.25	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$6,368.25	
			Construction	Stockpile S	ГМI - Total			\$6,368.25	
	0520	Total						\$0.00	
	0530	MGS GUARDRAIL, 8 FT. POSTS, 6	Construction Stockpile		8	Aug 4, 2025	SYSTEM	(\$1,480.71)	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT 3 IN	•		9	Aug 18, 2025	SYSTEM	(\$11,105.36)	Payment Estimate Item Adjustment generated Stockpile Transaction
					10	Sep 2, 2025	SYSTEM	(\$24,801.96)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$37,388.03)	
			Construction	Stockpile - 1	 Гotal			(\$37,388.03)	
			Construction Stockpile		1	Apr 16, 2025	SYSTEM	\$28,694.38	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMA	- Total				\$28,694.38	
			Construction	l stockpile S	ΓMA - Tota	al		\$28,694.38	
			Construction		1	Apr 16,	SYSTEM	\$9,626.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile STMI			2025		, , , , , , , , ,	, , , ,
			OTIVII	- Total				\$9,626.50	
			Construction	Stockpile S	TMI - Total			\$9,626.50	
	0530 -	Total						\$932.85	
	0540	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		10	Sep 2, 2025	SYSTEM	(\$5,208.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$5,208.00)	
			Construction	Stockpile - 1	Γotal			(\$5,208.00)	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$6,944.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			0	- Total				\$6,944.00	
			Construction	Stockpile S	ΓMI - Total			\$6,944.00	
	0540 -	Total						\$1,736.00	
	0550	MGS VERTICAL CONCRETE BARRIER	Construction Stockpile		8	Aug 4, 2025	SYSTEM	(\$3,472.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		TRANSITION			9	Aug 18, 2025	SYSTEM	(\$1,736.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$5,208.00)	
			Construction	Stockpile - 1	Γotal			(\$5,208.00)	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$5,208.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			J I IVII	- Total				\$5,208.00	
			Construction	Stockpile S	TMI - Total			\$5,208.00	
	0550 -	Total						\$0.00	
	0560	MGS END ANCHOR	Construction Stockpile		7	Jul 16, 2025	SYSTEM	(\$650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Aug 4, 2025	SYSTEM	(\$650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					9	Aug 18, 2025	SYSTEM	(\$650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,950.00)	
			Construction	Stockpile - 1	Γotal			(\$1,950.00)	
			Construction Stockpile		1	Apr 16, 2025	SYSTEM	\$1,950.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,950.00	
			Construction Stockpile STMI - Total					\$1,950.00	
	0560 -	Total						\$0.00	
	0570	TYPE A	Construction		7	Jul 16,	SYSTEM	(\$1,850.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



June	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
MASH	JSL0077	0570		Stockpile			2025														
10 Sep 2 SYSTEM (\$12,090,000) Payment Exempted Item Adjustment garanteed Stockgle Transaction 1 Sep 1 Sep 2 System (\$12,090,000)						8		SYSTEM	(\$9,250.00)	Payment Estimate Item Adjustment generated Stockpile Transaction											
Content Cont						9		SYSTEM	(\$11,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction											
Construction 1						10		SYSTEM	(\$12,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction											
Construction 1					- Total				(\$35,150.00)												
Stockple STM1				Construction	Stockpile - 1	Γotal			(\$35,150.00)												
Construction Stockpile STMI - Total September Se				Stockpile		1		SYSTEM	\$40,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction											
OSTO - Total				STIVII	- Total				\$40,700.00												
O710 CONDUIT 2 N. TRANCH WITH TRACER WIRE				Construction	Stockpile S	ГМI - Tota			\$40,700.00												
TRENCH WITH TRACER WIRE		0570 -	Total						\$5,550.00												
7		0710	TRENCH WITH	Material		7		SYSTEM	(\$392.00)												
8						7		SYSTEM	\$392.00	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment											
2025 Estimate Item Adjustment (0023) due to user estopon1 overridding Payment Estimate Exception 32 on the current Payment Estimate Item Adjustment (0023) due to user estopon1 overridding Payment Estimate Exception 32 on the current Payment Estimate Item Adjustment (0023) due to user estopon1 overridding Payment Estimate Exception 34 on the current Payment Estimate Exception 32 on the current Payment Estimate Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estimate Item Adjustment (006) due to user estopon 1 overridding Payment Estim								8		SYSTEM	(\$392.00)										
2025 9									8		SYSTEM	\$392.00	Estimate Item Adjustment (0023) due to user estopn1 overridding Payment								
2025 SySTEM Estimate Item Adjustment (0025) due to user estopnt overridding Payment Estimate Exception 34 on the current Payment Estimate.						9		SYSTEM	(\$392.00)												
10 Sep 2, SYSTEM \$392.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 32 on the current Payment Estimate.						9		SYSTEM	\$392.00	Estimate Item Adjustment (0025) due to user estopn1 overridding Payment											
Substitution Subs										10		SYSTEM	(\$392.00)								
Naterial - Total S0.00						10		SYSTEM	\$392.00	Estimate Item Adjustment (0023) due to user estopn1 overridding Payment											
					- Total				\$0.00												
CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Jul 1, 2025 6 Jul 1, 2YSTEM \$240.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 7 Jul 16, SYSTEM \$1,664.00 7 Jul 17, SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 8 Aug 4, 2025 8 Aug 4, 2025 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 8 Aug 4, 2025 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate Estimate Exception 18 on the current Payment Estimate Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, SYSTEM \$1,664.00 2025 This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate.				Material - Tot	otal				\$0.00												
TRENCH WITH TRACER WIRE System Sys		0710 -	Total						\$0.00												
SYSTEM 2025 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate. SYSTEM (\$1,664.00) Jul 16, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate Issimate Issimate Item Adjustment (0009) due to user estoph 1 overridding Payment Estimate Exception 18 on the current Payment Estimate. Aug 4, 2025 Aug 4, SYSTEM \$1,664.00 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate. SYSTEM \$1,664.00 Aug 18, 2025 Aug 18, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estoph 1 overridding Payment Estimate Item Adjustment (0026) due to user estoph 1 overridding Payment Estimate Exception 35 on the current Payment Estimate. Sep 2, 2025 SYSTEM \$1,664.00 Sep 2, SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate.		0720	TRENCH WITH	Material		6		SYSTEM	(\$240.00)												
7 Jul 16, SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Aug 4, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate.			TRACER WIRE			6		SYSTEM	\$240.00	Estimate Item Adjustment (0006) due to user estopn1 overridding Payment											
Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Aug 4, 2025 8 Aug 4, SYSTEM \$1,664.00 8 Aug 18, 2025 9 Aug 18, 2025 9 Aug 18, 2025 10 Sep 2, 2025 SYSTEM \$1,664.00 Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate. 9 This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate Estimate Exception 33 on the current Payment Estimate.												7		SYSTEM	(\$1,664.00)						
8 Aug 4, 2025 \$\frac{1}{2025}\$ \$\frac{1}																	7		SYSTEM	\$1,664.00	Estimate Item Adjustment (0009) due to user estopn1 overridding Payment
Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, 2025 9 Aug 18, 2025 9 Aug 18, 2025 10 Sep 2, 2025 10 Sep 2, 2025 SYSTEM \$1,664.00 \$1,664.00 \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate. 10 This adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 10 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.						8		SYSTEM	(\$1,664.00)												
9 Aug 18, 2025 \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, 2025 \$YSTEM (\$1,664.00) 10 Sep 2, 2025 \$YSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.																8	8		SYSTEM	\$1,664.00	Estimate Item Adjustment (0024) due to user estopn1 overridding Payment
Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, 2025 10 Sep 2, 2025 \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.								9		SYSTEM	(\$1,664.00)										
2025 10 Sep 2, 2025 10 Sep 2, 2025 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.						9		SYSTEM	\$1,664.00	Estimate Item Adjustment (0026) due to user estopn1 overridding Payment											
2025 Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.						10		SYSTEM	(\$1,664.00)												
- Total \$0.00						10		SYSTEM	\$1,664.00	Estimate Item Adjustment (0024) due to user estopn1 overridding Payment											
					- Total				\$0.00												



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
L0077	0720	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material - To	tal				\$0.00			
	0720 -	- Total						\$0.00			
	0730	PUSHED WITH	Material		6	Jul 1, 2025	SYSTEM	(\$2,128.00)			
		TRACER WIRE			6	Jul 1, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
					7	Jul 16, 2025	SYSTEM	(\$2,128.00)			
					7	Jul 16, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
					8	Aug 4, 2025	SYSTEM	(\$2,128.00)			
					8	Aug 4, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user estopn1 overridding Payment Estimate Exception 34 on the current Payment Estimate.		
					9	Aug 18, 2025	SYSTEM	(\$2,128.00)			
							9	Aug 18, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
						10	Sep 2, 2025	SYSTEM	(\$2,128.00)		
				10	Sep 2, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user estopn1 overridding Payment Estimate Exception 34 on the current Payment Estimate.			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
		D - Total CABLE, 10 AWG 1 CONDUCTOR,						\$0.00			
		CABLE, 10 AWG 1	Material		6	Jul 1, 2025	SYSTEM	(\$106.60)			
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6		SYSTEM SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
		CABLE, 10 AWG 1 CONDUCTOR,	Material			2025 Jul 1,		(\$106.60)	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment		
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6	2025 Jul 1, 2025 Jul 16,	SYSTEM	(\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment		
		CABLE, 10 AWG 1 CONDUCTOR,	Material		7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16,	SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60)	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment		
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment		
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment		
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7 8 8 8	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate.		
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7 8 8 8 9	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) (\$106.60)	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment		
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7 8 8 8 9 9 9	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment		
		CABLE, 10 AWG 1 CONDUCTOR,		- Total	6 7 7 8 8 8 9 9 10	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.		
	0740	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC	Material - To		6 7 7 8 8 8 9 9 10	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.		
		CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC			6 7 7 8 8 8 9 9 10	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.		
	0740	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC			6 7 7 8 8 8 9 9 10	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60 \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate.		



rainat	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks				
roject	Line	Description	Adjustment Type	Adjustment Type		Date	By	Amount	remars				
L0077	0800	PULL BOX, PREFORMED	Material		8	Aug 4, 2025	SYSTEM	(\$10,350.00)					
		CLASS 2			8	Aug 4, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.				
					9	Aug 18, 2025	SYSTEM	(\$10,350.00)					
					9	Aug 18, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate.				
					10	Sep 2, 2025	SYSTEM	(\$10,350.00)					
					10	Sep 2, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.				
				- Total				\$0.00	Estimate Exception of the fourther dymone Estimate.				
			Material - To					\$0.00					
	0800 -	Tatal	Waterial - 10	ıaı									
	0810	PULL BOX,	Material		6	Jul 1,	SYSTEM	\$0.00 (\$2,784.00)					
		PREFORMED CLASS 3			6	2025 Jul 1, 2025	SYSTEM	\$2,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment				
					7	Jul 16, 2025	SYSTEM	(\$5,568.00)	Estimate Exception 19 on the current Payment Estimate.				
									7	Jul 16, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
							8	Aug 4, 2025	SYSTEM	(\$5,568.00)			
							8	Aug 4, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate.		
					9	Aug 18, 2025	SYSTEM	(\$5,568.00)					
					9	Aug 18, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user estopn1 overridding Payment Estimate Exception 39 on the current Payment Estimate.				
					10	Sep 2, 2025	SYSTEM	(\$5,568.00)					
					10	Sep 2, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate.				
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0810 -	Total						\$0.00					
	0940	2 IN. PSST POST - 12 GA.	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$2,332.58	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total				\$2,332.58					
	00.10	T-4-1	Construction	Stockpile S	rwi - Tota			\$2,332.58					
	0940 -				_		a.va===	\$2,332.58					
	0950	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	Construction Stockpile STMI	- Total	5	Jun 16, 2025	SYSTEM	\$868.70 \$868.70	Payment Estimate Item Adjustment generated Stockpile Transaction				
			Construction	Stockpile S	ΓΜΙ - Tota			\$868.70					
	0950 -	Total						\$868.70					
	0960	SH-FLAT SHEET	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$2,623.50	Payment Estimate Item Adjustment generated Stockpile Transaction				
			O I IVII	- Total				\$2,623.50					
			Construction	Stockpile S	ΓΜΙ - Total			\$2,623.50					
	0960 -	Total						\$2,623.50					
	0970	ST-STRUCTURAL	Construction		5	Jun 16,	SYSTEM	\$1,288.80	Payment Estimate Item Adjustment generated Stockpile Transaction				



			Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
JSL007	7 0970	ST-STRUCTURAL	Stockpile			2025													
			STMI	- Total				\$1,288.80											
			Construction	Stockpile S	ГМI - Total			\$1,288.80											
	0970	- Total						\$1,288.80											
	0980	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$1,904.00	Payment Estimate Item Adjustment generated Stockpile Transaction										
			O TIVIII	- Total				\$1,904.00											
			Construction	Stockpile S	MI - Total			\$1,904.00											
	0980	- Total						\$1,904.00											
	1060	MISC. ITS	Material		6	Jul 1, 2025	SYSTEM	(\$2,350.00)											
					6	Jul 1, 2025	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.										
				2025 Estima	7		SYSTEM	(\$2,350.00)											
					This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate.														
					8	Aug 4, 2025	SYSTEM	(\$2,350.00)											
										8	Aug 4, 2025	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate.					
					9	Aug 18, 2025	SYSTEM	(\$2,350.00)											
					9	Aug 18, 2025	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate.										
							10	Sep 2, 2025	SYSTEM	(\$2,350.00)									
					10	Sep 2, 2025	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate.										
				- Total				\$0.00											
			Material - Tot	tal				\$0.00											
	1060	- Total						\$0.00											
	1120	MISC. ITS	Material		6	Jul 1, 2025	SYSTEM	(\$2,754.00)											
					6	Jul 1, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
					7	Jul 16, 2025	SYSTEM	(\$2,754.00)											
														7	Jul 16, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
					8	Aug 4, 2025	SYSTEM	(\$2,754.00)											
			8											8	8	8	Aug 4, 2025	SYSTEM	\$2,754.00
					9	Aug 18, 2025	SYSTEM	(\$2,754.00)											
					9	Aug 18, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Exception 41 on the current Payment Estimate.										
					10	Sep 2, 2025	SYSTEM	(\$2,754.00)											
					10	Sep 2, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user estopn1 overridding Payment Estimate Exception 39 on the current Payment Estimate.										
				- Total				\$0.00											



100 MISC, ITS Market 100 MISC, ITS Market 100	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1100 MSC, TTS	JSL0077	1120	MISC. ITS	Material - To	tal				\$0.00		
2005		1120 -	Total						\$0.00		
2005 September 1907-190 Just 10 succession for controlling Payment Estimate Exception 20 in the current Payment Estimate Estimate Exception 20 in the current Payment Estimate Estimate Estimate Exception 25 on the current Payment Estimate Estimate Exception 25 on the current Payment Estimate Estimate Exception 25 on the current Payment Estimate Estimate Estimate Estimate Exception 25 on the current Payment Estimate Estimate Estimate Estimate Exception 25 on the current Payment Estimate Exception 45 on the current Payment		1130	MISC. ITS	Material		6		SYSTEM	(\$140.00)		
2025 7						6		SYSTEM	\$140.00	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment	
2025 Estimate Item Adjustment (D076) due to user extoprol overidating Payment Estimate.						7		SYSTEM	(\$532.00)		
8 Aug 4, 2025 8 Aug 5, 2025 9 Aug 16, 2025 9 Aug 17, 2025 10 Sep 2, 2025 10 Sep 2						7		SYSTEM	\$532.00	Estimate Item Adjustment (0016) due to user estopn1 overridding Payment	
2025 SYSTEM (\$532.00						8		SYSTEM	(\$532.00)		
2025						8		SYSTEM	\$532.00	Estimate Item Adjustment (0031) due to user estopn1 overridding Payment	
2025 SYSTEM SS32.00 This adjustment (0033) due to user estops of overridding Payment Estimate Exception 42 on the current Payment Estimate Exception 42 on the current Payment Estimate Estimate Exception 42 on the current Payment Estimate Estimate Exception 42 on the current Payment Estimate Estimate Exception 40 on the current Payment Estimate Estimate Exception 40 on the current Payment Estimate Exception 60 on the current Payment Estimate Exception 70 on the current Payment Estimate Estimate Exception						9		SYSTEM	(\$532.00)		
10						9		SYSTEM	\$532.00	Estimate Item Adjustment (0033) due to user estopn1 overridding Payment	
Total Sum Su						10		SYSTEM	(\$532.00)		
130 - Total						10		SYSTEM	\$532.00	Estimate Item Adjustment (0031) due to user estopn1 overridding Payment	
1130 - Total					- Total				\$0.00		
1150 MISC. GUARDRAIL ITEM				Material - To				\$0.00			
GUARDRAIL ITEM		1130 -	Total						\$0.00		
2025 Estimate tem Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Estimate Exception 6 on the current Payment Estimate Estimate Estimate Exception 6 on the current Payment Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Estimate Exception 6 on the current Payment Estimate Estimate Estimate Exception 6 on the current Payment Estimate Estimate Estimate Estimate Exception 6 on the current Payment Estimate Estimate Estimate Exception 6 on the current Payment Estimate Estimate Estimate Estimate Estimate Exception 7 on the current Payment Estimate Estimate Estimate Exception 7 on the current Payment Estimate Estimate Estimate Exception 7 on the current Payment Estimate Estimate Estimate Exception 7 on the current Payment Estimate Estimate Estimate Exception 7 on the current Payment Estimate Estimate Estimate Exception 7 on the current Payment Estimate Estimate Exception 7 on the current Payment Estimate Exception 15 on the current Payment Estimate Excepti		1150	MISC.	Material		7		SYSTEM	(\$3,778.50)		
2025 8			GUARDRAIL ITEM			7		SYSTEM	\$3,778.50	Estimate Item Adjustment (0017) due to user estopn1 overridding Payment	
2025 Stynamore Stimate Stima							8		SYSTEM	(\$11,451.00)	
2025 9						8		SYSTEM	\$11,451.00	Estimate Item Adjustment (0032) due to user estopn1 overridding Payment	
2025 Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						9		SYSTEM	(\$29,865.00)		
10						9		SYSTEM	\$29,865.00	Estimate Item Adjustment (0034) due to user estopn1 overridding Payment	
Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate. **Total*** **So.00** **Material - Total** **So.00** **Initial Conduit, 2 In. Rigin, In Trench** **Rench** **Initial Conduit, 2 In. Rigin, In Trench** **Total** **Initial Conduit, 2 In. Rigin, In Trench** **Initial Conduit, 2 In. Rigin, 2 In. Rigi						10		SYSTEM	(\$29,865.00)		
1150 - Total S0.00						10		SYSTEM	\$29,865.00	Estimate Item Adjustment (0032) due to user estopn1 overridding Payment	
1150 - Total CONDUIT, 2 IN. RIGID, IN TRENCH BY STATEM CH CONDUIT, 2 IN. RIGID, IN TRENCH BY STATEM CH CONDUIT, 2 IN. RIGID, IN TRENCH BY STATEM CH CONDUIT, 2 IN. RIGID, IN TRENCH BY STATEM CH CONDUIT, 2 IN. RIGID, IN TRENCH CONDUIT, 2 IN. RIGID, IN TREN					- Total				\$0.00		
1160 CONDUIT, 2 IN. RIGID, IN TRENCH 6 Jul 1, 2025 6 Jul 1, 2025 7 Jul 16, 2025 7 Jul 16, 2025 8 SYSTEM (\$630.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 7 Jul 16, 2025 7 Jul 16, 2025 8 SYSTEM (\$1,400.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate.				Material - To	tal				\$0.00		
RIGID, IN TRENCH 2025 6 Jul 1, 2025 8630.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 7 Jul 16, 2025 7 Jul 16, 2025 8 SYSTEM \$1,400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 8 Aug 4, SYSTEM (\$1,400.00)		1150	Total						\$0.00		
6 Jul 1, 2025 SYSTEM \$630.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 7 Jul 16, 2025 SYSTEM \$1,400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 8 Aug 4, SYSTEM (\$1,400.00)		1160	RIGID, IN	Material		6		SYSTEM	(\$630.00)		
2025 7 Jul 16, 2025 8 SYSTEM \$1,400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 8 Aug 4, SYSTEM (\$1,400.00)			IKENCH			6		SYSTEM	\$630.00	Estimate Item Adjustment (0013) due to user estopn1 overridding Payment	
Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 8 Aug 4, SYSTEM (\$1,400.00)						7		SYSTEM	(\$1,400.00)		
						7		SYSTEM	\$1,400.00	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment	
						8	Aug 4, 2025	SYSTEM	(\$1,400.00)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
JSL0077	1160	CONDUIT, 2 IN. RIGID, IN TRENCH	Material		8	Aug 4, 2025	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate.												
					9	Aug 18, 2025	SYSTEM	(\$1,400.00)													
					9	Aug 18, 2025	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 32 on the current Payment Estimate.												
					10	Sep 2, 2025	SYSTEM	(\$1,400.00)													
					10	Sep 2, 2025	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate.												
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1160	- Total						\$0.00													
	1170	POWER SUPPLY ASSEMBLY, TYPE	Material		7	Jul 16, 2025	SYSTEM	(\$15,600.00)													
		2, 240/120			7	Jul 16, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
					8	Aug 4, 2025	SYSTEM	(\$15,600.00)													
					8	Aug 4, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.												
						9	Aug 18, 2025	SYSTEM	(\$15,600.00)												
				9	Aug 18, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.													
						10	Sep 2, 2025	SYSTEM	(\$15,600.00)												
					10	Sep 2, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.												
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1170	- Total						\$0.00													
JSL0077 -	- Total							(\$6,563.07)													
JSL0080	1280	MISC. SHAPING SLOPES	Material		2	May 2, 2025	SYSTEM	(\$2,000.00)													
					2	May 2, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
					3	May 16, 2025	SYSTEM	(\$8,750.00)													
																	3	May 16, 2025	SYSTEM	\$8,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
										4	4	Jun 2, 2025	SYSTEM	(\$8,750.00)							
				4	Jun 2, 2025	SYSTEM	\$8,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1280	- Total						\$0.00													
	1300	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Other Item Adjustment	FUEL	2	May 2, 2025	schirj1	\$5,266.58	BP1 AC INDEX from 4/15 to 4/26												
		1 304-22 (DF-1)		FUEL - Tota	ıl			\$5,266.58													
			Other Item A	djustment - T	otal			\$5,266.58													
			Overrun	Overrun	2	May 2,	SYSTEM	(\$164,432.00)													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0080	1300	BIT. PAVEMENT MIXTURE	Overrun	Overrun		2025			
		PG64-22 (BP-1)			8	Aug 4, 2025	SYSTEM	\$164,432.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',80.00000 - 80.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	1300 -	Total						\$5,266.58	
	1320	CHANGEABLE MESSAGE SIGN WITHOUT	Material		1	Apr 16, 2025	SYSTEM	(\$6,000.00)	
		COMMUNICATION INTERFACE, CONTRACTOR			1	Apr 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		FURNISHED / RETAINED			2	May 2, 2025	SYSTEM	(\$6,000.00)	
					2	May 2, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 16, 2025	SYSTEM	(\$6,000.00)	
					3	May 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Jun 2, 2025	SYSTEM	(\$6,000.00)	
					4	Jun 2, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1320 -	Total						\$0.00	
	1330	Total MISC.	Material		1	Apr 16, 2025	SYSTEM	(\$2,401.00)	
					1	Apr 16, 2025	SYSTEM	\$2,401.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	May 2, 2025	SYSTEM	(\$2,401.00)	
					2	May 2, 2025	SYSTEM	\$2,401.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	May 16, 2025	SYSTEM	(\$2,401.00)	
				2025	3		SYSTEM	\$2,401.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					(\$2,401.00)				
					4	Jun 2, 2025	SYSTEM	\$2,401.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1330 -	Total						\$0.00	
	1350	PREF THERMO PVMT MARK, 24 IN WHIT	Material		4	Jun 2, 2025	SYSTEM	(\$1,200.00)	
		H-4 AALIN]			4	Jun 2, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$1,200.00)	
					5	Jun 16, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jul 1,	SYSTEM	(\$1,200.00)	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
JSL0080	1350	PREF THERMO	Material	Туре		2025			
002000	1000	PVMT MARK, 24 IN WHIT	Waterial		6	Jul 1, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$1,200.00)	
					7	Jul 16, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$1,750.00)	
					8	Aug 4, 2025	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,750.00)	
					9	Aug 18, 2025	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	EM (\$425.00)	
					10	Sep 2, 2025	SYSTEM	\$425.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	8	Aug 4, 2025	SYSTEM	(\$550.00)	
					10	Sep 2, 2025	SYSTEM	\$550.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',25.00000 - 25.00000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	otal				\$0.00	
	1350 -	- Total						\$0.00	
		PREF THERMO							
		PREF THERMO PVMT MARK, LT/RT ARROW	Material		8	Aug 4, 2025	SYSTEM	(\$675.00)	
	1360	PVMT MARK,	Material		8		SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
	1360	PVMT MARK,	Material			2025 Aug 4,		(\$675.00)	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment
	1360	PVMT MARK,	Material		8	2025 Aug 4, 2025 Aug 18,	SYSTEM	(\$675.00) \$675.00	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment
	1360	PVMT MARK,	Material		8	2025 Aug 4, 2025 Aug 18, 2025 Aug 18,	SYSTEM	(\$675.00) \$675.00 (\$675.00)	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment
	1360	PVMT MARK,	Material		9	2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM	(\$675.00) \$675.00 (\$675.00) \$675.00	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment
	1360	PVMT MARK,	Material	- Total	8 9 9	2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$675.00) \$675.00 (\$675.00) \$675.00	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment
	1360	PVMT MARK,	Material - To		8 9 9	2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$675.00) \$675.00 (\$675.00) \$675.00 (\$675.00)	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment
		PVMT MARK,			8 9 9	2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$675.00) \$675.00 (\$675.00) \$675.00 (\$675.00) \$675.00	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment
		PVMT MARK, LT/RT ARROW -Total PREF THERMO PVMT MARK,			8 9 9	2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$675.00) \$675.00 (\$675.00) \$675.00 (\$675.00) \$675.00 \$0.00	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment
	1360	PVMT MARK, LT/RT ARROW	Material - To		8 9 9 10 10	2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$675.00) \$675.00 (\$675.00) \$675.00 (\$675.00) \$675.00 \$0.00 \$0.00	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment
	1360	PVMT MARK, LT/RT ARROW -Total PREF THERMO PVMT MARK,	Material - To		8 9 9 10 10	2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Jun 2, 2025 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$675.00) \$675.00 (\$675.00) \$675.00 (\$675.00) \$675.00 \$0.00 \$0.00 \$0.00 (\$750.00)	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment
	1360	PVMT MARK, LT/RT ARROW -Total PREF THERMO PVMT MARK,	Material - To		8 9 9 10 10 4 4	2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Jun 2, 2025 Jun 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$675.00) \$675.00 (\$675.00) \$675.00 (\$675.00) \$675.00 \$0.00 \$0.00 \$750.00	Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
L0080	1380	PREF THERMO PVMT MARK, YIELD TRIAN	Material		6	Jul 1, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					7	Jul 16, 2025	SYSTEM	(\$750.00)				
					7	Jul 16, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					8	Aug 4, 2025	SYSTEM	(\$750.00)				
					8	Aug 4, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					9	Aug 18, 2025	SYSTEM	(\$750.00)				
					9	Aug 18, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
					10	Sep 2, 2025	SYSTEM	(\$750.00)				
					10	Sep 2, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	tal				\$0.00				
		Total						\$0.00				
	1390	4 IN. YELLOW HIGH BUILD WATERBORNE	Material		4	Jun 2, 2025	SYSTEM	(\$7,085.20)				
		PAVEMENT MARKING PAINT, TYPE L BEADS			4	Jun 2, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
						5	Jun 16, 2025	SYSTEM	(\$7,085.20)			
					5	Jun 16, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					6	6	Jul 1, 2025	SYSTEM	(\$7,085.20)			
					6	Jul 1, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					7	Jul 16, 2025	SYSTEM	(\$7,085.20)				
					7	Jul 16, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					8	Aug 4, 2025	SYSTEM	(\$7,085.20)				
					8	Aug 4, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.			
								9	Aug 18, 2025	SYSTEM	(\$7,085.20)	
												9
				10	10	Sep 2, 2025	SYSTEM	(\$7,085.20)				
					10	Sep 2, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user estopn1 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	tal				\$0.00				
		Total						\$0.00				
	1400	4 IN. WHITE	Material		4	Jun 2,	SYSTEM	(\$5,715.40)				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0080	1400	WATERBORNE	Material			2025			
		PAVEMENT MARKING			4	Jun 2, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$5,715.40)	
					5	Jun 16, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$5,715.40)	
					6	Jul 1, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$5,715.40)	
					7	Jul 16, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$5,715.40)	
					8	Aug 4, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$5,715.40)	
					9	Aug 18, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user estopn1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1400 -	Total						\$0.00	
	1410	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	2	May 2, 2025	SYSTEM	(\$2,905.70)	
		INLINIOR GOINT.				Aug 4, 2025	SYSTEM	\$2,905.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.45000 - 2.45000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	tal				\$0.00	
	1410 -	Total						\$0.00	
	1470	MGS GUARDRAIL	Construction Stockpile		2	May 2, 2025	SYSTEM	(\$2,274.38)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 16, 2025	SYSTEM	(\$11,675.12)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$13,949.50)	
			Construction	Stockpile -	Total			(\$13,949.50)	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$13,949.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$13,949.50	
			Construction	Stockpile S	TMI - Total			\$13,949.50	
	1470 -	Total						\$0.00	
	1480	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile		2	May 2, 2025	SYSTEM	(\$2,221.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,221.50)	
			Construction	Stockpile -	Total			(\$2,221.50)	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$2,221.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			511111	- Total				\$2,221.50	
			Construction	Stockpile S	ГМI - Total			\$2,221.50	
	1480 -	Total						\$0.00	
	1490	MGS BR APP	Construction		2	May 2,	SYSTEM	(\$3,840.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
JSL0080	1490	TRANSITION	Stockpile			2025				
		(THRIE-BEAM BRIDGE			3	May 16, 2025	SYSTEM	(\$3,840.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$7,680.00)		
			Construction	Stockpile - 1	Γotal			(\$7,680.00)		
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$7,680.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STIVII	- Total				\$7,680.00		
			Construction	Stockpile S	TMI - Total			\$7,680.00		
	1490 -	Total						\$0.00		
	1500	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		2	May 2, 2025	SYSTEM	(\$7,400.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		(MASH)			3	May 16, 2025	SYSTEM	(\$22,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$29,600.00)		
			Construction	Stockpile - 1	Total			(\$29,600.00)		
				Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$29,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$29,600.00		
			Construction	Stockpile S	TMI - Total			\$29,600.00		
	1500 -							\$0.00		
	1540	2.5 IN. PSST POST - 12 GA.	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$369.28	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$369.28		
			Construction	Stockpile S	TMI - Total			\$369.28		
	1540 -							\$369.28		
	1550	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$360.78	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$360.78		
	4===		Construction	Stockpile S	TMI - Total			\$360.78		
	1550 -		0 1 "		-		0)/0==:	\$360.78		
	1560	SH-FLAT SHEET	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$1,237.50	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$1,237.50		
			Construction	Stockpile S	TMI - Total			\$1,237.50		
	1560 -							\$1,237.50		
	1570	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$100.80	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$100.80		
			Construction	Stockpile S	TMI - Total			\$100.80		
	1570 - Total							\$100.80		
JSL0080 -								\$7,334.94		
Overall -	otal							\$771.87		

MoDOT

Contract Adjustments for Contract - 241115-F10

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 34 of 34