

Pay Estimate Created Date: September 17, 2025

	Contract ID Prime Contractor	241115-F Pace Co	⁻ 10 nstruction Company, L		Pay Period Start Pay Period End		er 2, 2025 er 15, 2025	Original Contract Amount Net Change Order Amount Current Contract Amount	\$4,100,000.00 \$132,945.70 \$4,232,945.70
Approval Date									By User
September 17, 2025			Generated and	Approv	ed (and should b	e considere	ed Draft) at	the Project Office Level by	wolkt1
September 17, 2025			Reviewed and Appre	oved (a	and should be cor	nsidered Dr	aft) at the F	Resident Engineer Level by	wolkt1
September 18, 2025				Revie	wed and Approve	d at the Ce	ntral Office	Controllers Office Level by	ramses1
Original Completi	on Date	Current C	ompletion Date	A	ctual Completion	n Date	%	of Current Contract Amount	Complete
October 31, 20)25	Octob	er 31, 2025					89.63%	
	Contra	ct Informa	tional Dates					Milestones	
Date Description	Original Comple	tion Date	Current Completion	Date		No Miles	tones Exist	for Contract	
Acceptance Date									
Awarded Date	December 4, 202	4	December 4, 2024						
Letting Date	November 15, 20	24	November 15, 2024						
Notice to Proceed Date	January 6, 2025		January 6, 2025						
Work Began Date	April 14, 2025		April 14, 2025						

Contract Total Pa	ay For Estimate No. 11			
		This Estimate	Previous	To Date
241115-F10				
	Total Posted Items Pay	\$550,763.48	\$3,243,175.33	\$3,793,938.81
	Gross Item Adjustments	(\$230,714.05)	\$771.87	(\$229,942.18)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$3,243,947.20	\$3,563,996.63
Contract Total Pa	ayable This Estimate:	\$320,049.43		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JSL0077	0010	2019919	MISC.CLEARING VEGETATION AND DEBRIS	ACRE	\$45,000.000	0.200	\$9,000.00
	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$130,000.000	0.250	\$32,500.00
	0030	2079909	MISC.LINEAR GRADING CLASS 2 MODIFIED	STA	\$1,400.000	11.900	\$16,660.00
	0040	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED MATERIAL REQUIREMENT	100F	\$1,250.000	2.400	\$3,000.00
	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$3.250	74.500	\$242.13
	0800	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	TONS	\$105.000	3,196.700	\$335,653.50
	0100	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	GAL	\$5.000	5,791	\$28,955.00
	0230	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$375.000	35.400	\$13,275.00
	0260	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$4.900	74	\$362.60
	0470	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$3.000	28,857	\$86,571.00
	0530	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$32.000	62.500	\$2,000.00
	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$4,000.000	1	\$4,000.00
	0570	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,800.000	3	\$11,400.00
Project JSL	.0077 - To	tal					\$543,619.23
JSL0080	5101	6205902B	6 IN. WHITE CLASS 2 PAVEMENT MARKING PAINT (25-MIL, TYPE L BEADS)	LF	\$0.250	28,577	\$7,144.25
Project JSL	. <mark>0080 - T</mark> o	tal					\$7,144.25
Overall - To	ntal						\$550,763.48

Revision 9/2/2025 Page 1 of 37



Pay Estimate Created Date: September 17, 2025

\$4,100,000.00 \$132,945.70 \$4,232,945.70 Pay Period Start September 2, 2025 Pay Period End September 15, 2025 241115-F10 **Original Contract Amount** Progress Contract ID Estimate Number Net Change Order Amount Current Contract Amount Prime Contractor Pace Construction Company, LLC

Contract Adjustments This Estimate

roject	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
umber	No.		Туре	Adjustment Type		Quantity	Adjustment Unit Price	amount
SL0077	0050	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-226	\$3.25	(\$734.50)
	0050	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	226	\$3.25	\$734.50
	0800	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	Overrun			-1,618.20000	\$105.00	(\$169,911.00
	0100	MISC.	Material			-21,585	\$5.00	(\$107,925.00
	0100	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	21,585	\$5.00	\$107,925.00
	0100	MISC.	Overrun			-5,791	\$5.00	(\$28,955.00)
	0110	CONCRETE PAVEMENT (11 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-605.90000	\$145.00	(\$87,855.50)
	0110	CONCRETE PAVEMENT (11 IN. NON-REINFORCED 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	605.90000	\$145.00	\$87,855.50
	0130	TRUNCATED DOMES	Material			-163	\$25.50	(\$4,156.50)
	0130	TRUNCATED DOMES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	163	\$25.50	\$4,156.50
	0230	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-84.20000	\$375.00	(\$31,575.00)
	0230	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	84.20000	\$375.00	\$31,575.00
	0230	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun			-35.40000	\$375.00	(\$13,275.00)
	0250	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',56.00000 - 56.00000, 'is applied (if non-zero).	72	\$56.00	\$4,032.00
	0260	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-142	\$4.90	(\$695.80)
	0260	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	142	\$4.90	\$695.80

Revision 9/2/2025 Page 2 of 37



Pay Estimate Created Date: September 17, 2025

Estimat	gress e Numi 11		15-F10 Construction	Company, LL	Pay Period Start September 2, 2025 C Pay Period End September 15, 2025	Original Contract Net Change Ord Current Contract	er Amount	\$4,100,000.0 \$132,945.7 \$4,232,945.7
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0077	0260	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Overrun			-74	\$4.90	(\$362.60)
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-11	\$25.00	(\$275.00)
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	11	\$25.00	\$275.00
	0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-11	\$225.00	(\$2,475.00)
	0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	11	\$225.00	\$2,475.00
	0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	Material			-5	\$200.00	(\$1,000.00)
	0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	5	\$200.00	\$1,000.00
	0340	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material			-8	\$490.00	(\$3,920.00)
	0340	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	8	\$490.00	\$3,920.00
	0350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	Material			-7	\$350.00	(\$2,450.00)
	0350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	7	\$350.00	\$2,450.00
	0360	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material			-149	\$25.00	(\$3,725.00)
	0360	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	149	\$25.00	\$3,725.00
	0370	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW	Material			-3	\$350.00	(\$1,050.00)

Revision 9/2/2025 Page 3 of 37



Pay Estimate Created Date: September 17, 2025

Estimat	gress te Numi 11		115-F10 e Construction	Company, LL	C Pay Period End September 15, 2025	Original Contract Net Change Ord Current Contract	er Amount	\$4,100,000.0 \$132,945.7 \$4,232,945.7
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
SL0077	0370	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	3	\$350.00	\$1,050.00
	0380	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT FISH HOOK ARROW	Material			-3	\$350.00	(\$1,050.00
	0380	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT FISH HOOK ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	3	\$350.00	\$1,050.00
	0390	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW	Material			-11	\$350.00	(\$3,850.00
	0390	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	11	\$350.00	\$3,850.00
	0400	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-39,449	\$0.20	(\$7,889.80
	0400	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	39,449	\$0.20	\$7,889.80
	0425	MISC.	Material			-5	\$200.00	(\$1,000.00
	0425	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user estopn1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	5	\$200.00	\$1,000.00
	0430	MISC.	Material			-5	\$200.00	(\$1,000.00
	0430	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user estopn1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	5	\$200.00	\$1,000.00
	0460	MISC.	Material			-8	\$150.00	(\$1,200.00
	0460	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	8	\$150.00	\$1,200.00
	0470	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	Overrun			-4,677	\$3.00	(\$14,031.00
	0530	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction	d		(\$925.45
	0540	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction	i		(\$1,736.00)

Revision 9/2/2025 Page 4 of 37



Pay Estimate Created Date: September 17, 2025

stimat	gress e Numl 11		115-F10 ce Construction	Company, LL	C Pay Period End September 15, 2025	Original Contrac Net Change Ord Current Contrac	er Amount	\$4,100,000.0 \$132,945.7 \$4,232,945.7
oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
_0077	0570	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$5,550.00
	0710	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Material			-28	\$14.00	(\$392.00
	0710	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	28	\$14.00	\$392.00
	0720	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material			-104	\$16.00	(\$1,664.00
	0720	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	104	\$16.00	\$1,664.00
	0730	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material			-76	\$28.00	(\$2,128.00
	0730	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	76	\$28.00	\$2,128.00
	0740	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-164	\$0.65	(\$106.60
	0740	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	164	\$0.65	\$106.60
	0800	PULL BOX, PREFORMED CLASS 2	Material			-5	\$2,070.00	(\$10,350.00
	0800	PULL BOX, PREFORMED CLASS 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	5	\$2,070.00	\$10,350.00
	0810	PULL BOX, PREFORMED CLASS 3	Material			-2	\$2,784.00	(\$5,568.00
	0810	PULL BOX, PREFORMED CLASS 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	2	\$2,784.00	\$5,568.00
	1060	MISC.	Material			-1	\$2,350.00	(\$2,350.00
	1060	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	1	\$2,350.00	\$2,350.00
	1120	MISC.	Material			-102	\$27.00	(\$2,754.00
	1120	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user estopn1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	102	\$27.00	\$2,754.00
	1130	MISC.	Material			-38	\$14.00	(\$532.00
		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user estopn1	38	\$14.00	\$532.00

Revision 9/2/2025 Page 5 of 37



Pay Estimate Created Date: September 17, 2025

Estimate	gress e Numi 11		15-F10 Construction	Company, LL	C Pay Period End September 15, 2025 I	Original Contrac Net Change Ord Current Contrac	er Amount	\$4,100,000.00 \$132,945.70 \$4,232,945.70
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0077					overridding Payment Estimate Exception 40 on the current Payment Estimate.			
	1150	MISC.	Material			-1,810	\$16.50	(\$29,865.00)
	1150	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1,810	\$16.50	\$29,865.00
	1160	CONDUIT, 2 IN. RIGID, IN TRENCH	Material			-100	\$14.00	(\$1,400.00)
	1160	CONDUIT, 2 IN. RIGID, IN TRENCH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	100	\$14.00	\$1,400.00
	1170	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	Material			-2	\$7,800.00	(\$15,600.00)
	1170	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	2	\$7,800.00	\$15,600.00
JSL0080	1350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-17	\$25.00	(\$425.00)
	1350	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	17	\$25.00	\$425.00
	1360	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-3	\$225.00	(\$675.00)
	1360	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	3	\$225.00	\$675.00
	1380	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material			-30	\$25.00	(\$750.00)
	1380	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0043) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	30	\$25.00	\$750.00
	1390	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-35,426	\$0.20	(\$7,085.20)
	1390	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0044) due to user estopn1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	35,426	\$0.20	\$7,085.20
								(\$230,714.05)

Revision 9/2/2025 Page 6 of 37



					Co	ontract Project Informati	tion		
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work		
JSL0077	FAF-109-1 (30)	Coldmill, resurface and ADA improvements	109	ST LOUIS	from Manchester Road to	o Wild Horse Creek Rd. in W	/ildwood		
JSL0080	Results (052) FAS-S503 Coldmill and resurface BA ST LOUIS From Route 109 north intersection to Route 109 south intersection, near Babler State Park								
Totals b	y Job Nu	mbers							
JSL0077		Item Pay tem Adjustment	ts Gross Ite	em Pay	This Estimate \$543,619.23 (\$230,714.05) \$312,905.18	Previous \$2,131,044.13 (\$6,563.07) \$2,124,481.06	To Date \$2,674,663.36 (\$237,277.12) \$2,437,386.24		
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00		
JSL0080		Item Pay tem Adjustment	ts Gross Ite	em Pay	This Estimate \$7,144.25 \$0.00 \$7,144.25	Previous \$1,112,131.20 \$7,334.94 \$1,119,466.14	To Date \$1,119,275.45 \$7,334.94 \$1,126,610.39		
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00		

Revision 5/29/2025 Page 7 of 37



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 3040504, Project Item Line Number 0050, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 4079912, Project Item Line Number 0100, Material Set 407991296, Material 1015EASS1VH - Emulsified Asphalt - Non-Tracking Tack, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 5021311, Project Item Line Number 0110, Material Set 502131196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 5021311, Project Item Line Number 0110, Material Set 502131196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 5021311, Project Item Line Number 0110, Material Set 502131196, Material 1057JMDBEC6.12 - Dowel Bar Epoxy Ctd Gr60 1 1/2 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 5021311, Project Item Line Number 0110, Material Set 502131196, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6069903, Project Item Line Number 1150, Material Set 606990396, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6081012, Project Item Line Number 0130, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6131010, Project Item Line Number 0230, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6131015, Project Item Line Number 0260, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200015, Project Item Line Number 1350, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200018, Project Item Line Number 0310, Material Set 620001896, Material 1048PMPFYL - Preformed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200021, Project Item Line Number 0320, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200021, Project Item Line Number 1360, Material Set 620002196, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200021, Project Item Line Number 1360, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200024, Project Item Line Number 0330, Material Set 620002496, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200027, Project Item Line Number 0340, Material Set 620002796, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200030, Project Item Line Number 0350, Material Set 620003096, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200042, Project Item Line Number 0360, Material Set 620004296, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200042, Project Item Line Number 1380, Material Set 620004296, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0080, Item 6200042, Project Item Line Number 1380, Material Set 620004296, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200045, Project Item Line Number 0370, Material Set 6200045, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200048, Project Item Line Number 0380, Material Set 6200048, Material 0620PMSH - Pavement Marking Performance Shape, Acceptance Action Generic 0620PMSH is insufficient.	Working with materials to complete exception.	estopn1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0077, Item 6200051, Project Item Line Number 0390, Material Set 6200051, Material 0620PMSH - Pavement Marking Performance Shape,	Working with materials to complete exception.	estopn1	Overridden

Revision 5/29/2025 Page 8 of 37



Exceptions (Discrepancies) This Estimate Period

Explanation	Entered By	Status
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Working with materials to complete exception.	estopn1	Overridden
Waiting for Change order	estopn1	Acknowledged
Waiting for Change order	estopn1	Acknowledged
Waiting for Change order	estopn1	Acknowledged
Waiting for Change order	estopn1	Acknowledged
Waiting for Change order	estopn1	Acknowledged
	Working with materials to complete exception. Working or Change order Waiting for Change order Waiting for Change order Waiting for Change order	Working with materials to complete exception. estopn1 Working for Change order waiting for Change order estopn1 Waiting for Change order

Revision 5/29/2025 Page 9 of 37



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
5- JSL0077	0001	0010	2019919	MISC.CLEARING VEGETATION AND DEBRIS	0.20	0.00	0.20	ACRE	0.20	\$45,000.00	\$9,000.
	0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$130,000.00	\$130,000.
	0001	0030	2079909	MISC.LINEAR GRADING CLASS 2 MODIFIED	11.90	0.00	11.90	STA	11.90	\$1,400.00	\$16,660.
	0001	0040	2159910	MISC.SHAPING SLOPES CLASS III - MODIFIED MATERIAL REQUIREMENT	19.00	0.00	19.00	100F	18.80	\$1,250.00	\$23,500.
	0001	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	226.00	0.00	226.00	SQYD	226.00	\$3.25	\$734.
	0001	0060	3101003	GRAVEL (A)	211.00	0.00	211.00	SQYD	0.00	\$35.00	\$0
	0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	663.80	0.00	663.80	TONS	0.00	\$105.00	\$0
	0001	0800	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	10,593.30	0.00	10,593.30	TONS	12,211.50	\$105.00	\$1,282,207
	0001	0090	4071007	TACK COAT - NON-TRACKING	615.00	0.00	615.00	GAL	0.00	\$4.25	\$0
	0001	0100	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	11,794.00	0.00	11,794.00	GAL	21,585.00	\$5.00	\$107,925
	0001	0110	5021311	CONCRETE PAVEMENT (11 IN. NON-REINFORCED 15 FT. JOINTS)	818.40	-212.50	605.90	SQYD	605.90	\$145.00	\$87,855
	0001	0120	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	84.00	0.00	84.00	LF	0.00	\$82.50	\$0
	0001	0130	6081012	TRUNCATED DOMES	163.00	0.00	163.00	SQFT	163.00	\$25.50	\$4,156
	0001	0140	6083006	6 IN. CONCRETE MEDIAN STRIP	54.20	0.00	54.20	SQYD	0.00	\$185.00	\$0
	0001	0150	6086004	CONCRETE SIDEWALK, 4 IN.	151.50	0.00	151.50	SQYD	151.50	\$95.00	\$14,392
	0001	0160	6089902	MISC.10 FT WIDE ADA CURB RAMP	3.00	0.00	3.00	EA	3.00	\$5,000.00	\$15,000
	0001	0170	6089902	MISC.4 IN. BOLT DOWN BOLLARD	3.00	0.00	3.00	EA	0.00	\$3,600.00	\$
	0001	0180	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	50.00	72.00	122.00	LF	50.00	\$120.00	\$6,000
	0001	0190	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	84.00	0.00	84.00	CUYD	84.00	\$25.00	\$2,10
	0001	0200	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	89.00	0.00	89.00	CUYD	89.00	\$25.00	\$2,225
	0001	0210	6096041	PLACING TYPE 1 ROCK DITCH LINER	84.00	0.00	84.00	CUYD	84.00	\$75.00	\$6,30
	0001	0220	6096042	PLACING TYPE 2 ROCK DITCH LINER	89.00	0.00	89.00	CUYD	89.00	\$75.00	\$6,675
	0001	0230	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	84.20	-35.40	48.80	SQYD	84.20	\$375.00	\$31,575
	0001	0240	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	74.00	-74.00	0.00	SQYD	0.00	\$20.00	\$
	0001	0250	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	118.00	72.00	190.00	LF	190.00	\$56.00	\$10,64
	0001	0260	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	142.00	-74.00	68.00	EA	142.00	\$4.90	\$69
	0001	0270 6161098A CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED			2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,00
	0001	0280	6169901	MISC.TEMPORARY TRAFFIC CONTROL -	1.00	0.00	1.00	LS	1.00	\$22,029.00	\$22,02
	0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00		\$179,11
	0001	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	237.00	0.00	237.00	LF	0.00	\$25.00	\$
	0001	0310	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	11.00	0.00	11.00	LF	11.00	\$25.00	\$27
	0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	29.00	0.00	29.00	EA	5.00	\$225.00	\$2,47
	0001	0340	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING,	9.00	0.00	9.00	EA	8.00	\$200.00 \$490.00	\$1,00 \$3,92
	0001	0350	6200030	COMBINATION STR/LT/RT PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD	13.00	0.00	13.00	EA	7.00	\$350.00	\$2,45
	0001	0360	6200030	(ONLY) PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN	149.00	0.00	149.00	EA	149.00	\$25.00	\$3,72
	0001	0370	6200045	WHITE, YIELD LINE TRIANGLES PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT	3.00	0.00	3.00	EA	3.00	\$350.00	\$1,05
	0001	0380	6200048	FISH HOOK ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING,	4.00	0.00	4.00	EA	3.00	\$350.00	\$1,05
	0001	0390	6200051	STRAIGHT FISH HOOK ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING,	12.00	0.00	12.00	EA	11.00	\$350.00	\$3,85
	0001	0400	6205901A	COMBINATION STR/LT/RT FISH HOOK ARROW 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	50,755.00	0.00	50,755.00	LF	39,449.00	\$0.20	\$7,88
	0001	0410	6205902A	MARKING PAINT, TYPE L BEADS 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	55,594.00	0.00	55,594.00	LF	44,288.00	\$0.25	\$11,07
	0001	0420	6209901	PAINT, TYPE L BEADS MISC.TEMPORARY PAVEMENT MARKING	1.00	0.00	1.00	LS	0.00	\$1.00	\$
	0001	0425	6209902	MISC.BIKE LANE SYMBOL PREFORMED THERMOPLASTIC PAVEMENT MARKING	12.00	0.00	12.00	EA	5.00	\$200.00	\$1,00
	0001	0430	6209902	MISC.BIKE LANE ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING	12.00	0.00	12.00	EA	5.00	\$200.00	\$1,00
	0001	0440	6209902	MISC.CURB REFLECTOR	6.00	0.00	6.00	EA	0.00	\$35.00	\$
	0001	0450	6209902	MISC.ISLAND TUBULAR MARKER	6.00	0.00	6.00	EA	0.00	\$110.00	\$1

Page 10 of 37 Revision 5/29/2025



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	d on Report Generated date and can differ from the posts Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
ID	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
241115- F10	JSL0077	0001	0470	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	104,442.00	0.00	104,442.00	SQYD	109,119.00	\$3.00	\$327,357.00
		0001	0480	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	516.00	0.00	516.00	SQYD	0.00	\$3.50	\$0.00
		0001	0490	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	150.00	0.00	150.00	STA	150.00	\$65.00	\$9,750.00
		0001	0500	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.00
		0001	0510	8031000A	TURF TYPE TALL FESCUE SODDING	100.00	0.00	100.00	SQYD	0.00	\$25.00	\$0.00
		0010	0520	6061060	MGS GUARDRAIL	525.00	0.00	525.00	LF	525.00	\$28.00	\$14,700.00
		0010	0530	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,588.00	0.00	2,588.00	LF	2,587.50	\$32.00	\$82,800.00
		0010	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$4,000.00	\$16,000.00
		0010	0550	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	3.00	0.00	3.00	EA	3.00	\$4,000.00	\$12,000.00
		0010	0560	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	3.00	\$1,800.00	\$5,400.00
		0020	0570	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	22.00	0.00	22.00	EA	22.00	\$3,800.00	\$83,600.00
		0030	0580 0590	9019902	MISC.103W TOP MOUNTED LED-A LUMINAIRE SIGNAL HEAD, TYPE 3S	7.00 5.00	0.00	7.00 5.00	EA EA	0.00	\$500.00 \$936.00	\$0.00 \$0.00
		0030	0600	9020213	SIGNAL HEAD, TYPE 3S SIGNAL HEAD, TYPE 3B	10.00	0.00	10.00	EA	0.00	\$1,186.00	\$0.00
		0030	0610	9020513	SIGNAL HEAD, TYPE 3B SIGNAL HEAD, TYPE 4B	5.00	0.00	5.00	EA	0.00	\$1,186.00	\$0.00
		0030	0620	9020515	SIGNAL HEAD, TYPE 5B	1.00	0.00	1.00	EA	0.00	\$1,757.00	\$0.00
		0030	0630	9020833	SH-FLAT SHEET - SIGNAL SIGN	99.00	0.00	99.00	SQFT	0.00	\$40.00	\$0.00
		0030	0640	9020834	SIGNAL SIGN, MOUNTING HARDWARE	20.00	0.00	20.00	EA	0.00	\$220.00	\$0.00
		0030	0650	9020834	POST, SIGNAL 8 FT.	2.00	0.00	2.00	EA	0.00	\$1,112.00	\$0.00
		0030	0660	9022708	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	0.00	\$9,712.00	\$0.00
		0030	0670	9023125	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	0.00	\$11,386.00	\$0.00
		0030	0680	9023145	POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$12,824.00	\$0.00
		0030	0690	9023455	POST, TYPE BL, LONGEST ARM 55 FT.	1.00	0.00	1.00	EA	0.00	\$22,872.00	\$0.00
		0030	0700	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	2.00	0.00	2.00	EA	0.00	\$20,450.00	\$0.00
		0030	0710	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	43.00	0.00	43.00	LF	28.00	\$14.00	\$392.00
		0030	0720	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	207.00	0.00	207.00	LF	104.00	\$16.00	\$1,664.00
		0030	0730	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	544.00	0.00	544.00	LF	76.00	\$28.00	\$2,128.00
		0030	0740	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	420.00	0.00	420.00	LF	164.00	\$0.65	\$106.60
		0030	0750	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	170.00	0.00	170.00	LF	0.00	\$1.85	\$0.00
		0030	0760	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,150.00	0.00	1,150.00	LF	0.00	\$2.00	\$0.00
		0030	0770	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,090.00	0.00	1,090.00	LF	0.00	\$2.00	\$0.00
		0030	0780	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,100.00	0.00	1,100.00	LF	0.00	\$2.25	\$0.00
		0030	0790	9028311	CABLE, 16 AWG 7 CONDUCTOR	4,330.00	0.00	4,330.00	LF	0.00	\$3.00	\$0.00
		0030	0800	9028811	PULL BOX, PREFORMED CLASS 2	8.00	0.00	8.00	EA	5.00	\$2,070.00	\$10,350.00
		0030	0810	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	2.00	\$2,784.00	\$5,568.00
		0030	0820	9029100	BASE, CONCRETE	22.70	0.00	22.70	CUYD	16.00	\$2,500.00	\$40,000.00
		0030	0830	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE & PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$11,200.00	\$0.00
		0030	0840	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING WITH VERBAL WALK MESSAGE	4.00	0.00	4.00	EA	0.00	\$785.00	\$0.00
		0030	0850	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING POWER SUPPLY WITH UPS	2.00	0.00	2.00	EA	0.00	\$22,000.00	\$0.00
		0030	0860	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	8.00	0.00	8.00	EA	0.00	\$669.00	\$0.00
		0030	0870	9029902	MISC.EMERGENCY VEHICLE PREEMPTION SYSTEM REINSTALLATION	2.00	0.00	2.00	EA	0.00	\$2,780.00	\$0.00
		0030	0880	9029902	MISC.EXTENSIONS FOR PUSHBUTTONS (14-IN. MAX)	3.00	0.00	3.00	EA	0.00	\$200.00	\$0.00
		0030	0890	9029902	MISC.INSTALL MODOT FURNISHED TRAFFIC SIGNAL CONTROLLER	2.00	0.00	2.00	EA	0.00	\$450.00	\$0.00
		0030	0900	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	2.00	0.00	2.00	EA	0.00	\$1,402.00	\$0.00
		0030	0910	9029902	MISC.ST LOUIS DISTRICT TRAFFIC SIGNAL DETECTION SYSTEM	2.00	0.00	2.00	EA	0.00	\$48,000.00	\$0.00
		0040	0920	9031010	CONCRETE FOOTINGS, EMBEDDED	0.40	0.00	0.40	CUYD	0.00	\$8,000.00	\$0.00
		0040	0930	9031210	STRUCTURAL STEEL POSTS	350.00	0.00	350.00	LB	0.00	\$8.00	\$0.00
		0040	0940	9031270A		223.00	0.00	223.00	LF	0.00	\$32.00	\$0.00
		0040	0950	9031271A		17.00	0.00	17.00	EA	0.00	\$250.00	\$0.00
		0040	0960	9035004A		265.00	0.00	265.00	SQFT	0.00	\$36.00	\$0.00
		0040	0970	9035011A		72.00	0.00	72.00	SQFT	0.00	\$40.00	\$0.00
		0040	0980	9035069A	SHF-FLAT SHEET FLUORESCENT	170.00	0.00	170.00	SQFT	0.00	\$40.00	\$0.00
		0050	0990	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$450.00	\$0.00
		0050	1000	9109902	MISC.CCTV CAMERA ASSEMBLY	2.00 4.00	0.00	2.00	EA	0.00	\$6,066.00	\$0.00
	UUSU 1010 9109902 MISC.FIBER OPTIC FUSION SPLICE							4.00	EA	0.00	\$120.00	\$0.00

Revision 5/29/2025 Page 11 of 37



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report General d date and can differ from the posted amount at the time the Estimate was Generated.

ract Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
15- JSL0077	0050	1020	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.
	0050	1030	9109902	MISC.INSTALL MODOT FURNISHED IP ADDRESSABLE POWER STRIP	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.
	0050	1040	9109902	MISC.INSTALL NEW CONDUIT INTO EXISTING PULL BOX	3.00	0.00	3.00	EA	3.00	\$1,200.00	\$3,600.
	0050	1050	9109902	MISC.INSTALL OR RELOCATE EXISTING COMMUNICATIONS EQUIPMENT	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.
	0050	1060	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5	1.00	0.00	1.00	EA	1.00	\$2,350.00	\$2,350
	0050	1070	9109902	MISC.MODOT BURIED CABLE DRIVABLE DELINEATOR	4.00	0.00	4.00	EA	0.00	\$140.00	\$0
	0050	1080	9109902	MISC.SM FIBER OPTIC JUMPER	4.00	0.00	4.00	EA	0.00	\$20.00	\$0
	0050	1090	9109902	MISC.SM FIBER OPTIC PIGTAIL	4.00	0.00	4.00	EA	0.00	\$20.00	\$0
	0050	1100	9109902	MISC.WALL-MOUNT FIBER INTERCONNECT CENTER	2.00	0.00	2.00	EA	0.00	\$1,320.00	\$0
	0050	1110	9109903	MISC.CCTV Camera Cable	110.00	0.00	110.00	LF	0.00	\$2.20	\$0
	0050	1120	9109903	MISC.CONDUIT, HDPE, DRILL, 2"	102.00	0.00	102.00	LF	102.00	\$27.00	\$2,754
	0050	1130	9109903	MISC.CONDUIT, HDPE, TRENCH, 2"	38.00	0.00	38.00	LF	38.00	\$14.00	\$532
	0050	1140	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	785.00	0.00	785.00	LF	0.00	\$2.50	\$(
	0051	1150	6069903	MISC. POWDER COATING GUARDRAIL (INCLUDES POSTS, END TERMINALS, END ANCHORS)	1,810.00	0.00	1,810.00	LF	1,810.00	\$16.50	\$29,86
	0052	1160	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	100.00	0.00	100.00	LF	100.00	\$14.00	\$1,40
	0052	1170	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	2.00	0.00	2.00	EA	2.00	\$7,800.00	\$15,60
	0052	1180	9019902	MISC.ILLUMINATED STREET NAME SIGN (LED)	8.00	0.00	8.00	EA	0.00	\$4,551.00	\$
	0053	1190	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,410.00	0.00	1,410.00	LF	0.00	\$2.00	\$
	0053	1200	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, CONTROLLER ENCLOSURE	2.00	0.00	2.00	EA	0.00	\$240.00	\$
	0053	1210	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, PAD MOUNTED POWER SUPPLY ENCLOSURE	2.00	0.00	2.00	EA	0.00	\$240.00	\$
	0053	1220	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, PEDESTAL (8')	5.00	0.00	5.00	EA	0.00	\$105.00	\$
	0053	1230	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, TYPE CL POST W 25' MAST ARM	2.00	0.00	2.00	EA	0.00	\$693.00	4
	0053	1240	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, TYPE CL POST W/ 35' MAST ARM	3.00	0.00	3.00	EA	0.00	\$1,020.00	\$
	0053	1250	9029902	MISC.POWDER COATING SIGNAL EQUIPMENT, TYPE CL POST W/ 45' MAST ARM	1.00	0.00	1.00	EA	0.00	\$1,096.80	\$
	0053	1260	9029902	MISC.POWDER COATING SIGNAL EQUIPMENTM TYPE BL POST W/ 45' (LEFT ARM) AND 55' (RIGHT ARM)	1.00	0.00	1.00	EA	0.00	\$2,133.60	\$
	JSL0077 - T			Date as of Report Generated Date							
Project	_	otal Value	e Posted to D	vale as of Report Generaled Date							\$2,674,66
JSL0080	0001	1270	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$2,674,66 \$6,00
	0004				1.00 7.00	0.00	1.00 7.00	LS 100F	1.00 7.00	\$6,000.00 \$1,250.00	\$6,00
	0001	1270	2022010	REMOVAL OF IMPROVEMENTS							
	0001	1270 1280	2022010 2159910	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III	7.00	0.00	7.00	100F	7.00	\$1,250.00	\$6,00 \$8,75 \$
	0001 0001 0001	1270 1280 1290	2022010 2159910 3105003	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B)	7.00 100.00	0.00	7.00 100.00	100F SQYD	7.00	\$1,250.00 \$45.00	\$6,00 \$8,75 \$ \$708,11
	0001 0001 0001 0001	1270 1280 1290 1300	2022010 2159910 3105003 4011209	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	7.00 100.00 6,796.00	0.00 0.00 2,055.40	7.00 100.00 8,851.40	100F SQYD TONS	7.00 0.00 8,851.40	\$1,250.00 \$45.00 \$80.00	\$6,00 \$8,75 \$ \$708,11 \$22,42
	0001 0001 0001 0001 0001	1270 1280 1290 1300 1310	2022010 2159910 3105003 4011209 4071007	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	7.00 100.00 6,796.00 6,249.00	0.00 0.00 2,055.40 -972.00	7.00 100.00 8,851.40 5,277.00	100F SQYD TONS GAL	7.00 0.00 8,851.40 5,277.00	\$1,250.00 \$45.00 \$80.00 \$4.25	\$6,00 \$8,75 \$ \$708,11 \$22,42 \$6,00
	0001 0001 0001 0001 0001 0001	1270 1280 1290 1300 1310 1320	2022010 2159910 3105003 4011209 4071007 6161098A	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	7.00 100.00 6,796.00 6,249.00 3.00	0.00 0.00 2,055.40 -972.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00	100F SQYD TONS GAL EA	7.00 0.00 8,851.40 5,277.00 2.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00	\$6,00 \$8,75 \$ \$708,11 \$22,42 \$6,00
	0001 0001 0001 0001 0001 0001 0001	1270 1280 1290 1300 1310 1320	2022010 2159910 3105003 4011209 4071007 6161098A 6169901	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL	7.00 100.00 6,796.00 6,249.00 3.00	0.00 0.00 2,055.40 -972.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00	100F SQYD TONS GAL EA	7.00 0.00 8,851.40 5,277.00 2.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00	\$6,00 \$8,75 \$ \$708,11 \$22,42 \$6,00 \$4,80
	0001 0001 0001 0001 0001 0001 0001 000	1270 1280 1290 1300 1310 1320 1330 1340	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6181000	REMOVAL OF IMPROVEMENTS MISC. SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC. TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	7.00 100.00 6,796.00 6,249.00 3.00 1.00	0.00 0.00 2,055.40 -972.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00	100F SQYD TONS GAL EA LS	7.00 0.00 8,851.40 5,277.00 2.00 1.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00	\$6,00 \$8,76 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00
	0001 0001 0001 0001 0001 0001 0001 000	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6181000 6200015 6200021	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	7.00 100.00 6,796.00 6,249.00 3.00 1.00 48.00 3.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00	100F SQYD TONS GAL EA LS LS LF EA	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00	\$6,00 \$8,76 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42
	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6181000 6200015 6200021 6200024	REMOVAL OF IMPROVEMENTS MISC. SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC. TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	7.00 100.00 6,796.00 6,249.00 3.00 1.00 48.00 3.00 1.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 1.00	100F SQYD TONS GAL EA LS LS LF EA EA	7.00 0.00 8.851.40 5,277.00 2.00 1.00 17.00 3.00 30.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$200.00	\$6,00 \$8,76 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42
	0001 0001 0001 0001 0001 0001 0001 000	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6200015 6200021 6200024 6200042 6205901A	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, VIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7.00 100.00 6,796.00 6,249.00 3.00 1.00 48.00 3.00 1.00 3.00 3.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 1.00 30.00	100F SQYD TONS GAL EA LS LS EF EA EA	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00 0.00 35,426.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$200.00 \$25.00	\$6,00 \$8,76 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67
	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370 1380	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6181000 6200015 6200024 6200024 6200042 6205901A 6206000C	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT//IGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	7.00 100.00 6,796.00 6,249.00 3.00 1.00 48.00 3.00 1.00 35,426.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 1.00 30.00 35,426.00	100F SQYD TONS GAL EA LS LS LF EA EA EA LF	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00 0.00 35,426.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$75,000.00 \$25.00 \$200.00 \$25.00 \$0.20	\$6,00 \$8,75 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67 \$ \$775
	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6200015 6200021 6200024 6200042 6205901A	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	7.00 100.00 6,796.00 6,249.00 3.00 1.00 48.00 3.00 1.00 3.00 3.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 1.00 30.00	100F SQYD TONS GAL EA LS LS EF EA EA	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00 0.00 35,426.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$200.00 \$25.00	\$6,00 \$8,75 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67 \$
	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370 1380	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6181000 6200015 6200024 6200024 6200042 6205901A 6206000C	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE D BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	7.00 100.00 6,796.00 6,249.00 3.00 1.00 48.00 3.00 1.00 35,426.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 1.00 30.00 35,426.00	100F SQYD TONS GAL EA LS LS LF EA EA EA LF	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00 0.00 35,426.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$75,000.00 \$25.00 \$200.00 \$25.00 \$0.20	\$6,00 \$8,76 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67 \$7,08
	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370 1380 1400	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	7.00 100.00 6,796.00 6,249.00 1.00 1.00 48.00 3.00 3.00 30.00 35,426.00 28,577.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 1.00 30.00 35,426.00 0.00	100F SQYD TONS GAL EA LS LS LF EA EA EA SQYD	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00 0.00 35,426.00 0.00 63,675.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$0.20 \$0.20	\$6,00 \$8,76 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67 \$7,08 \$7,08
	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370 1380 1400 1410	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001 6274000	REMOVAL OF IMPROVEMENTS MISC. SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC. TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE D BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) CONTRACTOR FURNISHED SURVEYING AND STAKING	7.00 100.00 6,796.00 6,249.00 1.00 1.00 48.00 3.00 3.00 30.00 35,426.00 28,577.00 62,489.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 30.00 35,426.00 0.00 63,675.00	100F SQYD TONS GAL EA LS LS LF EA EA EA EA LF LF SQYD	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00 0.00 35,426.00 0.00 63,675.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$0.20 \$0.20 \$2.45	\$6,00 \$8,75 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67 \$ \$7,08 \$7,08
	0001 0001 0001 0001 0001 0001 0001 000	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370 1380 1400 1410 1420 1430	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001 6274000 8051000A	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE D BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) CONTRACTOR FURNISHED SURVEYING AND STAKING SEEDING - COOL SEASON GRASSES	7.00 100.00 6,796.00 6,249.00 3.00 1.00 1.00 48.00 3.00 3.00 28,577.00 62,489.00 1.00 0.10	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 30.00 35,426.00 0.00 63,675.00	100F SQYD TONS GAL EA LS LS LF EA EA EA CF LF SQYD LS ACRE	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00 30.00 35,426.00 0.00 63,675.00 1.00 0.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$0.20 \$0.20 \$1.00 \$4,000.00	\$6,00 \$8,75 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67 \$ \$7,08 \$7,08
	0001 0001 0001 0001 0001 0001 0001 000	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370 1380 1400 1410 1420 1430 1440	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001 6274000 8051000A 8061005	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) CONTRACTOR FURNISHED SURVEYING AND STAKING SEEDING - COOL SEASON GRASSES ROCK DITCH CHECK	7.00 100.00 6,796.00 6,249.00 3.00 1.00 1.00 48.00 3.00 3.00 28,577.00 62,489.00 1.00 50.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 30.00 35,426.00 0.00 63,675.00 1.00 0.10 50.00	100F SQYD TONS GAL EA LS LS LF EA EA EA A CF SQYD LS ACRE LF	7.00 0.00 8,851.40 5,277.00 2.00 1.00 17.00 3.00 30.00 35,426.00 0.00 63,675.00 1.00 0.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$0.20 \$0.20 \$1.00 \$40,000.00 \$55.00	\$6,00 \$8,76 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67
	0001 0001 0001 0001 0001 0001 0001 000	1270 1280 1290 1300 1310 1320 1330 1340 1350 1360 1370 1380 1400 1410 1420 1430 1440 1450	2022010 2159910 3105003 4011209 4071007 6161098A 6169901 6200015 6200021 6200024 6200042 6205901A 6206000C 6221001 6274000 8051000A 8061005 8061016	REMOVAL OF IMPROVEMENTS MISC.SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT - NON-TRACKING CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED MISC.TEMPORARY TRAFFIC CONTROL MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) CONTRACTOR FURNISHED SURVEYING AND STAKING SEEDING - COOL SEASON GRASSES ROCK DITCH CHECK SEDIMENT REMOVAL	7.00 100.00 6,796.00 6,249.00 3.00 1.00 1.00 48.00 3.00 3.00 3.00 28,577.00 62,489.00 1.00 5.00	0.00 0.00 2,055.40 -972.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	7.00 100.00 8,851.40 5,277.00 3.00 1.00 48.00 3.00 3.00 3.00 35,426.00 0.00 63,675.00 1.00 50.00 5.00	100F SQYD TONS GAL EA LS LS LF EA EA EA LF LF SQYD LS ACRE LF CUYD	7.00 0.00 8,851.40 5,277.00 2.00 1.00 1.00 17.00 3.00 30.00 35,426.00 0.00 63,675.00 1.00 0.00 0.00	\$1,250.00 \$45.00 \$80.00 \$4.25 \$3,000.00 \$4,802.00 \$75,000.00 \$25.00 \$225.00 \$200.00 \$25.00 \$0.20 \$1.00 \$4,000.00 \$55.00 \$150.00	\$6,00 \$8,75 \$ \$708,11 \$22,42 \$6,00 \$4,80 \$75,00 \$42 \$67 \$ \$7,08 \$7,08 \$156,00

Revision 5/29/2025 Page 12 of 37



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241115-	JSL0080	0010	1490	6061081	MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE)	4.00	0.00	4.00	EA	4.00	\$4,500.00	\$18,000.00
F10		0010	1500	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	16.00	0.00	16.00	EA	16.00	\$3,800.00	\$60,800.00
		0030	1510	9025020	CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE	22.00	0.00	22.00	LF	0.00	\$48.00	\$0.00
		0030	1520	9028500	CABLE, LOOP DETECTOR, IN DUCT	310.00	0.00	310.00	LF	0.00	\$7.00	\$0.00
		0030	1530	9028510	CABLE, LOOP DETECTOR, LEAD-IN	50.00	0.00	50.00	LF	0.00	\$2.00	\$0.00
		0040	1540	9031280	2.5 IN. PSST POST - 12 GA.	32.00	0.00	32.00	LF	0.00	\$36.00	\$0.00
		0040	1550	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	3.00	0.00	3.00	EA	0.00	\$300.00	\$0.00
		0040	1560	9035004A	SH-FLAT SHEET	125.00	0.00	125.00	SQFT	0.00	\$36.00	\$0.00
		0040	1570	9035069A	SHF-FLAT SHEET FLUORESCENT	9.00	0.00	9.00	SQFT	0.00	\$360.00	\$0.00
		0001	5101	6205902B	6 IN. WHITE CLASS 2 PAVEMENT MARKING PAINT (25-MIL, TYPE L BEADS)	0.00	34,850.00	34,850.00	LF	28,577.00	\$0.25	\$7,144.25
	Project J	SL0080 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,119,275.45
241115-F	10 Overall	- Total Val	ue Poste	d to Date as	of Report Generated Date							\$3,793,938.80

Revision 5/29/2025 Page 13 of 37



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JSL0077

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2019919	MISC. MOWING	9/10/25	9/11/25	1	0.20	ACRE	RTE 109	0+00	RT	270+08	LT	
0020	2022010	REMOVAL OF IMPROVEMENTS	9/10/25	9/11/25	1	0.25	LS	RTE 109	2701+08	RT	0+00	LT	
0030	2079909	MISC. GRADING	9/10/25	9/11/25	1	11.90	STA	RTE 109	0+00	RT	270+08	LT	
0040	2159910	MISC. SHAPING SLOPES	9/3/25	9/9/25	1	0.80	100F	(SW Portion of N BA Bridge)	233+76	LT	234+66	LT	
			9/4/25	9/9/25	1	1.60	100F	NB RTE 109	265+98	RT	267+63	RT	
0050	3040504	TYPE 5 AGGREGATE FOR BASE	9/10/25	9/11/25	1	74.50	SQYD	RTE 109	0+00	RT	270+08	LT	
0800	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP1	9/5/25	9/12/25	1	1,693.20	TONS	RTE 109	107+53	LT	89+00	RT	
			9/6/25	9/11/25	1	1,503.50	TONS	RTE 109	89+00	RT	107+53	LT	
0100	4079912	MISC.	9/5/25	9/12/25	1	3,094.00	GAL	RTE 109	107+53	LT	89+00	RT	
			9/6/25	9/11/25	1	2,697.00	GAL	RTE 109	89+00	RT	107+53	LT	
0230	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	9/10/25	9/11/25	1	35.40	SQYD	RTE 109	0+00	LT	270+08	RT	
0260	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	9/10/25	9/11/25	1	74.00	EA	RTE 109 -	0+00	RT	270+08	LT	
0470	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	9/5/25	9/12/25	1	15,333.00	SQYD	RTE 109	107+53	LT	89+00	RT	
			9/6/25	9/11/25	1	13,524.00	SQYD	RTE 109	89+00	RT	107+53	Lt	
0530	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	9/4/25	9/9/25	1	62.50	LF	NB RTE 109	265+98	RT	267+63	RT	
0540	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	9/3/25	9/9/25	1	1.00	EA	(SW Portion of N BA Bridge)	233+76	LT	234+66	LT	
0570	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	9/3/25	9/9/25	1	1.00	EA	(SW Portion of N BA Bridge)	233+76	LT	234+66	LT	
			9/4/25	9/9/25	1	2.00	EA	NB RTE 109	265+95	RT	267+63	RT	

Project: JSL0080

Line Number	Item Code	Description			Posting Sequence No.		Units			Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
5101	6205902B	6 IN. WHITE CLASS 2 PAVEMENT MARKING PAINT (25-MIL, TYPE L BEADS)	9/4/25	9/9/25	1	28,577.00	LF	RTE 109	0+00	RT	270+08	LT	

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 14 of 37



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
JSL0077	0050	TYPE 5 AGGREGATE	Material	Туре	9	Aug 18, 2025	SYSTEM	(\$492.38)				
		FOR BASE			9	Aug 18, 2025	SYSTEM	\$492.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					10	Sep 2, 2025	SYSTEM	(\$492.38)				
					10	Sep 2, 2025	SYSTEM	\$492.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					11	Sep 17, 2025	SYSTEM	(\$734.50)				
					11	Sep 17, 2025	SYSTEM	\$734.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To					\$0.00				
	0050 -	Total						\$0.00				
	0800	ASPHALTIC CONCRETE	Overrun	Overrun	11	Sep 17, 2025	SYSTEM	(\$169,911.00)				
		MIXTURE PG 70-22 (SP1		Overrun - T	otal			(\$169,911.00)				
			Overrun - To	tal				(\$169,911.00)				
	0080 -	Total						(\$169,911.00)				
	0090	DO90 TACK COAT - NON-TRACKING		Material		5	Jun 16, 2025	SYSTEM	(\$38,500.75)			
							5	Jun 16, 2025	SYSTEM	\$38,500.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
							- Total				\$0.00	
								Material - To	tal			
			Overrun	Overrun	5	Jun 16, 2025	SYSTEM	(\$35,887.00)				
					5	Jun 16, 2025	SYSTEM	\$35,887.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
				Overrun - T	otal			\$0.00				
			Overrun - To	tal				\$0.00				
	0090 -	Total						\$0.00				
	0100	MISC.	Material		6	Jul 1, 2025	SYSTEM	(\$78,970.00)				
					6	Jul 1, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					7	Jul 16, 2025	SYSTEM	(\$78,970.00)				
					7	Jul 16, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					8	Aug 4, 2025	SYSTEM	(\$78,970.00)				
					8	Aug 4, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					9	Aug 18, 2025	SYSTEM	(\$78,970.00)				
					9	Aug 18, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					10	Sep 2, 2025	SYSTEM	(\$78,970.00)				
					10	Sep 2, 2025	SYSTEM	\$78,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
77 (0100	MISC.	Material		11	Sep 17, 2025	SYSTEM	(\$107,925.00)	
					11	Sep 17, 2025	SYSTEM	\$107,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	6	Jul 1, 2025	SYSTEM	(\$20,000.00)	
					11	Sep 17, 2025	SYSTEM	(\$28,955.00)	
				Overrun - T	otal			(\$48,955.00)	
			Overrun - To	tal				(\$48,955.00)	
9	0100 -	Total						(\$48,955.00)	
(0110	CONCRETE PAVEMENT (11 IN. NON-	Material		4	Jun 2, 2025	SYSTEM	(\$64,974.50)	
		REINFORCED			4	Jun 2, 2025	SYSTEM	\$64,974.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$87,855.50)	
					5	Jun 16, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$87,855.50)	
					6	Jul 1, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$87,855.50)	
					7	Jul 16, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$87,855.50)	
					8	Aug 4, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$87,855.50)	
					9	Aug 18, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$87,855.50)	
					10	Sep 2, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$87,855.50)	
					11	Sep 17, 2025	SYSTEM	\$87,855.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0110 - 0130	TRUNCATED	Material		9	Aug 18,	SYSTEM	\$0.00 (\$4,156.50)	
		DOMES				2025			
					9	Aug 18, 2025	SYSTEM	\$4,156.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.



ct	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
,	LINE	Description	Туре	Adjustment Type	Number	Date	By	Amount	i veillains
77	0130	TRUNCATED DOMES	Material		10	Sep 2, 2025	SYSTEM	\$4,156.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$4,156.50)	
					11	Sep 17, 2025	SYSTEM	\$4,156.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0130 -	Total						\$0.00	
	0230	FURN & PLACE CONC MATL FOR	Material		4	Jun 2, 2025	SYSTEM	(\$18,300.00)	
		FULL DEPTH			4	Jun 2, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$18,300.00)	
					5	Jun 16, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$18,300.00)	
					6	Jul 1, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$18,300.00)	
					7	Jul 16, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$18,300.00)	
					8	Aug 4, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$18,300.00)	
					9	Aug 18, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$18,300.00)	
					10	Sep 2, 2025	SYSTEM	\$18,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$31,575.00)	
					11	Sep 17, 2025	SYSTEM	\$31,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	11	Sep 17, 2025	SYSTEM	(\$13,275.00)	
				Overrun - T	otal			(\$13,275.00)	
			Overrun - To	tal				(\$13,275.00)	
	0230 -	Total						(\$13,275.00)	
	0250	FULL DEPTH PAVEMENT	Overrun	Overrun	4	Jun 2, 2025	SYSTEM	(\$4,032.00)	
		REPAIR SAW CUT (FOR			11	Sep 17, 2025	SYSTEM	\$4,032.00	Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of ',56.00000 - 56.00000, 'i applied (if non-zero).
									applied (il flori zero).



St. St.	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks			
2020 Total Total				Туре		Number	Date	Ву					
SEP-AIR SAW CUT	JSL0077	0250		Overrun - To	tal				\$0.00				
1920 1920			REPAIR SAW CUT										
Section Control Burner Control Bur		0250 -	,						\$0.00				
FURNISHING AND				Material		4	Jun 2,	SYSTEM					
2025 Section Section			FURNISHING AND					OVOTELA	0045.00				
2025 South South			INST			4		SYSTEM	\$215.60	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment			
						5		SYSTEM	(\$333.20)				
SysTEM						5		SYSTEM	\$333.20	Estimate Item Adjustment (0005) due to user estopn1 overridding Payment			
2025 SYSTEM S333.20 This adjustment offsets the original system-generated Material Payment Estimate Secretary System S332.20 This adjustment offsets the original system-generated Material Payment Stating System S332.20 This adjustment offsets the original system-generated Material Payment Stating System S332.20 This adjustment offsets the original system-generated Material Payment Stating System S332.20 System Sy						6		SYSTEM	(\$333.20)	Estimate Exception 7 on the current Payment Estimate.			
2025						6		SYSTEM	\$333.20	Estimate Item Adjustment (0005) due to user estopn1 overridding Payment			
2025 September September						7		SYSTEM	(\$333.20)				
						7		SYSTEM	\$333.20	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment			
2025 SySTEM S333.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate Estimate Estimate Exc									8		SYSTEM	(\$333.20)	
9							8		SYSTEM	\$333.20	Estimate Item Adjustment (0004) due to user estopn1 overridding Payment		
2025 Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Payment								9		SYSTEM	(\$333.20)		
10						9		SYSTEM	\$333.20	Estimate Item Adjustment (0006) due to user estopn1 overridding Payment			
2025 SySTEM Estimate Exception 10 on the current Payment Estimate.						10		SYSTEM	(\$333.20)				
11						10		SYSTEM	\$333.20	Estimate Item Adjustment (0006) due to user estopn1 overridding Payment			
Solution Solution						11		SYSTEM	(\$695.80)				
Material - Total						11		SYSTEM	\$695.80	Estimate Item Adjustment (0011) due to user estopn1 overridding Payment			
Overrun Overrun 11 Sep 17, 2025 SYSTEM (\$362.60)					- Total				\$0.00				
Overrun - Total (\$362.60)				Material - To	tal				\$0.00				
Overrun - Total (\$362.60)				Overrun	Overrun	11		SYSTEM	(\$362.60)				
10 10 10 10 10 10 10 10						otal			V				
PREF THERMO PVMT MARK, 24 IN YELLOW Sep 2, 2025 SYSTEM				Overrun - To	tal								
PVMT MARK, 24 IN YELLOW 8 Aug 4, 2025 SYSTEM \$275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 9 Aug 18, 2025 SYSTEM (\$275.00) 9 Aug 18, 2025 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. 10 Sep 2, 2025 SYSTEM (\$275.00)				Motorial		0	Aug 4	CVCTEM					
Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 9 Aug 18, 2025 (\$275.00) 9 Aug 18, 2025 \$YSTEM \$275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. 10 Sep 2, 2025 \$YSTEM (\$275.00)		0310	PVMT MARK, 24	ivialerial			2025			This adjustment effects the original queters are rested. Notarial Deciment			
9 Aug 18, 2025 \$YSTEM \$275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. 10 Sep 2, 2025 \$YSTEM (\$275.00)		IIN YEI		8	8		2025			Estimate Item Adjustment (0005) due to user estopn1 overridding Payment			
2025 Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate. 10 Sep 2, 2025 SYSTEM (\$275.00)						9		SYSTEM	(\$275.00)				
2025						9		SYSTEM	\$275.00	Estimate Item Adjustment (0007) due to user estopn1 overridding Payment			
						10		SYSTEM	(\$275.00)				
						10		SYSTEM	\$275.00	This adjustment offsets the original system-generated Material Payment			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0310	PREF THERMO PVMT MARK, 24 IN YELLOW	Material			2025			Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$275.00)	
					11	Sep 17, 2025	SYSTEM	\$275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0310							\$0.00	
	0320	PREF THERMO PVMT MARK, LT/RT ARROW	Material		8	Aug 4, 2025	SYSTEM	(\$1,350.00)	
					8	Aug 4, 2025	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,350.00)	
					9	Aug 18, 2025	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$2,475.00)	
					10	Sep 2, 2025	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$2,475.00)	
					11	Sep 17, 2025	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Material - To		- Total				
			Material - To	Material - Total				\$0.00	
	0320		Madadal		0	A 4	OVOTEM	\$0.00	
	0330	PREF THERMO PVMT MRKG, STRIAGHT	Material		8	Aug 4, 2025	SYSTEM	(\$1,000.00)	This adjustment effects the asiginal austras grounded Material Daymont
		ARROW			0	Aug 4, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,000.00)	
					9	Aug 18, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,000.00)	
					10	Sep 2, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$1,000.00)	
					11	Sep 17, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				- Total				\$0.00	
	0000	Tatal	Material - To	tal				\$0.00	
		PREF THERMO	Material		8	Aug 4	SYSTEM	\$0.00	
	0340	PVMT MARKING, COMBO	Material		8	Aug 4, 2025		(\$3,920.00)	This adjustment offsets the original system goografed Material Powers
	COMBO					Aug 4, 2025	SYSTEM	\$3,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$3,920.00)	
					9	Aug 18,	SYSTEM	\$3,920.00	This adjustment offsets the original system-generated Material Payment



ct L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
077 0	0340	PREF THERMO PVMT MARKING, COMBO	Material			2025			Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
		COMBO			10	Sep 2, 2025	SYSTEM	(\$3,920.00)	
					10	Sep 2, 2025	SYSTEM	\$3,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Paymen Estimate Exception 17 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$3,920.00)	
					11	Sep 17, 2025	SYSTEM	\$3,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Paymen Estimate Exception 17 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		Total						\$0.00	
0	0350	PREF THERMO PVMT MARK, WORD (ONLY)	Material		8	Aug 4, 2025	SYSTEM	(\$2,450.00)	
		WORD (ONLY)			8	Aug 4, 2025	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Paymer Estimate Exception 16 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$2,450.00)	
					9	Aug 18, 2025	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Paymer Estimate Exception 18 on the current Payment Estimate.
				10	Sep 2, 2025	SYSTEM	(\$2,450.00)		
				10	Sep 2, 2025	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Paymer Estimate Exception 18 on the current Payment Estimate.	
					11	Sep 17, 2025	SYSTEM	(\$2,450.00)	
					11	Sep 17, 2025	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Paymer Estimate Exception 18 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
0	350 -	Total						\$0.00	
0	360	PREF THERMO PVMT MARK,	Material		8	Aug 4, 2025	SYSTEM	(\$2,825.00)	
		YIELD TRIAN			8	Aug 4, 2025	SYSTEM	\$2,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Paymer Estimate Exception 17 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$2,825.00)	
					9	Aug 18, 2025	SYSTEM	\$2,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Paymer Estimate Exception 19 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$3,725.00)	
					10	Sep 2, 2025	SYSTEM	\$3,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Paymer Estimate Exception 19 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$3,725.00)	
					11	Sep 17, 2025	SYSTEM	\$3,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Paymer Estimate Exception 19 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
0	360 -	Total						\$0.00	
0	0370	PREF THERMO PVMT MARK,	Material		8	Aug 4, 2025	SYSTEM	(\$1,050.00)	
		LT/RT FISH							



	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
9 Aug 18, 3/9TEM (\$1.00.00) 9 Aug 18, 3/9TEM \$1.00.00 10 Sep 2, 9/9TEM \$1.00.00 11 Sep 17, 9/9TEM \$1.0	JSL0077	0370	PVMT MARK,	Material			2025				
2005 Sept. 2007 10 Sept. 2 SYSTEM 31,000.00			LT/RT FISH			9		SYSTEM	(\$1,050.00)		
10 Sap 2 978 TEM 10.0000 11 Sap 17 878 TEM 10.0000 11 Sap 17 878 TEM 10.0000 11 Sap 17 878 TEM 10.0000 12 Sap 17 878 TEM 10.0000 12 Sap 17 878 TEM 10.0000 13 Sap 17 Sap 17 878 TEM 10.0000 13 Sap 17 S						9		SYSTEM	\$1,050.00	Estimate Item Adjustment (0013) due to user estopn1 overridding Payment	
2025 Sep 17, SYSTEM (\$1,650.00) This adjustment offsets the original system-generated Material Payment Estimate. Sep 17, SYSTEM (\$1,650.00) This adjustment offsets the original system-generated Material Payment Estimate. Sep 17, SYSTEM (\$1,650.00) This adjustment offsets the original system-generated Material Payment Estimate. Sep 17, SYSTEM Sep 17, SYST						10		SYSTEM	(\$1,050.00)		
1 Sep 17, SYSTEM \$1,00,00 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate (STR) Str. Str						10		SYSTEM	\$1,050.00	Estimate Item Adjustment (0013) due to user estopn1 overridding Payment	
Total						11		SYSTEM	(\$1,050.00)		
Material - Total So.00						11		SYSTEM	\$1,050.00	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment	
1					- Total				\$0.00		
PREFITERION PRINTMARK STR Park				Material - To	tal				\$0.00		
2025 SYSTEM \$1,050.00 This adjustment offisels the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate Exception 23 on the current Payment Estimate Estimate Exception 24 on the current Payment Estimate Estimate Exception 25 on the current Payment Estimate Estimate Exception 24 on the current Payment Estimate Estimate Exception 24 on the current Payment Estimate Estimate Exception 24 on the current Payment Estimate Estimate Estimate Exception 24 on the current Payment Estimate		0370 -	Total						\$0.00		
FISH		0380	PVMT MARK, STR	Material		8		SYSTEM	(\$1,050.00)		
2025 9						8	Aug 4,	SYSTEM	\$1,050.00	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment	
10 Sep 2, 2025 SYSTEM \$1,050.00 Statistical team Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate Exception 24 on the current Payment Estimate Exception 25 on the current Payment Estimate Estimate Exception 25 on the current Payment Estimate Est							9		SYSTEM	(\$1,050.00)	
10						9		SYSTEM	\$1,050.00	Estimate Item Adjustment (0014) due to user estopn1 overridding Payment	
2025 Settinate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate. Total							10		SYSTEM	(\$1,050.00)	
2025						10		SYSTEM	\$1,050.00	Estimate Item Adjustment (0014) due to user estopn1 overridding Payment	
Combo						11		SYSTEM	(\$1,050.00)		
Naterial - Total S0.00						11		SYSTEM	\$1,050.00	Estimate Item Adjustment (0019) due to user estopn1 overridding Payment	
Name					- Total				\$0.00		
Naterial PVMT MARK, COMBO FISH 8				Material - To	tal				\$0.00		
PVMT MARK, COMBO FISH 2025 Aug 4, 2025 Page 18, 2025 Aug 18, 2025 Page 2, 2025 Page 3,850.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. Provided in the current Payment Estimate in the stimate		0380 -	Total						\$0.00		
8 Aug 4, 2025 SYSTEM \$3,850.00 Estimate tem Adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 9 Aug 18, 2025 SYSTEM (\$3,850.00) 9 Aug 18, 2025 SYSTEM \$3,850.00 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate. 10 Sep 2, 2025 SYSTEM (\$3,850.00) 10 Sep 2, 2025 SYSTEM \$3,850.00 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0015) due to user estopn1 overridding Payment Estimate tem Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate. 11 Sep 17, 2025 SYSTEM (\$3,850.00) 11 Sep 17, 2025 SYSTEM S3,850.00 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		0390	PVMT MARK,	Material		8		SYSTEM	(\$3,850.00)		
9 Aug 18, 2025 \$\frac{3}{2025}\$ \$3			COMBO FISH			8		SYSTEM	\$3,850.00	Estimate Item Adjustment (0013) due to user estopn1 overridding Payment	
Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate. 10 Sep 2, 2025 10 Sep 2, 2025 SYSTEM \$3,850.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate. 11 Sep 17, 2025 SySTEM (\$3,850.00) 11 Sep 17, 2025 SYSTEM \$3,850.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.						9		SYSTEM	(\$3,850.00)		
2025 10 Sep 2, 2025 SYSTEM \$3,850.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate. 11 Sep 17, 2025 SYSTEM (\$3,850.00) 11 Sep 17, 2025 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.						9		SYSTEM	\$3,850.00	Estimate Item Adjustment (0015) due to user estopn1 overridding Payment	
Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate. 11 Sep 17, 2025 11 Sep 17, 2025 SYSTEM \$3,850.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.						10		SYSTEM	(\$3,850.00)		
2025 11 Sep 17, 2025 \$3,850.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate. - Total \$0.00						10		SYSTEM	\$3,850.00	Estimate Item Adjustment (0015) due to user estopn1 overridding Payment	
Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate. - Total \$0.00						11		SYSTEM	(\$3,850.00)		
						11		SYSTEM	\$3,850.00	Estimate Item Adjustment (0020) due to user estopn1 overridding Payment	
Material - Total \$0.00					- Total				\$0.00		
				Material - To	tal				\$0.00		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0390 -	Total						\$0.00	
	0400	4 IN. YELLOW HIGH BUILD	Material		8	Aug 4, 2025	SYSTEM	(\$7,889.80)	
		WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS			8	Aug 4, 2025	SYSTEM	\$7,889.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$7,889.80)	
					9	Aug 18, 2025	SYSTEM	\$7,889.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$7,889.80)	
					10	Sep 2, 2025	SYSTEM	\$7,889.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$7,889.80)	
					11	Sep 17, 2025	SYSTEM	\$7,889.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0400 - 0425	MISC. PAVEMENT	Material		8	Aug 4,	SYSTEM	\$0.00 (\$1,000.00)	
	0420	MARKINGS	Waterial		8	2025	SYSTEM	\$1.000.00	This adjustment effects the original system generated Material Doument
						Aug 4, 2025		, ,,	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,000.00)	
					9	Aug 18, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,000.00)	
					10	Sep 2, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$1,000.00)	
					11	Sep 17, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user estopn1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				- Total				\$0.00	
	0425	Total	Material - To	tal				\$0.00	
	0425 - 0430	MISC. PAVEMENT MARKINGS	Material		8	Aug 4, 2025	SYSTEM	\$0.00 (\$1,000.00)	
					8	Aug 4, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,000.00)	
					9	Aug 18, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,000.00)	
					10	Sep 2, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$1,000.00)	
					11	Sep 17,	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment



			1	1					
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0430	MISC. PAVEMENT MARKINGS	Material			2025			Estimate Item Adjustment (0023) due to user estopn1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0430 -	Total						\$0.00	
	0440	MISC. PAVEMENT MARKINGS	Construction Stockpile		5	Jun 16, 2025	SYSTEM	\$13.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$13.50	
			Construction	Stockpile S	TMI - Total			\$13.50	
	0440 -	Total						\$13.50	
	0450	MISC. PAVEMENT MARKINGS	Construction Stockpile		5	Jun 16, 2025	SYSTEM	\$219.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$219.00	
			Construction	Stockpile S	TMI - Total			\$219.00	
	0450 -	Total						\$219.00	
	0460	MISC. PAVEMENT MARKINGS	Material		8	Aug 4, 2025	SYSTEM	(\$1,050.00)	
					8	Aug 4, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$1,050.00)	
					9	Aug 18, 2025	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$1,200.00)	
					10	Sep 2, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$1,200.00)	
					11	Sep 17, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0460 -	Total						\$0.00	
	0470	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	11	Sep 17, 2025	SYSTEM	(\$14,031.00)	
		TALINI OF SUINI .		Overrun - T	otal			(\$14,031.00)	
			Overrun - To	tal				(\$14,031.00)	
	0470 -	Total						(\$14,031.00)	
	0520	MGS GUARDRAIL	Construction Stockpile		7	Jul 16, 2025	SYSTEM	(\$2,122.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Aug 4, 2025	SYSTEM	(\$606.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
					9	Aug 18, 2025	SYSTEM	(\$3,639.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$6,368.25)	
			Construction	Stockpile -	Total			(\$6,368.25)	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$6,368.25	Payment Estimate Item Adjustment generated Stockpile Transaction
			O I IVII	- Total				\$6,368.25	
			Construction	Stockpile S	TMI - Tota			\$6,368.25	
	0520 -	Total						\$0.00	
	0530	MGS GUARDRAIL, 8 FT. POSTS, 6	Construction Stockpile		8	Aug 4, 2025	SYSTEM	(\$1,480.71)	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT 3 IN			9	Aug 18, 2025	SYSTEM	(\$11,105.36)	Payment Estimate Item Adjustment generated Stockpile Transaction



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
L0077	0530	MGS GUARDRAIL, 8 FT. POSTS, 6	Construction Stockpile		10	Sep 2, 2025	SYSTEM	(\$24,801.96)	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT 3 IN			11	Sep 17, 2025	SYSTEM	(\$925.45)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$38,313.48)	
			Construction	Stockpile - 1	Total			(\$38,313.48)	
			Construction Stockpile STMA		1	Apr 16, 2025	SYSTEM	\$28,694.38	Payment Estimate Item Adjustment generated Stockpile Transaction
			O TIVIS C	- Total				\$28,694.38	
			Construction	Stockpile S	TMA - Tota	ıl		\$28,694.38	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$9,626.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$9,626.50	
			Construction	Stockpile S	TMI - Total			\$9,626.50	
	0530 -							\$7.40	
	0540	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		10	Sep 2, 2025	SYSTEM	(\$5,208.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					11	Sep 17, 2025	SYSTEM	(\$1,736.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 1 11	- Total				(\$6,944.00)	
			Construction	Stockpile -		A== 40	OVOTEM	(\$6,944.00)	Description to the Adjustment approach of Otto India Torons attention
			Construction Stockpile STMI	- Total	1	Apr 16, 2025	SYSTEM	\$6,944.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		TML Total			\$6,944.00 \$6,944.00	
	0540 -	Total	Construction	i Stockpile S	rivii - rotai			\$0.00	
	0550	MGS VERTICAL	Construction		8	Aug 4,	SYSTEM	(\$3,472.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	0330	CONCRETE BARRIER	Stockpile		9	2025 Aug 18,	SYSTEM	(\$1,736.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		TRANSITION		- Total		2025	0.0.2	(\$5,208.00)	System Example 16th Against goldender Scottput Halleston
			Construction	Stockpile - 1	Total			(\$5,208.00)	
			Construction Stockpile		1	Apr 16, 2025	SYSTEM	\$5,208.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$5,208.00	
			Construction	Stockpile S	TMI - Total			\$5,208.00	
	0550 -	Total						\$0.00	
	0560	MGS END ANCHOR	Construction Stockpile		7	Jul 16, 2025	SYSTEM	(\$650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Aug 4, 2025	SYSTEM	(\$650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					9	Aug 18, 2025	SYSTEM	(\$650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,950.00)	
			Construction	Stockpile - 1				(\$1,950.00)	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$1,950.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,950.00	
			Construction	Stockpile S	TMI - Total			\$1,950.00	
	0560 -		O-mat "		7	Ind 40	OVOTEL	\$0.00	Demonstratives to the set Adhertment and the Colon St. T
	0570	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		7	Jul 16, 2025	SYSTEM	(\$1,850.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			8	Aug 4, 2025	SYSTEM	(\$9,250.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					9	Aug 18, 2025	SYSTEM	(\$11,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					10	Sep 2, 2025	SYSTEM	(\$12,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



SECONT STATE Contraction 11 Sec. 17	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Construction	JSL0077	0570	CRASHWORTHY			11		SYSTEM	(\$5,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction 1 Apr 16, SYSTEM 2008 SYSTEM 340,700.00 Payment Estmate from Adjustment generated Stockpile Transaction 140,700.00					- Total				(\$40,700.00)	
Stockpile STM 1-total 1-tota				Construction	Stockpile - 1	Γotal			(\$40,700.00)	
Total				Stockpile		1		SYSTEM	\$40,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction
10 20 20 20 20 20 20 20				STIVII	- Total				\$40,700.00	
Process of Concount 2 Process of Concount 2 Process of Concount 3 Proc				Construction	Stockpile S	ГМI - Tota			\$40,700.00	
2025 2025		0570 -	- Total						\$0.00	
This adjustment offices the original system generated Material Psyment Estimate Exception 3 or to the current Psyment Estimate Extended Figure Estimate Exception 3 or to the current Psyment Estimate Extended Figure Estimate Exception 3 or to the current Psyment Estimate Extended Figure Estimate Exception 3 or to the current Psyment Estimate Extended Figure Estimate Exception 3 or to the current Psyment Estimate Extended Figure Estimate Exception 3 or to the current Psyment Estimate Exception 3 or to the current Psyment Estimate Extended Figure Estimate Exception 3 or to the current Psyment Estimate Exception 3 or to the current Psyment Estimate Exception 1 or to the Estimate Exception 1 or to the Estimate Exception 1 or to the current Psyment Estimate Exception 1 o		0710	TRENCH WITH	Material		7		SYSTEM	(\$392.00)	
2025 SySTEM S382.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 32 on the current Payment Estimate Exc			TRACER WIRE			7		SYSTEM	\$392.00	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment
2025 Estimate Exception 32 on the current Payment Estimate Payment Estimate Payment Estimate Payment Pay						8		SYSTEM	(\$392.00)	
10 Sep 2, 2 SYSTEM \$392.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 34 on the current Payment Estimate Exception 34 on the current Payment Estimate Exception 34 on the current Payment Estimate Extended Exception 34 on the current Payment Estimate Exception 32 on the current Payment Estimate Exception 33 on the current Payment Estimate Exception 33 on the current Payment Estimate Exception 34 on the current Payment Estimate Exception 35 on the current Payment Estimate Extended Extended Extended Extended Extended Exception 35 on the current Payment Estimate Exc						8		SYSTEM	\$392.00	Estimate Item Adjustment (0023) due to user estopn1 overridding Payment
2025 System Signature						9		SYSTEM	(\$392.00)	
2025 10 Sep 2 2026 2						9		SYSTEM	\$392.00	Estimate Item Adjustment (0025) due to user estopn1 overridding Payment
10						10		SYSTEM	(\$392.00)	
Sep 17, SySTEM Sag 2.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 32 on the current Payment Estimate.						10		SYSTEM	\$392.00	Estimate Item Adjustment (0023) due to user estopn1 overridding Payment
Condition Section Se						11		SYSTEM	(\$392.00)	
National Parameter Society Street Society Street Society Street Stre						11		SYSTEM	\$392.00	Estimate Item Adjustment (0029) due to user estopn1 overridding Payment
Solution					- Total				\$0.00	
CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6				Material - To	tal				\$0.00	
TRENCH WITH TRACER WIRE 2025		0710 -	- Total						\$0.00	
System S		0720	TRENCH WITH	Material		6		SYSTEM	(\$240.00)	
7 Jul 16, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 8 Aug 4, 2025 SYSTEM (\$1,664.00) 8 Aug 4, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, 2025 SYSTEM (\$1,664.00) 9 Aug 18, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, 2025 SYSTEM (\$1,664.00) 10 Sep 2, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.			TRACER WIRE			6		SYSTEM	\$240.00	Estimate Item Adjustment (0006) due to user estopn1 overridding Payment
Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Aug 4, 2025 8 Aug 4, 2025 8 YSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, 2025 9 Aug 18, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, 2025 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.						7		SYSTEM	(\$1,664.00)	
8 Aug 4, 2025 \$\frac{1}{2025}\$ \$\frac{1}						7		SYSTEM	\$1,664.00	Estimate Item Adjustment (0009) due to user estopn1 overridding Payment
Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate. 9 Aug 18, 2025 9 Aug 18, 2025 10 Sep 2, 2025 SYSTEM (\$1,664.00) 10 Sep 2, 2025 SYSTEM (\$1,664.00) 10 Sep 2, 2025 This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate. 10 This adjustment offsets the original system-generated Material Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, 2025 SYSTEM \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.						8		SYSTEM	(\$1,664.00)	
9 Aug 18, 2025 \$\frac{1}{2025}\$ \$1						8		SYSTEM	\$1,664.00	Estimate Item Adjustment (0024) due to user estopn1 overridding Payment
Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 10 Sep 2, 2025 10 Sep 2, 2025 \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.						9		SYSTEM	(\$1,664.00)	
2025 10 Sep 2, 2025 \$1,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.						9		SYSTEM	\$1,664.00	Estimate Item Adjustment (0026) due to user estopn1 overridding Payment
2025 Estimate Item Adjustment (0024) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.						10		SYSTEM	(\$1,664.00)	
11 Sep 17 SYSTEM (\$1.664.00)						10		SYSTEM	\$1,664.00	Estimate Item Adjustment (0024) due to user estopn1 overridding Payment
2025 (\$1,004.00)						11	Sep 17, 2025	SYSTEM	(\$1,664.00)	



	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Type	Adjustment Type	Number	Date	Ву		
JSL0077	0720	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		11	Sep 17, 2025	SYSTEM	\$1,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0720				0	1.14	OVOTELA	\$0.00	
	0730	CONDUIT, 3 IN., PUSHED WITH	Material		6	Jul 1, 2025	SYSTEM	(\$2,128.00)	
		TRACER WIRE			6	Jul 1, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$2,128.00)	
					7	Jul 16, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$2,128.00)	
					8	Aug 4, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user estopn1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$2,128.00)	
					9	Aug 18, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$2,128.00)	· · · · · · · · · · · · · · · · · · ·
					10	Sep 2, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user estopn1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$2,128.00)	
					11	Sep 17, 2025	SYSTEM	\$2,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0730 -	Total						\$0.00	
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6	Jul 1, 2025	SYSTEM	\$0.00 (\$106.60)	
		CABLE, 10 AWG 1	Material		6		SYSTEM SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		CABLE, 10 AWG 1 CONDUCTOR,	Material			2025 Jul 1,		(\$106.60)	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6	2025 Jul 1, 2025 Jul 16,	SYSTEM	(\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment
		CABLE, 10 AWG 1 CONDUCTOR,	Material		7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16,	SYSTEM	(\$106.60) \$106.60 (\$106.60)	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7 8	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7 8 8 8	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60)	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7 8 8 8 9	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60)	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment
		CABLE, 10 AWG 1 CONDUCTOR,	Material		6 7 7 8 8 8 9 9 9	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60) \$106.60 (\$106.60)	Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0740	CARLE 40 AWG 4	Material	Туре		2025			
J3L0077	0740	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC	Material		11	Sep 17, 2025	SYSTEM	\$106.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0740 -	Total						\$0.00	
	0800	PULL BOX, PREFORMED CLASS 2	Material		7	Jul 16, 2025	SYSTEM	(\$10,350.00)	
		OLAGO Z			7	Jul 16, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$10,350.00)	
					8	Aug 4, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$10,350.00)	
					9	Aug 18, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$10,350.00)	
					10	Sep 2, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$10,350.00)	
					11	Sep 17, 2025	SYSTEM	\$10,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0800 -						01/0==1/	\$0.00	
	0810	PULL BOX, PREFORMED CLASS 3	Material		6	Jul 1, 2025	SYSTEM	(\$2,784.00)	
					6	Jul 1, 2025	SYSTEM	\$2,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user estopn1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$5,568.00)	
					7	Jul 16, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$5,568.00)	
					8	Aug 4, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$5,568.00)	
					9	Aug 18, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user estopn1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$5,568.00)	
					10	Sep 2, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$5,568.00)	
					11	Sep 17, 2025	SYSTEM	\$5,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 37 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	0810	PULL BOX, PREFORMED	Material	- Total				\$0.00	
		CLASS 3	Material - To	tal				\$0.00	
	0810 -	- Total						\$0.00	
	0940	2 IN. PSST POST - 12 GA.	Construction Stockpile		5	Jun 16, 2025	SYSTEM	\$2,332.58	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$2,332.58	
			Construction	1 Stockpile S	TMI - Tota			\$2,332.58	
	0940	- Total						\$2,332.58	
	0950	DRIVEN POST ANCHOR FOR 2	Construction Stockpile		5	Jun 16, 2025	SYSTEM	\$868.70	Payment Estimate Item Adjustment generated Stockpile Transaction
		IN. PSST - 12 GA.	STMI	- Total				\$868.70	
			Construction	n Stockpile S	TMI - Total			\$868.70	
	0950	- Total						\$868.70	
	0960	SH-FLAT SHEET	Construction Stockpile		5	Jun 16, 2025	SYSTEM	\$2,623.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$2,623.50	
			Construction	n Stockpile S	TMI - Total			\$2,623.50	
	0960	- Total						\$2,623.50	
	0970	ST-STRUCTURAL	Construction Stockpile		5	Jun 16, 2025	SYSTEM	\$1,288.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,288.80	
			Construction	1 Stockpile S	TMI - Tota			\$1,288.80	
	0970	- Total						\$1,288.80	
	0980	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile		5	Jun 16, 2025	SYSTEM	\$1,904.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,904.00	
			Construction	Ota almila O	TMI Total			\$1,904.00	
			Construction	n Stockpile S	i wii - Tota			φ1,304.00	
	0980	- Total	Construction	1 Stockpile S	TIVII - TOTA			\$1,904.00	
		-Total MISC. ITS	Material	1 Stockpile S	6	Jul 1, 2025	SYSTEM		
				1 Stockpile S		Jul 1,	SYSTEM SYSTEM	\$1,904.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				1 Stockpile S	6	Jul 1, 2025 Jul 1,		\$1,904.00 (\$2,350.00)	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment
				1 Stockpile S	6	Jul 1, 2025 Jul 1, 2025 Jul 16,	SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment
				1 Stockpile S	6 6 7	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00)	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
				1 Stockpile S	6 6 7 7	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025	SYSTEM SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment
				1 Stockpile S	6 6 7 7	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00)	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment
				1 Stocкрие S	6 6 7 7 8 8	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment
				1 Stocкрие S	6 6 7 7 8 8	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment
				1 Stockpile S	6 6 7 7 8 8 8	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00)	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment
				1 Stockpile S	6 6 7 7 8 8 8 9 9	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00)	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate.
				1 Stockpile S	6 6 7 7 8 8 8 9 9	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00)	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate.
				- Total	6 6 7 7 8 8 8 9 9	Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 17,	SYSTEM	\$1,904.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00) \$2,350.00 (\$2,350.00)	Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user estopn1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 38 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	1060 -	- Total		Туре				\$0.00	
	1120	MISC. ITS	Material		6	Jul 1, 2025	SYSTEM	(\$2,754.00)	
					6	Jul 1, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$2,754.00)	
					7	Jul 16, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$2,754.00)	
					8	Aug 4, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user estopn1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$2,754.00)	
					9	Aug 18, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$2,754.00)	
					10	Sep 2, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user estopn1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$2,754.00)	
					11	Sep 17, 2025	SYSTEM	\$2,754.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user estopn1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				- Total				\$0.00	
	4400	Tabel	Material - To					\$0.00	
		-Total MISC. ITS	Material - To		6	Jul 1,	SYSTEM		
					6	Jul 1, 2025 Jul 1, 2025	SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Fetimate Fycention 22 on the current Payment Fetimate.
						2025 Jul 1, 2025 Jul 16,		\$0.00 \$0.00 (\$140.00)	
					6	2025 Jul 1, 2025	SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment
					6	Jul 1, 2025 Jul 16, 2025 Jul 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00 (\$532.00)	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment
					6 7 7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00 (\$532.00) \$532.00	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment
					6 7 7	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00 (\$532.00) \$532.00	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment
					6 7 7 8 8 8	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00 (\$532.00) \$532.00 (\$532.00)	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment
					6 7 7 8 8 8 9	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00 (\$532.00) \$532.00 (\$532.00) (\$532.00)	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment
					6 7 7 7 8 8 8 9 9 9	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00 (\$532.00) \$532.00 (\$532.00) (\$532.00) \$532.00	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment
					6 7 7 8 8 8 9 9 10	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00 (\$532.00) \$532.00 (\$532.00) \$532.00 (\$532.00)	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 42 on the current Payment Estimate.
					6 7 7 7 8 8 8 9 9 10 10 10	2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 17,	SYSTEM	\$0.00 \$0.00 (\$140.00) \$140.00 (\$532.00) \$532.00 (\$532.00) \$532.00 (\$532.00) \$532.00 (\$532.00)	Estimate Item Adjustment (0012) due to user estopn1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user estopn1 overridding Payment Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 42 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0077	1130	MISC. ITS	Material - To	tal				\$0.00	
	1130 -							\$0.00	
	1150	MISC. GUARDRAIL ITEM	Material		7	Jul 16, 2025	SYSTEM	(\$3,778.50)	
					7	Jul 16, 2025	SYSTEM	\$3,778.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$11,451.00)	
					8	Aug 4, 2025	SYSTEM	\$11,451.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$29,865.00)	
					9	Aug 18, 2025	SYSTEM	\$29,865.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$29,865.00)	
					10	Sep 2, 2025	SYSTEM	\$29,865.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$29,865.00)	
					11	Sep 17, 2025	SYSTEM	\$29,865.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user estopn1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1150 -	- Total						\$0.00	
	1160	CONDUIT, 2 IN. RIGID, IN TRENCH	Material		6	Jul 1, 2025	SYSTEM	(\$630.00)	
		TRENOT			6	Jul 1, 2025	SYSTEM	\$630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Jul 16,	SYSTEM	(4 (100 00)	
						2025		(\$1,400.00)	
					7	Jul 16, 2025	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Jul 16,	SYSTEM SYSTEM		Estimate Item Adjustment (0018) due to user estopn1 overridding Payment
						Jul 16, 2025 Aug 4,		\$1,400.00	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment
					8	Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM	\$1,400.00 (\$1,400.00)	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment
					8	Jul 16, 2025 Aug 4, 2025 Aug 4, 2025	SYSTEM SYSTEM	\$1,400.00 (\$1,400.00) \$1,400.00	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment
					8 8	Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Aug 18,	SYSTEM SYSTEM SYSTEM	\$1,400.00 (\$1,400.00) \$1,400.00	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment
					8 8 9	Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00)	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment
					8 8 9 9	Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00) (\$1,400.00)	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment
					8 8 9 9 10	Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00) (\$1,400.00) \$1,400.00	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment
				- Total	8 8 9 9 10 10 11 11	Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00)	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate.
			Material - Tol		8 8 9 9 10 10 11 11	Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00) (\$1,400.00) \$1,400.00	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate.
	1160 -	-Total	Material - Tot		8 8 9 9 10 10 11 11	Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00) \$1,400.00 (\$1,400.00) \$1,400.00 \$1,400.00	Estimate Item Adjustment (0018) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user estopn1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user estopn1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate.



Droinet	Lina	Doggrintian	A director on t	Other	Est.	Crostad	Created	Amerint	Domestre
Project	Line	Description	Adjustment Type	Adjustment Type	Number	Created Date	By	Amount	Remarks
JSL0077	1170	2, 240/120	Material		7	Jul 16, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user estopn1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$15,600.00)	
					8	Aug 4, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$15,600.00)	
					9	Aug 18, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user estopn1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$15,600.00)	
					10	Sep 2, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$15,600.00)	
					11	Sep 17, 2025	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user estopn1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1170 -	Total						\$0.00	
JSL0077	- Total							(\$237,277.12)	
JSL0080	1280	MISC. SHAPING SLOPES	Material		2	May 2, 2025	SYSTEM	(\$2,000.00)	
					2	May 2, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 16, 2025	SYSTEM	(\$8,750.00)	
					3	May 16, 2025	SYSTEM	\$8,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 2, 2025	SYSTEM	(\$8,750.00)	
					4	Jun 2, 2025	SYSTEM	\$8,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1280 -	Total						\$0.00	
	1300	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Other Item Adjustment	FUEL	2	May 2, 2025	schirj1	\$5,266.58	BP1 AC INDEX from 4/15 to 4/26
		. 504 22 (DI -1)		FUEL - Tota	ıl			\$5,266.58	
			Other Item A	djustment - T	otal			\$5,266.58	
			Overrun	Overrun	2	May 2, 2025	SYSTEM	(\$164,432.00)	
					8	Aug 4, 2025	SYSTEM	\$164,432.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',80.00000 - 80.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	1300 -	Total						\$5,266.58	
	1320	CHANGEABLE MESSAGE SIGN WITHOUT	Material		1	Apr 16, 2025	SYSTEM	(\$6,000.00)	
		COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /			1	Apr 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		RETAINED			2	May 2,	SYSTEM	(\$6,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
JSL0080	1320	CHANGEABLE	Material			2025									
		MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE,			2	May 2, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
		CONTRACTOR FURNISHED / RETAINED			3	May 16, 2025	SYSTEM	(\$6,000.00)							
					3	May 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					4	Jun 2, 2025	SYSTEM	(\$6,000.00)							
					4	Jun 2, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
				- Total				\$0.00							
			Material - To	tal				\$0.00							
	1320	Total						\$0.00							
	1330	MISC.	Material		1	Apr 16, 2025	SYSTEM	(\$2,401.00)							
											1	Apr 16, 2025	SYSTEM	\$2,401.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	May 2, 2025	SYSTEM	(\$2,401.00)							
						2	May 2, 2025	SYSTEM	\$2,401.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
											3	May 16, 2025	SYSTEM	(\$2,401.00)	
		2025 Estimate Item Adjustment (000		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user estopn1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					4	Jun 2, 2025	SYSTEM	(\$2,401.00)							
					4	Jun 2, 2025	SYSTEM	\$2,401.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user estopn1 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
				- Total				\$0.00							
			Material - To	tal				\$0.00							
	1330	- Total						\$0.00							
	1350	PREF THERMO PVMT MARK, 24 IN WHIT	Material		4	Jun 2, 2025	SYSTEM	(\$1,200.00)							
		IIN VVIII I			4	Jun 2, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user estopn1 overridding Payment Estimate Exception 15 on the current Payment Estimate.						
					5	Jun 16, 2025	SYSTEM	(\$1,200.00)							
					5	Jun 16, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					6	Jul 1, 2025	SYSTEM	(\$1,200.00)							
					6	Jul 1, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user estopn1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					7	Jul 16, 2025	SYSTEM	(\$1,200.00)							
					7	Jul 16, 2025	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					8	Aug 4, 2025	SYSTEM	(\$1,750.00)							
					8	Aug 4, 2025	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user estopn1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						



350 PREF THERMO PVMT MARK, 24 IN WHIT	verridding Payment laterial Payment verridding Payment laterial Payment
Aug 18, 2025 SYSTEM \$1,750.00 This adjustment offsets the original system-generated Measurement (0037) due to user estopn1 over Estimate Exception 11 on the current Payment Estimate. 10	verridding Payment laterial Payment verridding Payment laterial Payment
2025 10 Sep 2, 2025 \$YSTEM \$425.00 This adjustment offsets the original system-generated Magastimate Exception 11 on the current Payment Estimate. 11 Sep 17, 2025 \$YSTEM \$425.00 This adjustment offsets the original system-generated Magastimate Exception 11 on the current Payment Estimate. 11 Sep 17, 2025 \$YSTEM \$425.00 This adjustment offsets the original system-generated Magastimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Exception 11 on the current Payment Estimate. 11 \$0.00 This adjustment offsets the original system-generated Magastimate Item Adjustment (0041) due to user estopn1 over Estimate Exception 11 on the current Payment Estimate. 2025 \$0.00 This adjustment offsets the original system-generated Magastimate Item Adjustment offsets the original system-generated Magastimate Item Adjustment offsets the original system-generated Magastimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) due to user estopn1 over Estimate Item Adjustment (0041) d	verridding Payment . laterial Payment verridding Payment
2025 Estimate Item Adjustment (0039) due to user estopn1 over Estimate Exception 11 on the current Payment Estimate. 11 Sep 17, 2025 12 Sep 17, 2025 13 Sep 17, 2025 14 Sep 17, 2025 15 Sep 17, 2025 16 Sep 17, 2025 17 Sep 17, 2025 18 Sep 17, 2025 19 Sep 17, 2025 10 Sep 17, 2025 11 Sep	verridding Payment . laterial Payment verridding Payment
2025 11 Sep 17, SYSTEM \$425.00 This adjustment offsets the original system-generated Me Estimate Item Adjustment (0041) due to user estopn1 ove Estimate Exception 11 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 Overrun Overrun 8 Aug 4, SYSTEM (\$550.00)	erridding Payment
2025 Estimate Item Adjustment (0041) due to user estopn1 over Estimate Exception 11 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 Overrun Overrun 8 Aug 4, SYSTEM (\$550.00)	erridding Payment
Material - Total \$0.00 Overrun 8 Aug 4, SYSTEM (\$550.00)	
Overrun Overrun 8 Aug 4, SYSTEM (\$550.00)	
10 Sep 2, 2025 SYSTEM \$550.00 Unit price based on averaged overrun adjustments for ins previous payment estimates. Price Adjustments of ',25.00 applied (if non-zero).	
Overrun - Total \$0.00	
Overrun - Total \$0.00	
1350 - Total \$0.00	
1360 PREF THERMO Material 8 Aug 4, SYSTEM (\$675.00) PVMT MARK, 2025	
LT/RT ARROW 8 Aug 4, SYSTEM \$675.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0038) due to user estopn1 ov Estimate Exception 12 on the current Payment Estimate.	erridding Payment
9 Aug 18, SYSTEM (\$675.00)	
9 Aug 18, SYSTEM \$675.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0038) due to user estopn1 over Estimate Exception 14 on the current Payment Estimate.	erridding Payment
10 Sep 2, SYSTEM (\$675.00)	
10 Sep 2, 2025 SYSTEM \$675.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0035) due to user estopn1 over Estimate Exception 14 on the current Payment Estimate.	verridding Payment
11 Sep 17, SYSTEM (\$675.00)	
11 Sep 17, 2025 SYSTEM \$675.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0042) due to user estopn1 over Estimate Exception 14 on the current Payment Estimate.	verridding Payment
- Total \$0.00	
Material - Total \$0.00	
1360 - Total \$0.00	
1380 PREF THERMO Material 4 Jun 2, SYSTEM (\$750.00) PVMT MARK, YIELD TRIAN	
4 Jun 2, 2025 SYSTEM \$750.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0009) due to user estopn1 over Estimate Exception 16 on the current Payment Estimate.	erridding Payment
5 Jun 16, SYSTEM (\$750.00)	
5 Jun 16, SYSTEM \$750.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0014) due to user estopn1 ove Estimate Exception 9 on the current Payment Estimate.	
6 Jul 1, SYSTEM (\$750.00)	
6 Jul 1, SYSTEM \$750.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0015) due to user estopn1 over Estimate Exception 9 on the current Payment Estimate.	
7 Jul 16, SYSTEM (\$750.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0080	1380	PREF THERMO PVMT MARK, YIELD TRIAN	Material	Type .	7	Jul 16, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user estopn1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$750.00)	
					8	Aug 4, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$750.00)	
					9	Aug 18, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$750.00)	
					10	Sep 2, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$750.00)	
					11	Sep 17, 2025	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total					OVOTEM	\$0.00	
	1390	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		4	Jun 2, 2025	SYSTEM	(\$7,085.20)	
					4	Jun 2, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user estopn1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$7,085.20)	
					5	Jun 16, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$7,085.20)	
					6	Jul 1, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$7,085.20)	
					7	Jul 16, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user estopn1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$7,085.20)	
					8	Aug 4, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user estopn1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$7,085.20)	
					9	Aug 18, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user estopn1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$7,085.20)	
					10	Sep 2, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user estopn1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					11	Sep 17, 2025	SYSTEM	(\$7,085.20)	
					11	Sep 17, 2025	SYSTEM	\$7,085.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user estopn1 overridding Payment Estimate Exception 26 on the current Payment Estimate.



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
SL0080	1390	4 IN. YELLOW HIGH BUILD WATERBORNE	Material	- Total				\$0.00	
		PAVEMENT MARKING PAINT,	Material - To	tal				\$0.00	
		TYPE L BEADS							
	1390 -	Total						\$0.00	
		4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Jun 2, 2025	SYSTEM	(\$5,715.40)	
					4	Jun 2, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user estopn1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$5,715.40)	
					5	Jun 16, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$5,715.40)	
					6	Jul 1, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Jul 16, 2025	SYSTEM	(\$5,715.40)	
					7	Jul 16, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user estopn1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$5,715.40)	
					8	Aug 4, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user estopn1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					9	Aug 18, 2025	SYSTEM	(\$5,715.40)	
					9	Aug 18, 2025	SYSTEM	\$5,715.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user estopn1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1410 -	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	2	May 2, 2025	SYSTEM	\$0.00 (\$2,905.70)	
					8	Aug 4, 2025	SYSTEM	\$2,905.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.45000 - 2.45000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	, , ,
			Overrun - Total					\$0.00	
	1410 -	Total						\$0.00	
	1470	MGS GUARDRAIL	Construction Stockpile		2	May 2, 2025	SYSTEM	(\$2,274.38)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 16, 2025	SYSTEM	(\$11,675.12)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$13,949.50)	
			Construction	Stockpile - 1	Total			(\$13,949.50)	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$13,949.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$13,949.50	
			Construction	Stockpile S	ГМI - Total			\$13,949.50	
1470 - Total									
		MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile		2	May 2, 2025	SYSTEM	(\$2,221.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,221.50)	
			Construction	Stockpile - 1	Total			(\$2,221.50)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0080	1480	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile		1	Apr 16, 2025	SYSTEM	\$2,221.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$2,221.50	
			Construction Stockpile STMI - Total					\$2,221.50	
	1480 -	Total						\$0.00	
	1490	MGS BR APP TRANSITION (THRIE-BEAM BRIDGE	Construction Stockpile		2	May 2, 2025	SYSTEM	(\$3,840.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 16, 2025	SYSTEM	(\$3,840.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$7,680.00)	
			Construction	onstruction Stockpile - Total					
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$7,680.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$7,680.00	
			Construction	Stockpile S	ГМI - Total			\$7,680.00	
	1490 -	Total						\$0.00	
	1500	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	May 2, 2025	SYSTEM	(\$7,400.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 16, 2025	SYSTEM	(\$22,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$29,600.00)	
			Construction	Construction Stockpile - Total				(\$29,600.00)	
			Construction Stockpile STMI		1	Apr 16, 2025	SYSTEM	\$29,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$29,600.00	
			Construction	Construction Stockpile STMI - Total					
		1500 - Total							
	1540	2.5 IN. PSST POST - 12 GA.	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$369.28 \$369.28	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 1 11	- Total Construction Stockpile STMI - Total					
			Construction	Stockpile S	MI - Total			\$369.28	
	1540 -	DRIVEN POST ANCHOR FOR 2.5	Construction Stockpile		5	Jun 16, 2025	SYSTEM	\$369.28 \$360.78	Payment Estimate Item Adjustment generated Stockpile Transaction
		IN. PSST - 7 GA.	STMI	- Total				\$360.78	
			Construction Stockpile STMI - Total					\$360.78	
	1550 -	Total						\$360.78	
	1560	SH-FLAT SHEET	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$1,237.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,237.50	
			Construction	Stockpile ST	ΓΜΙ - Total			\$1,237.50	
	1560 -	Total						\$1,237.50	
	1570	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile STMI		5	Jun 16, 2025	SYSTEM	\$100.80	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$100.80	
			Construction	Stockpile S1	ΓΜΙ - Total			\$100.80 \$100.80	
		1570 - Total							
JSL0080 -	- Total							\$7,334.94	
Overall -	Total							(\$229,942.18)	

MoDOT

Contract Adjustments for Contract - 241115-F10

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 37 of 37