\$336,521.64



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2025

| Progress Estimate Number 12 | Contract ID Prime Contracto | 250117-l r Gershen | F03 son Construction Co., | | Pay Period Start Pay Period End | | er 2, 2025 er 15, 2025 | Original Contract Amount Net Change Order Amount Current Contract Amount | \$4,314,702.92 (\$93,523.52) \$4,221,179.40 |
|-----------------------------------|--------------------------------|-----------------------|------------------------------|---------|------------------------------------|-------------|---------------------------|--|---|
| Approval Date | | | | | | | | | By User |
| September 16, 2025 | | | Generated and | Approv | red (and should b | e considere | ed Draft) at | the Project Office Level by | litzam |
| September 16, 2025 | | | Reviewed and Appr | oved (a | and should be co | nsidered Dr | aft) at the F | Resident Engineer Level by | wolkt1 |
| September 18, 2025 | | | | Reviev | ved and Approve | d at the Ce | ntral Office | Controllers Office Level by | ramses1 |
| Original Completi | on Date | Current C | ompletion Date | Ad | tual Completion | n Date | % | of Current Contract Amount | Complete |
| December 1, 2 | 2025 | Decen | nber 1, 2025 | | | | | 59.83% | |
| | Contra | ct Informa | tional Dates | | | | | Milestones | |
| Date Description | Original Compl | etion Date | Current Completion | Date | | No Miles | tones Exis | t for Contract | |
| Acceptance Date | | | | | | | | | |
| Awarded Date | February 5, 2025 | 5 | February 5, 2025 | | | | | | |
| Letting Date | January 17, 202 | 5 | January 17, 2025 | | | | | | |
| Notice to Proceed Date | March 10, 2025 | | March 10, 2025 | | | | | | |
| Work Began Date | April 14, 2025 | | April 14, 2025 | | | | | | |

| Contract Total Pa | ay For Estimate No. 12 | | | |
|--------------------------|----------------------------|---------------|----------------|----------------|
| | | This Estimate | Previous | To Date |
| 250117-F03 | | | | |
| | Total Posted Items Pay | \$336,521.64 | \$2,189,110.92 | \$2,525,632.56 |
| | Gross Item Adjustments | \$11,511.62 | (\$63.62) | \$11,448.00 |
| | Incentive | \$0.00 | \$0.00 | \$0.00 |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 |
| | | | \$2,189,047.30 | \$2,537,080.56 |
| Contract Total Pa | ayable This Estimate: | \$348.033.26 | | |

Items Paid This Estimate Period

Overall - Total

Contract Adjustments This Estimate

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|---|------|---------------|--------------------------|-----------------------------|
| JSL0078 | 0180 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | LS | \$25,000.000 | 0.500 | \$12,500.00 |
| | 0190 | 6181000 | MOBILIZATION | LS | \$100,000.000 | 0.250 | \$25,000.00 |
| | 0340 | 8025006 | MULCHING | ACRE | \$1,800.000 | 0.450 | \$810.00 |
| | 0350 | 8051000A | SEEDING - COOL SEASON GRASSES | ACRE | \$3,000.000 | 0.450 | \$1,350.00 |
| Project JS | L0078 - To | otal | | | | | \$39,660.00 |
| JSL0121 | 0470 | 2022010 | REMOVAL OF IMPROVEMENTS | LS | \$225,000.000 | 0.200 | \$45,000.00 |
| | 0480 | 2031000 | CLASS A EXCAVATION | CUYD | \$38.000 | 500 | \$19,000.00 |
| | 0560 | 4019905 | MISC.OPTIONAL PAVEMENT | SQYD | \$130.000 | 740.900 | \$96,317.00 |
| | 0600 | 6044013 | PIPE COLLAR, TYPE C | EA | \$2,700.000 | 1 | \$2,700.00 |
| | 0610 | 6083006 | 6 IN. CONCRETE MEDIAN STRIP | SQYD | \$140.000 | 19.800 | \$2,772.00 |
| | 0720 | 6131017 | DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR | EA | \$10.000 | 11 | \$110.00 |
| | 0810 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | LS | \$25,000.000 | 0.500 | \$12,500.00 |
| | 0820 | 6173600D | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | LF | \$26.000 | 1,362.500 | \$35,425.00 |
| | 1150 | 6061060 | MGS GUARDRAIL | LF | \$28.500 | 2,512 | \$71,592.00 |
| | 5102 | 6141121 | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | EA | \$2,950.000 | 1 | \$2,950.00 |
| | 5104 | 7319902 | MISC.Cast In Place Concrete Inlet, 6 Ft. X 6 Ft. | EA | \$33,982.570 | 0.250 | \$8,495.64 |
| Project JS | L0121 - To | otal | | | | | \$296,861.64 |

Revision 9/2/2025 Page 1 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2025

Pay Period Start September 2, 2025 Pay Period End September 15, 2025 September 15, 2025 Original Contract Amount Net Change Order Amount Current Contract Amount \$4,314,702.92 (\$93,523.52) \$4,221,179.40 250117-F03 Contract ID **Progress** Estimate Number Prime Contractor Gershenson Construction Co., Inc.

No Contract Adjustments Exist on Contract

| D 1 : | | | A 11 | 011 | | A 11 | | A 11 |
|-------------------|-------------|---|--------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| JSL0078 | 0800 | CONCRETE PAVEMENT (11 INCH NON-REINFORCED) | Material | | | -167.60000 | \$370.00 | (\$62,012.00 |
| | 0080 | CONCRETE PAVEMENT (11 INCH NON-REINFORCED) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user litzam overridding Payment Estimate Exception 7 on the current Payment Estimate. | 167.60000 | \$370.00 | \$62,012.00 |
| | 0090 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | Material | | | -69.60000 | \$370.00 | (\$25,752.00 |
| | 0090 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user litzam overridding Payment Estimate Exception 13 on the current Payment Estimate. | 69.60000 | \$370.00 | \$25,752.00 |
| | 0100 | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -4 | \$1.00 | (\$4.00 |
| | 0130 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -19 | \$10.00 | (\$190.00 |
| | 0340 | MULCHING | Material | | | -0.45000 | \$1,800.00 | (\$810.00 |
| | 0340 | MULCHING | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user litzam overridding Payment Estimate Exception 18 on the current Payment Estimate. | 0.45000 | \$1,800.00 | \$810.00 |
| | 0350 | SEEDING - COOL SEASON GRASSES | Material | | | -0.45000 | \$3,000.00 | (\$1,350.00 |
| | 0350 | SEEDING - COOL SEASON GRASSES | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user litzam overridding Payment Estimate Exception 19 on the current Payment Estimate. | 0.45000 | \$3,000.00 | \$1,350.00 |
| | 5001 | MGS GUARDRAIL | Material | | | -2,925 | \$28.50 | (\$83,362.50 |
| | 5001 | MGS GUARDRAIL | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user litzam overridding Payment Estimate Exception 10 on the current Payment Estimate. | 2,925 | \$28.50 | \$83,362.50 |
| JSL0121 | 0490 | EMBANKMENT IN PLACE | Material | | | -4,099 | \$38.00 | (\$155,762.00) |
| | 0490 | EMBANKMENT IN PLACE | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate. | 4,099 | \$38.00 | \$155,762.00 |
| | 0540 | TYPE A2 SHOULDER | Material | | | -875.60000 | \$72.00 | (\$63,043.20) |
| | 0540 | TYPE A2 SHOULDER | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate. | 875.60000 | \$72.00 | \$63,043.20 |
| | 0560 | MISC. | Material | | | -4,173.20000 | \$130.00 | (\$542,516.00) |
| | 0560 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Exception 3 on | 4,173.20000 | \$130.00 | \$542,516.00 |

Revision 9/2/2025 Page 2 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2025

| Estimat | gress e Num 12 | | 117-F03 shenson Constr | ruction Co., Ir | nc. Pay Period End September 15, 2025 | Original Contrac Net Change Ordo Current Contrac | er Amount | \$4,314,702.92 (\$93,523.52 \$4,221,179.40 |
|-------------------|----------------------|--|---------------------------|----------------------------------|---|--|---------------------------------------|--|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| SL0121 | | | | | the current Payment Estimate. | | | |
| | 0610 | 6 IN. CONCRETE MEDIAN STRIP | Overrun | | | -5.20000 | \$140.00 | (\$728.00) |
| | 0620 | FURNISHING TYPE 2 ROCK DITCH LINER | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',56.00000 - 56.00000, 'is applied (if non-zero). | 112 | \$56.00 | \$6,272.00 |
| | 0630 | PLACING TYPE 2 ROCK DITCH LINER | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',28.00000 - 28.00000, 'is applied (if non-zero). | 112 | \$28.00 | \$3,136.00 |
| | 0680 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | Material | | | -28.60000 | \$500.00 | (\$14,300.00) |
| | 0680 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment Estimate Exception 12 on the current Payment Estimate. | 28.60000 | \$500.00 | \$14,300.00 |
| | 0720 | DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR | Material | | | -27 | \$10.00 | (\$270.00) |
| | 0720 | DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 14 on the current Payment Estimate. | 27 | \$10.00 | \$270.00 |
| | 0970 | PERMANENT EROSION CONTROL GEOTEXTILE | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.00000 - 4.00000, 'is applied (if non-zero). | 326 d | \$4.00 | \$1,304.00 |
| | 0990 | TYPE D BARRIER | Material | | | -72 | \$230.00 | (\$16,560.00) |
| | 0990 | TYPE D BARRIER | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user litzam overridding Payment Estimate Exception 16 on the current Payment Estimate. | 72 | \$230.00 | \$16,560.00 |
| | 0990 | TYPE D BARRIER | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',230.00000 - 230.00000, 'is applied (if non-zero). | 8 | \$230.00 | \$1,840.00 |
| | 1000 | TYPE C BARRIER | Material | | | -68 | \$230.00 | (\$15,640.00) |
| | 1000 | TYPE C BARRIER | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user litzam overridding Payment Estimate Exception 17 on the current Payment Estimate. | 68 | \$230.00 | \$15,640.00 |
| | 1000 | TYPE C BARRIER | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',230.00000 - 230.00000, 'is applied (if non-zero). | 7 | \$230.00 | \$1,610.00 |
| | 1150 | MGS GUARDRAIL | Construction Stockpile | | Payment Estimate Item Adjustment generated Stockpile Transaction | i | | (\$1,728.38) |
| | 1200 | SIGNAL HEAD, TYPE 3B | Material | | | -5 | \$1,233.00 | (\$6,165.00) |
| | | | | | | | | |

Revision 9/2/2025 Page 3 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2025

| stimate | gress e Numi 12 | | 17-F03 henson Constr | uction Co., In | c. Pay Period End September 15, 2025 | Original Contract Net Change Ord Current Contrac | er Amount | \$4,314,702.92 (\$93,523.52 \$4,221,179.40 |
|-----------------|-----------------------|---|-------------------------|----------------------------------|---|--|---------------------------------------|--|
| roject ımber | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| L0121 | 1200 | SIGNAL HEAD, TYPE 3B | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 22 on the current Payment Estimate. | 5 | \$1,233.00 | \$6,165.00 |
| | 1230 | POST, TYPE B, LONGEST ARM 55 FT. | Material | | | -1 | \$32,888.00 | (\$32,888.00 |
| | 1230 | POST, TYPE B, LONGEST ARM 55 FT. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user litzam overridding Payment Estimate Exception 23 on the current Payment Estimate. | 1 | \$32,888.00 | \$32,888.00 |
| | 1330 | OPTIONAL OVERHEAD SIGN TRUSS SUBSTRUCTURES | Material | | | -14.60000 | \$3,000.00 | (\$43,800.00 |
| | 1330 | OPTIONAL OVERHEAD SIGN TRUSS SUBSTRUCTURES | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user litzam overridding Payment Estimate Exception 25 on the current Payment Estimate. | 14.60000 | \$3,000.00 | \$43,800.00 |
| | 5101 | PULL BOX, PREFORMED CLASS 1 | Material | | | -1 | \$4,105.50 | (\$4,105.50 |
| | 5101 | PULL BOX, PREFORMED CLASS 1 | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user litzam overridding Payment Estimate Exception 21 on the current Payment Estimate. | 1 | \$4,105.50 | \$4,105.50 |
| | 5102 | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | Material | | | -1 | \$2,950.00 | (\$2,950.00 |
| | 5102 | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user litzam overridding Payment Estimate Exception 15 on the current Payment Estimate. | 1 | \$2,950.00 | \$2,950.00 |
| | 5106 | MISC. | Material | | | -1 | \$26,098.79 | (\$26,098.79 |
| | 5106 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user litzam overridding Payment Estimate Exception 26 on the current Payment Estimate. | 1 | \$26,098.79 | \$26,098.79 |
| tal | | | | | | | | \$11,511.62 |

Revision 9/2/2025 Page 4 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | Co | ntract Project Informa | ation | | | | | |
|-------------------|---|---------------------------|--------|-------------|---|--|--|--|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work | | | | | |
| JSL0078 | FAF-141-1 (54) | Coldmill and resurface | 141 | ST LOUIS | from St. Luke's Hospital R | oad to I-64 | | | | | | |
| JSL0121 | FAF-141-1 (56) | Interchange improvement | 141 | ST LOUIS | from I-64 to 0.62 south of | from I-64 to 0.62 south of I-64 | | | | | | |
| Totals I | y Job Nu | mbers | | | | | | | | | | |
| JSL0078 | Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive | | | | This Estimate \$39,660.00 (\$194.00) \$39,466.00 | Previous \$362,245.50 \$0.00 \$362,245.50 \$0.00 | To Date \$401,905.50 (\$194.00) \$401,711.50 | | | | | |
| | Disince Liquida | | tments | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | | | | |
| JSL0121 | | Item Pay tem Adjustmer | | tem Pay | This Estimate \$296,861.64 \$11,705.62 \$308,567.26 | Previous \$1,826,865.42 (\$63.62) \$1,826,801.80 | To Date \$2,123,727.06 \$11,642.00 \$2,135,369.06 | | | | | |
| | | | tments | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | | | | |

Revision 5/29/2025 Page 5 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|---|--|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 2035500, Project Item Line Number 0490, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient. | Working with the contractors QC to finalize the reports. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 4010150, Project Item Line Number 0540, Material Set 401015096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | Shoulders are optional asphalt or concrete. The discrepancy will remain until the asphalt portion has been completed and the line can be separated and reported. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 4019905, Project Item Line Number 0560, Material Set 401990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Line 0560 - Optional Pavement being asphalt or concrete. The discrepancy will remain until the asphalt portion has been completed. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 4019905, Project Item Line Number 0560, Material Set 401990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Line 0560 - Optional Pavement being asphalt or concrete. The discrepancy will remain until the asphalt portion has been completed. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 4019905, Project Item Line Number 0560, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient. | Line 0560 - Optional Pavement being asphalt or concrete. The discrepancy will remain until the asphalt portion has been completed. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 4019905, Project Item Line Number 0560, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA Pavement is insufficient. | Line 0560 - Optional Pavement being asphalt or concrete. The discrepancy will remain until the asphalt portion has been completed. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 5021111, Project Item Line Number 0080, Material Set 502111196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action 0501CCPAQCQA 11 in. is insufficient. | Working with MoDOT Materials to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 5021111, Project Item Line Number 0080, Material Set 502111196, Material 1057JMDAEC4.12 - Dowel Assemblies Epoxy Ctd Gr40 1 1/2" @, Acceptance Action Generic ReinforcingMisc is insufficient. | Working with MoDOT Materials to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 5021111, Project Item Line Number 0080, Material Set 502111196, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient. | Working with MoDOT Materials to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 6061060, Project Item Line Number 5001, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient. | Working with MoDOT Materials to add the line item to Line No. 1150 that has already been reported. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 6061060, Project Item Line Number 5001, Material Set 606106096, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. | Working with MoDOT Materials to add the line item to Line No. 1150 that has already been reported. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 6131010, Project Item Line Number 0680, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient. | Working with MoDOT Materials to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 6131010, Project Item Line Number 0090, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient. | Working with MoDOT Materials to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 6131017, Project Item Line Number 0720, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient. | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 6141121, Project Item Line Number 5102, Material Set 614112196, Material 0614DFGTCV - Curved Vane Grate and Frame, Acceptance Action Generic 0614DFGTCV is insufficient. | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 7034219A, Project Item Line Number 0990, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 7034411, Project Item Line Number 1000, Material Set 703441196, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient. | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 8025006, Project Item Line Number 0340, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient. | Material was paid for yesterday, waiting for inspector to complete the Sample ID. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 8051000A, Project Item Line Number 0350, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient. | Material was paid for yesterday, waiting for inspector to complete the Sample ID. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0078, Item 8051000A, Project Item Line Number 0350, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient. | Material was paid for yesterday, waiting for inspector to complete the Sample ID. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 9016110, Project Item Line Number 5101, Material Set 901611096, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient. | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 9020513, Project Item Line Number 1200, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 9023355, Project Item Line Number 1230, Material Set 902335596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 9023355, Project Item Line Number 1230, Material Set 902335596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| | | | |

Revision 5/29/2025 Page 6 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|---|---------------|--------------|
| Acceptance Action Generic 0902TSBTZCAB is insufficient. | | | |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 9031026, Project Item Line Number 1330, Material Set 903102696, Material 1036RSDFPL28M13 - Reinforcing Steel No. 4/M13 Gr 40/M280 @, Acceptance Action Generic ReSteelBars is insufficient. | Working with MoDOT Materials and the Inspector to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JSL0121, Item 9109901, Project Item Line Number 5106, Material Set 9109901, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient. | Working with MoDOT Materials and the contractor to resolve the issue. | litzam | Overridden |
| Estimate Exception Type: Item Overrun: Contract 250117-F03, Contract Project JSL0121, Project Item Line Number 0610, Contract Line Item Number 0610, Item 6083006, Minor Item. | Item is on Change Order 008. | litzam | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 250117-F03, Contract Project JSL0078, Project Item Line Number 0100, Contract Line Item Number 0100, Item 6131012, Minor Item. | Item is on Change Order 008. | litzam | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 250117-F03, Contract Project JSL0078, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6131015, Minor Item. | Item is on Change Order 008. | litzam | Acknowledged |

Revision 5/29/2025 Page 7 of 26



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

| Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTI To Date (See repo generated date) |
|----------------|----------|--------------|--------------------|--|-----------------|------------------------|------------------------------|----------|------------------------------------|------------------------|---|
| - JSL0078 | 0001 | 0010 | 1081000 | SIGNET DBE REPORTING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$1,000.00 | \$1,000 |
| | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 0.75 | \$40,000.00 | \$30,000 |
| | 0001 | 0030 | 2063500 | CULVERT CLEANOUT | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$2,000.00 | \$ |
| | 0001 | 0040 | 2159910 | MISC.SHAPING SLOPES CLASS III, MODIFIED | 6.00 | 0.00 | 6.00 | 100F | 6.00 | \$1,400.00 | \$8,40 |
| | 0001 | 0050 | 4030011 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095CLP MIX) | 4,824.90 | 0.00 | 4,824.90 | TONS | 0.00 | \$141.00 | \$ |
| | 0001 | 0060 | 4079912 | MISC.POLYMER MODIFIED EMULSION MEMBRANE | 10,112.00 | 0.00 | 10,112.00 | GAL | 0.00 | \$10.00 | \$ |
| | 0001 | 0070 | 4134000 | BITUMINOUS FOG SEAL | 207.00 | 0.00 | 207.00 | GAL | 0.00 | \$6.00 | \$ |
| | 0001 | 0080 | 5021111 | CONCRETE PAVEMENT (11 INCH NON-REINFORCED) | 267.00 | -99.40 | 167.60 | SQYD | 167.60 | \$370.00 | \$62,01 |
| | 0001 | 0090 | 6131010 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | 252.00 | -176.40 | 75.60 | SQYD | 69.60 | \$370.00 | \$25,75 |
| | 0001 | 0100 | 6131012 | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) | 25.00 | -4.00 | 21.00 | SQYD | 25.00 | \$1.00 | \$2 |
| | 0001 | 0110 | 6131013 | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) | 25.00 | -4.00 | 21.00 | SQYD | 0.00 | \$10.00 | \$ |
| | 0001 | 0120 | 6131014 | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) | 1,313.00 | -758.00 | 555.00 | LF | 501.00 | \$12.00 | \$6,01 |
| | 0001 | 0130 | 6131015 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | 401.00 | -236.00 | 165.00 | EA | 184.00 | \$10.00 | \$1,84 |
| | 0001 | 0140 | 6131018 | TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) | 421.00 | -200.00 | 221.00 | TONS | 0.00 | \$10.00 | \$ |
| | 0001 | 0150 | 6133018 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR | 10.00 | 0.00 | 10.00 | | 0.00 | \$415.00 | \$ |
| | 0001 | 0160 | 6133019 | REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR | 46.00 | 0.00 | 46.00 | SQYD | 0.00 | \$5.75 | \$ |
| | 0001 | 0170 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$2,000.00 | \$ |
| | 0001 | 0180 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$25,000.00 | \$25,00 |
| | 0001 | 0190 0200 | 6181000 6200009 | MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. | 1.00 318.00 | 0.00 | 1.00 318.00 | LS LF | 1.00 0.00 | \$100,000.00 \$5.25 | \$100,00 |
| | 0001 | 0200 | 6200015 | WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 9 IN. | 399.00 | 0.00 | 399.00 | LF | 0.00 | \$22.00 | 3 |
| | 0001 | 0220 | 6200021 | WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, | 54.00 | 0.00 | 54.00 | EA | 0.00 | \$233.00 | |
| | 0001 | 0230 | 6200024 | LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$125.00 | \$ |
| | 0001 | 0240 | 6200027 | STRAIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$330.00 | |
| | 0001 | 0250 | 6200030 | COMBINATION STR/LT/RT PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD | 5.00 | 0.00 | 5.00 | EA | 0.00 | \$375.00 | |
| | 0001 | 0260 | 6200042 | (ONLY) PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN | 168.00 | 0.00 | 168.00 | EA | 0.00 | \$19.00 | |
| | 0001 | 0270 | 6205901A | WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT | 13.303.00 | 0.00 | 13.303.00 | LF | 0.00 | \$0.16 | 5 |
| | 0001 | 0280 | 6205902A | MARKING PAINT, TYPE L BEADS 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING | 30,295.00 | 0.00 | 30,295.00 | LF | 0.00 | \$0.29 | |
| | 0001 | 0290 | 6209901 | PAINT, TYPE L BEADS MISC.PAVEMENT MARKING REMOVAL WITHIN CONCRETE | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$6,000.00 | |
| | 0001 | | | SURFACES | | | | | | | |
| | | 0300 | | MISC.TEMPORARY PAVEMENT MARKING PAINT | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$11,500.00 | 5 |
| | 0001 | 0310 | 6209902 | MISC.CURB REFLECTORS | 72.00 | 0.00 | 72.00 | EA | 0.00 | \$25.00 | \$ |
| | 0001 | 0320 | 6221011 | COLDMILLING CONCRETE PAVEMENT FOR REMOVAL OF SURFACE | 3,780.00 | 0.00 | 3,780.00 | SQYD | 0.00 | \$5.75 | |
| | | 0330 | 6229905 | MISC.COLDMILLING BITUMINOUS PAVEMENT WITH ADDITIONAL CLEANING | 50,562.00 | 0.00 | 50,562.00 | SQYD | 0.00 | \$2.95 | |
| | 0001 | 0340 | 8025006 | MULCHING | 1.00 | 0.00 | 1.00 | ACRE | 0.45 | \$1,800.00 | \$81 |
| | 0001 | 0350 | 8051000A | SEEDING - COOL SEASON GRASSES | 1.00 | 0.00 | 1.00 | ACRE | 0.45 | \$3,000.00 | \$1,35 |
| | 0001 | 0360 | 8061005 | ROCK DITCH CHECK | 20.00 | 0.00 | 20.00 | LF | 20.00 | \$25.00 | \$50 |
| | 0001 | 0370 | 8061007A | CURB INLET CHECK | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$125.00 | |
| | 0001 | 0380 | 8061016 | SEDIMENT REMOVAL | 64.00 | 0.00 | 64.00 | CUYD | 0.00 | \$1.00 | |
| | 0001 | 0390 | 8061019 | SILT FENCE | 4,160.00 | 0.00 | 4,160.00 | LF | 0.00 | \$1.00 | 5 |
| | 0010 | 0400 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | 3,313.00 | -2,800.00 | 513.00 | LF | 513.00 | \$34.00 | \$17,44 |
| | 0010 | 0410 | 6061070 | MGS VERTICAL CONCRETE BARRIER TRANSITION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$4,200.00 | \$8,40 |
| | 0010 | 0420 | 6061080 | MGS END ANCHOR | 5.00 | 0.00 | 5.00 | EA | 5.00 | \$2,100.00 | \$10,50 |
| | 0010 | 0430 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 5.00 | 0.00 | 5.00 | EA | 5.00 | \$3,900.00 | \$19,50 |
| | 0040 | 0440 | 9039902 | MISC.18 IN. ISLAND TUBULAR MARKERS | 24.00 | 0.00 | 24.00 | EA | 0.00 | \$85.00 | 5 |
| | 0050 | 0450 | 9109903 | MISC.MODOT ITS ASSETS RELOCATION | 181.00 | 0.00 | 181.00 | LF | 0.00 | \$28.00 | 5 |
| | 0010 | 5001 | 6061060 | MGS GUARDRAIL | 0.00 | 2,925.00 | 2,925.00 | LF | 2,925.00 | \$28.50 | \$83,36 |

Revision 5/29/2025 Page 8 of 26



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| | | | No. | Code | | Quantity | Change Order | Current Quantity | | Posted Approved Qty | | To Date (See report generated date) |
|-------|---------|------|------|---------------------|--|----------|-----------------|---------------------|----------|---------------------------|---------------------|-------------------------------------|
| 0117- | JSL0121 | 0001 | 0460 | 2013000 | CLEARING AND GRUBBING | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$9,100.00 | \$9,100.00 |
| 3 | | 0001 | 0470 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$225,000.00 | \$225,000.00 |
| | | 0001 | 0480 | 2031000 | CLASS A EXCAVATION | 1,680.00 | 0.00 | 1,680.00 | CUYD | 1,680.00 | \$38.00 | \$63,840.00 |
| | | 0001 | 0490 | 2035500 | EMBANKMENT IN PLACE | 4,099.00 | 0.00 | 4,099.00 | CUYD | 4,099.00 | \$38.00 | \$155,762.00 |
| | | 0001 | 0500 | 2037075 | COMPACTING IN CUT | 32.00 | 0.00 | 32.00 | STA | 0.00 | \$100.00 | \$0.00 |
| | | 0001 | 0510 | 2063000 | CLASS 3 EXCAVATION | 102.00 | 53.20 | 155.20 | CUYD | 155.20 | \$10.00 | \$1,552.0 |
| | | 0001 | 0520 | 2063500 | CULVERT CLEANOUT | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$2,000.00 | \$0.0 |
| | | 0001 | 0530 | 2159910 | MISC.SHAPING SLOPES, CLASS III | 5.00 | 0.00 | 5.00 | 100F | 1.60 | \$1,400.00 | \$2,240.0 |
| | | 0001 | 0540 | 4010150 | TYPE A2 SHOULDER | 1,666.00 | 0.00 | 1,666.00 | SQYD | 875.60 | \$72.00 | \$63,043.2 |
| | | 0001 | 0550 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | 68.50 | 0.00 | 68.50 | TONS | 0.00 | \$225.00 | \$0.0 |
| | | 0001 | 0560 | 4019905 | MISC.OPTIONAL PAVEMENT | 4,922.00 | 0.00 | 4,922.00 | SQYD | 4,173.20 | \$130.00 | \$542,516.0 |
| | | 0001 | 0570 | 4030132 | ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX) | 307.00 | 0.00 | 307.00 | TONS | 0.00 | \$190.00 | \$0.0 |
| | | 0001 | 0580 | 4071007 | TACK COAT - NON-TRACKING | 63.00 | 0.00 | 63.00 | GAL | 0.00 | \$6.00 | \$0.0 |
| | | 0001 | 0590 | 4079912 | MISC.POLYMER MODIFIED EMULSION MEMBRANE | 577.00 | 0.00 | 577.00 | GAL | 0.00 | \$10.00 | \$0.0 |
| | | 0001 | 0600 | 6044013 | PIPE COLLAR, TYPE C | 2.00 | 1.00 | 3.00 | EA | 2.00 | \$2,700.00 | \$5,400.0 |
| | | 0001 | 0610 | 6083006 | 6 IN. CONCRETE MEDIAN STRIP | 45.20 | 0.00 | 45.20 | SQYD | 50.40 | \$140.00 | \$7,056.0 |
| | | 0001 | 0620 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 151.00 | 286.00 | 437.00 | CUYD | 437.00 | \$56.00 | \$24,472.0 |
| | | 0001 | 0630 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 151.00 | 286.00 | 437.00 | CUYD | 437.00 | \$28.00 | \$12,236.0 |
| | | 0001 | 0640 | 6122009 | IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY) | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$3,200.00 | \$3,200.0 |
| | | 0001 | 0650 | 6122010 | IMPACT ATTENUATOR 50 MPH (SAND BARREL ARRAY) | 4.00 | 0.00 | 0.00 4.00 | EA | 4.00 | \$3,400.00 | \$13,600.0 |
| | | 0001 | 0660 | 6122020 | REPLACEMENT SAND BARREL | 12.00 | 0.00 | 12.00 | EA | 2.00 | \$550.00 | \$1,100.0 |
| | | 0001 | 0670 | 6122030 | IMPACT ATTENUATOR (RELOCATION) | 2.00 | 0.00 2.00 | EA | 0.00 | \$875.00 | \$0.0 | |
| | | 0001 | 0680 | 6131010 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | 33.00 | -4.40 | 28.60 | SQYD | 28.60 | \$500.00 | \$14,300.0 |
| | | 0001 | 0690 | 6131012 | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) | 33.00 | -4.40 | 28.60 | SQYD | 28.60 | \$1.00 | \$28.6 |
| | | 0001 | 0700 | 6131013 | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) | 33.00 | -33.00 | 0.00 | SQYD | 0.00 | \$10.00 | \$0.0 |
| | | 0001 | 0710 | 6131014 | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) | 134.00 | -21.00 | 113.00 | LF | 113.00 | \$15.00 | \$1,695.0 |
| | | 0001 | 0720 | 6131017 | DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR | 16.00 | 11.00 | 27.00 | EA | 27.00 | \$10.00 | \$270.0 |
| | | 0001 | 0730 | 6131018 | TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) FURNISHING AND PLACING BITUMINOUS MATERIAL FOR | 0.90 | -10.00 | 0.90 | TONS | 0.00 | \$10.00 \$550.00 | \$0.0 \$0.0 |
| | | 0001 | 0740 | 6133019 | CLASS B PARTIAL DEPTH PAVEMENT REPAIR REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR | 11.10 | 0.00 | 11.10 | SQYD | 0.00 | \$15.00 | \$0.0 |
| | | 0001 | 0760 | 6139911 | MISC.CLASS A PARTIAL DEPTH CONCRETE PAVEMENT REPAIR USING FLEXIBLE, HOT POLYMER MODIFIED REPAIR MATERIAL | 320.00 | 0.00 | 320.00 | LB | 0.00 | \$25.00 | \$0.0 |
| | | 0001 | 0770 | 6141022 | GRATE AND BEARING PLATE (3 FT. X 3 FT. OR 914 MM X 914 MM) | 1.00 | -1.00 | 0.00 | EA | 0.00 | \$2,600.00 | \$0.0 |
| | | 0001 | 0780 | 6141023 | GRATE AND BEARING PLATE (5 FT. X 2 FT. OR 1524 MM X 610 MM) | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$3,100.00 | \$0.0 |
| | | 0001 | 0790 | 6143010 | MANHOLE FRAME AND COVER, TYPE 1-A | 2.00 | -1.00 | 1.00 | EA | 0.00 | \$550.00 | \$0.0 |
| | | 0001 | 0800 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$2,000.00 | \$6,000.0 |
| | | 0001 | 0810 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$25,000.00 | \$25,000.0 |
| | | 0001 | 0820 | 6173600D | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | 3,875.00 | 1,525.00 | 5,400.00 | LF | 5,135.00 | \$26.00 | \$133,510.0 |
| | | 0001 | 0830 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$465,000,00 | \$465,000.0 |
| | | 0001 | 0840 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$600.00 | \$0.0 |
| | | 0001 | 0850 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 85.00 | 0.00 | 85.00 | LF | 0.00 | \$22.00 | \$0.0 |
| | | 0001 | 0860 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 11.00 | 0.00 | 11.00 | EA | 0.00 | \$233.00 | \$0.0 |
| | | 0001 | 0870 | 6200024 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$125.00 | \$0.0 |
| | | 0001 | 0880 | 6200027 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$330.00 | \$0.0 |
| | | 0001 | 0890 | 6200030 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$375.00 | \$0.0 |
| | | 0001 | 0900 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 5,293.00 | 0.00 | 5,293.00 | LF | 0.00 | \$0.34 | \$0.0 |
| | | 0001 | 0910 | 6205903A 6209902 | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS MISC.18 IN. WHITE ISLAND TUBULAR MARKER | 2,876.00 | 0.00 | 2,876.00 | LF EA | 0.00 | \$0.34 \$126.00 | \$0.0 |

Revision 5/29/2025 Page 9 of 26



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

| | | | | | Quantity | Change Order | Current Quantity | | Posted Approved Qty | | To Date (See report generated date) |
|-------------|------|------|---------------------|--|----------|-----------------|---------------------|------|---------------------------|-------------|-------------------------------------|
| 17- JSL0121 | 0001 | 0930 | 6209902 | MISC.18 IN. YELLOW ISLAND TUBULAR MARKER | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$126.00 | \$0.0 |
| | 0001 | 0940 | 6209902 | MISC.CURB REFLECTORS | 15.00 | 0.00 | 15.00 | EA | 0.00 | \$25.00 | \$0.0 |
| | 0001 | 0950 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 552.00 | 0.00 | 552.00 | SQYD | 0.00 | \$10.25 | \$0.0 |
| | 0001 | 0960 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 305.00 | 0.00 | 305.00 | SQYD | 0.00 | \$10.25 | \$0.0 |
| | 0001 | 0970 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 904.00 | 326.00 | 1,230.00 | SQYD | 1,230.00 | \$4.00 | \$4,920.0 |
| | 0001 | 0980 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 0.70 | \$25,000.00 | \$17,500. |
| | 0001 | 0990 | 7034219A | TYPE D BARRIER | 64.00 | 8.00 | 72.00 | LF | 72.00 | \$230.00 | \$16,560. |
| | 0001 | 1000 | 7034411 | TYPE C BARRIER | 61.00 | 7.00 | 68.00 | LF | 68.00 | \$230.00 | \$15,640. |
| | 0001 | 1010 | 7261012 | 12 IN. PIPE GROUP A | 36.00 | 7.00 | 43.00 | LF | 43.00 | \$101.00 | \$4,343. |
| | 0001 | 1020 | 7261030 | 30 IN. PIPE GROUP A | 37.00 | -17.00 | 20.00 | LF | 20.00 | \$176.00 | \$3,520. |
| | 0001 | 1030 | 7261036 | 36 IN. PIPE GROUP A | 4.00 | 0.00 | 4.00 | LF | 4.00 | \$580.00 | \$2,320. |
| | 0001 | 1040 | 7261048 | 48 IN. PIPE GROUP A | 81.00 | 1.00 | 82.00 | LF | 82.00 | \$300.00 | \$24,600. |
| | 0001 | 1050 | 7310072 | PRECAST CONCRETE MANHOLE - 72 IN. | 14.00 | -1.00 | 13.00 | FT | 13.00 | \$1,385.00 | \$18,005. |
| | 0001 | 1060 | 7311033 | PRECAST CONCRETE DROP INLET 3 FT X 3 FT | 6.00 | -6.00 | 0.00 | FT | 0.00 | \$581.08 | \$0. |
| | 0001 | 1070 | 7311053 | PRECAST CONCRETE DROP INLET 5 FT X 2 FT | 8.00 | 0.00 | 8.00 | FT | 8.00 | \$500.00 | \$4,000.0 |
| | 0001 | 1080 | 7311052 7320648A | 48 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$4,000.00 | \$4,000. |
| | 0001 | 1090 | 8025006 | MULCHING | 1.80 | 0.00 | 1.80 | ACRE | 0.00 | \$1,800.00 | \$0. |
| | 0001 | 1100 | 8052000A | SEEDING - WARM SEASON GRASSES | 0.90 | 0.00 | 0.90 | ACRE | 0.00 | \$3,000.00 | \$0. |
| | 0001 | 1110 | 8061005 | ROCK DITCH CHECK | 480.00 | 0.00 | 480.00 | LF | 217.00 | \$10.00 | \$2,170. |
| | 0001 | 1120 | 8061016 | SEDIMENT REMOVAL | 60.00 | 0.00 | 60.00 | CUYD | 36.00 | \$1.00 | \$36. |
| | 0001 | 1130 | 8061017 | TEMPORARY SEEDING | 0.90 | 0.00 | 0.90 | ACRE | 0.00 | \$2,500.00 | \$0. |
| | 0001 | | | | | | | | | | |
| | 0010 | 1140 | 8061019 | SILT FENCE | 3,390.00 | 0.00 | 3,390.00 | LF | 72.00 | \$1.00 | \$72. |
| | 0010 | 1150 | 6061060 | MGS GUARDRAIL | 2,650.00 | 0.00 | 2,650.00 | LF | 725.00 | \$28.50 | \$20,662. |
| | 0010 | 1160 | 6061080 | MGS END ANCHOR | 3.00 | 0.00 | 3.00 | EA | 1.00 | \$2,100.00 | \$2,100. |
| | 0010 | 1170 | 6061081 | MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE) | 4.00 | 0.00 | 4.00 | EA | 2.00 | \$4,200.00 | \$8,400. |
| | | 1180 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 5.00 | 0.00 | 5.00 | EA | 1.00 | \$3,900.00 | \$3,900. |
| | 0010 | 1190 | 6069902 | MISC.GUARDRAIL POSTS IN CONCRETE | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$250.00 | \$0. |
| | 0030 | 1200 | 9020513 | SIGNAL HEAD, TYPE 3B | 5.00 | 0.00 | 5.00 | EA | 5.00 | \$1,233.00 | \$6,165. |
| | 0030 | 1210 | 9020833 | SH-FLAT SHEET - SIGNAL SIGN | 28.00 | 0.00 | 28.00 | SQFT | 0.00 | \$33.00 | \$0. |
| | 0030 | 1220 | 9020834 | SIGNAL SIGN, MOUNTING HARDWARE | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$228.00 | \$0. |
| | 0030 | 1230 | 9023355 | POST, TYPE B, LONGEST ARM 55 FT. | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$32,888.00 | \$32,888. |
| | 0030 | 1240 | 9025300 | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | 17.00 | 0.00 | 17.00 | LF | 17.00 | \$20.00 | \$340 |
| | 0030 | 1250 | 9027300 | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE | 103.00 | 0.00 | 103.00 | LF | 103.00 | \$33.00 | \$3,399. |
| | 0030 | 1260 | 9028311 | CABLE, 16 AWG 7 CONDUCTOR | 1,070.00 | 0.00 | 1,070.00 | LF | 0.00 | \$3.00 | \$0. |
| | 0030 | 1270 | 9028811 | PULL BOX, PREFORMED CLASS 2 | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,840.00 | \$1,840. |
| | 0030 | 1280 | 9029100 | BASE, CONCRETE | 3.70 | 0.00 | 3.70 | CUYD | 3.70 | \$1,547.00 | \$5,723. |
| | 0030 | 1285 | 9029901 | MISC.LUMP SUM TRAFFIC SIGNAL MAINTENANCE & PROGRAMMING | 1.00 | 0.00 | 1.00 | LS | 0.25 | \$6,000.00 | \$1,500. |
| | 0030 | 1290 | 9029902 | MISC.RECONFIGURATION OF VIDEO DETECTION ZONES | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$400.00 | \$0. |
| | 0030 | 1300 | 9029902 | MISC.SL DISTRICT TRAFFIC SIGNAL DETECTION SYSTEM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$29,188.00 | \$0 |
| | 0040 | 1310 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 3.00 | 0.00 | 3.00 | CUYD | 0.00 | \$2,800.00 | \$0. |
| | 0040 | 1320 | 9031020 | CONCRETE FOOTINGS, BOLT DOWN | 9.60 | 0.00 | 9.60 | CUYD | 9.60 | \$3,000.00 | \$28,800 |
| | 0040 | 1330 | 9031026 | OPTIONAL OVERHEAD SIGN TRUSS SUBSTRUCTURES | 14.60 | 0.00 | 14.60 | CUYD | 14.60 | \$3,000.00 | \$43,800. |
| | 0040 | 1340 | 9031210 | STRUCTURAL STEEL POSTS | 650.00 | 0.00 | 650.00 | LB | 0.00 | \$6.00 | \$0. |
| | 0040 | 1350 | 9031220 | PIPE POSTS | 1,230.00 | 0.00 | 1,230.00 | LB | 0.00 | \$8.00 | \$0. |
| | 0040 | 1360 | 9035004A | SH-FLAT SHEET | 102.00 | 0.00 | 102.00 | SQFT | 0.00 | \$32.00 | \$0. |
| | 0040 | 1370 | 9035011A | ST-STRUCTURAL | 569.00 | 0.00 | 569.00 | SQFT | 0.00 | \$38.00 | \$0 |
| | 0040 | 1380 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 32.00 | 0.00 | 32.00 | SQFT | 0.00 | \$36.00 | \$0 |
| | 0040 | 1390 | 9035071A | STF-STRUCTURAL FLUORESCENT | 102.00 | 0.00 | 102.00 | SQFT | 0.00 | \$42.00 | \$0 |
| | 0040 | 1400 | 9039901 | MISC.23 FT. CANTILEVER BOX TRUSS | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$62,800.00 | \$0 |
| | 0040 | 1410 | 9039901 | MISC.TUBULAR SUPPORT, TYPE S-23316.5-65 | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$80,200.00 | \$0 |
| | 0040 | 1420 | 9039902 | MISC.SIGN REMOVAL AND RELOCATION | 7.00 | 0.00 | 7.00 | EA | 0.00 | \$150.00 | \$0 |
| | 0050 | 1430 | 9109901 | MISC.ITS ASSET MANAGEMENT TOOL | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$450.00 | \$0 |
| | 0050 | 1440 | 9109901 | MISC.FIBER OPTIC FUSION SPLICE | 102.00 | -102.00 | 0.00 | EA | 0.00 | \$50.00 | \$0. |
| | | 1450 | 9109902 | | | | | EA | | \$20.00 | |
| | 0050 | | - 9 TUMMUZ | MISC.FIBER OPTIC JUMPER | 12.00 | -12.00 | 0.00 | EA | 0.00 | \$20.00 | \$0. |
| | 0050 | 1460 | 9109902 | MISC.FIBER OPTIC PIGTAIL | 12.00 | -12.00 | 0.00 | EA | 0.00 | \$20.00 | \$0. |

Revision 5/29/2025 Page 10 of 26



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract ID | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-----------------|----------------|---------------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 250117- | JSL0121 | 0050 | 1480 | 9109902 | MISC.INTERCEPT CONDUIT WITH PULL BOX | 1.00 | -1.00 | 0.00 | EA | 0.00 | \$2,200.00 | \$0.00 |
| - 03 | | 0050 | 1490 | 9109902 | MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 2 | 3.00 | -3.00 | 0.00 | EA | 0.00 | \$2,370.00 | \$0.00 |
| | | 0050 | 1500 | 9109902 | MISC.MODOT BURIED CABLE DRIVABLE DELINEATOR POST | 23.00 | -23.00 | 0.00 | EA | 0.00 | \$200.00 | \$0.00 |
| | | 0050 | 1510 | 9109902 | MISC.UNDERGROUND SPLICE ENCLOSURE | 1.00 | -1.00 | 0.00 | EA | 0.00 | \$850.00 | \$0.00 |
| | | 0050 | 1520 | 9109902 | MISC.WALL-MOUNTED INTERCONNECT CENTER | 3.00 | -3.00 | 0.00 | EA | 0.00 | \$622.00 | \$0.00 |
| | | 0050 | 1530 | 9109903 | MISC.CONDUIT, HDPE, DRILL, 2" | 1,683.00 | -1,683.00 | 0.00 | LF | 0.00 | \$22.00 | \$0.00 |
| | | 0050 | 1540 | 9109903 | MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE | 7,592.00 | -7,592.00 | 0.00 | LF | 0.00 | \$3.25 | \$0.00 |
| | | 0050 | 1550 | 9109903 | MISC.RELOCATE FIBER OPTIC CABLE | 575.00 | -575.00 | 0.00 | LF | 0.00 | \$20.00 | \$0.00 |
| | | 0030 | 5101 | 9016110 | PULL BOX, PREFORMED CLASS 1 | 0.00 | 1.00 | 1.00 | EA | 1.00 | \$4,105.50 | \$4,105.50 |
| | | 0001 | 5102 | 6141121 | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | 0.00 | 1.00 | 1.00 | EA | 1.00 | \$2,950.00 | \$2,950.00 |
| | | 0001 | 5103 | 7320630A | 30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 0.00 | 1.00 | 1.00 | EA | 1.00 | \$3,465.00 | \$3,465.00 |
| | | 0001 | 5104 | 7319902 | MISC.Cast In Place Concrete Inlet, 6 Ft. X 6 Ft. | 0.00 | 1.00 | 1.00 | EA | 1.00 | \$33,982.57 | \$33,982.57 |
| | | 0001 | 5105 | 6143014 | MANHOLE FRAME AND COVER, TYPE 4 | 0.00 | 1.00 | 1.00 | EA | 0.00 | \$600.00 | \$0.00 |
| | | 0050 | 5106 | 9109901 | MISC.Misc. Relocating Fiber Optic Conduit | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$26,098.79 | \$26,098.79 |
| | Project J | SL0121 - To | otal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$2,123,727.06 |
| 50117-F | 03 Overal | l - Total Val | ue Poste | d to Date as | of Report Generated Date | | | | | | | \$2,525,632.56 |

Revision 5/29/2025 Page 11 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JSL0078

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Posting Sequence No. | | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|-------------------------------|-------------|-------------------------|----------------------------|------|-------|-----------------------------|---------------------------------|---------------------|-------------------------------|---------------------|-----------------------|
| 0180 | 6169901 | MISC. | 9/10/25 | 9/16/25 | 1 | 0.50 | LS | Rte. 141 | 96+00 | | 165+00 | | Phase 2 |
| 0190 | 6181000 | MOBILIZATION | 9/10/25 | 9/16/25 | 1 | 0.25 | LS | Rte. 141 | 96+00 | | 165+00 | | 30% Contract Complete |
| 0340 | 8025006 | MULCHING | 9/10/25 | 9/16/25 | 1 | 0.45 | ACRE | SB 141 South of EB off ramp | 145+00 | RT | 161+00 | RT | |
| 0350 | 8051000A | SEEDING - COOL SEASON GRASSES | 9/10/25 | 9/16/25 | 1 | 0.45 | ACRE | SB 141 South of EB off ramp | 145+00 | RT | 161+00 | RT | |

Project: JSL0121

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Posting Sequence No. | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|----------------------------|--------------------|-------|--|---------------------------------|---------------------|-------------------------------|---------------------|-------------------|
| 0470 | 2022010 | REMOVAL OF IMPROVEMENTS | 9/10/25 | 9/16/25 | 1 | 0.20 | LS | Rte. 141 | 146+00 | | 165+00 | | Assorted Removals |
| 0480 | 2031000 | CLASS A EXCAVATION | 9/10/25 | 9/16/25 | 1 | 500.00 | CUYD | Rte.141 | 145+61 | RT | 161+12 | RT | |
| 0560 | 4019905 | MISC. | 9/10/25 | 9/16/25 | 1 | 740.90 | SQYD | WB 64 to SB 141 New Turn Lanes | 134+59 | RT | 135+82 | RT | |
| 0600 | 6044013 | PIPE COLLAR, TYPE C | 9/10/25 | 9/16/25 | 1 | 1.00 | EA | Cast in Place Box | 134+50 | 115' RT | | | Pipe connections |
| 0610 | 6083006 | 6 IN. CONCRETE MEDIAN STRIP | 9/10/25 | 9/16/25 | 1 | 19.80 | SQYD | WB 64 to SB 141 New Right Turn Lanes | 134+65 | 70' RT | | | Median Island |
| 0720 | 6131017 | DOWEL BAR (FURNISH AND INSTALL WITH BASK | 9/4/25 | 9/15/25 | 1 | 11.00 | EA | Various locations, See Line No. 0680 for details. | 95+22 | | 135+77 | | |
| 0810 | 6169901 | MISC. | 9/10/25 | 9/16/25 | 1 | 0.50 | LS | Rte. 141 | 96+00 | | 165+00 | | Phase 2 |
| 0820 | 6173600D | TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE | 9/10/25 | 9/16/25 | 1 | 1,362.50 | LF | | 148+25 | RT | 161+30 | RT | |
| 1150 | 6061060 | MGS GUARDRAIL | 9/4/25 | 9/15/25 | 1 | 2,512.00 | LF | Various locations. Adjustment to correct quantities. | 94+92 | | 166+05 | | |
| 5102 | 6141121 | CURVED VANE GRATE AND FRAME(4 FT. X 2 FT | 9/10/25 | 9/16/25 | 1 | 1.00 | EA | Structure 01-03 | 134+44 | 88' RT | | | |
| 5104 | 7319902 | MISC. MANHOLES AND DROP INLETS | 9/10/25 | 9/16/25 | 1 | 0.25 | EA | | 134+50 | 115' RT | | | |

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 12 of 26



| oject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 0078 | 0040 | MISC. SHAPING SLOPES | Material | | 7 | Jul 1, 2025 | SYSTEM | (\$7,000.00) | |
| | | | | | 7 | Jul 1, 2025 | SYSTEM | \$7,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user cramec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0040 - | Total | | | | | | \$0.00 | |
| | 0800 | CONCRETE PAVEMENT (11 IN. | Material | | 10 | Aug 18, 2025 | SYSTEM | (\$62,012.00) | |
| | | NON-REINF) | | | 10 | Aug 18, 2025 | SYSTEM | \$62,012.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | (\$62,012.00) | |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | \$62,012.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user cramec1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | (\$62,012.00) | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$62,012.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user litzam overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0080 - | Total | | | | | | \$0.00 | |
| | 0090 | FURN & PLACE CONC MATL FOR FULL DEPTH | Material | | 10 | Aug 18, 2025 | SYSTEM | (\$25,752.00) | |
| | | TOLL DEF III | | | 10 | Aug 18, 2025 | SYSTEM | \$25,752.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user litzam overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | (\$25,752.00) | |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | \$25,752.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user cramec1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | (\$25,752.00) | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$25,752.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user litzam overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0090 - | Total | | | | | | \$0.00 | |
| | 0100 | SUBGRADE COMPACTION (6 IN. DEPTH) | Overrun | Overrun | 12 | Sep 16, 2025 | SYSTEM | (\$4.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | (PAVEM | | Overrun - To | otal | | | (\$4.00) | |
| | | | Overrun - To | tal | | | | (\$4.00) | |
| | 0100 - | Total | | | | | | (\$4.00) | |
| | 0130 | DOWEL BAR (DRILLING, FURNISHING AND | Material | | 10 | Aug 18, 2025 | SYSTEM | (\$1,840.00) | |
| | | INST | | | 10 | Aug 18, 2025 | SYSTEM | \$1,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Overrun | Overrun | 12 | Sep 16, 2025 | SYSTEM | (\$190.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | Overrun - To | otal | | | (\$190.00) | |
| | | | Overrun - To | tal | | | | (\$190.00) | |
| | 0130 - | Total | | | | | | (\$190.00) | |
| | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------------------|--|---|-----------------------------|----------------|-----------------|-----------------|-------------------------------|--|--|
| JSL0078 | 0340 | MULCHING | Material | Турс | 12 | Sep 16, 2025 | SYSTEM | (\$810.00) | | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$810.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user litzam overridding Payment Estimate Exception 18 on the current Payment Estimate. | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - Tot | al | | | | \$0.00 | | |
| | 0340 - | Total | | | | | | \$0.00 | | |
| | 0350 | SEEDING - COOL SEASON GRASSES | Material | | 12 | Sep 16, 2025 | SYSTEM | (\$1,350.00) | | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$1,350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user litzam overridding Payment Estimate Exception 19 on the current Payment Estimate. | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - Tot | al | | | | \$0.00 | | |
| | 0350 - | Total | | | | | | \$0.00 | | |
| | 0360 | ROCK DITCH CHECK | Material | | 10 | Aug 18, 2025 | SYSTEM | (\$500.00) | | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user litzam overridding Payment Estimate Exception 18 on the current Payment Estimate. | |
| | | | | - Total | | | | \$0.00 | | |
| | 0360 - | | Material - Tot | tal | | | | \$0.00 | | |
| | | Total | | | | | | \$0.00 | | |
| | 0400 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT. - 3 IN | Construction Stockpile | | 7 | Jul 1, 2025 | SYSTEM | (\$4,539.12) | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | | | 8 | Jul 16, 2025 | SYSTEM | (\$3,222.77) | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | | | | 10 | Aug 18, 2025 | SYSTEM | (\$42,365.11) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total Construction Stockpile - Total | | | | | (\$50,127.00) | | |
| | | | Construction | Stockpile - I | 1 | Apr 2, | SYSTEM | (\$50,127.00) \$34,937.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | Stockpile STMA | - Total | | 2025 | OTOTEM | \$34,937.00 | Toynon Louinde Rom Adjustmon gonorated exception Managed on | |
| | | | Construction | | MA - Tota | al | | \$34,937.00 | | |
| | | | Construction Stockpile | | 1 | Apr 2, 2025 | SYSTEM | \$15,190.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | STMI | - Total | | | | \$15,190.00 | | |
| | | | Construction | Stockpile S1 | MI - Tota | | | \$15,190.00 | | |
| | 0400 - | Total | | | | | | \$0.00 | | |
| | 0410 | MGS VERTICAL CONCRETE BARRIER | Construction Stockpile | | 7 | Jul 1, 2025 | SYSTEM | (\$3,520.00) | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | TRANSITION | | - Total | | | | (\$3,520.00) | | |
| | | | Construction | Stockpile - 1 | | | | (\$3,520.00) | | |
| | | | Construction Stockpile STMI | | 6 | Jun 16, 2025 | SYSTEM | \$3,520.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | Constructi | - Total | TANK Total | | | \$3,520.00 | | |
| | 0440 | Total | Construction | Stockpile S1 | Wii - Tota | | | \$3,520.00 | | |
| | 0410 - 0420 | MGS END ANCHOR | Construction Stockpile | | 7 | Jul 1, 2025 | SYSTEM | \$0.00 (\$3,250.00) | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | · | - Total | | | | (\$3,250.00) | | |
| | | | Construction | | otal | | | (\$3,250.00) | | |
| | | | Construction Stockpile | | 6 | Jun 16, 2025 | SYSTEM | \$3,250.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | STMI | - Total | | | | \$3,250.00 | | |
| | | | Construction | n Stockpile STMI - Total | | | | \$3,250.00 | | |
| | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|---------|---------------------------------------|-----------------------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| JSL0078 | 0420 | Total | | | | | | \$0.00 | |
| | 0430 | TYPE A CRASHWORTHY END TERMINAL | Construction Stockpile | | 7 | Jul 1, 2025 | SYSTEM | (\$9,250.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | (MASH) | | - Total | | | | (\$9,250.00) | |
| | | | Construction | Stockpile - 1 | Total | | | (\$9,250.00) | |
| | | | Construction Stockpile STMI | | 6 | Jun 16, 2025 | SYSTEM | \$9,250.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | \$9,250.00 | |
| | | | Construction | Stockpile S | TMI - Tota | | | \$9,250.00 | |
| | 0430 | | | | | | | \$0.00 | |
| | 5001 | MGS GUARDRAIL | Material | | 11 | Sep 2, 2025 | SYSTEM | (\$83,362.50) | |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | \$83,362.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user cramec1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | (\$83,362.50) | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$83,362.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user litzam overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | al | | | | \$0.00 | |
| | 5001 | Total | | | | | | \$0.00 | |
| JSL0078 | - Total | | | | | | | (\$194.00) | |
| JSL0121 | 0490 | EMBANKMENT IN PLACE | Material | | 7 | Jul 1, 2025 | SYSTEM | (\$9,093.40) | |
| | | | | | 7 | Jul 1, 2025 | SYSTEM | \$9,093.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user cramec1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 8 | Jul 16, 2025 | SYSTEM | (\$47,093.40) | |
| | | | | | 8 | Jul 16, 2025 | SYSTEM | \$47,093.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | (\$66,093.40) | |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | \$66,093.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | (\$155,762.00) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$155,762.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | (\$155,762.00) | |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | \$155,762.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user cramec1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | (\$155,762.00) | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$155,762.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0490 | Total | | | | | | \$0.00 | |
| | 0540 | TYPE A2 SHOULDER | Material | | 10 | Aug 18, 2025 | SYSTEM | (\$63,043.20) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$63,043.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, | SYSTEM | (\$63,043.20) | |



| 1972 1973 1974 1975 | Project | | | | | | | | | |
|---|---------|--------------|---|---------------|--------------|------------------|---|-----------------------------|--|--|
| SHOULDER | | Line | Description | | Adjustment | | | | Amount | Remarks |
| 1 Sep 2, SYSTEM 38C,04.2 20 This adjustment of finish the original system-generated Material Pyremet 2002 | SL0121 | 0540 | | Material | | | 2025 | | | |
| 1 | | | SHOULDER | | | 11 | | SYSTEM | \$63,043.20 | Estimate Item Adjustment (0002) due to user cramec1 overridding Payment |
| Section Sect | | | | | | 12 | | SYSTEM | (\$63,043.20) | |
| Material - Total | | | | | | 12 | | SYSTEM | \$63,043.20 | Estimate Item Adjustment (0002) due to user litzam overridding Payment |
| Material Total | | | | | - Total | | | | \$0.00 | |
| | | | | Material - To | tal | | | | \$0.00 | |
| Misc. Material | | 0540 | Total | | | | | | | |
| 2005 | | | | Material | | 9 | | SYSTEM | | |
| 10 | | | | | | 9 | | SYSTEM | \$310,310.00 | Estimate Item Adjustment (0002) due to user litzam overridding Payment |
| 2025 SYSTEM S446,190.00 Estimate Exception 3 on the current Payment Estimate. | | | | | | 10 | | SYSTEM | (\$423,631.00) | , |
| 11 Sep 16 SYSTEM S446,199.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user cramect overridding Payment Estimate Item Adjustment (0003) due to user cramect overridding Payment Estimate Item Adjustment (0003) due to user cramect overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0003) due to user item overridding Payment Item Adjustment (0003) due to user item overridding Payment Item Adjustment (0003) due to user item overridding Payment Item Adjustment (0003) due to user item overridding Payment Item Adjustment (0003) due to user item overridding Payment Item Adjustment (0003) due to user item overridding Payment Item Item Adjustment (0003) due to user cramect overridding Payment Item Item Adjustment (0003) due to user cramect overridding Payment Item Item Adjustment (0003) due to user cramect overridding Payment Item Item Adjustment (0003) due to user cramect overridding Payment Item Item Adjustment (0003) due to user cramect overridding Payment Item Item Adjustment (0003) due to user cramect overridding Payment Item Item Adjustment Item Adjustment Item Adjustment Item Adjustment Item Adjustment Item Item Adjustment Item Item Item Item Item Item Item Ite | | | | | | 10 | | SYSTEM | \$423,631.00 | Estimate Item Adjustment (0003) due to user litzam overridding Payment |
| 2025 Sep 16, SySTEM | | | | | | 11 | | SYSTEM | (\$446,199.00) | |
| 2025 12 Sep 16, SYSTEM \$542,516.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. So.00 | | | | | | 11 | | SYSTEM | \$446,199.00 | Estimate Item Adjustment (0003) due to user cramec1 overridding Payment |
| Solid Stimate Estimate Es | | | | | | 12 | | SYSTEM | (\$542,516.00) | |
| Material - Total S0.00 | | | | | | 12 | | SYSTEM | \$542,516.00 | Estimate Item Adjustment (0003) due to user litzam overridding Payment |
| Section Sect | | | | | - Total | | | | \$0.00 | |
| PIPE COLLAR, TYPE C Material 7 | | | | Material - To | tal | | | | \$0.00 | |
| TYPE C | | 0560 - | Total | | | | | | \$0.00 | |
| Page | | 0600 | | Material | | 7 | | SYSTEM | (\$2,700.00) | |
| Material - Total S0.00 | | | | | | 7 | | SYSTEM | \$2,700.00 | |
| Second S | | | | | | | | | | |
| Definition | | | | | - Total | | | | \$0.00 | |
| Overrun - Total (\$728.00) | | | | Material - To | | | | | | |
| Naterial System | | 0600 | ·Total | Material - To | | | | | \$0.00 | |
| D610 - Total SYSTEM SYSTEM SR,456.00 SYSTEM SR,456.00 SY | | | 6 IN. CONCRETE | | tal | 12 | | SYSTEM | \$0.00 \$0.00 | |
| System S | | | 6 IN. CONCRETE | | Overrun | | | SYSTEM | \$0.00 \$0.00 (\$728.00) | |
| ROCK DITCH LINER 2025 8 Jul 16, 2025 8 SYSTEM \$8,456.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate. 9 Aug 4, 2025 SYSTEM \$8,456.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate. 10 Aug 18, 2025 10 Aug 18, SYSTEM \$8,456.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. | | | 6 IN. CONCRETE | Overrun | Overrun - To | | | SYSTEM | \$0.00 \$0.00 (\$728.00) (\$728.00) | |
| 8 Jul 16, 2025 SYSTEM \$8,456.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 9 Aug 4, 2025 SYSTEM (\$8,456.00) 9 Aug 4, 2025 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 10 Aug 18, 2025 SYSTEM (\$8,456.00) 10 Aug 18, SYSTEM \$8,456.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 10 Aug 18, SYSTEM (\$8,456.00) 10 Aug 18, SYSTEM \$8,456.00 This adjustment offsets the original system-generated Material Payment | | 0610 | 6 IN. CONCRETE MEDIAN STRIP | Overrun | Overrun - To | | | SYSTEM | \$0.00 \$0.00 (\$728.00) (\$728.00) | |
| 9 Aug 4, 2025 \$\frac{1}{2025}\$ \$\frac{1} | | 0610 0610 | 6 IN. CONCRETE MEDIAN STRIP Total FURN. TYPE 2 ROCK DITCH | Overrun - To | Overrun - To | otal | Jul 16, | | \$0.00 \$0.00 (\$728.00) (\$728.00) (\$728.00) | |
| Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate. 10 Aug 18, 2025 (\$8,456.00) 10 Aug 18, SYSTEM \$8,456.00 This adjustment offsets the original system-generated Material Payment | | 0610 0610 | 6 IN. CONCRETE MEDIAN STRIP Total FURN. TYPE 2 ROCK DITCH | Overrun - To | Overrun - To | otal 8 | Jul 16, 2025 Jul 16, | SYSTEM | \$0.00 \$0.00 (\$728.00) (\$728.00) (\$728.00) (\$728.00) (\$8,456.00) | Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment |
| 2025 10 Aug 18, SYSTEM \$8,456.00 This adjustment offsets the original system-generated Material Payment | | 0610 0610 | 6 IN. CONCRETE MEDIAN STRIP Total FURN. TYPE 2 ROCK DITCH | Overrun - To | Overrun - To | 8 8 | Jul 16, 2025 Jul 16, 2025 Aug 4, | SYSTEM SYSTEM | \$0.00 \$0.00 (\$728.00) (\$728.00) (\$728.00) (\$728.00) (\$8,456.00) | Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment |
| | | 0610 0610 | 6 IN. CONCRETE MEDIAN STRIP Total FURN. TYPE 2 ROCK DITCH | Overrun - To | Overrun - To | 8 8 9 | Jul 16, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 | SYSTEM SYSTEM | \$0.00 \$0.00 (\$728.00) (\$728.00) (\$728.00) (\$728.00) (\$8,456.00) (\$8,456.00) | Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment |
| Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 11 on the current Payment Estimate. | | 0610 0610 | 6 IN. CONCRETE MEDIAN STRIP Total FURN. TYPE 2 ROCK DITCH | Overrun - To | Overrun - To | 8 8 8 9 | Jul 16, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4, | SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 (\$728.00) (\$728.00) (\$728.00) (\$728.00) (\$8,456.00) (\$8,456.00) (\$8,456.00) | Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | |
|---------|--------|------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|--|--|--|---|-----------------|--------|--------------|--|
| JSL0121 | 0620 | FURN. TYPE 2 ROCK DITCH | Material | - Total | | | | \$0.00 | | | | | | | | | |
| | | LINER | Material - To | | | | | \$0.00 | | | | | | | | | |
| | | | Overrun | Overrun | 11 | Sep 2, 2025 | SYSTEM | (\$6,272.00) | | | | | | | | | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$6,272.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',56.00000 - 56.00000, 'is applied (if non-zero). | | | | | | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | | | | | | | |
| | | | Overrun - To | tal | | | | \$0.00 | | | | | | | | | |
| | 0620 - | Total | | | | | | \$0.00 | | | | | | | | | |
| | 0630 | PLACING TYPE 2 ROCK DITCH | Overrun | Overrun | 11 | Sep 2, 2025 | SYSTEM | (\$3,136.00) | | | | | | | | | |
| | | LINER | | | 12 | Sep 16, 2025 | SYSTEM | \$3,136.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',28.00000 - 28.00000, 'is applied (if non-zero). | | | | | | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | | | | | | | |
| | | | Overrun - To | tal | | | | \$0.00 | | | | | | | | | |
| | 0630 - | Total | | | | | | \$0.00 | | | | | | | | | |
| | 0640 | IMPACT ATTENUATOR 45 | Material | | 2 | Apr 16, 2025 | SYSTEM | (\$3,200.00) | | | | | | | | | |
| | | MPH (SAND BARREL ARRAY) | | | 2 | Apr 16, 2025 | SYSTEM | \$3,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | |
| | | | | | 3 | May 2, 2025 | SYSTEM | (\$3,200.00) | | | | | | | | | |
| | | | | | 3 | May 2, 2025 | SYSTEM | \$3,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user cramec1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | |
| | | | | | | | | | | | | | 4 | May 16, 2025 | SYSTEM | (\$3,200.00) | |
| | | | | | 4 | May 16, 2025 | SYSTEM | \$3,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user cramec1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | |
| | | | | | 5 | Jun 2, 2025 | SYSTEM | (\$3,200.00) | | | | | | | | | |
| | | | | | 5 | Jun 2, 2025 | SYSTEM | \$3,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user cramec1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | |
| | 0640 - | Total | | | | | | \$0.00 | | | | | | | | | |
| | 0650 | IMPACT ATTENUATOR 50 | Material | | 2 | Apr 16, 2025 | SYSTEM | (\$3,400.00) | | | | | | | | | |
| | | MPH (SAND BARREL ARRAY) | | | 2 | Apr 16, 2025 | SYSTEM | \$3,400.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | | | | |
| | | | | | 3 | May 2, 2025 | SYSTEM | (\$13,600.00) | | | | | | | | | |
| | | | | | 3 | May 2, 2025 | SYSTEM | \$13,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cramec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | | | | |
| | | | | | 4 | May 16, 2025 | SYSTEM | (\$13,600.00) | | | | | | | | | |
| | | | | | 4 | May 16, 2025 | SYSTEM | \$13,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cramec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | | | | |
| | | | | | 5 | Jun 2, 2025 | SYSTEM | (\$13,600.00) | | | | | | | | | |
| | | | | | 5 | Jun 2, 2025 | SYSTEM | \$13,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cramec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | |
| | | | | | | | | | | | | | | | | | |



| JSL0121 0650 - Total \$0.00 0680 FURN & PLACE CONC MATL FOR FULL DEPTH 10 Aug 18, 2025 \$YSTEM (\$14,300.00) | |
|---|--|
| CONC MATL FOR 2025 | |
| | |
| 10 Aug 18, 2025 SYSTEM \$14,300.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0005) due to user lit Estimate Exception 12 on the current Payment | zam overridding Payment |
| 11 Sep 2, 2025 SYSTEM (\$14,300.00) | |
| 11 Sep 2, 2025 \$YSTEM \$14,300.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0006) due to user or Estimate Exception 10 on the current Payment | ramec1 overridding Payment |
| 12 Sep 16, 2025 SYSTEM (\$14,300.00) | |
| 12 Sep 16, 2025 SYSTEM \$14,300.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0007) due to user lit Estimate Exception 12 on the current Payment | zam overridding Payment |
| - Total \$0.00 | |
| Material - Total \$0.00 | |
| 0680 - Total \$0.00 | |
| 0720 DOWEL BAR Material 10 Aug 18, SYSTEM (\$160.00) (FURNISH AND 1NSTALL WITH 10 10 10 10 10 10 10 1 | |
| BASK 10 Aug 18, 2025 SYSTEM \$160.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0006) due to user lit Estimate Exception 15 on the current Payment | zam overridding Payment |
| 11 Sep 2, 2025 SYSTEM (\$160.00) | |
| 11 Sep 2, 2025 \$YSTEM \$160.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0007) due to user or Estimate Exception 12 on the current Payment | ramec1 overridding Payment |
| | |
| 12 Sep 16, 2025 SYSTEM (\$270.00) | |
| | zam overridding Payment |
| 2025 12 Sep 16, 2025 SYSTEM \$270.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment - Total \$0.00 | zam overridding Payment |
| 2025 12 Sep 16, 2025 12 Sep 16, 2025 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment - Total \$0.00 Material - Total \$0.00 | zam overridding Payment |
| 2025 12 Sep 16, 2025 12 Sep 16, 2025 13 SYSTEM \$270.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment - Total \$0.00 Material - Total \$0.00 0720 - Total \$0.00 | zam overridding Payment |
| 2025 12 Sep 16, 2025 | zam overridding Payment Estimate. |
| 2025 12 Sep 16, 2025 12 Sep 16, 2025 13 System \$270.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment 10 So.00 11 So.00 11 So.00 12 Apr 16, 2025 2 Apr 16, 2025 2 Apr 16, 2025 3 System \$6,000.00 11 System-gen Estimate Item Adjustment offsets the original system-gen Estimate Item Adjustment (0003) due to user lit Estimate Exception 3 on the current Payment Estimate Exception 3 on the current | zam overridding Payment Estimate. erated Material Payment zam overridding Payment |
| 2025 12 Sep 16, 2025 SYSTEM \$270.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment sitimate. |
| 2025 12 Sep 16, 2025 SYSTEM \$270.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment estimate. erated Material Payment amec1 overridding Payment |
| 2025 12 Sep 16, 2025 SYSTEM \$270.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment estimate. erated Material Payment amec1 overridding Payment |
| 2025 12 Sep 16, 2025 SYSTEM \$270.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment sistimate. erated Material Payment amec1 overridding Payment sistimate. erated Material Payment amec1 overridding Payment amec1 overridding Payment |
| 12 Sep 16, 2025 SYSTEM \$270.00 This adjustment offsets the original system-generation in the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment sistimate. erated Material Payment amec1 overridding Payment sistimate. erated Material Payment amec1 overridding Payment amec1 overridding Payment |
| 2025 12 Sep 16, 2025 SYSTEM \$270.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. |
| 2025 12 Sep 16, SYSTEM \$270.00 This adjustment offsets the original system-generatinate ltem Adjustment (0008) due to user lit Estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. |
| 12 Sep 16, SYSTEM \$270.00 This adjustment offsets the original system-general estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. |
| 12 Sep 16, SYSTEM \$270.00 This adjustment offsets the original system-general estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. |
| 2025 12 Sep 16, 2025 SYSTEM \$270.00 This adjustment (0008) due to user lit Estimate Exception 14 on the current Payment | zam overridding Payment Estimate. erated Material Payment zam overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. erated Material Payment amec1 overridding Payment istimate. |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks | | |
|---------|--|--|---------------|--------------------|-----------------|-------------------------|--------------|---|--|--------------|--|
| | | | Туре | Adjustment Type | Number | Date | Ву | | | | |
| JSL0121 | 0810 | MISC. | Material | | | | | | Estimate Exception 4 on the current Payment Estimate. | | |
| | | | | - Total | | | | \$0.00 | | | |
| | 0040 | T-4-1 | Material - To | tal | | | | \$0.00 | | | |
| | 0810 - 0820 | TEMPORARY | Material | | 2 | Apr 16, | SYSTEM | \$0.00 (\$43,550.00) | | | |
| | | TRAFFIC BARRIER, CONT. FURN/RE | | | 2 | 2025 Apr 16, 2025 | SYSTEM | \$43,550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | | | | 3 | May 2, 2025 | SYSTEM | (\$98,085.00) | Estimate Exception 4 of the editorit ayrion Estimate. | | |
| | | | | | 3 | May 2, 2025 | SYSTEM | \$98,085.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user cramec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | | | | 4 | May 16, 2025 | SYSTEM | (\$98,085.00) | Example 2.50pton 7.51 to Sunon Common Common | | |
| | | | | | 4 | May 16, 2025 | SYSTEM | \$98,085.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user cramec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | | | | 5 | Jun 2, 2025 | SYSTEM | (\$98,085.00) | | | |
| | | | | | 5 | Jun 2, 2025 | SYSTEM | \$98,085.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cramec1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | | | | | \$0.00 | | | |
| | 0820 - | Total | | | | | | \$0.00 | | | |
| | 0900 6 IN. WHITE HIGH BUILD WATERBORNE | BUILD | | | 2 | Apr 16, 2025 | SYSTEM | (\$399.50) | | | |
| | | WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | | | 2 | Apr 16, 2025 | SYSTEM | \$399.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 3 | May 2, 2025 | SYSTEM | (\$399.50) | | | |
| | | | | | 3 | May 2, 2025 | SYSTEM | \$399.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cramec1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | 0900 - | | | | | | | \$0.00 | | | |
| | 0970 | PERMANENT EROSION CONTROL | Material | | 8 | Jul 16, 2025 | SYSTEM | (\$3,616.00) | | | |
| | | GEOTEXTILE | | | 8 | Jul 16, 2025 | SYSTEM | \$3,616.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user litzam overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | (\$3,616.00) | | | |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | \$3,616.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate. | | |
| | | | | | | 10 | 10 | Aug 18, 2025 | SYSTEM | (\$3,616.00) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$3,616.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user litzam overridding Payment Estimate Exception 16 on the current Payment Estimate. | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | | Overrun | Overrun | 11 | Sep 2, 2025 | SYSTEM | (\$1,304.00) | | | | |
| | | | | 12 | Sep 16, 2025 | SYSTEM | \$1,304.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.00000 - 4.00000, 'is applied (if non-zero). | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | |
| | | | | | | | | | | | |



| Material Total | Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---|---------|--------|--------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---|--|
| 1 | JSL0121 | 0970 | EROSION CONTROL | Overrun - To | tal | | | | \$0.00 | |
| 1 | | 0970 | | | | | | | \$0.00 | |
| 11 Sep 2 SYSTEM \$10,000.00 The adjustment effects the original system-generated Material Payment Editinate Exception 13 on the current Payment Editinate Exception 14 on the current Payment Editinate Exception 15 on the current Payment Editinate Exception 16 on the current Payment Editinate Exception 17 on the current Payment Editina | | | | Material | | 11 | | SYSTEM | | |
| 1 | | | | | | 11 | Sep 2, | SYSTEM | \$16,560.00 | |
| 12 Sep 16 SYSTEM S16,360.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the outrent Payment Estimate Payment Payme | | | | | | 12 | | SYSTEM | (\$16.560.00) | |
| Part | | | | | | | 2025 | | , , | This adjustment offsets the original system-generated Material Payment |
| Material - Total | | | | | | | | | , ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | Estimate Item Adjustment (0011) due to user litzam overridding Payment |
| Overrun | | | | | - Total | | | | \$0.00 | |
| 2025 SySTEM \$1,840.00 Overrun = Total Spot SySTEM \$1,840.00 Overrun = Total Spot Spot | | | | Material - Tot | tal | | | | \$0.00 | |
| Description | | | | Overrun | Overrun | 11 | | SYSTEM | (\$1,840.00) | |
| 1000 Type C BARRIER Material | | | | | | 12 | | SYSTEM | \$1,840.00 | previous payment estimates. Price Adjustments of ',230.00000 - 230.00000, 'is |
| 1000 TYPE C BARRIER | | | | | Overrun - T | otal | | | \$0.00 | |
| 1000 TYPE C BARRIER | | | | Overrun - To | tal | | | | \$0.00 | |
| 100 | | 0990 - | Total | | | | | | \$0.00 | |
| 2025 SySTEM Stindard tem Adjustment (0072) due to user crannect overridding Payment Estimate Exception 14 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the Current Payment Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Estimate Exception 17 on the current Payment Estimate Estimate Estimate Estimate Exception 17 on the current Payment Estimate Est | | 1000 | TYPE C BARRIER | Material | | 11 | | SYSTEM | (\$15,640.00) | |
| 12 Sep 16, SYSTEM \$15,640.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. | | | | | | 11 | | SYSTEM | \$15,640.00 | Estimate Item Adjustment (0012) due to user cramec1 overridding Payment |
| Coverrun - Total Supplied (if non-zero). Supplied (if non-zero). | | | | | | 12 | | SYSTEM | (\$15,640.00) | |
| Material - Total | | | | | | 12 | | SYSTEM | \$15,640.00 | Estimate Item Adjustment (0013) due to user litzam overridding Payment |
| Overrun Overrun 11 | | | | | - Total | | | | \$0.00 | |
| 2025 12 Sep 16, SYSTEM \$1,610.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',230,00000 - 230,00000, 'is applied (if non-zero). Overrun - Total | | | | Material - Tot | tal | | | | \$0.00 | |
| Degree D | | | | Overrun | Overrun | 11 | | SYSTEM | (\$1,610.00) | |
| Total Summer Su | | | | | | 12 | | SYSTEM | \$1,610.00 | previous payment estimates. Price Adjustments of ',230.00000 - 230.00000, 'is |
| 1010 12 IN, PIPE GROUP A | | | | | Overrun - T | otal | | | \$0.00 | |
| 1010 12 IN. PIPE GROUP A Overrun 7 | | | | Overrun - To | tal | | | | \$0.00 | |
| GROUP A 7 Jul 1, 2025 7 Jul 1, 2025 8 YSTEM \$707.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate. Overrun - Total S0.00 Overrun - Total S0.00 1010 - Total 1040 48 IN. PIPE GROUP A Overrun Overrun Overrun Overrun 7 Jul 1, 2025 7 Jul 1, 2025 7 Jul 1, 2025 1040 \$300.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user cramec1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 8 Jul 16, 2025 SYSTEM (\$300.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 11 Sep 2, 2025 SYSTEM \$300.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',300.00000' -300.00000, 'is | | 1000 - | Total | | | | | | \$0.00 | |
| 2025 Estimate Item Adjustment (0003) due to user cramec1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Overrun - Total | | 1010 | | Overrun | Overrun | 7 | | SYSTEM | (\$707.00) | |
| Solution | | | | | | 7 | | SYSTEM | \$707.00 | Estimate Item Adjustment (0003) due to user cramec1 overridding Payment |
| Solution | | | | | Overrun - T | otal | | | \$0.00 | |
| 1010 - Total 1040 48 IN. PIPE GROUP A Overrun Overrun Overrun T Jul 1, 2025 T Jul 1, 2025 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user cramec1 overridding Payment Estimate Exception 8 on the current Payment Estimates. B Jul 16, 2025 SYSTEM 2025 SYSTEM \$300.00 Averaged Price Adjustment from this item on all previous payment estimates of "0.00000" is applied (if non-zero). 11 Sep 2, 2025 SYSTEM \$300.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ",300.00000 - 300.00000," is | | | | Overrun - To | tal | | | | \$0.00 | |
| 1040 48 IN. PIPE GROUP A Overrun Overrun 7 Jul 1, 2025 SYSTEM (\$300.00) 7 Jul 1, 2025 \$300.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user cramec1 overridding Payment Estimate Exception 8 on the current Payment Estimates. 8 Jul 16, 2025 \$YSTEM (\$300.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 11 Sep 2, 2025 \$300.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',300.00000' is 300.00000', is | | 1010 - | Total | | | | | | | |
| 7 Jul 1, 2025 \$300.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user cramec1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 8 Jul 16, 2025 \$YSTEM \$300.00 Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 11 Sep 2, 2025 \$YSTEM \$300.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',300.00000 - 300.00000, 'is | | | 48 IN. PIPE | Overrun | Overrun | 7 | | SYSTEM | | |
| 8 Jul 16, 2025 (\$300.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). 11 Sep 2, SYSTEM \$300.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',300.00000 - 300.00000, 'is | | | | | | 7 | Jul 1, | SYSTEM | \$300.00 | Estimate Item Adjustment (0004) due to user cramec1 overridding Payment |
| 11 Sep 2, SYSTEM \$300.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',300.00000 - 300.00000, 'is | | | | | | 8 | | SYSTEM | (\$300.00) | Averaged Price Adjustment from this item on all previous payment estimates |
| | | | | | | 11 | Sep 2, | SYSTEM | \$300.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',300.00000 - 300.00000, 'is |



| ect | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----|--------|------------------------|---------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 121 | 1040 | 48 IN. PIPE GROUP A | Overrun | Overrun - T | otal | | | \$0.00 | |
| | 1010 | T-4-1 | Overrun - To | tal | | | | \$0.00 | |
| | 1040 - | | | | | 11 10 | OVOTELL | \$0.00 | |
| | 1110 | ROCK DITCH CHECK | Material | | 4 | May 16, 2025 | | (\$430.00) | |
| | | | | | 4 | May 16, 2025 | SYSTEM | \$430.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cramec1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 5 | Jun 2, 2025 | SYSTEM | (\$430.00) | |
| | | | | | 5 | Jun 2, 2025 | SYSTEM | \$430.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user cramec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 6 | Jun 16, 2025 | SYSTEM | (\$890.00) | |
| | | | | | 6 | Jun 16, 2025 | SYSTEM | \$890.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user litzam overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 7 | Jul 1, 2025 | SYSTEM | (\$890.00) | |
| | | | | | 7 | Jul 1, 2025 | SYSTEM | \$890.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cramec1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 8 | Jul 16, 2025 | SYSTEM | (\$890.00) | |
| | | | | | 8 | Jul 16, 2025 | SYSTEM | \$890.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user litzam overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | (\$1,570.00) | |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | \$1,570.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user litzam overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | (\$2,170.00) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$2,170.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1110 - | Total | | | | | | \$0.00 | |
| | 1140 | SILT FENCE | Material | | 6 | Jun 16, 2025 | SYSTEM | (\$66.00) | |
| | | | | | 6 | Jun 16, 2025 | SYSTEM | \$66.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user litzam overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Jul 1, 2025 | SYSTEM | (\$66.00) | |
| | | | | | 7 | Jul 1, 2025 | SYSTEM | \$66.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user cramec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1140 - | Total | | | | | | \$0.00 | |
| | 1150 | MGS GUARDRAIL | Construction Stockpile | | 7 | Jul 1, 2025 | SYSTEM | (\$31,582.12) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | Stockbile | | Sep 16, 2025 | SYSTEM | (\$1,728.38) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | (\$33,310.50) | |
| | | | Construction | 1 Stockpile - ⁻ | Total | | | (\$33,310.50) | |
| | | | Construction | | 1 | Apr 2, | SYSTEM | \$33,310.50 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | Stockpile | | | 2025 | | | |



| JSL 1150 MCS GUARDRAIL 1150 TOTAL | 1160 - Total 1160 - Total 1170 - Total 1170 - Total 1180 - Total | Construction Stockpile Construction Stockpile STMI Construction Stockpile STMI Construction Stockpile EAM Construction Stockpile EAM | - Total - Total - Total - Total - Total - Total - Total | 11 Fotal 6 FMI - Total | Sep 2, 2025 Jun 16, 2025 Sep 2, | SYSTEM | \$0.00 (\$650.00) (\$650.00) (\$650.00) \$1,950.00 \$1,950.00 | |
|---|--|--|---|---------------------------|-----------------------------------|--------|--|---|
| | 1160 MGS END ANCHOR 1160 - Total 1170 MGS BR ATRANSITI (THRIE-BI BRIDGE 1180 TYPE A CRASHWEND TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction Stockpile STMI Construction Construction Construction Construction Stockpile EAM Construction Stockpile STMI | - Total - Total - Total - Total - Total - Total - Total | FMI - Total | Jun 16, 2025 | SYSTEM | (\$650.00) (\$650.00) (\$650.00) \$1,950.00 \$1,950.00 | |
| ANCHOR Slockpile 2025 (\$650.00 | 1160 - Total 1170 MGS BR TTRANSITI (THRIE-BI BRIDGE 1180 TYPE A CRASHWEND TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction Stockpile STMI Construction Construction Construction Construction Stockpile EAM Construction Stockpile STMI | - Total - Total - Total - Total - Total - Total - Total | FMI - Total | Jun 16, 2025 | SYSTEM | (\$650.00) (\$650.00) \$1,950.00 \$1,950.00 \$1,950.00 | |
| Construction Cons | 1170 MGS BR A TRANSITI (THRIE-BI BRIDGE) 1170 - Total 1180 TYPE A CRASHWEND TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction Stockpile STMI Construction ON EAM Construction Stockpile STMI Construction Stockpile STMI | n Stockpile - T - Total - Total - Total n Stockpile - T | 6 FMI - Total | 2025 Sep 2, | | (\$650.00) \$1,950.00 \$1,950.00 \$1,950.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Construction | 1170 MGS BR A TRANSITI (THRIE-BI BRIDGE) 1170 - Total 1180 TYPE A CRASHWEND TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction Stockpile STMI Construction ON EAM Construction Stockpile STMI Construction Stockpile STMI | - Total n Stockpile ST - Total n Stockpile - T | 6 FMI - Total | 2025 Sep 2, | | \$1,950.00 \$1,950.00 \$1,950.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Stockpile 2025 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 31,950,00 | 1170 MGS BR A TRANSITI (THRIE-BI BRIDGE) 1170 - Total 1180 TYPE A CRASHWEND TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction APP Construction Stockpile Construction Construction Construction Stockpile STMI | - Total n Stockpile ST - Total n Stockpile - T | TMI - Total | 2025 Sep 2, | | \$1,950.00 \$1,950.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Total | 1170 MGS BR A TRANSITI (THRIE-BI BRIDGE) 1170 - Total 1180 TYPE A CRASHWEND TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction APP ON EAM Construction Construction Stockpile STMI | n Stockpile ST - Total n Stockpile - T | 11 | Sep 2, | SYSTEM | \$1,950.00 | |
| 1100 Total 1170 MSB R APP 177 MSB R APP 178 | 1170 MGS BR A TRANSITI (THRIE-BI BRIDGE) 1170 - Total 1180 TYPE A CRASHWEND TERI (MASH) 1180 - Total 1200 SIGNAL H | APP Construction ON Stockpile Construction Construction Stockpile STMI | - Total n Stockpile - T | 11 | Sep 2, | SYSTEM | | |
| 1170 MCS BR APP TWANSTION TWANSTION THAILS BEAM Strickpile Transaction TWANSTION TWA | 1170 MGS BR A TRANSITI (THRIE-BI BRIDGE) 1170 - Total 1180 TYPE A CRASHWEND TERI (MASH) 1180 - Total 1200 SIGNAL H | ON Stockpile Construction Construction Stockpile STMI | - Total n Stockpile - T | | | SYSTEM | \$1,300.00 | |
| TRANSITION (THRIE-BEAM BRIDGE | TRANSITI (THRIE-BI BRIDGE 1170 - Total 1180 TYPE A CRASHW END TERI (MASH) 1180 - Total 1200 SIGNAL H | ON Stockpile Construction Construction Stockpile STMI | - Total n Stockpile - T | | | SYSTEM | | |
| SRIDGE | 1170 - Total 1180 TYPE A CRASHW END TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction Construction Stockpile STMI | n Stockpile - T | Гotal | | | (\$3,670.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Construction Slockpile STMI - Total S7,340,00 Payment Estimate Item Adjustment generated Stockpile Transaction Slockpile STMI - Total S7,340,00 | 1180 TYPE A CRASHW END TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction Stockpile STMI | | Γotal | | | (\$3,670.00) | |
| Stockpile STMI -Total Stockpile STMI -Total ST,340.00 | 1180 TYPE A CRASHW END TERI (MASH) 1180 - Total 1200 SIGNAL H | Stockpile STMI | | | | | (\$3,670.00) | |
| 1170 - Total | 1180 TYPE A CRASHW END TERI (MASH) 1180 - Total 1200 SIGNAL H | | - Total | 6 | | SYSTEM | \$7,340.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| 1170 - Total 1180 TYPE A CRASHWORTHY END TERMINAL (MASH) Construction Stockpile - Total (\$1,850.00) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total (\$1,850.00) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total (\$1,850.00) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total (\$1,850.00) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total \$9,250.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total \$9,250.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total \$9,250.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total \$9,250.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total \$9,250.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total \$9,250.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total \$9,250.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total \$9,250.00 Stockpile - Total \$9,250.00 Stockpile - Total \$0,000 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user iteram overridding Payment Estimate Item Adjustment (0015) due to user iteram overridding Payment Estimate Item Adjustment (0016) due to user iteram overridding Payment Estimate Item Adjustment (0016) due to user iteram overridding Payment Estimate Item Adjustment (0016) due to user iteram overridding Payment Estimate Item Adjustment (0016) due to user iteram overridding Payment Estimate Item Adjustment (0016) due to user iteram overridding Payment Estimate Item Adjustment (0016) due to user iteram overridding Payment Estimate Item Adjustment (0016) due to user iteram overridding Payment Estimate Item Adjustment (0016) due to user iteram overridding Pay | 1180 TYPE A CRASHW END TERI (MASH) 1180 - Total 1200 SIGNAL H | Construction | | | | | \$7,340.00 | |
| 1170 - Total | 1180 TYPE A CRASHW END TERI (MASH) 1180 - Total 1200 SIGNAL H | | n Stockpile ST | ΓΜΙ - Total | | | \$7,340.00 | |
| CRASHWORTHY END TERMINAL (MASH) | CRASHW END TERI (MASH) 1180 - Total 1200 SIGNAL H | | | | | | \$3,670.00 | |
| Construction Stockpile - Total System System System System System Stockpile Stimular System System System System Stockpile Stimular Stockpile Sto | 1180 - Total 1200 SIGNAL H | ORTHY Stockpile | | 11 | | SYSTEM | (\$1,850.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Construction Stockpile Total | 1180 - Total 1200 SIGNAL H | MINAL | - Total | | | | (\$1,85 <u>0.00)</u> | |
| Stockpile STMI -Total S9,250.00 | 1200 SIGNAL H | Construction | n Stockpile - T | Гotal | | | (\$1,850.00) | |
| Total \$9,250.00 | 1200 SIGNAL H | Stockpile | | 6 | | SYSTEM | \$9,250.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| 1180 - Total 11 | 1200 SIGNAL H | STMI | - Total | | | | \$9,250.00 | |
| 1200 SIGNAL HEAD, TYPE 3B | 1200 SIGNAL H | Construction | n Stockpile ST | ΓΜΙ - Total | | | \$9,250.00 | |
| TYPE 3B | | | | | | | \$7,400.00 | |
| Estimate Item Adjustment (0017) due to user cramec1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 12 Sep 16, SYSTEM (\$6,165.00) 12 Sep 16, SYSTEM \$6,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 22 on the current Payment Estimate. 12 Sep 16, SYSTEM \$6,165.00 This adjustment (0015) due to user litzam overridding Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 22 on the current Payment Estimate. 1200 - Total \$0.00 1200 | | EAD, Material | | 11 | | SYSTEM | (\$6,165.00) | |
| 2025 12 Sep 16, 2025 \$ SYSTEM \$6,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 22 on the current Payment Estimate. - Total \$0.00 1200 - Total \$0.00 1230 POST, TYPE B, LONGEST ARM 55 FT. Material 11 Sep 2, 2025 SYSTEM (\$32,888.00) | | | | 11 | | SYSTEM | \$6,165.00 | Estimate Item Adjustment (0017) due to user cramec1 overridding Payment |
| 2025 Estimate Item Adjustment (0015) due to user litzam overridding Payment Estimate Exception 22 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 1200 - Total \$0.00 1230 POST, TYPE B, LONGEST ARM 55 FT. SYSTEM (\$32,888.00) | | | | 12 | | SYSTEM | (\$6,165.00) | |
| Material - Total \$0.00 | | | | 12 | | SYSTEM | \$6,165.00 | Estimate Item Adjustment (0015) due to user litzam overridding Payment |
| Material - Total \$0.00 | | | - Total | | | | \$0.00 | |
| 1230 POST, TYPE B, LONGEST ARM 55 FT. | | Material - T | otal | | | | \$0.00 | |
| LONGEST ARM 55 2025 7 | 1200 - Total | | | | | | \$0.00 | |
| | LONGEST | | | 11 | | SYSTEM | (\$32,888.00) | |
| 11 Sep 2, 2025 SYSTEM \$32,888.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user cramec1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | FT. | | | 11 | | SYSTEM | \$32,888.00 | |
| 12 Sep 16, 2025 (\$32,888.00) | | | | 12 | | SYSTEM | (\$32,888.00) | |
| 12 Sep 16, 2025 \$32,888.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user litzam overridding Payment Estimate Exception 23 on the current Payment Estimate. | | | | 12 | | SYSTEM | \$32,888.00 | Estimate Item Adjustment (0016) due to user litzam overridding Payment |
| - Total \$0.00 | | | - Total | | | | \$0.00 | |
| | | Material - T | otal | | | | \$0.00 | |
| Material - Total \$0.00 | 1230 - Total | | | | | | \$0.00 | |
| | TRENCH | | | 9 | Aug 4, 2025 | SYSTEM | (\$340.00) | |
| 1230 - Total | TRACER | | | 9 | Aug 4, 2025 | SYSTEM | \$340.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user litzam overridding Payment |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---------|---------------|--|------------------|--------------------|--------|-----------------|---------|---------------|---|
| | 20 | Bossiiption | Туре | Adjustment Type | Number | Date | Ву | 7 1110 1111 | , containe |
| JSL0121 | 1240 | CONDUIT, 3 IN., | Material | | | | | | Estimate Exception 9 on the current Payment Estimate. |
| | | TRENCH WITH TRACER WIRE | | | 10 | Aug 18, 2025 | SYSTEM | (\$340.00) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$340.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment |
| | | | | - Total | | | | \$0.00 | Estimate Exception 20 on the current Payment Estimate. |
| | | | Material - To | | | | | \$0.00 | |
| | 1240 - | Total | | | | | | \$0.00 | |
| | 1250 | CONDUIT, 3 IN., PUSHED WITH | Material | | 8 | Jul 16, 2025 | SYSTEM | (\$3,399.00) | |
| | | TRACER WIRE | | | 8 | Jul 16, 2025 | SYSTEM | \$3,399.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user litzam overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | (\$3,399.00) | Zamilate Zasopitani, di ila zandini di dina zamilate. |
| | | | | | 9 | Aug 4, | SYSTEM | \$3,399.00 | This adjustment offsets the original system-generated Material Payment |
| | | | | | | 2025 | | | Estimate Item Adjustment (0007) due to user litzam overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | (\$3,399.00) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$3,399.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user litzam overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | 4050 | | Material - Total | | | | | \$0.00 | |
| | 1250 - | | Material | | | | | \$0.00 | |
| | 1270 | PULL BOX, PREFORMED CLASS 2 | Material | | 9 | Aug 4, 2025 | SYSTEM | (\$1,840.00) | |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | \$1,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | (\$1,840.00) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$1,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user litzam overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1270 - | Total | | | | | | \$0.00 | |
| | 1330 | OPT. OVERHEAD SIGN TRUSS SUBSTRUCTURES | Material | | 9 | Aug 4, 2025 | SYSTEM | (\$43,800.00) | |
| | | SUBSTRUCTURES | | | 9 | Aug 4, 2025 | SYSTEM | \$43,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | (\$43,800.00) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$43,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user litzam overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | (\$43,800.00) | |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | \$43,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user cramec1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | (\$43,800.00) | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$43,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user litzam overridding Payment Estimate Exception 25 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1330 - | Total | | | | | | \$0.00 | |
| | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------------------|--|--------------------|-----------------------------|----------------|-----------------|---------------|-----------------------------|---|
| JSL0121 | 5101 | PULL BOX, PREFORMED CLASS 1 | Material | | 8 | Jul 16, 2025 | SYSTEM | (\$4,105.50) | |
| | | | | | 8 | Jul 16, 2025 | SYSTEM | \$4,105.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user litzam overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | (\$4,105.50) | |
| | | | | | 9 | Aug 4, 2025 | SYSTEM | \$4,105.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user litzam overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | (\$4,105.50) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$4,105.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user litzam overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | (\$4,105.50) | |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | \$4,105.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user cramec1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | (\$4,105.50) | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$4,105.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user litzam overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 5101 - | Total CURVED VANE GRATE AND FRAME(4 FT. X 2 FT | | | | | | \$0.00 | |
| | 5102 | | Material | | 12 | Sep 16, 2025 | SYSTEM | (\$2,950.00) | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$2,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user litzam overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | Material - Total | | | | | | | |
| | | 5102 - Total 5103 - 30 IN GROUP A Material 8 Jul 16 SYSTEM | | | | | | \$0.00 | |
| | 5103 | 30 IN. GROUP A FLARED END SECT | Material | | 8 | Jul 16, 2025 | SYSTEM | (\$3,465.00) | |
| | | 0201 | | | 8 | Jul 16, 2025 | SYSTEM | \$3,465.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user litzam overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 5103 - 5106 | Total MISC. ITS | Material | | 9 | Aug 4, | SYSTEM | \$0.00 (\$26,098.79) | |
| | | | | | 9 | 2025 Aug 4, | SYSTEM | \$26,098.79 | This adjustment offsets the original system-generated Material Payment |
| | | | | | | 2025 | | | Estimate Item Adjustment (0011) due to user litzam overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | (\$26,098.79) | |
| | | | | | 10 | Aug 18, 2025 | SYSTEM | \$26,098.79 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user litzam overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | (\$26,098.79) | |
| | | | | | 11 | Sep 2, 2025 | SYSTEM | \$26,098.79 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user cramec1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | (\$26,098.79) | |
| | | | | | 12 | Sep 16, 2025 | SYSTEM | \$26,098.79 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user litzam overridding Payment Estimate Exception 26 on the current Payment Estimate. |





| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Amount | Remarks | |
|-----------------|--------------|-------------|--------------------|-----------------------------|----------------|-----------------|--------|-------------|--|
| JSL0121 | 5106 | MISC. ITS | Material | - Total | | | | \$0.00 | |
| | | | Material - Tot | al | | | | \$0.00 | |
| | 5106 - Total | | | | | | \$0.00 | | |
| JSL0121 - Total | | | | | | | | \$11,642.00 | |
| Overall - Total | | | | | | | | \$11,448.00 | |

MoDOT

Contract Adjustments for Contract - 250117-F03

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 26 of 26