

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2025

Progress Estimate Number 9	Contract ID Prime Contract	250117- or Fronaba	-H03 arger Concreters, Inc.		Period Start Period End	September 1 September 3	,	Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,720,535.7 \$0.0 \$2,720,535.7		
Approval Date									By User		
October 1, 2025		at the Project Office Level by	brophm1								
October 1, 2025	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by										
October 3, 2025		e Controllers Office Level by	ramses1								
Original Complete	ion Date	Current C	ompletion Date	Ac	tual Complet	ion Date	9,	% of Current Contract Amount	Amount Complete		
November 1, 2	2025	Novem	nber 1, 2025					69.93%			
	Contr	act Informa	tional Dates					Milestones			
Date Description	Original Comp	letion Date	Current Completion	n Date		No Milestones Exist for Contract					
Acceptance Date											
Awarded Date	February 5, 2025 February 5, 2025										
Letting Date	January 17, 202	25	January 17, 2025								
Notice to Proceed Date	March 10, 2025	;	March 10, 2025								
Work Began Date											

Contract Total Pa	ay For Estimate No. 9			
		This Estimate	Previous	To Date
250117-H03				
	Total Posted Items Pay	\$324,838.25	\$1,577,690.43	\$1,902,528.68
	Gross Item Adjustments	\$0.00	\$16,704.73	\$16,704.73
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,594,395.16	\$1,919,233.41
Contract Total Pa	avable This Estimate:	\$324.838.25		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9P3842	0040	2031000	CLASS A EXCAVATION	CUYD	\$23.000	278	\$6,394.00
	0060	2036000	COMPACTING EMBANKMENT	CUYD	\$7.000	192.500	\$1,347.50
	0070	2037075	COMPACTING IN CUT	STA	\$1,400.000	2.075	\$2,905.00
	0090	2079909	MISC.Modified Linear Grading Class 2	STA	\$3,300.000	3.300	\$10,890.00
	0120	4010150	TYPE A2 SHOULDER	SQYD	\$50.000	69.380	\$3,469.00
	0170	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	SQYD	\$95.000	2,775.750	\$263,696.25
	0230	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	CUYD	\$46.000	6.400	\$294.40
	0240	6096042	PLACING TYPE 2 ROCK DITCH LINER	CUYD	\$41.000	6.400	\$262.40
	0250	6099903	MISC.Modified Concrete Curb and Gutter, Type A	LF	\$43.000	676.400	\$29,085.20
	0470	6240104A	SEPARATION GEOTEXTILE	SQYD	\$5.000	20.900	\$104.50
	0500	7250321A	21 IN. PIPE GROUP B	LF	\$90.000	71	\$6,390.00
Project J9P3842	! - Total						\$324,838.25
Overall - Total							\$324,838.25

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3842	0120	TYPE A2 SHOULDER	Material			-610.67000	\$50.00	(\$30,533.50)
	0120	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	610.67000	\$50.00	\$30,533.50

Revision 9/2/2025 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2025

Estimate	gress e Numl 9		50117-H03 Fronabarger Con	creters, Inc.	Pay Period End September 30, 2025 No.	riginal Contract et Change Orde urrent Contract	r Amount	\$2,720,535.77 \$0.00 \$2,720,535.77
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
19P3842	0120	TYPE A2 SHOULDER	Other Item Adjustment	Fuel Price	Contractor did not select fuel adjustment on contract.			(\$13.98)
	0120	TYPE A2 SHOULDER	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	69.38000	\$0.20	\$13.98
	0170	CONCRETE PAVEMENT (!IN. NON-REINF)	9 Material			-7,718.45000	\$95.00	(\$733,252.75)
	0170	CONCRETE PAVEMENT (! IN. NON-REINF)	9 Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	7,718.45000	\$95.00	\$733,252.75
	0200	PAVED APPROACH, 8 IN.	Material			-578.90000	\$87.00	(\$50,364.30)
	0200	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	578.90000	\$87.00	\$50,364.30
	0210	MISC.	Material			-346.42000	\$120.00	(\$41,570.40)
	0210	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	346.42000	\$120.00	\$41,570.40
	0220	CONCRETE GUTTER TYPE	E Material			-6.30000	\$55.00	(\$346.50)
	0220	CONCRETE GUTTER TYPE A	E Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	6.30000	\$55.00	\$346.50
	0250	MISC.	Material			-1,412.70000	\$43.00	(\$60,746.10)
	0250	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	1,412.70000	\$43.00	\$60,746.10
	0560	SEEDING - COOL SEASON GRASSES	I Material			-0.80000	\$2,900.00	(\$2,320.00)
	0560	SEEDING - COOL SEASON GRASSES	I Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	0.80000	\$2,900.00	\$2,320.00
otal								\$0.00

Revision 9/2/2025 Page 2 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J9P3842	FAF 72-2(25)	Roundabout	72	BOLLINGER	at the intersection of Ro	oute 72 and Route 51						
Totals b	by Job N	lumbers										
J9P3842		ed Item Pay s Item Adjustn		s Item Pay	This Estimate \$324,838.25 \$0.00 \$324,838.25	Previous \$1,577,690.43 \$16,704.73 \$1,594,395.16	To Date \$1,902,528.68 \$16,704.73 \$1,919,233.41					
	Liqui	ntive Icentive dated Damage r Contract Adji	s	·	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 5/29/2025 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 4010150, Project Item Line Number 0120, Material Set 401015096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC testing has not been performed or inputted.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 4010150, Project Item Line Number 0120, Material Set 401015096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC and QA have been performed or inputted	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 5021109, Project Item Line Number 0170, Material Set 502110996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Not all QC and QA have been performed or inputted.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 5021109, Project Item Line Number 0170, Material Set 502110996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Not all QC and QA have been performed or inputted	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 5021109, Project Item Line Number 0170, Material Set 502110996, Material 1005FACCNSCB - Natural Sand for Conc Class B, Acceptance Action Generic 1005FACCNSCB is insufficient.	Not all QC and QA have been performed or inputted	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	The PAL for this line item has either not been inputted by MoDOT or submitted by Contractor. Inspector is working on this issue.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Tests need to be zeroed for contract.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Not all QC test have been performed or inputted.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Not all QC and QA have been performed or inputte	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6089905, Project Item Line Number 0210, Material Set 608990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Not all QC and QA have been performed or inputte	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6091041, Project Item Line Number 0220, Material Set 609104196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	PALs have not been inputted by Jefferson City.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6091041, Project Item Line Number 0220, Material Set 609104196, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PALs have not been inputted by Jefferson City.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6099903, Project Item Line Number 0250, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC test has not been inputted or performed.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6099903, Project Item Line Number 0250, Material Set 6099903, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Not all QC and QA test have been inputted.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6099903, Project Item Line Number 0250, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Tests need to be zeroed for contract.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 8051000A, Project Item Line Number 0560, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Inspector has emailed Contractor for paperwork.	brophm1	Overridden
Estimate Exception Type: Item Overrun: Contract 250117-H03, Contract Project J9P3842, Project Item Line Number 0390, Contract Line Item Number 0390, Item 6205309, Minor Item.	Change Order 0001 need to be wrote.	brophm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 250117-H03, Contract Project J9P3842, Project Item Line Number 0570, Contract Line Item Number 0570, Item 8061005, Minor Item.	Change Order 0001 need to be wrote.	brophm1	Acknowledged

Revision 5/29/2025 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
J9P3842	0001	0010	1041000	TEMPORARY SURFACING	662.00	0.00	662.00	CUYD	189.80	\$55.00	\$10,439.0
	0001	0020	1081000	SIGNET DBE REPORTING	1.00	0.00	1.00	LS	1.00	\$1,000.00	\$1,000.
	0001	0030	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.60	\$85,000.00	\$51,000.
	0001	0040	2031000	CLASS A EXCAVATION	3,252.00	0.00	3,252.00	CUYD	2,974.00	\$23.00	\$68,402.
	0001	0050	2035500	EMBANKMENT IN PLACE	1,551.00	0.00	1,551.00	CUYD	1,551.00	\$20.00	\$31,020.
	0001	0060	2036000	COMPACTING EMBANKMENT	2,828.00	0.00	2,828.00	CUYD	2,635.50	\$7.00	\$18,448.
	0001	0070	2037075	COMPACTING IN CUT	21.30	0.00	21.30	STA	19.26	\$1,400.00	\$26,971.
	0001	0080	2063000	CLASS 3 EXCAVATION	75.00	0.00	75.00	CUYD	45.00	\$40.00	\$1,800.
	0001	0090	2079909	MISC.Modified Linear Grading Class 2	24.10	0.00	24.10	STA	22.00	\$3,300.00	\$72,600.
	0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	11,162.00	0.00	11,162.00	SQYD	7,851.30	\$9.00	\$70,661.
	0001	0110	3109907	MISC.2 Inch Clean Rock	177.00	0.00	177.00	CUYD	177.00	\$52.00	\$9,204.
	0001	0120	4010150	TYPE A2 SHOULDER	839.40	0.00	839.40	SQYD	610.67	\$50.00	\$30,533.
	0001	0130	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,530.60	0.00	1,530.60	TONS	631.60	\$116.11	\$73,335.
	0001	0140	4019905	MISC.Optional Pavement	1,522.60	0.00	1,522.60	SQYD	1,356.80	\$58.58	\$79,481.
	0001	0150	4029905	MISC.Optional Base	929.30	0.00	929.30	SQYD	929.30	\$27.91	\$25,936.
	0001	0160	4071005	TACK COAT	412.00	0.00	412.00	GAL	412.00	\$3.99	\$1,643.
	0001	0170	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	8,945.80	0.00	8,945.80	SQYD	7,718.45	\$95.00	\$733,252.
	0001	0180	5029905	MISC.Tinted 9 inch PCCP	595.20	0.00	595.20	SQYD	574.10	\$126.00	\$72,336.
	0001	0190	6085007	PAVED APPROACH, 7 IN.	380.00	0.00	380.00	SQYD	0.00	\$82.00	\$0.
	0001	0200	6085008	PAVED APPROACH, 8 IN.	1,796.00	0.00	1,796.00	SQYD	578.90	\$87.00	\$50,364.
	0001	0210	6089905	MISC.Tinted 6 inch Concrete Median	829.50	0.00	829.50	SQYD	346.42	\$120.00	\$41,570.
	0001	0220	6091041	CONCRETE GUTTER TYPE A	93.00	0.00	93.00	LF	74.20	\$55.00	\$4,081.
	0001	0230	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	41.00	0.00	41.00	CUYD	22.90	\$46.00	\$1,053.
	0001	0240	6096042	PLACING TYPE 2 ROCK DITCH LINER	41.00	0.00	41.00	CUYD	22.90	\$41.00	\$938.
	0001	0250	6099903	MISC.Modified Concrete Curb and Gutter, Type A	1,744.00	0.00	1,744.00	LF	1,412.70	\$43.00	\$60,746.
	0001	0260	6099903	MISC.Tinted 6 inch Integral Curb, Type A	503.00	0.00	503.00	LF	503.00	\$15.00	\$7,545.
	0001	0270	6161005	CONSTRUCTION SIGNS	1,081.00	0.00	1,081.00	SQFT	779.00	\$9.00	\$7,043.
	0001	0280	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.
	0001	0290	6169901	MISC.Temporary Traffic Control	1.00	0.00	1.00	LS	0.75	\$7,625.00	\$5,718.
	0001	0300	6169902	MISC.Portable Traffic Signal System	1.00	0.00	1.00	EA	1.00	\$25,500.00	\$25,500.
	0001	0310	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,300.00	0.00	1,300.00	LF	1,300.00	\$36.44	\$47,372
	0001	0320	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$1,194.00	\$2,388
	0001	0330	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$205,000.00	\$205,000
	0001	0340	6200006	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	4,918.00	0.00	4,918.00	LF	0.00	\$5.00	\$0.
	0001	0350	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	4,782.00 77.00	0.00	4,782.00 77.00	LF LF	0.00	\$6.00 \$25.00	\$0. \$0.
		0300	0200010	YELLOW	77.00	0.00	77.00		0.00	Ψ23.00	ψΟ.
	0001	0370	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	200.00	0.00	200.00	LF	0.00	\$3.00	\$0.
	0001	0380	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	1,000.00	0.00	1,000.00	LF	0.00	\$3.00	\$0.
	0001	0390	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	36.00	0.00	36.00	LF	60.00	\$10.00	\$600.
	0001	0400	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	375.00	0.00	375.00	LF	0.00	\$5.00	\$0.
	0001	0410	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	12,172.00	0.00	12,172.00	LF	3,374.00	\$0.80	\$2,699
	0001	0420	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	36.00	0.00	36.00	LF	0.00	\$10.00	\$0
	0001	0430	6207001	PAVEMENT MARKING REMOVAL	1,236.00	0.00	1,236.00	LF	476.00	\$4.00	\$1,904.
	0001	0440	6209902	MISC.Preformed Thermoplastic Marking, 24 Inch, Yield Line	32.00	0.00	32.00	EA	0.00	\$75.00	\$0.
	0001	0450	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	775.00	0.00	775.00	SQYD	0.00	\$8.50	\$0.
	0001	0460	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	444.00	0.00	444.00	SQYD	334.00	\$14.83	\$4,953.
	0001	0470	6240104A	SEPARATION GEOTEXTILE	872.00	0.00	872.00	SQYD	814.50	\$5.00	\$4,072.
	0400 0274000 CONTRACTORY ORNIGINED SORVETING AND GLARING		1.00	0.00	1.00	LS	0.75	\$15,000.00	\$11,250.		
	0400 720010A 10 IV. 1 II E GIVOOL B			177.00	0.00	177.00	LF	147.00	\$85.00	\$12,495	
		0500	7250321A	21 IN. PIPE GROUP B	71.00	0.00	71.00	LF	71.00	\$90.00	\$6,390
	0001	0510	7261018	18 IN. PIPE GROUP A	100.00	0.00	100.00	LF	0.00	\$85.00	\$0.
	0001	0520	7261024	24 IN. PIPE GROUP A	62.00	0.00	62.00	LF	0.00	\$95.00	\$0

Revision 5/29/2025 Page 5 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract	Project	Category	Line	Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTE
ID	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See repor generated date)
50117- 03	J9P3842	0001	0530	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$650.00	\$1,300.0
		0001	0540	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$750.00	\$0.0
		0001	0550	8025006	MULCHING	1.10	0.00	1.10	ACRE	0.80	\$1,250.00	\$1,000.0
		0001	0560	8051000A	SEEDING - COOL SEASON GRASSES	1.10	0.00	1.10	ACRE	0.80	\$2,900.00	\$2,320.
		0001	0570	8061005	ROCK DITCH CHECK	180.00	0.00	180.00	LF	433.00	\$15.00	\$6,495.
		0001	0580	8061017	TEMPORARY SEEDING	0.70	0.00	0.70	ACRE	0.30	\$2,150.00	\$645.0
		0001	0590	8061019	SILT FENCE	3,540.00	0.00	3,540.00	LF	195.00	\$2.90	\$565.5
		0020	0600	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	8.00	0.00	8.00	EA	0.00	\$2,990.00	\$0.0
		0020	0610	9011106	BRACKET ARM, 6 FT. OR 1.8 M	8.00	0.00	8.00	EA	0.00	\$562.00	\$0.0
		0020	0620	9011312	LUMINAIRE, LED-B	8.00	0.00	8.00	EA	0.00	\$359.00	\$0.0
		0020	0630	9014003	CONDUIT, 3 IN. RIGID, PUSHED	186.00	0.00	186.00	LF	0.00	\$40.00	\$0.
		0020	0640	9015010	TRENCHING TYPE I	1,363.00	0.00	1,363.00	LF	0.00	\$8.61	\$0.
		0020	0650	9016110	PULL BOX, PREFORMED CLASS 1	6.00	0.00	6.00	EA	0.00	\$1,232.00	\$0.
		0020	0660	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	860.00	0.00	860.00	LF	0.00	\$1.00	\$0.
		0020	0670	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,940.00	0.00	1,940.00	LF	0.00	\$3.90	\$0.
		0020	0680	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	0.00	\$1,853.00	\$0.
		0040	0690	9031210	STRUCTURAL STEEL POSTS	260.00	0.00	260.00	LB	0.00	\$8.00	\$0.
		0040	0700	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	14.00	0.00	14.00	EA	0.00	\$350.00	\$0.
		0040	0710	9031270A	2 IN. PSST POST - 12 GA.	342.00	0.00	342.00	LF	0.00	\$26.00	\$0.
		0040	0720	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	34.00	0.00	34.00	EA	0.00	\$175.00	\$0.
		0040	0730	9031272A	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	9.00	0.00	9.00	EA	0.00	\$200.00	\$0.
		0040	0740	9031280	2.5 IN. PSST POST - 12 GA.	221.00	0.00	221.00	LF	0.00	\$28.00	\$0.
		0040	0750	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	16.00	0.00	16.00	EA	0.00	\$225.00	\$0.
		0040	0760	9035004A	SH-FLAT SHEET	340.00	0.00	340.00	SQFT	0.00	\$26.00	\$0.
		0040	0770	9035011A	ST-STRUCTURAL	160.00	0.00	160.00	SQFT	0.00	\$36.00	\$0.
		0040	0780	9035069A	SHF-FLAT SHEET FLUORESCENT	88.00	0.00	88.00	SQFT	0.00	\$32.00	\$0.
	Project J	9P3842 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,906,844.
0117-F	103 Overal	I - Total Va	lue Poste	ed to Date as	of Report Generated Date							\$1,906,844.

Revision 5/29/2025 Page 6 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3842

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	2031000	CLASS A EXCAVATION	9/18/25	9/22/25	1	278.00	CUYD	MO 51 South Leg	328+60.82	RT	332+75.96	RT	(415.14')*(5')*(3.61')/27 = 278 CY brophm1
0060	2036000	COMPACTING EMBANKMENT	9/18/25	9/22/25	1	192.50	CUYD	MO 51 South Leg	328+60.82	RT	332+75.96	RT	(415.14')*(12')(1.043')/27 = 192.5 CY brophm1
0070	2037075	COMPACTING IN CUT	9/18/25	9/22/25	1	2.08	STA	MO 51 South Leg	328+60.82	RT	332+75.96	RT	Field Measured and Verified brophm1
0090	2079909	MISC. GRADING	9/26/25	9/29/25	1	0.30	STA	MO 72 East Leg	427+28.77	LT	427+28.77	LT	Field Verified brophm1
				9/29/25	2	2.70	STA	MO 51 North Leg	321+11.21	LT	321+11.21	LT	Field Verified brophm1
				9/29/25	3	0.30	STA	MO 51 North Leg	324+07.01	LT	324+07.01	LT	Field Verified brophm1
0120	4010150	TYPE A2 SHOULDER	9/18/25	9/22/25	1	37.60	SQYD	RTE 72 BL (RANE_BL_72)	0+00.00	RT	0+84.55	RT	(84.6')*(4')/9 = 37.6 SY brophm1
				9/22/25	2	31.78	SQYD	RTE 72 BL (RANE_BL_72)	1+55.12	RT	2+26.58	RT	(71.5')*(4')/9 = 31.78 SY brophm1
0170	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	9/18/25	9/22/25	1	1,170.05	SQYD	MO 72 East Leg	423+70.57	LT	429+75.00	LT	(604.43')*(17.422')/9 = 1170.05 SY brophm1
			9/26/25	9/29/25	1	774.20	SQYD	MO 72 East Leg	423+70.57	LT	427+70.57	LT	(400')*(17.42')/9 = 774.2 SY brophm1
			9/29/25	9/30/25	2	831.50	SQYD	MO 51 South Leg	328+22.04	RT	332+75.96	RT	(453.92')*(16.486')/9 = 774.2 SY brophm1
0230	6096020	FURN. TYPE 2 ROCK DITCH LINER	9/30/25	10/1/25	1	6.40	CUYD	West Leg Route 72 (RASW_BL_72)	3+12.19	RT	3+12.19	RT	(10')*(11.52')*(1.5')/27 = 6.4 CY brophm1
0240	6096042	PLACING TYPE 2 ROCK DITCH LINER	9/30/25	10/1/25	1	6.40	CUYD	West Leg Route 72 (RASW_BL_72)	3+12.19	RT	3+12.19	RT	(10')*(11.52')*(1.5')/27 = 6.4 CY brophm1
0250	6099903	MISC. PAVED DRAINAGE	9/18/25	9/22/25	1	184.90	LF	RTE 72 BL (RANE_BL_72)	4+00.00	RT	6+17.22	RT	4" Curb and Gutter Field Measured and Verified brophm1
			9/26/25	9/29/25	1	279.70	LF	RTE 72 BL (RASE_BL_72)	3+77.32	LT	6+57.03	LT	4-inch curb field measured and verified brophm1
			9/29/25	9/30/25	2	211.80	LF	RTE 51 BL (RASE_BL_51)	2+56.62	RT	4+68.45	RT	4-inch curb field measured and verified brophm1
0470	6240104A	SEPARATION GEOTEXTILE	9/30/25	10/1/25	1	20.90	SQYD	West Leg Route 72 (RASW_BL_72)	3+12.19	RT	3+12.19	RT	(13')*(14.47')/9 = 20.9 SY brophm1
0500	7250321A	21 IN. PIPE CULVERT GROUP B	9/26/25	9/29/25	1	71.00	LF	MO 72 East Leg	427+28.77	LT	427+28.77	LT	Field Verified brophm1

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 7 of 16



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3842	0050	EMBANKMENT IN PLACE	Material		5	Aug 1, 2025	SYSTEM	(\$19,660.00)	
					5	Aug 1, 2025	SYSTEM	\$19,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0050 -							\$0.00	
	0060	COMPACTING EMBANKMENT	Material		5	Aug 1, 2025	SYSTEM	(\$10,528.00)	
					5	Aug 1, 2025	SYSTEM	\$10,528.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0060 -							\$0.00	
	0100	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		5	Aug 1, 2025	SYSTEM	(\$30,231.00)	
		THICK)			5	Aug 1, 2025	SYSTEM	\$30,231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Aug 18, 2025	SYSTEM	(\$52,201.80)	
					6	Aug 18, 2025	SYSTEM	\$52,201.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0100 -							\$0.00	
	0110	MISC. GRAVEL OR CR. STONE	Material		7	Sep 2, 2025	SYSTEM	(\$9,204.00)	
					7	Sep 2, 2025	SYSTEM	\$9,204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -							\$0.00	
	0120	TYPE A2 SHOULDER	Material		7	Sep 2, 2025	SYSTEM	(\$20,015.50)	
					7	Sep 2, 2025	SYSTEM	\$20,015.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Sep 16, 2025	SYSTEM	(\$27,064.50)	
					8	Sep 16, 2025	SYSTEM	\$27,064.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Oct 1, 2025	SYSTEM	(\$30,533.50)	
					9	Oct 1, 2025	SYSTEM	\$30,533.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment	FUEL	6	Aug 18, 2025	brophm1	(\$43.90)	All A2 shoulders on this project are concrete. The system assumed the shoulders are asphalt and took fuel out automatically.
					7	Sep 2, 2025	brophm1	(\$66.18)	System gave money for fuel adjustment. Contractor did not check fuel adjustment for concrete on contract.
					8	Sep 16, 2025	brophm1	(\$28.41)	System gave money for fuel adjustment. Contractor did not check fuel adjustment for concrete on contract
					9	Oct 1, 2025	brophm1	(\$13.98)	Contractor did not select fuel adjustment on contract.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type		Date	Ву		
J9P3842	0120	TYPE A2 SHOULDER	Other Item Adjustment	FUEL - Tota	ıl			(\$152.47)	
			Other Item	Adjustment -	Total			(\$152.47)	
			Price FUEL		6	Aug 18, 2025	SYSTEM	\$43.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Sep 2, 2025	SYSTEM	\$66.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 16, 2025	SYSTEM	\$28.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Oct 1, 2025	SYSTEM	\$13.98	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$152.47	
			Price FUEL	- Total				\$152.47	
	0120 -	Total	111001022	Total				\$0.00	
			011 11	4045		1.1.10			
	0130	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Other Item Adjustment	ACAD	4	Jul 16, 2025	brophm1	\$493.31	Contractor selected AC adjustment on contract.
		, ,			7	Sep 2, 2025	brophm1	\$24.60	Refer to the document called, "250117-H03 J9P3842 Estimate 0007 AC Index Price Adjustment Hot Mix Asphalt Ton" on eProjects for further information.
				ACAD - Tota	al			\$517.91	
		Other It		Adjustment -	Total			\$517.91	
			Price FUEL		4	Jul 16, 2025	SYSTEM	\$405.45	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Sep 2, 2025	SYSTEM	\$26.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		Price FUEL - To		- Total				\$431.55	
				- Total				\$431.55	
	0130 -	Total						\$949.46	
	0140	MISC.	Other Item Adjustment	ACAD	4	Jul 16, 2025	brophm1	\$331.33	Contractor selected AC adjustment on contract.
				ACAD - Tota	al			\$331.33	
			Other Item	Adjustment -	Total			\$331.33	
	0140 -	Total						\$331.33	
	0150	MISC. BITUMINOUS	Other Item Adjustment	ACAD	4	Jul 16, 2025	brophm1	\$151.29	Contractor selected AC adjustment on contract.
		PAVEMENT (SURF. LEVEL)		ACAD - Tota	al			\$151.29	
			Other Item	Adjustment -	Total			\$151.29	
	0150 -	Total						\$151.29	
	0160	TACK COAT	Material		4	Jul 16, 2025	SYSTEM	(\$1,643.88)	
					4	Jul 16, 2025	SYSTEM	\$1,643.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	Estimate Exception 1 of the current 1 dyment Estimate.
			Material - T						
	0400	Tatal	Material - I	Otal				\$0.00	
	0160 -	CONCRETE	Material		6	Aug 18,	SYSTEM	\$0.00 (\$188,831.50)	
		PAVEMENT (9 IN. NON-REINF)			6	2025 Aug 18, 2025	SYSTEM	\$188,831.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment
					7	Sep 2,	SYSTEM	(\$377,178.50)	Estimate Exception 2 on the current Payment Estimate.
						2025	J. GILIVI	(\$0.1,110.00)	
					7	Sep 2, 2025	SYSTEM	\$377,178.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Sep 16, 2025	SYSTEM	(\$469,556.50)	
					8	Sep 16, 2025	SYSTEM	\$469,556.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment
									Estimate Exception 3 on the current Payment Estimate.



10 10 10 10 10 10 10 10	ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks	
NON-REINY Part	842	0170	CONCRETE					,	(\$733,252.75)		
Section Control Cont			PAVEMENT (9 IN.				2025				
Malecrial Total						9		SYSTEM	\$733,252.75	Estimate Item Adjustment (0003) due to user brophm1 overridding Payment	
1970 - Total					- Total				\$0.00		
MISC. MISC. Material 6				Material - To	otal				\$0.00		
Part		0180	MISC.	Material			2025		,		
						6		SYSTEM	\$69,274.80	Estimate Item Adjustment (0004) due to user brophm1 overridding Payment	
PAPED APPROACH, 8 IN. Material					- Total				\$0.00		
PAYED				Material - To	otal				\$0.00		
APPROACH, 8 IN.		0180 -	Total						\$0.00		
2025 Sep 2, 2025 SYSTEM \$50,364.30 Stitume (Exemption 7 on the current Payment Estimate (Exception 7 on the current Payment Estimate (Exception 7 on the current Payment Estimate (2007) due to user brophent overridding Payment (2007) due to user brophent (2007) due		0200		Material		6		SYSTEM	(\$5,220.00)		
2025 7 2025 7 2025 7 2025 7 2025 7 2025 7 2025 7 2025 7 2025 7 2025 7 2025 7 2025						6		SYSTEM	\$5,220.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment	
2025 SySTEM SS0,364.30 Estimate tem Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						7		SYSTEM	(\$50,364.30)		
2025 September September						7		SYSTEM	\$50,364.30	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment	
2025 System Estimate Item Adjustment (0004) due to user brophm1 overridding Payme Estimate Exception 5 on the current Payment Estimate.						8		SYSTEM	(\$50,364.30)		
2025 9						8		SYSTEM	\$50,364.30	Estimate Item Adjustment (0004) due to user brophm1 overridding Payment	
Substitute Sub						9		SYSTEM	(\$50,364.30)		
Material - Total So.00						9		SYSTEM	\$50,364.30	Estimate Item Adjustment (0004) due to user brophm1 overridding Payment	
Second Part					- Total				\$0.00		
MISC. CONCRETE				Material - To	otal				\$0.00		
2025 8 Sep 16, 2025 8 Sep 16, 2025 9 Oct 1, 2025 SYSTEM S346.50 Oct 1		0200 -	Total						\$0.00		
2025 Estimate Item Adjustment (0005) due to user brophn1 overridding Paymer Estimate Exception 10 on the current Payment Estimate.		0210	MISC. CONCRETE	Material		8		SYSTEM	(\$41,570.40)		
2025 9 Oct 1, 27STEM \$41,570.40 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 1 Total S0.00 80.00 0210 - Total CONCRETE GUTTER TYPE A Material 8 Sep 16, 2025 8 Sep 16, SYSTEM (\$346.50) 8 Sep 16, SYSTEM (\$346.50) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 9 Oct 1, 2025 9 Oct 1, SYSTEM (\$346.50) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 9 SYSTEM (\$346.50) This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.							8		SYSTEM	\$41,570.40	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment
Solution						9		SYSTEM	(\$41,570.40)		
Solution						9		SYSTEM	\$41,570.40	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment	
Solution					- Total				\$0.00		
O220 CONCRETE GUTTER TYPE A 8 Sep 16, 2025 8 Sep 16, 2025 1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 9 Oct 1, 2025 9 Oct 1, SYSTEM \$346.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				Material - To	otal				\$0.00		
System 2025 8 Sep 16, 2025 8 Sep 16, 2025 9 Oct 1, 2025 9 Oct 1, 2025 9 Oct 1, 2025 9 System 2025 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0210 -	Total						\$0.00		
2025 Estimate Item Adjustment (0006) due to user brophm1 overridding Paymer Estimate Exception 11 on the current Payment Estimate. 9 Oct 1, 2025 9 Oct 1, SYSTEM \$346.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Paymer Estimate Exception 11 on the current Payment Estimate.		0220		Material		8		SYSTEM	(\$346.50)		
9 Oct 1, 2025 SYSTEM \$346.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						8	Sep 16, 2025	SYSTEM	\$346.50	Estimate Item Adjustment (0006) due to user brophm1 overridding Payment	
2025 Estimate Item Adjustment (0006) due to user brophm1 overridding Paymer Estimate Exception 11 on the current Payment Estimate.						9		SYSTEM	(\$346.50)		
- Total \$0.00						9		SYSTEM	\$346.50	Estimate Item Adjustment (0006) due to user brophm1 overridding Payment	
40.00					- Total				\$0.00		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3842	0220	CONCRETE GUTTER TYPE A	Material - To	otal				\$0.00	
	0220 -	Total						\$0.00	
	0230	FURN. TYPE 2 ROCK DITCH LINER	Material		5	Aug 1, 2025	SYSTEM	(\$92.00)	
		LINER			5	Aug 1, 2025	SYSTEM	\$92.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brophm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Aug 18, 2025	SYSTEM	(\$92.00)	
					6	Aug 18, 2025	SYSTEM	\$92.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Sep 2, 2025	SYSTEM	(\$501.40)	
					7	Sep 2, 2025	SYSTEM	\$501.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0230 -	Total						\$0.00	
	0250	MISC. PAVED DRAINAGE	Material		6	Aug 18, 2025	SYSTEM	(\$3,465.80)	
					6	Aug 18, 2025	SYSTEM	\$3,465.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Sep 2, 2025	SYSTEM	(\$21,689.20)	
					7	Sep 2, 2025	SYSTEM	\$21,689.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Sep 16, 2025	SYSTEM	(\$31,660.90)	
					8	Sep 16, 2025	SYSTEM	\$31,660.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Oct 1, 2025	SYSTEM	(\$60,746.10)	
					9	Oct 1, 2025	SYSTEM	\$60,746.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0250	Total						\$0.00	
	0260	MISC. PAVED DRAINAGE	Material		6	Aug 18, 2025	SYSTEM	(\$7,545.00)	
					6	Aug 18, 2025	SYSTEM	\$7,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0260	Total						\$0.00	
	0280	CHANGEABLE MESSAGE SIGN	Material		2	Jun 16, 2025	SYSTEM	(\$12,800.00)	
		WITHOUT COMMUNICATION INTERFACE, CONTRACTOR			2	Jun 16, 2025	SYSTEM	\$12,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		FURNISHED / RETAINED		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0280	Total						\$0.00	
	0320	TEMPORARY TRAFFIC BARRIER HEIGHT	Material		4	Jul 16, 2025	SYSTEM	(\$2,388.00)	



Type Adjustment Type Date By			B 10	A 11	011		0 1 1	0		B	
2005 SCHRACTOR CPURSUED	ect L	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks	
S Aug 1,	342 0	320	CONTRACTOR FURNISHED /	Material		4		SYSTEM	\$2,388.00	Estimate Item Adjustment (0003) due to user brophm1 overridding Payment	
Section Content Cont			RETAINED			5		SYSTEM	(\$2,388.00)		
Material - Total						5		SYSTEM	\$2,388.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment	
1030 Total					- Total				\$0.00		
SEPARATION Material A				Material - To	otal				\$0.00		
REMOVABLE A	0	320 -	Total						\$0.00		
24 N.	0	390	REMOVABLE	Material		4		SYSTEM	(\$360.00)		
2025 5						4		SYSTEM	\$360.00	Estimate Item Adjustment (0004) due to user brophm1 overridding Payment	
Part						5		SYSTEM	(\$360.00)		
Part						5		SYSTEM	\$360.00	Estimate Item Adjustment (0006) due to user brophm1 overridding Payment	
Setamate Item Adjustment (0069) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate. Total						6		SYSTEM	(\$360.00)		
Material - Total Overrun 8 Sep 16 Sep 16 SYSTEM (\$240.00)						6		SYSTEM	\$360.00	Estimate Item Adjustment (0009) due to user brophm1 overridding Payment	
Overrun Overrun 8					- Total				\$0.00		
2025 (\$240.00)				Material - To	otal				\$0.00		
Value				Overrun	Overrun	8		SYSTEM	(\$240.00)		
					Overrun - T	otal			(\$240.00)		
Material				Overrun - T	otal						
ARTERBORNE PAVEMENT MARKING			4 IN. YELLOW MATERBORNE PAVEMENT								
Company	0)410		Material			2025		, , ,		
Material - Total S0.00			MARKING			4		SYSTEM		Estimate Item Adjustment (0005) due to user brophm1 overridding Payment	
Naterial - Total Sum Substitute Subs											
Material				Waterial - I otal							
5 Aug 1, 2025 SYSTEM \$60.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 6 Aug 18, 2025 (\$60.00) 6 Aug 18, 2025 SYSTEM \$60.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. 90.00 9470 - Total 90.00 9470 - Total 90.00 9480 SYSTEM \$0.00 95.00 95.00 96.00 97.00 98.00 98.00 99.00 9			SEPARATION	Material		5		SYSTEM			
6 Aug 18, 2025 SYSTEM (\$60.00) 6 Aug 18, 2025 SYSTEM \$60.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 0470 - Total \$0.00 0530 18 IN. GROUP A FLARED END SECT SYSTEM SYSTEM STANDON SECT SYSTEM STANDON STANDON This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.							5	Aug 1,	SYSTEM	\$60.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment
6 Aug 18, 2025 \$YSTEM \$60.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. **So.00** **Material - Total** **So.00** **Outing 18 IN. GROUP A FLARED END SECT** **Aug 1, 2025** **SySTEM \$1,300.00) **This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate. **SySTEM \$1,300.00** **SySTEM \$1,3						6		SYSTEM	(\$60.00)	Estimate Exception 6 of the current rayment Estimate.	
Naterial - Total \$0.00						6	Aug 18,	SYSTEM	\$60.00	Estimate Item Adjustment (0010) due to user brophm1 overridding Payment	
Material - Total \$0.00					- Total				\$ <u>0.00</u>		
Sect Material Sect Sec				Material - To	otal				\$0.00		
FLARED END SECT 2025 5 Aug 1, 2025 5 SYSTEM \$1,300.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate. 6 Aug 18, 2025 SYSTEM (\$1,300.00)	0	470 -	Total						\$0.00		
5 Aug 1, 2025 SYSTEM \$1,300.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	0	530	FLARED END	Material		5		SYSTEM	(\$1,300.00)		
2025			SECI			5		SYSTEM	\$1,300.00	Estimate Item Adjustment (0008) due to user brophm1 overridding Payment	
6 Aug 18, SYSTEM \$1,300.00 This adjustment offsets the original system-generated Material Payment						6		SYSTEM	(\$1,300.00)		
						6	Aug 18,	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Material Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9P3842	0530	18 IN. GROUP A FLARED END SECT	Material			2025			Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0530 -							\$0.00		
	0550	MULCHING	Material		7	Sep 2, 2025	SYSTEM	(\$1,000.00)		
					7	Sep 2, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					8	Sep 16, 2025	SYSTEM	(\$1,000.00)		
					8	Sep 16, 2025	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brophm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0550 -	Total						\$0.00		
	0560	SEEDING - COOL SEASON	Material		7	Sep 2, 2025	SYSTEM	(\$2,320.00)		
		GRASSES				7	Sep 2, 2025	SYSTEM	\$2,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
						8	Sep 16, 2025	SYSTEM	(\$2,320.00)	
					8	Sep 16, 2025	SYSTEM	\$2,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
					9	Oct 1, 2025	SYSTEM	(\$2,320.00)		
					9	Oct 1, 2025	SYSTEM	\$2,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
				- Total	tal					
			Material - To	otal				\$0.00		
	0560 -	60 - Total						\$0.00		
	0570	ROCK DITCH CHECK	Material		2	Jun 16, 2025	SYSTEM	(\$2,565.00)		
					2	Jun 16, 2025	SYSTEM	\$2,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - T					\$0.00		
			Overrun	Overrun	5	Aug 1, 2025	SYSTEM	(\$3,795.00)		
				Overrun - T	otal			(\$3,795.00)		
			Overrun - T	verrun - Total						
	0570 -	Total						(\$3,795.00)		
	0580	TEMPORARY SEEDING	Material		4	Jul 16, 2025	SYSTEM	(\$645.00)		
					4	Jul 16, 2025	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					5	Aug 1, 2025	SYSTEM	(\$645.00)		
					5	Aug 1, 2025	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					6	Aug 18, 2025	SYSTEM	(\$645.00)		
					6	Aug 18, 2025	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brophm1 overridding Payment	



0590	SEEDING - Total	Material - T Material - T	- Total otal	2			\$0.00 \$0.00	Estimate Exception 17 on the current Payment Estimate.
0590) - Total			2			\$0.00	
0590			otal	2				
0590		Material		2				
	SILT FENCE	Material		2			\$0.00	
0590					Jun 16, 2025	SYSTEM	(\$565.50)	
0590				2	Jun 16, 2025	SYSTEM	\$565.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
0590			- Total				\$0.00	
0590		Material - T	otal				\$0.00	
	- Total						\$0.00	
0700	ASSEMBLY	Other Item Adjustment	STMI	7	Sep 2, 2025	brophm1	\$3,822.00	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further informat
	(PERFORATED SQUARE STEEL		STMI - Tota	J			\$3,822.00	MoDOT have received the certifications.
	TUBE)							
		Other Item	Adjustment -	lotal			\$3,822.00	
0700	- Total						\$3,822.00	
0710	2 IN. PSST POST - 12 GA.	Other Item Adjustment	STMI	7	Sep 2, 2025	brophm1	\$3,095.10	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further informat MoDOT have received the certifications.
			STMI - Tota				\$3,095.10	
		Other Item	Adjustment -	Total			\$3,095.10	
0710	- Total						\$3,095.10	
0720	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	Other Item Adjustment	STMI	7	Sep 2, 2025	brophm1	\$1,737.40	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further informat MoDOT have received the certifications.
			STMI - Tota	ı			\$1,737.40	
		Other Item	Adjustment -	Total			\$1,737.40	
0720	- Total						\$1,737.40	
0730	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	Other Item Adjustment	STMI	7	Sep 2, 2025	brophm1	\$502.74	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further informat MoDOT have received the certifications.
			STMI - Tota				\$502.74	
		Other Item	Adjustment -	Total			\$502.74	
0730	- Total						\$502.74	
0740	2.5 IN. PSST POST - 12 GA.	Other Item Adjustment	STMI	7	Sep 2, 2025	brophm1	\$2,362.49	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information MoDOT have received the certifications.
			STMI - Tota	ıl			\$2,362.49	
		Other Item	Adjustment -	Total			\$2,362.49	
0740	- Total						\$2,362.49	
0750	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	RIVEN POST Other Item ICHOR FOR 2.5 Adjustment	STMI	7	Sep 2, 2025	brophm1	\$1,731.52	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further informated MoDOT have received the certifications.
			STMI - Tota	ıl			\$1,731.52	
		Other Item	Adjustment -	Total			\$1,731.52	
		50 - Total						
0750	- Total				Sep 2,	brophm1	\$1,731.52 \$2,754.00	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further informat
	D - Total SH-FLAT SHEET	Other Item Adjustment	STMI	7	2025			MoDOT have received the certifications.
			STMI - Tota				\$2,754.00	MoDOT have received the certifications.
		Adjustment		ıl			\$2,754.00 \$2,754.00	MoDOT have received the certifications.
0760		Adjustment	STMI - Tota	ıl			\$2,754.00	MoDOT have received the certifications.
0760 0760	SH-FLAT SHEET	Adjustment	STMI - Tota	ıl		brophm1		MoDOT have received the certifications. Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further informat MoDOT have received the certifications.





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3842	042 0770 ST-STRUCTURAL Other Item Adjustment - Total							\$2,440.00	
	0770 -	70 - Total							
	0780	SHF-FLAT SHEET FLUORESCENT	Other Item Adjustment	STMI	7	Sep 2, 2025	brophm1	\$862.40	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications.
				STMI - Total				\$862.40	
			Other Item	Adjustment -	Total			\$862.40	
	0780 -	- Total						\$862.40	
J9P3842 -	J9P3842 - Total								
Overall -	Total						\$16,704.73		

MoDOT

Contract Adjustments for Contract - 250117-H03

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 16 of 16