

Pay Estimate Created Date: October 16, 2025

Progress Estimate Number 12	Contract ID Prime Contra	250221 actor Clarkso	-C02 n Construction Company	Pay Period Start Pay Period End	October 1 October 1		Original Contract Amount Net Change Order Amount Current Contract Amount	\$9,062,329.70 \$562,899.23 \$9,625,228.93
Approval Date								By User
October 16, 2025			Generated and	Generated and Approved (and should be considered Draft) at the Project Office Level by				
October 16, 2025			Reviewed and Appr	oved (and should be cor	nsidered Dra	aft) at the	e Resident Engineer Level by	ilesb1
October 20, 2025				Reviewed and Approved	d at the Cen	tral Offic	ce Controllers Office Level by	ramses1
Original Completion Date Current			Completion Date	Date	Date % of Current Contract Amount Complete			
December 1, 2	2025	Dece	mber 1, 2025				37.88%	
	Co	ontract Informa	ational Dates				Milestones	
Date Description	Original Co	mpletion Date	Current Completion D	ate	No Milesto	ones Exi	st for Contract	
Acceptance Date								
Awarded Date	March 5, 202	25	March 5, 2025					
Letting Date	February 21,	2025	February 21, 2025					
Notice to Proceed Date	February 20,	2025	February 20, 2025					
Work Began Date	May 5, 2025		May 5, 2025					

Contract Total Pa	ay For Estimate No. 12			
		This Estimate	Previous	To Date
250221-C02				
	Total Posted Items Pay	\$480,376.10	\$3,165,349.85	\$3,645,725.95
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$3,165,349.85	\$3,645,725.95
Contract Total Pa	vable This Estimate:	\$480.376.10		

Items Paid This Estimate Period

Contract Adjustments This Estimate

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JKR0136	0030	2022010	REMOVAL OF IMPROVEMENTS	LS	\$360,000.000	0.100	\$36,000.00
	0060	2036000	COMPACTING EMBANKMENT	CUYD	\$1.000	80	\$80.00
	0800	2063000	CLASS 3 EXCAVATION	CUYD	\$15.000	61.700	\$925.50
	0110	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	100F	\$370.000	1.400	\$518.00
	0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$12.000	270	\$3,240.00
	0160	6083006	6 IN. CONCRETE MEDIAN STRIP	SQYD	\$123.000	73.600	\$9,052.80
	0430	7261015	15 IN. PIPE GROUP A	LF	\$57.000	92	\$5,244.00
	0490	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	EA	\$625.000	2	\$1,250.00
	0540	8025006	MULCHING	ACRE	\$2,000.000	1.160	\$2,320.00
	0550	8051000A	SEEDING - COOL SEASON GRASSES	ACRE	\$1,600.000	1.160	\$1,856.00
	0890	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$77.000	857	\$65,989.00
Project JKR01	I36 - Total						\$126,475.30
JKR0137	0990	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$11.000	4,077	\$44,847.00
	1420	9014003	CONDUIT, 3 IN. RIGID, PUSHED	LF	\$29.500	528	\$15,576.00
	1460	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	EA	\$2,800.000	1	\$2,800.00
	1560	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$78.000	2,795.900	\$218,080.20
	1580	5021340	TYPE A2 SHOULDER	SQYD	\$73.000	983.700	\$71,810.10
	5107	9019901		LS	\$787.500	1	\$787.50
Project JKR01	137 - Total						\$353,900.80
Overall - Tota							\$480,376.10

Revision 10/17/2025 Page 1 of 33



Pay Estimate Created Date: October 16, 2025

Progress
Estimate Number
12Contract ID
Prime Contractor250221-C02
Clarkson Construction CompanyPay Period Start
Pay Period EndOctober 1, 2025
October 15, 2025Original Contract Amount
Net Change Order Amount
Current Contract Amount\$9,062,329.70
\$562,899.23

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
KR0136	0110	SUBGRADE COMPACTION (6-INCH DEPTH)	Material			-98.90000	\$370.00	(\$36,593.00)
	0110	SUBGRADE COMPACTION (6-INCH DEPTH)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.	98.90000	\$370.00	\$36,593.00
	0150	PIPE COLLAR, TYPE A	Material			-4	\$450.00	(\$1,800.00)
	0150 PIPE COLLAR, TYPE A Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.		4	\$450.00	\$1,800.00			
	0160	6 IN. CONCRETE MEDIAN STRIP	Material			-73.60000	\$123.00	(\$9,052.80)
	0160	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.	73.60000	\$123.00	\$9,052.80
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-78	\$21.00	(\$1,638.00)
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.	78	\$21.00	\$1,638.00
	0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-10	\$300.00	(\$3,000.00)
	0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.	10	\$300.00	\$3,000.00
	0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material			-5	\$50.00	(\$250.00)
	0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.	5	\$50.00	\$250.00
	0430	15 IN. PIPE GROUP A	Material			-92	\$57.00	(\$5,244.00)
	0430	15 IN. PIPE GROUP A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.	92	\$57.00	\$5,244.00
	0440	18 IN. PIPE GROUP A	Material			-320	\$62.00	(\$19,840.00)
	0440	18 IN. PIPE GROUP A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.	320	\$62.00	\$19,840.00

Revision 10/17/2025 Page 2 of 33



Pay Estimate Created Date: October 16, 2025

Estimat	gress e Numl 12	Contract ID ber Prime Contractor	250221-C02 Clarkson Constru	iction Compai	Pay Period Start ny Pay Period End	October 1, 2025 October 15, 2025	Original Contract Net Change Orde Current Contract	er Amount	\$9,062,329.70 \$562,899.23 \$9,625,228.93
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Commer	nts	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JKR0136	0450	24 IN. PIPE GROUP A	Material				-11	\$67.00	(\$737.00)
	0450	24 IN. PIPE GROUP A	Material		This adjustment offsets the generated Material Payme Adjustment (0021) due to o overridding Payment Estim on the current Payment Es	nt Estimate Item user hargrr nate Exception 16	11	\$67.00	\$737.00
	0460	30 IN. PIPE GROUP A	Material				-13	\$96.00	(\$1,248.00)
	0460	30 IN. PIPE GROUP A	Material		This adjustment offsets the generated Material Payme Adjustment (0022) due to overridding Payment Estim on the current Payment Es	nt Estimate Item user hargrr nate Exception 18	13	\$96.00	\$1,248.00
	0470	36 IN. PIPE GROUP A	Material				-39	\$126.00	(\$4,914.00)
	0470	36 IN. PIPE GROUP A	Material		This adjustment offsets the generated Material Payme Adjustment (0023) due to overridding Payment Estimon the current Payment Es	nt Estimate Item user hargrr nate Exception 20	39	\$126.00	\$4,914.00
	0480	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material				-9.10000	\$1,459.00	(\$13,276.90)
	0480	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		This adjustment offsets the generated Material Payme Adjustment (0024) due to overridding Payment Estimon the current Payment Es	nt Estimate Item user hargrr nate Exception 21	9.10000	\$1,459.00	\$13,276.90
	0490	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material				-2	\$625.00	(\$1,250.00)
	0490	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the generated Material Payme Adjustment (0025) due to u overridding Payment Estim on the current Payment Es	nt Estimate Item user hargrr nate Exception 22	2	\$625.00	\$1,250.00
	0500	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material				-7	\$675.00	(\$4,725.00)
	0500	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the generated Material Payme Adjustment (0026) due to overridding Payment Estim on the current Payment Es	nt Estimate Item user hargrr nate Exception 24	7	\$675.00	\$4,725.00
	0510	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material				-1	\$800.00	(\$800.00)
	0510	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the generated Material Payme Adjustment (0027) due to overridding Payment Estim on the current Payment Es	nt Estimate Item user hargrr nate Exception 25	1	\$800.00	\$800.00
	0520	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material				-1	\$1,100.00	(\$1,100.00)
	0520	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the generated Material Payme Adjustment (0028) due to overridding Payment Estimon the current Payment Es	nt Estimate Item user hargrr nate Exception 27	1	\$1,100.00	\$1,100.00
	0530	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material				-1	\$1,500.00	(\$1,500.00)
	0530	36 IN. OR ALLOWED SUBSTITUTE GROUP A	Material		This adjustment offsets the generated Material Payme		1	\$1,500.00	\$1,500.00

Revision 10/17/2025 Page 3 of 33



Pay Estimate Created Date: October 16, 2025

Estimate	gress e Numl 12		250221-C02 Clarkson Constru	iction Compa	ny Pay Period End October 15, 2025	Original Contrac Net Change Ordo Current Contrac	er Amount	\$9,062,329.70 \$562,899.23 \$9,625,228.93
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JKR0136		FLARED END SECTION			Adjustment (0029) due to user hargrr overridding Payment Estimate Exception 29 on the current Payment Estimate.			
	0540	MULCHING	Material			-1.16000	\$2,000.00	(\$2,320.00)
	0540	MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Payment Estimate Exception 30 on the current Payment Estimate.	1.16000	\$2,000.00	\$2,320.00
	0550	SEEDING - COOL SEASOI GRASSES	N Material			-1.16000	\$1,600.00	(\$1,856.00)
	0550	SEEDING - COOL SEASOI GRASSES	N Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user hargrr overridding Payment Estimate Exception 31 on the current Payment Estimate.	1.16000	\$1,600.00	\$1,856.00
	0760	2 IN. PSST POST - 12 GA.	Material			-300	\$13.00	(\$3,900.00)
	0760	2 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user hargrr overridding Payment Estimate Exception 35 on the current Payment Estimate.	300	\$13.00	\$3,900.00
	0780	2.5 IN. PSST POST - 12 G/	A. Material			-75	\$21.00	(\$1,575.00)
	0780	2.5 IN. PSST POST - 12 G	A. Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user hargrr overridding Payment Estimate Exception 36 on the current Payment Estimate.	75	\$21.00	\$1,575.00
	0800	SH-FLAT SHEET	Material			-244.32000	\$12.50	(\$3,054.00)
	0800	SH-FLAT SHEET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user hargrr overridding Payment Estimate Exception 37 on the current Payment Estimate.	244.32000	\$12.50	\$3,054.00
	0810	SHF-FLAT SHEET FLUORESCENT	Material			-9	\$68.00	(\$612.00)
	0810	SHF-FLAT SHEET FLUORESCENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user hargrr overridding Payment Estimate Exception 38 on the current Payment Estimate.	9	\$68.00	\$612.00
	0890	CONCRETE PAVEMENT (IN. NON-REINFORCED, 15 FT. JOINTS)				-15,311.30000	\$77.00	(\$1,178,970.10)
	0890	CONCRETE PAVEMENT (IN. NON-REINFORCED, 18 FT. JOINTS)			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.	15,311.30000	\$77.00	\$1,178,970.10
JKR0137	0940	COMPACTING EMBANKMENT	Material			-2,046	\$0.01	(\$20.46)
	0940	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,046	\$0.01	\$20.46
	0990	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	R Material			-11,352	\$11.00	(\$124,872.00)
	0990	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	R Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 3 on	11,352	\$11.00	\$124,872.00

Revision 10/17/2025 Page 4 of 33



Pay Estimate Created Date: October 16, 2025

Estimat	gress e Numl 12		250221-C02 Clarkson Constru	ction Compa	Pay Period Start Pay Period End		Original Contrac Net Change Orde Current Contract	er Amount	\$9,062,329.7 \$562,899.2 \$9,625,228.9
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comm	ents	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
KR0137					the current Payment Esti	mate.			
	1000	PIPE COLLAR, TYPE A	Material				-1	\$450.00	(\$450.00
	1000	PIPE COLLAR, TYPE A	Material		This adjustment offsets the generated Material Paymr Adjustment (0004) due to overridding Payment Estithe current Payment Esti	ent Estimate Item ouser hargrr mate Exception 7 on	1	\$450.00	\$450.00
	1200	18 IN. PIPE GROUP A	Material				-384	\$62.00	(\$23,808.00
	1200	18 IN. PIPE GROUP A	Material		This adjustment offsets to generated Material Paym Adjustment (0005) due to overridding Payment Est on the current Payment E	ent Estimate Item o user hargrr mate Exception 14	384	\$62.00	\$23,808.00
	1210	30 IN. PIPE GROUP A	Material				-15	\$96.00	(\$1,440.00)
	1210	30 IN. PIPE GROUP A	Material		This adjustment offsets the generated Material Paym Adjustment (0006) due to overridding Payment Est on the current Payment E	ent Estimate Item ouser hargrr mate Exception 17	15	\$96.00	\$1,440.00
	1220	36 IN. PIPE GROUP A	Material				-14	\$126.00	(\$1,764.00)
	1220							\$126.00	\$1,764.00
	1230	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION			-3	\$675.00	(\$2,025.00)		
	1230	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the generated Material Paym Adjustment (0007) due to overridding Payment Est on the current Payment E	ent Estimate Item o user hargrr mate Exception 23	3	\$675.00	\$2,025.00
	1240	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material				-1	\$1,100.00	(\$1,100.00)
	1240	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the generated Material Paym Adjustment (0008) due to overridding Payment Est on the current Payment E	ent Estimate Item user hargrr mate Exception 26	1	\$1,100.00	\$1,100.00
	1250	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material				-1	\$1,500.00	(\$1,500.00)
	1250	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the generated Material Paym Adjustment (0009) due to overridding Payment Est on the current Payment E	ent Estimate Item o user hargrr mate Exception 28	1	\$1,500.00	\$1,500.00
	1420	CONDUIT, 3 IN. RIGID, PUSHED	Material			-528	\$29.50	(\$15,576.00)	
	1420	CONDUIT, 3 IN. RIGID, PUSHED	Material		This adjustment offsets to generated Material Paym Adjustment (0010) due to overridding Payment Est on the current Payment E	528	\$29.50	\$15,576.00	
	1460	POLE FOUNDATION (45 F OR 13.5 M MOUNTING HEIGHT)	T. Material				-1	\$2,800.00	(\$2,800.00)
	1460	POLE FOUNDATION (45 F OR 13.5 M MOUNTING HEIGHT)	T. Material		This adjustment offsets to generated Material Paym Adjustment (0011) due to	ent Estimate Item	1	\$2,800.00	\$2,800.00

Revision 10/17/2025 Page 5 of 33



Pay Estimate Created Date: October 16, 2025

Estimate	gress e Numl 12	Contract ID prime Contractor	250221-C02 Clarkson Constru	ıction Compa	Pay Period Start ny Pay Period End	October 1, 2025 October 15, 2025	Original Contract Net Change Ord Current Contract	er Amount	\$9,062,329.70 \$562,899.23 \$9,625,228.93
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comme	ents	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JKR0137					overridding Payment Esti on the current Payment E				
	1560	CONCRETE PAVEMENT IN. NON-REINFORCED, 1 FT. JOINTS)					-4,295.90000	\$78.00	(\$335,080.20)
	1560	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 4 of the current Payment Estimate.				ent Estimate Item ouser hargrr mate Exception 4 or	4,295.90000	\$78.00	\$335,080.20
	5107	MISC.	Material				-1	\$787.50	(\$787.50)
	5107	MISC.	Material		This adjustment offsets the generated Material Paym Adjustment (0037) due to overridding Payment Estion the current Payment E	ent Estimate Item user hargrr mate Exception 34	1	\$787.50	\$787.50
Total									\$0.00

Revision 10/17/2025 Page 6 of 33



					Co	ontract Project Informat	tion			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
JKR0136	FAF-50-2 (70)	Intersection improvements and add J-Turns	50	JOHNSON	0.7 mile east of Rte. 5	.7 mile east of Rte. 58 and 0.2 mile east of Northwest 121st Road				
JKR0137	KR0137 FAF-50-2 Intersection 50 JOHNSON West Intersection of Bus 50 and Rte 50									
Totals b	y Job Nu	ımbers								
JKR0136	Incenti Disince Liquida	entive ated Damages	Gross I	tem Pay	This Estimate \$126,475.30 \$0.00 \$126,475.30 \$0.00 \$0.00 \$0.00 \$0.00	Previous \$2,670,211.23 \$0.00 \$2,670,211.23 \$0.00 \$0.00 \$0.00 \$0.00	To Date \$2,796,686.53 \$0.00 \$2,796,686.53 \$0.00 \$0.00 \$0.00 \$0.00			
JKR0137	Other Contract Adjustments Posted Item Pay Gross Item Adjustments Gross Item Pay				This Estimate \$353,900.80 \$0.00 \$353,900.80	Previous \$495,138.62 \$0.00 \$495,138.62	To Date \$849,039.42 \$0.00 \$849,039.42			
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 5/29/2025 Page 7 of 33



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate 1 enough	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 2036000, Project Item Line Number 0940, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 2101006A, Project Item Line Number 0110, Material Set 2101006A96, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 3040506, Project Item Line Number 0990, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 5021308, Project Item Line Number 1560, Material Set 502130896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 5021308, Project Item Line Number 0890, Material Set 502130896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 5021308, Project Item Line Number 0890, Material Set 502130896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 6044011, Project Item Line Number 1000, Material Set 604401196, Material 0604CPCR - Collar for Pipe Connection, Acceptance Action Generic 0604CPCR is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 6044011, Project Item Line Number 0150, Material Set 604401196, Material 0604CPCR - Collar for Pipe Connection, Acceptance Action Generic 0604CPCR is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 6083006, Project Item Line Number 0160, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Material has been tested and accepted, and information will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 6200015, Project Item Line Number 0310, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 6200021, Project Item Line Number 0320, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 6200042, Project Item Line Number 0330, Material Set 620004296, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7261015, Project Item Line Number 0430, Material Set 726101596, Material 1026CPRCC3.015 - Reinf Conc Culv Pipe Cl3 15" (375 mm), Acceptance Action Generic 1026CPRCC3.015 is insufficient.	District Materials will need to change this item from concrete to plastic.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 7261018, Project Item Line Number 1200, Material Set 726101896, Material 1026CPRCC3.018 - Reinf Conc Culv Pipe Cl3 18" (450 mm), Acceptance Action Generic 1026CPRCC3.018 is insufficient.	District Materials will need to change this item from concrete to plastic.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7261018, Project Item Line Number 0440, Material Set 726101896, Material 1026CPRCC3.018 - Reinf Conc Culv Pipe Cl3 18" (450 mm), Acceptance Action Generic 1026CPRCC3.018 is insufficient.	District Materials will need to change this item from concrete to plastic.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7261024, Project Item Line Number 0450, Material Set 726102496, Material 1026CPRCC3.024 - Reinf Conc Culv Pipe Cl3 24" (600 mm), Acceptance Action Generic 1026CPRCC3.024 is insufficient.	District Materials will need to change this item from concrete to plastic.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 7261030, Project Item Line Number 1210, Material Set 726103096, Material 1026CPRCC3.030 - Reinf Conc Culv Pipe Cl3 30" (750 mm), Acceptance Action Generic 1026CPRCC3.030 is insufficient.	District Materials will need to change this item from concrete to plastic.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7261030, Project Item Line Number 0460, Material Set 726103096, Material 1026CPRCC3.030 - Reinf Conc Culv Pipe Cl3 30" (750 mm), Acceptance Action Generic 1026CPRCC3.030 is insufficient.	District Materials will need to change this item from concrete to plastic.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 7261036, Project Item Line Number 1220, Material Set 726103696, Material 1026CPRCC3.036 - Reinf Conc Culv Pipe Cl3 36" (900 mm), Acceptance Action Generic 1026CPRCC3.036 is insufficient.	District Materials will need to change this item from concrete to plastic.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7261036, Project Item Line Number 0470, Material Set 726103696, Material 1026CPRCC3.036 - Reinf Conc Culv Pipe Cl3 36" (900 mm), Acceptance Action Generic 1026CPRCC3.036 is insufficient.	District Materials will need to change this item from concrete to plastic.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7311053, Project Item Line Number 0480, Material Set 731105396, Material 1033DIRCPK - Precast Conc Drop Inlet, Acceptance Action Generic 1033DIRCPK is insufficient.	District Materials will enter the information.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7320615A, Project Item Line Number 0490, Material Set 7320615A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	District Materials will need to change this item from concrete to metal.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 7320618A, Project Item Line Number 1230, Material Set 7320618A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	District Materials will need to change this item from concrete to metal.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7320618A, Project Item Line Number 0500, Material Set 7320618A96, Material 1032ESRCF - Conc End Section for Round Pipe,	District Materials will need to change this item from concrete to metal.	hargrr	Overridden

Revision 5/29/2025 Page 8 of 33



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 1032ESRCF is insufficient.			
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7320624A, Project Item Line Number 0510, Material Set 7320624A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	District Materials will need to change this item from concrete to metal.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 7320630A, Project Item Line Number 1240, Material Set 7320630A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	District Materials will need to change this item from concrete to metal.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7320630A, Project Item Line Number 0520, Material Set 7320630A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	District Materials will need to change this item from concrete to metal.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 7320636A, Project Item Line Number 1250, Material Set 7320636A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	District Materials will need to change this item from concrete to metal.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 7320636A, Project Item Line Number 0530, Material Set 7320636A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	District Materials will need to change this item from concrete to metal.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 8025006, Project Item Line Number 0540, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 8051000A, Project Item Line Number 0550, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 9014003, Project Item Line Number 1420, Material Set 901400396, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 9018245, Project Item Line Number 1460, Material Set 901824596, Material 0901LHPFSA - Foundation for Highway Lighting, Acceptance Action Generic 0901LHPFSA is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0137, Item 9019901, Project Item Line Number 5107, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 9031270A, Project Item Line Number 0760, Material Set 9031270A96, Material 0903HSTS - OBSOLETE (DO NOT USE for 2025 or later contracts) Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 9031280, Project Item Line Number 0780, Material Set 903128096, Material 0903HSTS - OBSOLETE (DO NOT USE for 2025 or later contracts) Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 9035004A, Project Item Line Number 0800, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Certifications will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0136, Item 9035069A, Project Item Line Number 0810, Material Set 9035069A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Certifications will be entered into the system.	hargrr	Overridden

Revision 5/29/2025 Page 9 of 33



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
250221-	JKR0136	0001	0010	1081000	SIGNET DBE REPORTING	1.00	0.00	1.00	LS	1.00	\$1,000.00	\$1,000.00
C02		0001	0020	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	2.00	\$3,600.00	\$7,200.00
		0001	0030	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.40	\$360,000.00	\$144,000.00
		0001	0040	2035000	UNCLASSIFIED EXCAVATION	23,117.00	0.00	23,117.00	CUYD	3,541.30	\$16.00	\$56,660.80
		0001	0050	2035500	EMBANKMENT IN PLACE	1,310.00	-1,310.00	0.00	CUYD	0.00	\$6.75	\$0.00
		0001	0060	2036000	COMPACTING EMBANKMENT	14,718.00	0.00	14,718.00	CUYD	4,223.20	\$1.00	\$4,223.20
		0001	0070	2037075	COMPACTING IN CUT	10.20	0.00	10.20	STA	0.00	\$1,400.00	\$0.00
		0001	0800	2063000	CLASS 3 EXCAVATION	1,537.00	-297.00	1,240.00	CUYD	456.60	\$15.00	\$6,849.00
		0001	0090	2063500	CULVERT CLEANOUT	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.00
		0001	0100	2071000	LINEAR GRADING CLASS 1	19.20	0.00	19.20	STA	0.00	\$1,125.00	\$0.00
		0001	0110	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	227.00	0.00	227.00	100F	98.90	\$370.00	\$36,593.00
		0001	0120	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	2,255.00	0.00	2,255.00	SQYD	0.00	\$9.00	\$0.00
		0001	0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	49,981.00	0.00	49,981.00	SQYD	20,066.20	\$12.00	\$240,794.40
		0001	0140	4019905	MISC.OPTIONAL PAVEMENT	2,254.70	0.00	2,254.70	SQYD	0.00	\$78.00	\$0.00
		0001	0150	6044011	PIPE COLLAR, TYPE A	9.00	-5.00	4.00	EA	4.00	\$450.00	\$1,800.00
		0001	0160	6083006	6 IN. CONCRETE MEDIAN STRIP	160.80	0.00	160.80	SQYD	73.60	\$123.00	\$9,052.80
		0001	0170	6097000	ROCK LINING	6.00	0.00	6.00	CUYD	0.00	\$230.00	\$0.00
		0001	0180	6143012	MANHOLE FRAME AND COVER, TYPE 2	1.00	-1.00	0.00	EA	0.00	\$2,400.00	\$0.00
		0001	0190	6161005	CONSTRUCTION SIGNS	1,520.00	0.00	1,520.00	SQFT	873.75	\$7.30	\$6,378.38
		0001	0200	6161008 6161025	ADVANCED WARNING RAIL SYSTEM	12.00 170.00	0.00	12.00	EA EA	8.00	\$61.00	\$488.00 \$4,207.50
		0001	0210	6161030	CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE	33.00	0.00	170.00 33.00	EA	170.00 22.00	\$24.75 \$190.00	\$4,180.00
		0001	0230	6161033	DIRECTION INDICATOR BARRICADE	28.00	0.00	28.00	EA	28.00	\$95.00	\$2,660.00
		0001	0240	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$4,000.00	\$8,000.00
		0001	0250	6161055	SEQUENTIAL FLASHING WARNING LIGHT	28.00	0.00	28.00	EA	28.00	\$107.00	\$2,996.00
		0001 0260 6161070	TUBULAR MARKER	216.00	0.00	216.00	EA	0.00	\$95.00	\$0.00		
		0004		6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	8.00	0.00	8.00	EA	8.00	\$5,600.00	\$44,800.00
		0001	0280	6181000	INTERFACE, CONTRACTOR FURNISHED / RETAINED MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$731,185.00	\$548,388.75
		0001	0290	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001 0300 6191000 0001 0310 6200015 0001 0320 6200021	PAVEMENT EDGE TREATMENT	23,922.00	0.00	23,922.00	LF	4,244.20	\$2.00	\$8,488.40		
					PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	220.00	0.00	220.00	LF	78.00	\$21.00	\$1,638.00
			PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	44.00	0.00	44.00	EA	10.00	\$300.00	\$3,000.00		
		0001	0330	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	48.00	0.00	48.00	EA	5.00	\$50.00	\$250.00
		0001	0340	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	9,409.00	0.00	9,409.00	LF	0.00	\$2.25	\$0.00
		0001	0350	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	18,072.00	0.00	18,072.00	LF	0.00	\$2.25	\$0.00
		0001	0360	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	14,277.00	0.00	14,277.00	LF	0.00	\$1.11	\$0.00
		0001	0370	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	16,373.00	0.00	16,373.00	LF	0.00	\$0.30	\$0.00
		0001	0380	6205906A	12 IN, WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6,573.00	0.00	6,573.00	LF	0.00	\$0.60	\$0.00
		0001	0390	6207001	PAVEMENT MARKING REMOVAL	1,764.00	0.00	1,764.00	LF	0.00	\$0.70	\$0.00
		0001	0400	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	1,764.00	0.00	1,764.00	LF	0.00	\$0.30	\$0.00
		0001	0410	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$90,000.00	\$45,000.00
		0001	0420	7250315A	15 IN. PIPE GROUP B	679.00	0.00	679.00	LF	0.00	\$57.00	\$0.00
		0001	0430	7261015	15 IN. PIPE GROUP A	231.00	-6.00	225.00	LF	92.00	\$57.00	\$5,244.00
		0001	0440	7261018	18 IN. PIPE GROUP A	1,290.00	-298.00	992.00	LF	320.00	\$62.00	\$19,840.00
		0001	0450	7261024	24 IN. PIPE GROUP A	14.00	0.00	14.00	LF	11.00	\$67.00	\$737.00
		0001	0460	7261030	30 IN. PIPE GROUP A	25.00	0.00	25.00	LF	13.00	\$96.00	\$1,248.00
		0001	0470	7261036	36 IN. PIPE GROUP A	109.00	0.00	109.00	LF	39.00	\$126.00	\$4,914.00
		0001	0480	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	51.00	0.00	51.00	FT	9.10	\$1,459.00	\$13,276.90
		0001	0490	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	6.00	0.00	6.00	EA	2.00	\$625.00	\$1,250.00
		0001	0500	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	19.00	0.00	19.00	EA	7.00	\$675.00	\$4,725.00
		0001	0510	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$800.00	\$800.00
		0001	0520	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,100.00	\$1,100.00

Page 10 of 33 Revision 5/29/2025



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total

Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
JKR0136	0001	0530	7320636A	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	3.00	0.00	3.00	EA	1.00	\$1,500.00	\$1,500.00
	0001	0540	8025006	MULCHING	11.00	0.00	11.00	ACRE	1.16	\$2,000.00	\$2,320.00
	0001	0550	8051000A	SEEDING - COOL SEASON GRASSES	11.00	0.00	11.00	ACRE	1.16	\$1,600.00	\$1,856.0
	0001	0560	8061004	SEDIMENT TRAP ROCK	15.00	0.00	15.00	CUYD	0.00	\$70.00	\$0.0
	0001	0570	8061005	ROCK DITCH CHECK	795.00	0.00	795.00	LF	269.00	\$14.00	\$3,766.0
	0001	0580	8061006	ALTERNATE DITCH CHECK	1,926.00	0.00	1,926.00	LF	340.00	\$10.00	\$3,400.0
	0001	0590	8061016	SEDIMENT REMOVAL	275.00	0.00	275.00	CUYD	0.00	\$28.00	\$0.0
	0001	0600	8061017	TEMPORARY SEEDING	2.80	0.00	2.80	ACRE	0.00	\$900.00	\$0.0
	0001	0610	8061019	SILT FENCE	8,495.00	0.00	8,495.00	LF	3,048.00	\$3.00	\$9,144.0
	0001	0620	8064135	TYPE 2A EROSION CONTROL BLANKET	53,010.00	0.00	53,010.00	SQYD	0.00	\$2.00	\$0.0
	0020	0630	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	14.00	0.00	14.00	EA	0.00	\$3,800.00	\$0.0
	0020	0640	9011115	BRACKET ARM, 15 FT. OR 4.6 M	14.00	0.00	14.00	EA	0.00	\$1,150.00	\$0.0
	0020	0650	9011312	LUMINAIRE, LED-B	14.00	0.00	14.00	EA	0.00	\$830.00	\$0.0
	0020	0660	9014004	CONDUIT, 4 IN. RIGID, PUSHED	1,660.00	0.00	1,660.00	LF	0.00	\$26.00	\$0.0
	0020	0670	9016110	PULL BOX, PREFORMED CLASS 1	25.00	0.00	25.00	EA	0.00	\$2,150.00	\$0.0
	0020	0680	9016111	PULL BOX, PREFORMED CLASS 2	5.00	0.00	5.00	EA	0.00	\$2,400.00	\$0.0
	0020										
	0020	0690	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	1,680.00 11,690.00	1,660.00	1,680.00 13,350.00	LF LF	0.00	\$1.90 \$8.00	\$0.0 \$0.0
	0020	0710	9018245	NEUTRAL, 8 AWG POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	14.00	0.00	14.00	EA	0.00	\$2,800.00	\$0.0
	0020	0720	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	3.00	0.00	3.00	EA	0.00	\$7,100.00	\$0.0
	0040	0730	9031010	CONCRETE FOOTINGS, EMBEDDED	5.70	0.00	5.70	CUYD	0.72	\$1,225.00	\$882.0
	0040	0740	9031210	STRUCTURAL STEEL POSTS	2,490.00	0.00	2,490.00	LB	0.00	\$14.50	\$0.0
	0040	0750	9031220	PIPE POSTS	2,800.00	133.00	2,933.00	LB	219.15	\$6.75	\$1,479.2
	0040	0760	9031270A	2 IN. PSST POST - 12 GA.	2,040.00	0.00	2,040.00	LF	300.00	\$13.00	\$3,900.0
	0040	0770	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	136.00	0.00	136.00	EA	10.00	\$105.00	\$1,050.0
	0040	0780	9031280	2.5 IN. PSST POST - 12 GA.	420.00	0.00	420.00	LF	75.00	\$21.00	\$1,575.0
	0040	0790		DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	28.00	0.00	28.00	EA			
	0040		9031281A						5.00	\$280.00	\$1,400.0
	0040	0800	9035004A	SH-FLAT SHEET	1,992.00	-49.00	1,943.00	SQFT	244.32	\$12.50	\$3,054.
	0052	0810 0830	9035069A 5021333	SHF-FLAT SHEET FLUORESCENT CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT.	27.00 3,692.80	0.00	27.00 3,692.80	SQFT	9.00	\$68.00 \$78.00	\$612.0 \$0.0
	0054	0860	5021340	JOINTS) TYPE A2 SHOULDER	1.005.70	0.00	1,025.70	SQYD	0.00	\$63.00	\$0.
	0054				1,025.70						
	0056	0870 0890	6262000A 5021308	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	16.90 35,497.50	0.00	16.90 35,497.50	SQYD	0.00 15,311.30	\$490.00 \$77.00	\$0.0 \$1,178,970.
	0058	0910	5021340	TYPE A2 SHOULDER	9,764.40	0.00	9,764.40	SQYD	4,474.90	\$66.00	\$295,343.4
	0001	5001	1094000	FORCE ACCOUNT	0.00	243,300.32	243,300.32	EA	44,651.64	\$1.00	\$44,651.0
	0020	5002	9015010	TRENCHING TYPE I	0.00	11,690.00	11,690.00	LF	0.00	\$8.92	\$0.0
	0020	5003	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	0.00	3.00	3.00	EA	0.00	\$11,529.00	\$0.0
	0001	5004	6143014	MANHOLE FRAME AND COVER, TYPE 4	0.00	6.00	6.00	EA	0.00	\$1,575.00	\$0.0
	0001	5005	6143010	MANHOLE FRAME AND COVER, TYPE 1-A	0.00	1.00	1.00	EA	0.00	\$1,575.00	\$0.0
	0001	5006	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	0.00	28.00	28.00	FT	0.00	\$682.50	\$0.0
	0001	5007	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	0.00	7.00	7.00	FT	0.00	\$1,590.75	\$0.0
	0001	5008	7310072	PRECAST CONCRETE MANHOLE - 72 IN.	0.00	10.00	10.00	FT	0.00	\$968.10	\$0.
	0040	5009		ST-STRUCTURAL	0.00	49.00	49.00	SQFT	0.00	\$22.15	\$0.
Project	KD0426 T			Date as of Report Generated Date	0.00	45.00	49.00	JQI I	0.00	ΨΖΖ.13	\$2,796,686.5
	0004				1.00	0.00	1.00	1.0	1.00	¢55,000,00	
JKR0137	0001	0920	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000.
	0001	0930	2035000	UNCLASSIFIED EXCAVATION	5,303.00	0.00	5,303.00	CUYD	2,407.00	\$15.00	\$36,105.
		0940	2036000	COMPACTING EMBANKMENT	3,800.00	0.00	3,800.00	CUYD	2,046.00	\$0.01	\$20.
	0001	0950	2037075	COMPACTING IN CUT	8.40	0.00	8.40	STA	0.00	\$1,000.00	\$0.
	0001	0960	2063000	CLASS 3 EXCAVATION	189.00	53.00	242.00	CUYD	232.00	\$15.00	\$3,480.0
	0001	0970	2063500	CULVERT CLEANOUT	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.
	0001	0980	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	47.00	0.00	47.00	100F	47.00	\$380.00	\$17,860.
	0001	0990	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	11,352.00	0.00	11,352.00	SQYD	11,352.00	\$11.00	\$124,872.0
	0001	1000	6044011	PIPE COLLAR, TYPE A	3.00	-2.00	1.00	EA	1.00	\$450.00	\$450.0
	0001	1010	6083006	6 IN. CONCRETE MEDIAN STRIP	517.00	0.00	517.00	SQYD	0.00	\$115.00	\$0.0
	0001	.0.0									
	0001	1020	6097000	ROCK LINING	2.00	0.00	2.00	CUYD	0.00	\$200.00	\$0.0

Page 11 of 33 Revision 5/29/2025



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	Note: Po					d on Report Generated date and can differ from the poste Description					enerated.	Unit Price	Total Value POSTED
Color	Contract	Project No.	Category	Line No.	Item Code	Description	Bid Quantity			Unit	Approved	Office Price	To Date (See report
100 100		JKR0137	0001	1040	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	5.00	\$46.00	\$230.00
1995 1996	C02		0001	1050	6161025	CHANNELIZER (TRIM-LINE)	44.00	0.00	44.00	EA	44.00	\$18.50	\$814.00
March Marc			0001	1060	6161030	TYPE 3 MOVEABLE BARRICADE	9.00	0.00	9.00	EA	9.00	\$170.00	\$1,530.00
			0001	1070	6161033	DIRECTION INDICATOR BARRICADE	28.00	0.00	28.00	EA	28.00	\$85.00	\$2,380.00
			0001	1080	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$3,100.00	\$6,200.00
March Marc			0001	1090	6161055	SEQUENTIAL FLASHING WARNING LIGHT	28.00	0.00	28.00	EA	28.00	\$80.00	\$2,240.00
			0001	1100	6161098A		6.00	0.00	6.00	EA	3.00	\$5,100.00	\$15,300.00
			0001	1110	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$25,000.00	\$25,000.00
Col. 110 Col. 110 Col. 120 Col			0001	1120	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.00
Marie Mari			0001	1130	6191000	PAVEMENT EDGE TREATMENT	4,996.00	0.00	4,996.00	LF	0.00	\$9.00	\$0.00
1996				1140	6200015		12.00	0.00	12.00	LF	0.00	\$20.50	\$0.00
1000				1150	6200021		4.00	0.00	4.00	EA	0.00	\$300.00	\$0.00
Mary				1160	6205902A		4,038.00	0.00	4,038.00	LF	0.00	\$1.11	\$0.00
MARKENS FRANT, TYPE; BEADS 100				1170	6205903A		2,624.00	0.00	2,624.00	LF	0.00	\$0.30	\$0.00
10071 1210 1251003 30 N. PRE CROUNE A 188.00 200.00 380.00 LF 380.00 582.00 523.086.00 10071 1210 7251003 30 N. PRE CROUNE A 147.00 2.00 150.00 LF 14.00 580.00 534.04.00 10071 1210 123003 30 N. PRE CROUNE A 14.00 0.00 14.00 LF 14.00 381.00 587				1180	6205906A		1,676.00	0.00	1,676.00	LF	0.00		\$0.00
March 1,000 1,00				1190	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$17,000.00	\$8,500.00
1001 1200 7201083 SIN PPE CROUP A 1400				1200	7261018	18 IN. PIPE GROUP A	188.00	205.00	393.00	LF	384.00	\$62.00	\$23,808.00
120 120				1210	7261030	30 IN. PIPE GROUP A	17.00	-2.00	15.00	LF	15.00	\$96.00	\$1,440.00
0.001 1240 232030A 201 NO ALLOWED SUBSTITUTE GROUP A FLARED END 1.00 0.00 1.00 EA 1.00 \$1,100.				1220	7261036	36 IN. PIPE GROUP A	14.00	0.00	14.00	LF	14.00	\$126.00	\$1,764.00
SECTION 1.00				1230	7320618A		3.00	0.00	3.00	EA	3.00	\$675.00	\$2,025.00
SECTION 1260 8025006 MULCHING 1.30 0.00 1.30 ACRE 0.00 \$1,800.00 \$50.00 \$0.00 \$0.00 \$1.00 \$1.00 \$1.00 \$0.00 \$1.00 \$0.00 \$1.00 \$1.00 \$1.00 \$0.00 \$1.00 \$1.00 \$0.00 \$1.00 \$1.00 \$0.00 \$1.00 \$1.00 \$1.00 \$1.00 \$0.00 \$1.00 \$0.00 \$1.00				1240	7320630A		1.00	0.00	1.00	EA	1.00	\$1,100.00	\$1,100.00
1200 1270 8051000A SEEDING-COOL SEASON GRASSES 1.30				1250	7320636A		1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.00
1260				1260	8025006	MULCHING	1.30	0.00	1.30	ACRE	0.00	\$1,800.00	\$0.00
1001 1290 8061005 ROCK DITCH CHECK 150.00 150.00 300.00 LF 178.00 \$14.00 \$2,482.00				1270	8051000A	SEEDING - COOL SEASON GRASSES	1.30	0.00	1.30		0.00	\$1,700.00	\$0.00
1001 1300 8051006 ALTERNATE DITCH CHECK 360.00 0.00 360.00 LF 43.00 \$10.00 \$439.00					8061004	SEDIMENT TRAP ROCK	2.00	0.00	2.00		0.00	\$60.00	\$0.00
1001 1310 80610072 CURB INLET CHECK 2.00 0.00 2.00 EA 0.00 \$220.00 0.00					8061005	ROCK DITCH CHECK	150.00	150.00	300.00		178.00	\$14.00	
1001 1320 8681015 SEMIMENT REMOVAL 868.00 0.00 86.00 CUYD 0.00 \$27.00 \$0.00				1300	8061006	ALTERNATE DITCH CHECK	360.00	0.00	360.00	LF	43.00	\$10.00	\$430.00
1,22				1310	8061007A	CURB INLET CHECK	2.00	0.00	2.00		0.00	\$220.00	
1340 8061019 SILT FENCE 1,328.00 0.00 1,328.00 LF 0.00 \$2.90 \$0.00				1320	8061016		68.00	0.00	68.00		0.00		
0001				1330	8061017	TEMPORARY SEEDING	0.30	0.00	0.30		0.00	\$11,000.00	\$0.00
0010 1380 6661060 MGS GUARDRAIL 550.00 0.00 550.00 LF 0.00 \$29.00 \$0.00				1340	8061019	SILT FENCE	1,328.00	0.00	1,328.00	LF	0.00	\$2.90	\$0.00
0010 1370 6661080 MGS END ANCHOR 1.00 0.00 1.00 EA 0.00 \$2,600.00 \$0,00				1350	8064135	TYPE 2A EROSION CONTROL BLANKET	6,292.00	0.00	6,292.00		0.00	\$2.00	\$0.00
0010 1380 6063014 TyPE A CRASHWORTHY END TERMINAL (MASH) 2.00 0.00 2.00 EA 0.00 \$3,750.00 \$0.00				1360	6061060	MGS GUARDRAIL	550.00	0.00	550.00	LF	0.00	\$29.00	\$0.00
1020 1390 9011082 LIGHTINS POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2 4.00 0.00 4.00 EA 0.00 \$3,750.00 \$0.00				1370	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$2,600.00	\$0.00
0020				1380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,750.00	\$0.00
0020				1390	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	4.00	0.00	4.00	EA	0.00	\$3,750.00	\$0.00
140 1420 9014003 CONDUIT, 3 IN. RIGID, PUSHED 348.00 180.00 528.00 LF 528.00 \$29.50 \$15,576.00			0020	1400	9011115	BRACKET ARM, 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	0.00	\$1,200.00	\$0.00
1420 9018103 CONDUIT, SIN, KIGHZ, FUSHED 388.00 180.00 328.00 12 328.00 328			0020	1410	9011312	LUMINAIRE, LED-B	4.00	0.00	4.00	EA	0.00	\$850.00	\$0.00
1440 9017110 CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET 480.00 0.00 480.00 LF 0.00 \$13.50 \$0.00				1420	9014003	CONDUIT, 3 IN. RIGID, PUSHED	348.00	180.00	528.00	LF	528.00	\$29.50	\$15,576.00
1450 9017407 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE 1,300.00 0.00 1,300.00 LF 0.00 \$9.00 \$0.00			0020	1430	9016110	PULL BOX, PREFORMED CLASS 1	1.00	0.00	1.00	EA	0.00	\$3,300.00	\$0.00
NEUTRAL, 8 AWG NEUT			0020	1440	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	480.00	0.00	480.00	LF	0.00	\$13.50	\$0.00
1470 9018612 POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, 1.00 0.00 1.00 EA 0.00 \$7,000.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1.00			0020	1450	9017407		1,300.00	0.00	1,300.00	LF	0.00	\$9.00	\$0.00
0040			0020	1460	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	1.00	\$2,800.00	\$2,800.00
0040			0020	1470	9018612		1.00	0.00	1.00	EA	0.00	\$7,000.00	\$0.00
0040 1500 9031220 PIPE POSTS 160.00 5.00 165.00 LB 0.00 \$13.00 \$0.00 0040 1510 9031270A 2 IN. PSST POST - 12 GA. 540.00 0.00 540.00 LF 0.00 \$18.00 \$0.00 0040 1520 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 36.00 0.00 36.00 EA 0.00 \$170.00 \$0.00 0040 1530 9035004A SH-FLAT SHEET 437.00 -66.00 371.00 SQFT 0.00 \$19.00 \$0.00 0040 1540 9035069A SHF-FLAT SHEET FLUORESCENT 18.00 0.00 18.00 SQFT 0.00 \$85.00 \$0.00 0051 1560 5021308 CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. 8,773.10 0.00 8,773.10 SQFD 4,295.90 \$78.00 \$335,080.20			0040	1480	9031010	CONCRETE FOOTINGS, EMBEDDED	0.70	0.00	0.70	CUYD	0.00	\$3,500.00	\$0.00
0040 1510 9031270A 2 IN. PSST POST - 12 GA. 540.00 0.00 540.00 LF 0.00 \$18.00 \$0.00 \$0.00 \$15.			0040	1490	9031210	STRUCTURAL STEEL POSTS	700.00	0.00	700.00	LB	0.00	\$7.50	\$0.00
0040 1520 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 36.00 0.00 36.00 EA 0.00 \$170.00 \$0.00 0040 1530 9035004A SH-FLAT SHEET 437.00 -66.00 371.00 SQFT 0.00 \$19.00 \$0.00 0040 1540 9035069A SHF-FLAT SHEET FLUORESCENT 18.00 0.00 18.00 SQFT 0.00 \$85.00 \$0.00 0051 1560 5021308 CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. 8,773.10 0.00 8,773.10 SQFD 4,295.90 \$78.00 \$335,080.20			0040	1500	9031220	PIPE POSTS	160.00	5.00	165.00	LB	0.00	\$13.00	\$0.00
0040 1530 9035004A SH-FLAT SHEET 437.00 -66.00 371.00 SQFT 0.00 \$19.00 \$0.00 0040 1540 9035069A SHF-FLAT SHEET FLUORESCENT 18.00 0.00 18.00 SQFT 0.00 \$85.00 \$0.00 0051 1560 5021308 CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. 8,773.10 0.00 8,773.10 SQFD 4,295.90 \$78.00 \$335,080.20			0040	1510	9031270A	2 IN. PSST POST - 12 GA.	540.00	0.00	540.00	LF	0.00	\$18.00	\$0.00
0040 1540 9035069A SHF-FLAT SHEET FLUORESCENT 18.00 0.00 18.00 SQFT 0.00 \$85.00 \$0.0			0040	1520	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	36.00	0.00	36.00	EA	0.00	\$170.00	\$0.00
0051 1560 5021308 CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. 8,773.10 0.00 8,773.10 SQYD 4,295.90 \$78.00 \$335,080.20			0040	1530	9035004A	SH-FLAT SHEET	437.00	-66.00	371.00	SQFT	0.00	\$19.00	\$0.00
1000 0021000 CONCRETE FAVENIENT (6 IN. NON-KEINFORGED, 15 FT. 6,773.10 0.00 6,773.10 0.00 4,295.90 \$76.00 \$555,000.20			0040	1540	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$85.00	\$0.00
			0051	1560	5021308		8,773.10	0.00	8,773.10	SQYD	4,295.90	\$78.00	\$335,080.20

Revision 5/29/2025 Page 12 of 33



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
250221-	JKR0137	0053	1580	5021340	TYPE A2 SHOULDER	2,579.30	0.00	2,579.30	SQYD	1,746.70	\$73.00	\$127,509.10
C02		0001	5101	1094000	FORCE ACCOUNT	0.00	76,680.08	76,680.08	EA	7,470.16	\$1.00	\$7,470.16
		0020	5102	9015010	TRENCHING TYPE I	0.00	952.00	952.00	LF	0.00	\$9.97	\$0.00
		0020	5103	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	0.00	1.00	1.00	EA	0.00	\$11,529.00	\$0.00
		0040	5104	9035011A	ST-STRUCTURAL	0.00	66.00	66.00	SQFT	0.00	\$27.89	\$0.00
		0001	5105	7311032	PRECAST CONCRETE DROP INLET 3 FT X 2 FT	0.00	7.00	7.00	FT	7.00	\$1,459.00	\$10,213.00
		0001	5106	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	0.00	15.00	15.00	FT	8.00	\$1,515.00	\$12,120.00
		0020	5107	9019901		0.00	1.00	1.00	LS	1.00	\$787.50	\$787.50
	Project Jr	(R0137 - To	otal Value	Posted to D	Date as of Report Generated Date							\$849,039.42
250221-C02 Overall - Total Value Posted to Date as of Report Generated Date												\$3,645,725.95

Page 13 of 33 Revision 5/29/2025



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JKR0136

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2022010	REMOVAL OF IMPROVEMENTS	10/14/25	10/16/25	1	0.10	LS		993+00		1175+00		
0060	2036000	COMPACTING EMBANKMENT	10/14/25	10/16/25	1	80.00	CUYD		1164+14		1171+79		121 WB Decel Loon
0080	2063000	CLASS 3 EXCAVATION	10/14/25	10/16/25	1	61.70	CUYD		1126+11		1127+02		P-16
0110	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	10/14/25	10/16/25	1	1.40	100F		1164+14		1171+79		121 WB Decel Loon
0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	10/14/25	10/16/25	1	270.00	SQYD		1164+14		1171+79		121 WB Decel Loon.
0160	6083006	6 IN. CONCRETE MEDIAN STRIP	10/14/25	10/16/25	1	73.60	SQYD		1043+24		1097+17		Island at 361 and 251
0430	7261015	15 IN. PIPE GROUP A	10/14/25	10/16/25	1	92.00	LF		1126+11		1127+02		P-16
0490	7320615A	15 IN. GROUP A FLARED END SECT	10/14/25	10/16/25	1	2.00	EA		1126+11		1127+02		P-16
0540	8025006	MULCHING	10/14/25	10/16/25	1	1.16	ACRE		993+00		1175+00		1.45 was total AC. Paying 80% until established seed growth.
0550	8051000A	SEEDING - COOL SEASON GRASSES	10/14/25	10/16/25	1	1.16	ACRE		993+00		1175+00		1.45 was total AC. Paying 80% until established seed growth.
0890	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	10/14/25	10/16/25	1	857.00	SQYD		993+00		1175+00		Partial pours at 271 WB Decel, 191 WB Decel, 331 WB J- Turn

Project: JKR0137

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0990	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	10/14/25	10/16/25	1	4,077.00	SQYD		0+00		33+00		
1420	9014003	CONDUIT, 3 IN. RIGID, PUSHED	10/14/25	10/16/25	1	528.00	LF		0+00		33+00		
1460	9018245	POLE FOUNDATION (45 FT. OR 13.5 M	10/14/25	10/16/25	1	1.00	EA		6+00		6+00		Light Base in island for WB Accel
1560	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	10/14/25	10/16/25	1	2,795.90	SQYD		7+03		33+23		527.0 SY EB Decel 2268.9 SY EB Accel
1580	5021340	TYPE A2 SHOULDER	10/14/25	10/16/25	1	983.70	SQYD		7+03		33+23		167.0 SY EB Decel 816.7 SY EB Accel
5107	9019901	MISC. HIGHWAY LIGHTING	10/14/25	10/16/25	1	1.00	LS		6+50		6+50		Reconnect wiring to existing light pole at Bus. 50.

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 14 of 33



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0136	0110	SUBGRADE COMPACTION (6-	Material		9	Sep 2, 2025	SYSTEM	(\$36,075.00)	
		INCH DEPTH)			9	Sep 2, 2025	SYSTEM	\$36,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$36,075.00)	
					10	Sep 16, 2025	SYSTEM	\$36,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$36,075.00)	
					11	Oct 1, 2025	SYSTEM	\$36,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$36,593.00)	
					12	Oct 16, 2025	SYSTEM	\$36,593.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
	0110 -	Total	Material - To	otal				\$0.00	
		TYPE 5	Material		4	Jun 16,	SYSTEM	\$0.00 (\$75,652.80)	
		AGGREGATE FOR BASE (6 IN. THICK)			4	2025 Jun 16, 2025	SYSTEM	\$75,652.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$97,180.80)	Estimate Exception 1 on the sunoit 1 dynoit Estimate.
					5	Jul 1, 2025	SYSTEM	\$97,180.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$99,870.00)	
					6	Jul 16, 2025	SYSTEM	\$99,870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$99,870.00)	
					7	Aug 4, 2025	SYSTEM	\$99,870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Aug 18, 2025	SYSTEM	(\$99,870.00)	
					8	Aug 18, 2025	SYSTEM	\$99,870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$237,554.40)	
					9	Sep 2, 2025	SYSTEM	\$237,554.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0130 -		Market		0	A., 25	OVOTE	\$0.00	
	U150	PIPE COLLAR, TYPE A	Material		8	Aug 18, 2025	SYSTEM	(\$1,800.00)	
					8	Aug 18, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$1,800.00)	
					9	Sep 2, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0136	0150	PIPE COLLAR, TYPE A	Material	. 7/	10	Sep 16, 2025	SYSTEM	(\$1,800.00)	
					10	Sep 16, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$1,800.00)	
					11	Oct 1, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$1,800.00)	
					12	Oct 16, 2025	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150	Total	III atoriai	J. 1.				\$0.00	
	0160	6 IN. CONCRETE	Material		12	Oct 16,	SYSTEM	(\$9,052.80)	
	0100	MEDIAN STRIP	ivialeriai		12	2025	STSTEW	(\$9,032.60)	
					12	Oct 16, 2025	SYSTEM	\$9,052.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0160 -	Total						\$0.00	
	0190	CONSTRUCTION SIGNS	Material		2	May 16, 2025	SYSTEM	(\$6,378.38)	
					2	May 16, 2025	SYSTEM	\$6,378.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
	0200	ADVANCED WARNING RAIL SYSTEM	Material		2	May 16, 2025	SYSTEM	(\$488.00)	
		0.0.2			2	May 16, 2025	SYSTEM	\$488.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0200 -	Total						\$0.00	
	0210	CHANNELIZER (TRIM-LINE)	Material		2	May 16, 2025	SYSTEM	(\$4,207.50)	
					2	May 16, 2025	SYSTEM	\$4,207.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0210	Total						\$0.00	
	0220	TYPE 3 MOVEABLE	Material		2	May 16, 2025	SYSTEM	(\$4,180.00)	
					2	May 16, 2025	SYSTEM	\$4,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0220	Total						\$0.00	
	0230	DIRECTION INDICATOR	Material		2	May 16, 2025	SYSTEM	(\$2,660.00)	
		BARRICADE			2	May 16, 2025	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0136	0230	DIRECTION	Material						Estimate Exception 5 on the current Payment Estimate.
		INDICATOR BARRICADE		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0230 -							\$0.00	
	0240	FLASHING ARROW PANEL	Material		2	May 16, 2025	SYSTEM	(\$4,000.00)	
					2	May 16, 2025	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0240 -	Total						\$0.00	
	0250	FLASHING	Material		2	May 16, 2025	SYSTEM	(\$1,498.00)	
		WARNING LIGHT			2	May 16, 2025	SYSTEM	\$1,498.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Jun 2, 2025	SYSTEM	(\$2,996.00)	
					3	Jun 2, 2025	SYSTEM	\$2,996.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	MESSAI WITHOU COMMU INTERF. CONTR.	Total						\$0.00	
		CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Material		2	May 16, 2025	SYSTEM	(\$22,400.00)	
		COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /			2	May 16, 2025	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
		CONTRACTOR FURNISHED / RETAINED		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0300		Material		4	Jun 16, 2025	SYSTEM	(\$5,105.60)	
			IREAIMENI			4	Jun 16, 2025	SYSTEM	\$5,105.60
					5	Jul 1, 2025	SYSTEM	(\$8,488.40)	
					5	Jul 1, 2025	SYSTEM	\$8,488.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$8,488.40)	
					6	Jul 16, 2025	SYSTEM	\$8,488.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$8,488.40)	
					7	Aug 4, 2025	SYSTEM	\$8,488.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0300 -	Total						\$0.00	
	0310	PVMT MARK, 24	Material		10	Sep 16, 2025	SYSTEM	(\$1,638.00)	
		IN WHIT			10	Sep 16, 2025	SYSTEM	\$1,638.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Oct 1,	SYSTEM	(\$1,638.00)	



D		5	A 11	0.11		0 1 1	0 1 1		5 1
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0136	0310	PREF THERMO	Material			2025			
		PVMT MARK, 24 IN WHIT			11	Oct 1, 2025	SYSTEM	\$1,638.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$1,638.00)	
					12	Oct 16, 2025	SYSTEM	\$1,638.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0310	- Total						\$0.00	
		PREF THERMO PVMT MARK,	Material		7	Aug 4, 2025	SYSTEM	(\$900.00)	
		LT/RT ARROW			7	Aug 4, 2025	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Aug 18, 2025	SYSTEM	(\$900.00)	
					8	Aug 18, 2025	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$900.00)	
					9	Sep 2, 2025	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$3,000.00)	
					10	Sep 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$3,000.00)	
					11	Oct 1, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$3,000.00)	
					12	Oct 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0320	- Total						\$0.00	
	0330	PREF THERMO PVMT MARK, YIELD TRIAN	Material		10	Sep 16, 2025	SYSTEM	(\$250.00)	
		TILLD TRIAN			10	Sep 16, 2025	SYSTEM	\$250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$250.00)	
					11	Oct 1, 2025	SYSTEM	\$250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$250.00)	
					12	Oct 16, 2025	SYSTEM	\$250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0330	- Total						\$0.00	
	0430	15 IN. PIPE	Material		12	Oct 16,	SYSTEM	(\$5,244.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0136	0430	GROUP A	Material			2025			
					12	Oct 16, 2025	SYSTEM	\$5,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0430 -							\$0.00	
	0440	18 IN. PIPE GROUP A	Material		4	Jun 16, 2025	SYSTEM	(\$9,176.00)	
					4	Jun 16, 2025	SYSTEM	\$9,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jul 1, 2025	SYSTEM	(\$9,176.00)	
					5	Jul 1, 2025	SYSTEM	\$9,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$10,044.00)	
					6	Jul 16, 2025	SYSTEM	\$10,044.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$10,044.00)	
					7	Aug 4, 2025	SYSTEM	\$10,044.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Aug 18, 2025	SYSTEM	(\$15,500.00)	
					8	Aug 18, 2025	SYSTEM	\$15,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$19,840.00)	
					9	Sep 2, 2025	SYSTEM	\$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$19,840.00)	
					10	Sep 16, 2025	SYSTEM	\$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$19,840.00)	
					11	Oct 1, 2025	SYSTEM	\$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$19,840.00)	
					12	Oct 16, 2025	SYSTEM	\$19,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0440 -							\$0.00	
	0450	24 IN. PIPE GROUP A	Material		8	Aug 18, 2025	SYSTEM	(\$737.00)	
					8	Aug 18, 2025	SYSTEM	\$737.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$737.00)	
					9	Sep 2, 2025	SYSTEM	\$737.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
JKR0136	0450	24 IN. PIPE GROUP A	Material		10	Sep 16, 2025	SYSTEM	(\$737.00)				
					10	Sep 16, 2025	SYSTEM	\$737.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					11	Oct 1, 2025	SYSTEM	(\$737.00)				
					11	Oct 1, 2025	SYSTEM	\$737.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					12	Oct 16, 2025	SYSTEM	(\$737.00)				
					12	Oct 16, 2025	SYSTEM	\$737.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0450 -							\$0.00				
	0460	30 IN. PIPE GROUP A	Material		8	Aug 18, 2025	SYSTEM	(\$1,248.00)				
					8	Aug 18, 2025	SYSTEM	\$1,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.			
						9	Sep 2, 2025	SYSTEM	(\$1,248.00)			
						9	Sep 2, 2025	SYSTEM	\$1,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.		
					10	Sep 16, 2025	SYSTEM	(\$1,248.00)				
					10	Sep 16, 2025	SYSTEM	\$1,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					11	Oct 1, 2025	SYSTEM	(\$1,248.00)				
					11	Oct 1, 2025	SYSTEM	\$1,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.			
					12	Oct 16, 2025	SYSTEM	(\$1,248.00)				
					12	Oct 16, 2025	SYSTEM	\$1,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0460 -	Total 36 IN. PIPE	Material		8	Aug 18,	SYSTEM	\$0.00 (\$4,914.00)				
	0470	GROUP A	Waterial			2025		, , , ,				
					8	Aug 18, 2025	SYSTEM	\$4,914.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					9	Sep 2, 2025	SYSTEM	(\$4,914.00)				
			5				9	9	Sep 2, 2025	SYSTEM	\$4,914.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$4,914.00)				
					10	Sep 16, 2025	SYSTEM	\$4,914.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					11	Oct 1, 2025	SYSTEM	(\$4,914.00)				
					11	Oct 1, 2025	SYSTEM	\$4,914.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
JKR0136	0470	36 IN. PIPE GROUP A	Material		12	Oct 16, 2025	SYSTEM	(\$4,914.00)		
					12	Oct 16, 2025	SYSTEM	\$4,914.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0470 -	Total						\$0.00		
	0480	PRECAST CONCRETE DROP INLET 5 FT	Material		6	Jul 16, 2025	SYSTEM	(\$13,276.90)		
		X 3 FT			6	Jul 16, 2025	SYSTEM	\$13,276.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					7	Aug 4, 2025	SYSTEM	(\$13,276.90)		
					7	Aug 4, 2025	SYSTEM	\$13,276.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					8	Aug 18, 2025	SYSTEM	(\$13,276.90)		
					8	Aug 18, 2025	SYSTEM	\$13,276.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					9	Sep 2, 2025	SYSTEM	(\$13,276.90)		
						9	Sep 2, 2025	SYSTEM	\$13,276.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$13,276.90)		
					10	Sep 16, 2025	SYSTEM	\$13,276.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate.	
						11	Oct 1, 2025	SYSTEM	(\$13,276.90)	
						11	Oct 1, 2025	SYSTEM	\$13,276.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$13,276.90)		
					12	Oct 16, 2025	SYSTEM	\$13,276.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0480 -	Total						\$0.00		
	0490	15 IN. GROUP A FLARED END SECT	Material		12	Oct 16, 2025	SYSTEM	(\$1,250.00)		
		SECT			12	Oct 16, 2025	SYSTEM	\$1,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hargrr overridding Payment Estimate Exception 22 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
								\$0.00		
	0500	18 IN. GROUP A FLARED END SECT	Material		4	Jun 16, 2025	SYSTEM	(\$1,350.00)		
			4	4	4	Jun 16, 2025	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					5	Jul 1, 2025	SYSTEM	(\$1,350.00)		
					5	Jul 1, 2025	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.	



Material Total	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
SECT	KR0136	0500		Material	Туре	6		SYSTEM	(\$1,350.00)	
Part						6	Jul 16,	SYSTEM	\$1,350.00	Estimate Item Adjustment (0009) due to user hargrr overridding Payment
						7		SYSTEM	(\$1,350.00)	
2025 8 Aug 18, SYSTEM \$3.375.00 This adjustment offsets the original system-generated Material Payment Estimate Extraction (2013) due to user harger overriding Payment Estimate Extraction (2013) due to user harger overriding Payment Estimate (2014) due to user harger overriding Payment Estimate (2014) due to user harger overriding Payment (2014) due to user harger overriding Payment (2014) due to user harger overriding Payment (2015) due to user harger overriding Payment (2016) due to user harger over						7		SYSTEM	\$1,350.00	Estimate Item Adjustment (0010) due to user hargrr overridding Payment
2075 Sep 16, 2075 SYSTEM (\$4,725.00) Sep 16, 2075 SYSTEM (\$4,725.00) Sep 17, 2075 SYSTEM (\$4,725.00) Sep 18, 2075 SYSTEM						8		SYSTEM	(\$3,375.00)	
9 Sep 2 SYSTEM \$4,725.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (D014) Oue to use harger overridding Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment (D014) Oue to use harger overridding Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment (D015) Oue to use harger overridding Payment Estimate Item Adjustment (D015) Oue to user harger overridding Payment Estimate Item Adjustment (D015) Oue to user harger overridding Payment Estimate Item Adjustment (D015) Oue to user harger overridding Payment Estimate Item Adjustment (D015) Oue to user harger overridding Payment Estimate Item Adjustment (D015) Oue to user harger overridding Payment Estimate Item Adjustment (D015) Oue to user harger overridding Payment Estimate Exception 13 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 25 on the current Payment Estimate Item Adjustment (D025) due to user harger overridding Payment Estimate Exception 25 on the current Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment Offsets the original system-generated Material Payment Estimate Exception 25 on the current Payment Estimate Item Adjustmen						8		SYSTEM	\$3,375.00	Estimate Item Adjustment (0013) due to user hargrr overridding Payment
2025 SYSTEM SA-725.00 Sep 16, SYSTEM SA-725.00 Sep 16, SYSTEM SA-725.00 Sep 16, SYSTEM SA-725.00 Statute Section Section Sep 16, SYSTEM SA-725.00 Statute Section Sep 16, SYSTEM SA-725.00 SEP 17, SYSTEM SA-725.00 Sep 17, SYSTEM SA-725.00 Sep 18, SYSTEM SA-7						9		SYSTEM	(\$4,725.00)	,
10						9		SYSTEM	\$4,725.00	Estimate Item Adjustment (0014) due to user hargrr overridding Payment
2025 Estimate Item Adjustment (0018) due to user harger overridding Payment Estimate Exception 19 on the current Payment Estimate Item Adjustment (018) due to user harger overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user harger overridding Payment Estimate Item Adjustment (0027) due to user harger overridding Payment Estimate Exception 23 on the current Payment Estimate Item Adjustment (0027) due to user harger overridding Payment Estimate Item Adjustment (0028) due to user harger overridding Payment Estimate Exception 24 on the current Payment Estimate Exception 25 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 25 on the current Payment Es						10		SYSTEM	(\$4,725.00)	
11						10		SYSTEM	\$4,725.00	Estimate Item Adjustment (0018) due to user hargrr overridding Payment
2025 Estimate Item Adjustment (10021) due to user harger overridding Payment Estimate Item Adjustment (10021) due to user harger overridding Payment Estimate Exception 23 on the current Payment Estimate.						11		SYSTEM	(\$4,725.00)	
2025 12						11		SYSTEM	\$4,725.00	Estimate Item Adjustment (0021) due to user hargrr overridding Payment
Estimate Item Adjustment (0026) due to user harger overridding Payment Estimate. Source						12		SYSTEM	(\$4,725.00)	
Sound Soun						12		SYSTEM	\$4,725.00	Estimate Item Adjustment (0026) due to user hargrr overridding Payment
Solid Soli										
Second S		0500	Total	Material - To	otal					
SECT			24 IN. GROUP A	Material		8		SYSTEM		
2025			SECT			8	Aug 18,	SYSTEM	\$800.00	Estimate Item Adjustment (0014) due to user hargrr overridding Payment
2025 Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.						9		SYSTEM	(\$800.00)	
10						9		SYSTEM	\$800.00	Estimate Item Adjustment (0015) due to user hargrr overridding Payment
Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate. 11 Oct 1, 2025 SYSTEM (\$800.00) 11 Oct 1, 2025 SYSTEM \$800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 24 on the current Payment Estimate. 12 Oct 16, 2025 SYSTEM (\$800.00) 12 Oct 16, 2025 SYSTEM \$800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate. 1 Total \$0.00						10		SYSTEM	(\$800.00)	
2025 11 Oct 1, 2025 \$\frac{1}{2025}\$ \$\						10		SYSTEM	\$800.00	Estimate Item Adjustment (0019) due to user hargrr overridding Payment
Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 24 on the current Payment Estimate. 12 Oct 16, 2025 (\$800.00) 12 Oct 16, 2025 (\$800.00) 13 Oct 16, 2025 (\$800.00) 14 Oct 16, 2025 (\$800.00) 15 SYSTEM (\$800.00) 16 SYSTEM (\$800.00) 17 Inis adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate. 16 System (\$800.00) 17 Inis adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment Item Adjustment (0027) due to user hargrr overridding Payment I						11		SYSTEM	(\$800.00)	
2025 12 Oct 16, 2025 12 SYSTEM \$800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00						11		SYSTEM	\$800.00	Estimate Item Adjustment (0022) due to user hargrr overridding Payment
Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00						12		SYSTEM	(\$800.00)	
Material - Total \$0.00						12		SYSTEM	\$800.00	Estimate Item Adjustment (0027) due to user hargrr overridding Payment
					- Total				\$0.00	
0510 - Total \$0.00				Material - To	otal				\$0.00	
		0510	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0136	0520	30 IN. GROUP A FLARED END	Material		8	Aug 18, 2025	SYSTEM	(\$1,100.00)	
		SECT			8	Aug 18, 2025	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$1,100.00)	
					9	Sep 2, 2025	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$1,100.00)	
					10	Sep 16, 2025	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 22 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$1,100.00)	
					11	Oct 1, 2025	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hargrr overridding Payment Estimate Exception 26 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$1,100.00)	
					12	Oct 16, 2025	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hargrr overridding Payment Estimate Exception 27 on the current Payment Estimate.
				- Total				\$0.00	
	0500	T-4-I	Material - To	otal				\$0.00	
	0520 - 0530	36 IN. GROUP A	Material		8	Aug 18,	SYSTEM	\$0.00 (\$1,500.00)	
		FLARED END SECT			8	2025 Aug 18, 2025	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user harger overridding Payment
					9	Sep 2, 2025	SYSTEM	(\$1,500.00)	Estimate Exception 17 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$1,500.00)	
					10	Sep 16, 2025	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 23 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$1,500.00)	
					11	Oct 1, 2025	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hargrr overridding Payment Estimate Exception 28 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$1,500.00)	
					12	Oct 16, 2025	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hargrr overridding Payment Estimate Exception 29 on the current Payment Estimate.
				- Total				\$0.00	
	0520	Total	Material - To	otal				\$0.00	
	0530 - 0540	MULCHING	Material		12	Oct 16, 2025	SYSTEM	\$0.00 (\$2,320.00)	
					12	Oct 16, 2025	SYSTEM	\$2,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Payment Estimate Exception 30 on the current Payment Estimate.
				- Total				\$0.00	Estimate Exception 50 on the current Fayment Estimate.
			Material - To					\$0.00	
	0540 -	Total						\$0.00	
	0340 -	ı olai						φυ.υυ	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
JKR0136	0550	SEEDING - COOL SEASON	Material	,,,	12	Oct 16, 2025	SYSTEM	(\$1,856.00)															
		GRASSES			12	Oct 16, 2025	SYSTEM	\$1,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hargrr overridding Payment Estimate Exception 31 on the current Payment Estimate.														
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	0550 -	Total						\$0.00															
	0570	ROCK DITCH CHECK	Material		2	May 16, 2025	SYSTEM	(\$3,346.00)															
					2	May 16, 2025	SYSTEM	\$3,346.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					3	Jun 2, 2025	SYSTEM	(\$3,346.00)															
					3	Jun 2, 2025	SYSTEM	\$3,346.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.														
					4	Jun 16, 2025	SYSTEM	(\$3,346.00)															
					4	Jun 16, 2025	SYSTEM	\$3,346.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate.														
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	0570 -							\$0.00															
	0760	2 IN. PSST POST - 12 GA.	Material		7	Aug 4, 2025	SYSTEM	(\$3,900.00)															
					7	Aug 4, 2025	SYSTEM	\$3,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.														
					8	Aug 18, 2025	SYSTEM	(\$3,900.00)															
						8	Aug 18, 2025	SYSTEM	\$3,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.													
					9	Sep 2, 2025	SYSTEM	(\$3,900.00)															
					9	Sep 2, 2025	SYSTEM	\$3,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 19 on the current Payment Estimate.														
					10	Sep 16, 2025	SYSTEM	(\$3,900.00)															
					10	Sep 16, 2025	SYSTEM	\$3,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 24 on the current Payment Estimate.														
								11	Oct 1, 2025	SYSTEM	(\$3,900.00)												
																			11	Oct 1, 2025	SYSTEM	\$3,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hargrr overridding Payment Estimate Exception 29 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	\$3,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hargrr overridding Payment Estimate Exception 35 on the current Payment Estimate.														
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	0760 -				_		a=	\$0.00															
	0780	2.5 IN. PSST POST - 12 GA.	Material		7	Aug 4, 2025	SYSTEM	(\$1,575.00)															
					7	Aug 4, 2025	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.														



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
R0136	0780	2.5 IN. PSST POST - 12 GA.	Material		8	Aug 18, 2025	SYSTEM	(\$1,575.00)	
					8	Aug 18, 2025	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 19 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$1,575.00)	
					9	Sep 2, 2025	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$1,575.00)	
					10	Sep 16, 2025	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$1,575.00)	
					11	Oct 1, 2025	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hargrr overridding Payment Estimate Exception 30 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$1,575.00)	
					12	Oct 16, 2025	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hargrr overridding Payment Estimate Exception 36 on the current Payment Estimate.
				- Total				\$0.00	
	0700	T-4-1	Material - To	otal				\$0.00	
	0780 -	SH-FLAT SHEET	Material		7	Aug 4,	SYSTEM	\$0.00 (\$3,054.00)	
					7	2025 Aug 4,	SYSTEM	\$3,054.00	This adjustment offsets the original system-generated Material Payment
					,	2025	STOTEM	\$5,054.00	Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Aug 18, 2025	SYSTEM	(\$3,054.00)	
					8	Aug 18, 2025	SYSTEM	\$3,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$3,054.00)	
					9	Sep 2, 2025	SYSTEM	\$3,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$3,054.00)	
					10	Sep 16, 2025	SYSTEM	\$3,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hargrr overridding Payment Estimate Exception 26 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$3,054.00)	
					11	Oct 1, 2025	SYSTEM	\$3,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 31 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$3,054.00)	
					12	Oct 16, 2025	SYSTEM	\$3,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hargrr overridding Payment Estimate Exception 37 on the current Payment Estimate.
				- Total				\$0.00	
	0000	T-4-1	Material - To	otal				\$0.00	
	0800 -		Material		7	Aug 4	QVQTEM	\$0.00	
	0610	SHF-FLAT SHEET FLUORESCENT	Material		7	Aug 4, 2025	SYSTEM	(\$612.00)	
					7	Aug 4, 2025	SYSTEM	\$612.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0136	0810	SHF-FLAT SHEET FLUORESCENT	Material		8	Aug 18, 2025	SYSTEM	(\$612.00)	
					8	Aug 18, 2025	SYSTEM	\$612.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$612.00)	
					9	Sep 2, 2025	SYSTEM	\$612.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$612.00)	
					10	Sep 16, 2025	SYSTEM	\$612.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hargrr overridding Payment Estimate Exception 27 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$612.00)	
					11	Oct 1, 2025	SYSTEM	\$612.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hargrr overridding Payment Estimate Exception 32 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$612.00)	
					12	Oct 16, 2025	SYSTEM	\$612.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hargrr overridding Payment Estimate Exception 38 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		- Total CONCRETE	Material		5	Jul 1,	SYSTEM	\$0.00 (\$288,234.10)	
	0690	PAVEMENT (8 IN. NON-	iviateriai		5	2025 Jul 1,	SYSTEM	, , ,	This adjustment effects the original system generated Meterial Dayment
		REINFORCED,			5	2025	STSTEM	\$288,234.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$487,602.50)	
					6	Jul 16,	SYSTEM	\$487,602.50	This adjustment offsets the original system-generated Material Payment
						2025		ψ101,00 <u>2</u> .00	Estimate Item Adjustment (0010) dué to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7		SYSTEM	(\$487,602.50)	Estimate Item Adjustment (0010) due to user hargrr overridding Payment
					7	2025 Aug 4,			Estimate Item Adjustment (0010) due to user hargrr overridding Payment
						2025 Aug 4, 2025 Aug 4,	SYSTEM	(\$487,602.50)	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment
					7	2025 Aug 4, 2025 Aug 4, 2025	SYSTEM	(\$487,602.50) \$487,602.50	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment
					7	2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Aug 18,	SYSTEM SYSTEM SYSTEM	(\$487,602.50) \$487,602.50 (\$487,602.50)	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment
					7 8 8	2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$487,602.50) \$487,602.50 (\$487,602.50) \$487,602.50	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment
					7 8 8 9	2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$487,602.50) \$487,602.50 (\$487,602.50) \$487,602.50 (\$506,898.70)	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment
					7 8 8 9 9	2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$487,602.50) \$487,602.50 (\$487,602.50) \$487,602.50 (\$506,898.70) \$506,898.70	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment
					7 8 8 9 9	2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 16, 2025 Sep 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$487,602.50) \$487,602.50 (\$487,602.50) \$487,602.50 (\$506,898.70) \$506,898.70	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
					7 8 8 9 9 10	2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 16, 2025 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$487,602.50) \$487,602.50 (\$487,602.50) \$487,602.50 (\$506,898.70) \$506,898.70 (\$610,987.30) \$610,987.30	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
					7 8 8 9 9 10 10	2025 Aug 4, 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$487,602.50) \$487,602.50 (\$487,602.50) \$487,602.50 (\$506,898.70) \$506,898.70 (\$610,987.30) \$610,987.30	Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0136	0890	CONCRETE PAVEMENT (8 IN.	Material						Estimate Exception 5 on the current Payment Estimate.
		NON- REINFORCED,		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0890 -		Meterial		-	Int. 4	CVCTEM	\$0.00	
	0910	TYPE A2 SHOULDER	Material		5	Jul 1, 2025	SYSTEM	(\$71,583.60)	
					5	Jul 1, 2025	SYSTEM	\$71,583.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0910 -	Total						\$0.00	
JKR0136 -								\$0.00	
JKR0137	0940	COMPACTING EMBANKMENT	Material		5	Jul 1, 2025	SYSTEM	(\$2.65)	
					5	Jul 1, 2025	SYSTEM	\$2.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$2.65)	
					6	Jul 16, 2025	SYSTEM	\$2.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Aug 4, 2025	SYSTEM	(\$2.65)	
					7	Aug 4, 2025	SYSTEM	\$2.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Aug 18, 2025	SYSTEM	(\$2.65)	
					8	Aug 18, 2025	SYSTEM	\$2.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$9.29)	
					9	Sep 2, 2025	SYSTEM	\$9.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$9.29)	
					10	Sep 16, 2025	SYSTEM	\$9.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$20.46)	
					11	Oct 1, 2025	SYSTEM	\$20.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$20.46)	
					12	Oct 16, 2025	SYSTEM	\$20.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0940 -	Total						\$0.00	
	0990	TYPE 5 AGGREGATE	Material		5	Jul 1, 2025	SYSTEM	(\$29,639.50)	
		FOR BASE (6 IN. THICK)			5	Jul 1, 2025	SYSTEM	\$29,639.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jul 16, 2025	SYSTEM	(\$29,639.50)	
					6	Jul 16,	SYSTEM	\$29,639.50	This adjustment offsets the original system-generated Material Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0137	0990	TYPE 5 AGGREGATE	Material			2025			Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
		FOR BASE (6 IN. THICK)			7	Aug 4, 2025	SYSTEM	(\$29,639.50)	
					7	Aug 4, 2025	SYSTEM	\$29,639.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Aug 18, 2025	SYSTEM	(\$29,639.50)	
					8	Aug 18, 2025	SYSTEM	\$29,639.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$80,025.00)	
					9	Sep 2, 2025	SYSTEM	\$80,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$80,025.00)	
					10	Sep 16, 2025	SYSTEM	\$80,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$80,025.00)	
					11	Oct 1, 2025	SYSTEM	\$80,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$124,872.00)	
					12	Oct 16, 2025	SYSTEM	\$124,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
	0000	Tatal	Material - To	otal				\$0.00	
		- Total PIPE COLLAR,	Material - To	otal	11	Oct 1,	SYSTEM	\$0.00 \$0.00 (\$450.00)	
				otal	11	Oct 1, 2025 Oct 1, 2025	SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment
		PIPE COLLAR,		otal		2025 Oct 1, 2025 Oct 16,		\$0.00 (\$450.00)	
		PIPE COLLAR,		otal	11	2025 Oct 1, 2025	SYSTEM	\$0.00 (\$450.00) \$450.00	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment
		PIPE COLLAR,		- Total	11 12	2025 Oct 1, 2025 Oct 16, 2025 Oct 16,	SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00)	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		PIPE COLLAR,		- Total	11 12	2025 Oct 1, 2025 Oct 16, 2025 Oct 16,	SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00) \$450.00	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment
	1000	PIPE COLLAR,	Material	- Total	11 12	2025 Oct 1, 2025 Oct 16, 2025 Oct 16,	SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00) \$450.00	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment
	1000	PIPE COLLAR, TYPE A	Material	- Total	11 12	2025 Oct 1, 2025 Oct 16, 2025 Oct 16,	SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00) \$450.00 \$0.00	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment
	1000	PIPE COLLAR, TYPE A -Total 18 IN. PIPE	Material Material - To	- Total	11 12 12	2025 Oct 1, 2025 Oct 16, 2025 Oct 16, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00) \$450.00 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment
	1000	PIPE COLLAR, TYPE A -Total 18 IN. PIPE	Material Material - To	- Total	11 12 12	2025 Oct 1, 2025 Oct 16, 2025 Oct 16, 2025 Jul 1, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00) \$450.00 \$0.00 \$0.00 \$0.00 (\$10,478.00)	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment
	1000	PIPE COLLAR, TYPE A -Total 18 IN. PIPE	Material Material - To	- Total	11 12 12 5 5	2025 Oct 1, 2025 Oct 16, 2025 Oct 16, 2025 Jul 1, 2025 Jul 1, 2025 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00) \$450.00 \$0.00 \$0.00 \$10,478.00)	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment
	1000	PIPE COLLAR, TYPE A -Total 18 IN. PIPE	Material Material - To	- Total	11 12 12 12 5 5 6	2025 Oct 1, 2025 Oct 16, 2025 Oct 16, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00) \$450.00 \$0.00 \$0.00 (\$10,478.00) (\$10,478.00)	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment
	1000	PIPE COLLAR, TYPE A -Total 18 IN. PIPE	Material Material - To	- Total	11 12 12 12 5 5 5 6 6 6	2025 Oct 1, 2025 Oct 16, 2025 Oct 16, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$450.00) \$450.00 (\$450.00) \$450.00 \$0.00 \$0.00 \$10,478.00 (\$10,478.00) \$10,478.00	Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment



Project		Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	Line	Description	Type	Adjustment Type	Number	Date	By	Amount	Remains
JKR0137	1200	18 IN. PIPE GROUP A	Material		8	Aug 18, 2025	SYSTEM	\$10,478.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Sep 2, 2025	SYSTEM	(\$10,478.00)	
					9	Sep 2, 2025	SYSTEM	\$10,478.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Sep 16, 2025	SYSTEM	(\$10,478.00)	
					10	Sep 16, 2025	SYSTEM	\$10,478.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$23,808.00)	
					11	Oct 1, 2025	SYSTEM	\$23,808.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.
					12	Oct 16, 2025	SYSTEM	(\$23,808.00)	
					12	Oct 16, 2025	SYSTEM	\$23,808.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1200 -	- Total						\$0.00	
	1210	30 IN. PIPE GROUP A	Material		10	Sep 16, 2025	SYSTEM	(\$1,440.00)	
					10	Sep 16, 2025	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Oct 1, 2025	SYSTEM	(\$1,440.00)	
					4.4	Oct 1,	SYSTEM	04 440 00	TI: 11
					11	2025	STOTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.
					12		SYSTEM	(\$1,440.00)	Estimate Item Adjustment (0006) due to user hargrr overridding Payment
						2025 Oct 16,			Estimate Item Adjustment (0006) due to user hargrr overridding Payment
				- Total	12	2025 Oct 16, 2025 Oct 16,	SYSTEM	(\$1,440.00) \$1,440.00 \$0.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment
			Material - To		12	2025 Oct 16, 2025 Oct 16,	SYSTEM	(\$1,440.00) \$1,440.00 \$0.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment
		- Total			12	2025 Oct 16, 2025 Oct 16, 2025	SYSTEM SYSTEM	(\$1,440.00) \$1,440.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment
	1210 1220		Material - To		12 12 11	2025 Oct 16, 2025 Oct 16, 2025 Oct 11, 2025	SYSTEM SYSTEM	(\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$0.00 (\$1,764.00)	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment
		36 IN. PIPE			12	2025 Oct 16, 2025 Oct 16, 2025 Oct 16, 2025	SYSTEM SYSTEM	(\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$0.00 (\$1,764.00)	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment
		36 IN. PIPE			12 12 11	2025 Oct 16, 2025 Oct 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM SYSTEM	(\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$0.00 (\$1,764.00)	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment
		36 IN. PIPE		otal	12 12 11 11 11	2025 Oct 16, 2025 Oct 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$0.00 (\$1,764.00) \$1,764.00 \$1,764.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment
		36 IN. PIPE	Material	otal - Total	12 12 11 11 11	2025 Oct 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$1,764.00 (\$1,764.00) \$1,764.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment
	1220	36 IN. PIPE GROUP A		otal - Total	12 12 11 11 11	2025 Oct 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$1,764.00) \$1,764.00 \$1,764.00 \$1,764.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment
	1220	36 IN. PIPE GROUP A	Material Material - To	otal - Total	12 12 11 11 11 12 12	2025 Oct 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025 Oct 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$1,764.00 (\$1,764.00) \$1,764.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment
	1220	36 IN. PIPE GROUP A - Total 18 IN. GROUP A FLARED END	Material	otal - Total	12 12 11 11 11	2025 Oct 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$1,764.00) \$1,764.00 \$1,764.00 \$1,764.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment
	1220	36 IN. PIPE GROUP A - Total 18 IN. GROUP A	Material Material - To	otal - Total	12 12 11 11 11 12 12	2025 Oct 16, 2025 Oct 16, 2025 Oct 1, 2025 Oct 16, 2025 Oct 16, 2025 Oct 16, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,440.00) \$1,440.00 \$0.00 \$0.00 \$1,764.00 (\$1,764.00) \$1,764.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment



1230 18 N. GROUP A FLARED END SECT
Estimate Exception 11 on the current Payment Estimate.
7 Aug 4, 2025 7 Aug 4, 2025 8 SYSTEM \$1,350.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate. 8 Aug 18, SYSTEM (\$1,350.00) 2025 8 Aug 18, SYSTEM \$1,350.00 2025 9 Sep 2, SYSTEM (\$1,350.00) 9 Sep 2, SYSTEM \$1,350.00 10 Sep 16, SYSTEM (\$1,350.00) 2025 10 Sep 16, SYSTEM \$1,350.00 10 Sep 16, SYSTEM \$1,350.00 11 Oct 1, SYSTEM (\$2,025.00) 11 Oct 1, SYSTEM (\$2,025.00) 11 Oct 1, SYSTEM (\$2,025.00) 12 Oct 16, SYSTEM (\$2,025.00) 15 Oct 16, SYSTEM \$2,025.00 16 SYSTEM SYSTEM SANDER SYSTEM
Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate. 8 Aug 18, SYSTEM (\$1,350.00) 8 Aug 18, SYSTEM \$1,350.00 2025 9 Sep 2, SYSTEM (\$1,350.00) 9 Sep 2, SYSTEM (\$1,350.00) 9 Sep 2, SYSTEM \$1,350.00 10 Sep 16, SYSTEM (\$1,350.00) 10 Sep 16, SYSTEM \$1,350.00 10 Sep 16, SYSTEM \$1,350.00 10 Sep 16, SYSTEM \$1,350.00 11 Oct 1, SYSTEM \$1,350.00 11 Oct 1, SYSTEM (\$2,025.00) 12 Oct 16, SYSTEM \$2,025.00 13 Oct 16, SYSTEM \$2,025.00 14 Oct 16, SYSTEM \$2,025.00 15 SySTEM
8 Aug 18, 2025 8 Aug 18, 2025 9 Sep 2, 2025 9 Sep 2, 2025 10 Sep 16, 2025 10 Sep 16, 2025 11 Oct 1, 2025 11 Oct 1, 2025 11 Oct 1, 2025 12 Oct 18, 2025 12 Oct 18, 2025 12 Oct 18, 2025 12 Oct 18, 2025 13 SYSTEM \$2,025,00 15 SYSTEM \$2,025,00 16 Sep 16, 2025 17 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. 10 Sep 16, 2025 11 Oct 1, 2025 11 Oct 1, 2025 11 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. 10 Sep 16, 2025 11 Oct 1, 2025 11 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 12 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 12 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user harger overridding Payment Estimate Item Adjustment (0007) due to user harger overridding Payment Estimate Exception 22 on the current Payment Estimate. 12 Oct 16, 2025 13 SYSTEM \$2,025.00 14 Dot 16, 2025 15 SYSTEM \$2,025.00 16 SYSTEM \$2,025.00 17 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate.
Sep 2, 2025 SYSTEM (\$1,350.00)
9 Sep 2, 2025 \$1,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user harger overridding Payment Estimate Exception 14 on the current Payment Estimate. 10 Sep 16, 2025 \$1,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user harger overridding Payment Estimate Item Adjustment (0005) due to user harger overridding Payment Estimate Exception 18 on the current Payment Estimate. 11 Oct 1, 29STEM (\$2,025.00) \$2,025.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user harger overridding Payment Estimate Exception 22 on the current Payment Estimate. 12 Oct 16, 29STEM (\$2,025.00) \$2,025.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 12 Oct 16, 29STEM (\$2,025.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate Estimate Item Adjustment (0007) due to user harger overridding Payment Estimate Exception 23 on the current Payment Estimate.
Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate. 10 Sep 16, 2025 10 Sep 16, SYSTEM \$1,350.00 11 Oct 1, 2025 11 Oct 1, 2025 12 Oct 16, 2025 13 Oct 16, 2025 14 Oct 16, 2025 15 Oct 16, 2025 16 SYSTEM \$2,025.00 17 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 11 Oct 1, SYSTEM \$2,025.00 12 Oct 16, SYSTEM \$2,025.00 13 Oct 16, SYSTEM \$2,025.00 14 Oct 16, SYSTEM \$2,025.00 15 SYSTEM \$2,025.00 16 SYSTEM \$2,025.00 17 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate.
2025 10 Sep 16, 2025 \$1,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate. 11 Oct 1, 2025 \$1 SYSTEM \$2,025.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 22 on the current Payment Estimate. 12 Oct 16, SYSTEM \$2,025.00 This adjustment (0007) due to user hargrr overridding Payment Estimate Exception 22 on the current Payment Estimate. 12 Oct 16, SYSTEM \$2,025.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 23 on the current Payment Estimate.
2025 Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.
2025 11 Oct 1, 2025 \$\frac{1}{2025}\$ \$\
2025 Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 22 on the current Payment Estimate. 12 Oct 16, 2025 12 Oct 16, 2025 12 Oct 16, 2025 13 SYSTEM \$2,025.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 23 on the current Payment Estimate. - Total
2025 12 Oct 16, 2025 SYSTEM \$2,025.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 23 on the current Payment Estimate. - Total \$0.00
2025 Estimaté Item Adjustment (0007) dué to user hargrr overridding Payment Estimate Exception 23 on the current Payment Estimate. - Total \$0.00
Material - Total \$0.00
1230 - Total \$0.00
FLARED END 2025 SECT
2025 Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.
11 Oct 1, 2025 (\$1,100.00)
11 Oct 1, SYSTEM \$1,100.00 This adjustment offsets the original system-generated Material Payment 2025 This adjustment (0008) due to user hargrr overridding Payment
Estimate Exception 25 on the current Payment Estimate.
Estimate Exception 25 on the current Payment Estimate. 12 Oct 16, SYSTEM (\$1,100.00)
Estimate Exception 25 on the current Payment Estimate. 12 Oct 16, 2025 (\$1,100.00) 12 Oct 16, 2025 \$1,100.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 26 on the current Payment Estimate. - Total \$0.00
Estimate Exception 25 on the current Payment Estimate. 12
Estimate Exception 25 on the current Payment Estimate. 12
Estimate Exception 25 on the current Payment Estimate. 12
Estimate Exception 25 on the current Payment Estimate. 12 Oct 16, 2025 SYSTEM (\$1,100.00) 12 Oct 16, 2025 SYSTEM \$1,100.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 26 on the current Payment Estimate. 1240 - Total \$0.00 1240 - Total \$0.00 1250 36 IN. GROUP A FLARED END SECT Material
Estimate Exception 25 on the current Payment Estimate. 12
Estimate Exception 25 on the current Payment Estimate. 12 Oct 16, 2025



Total Support Suppor	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1290 RCOK DTCH Material	KR0137	1250	FLARED END	Material - T	otal				\$0.00		
A		1250	- Total						\$0.00		
Post		1290		Material		4		SYSTEM	(\$1,680.00)		
120 Total						4		SYSTEM	\$1,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.	
1200 - Total 1420 CONDUIT, 3 IN, RIGID, PUSHED 12									\$0.00		
1420 CONDUIT, 3 IN RIGID, PUSHED Material 12				Material - To	otal				\$0.00		
RIGID, PUSHED											
Solid Soli		1420		Material		12		SYSTEM	(\$15,576.00)		
120 - Total 1360 -						12		SYSTEM	\$15,576.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 32 on the current Payment Estimate.	
1420 - Total					- Total				\$0.00		
1460 POLE FUNDATION (45 FT. OR 13.5 M				Material - To	otal				\$0.00		
FOUNDATION (45 FT. OR 13.5 M		1420	- Total						\$0.00		
12		1460	FOUNDATION (45	Material		12		SYSTEM	(\$2,800.00)		
1460 - Total 1560 CONCRETE PAVEMENT (8 IN. NON. REINFORCED, 10 Sep 16, 2025 SYSTEM \$117,000.00 SYSTEM			11. OK 13.3 W			12		SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 33 on the current Payment Estimate.	
1460 - Total					- Total				\$0.00		
1560 CONCRETE PAVEMENT (8 IN. NON- REINFORCED, Material Pavement (907) due to user harger overridding Payment				Material - T	otal				\$0.00		
PAVEMENT (8 IN. NON- REINFORCED, 10 Sep 16, 2025 11 Oct 1, 2025 202											
2025 Estimate Item Adjustment (0007) due to user hargrr overridding Paymen Estimate Exception 4 on the current Payment Estimate. 11		1560	PAVEMENT (8 IN.	Material			2025				
2025 11			NON-			10		SYSTEM	\$117,000.00	Estimate Item Adjustment (0007) due to user hargrr overridding Payment	
2025 Estimate Item Adjustment (0010) due to user hargrr overridding Paymen Estimate Exception 4 on the current Payment Estimate.							11		SYSTEM	(\$117,000.00)	
2025 12 Oct 16, SYSTEM \$335,080.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user harger overridding Paymen Estimate Exception 4 on the current Payment Estimate. **O.00** **Material - Total** \$0.00** **Material - Total** \$0.00** **Total** \$0.00** **						11		SYSTEM	\$117,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate.	
2025 Estimate Item Adjustment (0012) due to user harger overridding Paymen Estimate Exception 4 on the current Payment Estimate. **Total*** **So.00*** **Material - Total** **So.00*** **Total*** **Total*** **So.00*** **Total*** **So.00*** **Total*** **So.00*** **Total*** **Total*** **So.00*** **Total*** **So.00*** **Total** **So.00*** **Total** **So.00** **Total** **So.00** **Total** **Total** **So.00** **Total** **Total** **So.00** **Total** **So.00** **Total** **Total** **So.00** **Total** **Total** **So.00** **Total** **Total** **So.00** **Total** **Total** **Total** **So.00** **Total** **Total** **Total** **Total** **So.00** **Total**						12		SYSTEM	(\$335,080.20)		
Material - Total \$0.00							12		SYSTEM	\$335,080.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate.
Solution					- Total				\$0.00		
5105 PRECAST CONCRETE DROP INLET 3 FT X 2 FT Material 11 Oct 1, 2025 SYSTEM (\$10,213.00) 11 Oct 1, 2025 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.				Material - T	otal				\$0.00		
CONCRETE DROP INLET 3 FT X 2 FT 11 Oct 1, 2025 11 Oct 1, 2025 SYSTEM \$10,213.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Paymen Estimate Exception 20 on the current Payment Estimate.		1560	- Total						\$0.00		
X 2 FT 11 Oct 1, 2025 SYSTEM \$10,213.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Paymen Estimate Exception 20 on the current Payment Estimate.		5105	CONCRETE	Material		11		SYSTEM	(\$10,213.00)		
- Total \$0.00						11		SYSTEM	\$10,213.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					- Total				\$0.00		
Material - Total \$0.00				Material - T	otal				\$0.00		
5105 - Total \$0.00											
5106 PRECAST CONCRETE Material 10 Sep 16, 2025 (\$12,120.00)		5106	CONCRETE	Material			2025				
10 Sep 16, SYSTEM \$12,120.00 This adjustment offsets the original system-generated Material Payment						10		SYSTEM	\$12,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.	
11 Oct 1, 2025 (\$12,120.00)						11		SYSTEM	(\$12,120.00)		
							2025				





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0137	5106	PRECAST CONCRETE	Material			2025			Estimate Item Adjustment (0031) due to user hargrr overridding Payment Estimate Exception 19 on the current Payment Estimate.
		MANHOLE - 60 IN.		- Total				\$0.00	
			Material - To	otal				\$0.00	
	5106 -	Total						\$0.00	
	5107	MISC. HIGHWAY LIGHTING	Material		12	Oct 16, 2025	SYSTEM	(\$787.50)	
					12	Oct 16, 2025	SYSTEM	\$787.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hargrr overridding Payment Estimate Exception 34 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5107 -	Total						\$0.00	
JKR0137	- Total							\$0.00	
Overall -	Total						\$0.00		

MoDOT

Contract Adjustments for Contract - 250221-C02

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 33 of 33