

Pay Estimate Created Date: November 3, 2025

| Progress Estimate Number 12 | Contract ID Prime Contract | 250314 or Emery | I-C01 Sapp & Sons, Inc. | Pay Period Start Pay Period End | October 16, 2 November 1, | | Original Contract Amount Net Change Order Amount Current Contract Amount | \$11,325,502.80 (\$247,740.69 \$11,077,762.1 | | |
|-----------------------------------|---|--------------------|--|--------------------------------------|------------------------------|---|--|--|--|--|
| Approval Date | | | | | | | | By User | | |
| November 3, 2025 | | | Generated an | raft) at the Project Office Level by | johnsm7 | | | | | |
| November 3, 2025 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Lev | | | | | | | ilesb1 | | |
| November 4, 2025 | Reviewed and Approved at the Central Office Controllers Office Leve | | | | | | | ramses1 | | |
| Original Completi | on Date | Current C | Completion Date Actual Completion Date | | | ate % of Current Contract Amount Comple | | | | |
| June 30, 202 | 26 | Jun | e 30, 2026 | October 2 | 4, 2025 | | 97.54% | | | |
| | Cont | tract Informa | ational Dates | | | | Milestones | | | |
| Date Description | Original Comp | oletion Date | Current Completion | Date | No Mile | stones | Exist for Contract | | | |
| Acceptance Date | | | | | | | | | | |
| Awarded Date | April 2, 2025 | | April 2, 2025 | | | | | | | |
| Letting Date | March 14, 2025 | 5 | March 14, 2025 | | | | | | | |
| Notice to Proceed Date | May 5, 2025 | | May 5, 2025 | | | | | | | |
| Work Began Date | June 10, 2025 | | June 10, 2025 | | | | | | | |

| Contract Total Pa | y For Estimate No. 12 | | | |
|-------------------|----------------------------|---------------|-----------------|-----------------|
| | | This Estimate | Previous | To Date |
| 250314-C01 | | | | |
| | Total Posted Items Pay | \$54,880.25 | \$10,750,342.82 | \$10,805,223.07 |
| | Gross Item Adjustments | \$0.00 | \$8,961.64 | \$8,961.64 |
| | Incentive | \$0.00 | \$0.00 | \$0.00 |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 |
| | Other Contract Adjustments | \$0.00 | \$94,047.92 | \$94,047.92 |
| | • | | \$10,853,352.38 | \$10,908,232.63 |
| Contract Total Pa | vable This Estimate: | \$54 880 25 | | |

| tems | Paid | <u>This</u> | Estima | ite P | <u>'eriod</u> |
|------|------|-------------|---------------|-------|---------------|
| | | | | | |

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|--|------|--------------|--------------------------|-----------------------------|
| J3P3158 | 0110 | 6081012 | TRUNCATED DOMES | SQFT | \$35.000 | 60 | \$2,100.00 |
| | 0370 | 8051000A | SEEDING - COOL SEASON GRASSES | ACRE | \$78,000.000 | 0.020 | \$1,560.00 |
| | 0420 | 6161047 | TYPE 3 OBJECT MARKER | EA | \$105.000 | 12 | \$1,260.00 |
| | 0430 | 9031270A | 2 IN. PSST POST - 12 GA. | LF | \$28.000 | 140 | \$3,920.00 |
| | 0440 | 9031271A | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | EA | \$136.000 | 14 | \$1,904.00 |
| | 0450 | 9035004A | SH-FLAT SHEET | SQFT | \$28.000 | 20 | \$560.00 |
| | 0460 | 9039902 | MISC.RELOCATE EXISTING SIGN ASSEMBLIES | EA | \$435.000 | 1 | \$435.00 |
| Project J3P315 | 8 - Total | | | | | | \$11,739.00 |
| JKR0249 | 0470 | 2022010 | REMOVAL OF IMPROVEMENTS | LS | \$11,500.000 | 0.189 | \$2,173.50 |
| | 0480 | 2153000 | SHAPING SLOPES, CLASS III | 100F | \$1,250.000 | 4.750 | \$5,937.50 |
| | 0780 | 6061060 | MGS GUARDRAIL | LF | \$25.000 | 400.500 | \$10,012.50 |
| | 0790 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | LF | \$29.500 | 350.500 | \$10,339.75 |
| | 0810 | 6061080 | MGS END ANCHOR | EA | \$1,400.000 | 3 | \$4,200.00 |
| | 0820 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | EA | \$3,350.000 | 3 | \$10,050.00 |
| | 0830 | 6161047 | TYPE 3 OBJECT MARKER | EA | \$110.000 | 1 | \$110.00 |
| | 0840 | 9031270A | 2 IN. PSST POST - 12 GA. | LF | \$28.000 | 6 | \$168.00 |
| | 0850 | 9031271A | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | EA | \$150.000 | 1 | \$150.00 |
| Project JKR024 | 9 - Total | | | | | | \$43,141.25 |
| Overall - Total | | | | | | | \$54,880.25 |
| Contract Adjusti | ments This E | stimate | | | | | |

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 10/17/2025 Page 1 of 29



Pay Estimate Created Date: November 3, 2025

| Estimat | gress e Numl 12 | Contract ID per Prime Contractor | 250314-C01 Emery Sapp & S | ons, Inc. | Pay Period End November 1, 2025 | Original Contract Amo Net Change Order Am Current Contract Amo | ount | \$11,325,502.80 (\$247,740.69 \$11,077,762.11 |
|-------------------|-----------------------|--|------------------------------|----------------------------------|--|--|---------------------------------------|---|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| 3P3158 | 0080 | BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP- | Material | | | -169.62000 | \$84.00 | (\$14,248.08 |
| | 0800 | BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP- | Material | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 1 the current Payment Estimate. | 1 | \$84.00 | \$14,248.08 |
| | 0140 | FURNISHING AND PLACIN CONCRETE MATERIAL FO FULL DEPTH PAVEMENT REPAIR | | | | -380 | \$285.00 | (\$108,300.00 |
| | 0140 | FURNISHING AND PLACIN CONCRETE MATERIAL FO FULL DEPTH PAVEMENT REPAIR | | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 8 the current Payment Estimate. | 1 | \$285.00 | \$108,300.00 |
| | 0190 | DOWEL BAR (FURNISHIN AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPA | | | | -60 | \$17.00 | (\$1,020.00 |
| | 0190 | DOWEL BAR (FURNISHIN AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPA | | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 1 | \$17.00 | \$1,020.00 |
| | 0200 | TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULI DEPTH PAVEMENT REPA (TYPE L JOINTS) | | | | -27 | \$6.50 | (\$175.50 |
| | 0200 | TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULI DEPTH PAVEMENT REPA (TYPE L JOINTS) | | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 1 | \$6.50 | \$175.50 |
| | 0270 | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | | | | -131,572.80000 | \$0.21 | (\$27,630.29 |
| | 0270 | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 1 | \$0.21 | \$27,630.29 |
| | 0280 | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | Material T | | | -153,865.60000 | \$0.23 | (\$35,389.09 |
| | 0280 | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | Material T | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 1 | \$0.23 | \$35,389.09 |
| | 0410 | TYPE 1C EROSION CONTROL BLANKET | Material | | | -112 | \$6.00 | (\$672.00 |
| | 0410 | TYPE 1C EROSION CONTROL BLANKET | Material | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 1 | \$6.00 | \$672.00 |
| | 0420 | TYPE 3 OBJECT MARKER | Material | | | -12 | \$105.00 | (\$1,260.00) |
| | 0420 | TYPE 3 OBJECT MARKER | Material | | This adjustment offsets the original system generated Material Payment Estimate Item | | \$105.00 | \$1,260.00 |

Revision 10/17/2025 Page 2 of 29



Pay Estimate Created Date: November 3, 2025

| Estimate | gress e Numl 12 | | 50314-C01 mery Sapp & S | ons, Inc. | Pay Period End November 1, 2025 No | riginal Contract Amo et Change Order Am urrent Contract Amo | ount | \$11,325,502.80 (\$247,740.69 \$11,077,762.11 |
|-------------------|-----------------------|---|----------------------------|----------------------------------|--|---|---------------------------------------|---|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J3P3158 | | | | | Adjustment (0008) due to user johnsm7 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | |
| | 0430 | 2 IN. PSST POST - 12 GA. | Material | | | -140 | \$28.00 | (\$3,920.00) |
| | 0430 | 2 IN. PSST POST - 12 GA. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment Estimate Exception 31 on the current Payment Estimate. | 140 | \$28.00 | \$3,920.00 |
| | 0440 | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | Material | | | -14 | \$136.00 | (\$1,904.00) |
| | 0440 | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user johnsm7 overridding Payment Estimate Exception 33 on the current Payment Estimate. | 14 | \$136.00 | \$1,904.00 |
| | 0450 | SH-FLAT SHEET | Material | | | -20 | \$28.00 | (\$560.00) |
| | 0450 | SH-FLAT SHEET | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user johnsm7 overridding Payment Estimate Exception 35 on the current Payment Estimate. | 20 | \$28.00 | \$560.00 |
| JKR0249 | 0490 | MISC. | Material | | | -2,778.83000 | \$27.25 | (\$75,723.12) |
| | 0490 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user johnsm7 overridding Payment Estimate Exception 3 of the current Payment Estimate. | 2,778.83000 on | \$27.25 | \$75,723.12 |
| | 0500 | BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1) | Material | | | -28.27000 | \$80.35 | (\$2,271.49) |
| | 0500 | BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user johnsm7 overridding Payment Estimate Exception 2 of the current Payment Estimate. | 28.27000 on | \$80.35 | \$2,271.49 |
| | 0520 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | | | | -1,689.50000 | \$250.00 | (\$422,375.00) |
| | 0520 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user johnsm7 overridding Payment Estimate Exception 9 of the current Payment Estimate. | 1,689.50000 | \$250.00 | \$422,375.00 |
| | 0560 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | Material | | | -3,564 | \$6.25 | (\$22,275.00) |
| | 0560 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user johnsm7 overridding Payment Estimate Exception 10 on the current Payment Estimate. | 3,564 | \$6.25 | \$22,275.00 |
| | 0680 | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | | -88,962 | \$0.23 | (\$20,461.26) |
| | 0680 | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user johnsm7 overridding Payment Estimate Exception 20 on the current Payment Estimate. | 88,962 | \$0.23 | \$20,461.26 |

Revision 10/17/2025 Page 3 of 29



Pay Estimate Created Date: November 3, 2025

| Estimate | gress e Numl 12 | Contract ID per Prime Contractor | 250314-C01 Emery Sapp & S | ons, Inc. | Pay Period End November 1, 2025 | Original Contract Amo Net Change Order Am Current Contract Amo | ount | \$11,325,502.80 (\$247,740.69 \$11,077,762.11 |
|-------------------|-----------------------|---|------------------------------|----------------------------------|--|--|---------------------------------------|---|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| KR0249 | 0690 | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | | | | -180,946 | \$0.26 | (\$47,045.96 |
| | 0690 | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0017) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 1 | \$0.26 | \$47,045.96 |
| | 0700 | 6 IN. YELLOW HIGH BUIL WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | NT | | | -21,439 | \$0.26 | (\$5,574.14 |
| | 0700 | 6 IN. YELLOW HIGH BUIL WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | NT | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0018) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 1 | \$0.26 | \$5,574.14 |
| | 0710 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | NT | | | -966 | \$1.05 | (\$1,014.30 |
| | 0710 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMEN MARKING PAINT, TYPE L BEADS | NT | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 1 | \$1.05 | \$1,014.30 |
| | 0780 | MGS GUARDRAIL | Material | | | -2,628 | \$25.00 | (\$65,700.00 |
| | 0780 | MGS GUARDRAIL | Material | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0020) due to user johnsm7 overridding Payment Estimate Exception 4 the current Payment Estimate. | 1 | \$25.00 | \$65,700.00 |
| | 0790 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | Material | | | -3,438 | \$29.50 | (\$101,421.00 |
| | 0790 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | Material | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0021) due to user johnsm7 overridding Payment Estimate Exception 6 the current Payment Estimate. | 1 | \$29.50 | \$101,421.00 |
| | 0830 | TYPE 3 OBJECT MARKER | R Material | | | -1 | \$110.00 | (\$110.00 |
| | 0830 | TYPE 3 OBJECT MARKER | R Material | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0022) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 1 | \$110.00 | \$110.00 |
| | 0840 | 2 IN. PSST POST - 12 GA. | Material | | | -6 | \$28.00 | (\$168.00 |
| | 0840 | 2 IN. PSST POST - 12 GA. | Material | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0023) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 1 | \$28.00 | \$168.00 |
| | 0850 | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | Material | | | -1 | \$150.00 | (\$150.00 |
| | 0850 | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | Material | | This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0024) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 1 | \$150.00 | \$150.00 |
| otal | | | | | | | | \$0.00 |

Revision 10/17/2025 Page 4 of 29



| | | | | | С | ontract Project Informat | tion |
|-------------------|----------------------------|---|-------|-----------|---|--|---|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J3P3158 | FAF 24-1(96) | Resurface and ADA improvements | 24 | LAFAYETTE | from Lexington to W | averly | |
| JKR0249 | FAF 13-3(96) | Resurface | 24 | LAFAYETTE | from Jackson County | y line to Route 13 in Lexington | n |
| Totals b | y Job N | umbers | | | | | |
| J3P3158 | Incent Dising | d Item Pay s Item Adjustme tive centive dated Damages | Gross | ltem Pay | This Estimate \$11,739.00 \$0.00 \$11,739.00 \$0.00 \$0.00 \$0.00 | Previous \$4,490,491.96 \$3,416.79 \$4,493,908.75 \$0.00 \$0.00 \$0.00 | To Date \$4,502,230.96 \$3,416.79 \$4,505,647.75 \$0.00 \$0.00 \$0.00 |
| | | Contract Adjus | | | \$0.00 | \$50,882.50 | \$50,882.50 |
| JKR0249 | | d Item Pay Item Adjustme | | Item Pay | This Estimate \$43,141.25 \$0.00 \$43,141.25 | Previous \$6,259,850.86 \$5,544.85 \$6,265,395.71 | To Date \$6,302,992.11 \$5,544.85 \$6,308,536.96 |
| | Liquid | tive centive dated Damages Contract Adjus | | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$43,165.42 | \$0.00 \$0.00 \$0.00 \$43,165.42 |

Revision 5/29/2025 Page 5 of 29



Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|---|--|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 4011231, Project Item Line Number 0080, Material Set 4011231, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient. | Tests have passed but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 4011231, Project Item Line Number 0500, Material Set 4011231, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient. | Tests have passed but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 3049910, Project Item Line Number 0490, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | Tests have passed but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6061060, Project Item Line Number 0780, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6061060, Project Item Line Number 0780, Material Set 606106096, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6061061, Project Item Line Number 0790, Material Set 606106196, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6061061, Project Item Line Number 0790, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131010, Project Item Line Number 0140, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient. | Tests have passed but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6131010, Project Item Line Number 0520, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient. | Tests have passed but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6131015, Project Item Line Number 0560, Material Set 613101596, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6131015, Project Item Line Number 0560, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131017, Project Item Line Number 0190, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient. | PAL form has been generated but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131017, Project Item Line Number 0190, Material Set 613101796, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | PAL form has been generated but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131018, Project Item Line Number 0200, Material Set 613101896, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131018, Project Item Line Number 0200, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6161047, Project Item Line Number 0420, Material Set 616104796, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6161047, Project Item Line Number 0830, Material Set 616104796, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6205901A, Project Item Line Number 0270, Material Set 6205901A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6205901A, Project Item Line Number 0270, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6205901A, Project Item Line Number 0680, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6205901A, Project Item Line Number 0680, Material Set 6205901A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6205902A, Project Item Line Number 0280, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6205902A, Project Item Line Number 0280, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6205902A, Project Item Line Number 0690, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr | Certificates received but not yet entered into the system. | johnsm7 | Overridden |

Revision 5/29/2025 Page 6 of 29



Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|--|---------------|------------|
| HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | | | |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6205902A, Project Item Line Number 0690, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6205903A, Project Item Line Number 0700, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6205903A, Project Item Line Number 0700, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6205906A, Project Item Line Number 0710, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6205906A, Project Item Line Number 0710, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 8064133, Project Item Line Number 0410, Material Set 8064133, Material 0806EKBL - Erosion Control Blanket, Acceptance Action Generic 0806EKBL is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 9031270A, Project Item Line Number 0430, Material Set 9031270A96, Material 0903HSTS - OBSOLETE (DO NOT USE for 2025 or later contracts) Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 9031270A, Project Item Line Number 0840, Material Set 9031270A96, Material 0903HSTS - OBSOLETE (DO NOT USE for 2025 or later contracts) Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 9031271A, Project Item Line Number 0440, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 9031271A, Project Item Line Number 0850, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 9035004A, Project Item Line Number 0450, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient. | Certificates received but not yet entered into the system. | johnsm7 | Overridden |

Revision 5/29/2025 Page 7 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| | intities and | | | d on Report Generated date and can differ from the poste | | | | | enerated. | | |
|----------------|--------------|--------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| J3P3158 | 0001 | 0010 | 1081000 | SIGNET DBE REPORTING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$1,000.00 | \$1,000.00 |
| | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$250.00 | \$250.00 |
| | 0001 | 0030 | 2063000 | CLASS 3 EXCAVATION | 34.00 | 0.00 | 34.00 | CUYD | 34.00 | \$87.00 | \$2,958.00 |
| | 0001 | 0040 | 2063500 | CULVERT CLEANOUT | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,200.00 | \$1,200.00 |
| | 0001 | 0050 | 2071000 | LINEAR GRADING CLASS 1 | 1.00 | 0.00 | 1.00 | STA | 1.00 | \$5,250.00 | \$5,250.00 |
| | 0001 | 0070 | 3049910 | MISC.PERMANENT AGGREGATE EDGE TREATMENT | 11,441.40 | -8,310.04 | 3,131.36 | TONS | 3,131.36 | \$27.80 | \$87,051.81 |
| | 0001 | 0080 | 4011231 | BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1) | 39,553.80 | 615.82 | 40,169.62 | TONS | 40,169.62 | \$84.00 | \$3,374,248.0 |
| | 0001 | 0090 | 4079912 | MISC.MODIFIED TACK COAT | 71,307.00 | -3,034.00 | 68,273.00 | GAL | 68,273.00 | \$3.75 | \$256,023.7 |
| | 0001 | 0100 | 6081010 | CONCRETE CURB RAMP | 8.50 | 0.00 | 8.50 | SQYD | 8.50 | \$450.00 | \$3,825.0 |
| | 0001 | 0110 | 6081012 | TRUNCATED DOMES | 60.00 | 0.00 | 60.00 | SQFT | 60.00 | \$35.00 | \$2,100.0 |
| | 0001 | 0120 | 6086004 | CONCRETE SIDEWALK, 4 IN. | 30.90 | 0.00 | 30.90 | SQYD | 30.90 | \$185.00 | \$5,716.5 |
| | 0001 | 0130 | 6097000 | ROCK LINING | 2.00 | 0.00 | 2.00 | CUYD | 2.00 | \$275.00 | \$550.0 |
| | 0001 | 0140 | 6131010 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | 384.00 | -4.00 | 380.00 | SQYD | 380.00 | \$285.00 | \$108,300.0 |
| | 0001 | 0150 | 6131012 | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) | 38.00 | -38.00 | 0.00 | SQYD | 0.00 | \$1.00 | \$0.0 |
| | 0001 | 0160 | 6131013 | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) | 38.00 | -38.00 | 0.00 | SQYD | 0.00 | \$4.35 | \$0.0 |
| | 0001 | 0170 | 6131014 | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) | 1,110.00 | -5.00 | 1,105.00 | LF | 1,105.00 | \$4.90 | \$5,414.5 |
| | 0001 | 0180 | 6131015 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | 660.00 | -230.00 | 430.00 | EA | 430.00 | \$6.25 | \$2,687.5 |
| | 0001 | 0190 | 6131017 | DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR | 40.00 | 20.00 | 60.00 | EA | 60.00 | \$17.00 | \$1,020.0 |
| | 0001 | 0200 | 6131018 | TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) | 32.00 | -5.00 | 27.00 | EA | 27.00 | \$6.50 | \$175.5 |
| | 0001 | 0210 | 6161005 | CONSTRUCTION SIGNS | 2,292.00 | 0.00 | 2,292.00 | SQFT | 2,186.63 | \$7.00 | \$15,306.4 |
| | 0001 | 0220 | 6161025 | CHANNELIZER (TRIM-LINE) | 200.00 | -100.00 | 100.00 | EA | 100.00 | \$19.00 | \$1,900.0 |
| | 0001 | 0230 | 6161040 | FLASHING ARROW PANEL | 2.00 | -2.00 | 0.00 | EA | 0.00 | \$900.00 | \$0.0 |
| | 0001 | 0240 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,600.00 | \$7,200.0 |
| | 0001 | 0250 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$376,250.00 | \$376,250.0 |
| | 0001 | 0260 | 6200036 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | 5.00 | 0.00 | 5.00 | EA | 5.00 | \$225.00 | \$1,125.0 |
| | 0001 | 0270 | 6205901A | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 164,466.00 | 0.00 | 164,466.00 | LF | 131,572.80 | \$0.21 | \$27,630.2 |
| | 0001 | 0280 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 196,332.00 | 0.00 | 196,332.00 | LF | 153,865.60 | \$0.23 | \$35,389.0 |
| | 0001 | 0290 | 6209901 | MISC.OPTIONAL TEMPORARY PAVEMENT MARKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$33,100.00 | \$33,100.0 |
| | 0001 | 0300 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 845.00 | 0.00 | 845.00 | SQYD | 845.00 | \$9.00 | \$7,605.0 |
| | 0001 | 0310 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 10,115.00 | 0.00 | 10,115.00 | SQYD | 8,916.94 | \$7.20 | \$64,201. |
| | 0001 | 0320 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 1,952.70 | 0.00 | 1,952.70 | STA | 1,537.46 | \$19.90 | \$30,595. |
| | 0001 | 0330 | 6261001 | BITUMINOUS CENTERLINE RUMBLE STRIP | 976.30 | 0.00 | 976.30 | STA | 886.84 | \$19.90 | \$17,648. |
| | 0001 | 0340 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$4,500.00 | \$4,500. |
| | 0001 | 0350 | 7250315A | 15 IN. PIPE GROUP B | 50.00 | 0.00 | 50.00 | LF | 50.00 | \$75.00 | \$3,750. |
| | 0001 | 0360 | 7320015A | 15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$300.00 | \$300. |
| | 0001 | 0370 | 8051000A | SEEDING - COOL SEASON GRASSES | 0.10 | 0.00 | 0.10 | ACRE | 0.10 | \$78,000.00 | \$7,800. |
| | 0001 | 0380 | 8061004 | SEDIMENT TRAP ROCK | 2.00 | 0.00 | 2.00 | CUYD | 2.00 | \$200.00 | \$400. |
| | 0001 | 0390 | 8061005 | ROCK DITCH CHECK | 24.00 | 0.00 | 24.00 | LF | 24.00 | \$42.00 | \$1,008. |
| | 0001 | 0400 | 8061016 | SEDIMENT REMOVAL | 3.00 | 0.00 | 3.00 | CUYD | 0.00 | \$45.00 | \$0. |
| | 0001 | 0410 | 8064133 | TYPE 1C EROSION CONTROL BLANKET | 112.00 | 0.00 | 112.00 | SQYD | 112.00 | \$6.00 | \$672. |
| | 0040 | 0420 | 6161047 | TYPE 3 OBJECT MARKER | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$105.00 | \$1,260. |
| | 0040 | 0430 | 9031270A | 2 IN. PSST POST - 12 GA. | 140.00 | 0.00 | 140.00 | LF | 140.00 | \$28.00 | \$3,920. |
| | 0040 | 0440 | 9031271A | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | 14.00 | 0.00 | 14.00 | EA | 14.00 | \$136.00 | \$1,904. |
| | 0040 | 0450 | 9035004A | SH-FLAT SHEET | 20.00 | 0.00 | 20.00 | SQFT | 20.00 | \$28.00 | \$560. |
| | 0040 | 0460 | 9039902 | MISC.RELOCATE EXISTING SIGN ASSEMBLIES | 2.00 | 0.00 | 2.00 | EA | 1.00 | \$435.00 | \$435. |
| oject J | 3P3158 - To | tal Value | Posted to D | late as of Report Generated Date | | | | | | | \$4,502,230. |
| KR0249 | 0001 | 0470 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$11,500.00 | \$11,500. |
| | 0001 | 0480 | 2153000 | SHAPING SLOPES, CLASS III | 26.00 | 0.00 | 26.00 | 100F | 26.00 | \$1,250.00 | \$32,500.0 |
| | 0001 | 0490 | 3049910 | MISC.PERMANENT AGGREGATE EDGE TREATMENT | 10,966.00 | 0.00 | 10,966.00 | TONS | 2,778.83 | \$27.25 | \$75,723. |
| | | | 1011001 | BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1) | 49,537.00 | 491.27 | 50,028.27 | TONS | 50,028.27 | \$80.35 | \$4,019,771.4 |
| | 0001 | 0500 | 4011231 | BITUININGUS PAVEINENT MIXTURE PG30-2011, (BF-1) | 10,001.00 | | | | | | |
| | 0001 | 0500 0510 | 4011231 | MISC.MODIFIED TACK COAT | | -11,986.00 | 78,374.00 | GAL | 78,374.00 | \$3.75 | \$293,902.5 |

Revision 5/29/2025 Page 8 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| ontract ID | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTE To Date (See repor generated date) |
|---------------|----------------|-------------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 50314- | JKR0249 | | | | DEPTH PAVEMENT REPAIR | | | | | | | |
| 01 | | 0001 | 0530 | 6131012 | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) | 180.00 | -180.00 | 0.00 | SQYD | 0.00 | \$1.00 | \$0.0 |
| | | 0001 | 0540 | 6131013 | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) | 180.00 | -180.00 | 0.00 | SQYD | 0.00 | \$4.35 | \$0.0 |
| | | 0001 | 0550 | 6131014 | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) | 6,152.00 | 107.00 | 6,259.00 | LF | 6,259.00 | \$4.90 | \$30,669. |
| | | 0001 | 0560 | 6131015 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | 4,242.00 | -678.00 | 3,564.00 | EA | 3,564.00 | \$6.25 | \$22,275.0 |
| | | 0001 | 0570 | 6133020 | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | 511.00 | 0.00 | 511.00 | TONS | 511.00 | \$115.00 | \$58,765.0 |
| | | 0001 | 0580 | 6133021 | REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | 1,621.60 | 0.00 | 1,621.60 | SQYD | 1,621.60 | \$131.50 | \$213,240.4 |
| | | 0001 | 0590 | 6161005 | CONSTRUCTION SIGNS | 3,562.00 | 0.00 | 3,562.00 | SQFT | 2,838.13 | \$7.00 | \$19,866.9 |
| | | 0001 | 0600 | 6161025 | CHANNELIZER (TRIM-LINE) | 150.00 | 0.00 | 150.00 | EA | 100.00 | \$19.00 | \$1,900. |
| | | 0001 | 0610 | 6161030 | TYPE 3 MOVEABLE BARRICADE | 18.00 | -18.00 | 0.00 | EA | 0.00 | \$250.00 | \$0. |
| | | 0001 | 0620 | 6161040 | FLASHING ARROW PANEL | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,450.00 | \$2,900 |
| | | 0001 | 0630 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED | 4.00 | -2.00 | 2.00 | EA | 2.00 | \$4,750.00 | \$9,500. |
| | | 0001 | 0640 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$550,000.00 | \$550,000 |
| | | 0001 | 0650 | 6200012 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE | 42.00 | 0.00 | 42.00 | LF | 32.00 | \$16.50 | \$528 |
| | | 0001 | 0660 | 6200018 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW | 96.00 | 0.00 | 96.00 | LF | 65.00 | \$27.50 | \$1,787 |
| | | 0001 | 0670 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$500.00 | \$500 |
| | | 0001 | 0680 | 6205901A | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 88,962.00 | 0.00 | 88,962.00 | LF | 88,962.00 | \$0.23 | \$20,461 |
| | | 0001 | 0690 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 183,181.00 | 0.00 | 183,181.00 | LF | 180,946.00 | \$0.26 | \$47,045 |
| | | 0001 | 0700 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 21,439.00 | 0.00 | 21,439.00 | LF | 21,439.00 | \$0.26 | \$5,574 |
| | | 0001 | 0710 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 1,432.00 | 0.00 | 1,432.00 | LF | 966.00 | \$1.05 | \$1,014 |
| | | 0001 | 0720 | 6209901 | MISC.OPTIONAL TEMPORARY PAVEMENT MARKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$1.00 | \$1 |
| | | 0001 | 0730 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 33,562.00 | 0.00 | 33,562.00 | SQYD | 33,562.00 | \$2.25 | \$75,514 |
| | | 0001 | 0740 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 4,838.00 | 0.00 | 4,838.00 | SQYD | 4,838.00 | \$8.75 | \$42,332 |
| | | 0001 | 0750 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 1,787.00 | 0.00 | 1,787.00 | STA | 1,588.10 | \$19.90 | \$31,603 |
| | | 0001 | 0760 | 6261001 | BITUMINOUS CENTERLINE RUMBLE STRIP | 742.00 | 0.00 | 742.00 | STA | 705.64 | \$19.90 | \$14,042 |
| | | 0001 | 0770 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$4,500.00 | \$4,500 |
| | | 0010 | 0780 | 6061060 | MGS GUARDRAIL | 2,628.00 | 0.00 | 2,628.00 | LF | 2,628.00 | \$25.00 | \$65,700 |
| | | 0010 | 0790 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | 3,438.00 | 0.00 | 3,438.00 | LF | 3,438.00 | \$29.50 | \$101,421 |
| | | 0010 | 0800 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$3,700.00 | \$29,600 |
| | | 0010 | 0810 | 6061080 | MGS END ANCHOR | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$1,400.00 | \$5,600 |
| | | 0010 | 0820 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 27.00 | 0.00 | 27.00 | EA | 27.00 | \$3,350.00 | \$90,450 |
| | | 0040 | 0830 | 6161047 | TYPE 3 OBJECT MARKER | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$110.00 | \$110 |
| | | 0040 | 0840 | 9031270A | 2 IN. PSST POST - 12 GA. | 6.00 | 0.00 | 6.00 | LF | 6.00 | \$28.00 | \$16 |
| | | 0040 | 0850 | | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$150.00 | \$150 |
| | Project II | (R0249 - To | | | Date as of Report Generated Date | | | | | | | \$6.302.99 |
| | | | | | of Report Generated Date | | | | | | | \$10,805,22 |

Revision 5/29/2025 Page 9 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J3P3158

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Posting Sequence No. | Quantity Posted | Units | Location | From Station/Log Mile | Offset/ Distance | To Station/Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|----------------------------|--------------------|-------|--|-----------------------------|---------------------|---------------------------|---------------------|----------|
| 0110 | 6081012 | TRUNCATED DOMES | 10/24/25 | 10/30/25 | 1 | 60.00 | SQFT | Santa Fe Elementary School 1041+66.58 36.67° LT. 1042+12.07 16.41° LT. 1042+12.07 15.33° RT. | | | | | |
| 0370 | 8051000A | SEEDING - COOL SEASON GRASSES | 10/24/25 | 10/30/25 | 1 | 0.02 | ACRE | | 1041+50.00 | | 1042+25.00 | | |
| 0420 | 6161047 | TYPE 3 OBJECT MARKER | 10/22/25 | 10/30/25 | 1 | 12.00 | EA | Log miles: (two markers per) 54.287, 54.661, 59.005, 59.345, 64.257, 66.945 | | | | | |
| 0430 | 9031270A | 2 IN. PSST POST - 12 GA. | 10/22/25 | 10/30/25 | 1 | 140.00 | LF | Sta. 1043+19.78 Sta. 1042+10.08 Log miles: (two posts per) 54.287, 54.661, 59.005, 59.345, 64.257, 66.945 | | | | | |
| 0440 | 9031271A | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | 10/22/25 | 10/30/25 | 1 | 14.00 | EA | Sta. 1043+19.78 Sta. 1042+10.08 Log miles: (two posts per) 54.287, 54.661, 59.005, 59.345, 64.257, 66.945 | | | | | |
| 0450 | 9035004A | SH-FLAT SHEET | 10/22/25 | 10/30/25 | 1 | 20.00 | SQFT | Sta. 1043+19.78 - Pedestrian & Ahead sign - 11 sqft Sta. 1042+10.08 - Pedestrian sign 9 sqft | | | | | |
| 0460 | 9039902 | MISC. | 10/22/25 | 10/30/25 | 1 | 1.00 | EA | Santa Fe Elementary School Eastside of the ramp | 1041+80.88 | 29.09' LT. | 1042+19.12 | 18.42' LT. | |

Project: JKR0249

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Posting Sequence No. | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|----------------------------|--------------------|-------|---|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0470 | 2022010 | REMOVAL OF IMPROVEMENTS | 10/16/25 | 10/30/25 | 1 | 0.05 | LS | WB&EB passing lanes for pier protection 47.118 to 47.164 / 174.147 to 174.192. | 47.118 | | 47.164 | | |
| | | | 10/17/25 | 10/30/25 | 1 | 0.14 | LS | Ramp 244 to Rte 13 0.038 to 0.123 | 0.038 | | 0.123 | | |
| 0480 | 2153000 | SHAPING SLOPES, CLASS III | 10/16/25 | 10/30/25 | 1 | 3.70 | 100F | WB&EB passing lanes for pier protection 47.118 to 47.164 / 174.147 to 174.192. | 47.118 | | 47.164 | | |
| | | | 10/17/25 | 10/30/25 | 1 | 1.05 | 100F | Ramp 244 to Rte 13 0.038 to 0.123 | 0.038 | | 0.123 | | |
| 0780 | 6061060 | MGS GUARDRAIL | 10/17/25 | 10/30/25 | 1 | 400.50 | LF | Ramp 244 to Rte 13 0.038 to 0.123 | 0.038 | | 0.123 | | |
| 0790 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN | 10/16/25 | 10/30/25 | 1 | 350.50 | LF | WB&EB passing lanes for pier protection 47.118 to 47.164 / 174.147 to 174.192. | 47.118 | | 47.164 | | |
| 0810 | 6061080 | MGS END ANCHOR | 10/16/25 | 10/30/25 | 1 | 2.00 | EA | WB&EB passing lanes for pier protection 47.118 to 47.164 / 174.147 to 174.192. | 47.118 | | 47.164 | | |
| | | | 10/17/25 | 10/30/25 | 1 | 1.00 | EA | Ramp 244 to Rte 13 0.038 to 0.123 | 0.038 | | 0.123 | | |
| 0820 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 10/16/25 | 10/30/25 | 1 | 2.00 | EA | WB&EB passing lanes for pier protection 47.118 to 47.164 / 174.147 to 174.192. | 47.118 | | 47.164 | | |
| | | | 10/17/25 | 10/30/25 | 1 | 1.00 | EA | Ramp 244 to Rte 13 0.038 to 0.123 | 0.038 | | 0.123 | | |
| 0830 | 6161047 | TYPE 3 OBJECT MARKER | 10/22/25 | 10/30/25 | 1 | 1.00 | EA | OLD SANTA FE TRAIL & ROUTE 24 EB 34.078 | 34.078 | | 34.078 | | |
| 0840 | 9031270A | 2 IN. PSST POST - 12 GA. | 10/22/25 | 10/30/25 | 1 | 6.00 | LF | OLD SANTA FE TRAIL & ROUTE 24 EB 34.078 | 34.078 | | 34.078 | | |
| 0850 | 9031271A | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | 10/22/25 | 10/30/25 | 1 | 1.00 | EA | OLD SANTA FE TRAIL & ROUTE 24 EB 34.078 | 34.078 | | 34.078 | | |

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 10 of 29



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | |
|---------|--------|---|--------------------------|-----------------------------|-----------------|-----------------|-----------------|--|--|--|----|----------------|-----------------|---------------|---------------|-----------------|
| J3P3158 | 0070 | MISC. AGGREGATE | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$87,051.81) | | | | | | | | |
| | | FOR BASE | | | 10 | Oct 1, 2025 | SYSTEM | \$87,051.81 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$87,051.81) | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$87,051.81 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | |
| | 0070 - | Total | | | | | | \$0.00 | | | | | | | | |
| | 0800 | BIT. PAVEMENT MIXTURE PG58-28H (BP-1) | Material | | 8 | Sep 2, 2025 | SYSTEM | (\$1,079.40) | | | | | | | | |
| | | F G 30-2011 (BF-1) | | | 8 | Sep 2, 2025 | SYSTEM | \$1,079.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$14,248.08) | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$14,248.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | |
| | | | | | | | | | | 12 | 12 | Nov 3, 2025 | SYSTEM | (\$14,248.08) | | |
| | | | | | | 12 | Nov 3, 2025 | SYSTEM | \$14,248.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$14,248.08) | | | | | | | | |
| | | | | - Total | | | | (\$14,248.08) | | | | | | | | |
| | | | Material - To | otal | | | | (\$14,248.08) | | | | | | | | |
| | | | Other Item Adjustment | ACAD | 7 | Aug 18, 2025 | johnsm7 | \$631.62 | AC Adjustment Line Number: 0080 Install Quantity: 7430.84 (tons) @3.4% (virgin) * 2.5 (diff) = \$631.62 | | | | | | | |
| | | | | | 8 | Sep 2, 2025 | johnsm7 | \$1,069.47 | AC Adjustment Line Number: 0080 Install Quantity: 12582.01 (tons) @3.4% (virgin) * 2.5 (diff) = \$1069.47 | | | | | | | |
| | | | | | 9 | Sep 16, 2025 | johnsm7 | \$1,715.70 | AC adjustment Linie Number: 0080 Install Quantity: 20184.69 (tons) @3.4% (virgin) * 2.5 (diff) = \$1715.70 | | | | | | | |
| | | | | ACAD - Tota | al | | | \$3,416.79 | | | | | | | | |
| | | | Other Item | Adjustment - | Total | | | \$3,416.79 | | | | | | | | |
| | 0080 - | Total | | | | | | (\$10,831.29) | | | | | | | | |
| | 0090 | MISC. | Material 7 7 7 8 | 7 | Material | Material | Material | Material | Material | Material | | 7 | Aug 18, 2025 | SYSTEM | (\$47,535.00) | |
| | | | | | | | | | | | 7 | 7 | | 7 | 7 | Aug 18, 2025 |
| | | 8 | | | 8 | 8 | 8 | Sep 2, 2025 | SYSTEM | (\$129,956.25) | | | | | | |
| | | | | 9 | 8 | Sep 2, 2025 | SYSTEM | \$129,956.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | | | |
| | | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$256,023.75) | | | | | | | |
| | | | | | Sep 16, 2025 | SYSTEM | \$256,023.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$256,023.75) | | | | | | | | |
| | | | | | 10 | Oct 1, | SYSTEM | \$256,023.75 | This adjustment offsets the original system-generated Material Payment | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | |
|---------|--------|-------------------------------|--------------------|-----------------------------|--------------------------------------|--|--|--|---|---|------------|
| J3P3158 | 0090 | MISC. | Material | | | 2025 | | | Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$256,023.75) | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$256,023.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - T | otal | | | | \$0.00 | | | |
| | 0090 - | - Total | | | | | | \$0.00 | | | |
| | 0130 | ROCK LINING | Material | | 8 | Sep 2, 2025 | SYSTEM | (\$550.00) | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$550.00) | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | \$550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$550.00) | | | |
| | | | | | | | 10 | | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | |
| | | | | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$550.00) |
| | | | | | | 11 | Oct 16, 2025 | SYSTEM | \$550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 13 on the current Payment Estimate. | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | otal | | | | \$0.00 | | | |
| | | | Material - To | | | | | | | | |
| | 0130 - | - Total | | | | | | \$0.00 | | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 | Aug 4, 2025 | SYSTEM | \$0.00 (\$108,300.00) | | | |
| | | FURN & PLACE | Material | | 6 | | SYSTEM SYSTEM | | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | |
| | | FURN & PLACE CONC MATL FOR | Material | | | 2025 Aug 4, | | (\$108,300.00) | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 | 2025 Aug 4, 2025 Aug 18, | SYSTEM | (\$108,300.00) \$108,300.00 | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 7 | 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, | SYSTEM SYSTEM | (\$108,300.00) \$108,300.00 (\$108,300.00) | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 7 7 | 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, | SYSTEM SYSTEM | (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 7 7 | 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, | SYSTEM SYSTEM SYSTEM | (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 7 7 8 8 8 | 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 16, 6 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 7 7 8 8 8 9 | 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 16, 2025 Sep 16, 2025 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 7 7 8 8 8 9 9 9 | 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 16, 2025 Oct 1, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 7 7 8 8 8 9 9 10 | 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | FURN & PLACE CONC MATL FOR | Material | | 6 7 7 8 8 8 9 9 | 2025 Aug 4, 2025 Aug 18, 2025 Aug 18, 2025 Sep 2, 2025 Sep 2, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) \$108,300.00 (\$108,300.00) | Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|--------|--------------|-----------------|--------|------------|--|-----------------|--------|-----------------|--------|----------------|---|------------|---|
| J3P3158 | 0140 | FURN & PLACE CONC MATL FOR FULL DEPTH | Material | | 12 | Nov 3, 2025 | SYSTEM | \$108,300.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0140 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0180 | DOWEL BAR (DRILLING, FURNISHING AND | Material | | 6 | Aug 4, 2025 | SYSTEM | (\$2,687.50) | | | | | | | | | | | | | | | |
| | | INST | | | 6 | Aug 4, 2025 | SYSTEM | \$2,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | (\$2,687.50) | | | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$2,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$2,687.50) | | | | | | | | | | | | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$2,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$2,687.50) | | | | | | | | | | | | | | | |
| | | | | | | | | | | | 9 | Sep 16, 2025 | SYSTEM | \$2,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | | | |
| | | | | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$2,687.50) | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | 10 | Oct 1, 2025 | SYSTEM | \$2,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | | | | | | | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$2,687.50) | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$2,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0180 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0190 | DOWEL BAR (FURNISH AND INSTALL WITH | Material | | 6 | Aug 4, 2025 | SYSTEM | (\$680.00) | | | | | | | | | | | | | | | |
| | | BASK | | | 6 | Aug 4, 2025 | SYSTEM | \$680.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | (\$680.00) | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 7 | Aug 18, 2025 | SYSTEM | \$680.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$680.00) | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 8 | Sep 2, 2025 | SYSTEM | \$680.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$680.00) | | | | | | | | | | | | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | \$680.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$680.00) | | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$680.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, | SYSTEM | (\$1,020.00) | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | | | |
|---------|--------|-----------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|----------------|---|---|----------------|--------|----------|---|--------|------------|--|--|--|--|----|----------------|--------|------------|---|
| J3P3158 | 0190 | DOWEL BAR (FURNISH AND | Material | | | 2025 | | | | | | | | | | | | | | | | | | | |
| | | INSTALL WITH BASK | | | 11 | Oct 16, 2025 | SYSTEM | \$1,020.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$1,020.00) | | | | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$1,020.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | | | | | | | | | | | | | |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$1,020.00) | | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | (\$1,020.00) | | | | | | | | | | | | | | | | | |
| | | | Material - To | otal | | | | (\$1,020.00) | | | | | | | | | | | | | | | | | |
| | 0190 - | Total | | | | | | (\$1,020.00) | | | | | | | | | | | | | | | | | |
| | 0200 | TIE BAR (DRILL, FURN & INSTAL) | Material | | 6 | Aug 4, 2025 | SYSTEM | (\$175.50) | | | | | | | | | | | | | | | | | |
| | | (TYPE L | | | 6 | Aug 4, 2025 | SYSTEM | \$175.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | (\$175.50) | | | | | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$175.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$175.50) | |
| | | | | | | | | | | 8 | Sep 2, 2025 | SYSTEM | \$175.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | | | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$175.50) | | | | | | | | | |
| | | | | | | 9 | Sep 16, 2025 | SYSTEM | \$175.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | | | | | | | | | |
| | | | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$175.50) | | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$175.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$175.50) | | | | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$175.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsm7 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$175.50) | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | 12 | Nov 3, 2025 | SYSTEM | \$175.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$175.50) | | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | (\$175.50) | | | | | | | | | | | | | | | | | |
| | | | Material - T | otal | | | | (\$175.50) | | | | | | | | | | | | | | | | | |
| | 0200 - | Total | | | | | | (\$175.50) | | | | | | | | | | | | | | | | | |
| | 0210 | CONSTRUCTION SIGNS | Material | | 2 | Jun 2, 2025 | SYSTEM | (\$2,450.00) | | | | | | | | | | | | | | | | | |
| | | | | | 2 | Jun 2, 2025 | SYSTEM | \$2,450.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | |
| | | | | | 3 | Jun 16, 2025 | SYSTEM | (\$2,450.00) | | | | | | | | | | | | | | | | | |
| | | | | | 3 | Jun 16, 2025 | SYSTEM | \$2,450.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | |
|---------|--------------------|--------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|-------------------------------|---|---|---------------|------------|---|----------------|-----------------|------------|---|---|--------------|---|--------|
| J3P3158 | 0210 | CONSTRUCTION SIGNS | Material | | 4 | Jul 1, 2025 | SYSTEM | (\$2,450.00) | | | | | | | | | | | | | |
| | | | | | 4 | Jul 1, 2025 | SYSTEM | \$2,450.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | (\$2,450.00) | | | | | | | | | | | | | |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | \$2,450.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 6 | Aug 4, 2025 | SYSTEM | (\$2,450.00) | | | | | | | | | | | | | |
| | | | | | 6 | Aug 4, 2025 | SYSTEM | \$2,450.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | (\$2,450.00) | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$2,450.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$6,034.00) | | | | | | | | | | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$6,034.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsm7 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$6,034.00) | | | | | | | | | | | | | |
| | | | | | | | | | 9 | Sep 16, 2025 | SYSTEM | \$6,034.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | | | | | | |
| | | | | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$15,306.41) | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$15,306.41 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsm7 overridding Payment Estimate Exception 25 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$15,306.41) | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$15,306.41 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment Estimate Exception 25 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | | | |
| | 0210 - 0220 | CHANNELIZER | Material | | 8 | Sep 2, | SYSTEM | \$0.00 (\$1,900.00) | | | | | | | | | | | | | |
| | | (TRIM-LINE) | | | | | | | | | | | | | 8 | 8 | 2025 Sep 2, 2025 | SYSTEM | \$1,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment Estimate Exception 19 on the current Payment Estimate. | |
| | | | | | | | | | | | | | | | | | | | 9 | Sep 16, 2025 | SYSTEM |
| | | | | | | | | | | | | | | 9 | Sep 16, 2025 | SYSTEM | \$1,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsm7 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | |
| | | | | | | | | | | | 10 | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$1,900.00) | | |
| | | | | | | | | | | | | | 10 | Oct 1, 2025 | SYSTEM | \$1,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment Estimate Exception 26 on the current Payment Estimate. | | | | |
| | | | | | 11 | 11 | Oct 16, 2025 | SYSTEM | (\$1,900.00) | | | | | | | | | | | | |
| | | | | | | 11 | Oct 16, 2025 | SYSTEM | \$1,900.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsm7 overridding Payment Estimate Exception 26 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | | \$0.00 | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J3P3158 | 0220 - | Total | | | | | | \$0.00 | |
| | 0240 | CHANGEABLE MESSAGE SIGN WITHOUT | Material | | 2 | Jun 2, 2025 | SYSTEM | (\$7,200.00) | |
| | | COMMUNICATION INTERFACE, CONTRACTOR | | | 2 | Jun 2, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | FURNISHED / RETAINED | | | 3 | Jun 16, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 3 | Jun 16, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 4 | Jul 1, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 4 | Jul 1, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 6 | Aug 4, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 6 | Aug 4, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsm7 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsm7 overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$7,200.00) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$7,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsm7 overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0240 - | | | | | | | \$0.00 | |
| | 0260 | PREF THERMO PVMT MARK, 30" WHT MIDBL | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$1,125.00) | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$1,125.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsm7 overridding Payment Estimate Exception 31 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$1,125.00) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$1,125.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsm7 overridding Payment Estimate Exception 31 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | |
|---------|---|--|--------------------|-----------------------------|-----------------|-----------------|----------------|---|---|---|---------------|-----|--|-----|--------|--|---|-----------------|--------|--------------|---|
| J3P3158 | 0260 | PREF THERMO PVMT MARK, 30" WHT MIDBL | Material - T | otal | | | | \$0.00 | | | | | | | | | | | | | |
| | 0260 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | |
| | 0270 | 4 IN. YELLOW HIGH BUILD | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$27,630.29) | | | | | | | | | | | | | |
| | | WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | | | 10 | Oct 1, 2025 | SYSTEM | \$27,630.29 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsm7 overridding Payment Estimate Exception 32 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$27,630.29) | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$27,630.29 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsm7 overridding Payment Estimate Exception 32 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$27,630.29) | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$27,630.29 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$27,630.29) | | | | | | | | | | | | | |
| | | | | - Total | | | | (\$27,630.29) | | | | | | | | | | | | | |
| | | | Material - T | otal | | | | (\$27,630.29) | | | | | | | | | | | | | |
| | 0270 - | Total | | | | | | (\$27,630.29) | | | | | | | | | | | | | |
| | 0280 | 6 IN. WHITE HIGH BUILD | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$35,389.09) | | | | | | | | | | | | | |
| | BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | AINT, | | | | 10 | Oct 1, 2025 | SYSTEM | \$35,389.09 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsm7 overridding Payment Estimate Exception 36 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$35,389.09) | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$35,389.09 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsm7 overridding Payment Estimate Exception 36 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$35,389.09) | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$35,389.09 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$35,389.09) | | | | | | | | | | | | | |
| | | | | - Total | | | | (\$35,389.09) | | | | | | | | | | | | | |
| | | | Material - T | otal | | | | (\$35,389.09) | | | | | | | | | | | | | |
| | 0280 - | Total | | | | | | (\$35,389.09) | | | | | | | | | | | | | |
| | 0350 | 15 IN. PIPE CULVERT GROUP | Material | | 7 | Aug 18, 2025 | SYSTEM | (\$3,750.00) | | | | | | | | | | | | | |
| | | В | 8 | 7 | 7 | | | 7 | 7 | P 7 | P 7 | P 7 | | P 7 | 7 7 | | 7 | Aug 18, 2025 | SYSTEM | \$3,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsm7 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | | | | | | | | | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$3,750.00) | |
| | | | | 8 | Sep 2, 2025 | SYSTEM | \$3,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsm7 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | | | | | | | | |
| | | | | | | Sep 16, 2025 | SYSTEM | (\$3,750.00) | | | | | | | | | | | | | |
| | | | | 9 | Sep 16, 2025 | SYSTEM | \$3,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsm7 overridding Payment Estimate Exception 24 on the current Payment Estimate. | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$3,750.00) | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$3,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsm7 overridding Payment Estimate Exception 44 on the current Payment Estimate. | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | |
|---------|--------|-------------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|--------------|---|---|------------|--|
| J3P3158 | 0350 | 15 IN. PIPE CULVERT GROUP | Material | | 11 | Oct 16, 2025 | SYSTEM | (\$3,750.00) | | | | |
| | | В | | | 11 | Oct 16, 2025 | SYSTEM | \$3,750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user johnsm7 overridding Payment Estimate Exception 44 on the current Payment Estimate. | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | |
| | 0350 - | Total | | | | | | \$0.00 | | | | |
| | 0360 | 15 IN. GROUP B FLARED END SEC | Material | | 7 | Aug 18, 2025 | SYSTEM | (\$300.00) | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$300.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$300.00) | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$300.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsm7 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$300.00) | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | \$300.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsm7 overridding Payment Estimate Exception 25 on the current Payment Estimate. | | | |
| | | | | | 10 | | | 10 | Oct 1, 2025 | SYSTEM | (\$300.00) | |
| | | | | | | 10 | Oct 1, 2025 | SYSTEM | \$300.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user johnsm7 overridding Payment Estimate Exception 45 on the current Payment Estimate. | | |
| | | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$300.00) | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$300.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user johnsm7 overridding Payment Estimate Exception 45 on the current Payment Estimate. | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | |
| | 0360 - | Total | | | | | | \$0.00 | | | | |
| | 0370 | SEEDING - COOL SEASON GRASSES | Material | | 9 | Sep 16, 2025 | SYSTEM | (\$6,240.00) | | | | |
| | | ONAGGEO | | | 9 | Sep 16, 2025 | SYSTEM | \$6,240.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsm7 overridding Payment Estimate Exception 26 on the current Payment Estimate. | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$6,240.00) | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$6,240.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user johnsm7 overridding Payment Estimate Exception 46 on the current Payment Estimate. | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$6,240.00) | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$6,240.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user johnsm7 overridding Payment Estimate Exception 46 on the current Payment Estimate. | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | |
| | 0370 - | Total | | | | | | \$0.00 | | | | |
| | 0380 | SEDIMENT TRAP ROCK | Material | | 7 | Aug 18, 2025 | SYSTEM | (\$400.00) | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$400.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsm7 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$400.00) | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$400.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsm7 overridding Payment Estimate Exception 23 on the current Payment Estimate. | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | |
|---------|---------------|-------------------------------|--------------------|-----------------------------|-----------------|-----------------|---------------|-----------------------------|---|--|--|--|---|-------------------------|--------|----------|--|----|--------|----------------|------------|--|--|
| J3P3158 | 0380 | SEDIMENT TRAP ROCK | Material | | 9 | Sep 16, 2025 | SYSTEM | (\$400.00) | | | | | | | | | | | | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | \$400.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsm7 overridding Payment Estimate Exception 27 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$400.00) | | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$400.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user johnsm7 overridding Payment Estimate Exception 47 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$400.00) | | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$400.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user johnsm7 overridding Payment Estimate Exception 47 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0380 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0390 | ROCK DITCH CHECK | Material | | 7 | Aug 18, 2025 | SYSTEM | (\$1,008.00) | | | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$1,008.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsm7 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$1,008.00) | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$1,008.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsm7 overridding Payment Estimate Exception 24 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$1,008.00) | | | | | | | | | | | | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | \$1,008.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsm7 overridding Payment Estimate Exception 28 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$1,008.00) | | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$1,008.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user johnsm7 overridding Payment Estimate Exception 48 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$1,008.00) | | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$1,008.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment Estimate Exception 48 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0390 - | TYPE 1C | Material | | 9 | Sep 16, | SYSTEM | \$0.00 (\$672.00) | | | | | | | | | | | | | | | |
| | | EROSION CONTROL BLANKET | ON OL | Material . | Material | Material | | | | | | | 9 | 2025 Sep 16, 2025 | SYSTEM | \$672.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user johnsm7 overridding Payment | | | | | | |
| | | | | | | | | | | | | | | | | | | 10 | Oct 1, | SYSTEM | (\$672.00) | Estimate Exception 29 on the current Payment Estimate. | |
| | | | | | | 10 | 2025 | CVCTE*4 | | This adjustment effects the original system report of Matrix | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$672.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment Estimate Exception 49 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | 11 | Oct 16, 2025 | SYSTEM | (\$672.00) | | | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$672.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user johnsm7 overridding Payment Estimate Exception 49 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$672.00) | | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$672.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|--------|--|--------------------|-----------------------------|-----------------------|--------------------------|---------------|----------------------------|---|
| J3P3158 | 0410 | TYPE 1C | Material | | | | | | Estimate Exception 30 on the current Payment Estimate. |
| | | EROSION CONTROL BLANKET | | | 13 | Nov 4, 2025 | SYSTEM | (\$672.00) | |
| | | | | - Total | | | | (\$672.00) | |
| | | | Material - To | otal | | | | (\$672.00) | |
| | 0410 - | | | | 40 | N. O | 0)/07514 | (\$672.00) | |
| | 0420 | TYPE 3 OBJECT MARKER | Material | | 12 | Nov 3, 2025 Nov 3, | SYSTEM | (\$1,260.00) \$1,260.00 | This adjustment offsets the original system-generated Material Payment |
| | | | | | 12 | 2025 | OTOTEM | ψ1,200.00 | Estimate Item Adjustment (0008) due to user johnsm7 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$1,260.00) | |
| | | | | - Total | | | | (\$1,260.00) | |
| | 0.100 | | Material - To | otal | | | | (\$1,260.00) | |
| | 0420 - | | Made 1 | | 40 | (\$1,260.00) | | | |
| | 0430 | 2 IN. PSST POST - 12 GA. | Material | | 12 | Nov 3, 2025 | SYSTEM | (\$3,920.00) | This adjustment offsets the original system-generated Material Payment |
| | | | | | 14 | 2025 | JIJIEW | ψυ,σ∠0.00 | Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment Estimate Exception 31 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0430 - | DRIVEN POST | | | | | | \$0.00 | |
| | 0440 | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | Material | | 12 | Nov 3, 2025 | SYSTEM | (\$1,904.00) | |
| | | | | | 12 Nov 3, SYSTEM 2025 | | | \$1,904.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsm7 overridding Payment Estimate Exception 33 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0440 - | Total | | | | | | \$0.00 | |
| | 0450 | SH-FLAT SHEET | Material | | 12 | Nov 3, 2025 | SYSTEM | (\$560.00) | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$560.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsm7 overridding Payment Estimate Exception 35 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$560.00) | |
| | | | | - Total | | | | (\$560.00) | |
| | | | Material - To | otal | | | | (\$560.00) | |
| | 0450 - | Total | | | | | | (\$560.00) | |
| J3P3158 - | Total | | | | | | | (\$77,538.17) | |
| JKR0249 | 0480 | SHAPING SLOPES, CLASS III | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$9,375.00) | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$9,375.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$26,562.50) | |
| | | | | | | 11 Oct 16, 2025 | | \$26,562.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0480 - | Total | | | | | | \$0.00 | |
| | 0490 | MISC. AGGREGATE FOR BASE | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$75,723.12) | |
| | | I ON DAGE | | | 10 | Oct 1, 2025 | SYSTEM | \$75,723.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user johnsm7 overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| JKR0249 | 0490 | MISC. | Material | | | | | | Estimate Exception 3 on the current Payment Estimate. |
| | | AGGREGATE FOR BASE | | | 11 | Oct 16, 2025 | SYSTEM | (\$75,723.12) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$75,723.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user johnsm7 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$75,723.12) | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$75,723.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$75,723.12) | |
| | | | | - Total | | | | (\$75,723.12) | |
| | | | Material - To | otal | | | | (\$75,723.12) | |
| | 0490 - | Total | | | | | | (\$75,723.12) | |
| | 0500 | BIT. PAVEMENT MIXTURE | Material | | 5 | Jul 16, 2025 | SYSTEM | (\$295,350.53) | |
| | | PG58-28H (BP-1) | | | 5 | Jul 16, 2025 | SYSTEM | \$295,350.53 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$2,271.49) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$2,271.49 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$2,271.49) | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$2,271.49 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$2,271.49) | |
| | | | | - Total | | | | (\$2,271.49) | |
| | | | Material - To | otal | | | | (\$2,271.49) | |
| | | | Other Item Adjustment | | 5 | Jul 16, 2025 | hessec2 | \$1,077.44 | AC Adjustment Line No. 0500 Installed Quantity = |
| | | | | | | | | | 12,675.80 (tons) @ 3.4% (Virgin) X 2.5 (difference) = \$1,077.44 |
| | | | | | 6 | Aug 4, 2025 | johnsm7 | \$2,126.19 | AC adjustment Line number: 0500 Install quantity: 25014.03 (tons) @3.4% (virgin) * 2.5 (diff) = \$2126.19 |
| | | | | | 7 | Aug 18, 2025 | johnsm7 | \$1,048.77 | AC Adjustment Line Number: 0500 Install Quantity: 12338.44 (tons) @3.4% (virgin) * 2.5 (diff) = \$1048.77 |
| | | | | ACAD - Tota | al | | | \$4,252.40 | |
| | | | Other Item | Adjustment - | Total | | | \$4,252.40 | |
| | 0500 - | Total | | | | | | \$1,980.91 | |
| | 0510 | MISC. | Material | | 5 | Jul 16, 2025 | SYSTEM | (\$69,768.75) | |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | \$69,768.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 6 | Aug 4, 2025 | SYSTEM | (\$207,412.50) | |
| | | | | | 6 | Aug 4, 2025 | SYSTEM | \$207,412.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | (\$291,821.25) | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$291,821.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsm7 overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | |
|---------|--------|---|--------------------|-----------------------------|-----------------|-----------------|----------------|--|--|--------------|---|--|
| JKR0249 | 0510 | MISC. | Material | | | | | | Estimate Exception 2 on the current Payment Estimate. | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$293,902.50) | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$293,902.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$293,902.50) | | | | |
| | | | | 9 | Sep 16, 2025 | SYSTEM | \$293,902.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | |
| | | | | 10 | Oct 1, 2025 | SYSTEM | (\$307,275.00) | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$307,275.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$293,902.50) | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$293,902.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user johnsm7 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | |
| | 0510 - | | | | | | | \$0.00 | | | | |
| | 0520 | D FURN & PLACE CONC MATL FOR FULL DEPTH | Material | Material | 3 | Jun 16, 2025 | SYSTEM | (\$115,000.00) | | | | |
| | | | | | 3 | Jun 16, 2025 | SYSTEM | \$115,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | |
| | | | | | 4 | Jul 1, 2025 | SYSTEM | (\$254,333.25) | | | | |
| | | | | | 4 | Jul 1, 2025 | SYSTEM | \$254,333.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | (\$347,658.25) | | | | |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | \$347,658.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | |
| | | | | | 6 | Aug 4, 2025 | SYSTEM | (\$347,658.25) | | | | |
| | | | | | 6 | Aug 4, 2025 | SYSTEM | \$347,658.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsm7 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | |
| | | | | | | | | 7 | Aug 18, 2025 | SYSTEM | (\$347,658.25) | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$347,658.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$412,325.00) | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$412,325.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$412,325.00) | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | \$412,325.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user johnsm7 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$422,375.00) | | | | |
| | | | | | | | 10 | Oct 1, 2025 | SYSTEM | \$422,375.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user johnsm7 overridding Payment Estimate Exception 15 on the current Payment Estimate. | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$422,375.00) | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|----------------|----------------|---|--|-------------|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|---|--|--|--|----|----------------|--------|-------------|
| JKR0249 | 0520 | FURN & PLACE CONC MATL FOR FULL DEPTH | Material | | 11 | Oct 16, 2025 | SYSTEM | \$422,375.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user johnsm7 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$422,375.00) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$422,375.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsm7 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 0520 - | | | | | | | \$0.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 0560 | DOWEL BAR (DRILLING, FURNISHING AND | Material | | 3 | Jun 16, 2025 | SYSTEM | (\$6,225.00) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | INST | | | 3 | Jun 16, 2025 | SYSTEM | \$6,225.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 4 | Jul 1, 2025 | SYSTEM | (\$13,506.25) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 4 | Jul 1, 2025 | SYSTEM | \$13,506.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | (\$18,218.75) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 5 | Jul 16, 2025 | SYSTEM | \$18,218.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | 6 | Aug 4, 2025 | SYSTEM | (\$18,218.75) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 6 | Aug 4, 2025 | SYSTEM | \$18,218.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | (\$18,218.75) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 7 | Aug 18, 2025 | SYSTEM | \$18,218.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsm7 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | (\$21,312.50) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 8 | Sep 2, 2025 | SYSTEM | \$21,312.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user johnsm7 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 9 | Sep 16, 2025 | SYSTEM | (\$21,312.50) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | 9 | Sep 16, 2025 | SYSTEM | \$21,312.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user johnsm7 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$22,275.00) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$22,275.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user johnsm7 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$22,275.00) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$22,275.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user johnsm7 overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$22,275.00) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 1 | | | | 12 | Nov 3, 2025 | SYSTEM | \$22,275.00 |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$22,275.00) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | (\$22,275.00) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | Material - To | otal | | | | (\$22,275.00) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|----------------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|-----------------------------|--|
| JKR0249 | 0560 - | Total | | | | | | (\$22,275.00) | |
| | 0570 | FURN & PLACE BIT. MATL FOR CL C PARTIAL | Other Item Adjustment | ACAD | 4 | Jul 1, 2025 | hessec2 | \$7.98 | AC Adjustment Line No. 0570 Installed Quantity |
| | | | | | | | | | 93.60 (tons) X 2.5 (diff) @ 3.41 (virgin) = \$7.98 |
| | | | | | 5 | Jul 16, 2025 | hessec2 | \$35.48 | AC Adjustment Line No. 0570 Installed Quantity = |
| | | | | ACAD - Tota | | | | 040.40 | 417.40 (tons) @ 3.4% (virgin) X 2.5 (difference) = \$35.48 |
| | | | Othor Itom | | | | | \$43.46 \$43.46 | |
| | 0570 - | Total | Other item? | Adjustment - | TOtal | | | \$43.46 | |
| | 0590 | CONSTRUCTION SIGNS | Material | | 2 | Jun 2, 2025 | SYSTEM | (\$3,458.00) | |
| | | | | | 2 | Jun 2, 2025 | SYSTEM | \$3,458.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 3 | Jun 16, 2025 | SYSTEM | (\$3,458.00) | |
| | | | | | 3 | Jun 16, 2025 | SYSTEM | \$3,458.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0590 - | Total | | | | | | \$0.00 | |
| | 0630 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / | Material | | 2 | Jun 2, 2025 | SYSTEM | (\$9,500.00) | |
| | | | | | 2 | Jun 2, 2025 | SYSTEM | \$9,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | RETAINED | | | 3 | Jun 16, 2025 | SYSTEM | (\$9,500.00) | |
| | | | | | 3 | Jun 16, 2025 | SYSTEM | \$9,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0630 - 0650 | Total PREF THERMO | Material | | 10 | Oct 1, 2025 | SYSTEM | \$0.00 (\$422.40) | |
| | | PAVMT MARKING, 12 IN WHITE | | | 10 | Oct 1, 2025 | SYSTEM | \$422.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user johnsm7 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$528.00) | · |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$528.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user johnsm7 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0650 | Total | | | | | | \$0.00 | |
| | 0660 | PREF THERMO PVMT MARK, 24 IN YELLOW | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$1,430.00) | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$1,430.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user johnsm7 overridding Payment Estimate Exception 29 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$1,787.50) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$1,787.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user johnsm7 overridding Payment Estimate Exception 29 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | |
|---------|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|--|--|--|--|--|----|-----------------|--------|-------------|
| JKR0249 | 0660 | PREF THERMO PVMT MARK, 24 IN YELLOW | Material - To | otal | | | | \$0.00 | | | | | | | | | | |
| | 0660 - | Total | | | | | | \$0.00 | | | | | | | | | | |
| | 0670 | PREF THERMO PVMT MARK, LT/RT ARROW | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$400.00) | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$400.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user johnsm7 overridding Payment Estimate Exception 30 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$500.00) | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user johnsm7 overridding Payment Estimate Exception 30 on the current Payment Estimate. | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | |
| | 0670 - | Total | | | | | | \$0.00 | | | | | | | | | | |
| | 0680 | 4 IN. YELLOW HIGH BUILD | Material | | 9 | Sep 16, 2025 | SYSTEM | (\$16,369.01) | | | | | | | | | | |
| | | WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | | | 9 | Sep 16, 2025 | SYSTEM | \$16,369.01 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$16,369.01) | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$16,369.01 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user johnsm7 overridding Payment Estimate Exception 34 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$20,461.26) | | | | | | | | | | |
| | | | | | | | | | | | | | | | 11 | Oct 16, 2025 | SYSTEM | \$20,461.26 |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$20,461.26) | | | | | | | | | | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$20,461.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user johnsm7 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$20,461.26) | | | | | | | | | | |
| | | | | - Total | | | | (\$20,461.26) | | | | | | | | | | |
| | | | Material - To | otal | | | | (\$20,461.26) | | | | | | | | | | |
| | | | Other Item Adjustment | REFL | 11 | Oct 16, 2025 | johnsm7 | (\$562.81) | Reflectivity Adjustment 0680 - total \$21,464.75 * (80%) 22.6% = -\$971.07 0680 - total \$21,464.75 * (100%) 39.3% = \$0 0680 - total \$21,464.75 * (105%) 38.0% = \$408.26 | | | | | | | | | |
| | | | | REFL - Tota | ıl | | | (\$562.81) | | | | | | | | | | |
| | | | Other Item | Adjustment - Total | | | (\$562.81) | | | | | | | | | | | |
| | 0680 - | Total | | | | | | (\$21,024.07) | | | | | | | | | | |
| | 0690 | 6 IN. WHITE HIGH BUILD | Material | | 9 | Sep 16, 2025 | SYSTEM | (\$38,101.65) | | | | | | | | | | |
| | | WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | | | 9 | Sep 16, 2025 | SYSTEM | \$38,101.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user johnsm7 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | (\$38,101.65) | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$38,101.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user johnsm7 overridding Payment Estimate Exception 38 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$47,045.96) | | | | | | | | | | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$47,045.96 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user johnsm7 overridding Payment Estimate Exception 38 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 12 | Nov 3, | SYSTEM | (\$47,045.96) | | | | | | | | | | |



| roject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|------|--|--------------------------|-----------------------------|----------------|------------------------|------------------|------------------------------|---|
| R0249 | 0690 | 6 IN. WHITE HIGH BUILD | Material | | | 2025 | | | |
| | | WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | | | 12 | Nov 3, 2025 | SYSTEM | \$47,045.96 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user johnsm7 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$47,045.96) | |
| | | | | - Total | | | | (\$47,045.96) | |
| | | | Material - To | otal | | | | (\$47,045.96) | |
| | | | Other Item Adjustment | REFL | 11 | Oct 16, 2025 | johnsm7 | \$1,965.82 | Reflectivity Adjustment 0690 - total \$47,045.96 * (100%) 16.4% = \$0 0690 - total \$47,045.96 * (105%) 83.6% = \$1965.82 |
| | | | | REFL - Tota | ıl | | | \$1,965.82 | |
| | | | Other Item | Adjustment - | Total | | | \$1,965.82 | |
| | 0690 | - Total | | | | | | (\$45,080.14) | |
| | 0700 | 6 IN. YELLOW HIGH BUILD | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$4,459.31) | |
| | | WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | | | 10 | Oct 1, 2025 | SYSTEM | \$4,459.31 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user johnsm7 overridding Payment Estimate Exception 40 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$5,574.14) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$5,574.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user johnsm7 overridding Payment Estimate Exception 40 on the current Payment Estimate. |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$5,574.14) | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$5,574.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user johnsm7 overridding Payment Estimate Exception 26 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$5,574.14) | |
| | | | | - Total | | | | (\$5,574.14) | |
| | | | Material - To | otal | | | | (\$5,574.14) | |
| | | | Other Item Adjustment | REFL | 11 | Oct 16, 2025 | johnsm7 | (\$154.02) | Reflectivity Adjustment 0700- total \$5,874.18 * (80%) 22.6% = -\$265.75 0700 - total \$5,874.18 * (100%) 39.3% = \$0 0700 - total \$5,874.18* (105%) 38.0% = \$111.73 |
| | | | | REFL - Total | | | | (\$154.02) | |
| | | | Other Item | Adjustment - | Total | | | (\$154.02) | |
| | 0700 | - Total | | | | | | (\$5,728.16) | |
| | 0710 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$811.44) | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$811.44 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user johnsm7 overridding Payment Estimate Exception 42 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$1,014.30) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$1,014.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user johnsm7 overridding Payment Estimate Exception 42 on the current Payment Estimate. |
| | | | | | 12 | Nov 3, | SYSTEM | (\$1,014.30) | |
| | | | | | 12 | 2025 | | | |
| | | | | | 12 | 2025 Nov 3, 2025 | SYSTEM | \$1,014.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | | Nov 3, | SYSTEM SYSTEM | (\$1,014.30) | Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment |
| | | | | - Total | 12 | Nov 3, 2025 | | | Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment |
| | | | Material - To | | 12 | Nov 3, 2025 | | (\$1,014.30) | Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment |
| | 0710 | - Total | Material - To | | 12 | Nov 3, 2025 | | (\$1,014.30) (\$1,014.30) | Estimate Item Adjustment (0019) due to user johnsm7 overridding Payment |



| | | 5 | A 11 | 011 | | 0 | 0 | | D 1 |
|------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| ject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
| 0249 | 0780 | MGS GUARDRAIL | Material | | 10 | Oct 1, 2025 | SYSTEM | \$25,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$55,687.50) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$55,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user johnsm7 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$65,700.00) | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$65,700.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$65,700.00) | |
| | | | | - Total | | | | (\$65,700.00) | |
| | | | Material - T | otal | | | | (\$65,700.00) | |
| | 0780 - | Total | | | | | | (\$65,700.00) | |
| | 0790 | MGS GUARDRAIL, 8 FT. POSTS, 6 | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$41,300.00) | |
| | | FT 3 IN | | | 10 | Oct 1, 2025 | SYSTEM | \$41,300.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user johnsm7 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | (\$91,081.25) | |
| | | | | | 11 | Oct 16, 2025 | SYSTEM | \$91,081.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user johnsm7 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | (\$101,421.00) | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$101,421.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$101,421.00) | |
| | | | | - Total | | | | (\$101,421.00) | |
| | | | Material - T | otal | | | | (\$101,421.00) | |
| | 0790 - | Total | | | | | | (\$101,421.00) | |
| | 0800 | MGS BRIDGE APP. TRANS SEC (REG/NO CURB) | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$14,800.00) | |
| | | | | | 10 | Oct 1, 2025 | SYSTEM | \$14,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user johnsm7 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0800 - | Total | | | | | | \$0.00 | |
| | 0820 | TYPE A CRASHWORTHY | Material | | 10 | Oct 1, 2025 | SYSTEM | (\$33,500.00) | |
| | | END TERMINAL (MASH) | | | 10 | Oct 1, 2025 | SYSTEM | \$33,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user johnsm7 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | Mate | | | | | | \$0.00 | |
| | 0820 - | Total | | erial - Total | | | | \$0.00 | |
| | | TYPE 3 OBJECT MARKER | Material | | 12 | Nov 3, 2025 | SYSTEM | (\$110.00) | |
| | | WAINLIN | | | 12 | Nov 3, 2025 | SYSTEM | \$110.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user johnsm7 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$110.00) | |
| | | | | - Total | | | | (\$110.00) | |
| | | | | | | | | | |





| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|-----------------|--|--------------------|-----------------------------|----------------|-----------------|---------------|------------|---|
| JKR0249 | 0830 | TYPE 3 OBJECT MARKER | Material - To | otal | | | | (\$110.00) | |
| | 0830 - | Total | | | | | | (\$110.00) | |
| | 0840 | 2 IN. PSST POST - 12 GA. | Material | | 12 | Nov 3, 2025 | SYSTEM | (\$168.00) | |
| | | | | | 12 | Nov 3, 2025 | SYSTEM | \$168.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user johnsm7 overridding Payment Estimate Exception 32 on the current Payment Estimate. |
| | | | | | 13 | Nov 4, 2025 | SYSTEM | (\$168.00) | |
| | | | | - Total | | | | (\$168.00) | |
| | | | Material - To | otal | | | | (\$168.00) | |
| | 0840 - | Total | | | | | | (\$168.00) | |
| | 0850 | DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. | Material | | 12 | Nov 3, 2025 | SYSTEM | (\$150.00) | |
| | | | | | | Nov 3, 2025 | SYSTEM | \$150.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user johnsm7 overridding Payment Estimate Exception 34 on the current Payment Estimate. |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0850 - | Total | | | | | | \$0.00 | |
| JKR0249 | KR0249 - Total | | | | | | | | |
| Overall - | overall - Total | | | | | | | | |



Contract Adjustments for Contract - 250314-C01

| Estimate Number | Project | Adjustment Type | Other Adjustment Type | Adjustment Amount | Adjustment Percentage by Project | Created Date | Created By | Comments |
|--------------------|---------|------------------------------|--------------------------|----------------------|-------------------------------------|-----------------------|---------------|--|
| 7 | JKR0249 | Other Contract Adjustment | ABIR | \$776.02 | 100 | August 18, 2025 | johnsm7 | EB Lane 46.428 to 47.740 WB Lane 173.549 to 174.776 Total = \$776.02 |
| | | Other Contract Adjustment | ABIR | \$8,901.74 | 100 | August 18, 2025 | johnsm7 | EB Lane 33.941 to 40.600 = \$8,901.74 |
| | | Other Contract Adjustment | ABIR | \$9,637.71 | 100 | August 18, 2025 | johnsm7 | WB Driving Lane 180.768 to 187.427 WB Passing Lane 180.768 to 187.427 Total = \$9637.71 |
| | | Other Contract Adjustment | ABIR | \$11,259.05 | 100 | August 18, 2025 | johnsm7 | WB Driving Lane 172.382 to 180.472 WB Passing Lane 172.382 to 180.472 Total = \$11259.05 |
| | | Other Contract Adjustment | ABIR | \$12,590.90 | 100 | August 18, 2025 | johnsm7 | EB Lane 40.880 to 48.977 = \$12590.90 |
| 7 - Total | | | | \$43,165.42 | | | | |
| 9 | J3P3158 | Other Contract Adjustment | ABIR | \$25,362.03 | 100 | September 16, 2025 | johnsm7 | WB Lane 152.784 to 171.374 Total = \$25,362.03 |
| | | Other Contract Adjustment | ABIR | \$25,520.47 | 100 | September 16, 2025 | johnsm7 | EB Lane 49.978 to 68.570 Total = \$25,520.47 |
| 9 - Total | | | | \$50,882.50 | | | | |
| Overall - Total | | | | \$94,047.92 | | | | |

Revision 5/29/2025 Page 29 of 29