\$108,852.92

\$108,852.92



#### Missouri Department of Transportation **Contractor's Pay Estimate Summary**

Pay Estimate Created Date: October 1, 2025

Progress Estimate Number	Contract ID	250314-C03	Pay Period Start	September 16, 2025	Original Contract Amount	\$1,904,946.53
3	Prime Contractor	Leavenworth Excavating & Equipment Company, Inc.	Pay Period End	September 30, 2025	Net Change Order Amount	\$16,978.56
					Current Contract Amount	\$1,921,925.09

Approval Date		By User
October 1, 2025	Generated and Approved (and should be considered Draft) at the Project Office Level by	jamesc2
October 1, 2025	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	ilesb1
October 3, 2025	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion D	Date	% of Current Contract Amount Complete		
September 1, 2026	September 1, 2026	2026		23.38%		
Co	ontract Informational Dates			Milestones		

No Milestones Exist for Contract

**Date Description** Acceptance Date Awarded Date April 2, 2025 April 2, 2025 March 14, 2025 Letting Date March 14, 2025 Notice to Proceed Date May 5, 2025 May 5, 2025 Work Began Date

Contract Total Pay For Estimate No. 3											
		This Estimate	Previous	To Date							
250314-C03											
	Total Posted Items Pay	\$108,852.92	\$340,516.54	\$449,369.46							
	Gross Item Adjustments	\$57.75	\$111.88	\$169.63							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
	•		\$340,628.42	\$449,539.09							

**Contract Total Payable This Estimate:** \$108,910.67

<u>Items</u>	Paid	This	Estimat	e Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JKR0134	0030	2035000	UNCLASSIFIED EXCAVATION	CUYD	\$25.000	645.700	\$16,142.50
	0040	2035500	EMBANKMENT IN PLACE	CUYD	\$37.580	411.500	\$15,464.17
	0050	2036000	COMPACTING EMBANKMENT	CUYD	\$5.000	1,467.700	\$7,338.50
	0060	2063000	CLASS 3 EXCAVATION	CUYD	\$20.000	38	\$760.00
	0160	6161005	CONSTRUCTION SIGNS	SQFT	\$7.250	39	\$282.75
	0180	6161025	CHANNELIZER (TRIM-LINE)	EA	\$24.000	211	\$5,064.00
	0190	6161030	TYPE 3 MOVEABLE BARRICADE	EA	\$230.000	25	\$5,750.00
	0360	7261018	18 IN. PIPE GROUP A	LF	\$89.000	84	\$7,476.00
	0380	7269903	MISC.18 IN. CLASS IV REINFORCED CONCRETE PIPE	LF	\$105.000	117	\$12,285.00
	0420	7329902	MISC.18 IN. PRECAST CONCRETE FLARED END SECTION	EA	\$2,060.000	6	\$12,360.00
	0430	7339901	MISC.MEDIAN CULVERT REPAIR	LS	\$20,050.000	1	\$20,050.00
	5001	6161033	DIRECTION INDICATOR BARRICADE	EA	\$115.000	28	\$3,220.00
	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	EA	\$95.000	28	\$2,660.00

### Contract Adjustments This Estimate

Project JKR0134 - Total

Overall - Total

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 9/2/2025 Page 1 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2025

Progress Estimate Number	Contract ID	250314-C03	Pay Period Start	September 16, 2025	Original Contract Amount	\$1,904,946.53
3	Prime Contractor	Leavenworth Excavating & Equipment Company, Inc.	Pay Period End	September 30, 2025	Net Change Order Amount	\$16,978.56
					Current Contract	\$1,921,925.09

						Amount	Ψ1,321,320.03	
ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
)134	0030	UNCLASSIFIED EXCAVATION	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	645.70000	\$0.05	\$33.12
	0040	EMBANKMENT IN PLACE	Material			-411.50000	\$37.58	(\$15,464.17)
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user jamesc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	411.50000	\$37.58	\$15,464.17
	0040	EMBANKMENT IN PLACE	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	411.50000	\$0.06	\$24.63
	0050	COMPACTING EMBANKMENT	Material			-1,467.70000	\$5.00	(\$7,338.50)
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user jamesc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1,467.70000	\$5.00	\$7,338.50
	0140	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	Material			-2	\$1,500.00	(\$3,000.00)
	0140	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user jamesc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	2	\$1,500.00	\$3,000.00
	0160	CONSTRUCTION SIGNS	Material			-876	\$7.25	(\$6,351.00)
	0160	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user jamesc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	876	\$7.25	\$6,351.00
	0180	CHANNELIZER (TRIM-LINE)	Material			-295	\$24.00	(\$7,080.00)
	0180	CHANNELIZER (TRIM-LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user jamesc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	295	\$24.00	\$7,080.00
	0190	TYPE 3 MOVEABLE BARRICADE	Material			-39	\$230.00	(\$8,970.00)
	0190	TYPE 3 MOVEABLE BARRICADE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	39	\$230.00	\$8,970.00
	0200	FLASHING ARROW PANEL	Material			-2	\$1,350.00	(\$2,700.00)
	0200	FLASHING ARROW PANEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user jamesc2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	2	\$1,350.00	\$2,700.00
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material			-4	\$4,200.00	(\$16,800.00)
	0210	CHANGEABLE MESSAGE SIGN WITH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	4	\$4,200.00	\$16,800.00

Revision 9/2/2025 Page 2 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2025

September 16, 2025 **Pay Period Original Contract Progress** 250314-C03 \$1,904,946.53 **Contract ID Estimate Number** Start Amount Prime Leavenworth Excavating & Equipment Company, Pay Period September 30, **Net Change Order** \$16,978.56 Contractor End 2025 Amount **Current Contract** \$1,921,925.09 Amount

Project Number   No.   Item Description   Adjustment Type   Adjustment Type   Adjustment Type   Adjustment Type   Adjustment Type   Adjustment (0010) due to user jamesc2 overridding Payment Estimate Exception 10 on the current Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 13 on the current Payment Estimate	
INTERFACE, CONTRACTOR FURNISHED / RETAINED  Overridding Payment Estimate Exception 10 on the current Payment Estimate.  Description of the current Payment Estimate on the current Payment Estimate.  Description on the current Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Item Adjustment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Item Adjustment Estimate Exception 13 on the current Payment Estimate Exception 13 on the curr	Adjustment amount
BARRIER, CONTRACTOR FURNISHED / RETAINED  0220 TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  0360 18 IN. PIPE GROUP A Material  15 Inis adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Exception 13 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 13	
BARRIER, CONTRACTOR FURNISHED / RETAINED  generated Material Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Exception 11 on the current Payment Estimate.  360 18 IN. PIPE GROUP A  Material  This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Exception 12 on the current Payment Estimate.  56 \$120.00  This adjustment offsets the original system- generated Material Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Exception 13 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 13	(\$29,600.00)
18 IN. PIPE GROUP A Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Exception 12 on the current Payment Estimate.  5 SEDIMENT TRAP ROCK Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	\$29,600.00
generated Material Payment Estimate Item Adjustment (0012) due to user jamesc2 overridding Payment Estimate Exception 12 on the current Payment Estimate.  6 \$120.00  SEDIMENT TRAP ROCK Material  This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	(\$7,476.00)
O460 SEDIMENT TRAP ROCK  Material  This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	\$7,476.00
generaled Material Payment Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	(\$720.00)
0470 ALTERNATE DITCH CHECK Material -109 \$8.31	\$720.00
	(\$905.79)
0470 ALTERNATE DITCH CHECK  Material  This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user jamesc2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	\$905.79
5001 DIRECTION INDICATOR Material -28 \$115.00	(\$3,220.00)
DIRECTION INDICATOR BARRICADE  Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user jamesc2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	\$3,220.00
5002 SEQUENTIAL FLASHING Material -28 \$95.00 WARNING LIGHT	(\$2,660.00)
5002 SEQUENTIAL FLASHING WARNING LIGHT  Material  This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user jamesc2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	\$2,660.00
Total Control of the	\$57.75

Revision 9/2/2025 Page 3 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Informa	ation					
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work						
JKR0134	FAF-50-2 (72)	J-Turns and new crossovers	50	JOHNSON	at Powell Garden, NW	owell Garden, NW 1601st Road and NW 550th Road near Pittsville						
Totals b	y Job Nu	ımbers										
JKR0134		l Item Pay Item Adjustmo		Item Pay	This Estimate \$108,852.92 \$57.75 <b>\$108,910.67</b>	Previous \$340,516.54 \$111.88 \$340,628.42	To Date \$449,369.46 \$169.63 \$449,539.09					
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 5/29/2025 Page 4 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Feriod			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	QC/QA Compaction test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	QC/QA Compaction test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6122017, Project Item Line Number 0140, Material Set 612201796, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6161005, Project Item Line Number 0160, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6161025, Project Item Line Number 0180, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6161030, Project Item Line Number 0190, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6161033, Project Item Line Number 5001, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6161040, Project Item Line Number 0200, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6161055, Project Item Line Number 5002, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6161099, Project Item Line Number 0210, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 6173600D, Project Item Line Number 0220, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Certifications are on SharePoint. Test need entered	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 7261018, Project Item Line Number 0360, Material Set 726101896, Material 1026CPRCC3.018 - Reinf Conc Culv Pipe Cl3 18" (450 mm), Acceptance Action Generic 1026CPRCC3.018 is insufficient.	District Materials needs to enter test	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 8061004, Project Item Line Number 0460, Material Set 806100496, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Visual test need enter	jamesc2	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0134, Item 8061006, Project Item Line Number 0470, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Visual test need enter	jamesc2	Overridden

Revision 5/29/2025 Page 5 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

10tc. 1 0	sieu Qua	illues and	values	are base	d on Report Generated date and can differ from the poste	amount	at the th	ne the Estin	iate was	Generaled		
Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
250314-	JKR0134	0001	0010	1081000	SIGNET DBE REPORTING	1.00	0.00	1.00	LS	1.00	\$1,000.00	\$1,000.00
C03		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$151,645.00	\$75,822.50
		0001	0030	2035000	UNCLASSIFIED EXCAVATION	3,944.00	0.00	3,944.00	CUYD	2,826.50	\$25.00	\$70,662.50
		0001	0040	2035500	EMBANKMENT IN PLACE	1,373.00	0.00	1,373.00	CUYD	411.50	\$37.58	\$15,464.17
		0001	0050	2036000	COMPACTING EMBANKMENT	2,588.00	0.00	2,588.00	CUYD	1,467.70	\$5.00	\$7,338.50
		0001	0060	2063000	CLASS 3 EXCAVATION	57.00	0.00	57.00	CUYD	38.00	\$20.00	\$760.00
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	13,564.00	0.00	13,564.00	SQYD	0.00	\$16.50	\$0.00
		0001	0800	4010150	TYPE A2 SHOULDER	1,007.00	0.00	1,007.00	SQYD	0.00	\$45.70	\$0.00
		0001	0090	4019905	MISC.OPTIONAL PAVEMENT	9,639.00	0.00	9,639.00	SQYD	0.00	\$44.03	\$0.00
		0001	0100	4019905	MISC.OPTIONAL SHOULDER	2,490.00	0.00	2,490.00	SQYD	0.00	\$44.03	\$0.00
		0001	0110	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	428.00	0.00	428.00	SQYD	0.00	\$78.60	\$0.00
		0001	0120	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	0.00	\$1,615.00	\$0.00
		0001	0130	6083003	3 IN. CONCRETE MEDIAN STRIP	42.00	0.00	42.00	SQYD	0.00	\$100.00	\$0.00
		0001	0140	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0150	6122020	REPLACEMENT SAND BARREL	2.00	0.00	2.00	EA	0.00	\$300.00	\$0.00
		0001	0160	6161005	CONSTRUCTION SIGNS	837.00	39.25	876.25	SQFT	876.00	\$7.25	\$6,351.00
		0001	0170	6161010	RELOCATED SIGNS	7.00	0.00	7.00	SQFT	0.00	\$15.00	\$0.00
		0001	0180	6161025	CHANNELIZER (TRIM-LINE)	84.00	211.00	295.00	EA	295.00	\$24.00	\$7,080.00
		0001	0190	6161030	TYPE 3 MOVEABLE BARRICADE	14.00	25.00	39.00	EA	39.00	\$230.00	\$8,970.00
		0001	0200	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,350,00	\$2,700.00
		0001	0210	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	4.00	0.00	4.00	EA	4.00	\$4,200.00	\$16,800.00
		0001	0220	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	800.00	0.00	800.00	LF	800.00	\$37.00	\$29,600.00
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$188,000.00	\$141,000.00
		0001	0240	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0250	6191000	PAVEMENT EDGE TREATMENT	8,798.00	0.00	8,798.00	LF	0.00	\$6.10	\$0.00
		0001	0260	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	254.00	0.00	254.00	LF	0.00	\$27.00	\$0.00
		0001	0270	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	12.00	0.00	12.00	EA	0.00	\$275.00	\$0.00
		0001	0280	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	4.00	0.00	4.00	EA	0.00	\$55.00	\$0.00
		0001	0290	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	175.00	0.00	175.00	LF	0.00	\$2.40	\$0.00
		0001	0300	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,765.00	0.00	5,765.00	LF	0.00	\$0.38	\$0.00
		0001	0310	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,874.00	0.00	7,874.00	LF	0.00	\$0.38	\$0.00
		0001	0320	6206000C 6207001	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  PAVEMENT MARKING REMOVAL	93.00	0.00	93.00	LF LF	0.00	\$2.40 \$3.50	\$0.00 \$0.00
		0001	0340	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00		\$3.144.00
		0001	0350	7261015	15 IN. PIPE GROUP A	107.00	0.00	107.00	LF	0.25	\$12,576.00	\$3,144.00
		0001	0360	7261015	18 IN. PIPE GROUP A	84.00	0.00	84.00	LF	84.00	\$89.00	\$7,476.00
		0001	0370	7269902	MISC.23 IN. X 14 IN. PRECAST CONCRETE ELLIPTICAL FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$3,070.00	\$0.00
		0001	0380	7269903	MISC.18 IN. CLASS IV REINFORCED CONCRETE PIPE	117.00	0.00	117.00	LF	117.00	\$105.00	\$12,285.00
		0001	0390	7269913	MISC.23 IN. X 14 IN. CLASS IV REINFORCED CONCRETE ELLIPTICAL PIPE	51.00	0.00	51.00	FT	0.00	\$199.00	\$0.00
		0001	0400	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	3.00	0.00	3.00	EA	0.00	\$1,715.00	\$0.00
		0001	0410	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$2,155.00	\$0.00
		0001	0420	7329902	MISC.18 IN. PRECAST CONCRETE FLARED END SECTION	6.00	0.00	6.00	EA	6.00	\$2,060.00	\$12,360.00
		0001	0430	7339901	MISC.MEDIAN CULVERT REPAIR	1.00	0.00	1.00	LS	1.00	\$20,050.00	\$20,050.00
		0001	0440	8051000A	SEEDING - COOL SEASON GRASSES	2.50	0.00	2.50	ACRE	0.00	\$1,800.00	\$0.00
		0001	0450	8061003	SEDIMENT TRAP EXCAVATION	12.00	0.00	12.00	CUYD	0.00	\$35.00	\$0.00
		0001	0460	8061004	SEDIMENT TRAP ROCK	12.00	0.00	12.00	CUYD	6.00	\$120.00	\$720.00
		0001	0470	8061006	ALTERNATE DITCH CHECK	1,910.00	0.00	1,910.00	LF	109.00	\$8.31	\$905.79
		0001	0480	8061016	SEDIMENT REMOVAL	210.00	0.00	210.00	CUYD	0.00	\$14.55	\$0.00
		0001	0490	8061019	SILT FENCE	739.00	0.00	739.00	LF	0.00	\$5.10	\$0.00
		0001	0500	8064130	TYPE 3 TURF REINFORCEMENT MAT	9,962.00	0.00	9,962.00	SQYD	0.00	\$5.10	\$0.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

tract D	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
314-	JKR0134	0001	0510	8064140	TYPE 3B EROSION CONTROL BLANKET	7,317.00	0.00	7,317.00	SQYD	0.00	\$1.65	\$0.00
		0020	0520	9011010	RELOCATED POLE	1.00	0.00	1.00	EA	0.00	\$2,005.00	\$0.0
		0020	0530	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	1.00	0.00	1.00	EA	0.00	\$3,285.00	\$0.0
		0020	0540	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	6.00	0.00	6.00	EA	0.00	\$3,210.00	\$0.0
		0020	0550	9011115	BRACKET ARM, 15 FT. OR 4.6 M	8.00	0.00	8.00	EA	0.00	\$1,355.00	\$0.0
		0020	0560	9011312	LUMINAIRE, LED-B	8.00	0.00	8.00	EA	0.00	\$470.00	\$0.0
		0020	0570	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	2.00	0.00	2.00	EA	0.00	\$3,280.00	\$0.0
		0020	0580	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	51.00	0.00	51.00	LF	0.00	\$43.00	\$0.0
		0020	0590	9014004	CONDUIT, 4 IN. RIGID, PUSHED	602.00	0.00	602.00	LF	0.00	\$24.00	\$0.0
		0020	0600	9015010	TRENCHING TYPE I	4,143.00	0.00	4,143.00	LF	0.00	\$3.40	\$0.0
		0020	0610	9016110	PULL BOX, PREFORMED CLASS 1	13.00	0.00	13.00	EA	0.00	\$1,280.00	\$0.0
		0020	0620	9017002	CABLE, 2 AWG 1 CONDUCTOR	230.00	0.00	230.00	LF	0.00	\$8.25	\$0.0
		0020	0630	9017006	CABLE, 6 AWG 1 CONDUCTOR	4,120.00	0.00	4,120.00	LF	0.00	\$5.90	\$0.0
		0020	0640	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,000.00	0.00	1,000.00	LF	0.00	\$4.85	\$0.0
		0020	0650	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	840.00	0.00	840.00	LF	0.00	\$1.20	\$0.0
		0020	0660	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	7.00	0.00	7.00	EA	0.00	\$1,305.00	\$0.0
		0020	0670	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	2.00	0.00	2.00	EA	0.00	\$3,285.00	\$0.0
		0040	0680	9031010	CONCRETE FOOTINGS, EMBEDDED	15.00	0.00	15.00	CUYD	0.00	\$1,100.00	\$0.0
		0040	0690	9031220	PIPE POSTS	9,130.00	0.00	9,130.00	LB	0.00	\$5.00	\$0.0
		0040	0700	9031270A	2 IN. PSST POST - 12 GA.	280.00	0.00	280.00	LF	0.00	\$20.00	\$0.0
		0040	0710	9031274	CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.	17.00	0.00	17.00	EA	0.00	\$185.00	\$0.0
		0040	0720	9031280	2.5 IN. PSST POST - 12 GA.	88.00	0.00	88.00	LF	0.00	\$21.00	\$0.0
		0040	0730	9031285	CONCRETE POST ANCHOR FOR 2.5 IN. PSST 7 GA.	5.00	0.00	5.00	EA	0.00	\$200.00	\$0.0
		0040	0740	9035004A	SH-FLAT SHEET	793.00	0.00	793.00	SQFT	0.00	\$17.00	\$0.0
		0040	0750	9035069A	SHF-FLAT SHEET FLUORESCENT	36.00	0.00	36.00	SQFT	0.00	\$18.50	\$0.0
		0001	5001	6161033	DIRECTION INDICATOR BARRICADE	0.00	28.00	28.00	EA	28.00	\$115.00	\$3,220.0
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	28.00	28.00	EA	28.00	\$95.00	\$2,660.0
	Project Ji	KR0134 <u>-</u> To	otal Va <u>lu</u>	e Posted to D	Date as of Report Generated Date							\$449,369.4
314-C	03 Overall	l - Total Val	ue Poste	d to Date as	of Report Generated Date							\$449,369.4

Revision 5/29/2025 Page 7 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JKR0134

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2035000	UNCLASSIFIED EXCAVATION	9/29/25	9/30/25	1	645.70	CUYD	550th Turn lane	0+00		9+60.91		
0040	2035500	EMBANKMENT IN PLACE	9/29/25	9/30/25	1	411.50	CUYD	West j turn, 1601 turn lanes, Powell Gardens turn lane	8+06.21		6+42.41		
0050	2036000	COMPACTING EMBANKMENT	9/29/25	9/30/25	1	1,467.70	CUYD		8+06.21		6+42.41		
0060	2063000	CLASS 3 EXCAVATION	9/30/25	10/1/25	1	38.00	CUYD		2+29.61		5+65.06		
0160	6161005	CONSTRUCTION SIGNS	9/17/25	9/30/25	1	39.00	SQFT		294+20		192+20		
0180	6161025	CHANNELIZER (TRIM-LINE)	9/17/25	9/30/25	1	211.00	EA		294+20		192+20		
0190	6161030	TYPE 3 MOVEABLE BARRICADE	9/17/25	9/30/25	1	25.00	EA		294+20		192+20		
0360	7261018	18 IN. PIPE GROUP A	9/17/25	9/30/25	1	84.00	LF	West J turn	0+18.79		0+50.15		
0380	7269903	MISC. RIGID PIPE CULVERT	9/22/25	9/29/25	1	117.00	LF	Powell Gardens, 1601 turn lanes	0+18.79		5+65.06		
0420	7329902	MISC. FLARED END SECTIONS	9/30/25	10/1/25	1	6.00	EA	Powell Turn lane, 1601 turn lanes	2+29.61		5+65.06		
0430	7339901	MISC.	9/26/25	9/30/25	1	1.00	LS	Between 1601 and Powell Gardens	217+75		217+75		
5001	6161033	DIRECTION INDICATOR BARRICADE	9/17/25	9/30/25	1	28.00	EA		294+20		192+20		
5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	9/17/25	9/30/25	1	28.00	EA		294+20	192+20			

Revision 6/5/2025 Page 8 of 12



## Line Item Adjustments by Estimate

Contract ID: 250314-C03

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
JKR0134	0030	UNCLASSIFIED EXCAVATION	Price FUEL		2	Sep 16, 2025	SYSTEM	\$111.88	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					3	Oct 1, 2025	SYSTEM	\$33.12	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$145.00			
			Price FUEL	- Total				\$145.00			
	0030 -	Total						\$145.00			
	0040	EMBANKMENT IN PLACE	Material		3	Oct 1, 2025	SYSTEM	(\$15,464.17)			
					3	Oct 1, 2025	SYSTEM	\$15,464.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Price FUEL		3	Oct 1, 2025	SYSTEM	\$24.63	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$24.63			
			Price FUEL	- Total				\$24.63			
	0040 -	Total						\$24.63			
	0050	COMPACTING EMBANKMENT	Material		3	Oct 1, 2025	SYSTEM	(\$7,338.50)			
					3	Oct 1, 2025	SYSTEM	\$7,338.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jamesc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0050 -	Total						\$0.00			
	0140	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	ENUATOR 65 (SAND		2	Sep 16, 2025	SYSTEM	(\$3,000.00)			
							2	Sep 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
							3	Oct 1, 2025	SYSTEM	(\$3,000.00)	
					3	Oct 1, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jamesc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				- Total							
			Material - To	otal				\$0.00			
	0140 -	Total						\$0.00			
	0160	CONSTRUCTION SIGNS	Material		2	Sep 16, 2025	SYSTEM	(\$6,068.25)			
							2	2	Sep 16, 2025	SYSTEM	\$6,068.25
					3	Oct 1, 2025	SYSTEM	(\$6,351.00)			
					3	Oct 1, 2025	SYSTEM	\$6,351.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0160 -	Total						\$0.00			
	0180	CHANNELIZER (TRIM-LINE)	Material		2	Sep 16, 2025	SYSTEM	(\$2,016.00)			
					2	Sep 16, 2025	SYSTEM	\$2,016.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jamesc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.		



## Line Item Adjustments by Estimate

Contract ID: 250314-C03

oject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
,			Туре	Adjustment Type		Date	Ву		
0134	0180	CHANNELIZER (TRIM-LINE)	Material		3	Oct 1, 2025	SYSTEM	\$7,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user jamesc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0180 -	Total						\$0.00	
	0190	TYPE 3 MOVEABLE	Material		2	Sep 16, 2025	SYSTEM	(\$3,220.00)	
		BARRICADE			2	Sep 16, 2025	SYSTEM	\$3,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jamesc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Oct 1, 2025	SYSTEM	(\$8,970.00)	
					3	Oct 1, 2025	SYSTEM	\$8,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
	0200	FLASHING ARROW PANEL	Material		2	Sep 16, 2025	SYSTEM	(\$2,700.00)	
					2	Sep 16, 2025	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc2 overridding Paymen Estimate Exception 5 on the current Payment Estimate.
					3	Oct 1, 2025	SYSTEM	(\$2,700.00)	
					3	Oct 1, 2025	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc2 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
								φυ.υυ	
			Material - To	otal				\$0.00	
	0200 -	· Total	Material - To	otal					
		CHANGEABLE MESSAGE SIGN	Material - To	otal	2	Sep 16, 2025	SYSTEM	\$0.00	
		CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR		otal	2		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymer Estimate Exception 6 on the current Payment Estimate.
		CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE,		otal		2025 Sep 16,		\$0.00 \$0.00 (\$16,800.00)	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymer
		CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /		otal	2	2025 Sep 16, 2025 Oct 1,	SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment
		CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /		otal - Total	2	2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00)	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymen Estimate Exception 10 on the current Payment Estimate.
		CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /		- Total	2	2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00)	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymen Estimate Exception 10 on the current Payment Estimate.
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /	Material	- Total	2	2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymer Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymer Estimate Exception 10 on the current Payment Estimate.
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  Total  TEMPORARY TRAFFIC	Material	- Total	2	2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymer Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymer Estimate Exception 10 on the current Payment Estimate.
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material  Material - To	- Total	3 3	2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00 \$0.00 \$0.00	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymer Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymer Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  Total  TEMPORARY TRAFFIC BARRIER, CONT.	Material  Material - To	- Total	3 3 2	2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Sep 16, 2025 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00 \$0.00 \$0.00 (\$29,600.00)	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymer Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymer Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Payment
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  Total  TEMPORARY TRAFFIC BARRIER, CONT.	Material  Material - To	- Total	2 2 2	2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00 \$0.00 \$0.00 \$29,600.00)	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymen Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Paymen Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  Total  TEMPORARY TRAFFIC BARRIER, CONT.	Material  Material - To	- Total	2 2 2 3	2025 Sep 16, 2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00 \$0.00 \$0.00 \$29,600.00) (\$29,600.00)	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymen Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Paymen Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  Total  TEMPORARY TRAFFIC BARRIER, CONT.	Material  Material - To	- Total otal - Total	2 2 2 3	2025 Sep 16, 2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00 \$0.00 \$0.00 (\$29,600.00) (\$29,600.00)	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymen Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Paymen Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment
	0210	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  Total  TEMPORARY TRAFFIC BARRIER, CONT. FURNI/RE	Material - To	- Total otal - Total	2 2 2 3	2025 Sep 16, 2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00 \$0.00 \$0.00 \$29,600.00) (\$29,600.00) \$29,600.00	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymer Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymer Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Paymer Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment
	0210 - 0210 - 0220 - 02	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  Total  TEMPORARY TRAFFIC BARRIER, CONT. FURNI/RE	Material - To	- Total otal - Total	2 2 2 3	2025 Sep 16, 2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$16,800.00) \$16,800.00 (\$16,800.00) \$16,800.00 \$0.00 \$0.00 \$29,600.00) (\$29,600.00) \$29,600.00 \$0.00	Estimate Item Adjustment (0007) due to user jamesc2 overridding Paymer Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc2 overridding Paymer Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc2 overridding Paymer Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment Estimate Item Adjustment (0011) due to user jamesc2 overridding Payment



## Line Item Adjustments by Estimate

Contract ID: 250314-C03

JURISH   1980   1981   1982	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
Material - Total	JKR0134	0360		Material			2025							
					- Total				\$0.00					
ORGO   SEDIMENT TRAP   Material   2   Sap 16, SYSTEM   SY20.00   This adjustment offsets the original system-generated Material Payment   Stimule Exception 8 on the current Payment Estimate.				Material - Total					\$0.00					
ROCK		0360 -	Total						\$0.00					
2025   System   Sys		0460		Material		2		SYSTEM	(\$720.00)					
2025   SYSTEM   \$720.00   This adjustment offsets the original system-generated Malerial Payment Estimate Item Adjustment ((013) due to user jamesez overridding Payment Estimate Item Adjustment ((013) due to user jamesez overridding Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Estimate Item Adjustment (014) due to user jamesez overridding Payment Item Adjustment (015) due to user jamesez overridding Payment Item Adjustment (015) due to user jamesez overridding Payment Item Adjustment (015) due to user jamesez overridding Payment Item Adjustment (015) due to user jamesez overridding Payment Item Adjustment (015) due to user jamesez overridding Payment Item Adjustment (016) due to user jamesez overridding Payment Item Adjustment (016) due to user jamesez overridding Payment Item Adjustment (016) due to user jamesez overridding Payment Item Adjustment (016) due to user jamesez overridding Payment Item Adjustment (016) due to user jamesez overridding Payment Item Adjustment (016) due to user jamesez overridding Payment Item Adjustment (016) due to use						2		SYSTEM	\$720.00	Estimate Item Adjustment (0009) due to user jamesc2 overridding Payment				
Page						3		SYSTEM	(\$720.00)					
Material - Total						3		SYSTEM	\$720.00	Estimate Item Adjustment (0013) due to user jamesc2 overridding Payment				
O460 - Total					- Total				\$0.00					
0470   ALTERNATE   DITCH CHECK   Material   2   Sep 16, 2025   2   Sep 18, 2025   2   S				Material - To	otal				\$0.00					
DITCH CHECK		0460 -	Total						\$0.00					
2025   Setable   Estimate   Est		0470		Material		2		SYSTEM	(\$905.79)					
2025   3						2		SYSTEM	\$905.79	Estimate Item Adjustment (0010) due to user jamesc2 overridding Payment				
Company						3		SYSTEM	(\$905.79)					
Material - Total   \$0.00										3		SYSTEM	\$905.79	Estimate Item Adjustment (0014) due to user jamesc2 overridding Payment
Naterial - Total   Superior   S					- Total				\$0.00					
South   Direction   Material				Material - To	otal				\$0.00					
INDICATOR BARRICADE		0470 -	Total						\$0.00					
3 Oct 1, 2025 SYSTEM \$3,220.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate.  5001 - Total \$0.00  5001 - Total \$0.00  5002 SEQUENTIAL FLASHING WARNING LIGHT  3 Oct 1, 2025 SYSTEM \$2,660.00  3 Oct 1, 2025 This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.  5002 - Total \$0.00  5002 - Total \$0.00  SYSTEM \$0.00  SYSTEM \$2,660.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.  50.00  SYSTEM \$0.00  SYSTEM \$		5001	INDICATOR	Material		3		SYSTEM	(\$3,220.00)					
Material - Total   \$0.00						3		SYSTEM	\$3,220.00	Estimate Item Adjustment (0015) due to user jamesc2 overridding Payment				
Sequential					- Total			\$0.00						
SEQUENTIAL FLASHING WARNING LIGHT   3				Material - To	otal				\$0.00					
FLASHING WARNING LIGHT  3 Oct 1, SYSTEM \$2,660.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user jamesc2 overridding Payment Estimate Exception 9 on the current Payment Estimate.  - Total  \$0.00  Material - Total  \$0.00  JKR0134 - Total  \$169.63		5001 -	Total						\$0.00					
3 Oct 1, 2025 SYSTEM \$2,660.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user jamesc2 overridding Payment Estimate Exception 9 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00  5002 - Total \$0.00  JKR0134 - Total \$10.00		5002	FLASHING	Material		3		SYSTEM	(\$2,660.00)					
Material - Total						3	,	SYSTEM	\$2,660.00	Estimate Item Adjustment (0016) due to user jamesc2 overridding Payment				
5002 - Total         \$0.00           JKR0134 - Total         \$169.63					- Total				\$0.00					
JKR0134 - Total \$169.63				Material - To	otal				\$0.00					
		5002 -	Total						\$0.00					
Overall - Total \$169.63	JKR0134	Total							\$169.63					
	Overall - 1	Total							\$169.63					

# MoDOT

## Contract Adjustments for Contract - 250314-C03

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 12 of 12