\$132,445.37



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2025

. 5	Contract ID Prime Contr		14-F01 ny-Wagner, Inc.	•	riod Start riod End	July 1, 2025 July 15, 2025	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,922,080.1 \$0.0 \$1,922,080.1
Approval Date								By User
July 16, 2025			Generated and	d Approve	ed (and shoเ	uld be considered	Draft) at the Project Office Level by	fullek2
July 17, 2025			Reviewed and App	oroved (a	nd should be	considered Dra	ft) at the Resident Engineer Level by	bauerd1
July 18, 2025				Review	ed and Appr	oved at the Cent	ral Office Controllers Office Level by	ramses1
Original Completion	on Date	Current C	ompletion Date	Ac	tual Comple	etion Date	% of Current Contract Amoun	t Complete
December 1, 2	025	Decen	nber 1, 2025				31.05%	
	Co	ontract Informa	tional Dates				Milestones	
Date Description	Original Co	mpletion Date	Current Completion	on Date		No Milesto	ones Exist for Contract	
Acceptance Date								
Awarded Date	April 2, 2025	5	April 2, 2025					
Letting Date	March 14, 2	025	March 14, 2025					
Notice to Proceed Date	May 5, 2025	5	May 5, 2025					
Work Began Date								

Contract Total Pa	ay For Estimate No. 5				
		This Estimate	Previous	To Date	
250314-F01					
	Total Posted Items Pay	\$132,445.37	\$464,301.65	\$596,747.02	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$464,301.65	\$596,747.02	
Contract Total Pa	ayable This Estimate:	\$132.445.37			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3573B	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$180,143.000	0.150	\$27,021.45
	0030	2035000	UNCLASSIFIED EXCAVATION	CUYD	\$125.000	8	\$1,000.00
	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$17.300	138.700	\$2,399.51
	0060	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$20.000	46.700	\$934.00
	0100	5024009	CONCRETE BASE (9 IN. NON-REINF)	SQYD	\$122.000	46.700	\$5,697.40
	0110	6042010	ADJUSTING MANHOLE	EA	\$1,265.000	1	\$1,265.00
	0140	6081012	TRUNCATED DOMES	SQFT	\$32.500	19.500	\$633.75
	0150	6085008	PAVED APPROACH, 8 IN.	SQYD	\$95.500	58.600	\$5,596.30
	0160	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$74.200	31.800	\$2,359.56
	0170	6089902	MISC.ADA CURB RAMP	EA	\$2,050.000	4	\$8,200.00
	0180	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$48.000	39.900	\$1,915.20
	0190	6091052	CURB AND GUTTER TYPE B	LF	\$47.500	27	\$1,282.50
	0260	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	LF	\$21.000	125	\$2,625.00
	0270	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED	EA	\$1,000.000	2	\$2,000.00
	0550	2169904	MISC.REMOVAL OF EXISTING CANTILEVER SIDEWALK	SQFT	\$54.600	794.500	\$43,379.70
	0600	7034216	TYPE H BARRIER	LF	\$176.000	148.500	\$26,136.00
Project J6I	3573B - To	otal					\$132,445.37

Overall - Total Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Page 1 of 12 Revision 5/29/2025



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2025

Project Line Line Description Aglishment Agli	Estimate	gress e Numb 5		250314-F01 Kozeny-Wagne		Pay Period Start Pay Period End	July 1, 2025 July 15, 2025	Net Chan	Contract Amou ge Order Amo Contract Amou	unt	\$1,922,080.11 \$0.00 \$1,922,080.11
BASE (4 IN, THICK) Separate (2001) Labor but our surfailed covered by the cov			Item Description		Adjustment		Comments			Adjustment	
BASE (4 IN. THICK) 1010 CONCRETE BASE (9 IN. Material NON-REINF) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfields overridding Payment Estimate Item Adjustment (OOQ) also to user fulfield to user fulfield overridding Payment Estimate. OFFICE ON ADDITION ON ADDIT	J6l3573B	0050		Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 1) due to user fullel nent Estimate Exce	te Item (2	138.70000	\$17.30	\$2,399.51
NON-REINF		0050		Material					-138.70000	\$17.30	(\$2,399.51)
NON-REINF		0100	,	Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 2) due to user fullel nent Estimate Exce	te Item (2	46.70000	\$122.00	\$5,697.40
generated Material Payment Estimate Item Adjustment (0003) due to user fullek2 overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 8 on the Current Payment Estimate Exception 8 on the Current Payment Estimate Exception 9 on the Current Payment Estimate Exception 8 on the Current Payment Estimate Exception 9 on the Current Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0008) due to user fullek2 overridding Payment Estimate Item Adjustment (0008) due to user fullek2 overridding Payment Estimate Item Adjustment (0008) due to user fullek2 overridding Payment Estimate Item		0100		Material					-46.70000	\$122.00	(\$5,697.40)
Day		0140	TRUNCATED DOMES	Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 3) due to user fullel nent Estimate Exce	te Item <2	19.50000	\$32.50	\$633.75
generated Material Payment Estimate Item Adjustment (0004) due to user fullek2 overridding Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Item Adjustment Item		0140	TRUNCATED DOMES	Material					-19.50000	\$32.50	(\$633.75)
O160 CONCRETE SIDEWALK, 4 IN. Material IN. O2005 due to user fullek2 overridding Payment Estimate Exception 9 on the current Payment Estimate31.80000 \$74.20 (\$2,359.56) O160 CONCRETE SIDEWALK, 4 Material IN. O2005 due to user fullek2 overridding Payment Estimate31.80000 \$74.20 (\$2,359.56) O170 CURB AND GUTTER TYPE B Material Payment Estimate Item Adjustment (0000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (000) due to user fullek2 overridding Payment Estimate Item Adjustment (0000) due to user fullek2 overridding Payment Estimate Item Adjustment (0000) due to user fullek2 overridding Payment Estimate Item Adjustment (0000) due to user fullek2 overridding Payment Estimate Item Adjustment (0000) due to user fullek2 overridding Payment Estimate Item Adjustment (0000) due to user fullek2 overridding Payment Estimate Item Adjustment (0000) due to user fullek2 overridding Payment Estimate Item Adjustment (0000) due to user f		0150	PAVED APPROACH, 8 IN.	Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 4) due to user fullel nent Estimate Exce	te Item (2	58.60000	\$95.50	\$5,596.30
IN. generated Material Payment Estimate Item Adjustment (0005) due to user fullek2 overridding Payment Estimate Exception 9 on the current Payment Estimate. 31.80000 \$74.20 \$2,359.56		0150	PAVED APPROACH, 8 IN.	Material					-58.60000	\$95.50	(\$5,596.30)
IN. O190 CURB AND GUTTER TYPE B Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Exception 10 on the current Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 11 on the current Payment Estimate Ex		0160		Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 5) due to user fullel nent Estimate Exce	te Item (2	31.80000	\$74.20	\$2,359.56
generated Material Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Exception 10 on the current Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0008) due to user fullek2 overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate.		0160		Material					-31.80000	\$74.20	(\$2,359.56)
SUPPLEMENTARY WEARING SURFACE Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0008) due to user fullek2 Surface		0190	CURB AND GUTTER TYPE E	3 Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 6) due to user fullel nent Estimate Exce	te Item (2	27	\$47.50	\$1,282.50
WEARING SURFACE MATERIAL generated Material Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullek2 overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullek2 overridding Payment Estimate Item Adjustment (0009) due to user fullek2 overridding Payment Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate.		0190	CURB AND GUTTER TYPE I	3 Material					-27	\$47.50	(\$1,282.50)
WEARING SURFACE MATERIAL 0570 LATEX MODIFIED CONCRETE WEARING SURFACE Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user fullek2 overridding Payment Estimate Exception 5 on the current Payment Estimate. 510 \$232.00 \$118,320.00 \$118,320.00 \$232.00 \$118,320.00 \$232.00 \$118,320.00 Type H Barrier This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user fullek2 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0560	WEARING SURFACE	Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 7) due to user fullel nent Estimate Exce	te Item	5	\$1,000.00	\$5,000.00
CONCRETE WEARING SURFACE generated Material Payment Estimate Item Adjustment (0008) due to user fullek2 overridding Payment Estimate Exception 5 on the current Payment Estimate. -510 \$232.00 (\$118,320.00) CONCRETE WEARING SURFACE Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user fullek2 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0560	WEARING SURFACE	Material					-5	\$1,000.00	(\$5,000.00)
CONCRETE WEARING SURFACE Type H Barrier Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullek2 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0570	CONCRETE WEARING	Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 8) due to user fullel nent Estimate Exce	te Item (2	510	\$232.00	\$118,320.00
generated Material Payment Estimate Item Adjustment (0009) due to user fullek2 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0570	CONCRETE WEARING	Material					-510	\$232.00	(\$118,320.00)
0600 TYPE H BARRIER Material -148.50000 \$176.00 (\$26,136.00)		0600	TYPE H BARRIER	Material		generated Mater Adjustment (000 overridding Payr	ial Payment Estima 9) due to user fullel nent Estimate Exce	te Item (2	148.50000	\$176.00	\$26,136.00
		0600	TYPE H BARRIER	Material					-148.50000	\$176.00	(\$26,136.00)

Revision 5/29/2025 Page 2 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2025

Prog Estimate	gress • Numb 5	Contract ID per Prime Contractor	250314-F01 Kozeny-Wagne		Pay Period Start Pay Period End	July 1, 2025 July 15, 2025	Net Chan	Contract Amou ige Order Amo Contract Amou	unt	\$1,922,080.11 \$0.00 \$1,922,080.11
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustmen Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3573B	0610	SIDEWALK (BRIDGES)	Material		generated Materi Adjustment (0010	offsets the original al Payment Estima i) due to user fullel lent Estimate Exce yment Estimate.	te Item (2	1,164.50000	\$40.20	\$46,812.90
	0610	SIDEWALK (BRIDGES)	Material					-1,164.50000	\$40.20	(\$46,812.90)
Total										\$0.00

Revision 5/29/2025 Page 3 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Inform	ation
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6I3573B	FAS S504(6)	Bridge rehabilitation and ADA improvements	AC	ST LOUIS	over Maline Creek		
Totals b	y Job N	umbers					
J6I3573B		d Item Pay Item Adjustme		tem Pay	This Estimate \$132,445.37 \$0.00 \$132,445.37	Previous \$464,301.65 \$0.00 \$464,301.65	To Date \$596,747.02 \$0.00 \$596,747.02
	Liquid	tive entive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 5/29/2025 Page 4 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 3040504, Project Item Line Number 0050, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 5024009, Project Item Line Number 0100, Material Set 502400996, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 5050004, Project Item Line Number 0560, Material Set 5050004, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 5050004, Project Item Line Number 0560, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 5052000, Project Item Line Number 0570, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 5052000, Project Item Line Number 0570, Material Set 505200096, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 6081012, Project Item Line Number 0140, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 6085008, Project Item Line Number 0150, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 6086004, Project Item Line Number 0160, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 6091052, Project Item Line Number 0190, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 7034216, Project Item Line Number 0600, Material Set 703421696, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 7034216, Project Item Line Number 0600, Material Set 703421696, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 7034430, Project Item Line Number 0610, Material Set 703443096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 7034430, Project Item Line Number 0610, Material Set 703443096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 7034430, Project Item Line Number 0610, Material Set 703443096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 7034430, Project Item Line Number 0610, Material Set 703443096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3573B, Item 7034430, Project Item Line Number 0610, Material Set 703443096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on material reporting.	fullek2	Overridden

Revision 5/29/2025 Page 5 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					d on Report Generated date and can differ from the poste							
Contract	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
	J6I3573B	0001	0010	1081000	SIGNET DBE REPORTING	1.00	0.00	1.00	LS	0.00	\$1,000.00	\$0.00
F01		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.40	\$180,143.00	\$72,057.20
		0001	0030	2035000	UNCLASSIFIED EXCAVATION	16.00	0.00	16.00	CUYD	8.00	\$125.00	\$1,000.00
		0001	0040	2035500	EMBANKMENT IN PLACE	387.00	0.00	387.00	CUYD	132.00	\$44.50	\$5,874.00
		0001	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	735.00	0.00	735.00	SQYD	288.05	\$17.30	\$4,983.26
		0001	0060	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	90.00	0.00	90.00	SQYD	46.70	\$20.00	\$934.00
		0001	0070	4030012	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095CLP MIX)	102.50	0.00	102.50	TONS	0.00	\$308.00	\$0.00
		0001	0800	4030105	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125C MIX)	154.80	0.00	154.80	TONS	0.00	\$308.00	\$0.00
		0001	0090	4071005	TACK COAT	193.00	0.00	193.00	GAL	0.00	\$3.00	\$0.00
		0001	0100	5024009	CONCRETE BASE (9 IN. NON-REINF)	89.60	0.00	89.60	SQYD	46.70	\$122.00	\$5,697.40
		0001	0110	6042010	ADJUSTING MANHOLE	4.00	0.00	4.00	EA	1.00	\$1,265.00	\$1,265.00
		0001	0120	6049902	MISC.CONCRETE MANHOLE APRON	4.00	0.00	4.00	EA	0.00	\$461.00	\$0.00
		0001	0130	6079903	MISC.TEMPORARY PEDESTRIAN FENCING	1,698.00	0.00	1,698.00	LF	420.00	\$13.30	\$5,586.00
		0001	0140	6081012	TRUNCATED DOMES	39.00	0.00	39.00	SQFT	39.00	\$32.50	\$1,267.50
		0001	0150	6085008	PAVED APPROACH, 8 IN.	179.30	0.00	179.30	SQYD	117.60	\$95.50	\$11,230.80
		0001	0160	6086004	CONCRETE SIDEWALK, 4 IN.	360.80	0.00	360.80	SQYD	85.20	\$74.20	\$6,321.84
		0001	0170	6089902	MISC.ADA CURB RAMP	7.00	0.00	7.00	EA	5.00	\$2,050.00	\$10,250.00
		0001	0180	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	168.00	0.00	168.00	LF	39.90	\$48.00	\$1,915.20
		0001	0190	6091052	CURB AND GUTTER TYPE B	413.00	0.00	413.00	LF	86.00	\$47.50	\$4,085.00
		0001	0200	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	55.00	0.00	55.00	TONS	0.00	\$280.00	\$0.00
		0001	0210	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	79.10	0.00	79.10	SQYD	0.00	\$30.00	\$0.00
		0001	0220	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	3.00	0.00	3.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0230	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	8.00	\$950.00	\$7,600.00
		0001	0240	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$34,569.00	\$17,284.50
		0001	0250	6169902	MISC.ADA-COMPLIANT TYPE III MOVEABLE BARRICADES	8.00	0.00	8.00	EA	6.00	\$155.00	\$930.00
		0001	0260	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	963.00	0.00	963.00	LF	375.00	\$21.00	\$7,875.00
		0001	0270	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED	6.00	0.00	6.00	EA	4.00	\$1,000.00	\$4,000.00
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	313.00	0.00	313.00	LF	0.00	\$10.00	\$0.00
		0001	0290	6175020A	RELOCATING TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0300	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$193,501.00	\$95,976.50
		0001	0310	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.00
		0001	0320	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	37.00	0.00	37.00	LF	0.00	\$30.00	\$0.00
		0001	0330	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	0.00	\$500.00	\$0.00
		0001	0340	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	4,552.00 3,062.00	0.00	4,552.00	LF LF	0.00	\$2.00 \$2.00	\$0.00 \$0.00
		0001	0360	6205901A	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,509.00	0.00	3,062.00 5,509.00	LF	0.00	\$2.00	\$0.00
		0001	0370	6205902A		7,579.00	0.00	7,579.00	LF	0.00	\$0.70	\$0.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	25,943.00	0.00	25,943.00	LF	4,500.00	\$1.00	\$4,500.00
		0001	0390	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	7,481.00	0.00	7,481.00	LF	6,186.00	\$1.00	\$6,186.00
		0001	0400	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	963.00	0.00	963.00	SQYD	0.00	\$9.50	\$0.00
		0001	0410	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0001	0420	7034216	TYPE H BARRIER	80.00	0.00	80.00	LF	40.00	\$162.00	\$6,480.00
		0001	0430	7034430	SIDEWALK (BRIDGES)	627.00	0.00	627.00	SQFT	313.50	\$20.40	\$6,395.40
		0001	0440	7069902	MISC.6.5 FT X 4 FT DRAINAGE FLUME	1.00	0.00	1.00	EA	0.00	\$13,201.00	\$0.00
		0001	0450	8025006	MULCHING	0.20	0.00	0.20	ACRE	0.03	\$12,000.00	\$360.00
		0001	0460	8051000A	SEEDING - COOL SEASON GRASSES	0.20	0.00	0.20	ACRE	0.03	\$12,000.00	\$360.00
		0001	0470	8061019	SILT FENCE	675.00	0.00	675.00	LF	675.00	\$3.00	\$2,025.00
		0040	0480	9031270A	2 IN. PSST POST - 12 GA.	14.00	0.00	14.00	LF	0.00	\$40.00	\$0.00
		0040	0490	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	1.00	0.00	1.00	EA	0.00	\$500.00	\$0.00
		0070	0500	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	14.00	0.00	14.00	SQFT	7.00	\$500.00	\$3,500.00
		0070	0510	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,189.00	0.00	1,189.00	SQYD	594.00	\$74.00	\$43,956.00

Revision 5/29/2025 Page 6 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
250314-	J6I3573B	0070	0530	2161503	REMOVAL OF EXISTING DECK REPAIR	1,575.00	0.00	1,575.00	SQFT	25.00	\$46.80	\$1,170.00
F01		0070	0540	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.50	\$38,792.00	\$19,396.00
		0070	0550	2169904	MISC.REMOVAL OF EXISTING CANTILEVER SIDEWALK	1,598.00	0.00	1,598.00	SQFT	794.50	\$54.60	\$43,379.70
		0070	0560	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	10.00	0.00	10.00	CY	5.00	\$1,000.00	\$5,000.00
		0070	0570	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	931.00	0.00	931.00	SQYD	510.00	\$232.00	\$118,320.00
		0070	0580	6071066	(72 IN.) PEDESTRIAN FENCE (STRUCTURES)	315.00	0.00	315.00	LF	157.50	\$250.00	\$39,375.00
		0070	0590	7031004	DIAMOND GRINDING	931.00	0.00	931.00	SQYD	0.00	\$11.10	\$0.00
		0070	0600	7034216	TYPE H BARRIER	297.00	0.00	297.00	LF	148.50	\$176.00	\$26,136.00
		0070	0610	7034430	SIDEWALK (BRIDGES)	2,329.00	0.00	2,329.00	SQFT	1,164.50	\$40.20	\$46,812.90
		0070	0620	7040104	HALF-SOLE REPAIR	1,000.00	0.00	1,000.00	SQFT	70.00	\$93.90	\$6,573.00
		0070	0630	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	700.00	0.00	700.00	SQFT	0.00	\$265.00	\$0.00
	Project J6	13573B - To	tal Value	Posted to I	Date as of Report Generated Date							\$673,258.20
250314-F	01 Overall	- Total Valu	ue Posted	to Date as	of Report Generated Date							\$673,258.20

Revision 5/29/2025 Page 7 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6l3573B

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2022010	REMOVAL OF IMPROVEMENTS	7/11/25	7/11/25	1	0.15	LS	RT					sidewalk, entrances, sawcut
0030	2035000	UNCLASSIFIED EXCAVATION	7/9/25	7/11/25	1	8.00	CUYD	RT	430+07		431+05		
0050	3040504	TYPE 5 AGGREGATE FOR BASE	7/9/25	7/11/25	1	9.00	SQYD	RT	430+76.98		431+03.14		curb and gutter
				7/11/25	2	7.60	SQYD	RT	431+03.14		431+25.73		curb and gutter
				7/11/25	3	5.70	SQYD	RT	432+74.73		432+91.85		cur and gutter
				7/11/25	4	23.10	SQYD	RT	430+06.59		431+36.10		curb ramp
				7/11/25	5	31.80	SQYD	RT	430+06.59		431+25.56		Sidewalk
				7/11/25	6	61.50	SQYD	RT	430+37.22				Entrance to Sam's Market
0060	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	7/9/25	7/11/25	1	26.30	SQYD	RT	431+03.15		431+26.62		9" Pavement for H Barrier
				7/11/25	2	20.40	SQYD	RT	432+75.47		432+91.91		9" Pavement for H Barrier
100	5024009	CONCRETE BASE (9 IN. NON-REINF)	7/1/25	7/2/25	1	26.30	SQYD		431+03.15 RT		431+26.62 RT		
				7/2/25	2	20.40	SQYD		432+75.47 RT		432+91.91 RT		
110	6042010	ADJUSTING MANHOLE	7/1/25	7/2/25	1	1.00	EA		430+73.76 RT				Sanitary MH
140	6081012	TRUNCATED DOMES	7/11/25	7/11/25	1	19.50	SQFT	RT	433+64.43		433+74.56		
150	6085008	PAVED APPROACH, 8 IN.	7/11/25	7/11/25	1	58.60	SQYD	RT	430+37.22				Sam's Market Entrance
160	6086004	CONCRETE SIDEWALK, 4 IN.	7/11/25	7/11/25	1	31.80	SQYD	RT	430+06.59		431+25.56		
170	6089902	MISC. CONCRETE	7/11/25	7/11/25	1	3.00	EA	RT	430+06.59		431+36.10		
				7/11/25	2	1.00	EA	RT	433+17.38		434+36.17		
180	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	7/11/25	7/11/25	1	22.70	LF	RT	431+06.14		431+25.73		
				7/11/25	2	17.20	LF	RT	432+74.73		432+91.85		
190	6091052	CURB AND GUTTER TYPE B	7/11/25	7/11/25	1	27.00	LF	RT	430+76.98		431+03.14		
260	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	7/2/25	7/9/25	1	125.00	LF	Along face of curb/sidewalk	431+35+/- RT		432+85+/- RT		
270	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED	7/2/25	7/9/25	1	1.00	EA		431+35+/- RT				
				7/9/25	2	1.00	EA		432+85+/- RT				
0550	2169904	MISC. REMOVALS	7/1/25	7/2/25	1	794.50	SQFT		431+35+/-		432+85+/-		
0600	7034216	TYPE H BARRIER	7/10/25	7/11/25	1	148.50	LF	RT	431+35		432+85		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 8 of 12



Line Item Adjustments by Estimate

Contract ID: 250314-F01

roject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		·	Туре	Adjustment Type	Number	Date	Ву		
3573B	0050	TYPE 5 AGGREGATE FOR BASE	Material		5	Jul 16, 2025	SYSTEM	(\$2,399.51)	
		5.102			5	Jul 16, 2025	SYSTEM	\$2,399.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullek2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0050 -	Total						\$0.00	
	0100	CONCRETE BASE (9 IN. NON- REINF)	Material		5	Jul 16, 2025	SYSTEM	(\$5,697.40)	
		·			5	Jul 16, 2025	SYSTEM	\$5,697.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullek2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0100 -	Total TRUNCATED	Material		5	Jul 16,	SYSTEM	\$0.00 (\$633.75)	
	0140	DOMES	Material		5	2025	STSTEIN	(\$033.73)	
					5	Jul 16, 2025	SYSTEM	\$633.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullek2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0140 -	Total						\$0.00	
	0150	PAVED APPROACH, 8 IN.	Material		5	Jul 16, 2025	SYSTEM	(\$5,596.30)	
					5	Jul 16, 2025	SYSTEM	\$5,596.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullek2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otai				\$0.00	
	0150 -				-	1.1.10	OVOTEM	\$0.00	
	0160	CONCRETE SIDEWALK, 4 IN.	Material		5	Jul 16, 2025	SYSTEM	(\$2,359.56)	
					5 Jul 16, SYSTEI 2025			\$2,359.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullek2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0160 -	Total						\$0.00	
	0190	CURB AND GUTTER TYPE B	Material		5	Jul 16, 2025	SYSTEM	(\$1,282.50)	
					5	Jul 16, 2025	SYSTEM	\$1,282.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0190 -	Total						\$0.00	
		MESSAGE SIGN	Material		1	May 16, 2025	SYSTEM	(\$5,000.00)	
		WITHOUT COMMUNICATION INTERFACE, CONTRACTOR			1	May 16, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullek2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		FURNISHED / RETAINED		- Total				\$0.00	
			Material - T	otal				\$0.00	
	0220 -	Total						\$0.00	
	0230	LONG-TERM	Material		1	May 16, 2025	SYSTEM	(\$7,600.00)	
		RUMBLE STRIPS			1	May 16, 2025	SYSTEM	\$7,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullek2 overridding Payment



Line Item Adjustments by Estimate

Contract ID: 250314-F01

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3B	0230	TEMPORARY LONG-TERM	Material	- Total				\$0.00	Estimate Exception 2 on the current Payment Estimate.
		RUMBLE STRIPS	Material - To					\$0.00	
	0230 -	Total	Waterial - 1	Jiai				\$0.00	
		MISC.	Material		1	May 16, 2025	SYSTEM	(\$17,284.50)	
					1	May 16, 2025	SYSTEM	\$17,284.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullek2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0240 -	Total						\$0.00	
	0250	MISC. TRAFFIC CONTROL	Material		1	May 16, 2025	SYSTEM	(\$930.00)	
		DEVICES			1	May 16, 2025	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullek2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0250 -	- Total	_					\$0.00	
	0260	TEMPORARY TRAFFIC	Material		1	May 16, 2025	SYSTEM	(\$5,250.00)	
		BARRIER, CONT. FURN/RE			1	May 16, 2025	SYSTEM	\$5,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullek2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
		0260 - Total 0270 TEMPORARY TRAFFIC BARDIER HEIGHT	Material - To	otal				\$0.00	
	0260 -							\$0.00	
	0270		TRAFFIC BARRIER HEIGHT	Material		1	May 16, 2025	SYSTEM	(\$2,000.00)
		TRANSITION, CONTRACTOR FURNISHED /			1	May 16, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullek2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		RETAINED			2	Jun 2, 2025	SYSTEM	(\$2,000.00)	
					2	Jun 2, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stront1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
					3	Jun 16, 2025	SYSTEM	(\$2,000.00)	
					3	Jun 16, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stront1 overridding Paymen Estimate Exception 3 on the current Payment Estimate.
					4	Jul 1, 2025	SYSTEM	(\$2,000.00)	
					4	Jul 1, 2025	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullek2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0270 -	Total						\$0.00	
	0470	SILT FENCE	Material		2	Jun 2, 2025	SYSTEM	(\$2,025.00)	
					2	Jun 2, 2025	SYSTEM	\$2,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stront1 overridding Paymen Estimate Exception 2 on the current Payment Estimate.
								00.00	
				- Total				\$0.00	
			Material - To					\$0.00	
	0470 -	- Total	Material - To						



Line Item Adjustments by Estimate

Contract ID: 250314-F01

						1			
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3573B	0560	SURFACE MATERIAL	Material		3	Jun 16, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stront1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jul 1, 2025	SYSTEM	(\$5,000.00)	
					4	Jul 1, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullek2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jul 16, 2025	SYSTEM	(\$5,000.00)	
					5	Jul 16, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullek2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0560	0560 - Total							
		LATEX MODIFIED CONCRETE WEARING SURFACE	Material		3	Jun 16,	SYSTEM	\$0.00 (\$118,320.00)	
					3	2025 Jun 16, 2025	SYSTEM	\$118,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stront1 overridding Payment
					4	Jul 1, 2025	SYSTEM	(\$118,320.00)	Estimate Exception 2 on the current Payment Estimate.
					4	Jul 1, 2025	SYSTEM	\$118,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullek2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jul 16, 2025	SYSTEM	(\$118,320.00)	
					5	Jul 16, 2025	SYSTEM	\$118,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullek2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
	0570 -	0570 - Total						\$0.00	
	0600	TYPE H BARRIER	Material		5	Jul 16, 2025	SYSTEM	(\$26,136.00)	
					5	Jul 16, 2025	SYSTEM	\$26,136.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullek2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	Material - Total				\$0.00	
	0600	- Total						\$0.00	
	0610	SIDEWALK (BRIDGES)	Material		4	Jul 1, 2025	SYSTEM	(\$46,812.90)	
					4	Jul 1, 2025	SYSTEM	\$46,812.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullek2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Jul 16, 2025	SYSTEM	(\$46,812.90)	
					5	Jul 16, 2025	SYSTEM	\$46,812.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullek2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0610 - Total							\$0.00	
J6l3573B - Total								\$0.00	
Overall - Total								\$0.00	

MoDOT

Contract Adjustments for Contract - 250314-F01

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 12 of 12