

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2025

Progress Estimate Number	Contract ID	250516-H11	Pay Period Start	September 16, 2025	Original Contract Amount	\$196,429.11
3	Prime Contractor	Courtney Construction, LLC dba Courtney Excavating & Construction	Pay Period End	September 30, 2025	Net Change Order Amount	\$48,041.52
					Current Contract Amount	\$244,470.63

Approval Date		By User
October 1, 2025	Generated and Approved (and should be considered Draft) at the Project Office Level by	davidm1
October 1, 2025	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	hillsd1
October 3, 2025	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion D	ate	% of Current Contract Amount Complete
October 1, 2025	October 1, 2025	September 18, 202	5	77.66%
Co	ontract Informational Dates			Milestones

Date DescriptionOriginal Completion DateCurrent Completion DateAcceptance DateJune 5, 2025June 5, 2025Letting DateMay 16, 2025May 16, 2025Notice to Proceed DateJuly 7, 2025July 7, 2025Work Began DateAugust 25, 2025August 25, 2025

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 3											
	This Estimate	Previous	To Date								
250516-H11											
Total Posted Items Pay	\$2,566.00	\$187,281.13	\$189,847.13								
Gross Item Adjustments	\$59,157.60	(\$61,723.60)	(\$2,566.00)								
Incentive	\$0.00	\$0.00	\$0.00								
Disincentive	\$0.00	\$0.00	\$0.00								
Liquidated Damage	\$0.00	\$0.00	\$0.00								
Other Contract Adjustments	\$0.00	\$0.00	\$0.00								
		\$125,557.53	\$187,281.13								
Contract Total Payable This Estimate:	\$61,723.60										

tems	Paid	This	Estim	ate I	Period	

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
JSEM0081	0140	8061019	SILT FENCE	LF	\$12.830	200	\$2,566.00
Project JSEM0081 -	\$2,566.00						
Overall Total							\$2.566.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ents This Estimate						
Project Number	Line No. Item Description Adjustment Type Other Item Adjustment Type Adjustment Type Other Item Comments Type					Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSEM0081	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material			-50	\$128.42	(\$6,421.00)
	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user davidm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	50	\$128.42	\$6,421.00
	0040	FURNISHING TYPE 2 ROCK BLANKET	Material			-1,340	\$50.58	(\$67,777.20)
	0040	FURNISHING TYPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user davidm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1,340	\$50.58	\$67,777.20
	0040	FURNISHING TYPE 2 ROCK BLANKET	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.58000 - 50.58000, 'is	580	\$50.58	\$29,336.40

Revision 9/2/2025 Page 1 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2025

September 16, 2025 **Progress Pay Period Original Contract** Contract ID 250516-H11 \$196,429.11 Amount Net Change Order Estimate Number Start Courtney Construction, LLC dba Courtney Excavating & Construction September 30, 2025 Prime **Pay Period** \$48,041.52 Amount
Current Contract
Amount Contractor End \$244,470.63

						Alliouli		
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSEM0081					applied (if non-zero).			
	0050	O PLACING TYPE 2 ROCK BLANKET Overrun Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero).		580	\$55.84	\$32,387.20		
	0060	CONSTRUCTION SIGNS	Material			-128	\$8.33	(\$1,066.24)
	0060	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	128	\$8.33	\$1,066.24
	0070	CHANNELIZER (TRIM-LINE)	Material			-10	\$14.28	(\$142.80)
	0070	CHANNELIZER (TRIM-LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user davidm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	10	\$14.28	\$142.80
	0800	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material			-2	\$2,975.00	(\$5,950.00)
	0080	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user davidm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2	\$2,975.00	\$5,950.00
	0110	MULCHING	Material			-0.20000	\$14,494.10	(\$2,898.82)
	0110	MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user davidm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	0.20000	\$14,494.10	\$2,898.82
	0120	SEEDING - COOL SEASON GRASSES	Material			-0.20000	\$18,361.60	(\$3,672.32)
	0120	SEEDING - COOL SEASON GRASSES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user davidm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	0.20000	\$18,361.60	\$3,672.32
	0140	SILT FENCE	Material			-200	\$12.83	(\$2,566.00)
Total								\$59,157.60

Revision 9/2/2025 Page 2 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information												
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work							
JSEM0081		Slope repair	95	OZARK	at Little North Fork White	Little North Fork White River							
Totals by	Job Nu	mbers											
JSEM0081		Item Pay tem Adjustme		Item Pay	This Estimate \$2,566.00 \$59,157.60 \$61,723.60	Previous \$187,281.13 (\$61,723.60) \$125,557.53	To Date \$189,847.13 (\$2,566.00) \$187,281.13						
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						

Revision 5/29/2025 Page 3 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 3105002, Project Item Line Number 0030, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on certification	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 6113020, Project Item Line Number 0040, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	Pending report	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 6161005, Project Item Line Number 0060, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on certification	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 6161025, Project Item Line Number 0070, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on certification	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 6161098A, Project Item Line Number 0080, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on certification	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 8025006, Project Item Line Number 0110, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Pending report	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 8051000A, Project Item Line Number 0120, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Pending report	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 8051000A, Project Item Line Number 0120, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Pending report	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 8051000A, Project Item Line Number 0120, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Waiting on change order	davidm1	Overridden
Estimate Exception Type: Insufficient Materials: Project JSEM0081, Item 8061019, Project Item Line Number 0140, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	waiting on change order	davidm1	Acknowledged

Revision 5/29/2025 Page 4 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
250516-	JSEM0081	0001	0010	2031000	CLASS A EXCAVATION	320.00	0.00	320.00	CUYD	0.00	\$74.95	\$0.00
H11		0001	0020	2072000	LINEAR GRADING CLASS 2	4.90	-3.40	1.50	STA	1.50	\$3,230.96	\$4,846.44
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	71.00	-21.00	50.00	TONS	50.00	\$128.42	\$6,421.00
		0001	0040	6113020	FURNISHING TYPE 2 ROCK BLANKET	760.00	580.00	1,340.00	CUYD	1,340.00	\$50.58	\$67,777.20
		0001	0050	6113040	PLACING TYPE 2 ROCK BLANKET	760.00	580.00	1,340.00	CUYD	1,340.00	\$55.84	\$74,825.60
		0001	0060	6161005	CONSTRUCTION SIGNS	128.00	0.00	128.00	SQFT	128.00	\$8.33	\$1,066.24
		0001	0070	6161025	CHANNELIZER (TRIM-LINE)	10.00	0.00	10.00	EA	10.00	\$14.28	\$142.80
	0001 0080 6161098A CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED			CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,975.00	\$5,950.00	
		0001	0090	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.98	\$20,082.36	\$19,680.71
		0001	0100	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$3,570.00	\$0.00
		0001	0110	8025006	MULCHING	0.20	0.00	0.20	ACRE	0.20	\$14,494.10	\$2,898.82
		0001	0120	8051000A	SEEDING - COOL SEASON GRASSES	0.20	0.00	0.20	ACRE	0.20	\$18,361.60	\$3,672.32
		0001	0130	8061016	SEDIMENT REMOVAL	9.00	0.00	9.00	CUYD	0.00	\$304.70	\$0.00
		0001	0140	8061019	SILT FENCE	376.00	0.00	376.00	LF	200.00	\$12.83	\$2,566.00
		0001	0150	8061050	TYPE C BERM	363.00	0.00	363.00	LF	0.00	\$59.69	\$0.00
	Project JSE	M0081 - To	tal Value	Posted to D	late as of Report Generated Date							\$189,847.13
250516-H	11 Overall -	Total Value	Posted	to Date as o	Report Generated Date							\$189,847.13

Revision 5/29/2025 Page 5 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JSEM0081

Line	Item	Description	DWR	DWR	Posting		Units			Offset/	To	Offset/	Comments
Number	Code		Date	Approval Date	Sequence No.	Posted			Station/ Log Mile	Distance	Station/ Log Mile	Distance	
0140	8061019	SILT FENCE	9/16/25	10/1/25	1	200.00	LF	MO 95 - Bridge B0452	Bridge B0452		Bridge B0452		Bridge B0452

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 6 of 9



Line Item Adjustments by Estimate

Contract ID: 250516-H11

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSEM0081	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material		2	Sep 16, 2025	SYSTEM	(\$6,421.00)	
					2	Sep 16, 2025	SYSTEM	\$6,421.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user davidm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Oct 1, 2025	SYSTEM	(\$6,421.00)	
					3	Oct 1, 2025	SYSTEM	\$6,421.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user davidm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
	0030	- Total						\$0.00	
	0040		Material		2	Sep 16, 2025	SYSTEM	(\$67,777.20)	
					2	Sep 16, 2025	SYSTEM	\$67,777.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user davidm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Oct 1, 2025	SYSTEM	(\$67,777.20)	
					3	Oct 1, 2025	SYSTEM	\$67,777.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user davidm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	2	Sep 16, 2025	SYSTEM	(\$29,336.40)	
					3	Oct 1, 2025	SYSTEM	\$29,336.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.58000 - 50.58000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T		otal			\$0.00 \$0.00	
	0040	- Total	Overrun - T		otal				
	0040	PLACING TYPE 2 ROCK BLANKET	Overrun - T		otal 2	Sep 16, 2025	SYSTEM	\$0.00	
		PLACING TYPE 2		otal			SYSTEM SYSTEM	\$0.00 \$0.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero).
		PLACING TYPE 2		otal	3	2025 Oct 1,		\$0.00 \$0.00 (\$32,387.20)	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is
		PLACING TYPE 2		Overrun - T	3	2025 Oct 1,		\$0.00 \$0.00 (\$32,387.20) \$32,387.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is
	0050	PLACING TYPE 2	Overrun	Overrun - T	3	2025 Oct 1,		\$0.00 \$0.00 (\$32,387.20) \$32,387.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is
	0050	PLACING TYPE 2 ROCK BLANKET	Overrun	Overrun - T	3	2025 Oct 1,		\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is
	0050	PLACING TYPE 2 ROCK BLANKET - Total CONSTRUCTION	Overrun - T	Overrun - T	2 3	2025 Oct 1, 2025	SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment
	0050	PLACING TYPE 2 ROCK BLANKET - Total CONSTRUCTION	Overrun - T	Overrun - T	2 3 otal	2025 Oct 1, 2025 Sep 16, 2025 Sep 16,	SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24)	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment
	0050	PLACING TYPE 2 ROCK BLANKET - Total CONSTRUCTION	Overrun - T	Overrun - T	2 3 iotal	2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24)	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment
	0050	PLACING TYPE 2 ROCK BLANKET - Total CONSTRUCTION	Overrun - T	Overrun - T	2 3 3 2 2 2 3 3	2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24) (\$1,066.24)	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment
	0050	PLACING TYPE 2 ROCK BLANKET - Total CONSTRUCTION	Overrun - T Material	Overrun - Total	2 3 3 2 2 2 3 3	2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24) \$1,066.24 (\$1,066.24)	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment
	0050 0050 0060	PLACING TYPE 2 ROCK BLANKET -Total CONSTRUCTION SIGNS	Overrun - T	Overrun - Total	2 3 3 2 2 2 3 3	2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24) \$1,066.24 (\$1,066.24) \$1,066.24	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment
	0050 0050 0060	PLACING TYPE 2 ROCK BLANKET -Total CONSTRUCTION SIGNS -Total CHANNELIZER	Overrun - T Material	Overrun - Total	2 3 3 2 2 2 3 3	2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Sep 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24) \$1,066.24 (\$1,066.24)	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment
	0050 0050 0060	PLACING TYPE 2 ROCK BLANKET - Total CONSTRUCTION SIGNS	Overrun - T Material Material - To	Overrun - Total	2 3 3 3 3 2 2	2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Sep 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24) \$1,066.24 (\$1,066.24) \$1,066.24	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	0050 0050 0060	PLACING TYPE 2 ROCK BLANKET -Total CONSTRUCTION SIGNS -Total CHANNELIZER	Overrun - T Material Material - To	Overrun - Total	2 3 3 3 3 3	2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Sep 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24) \$1,066.24 (\$1,066.24) \$1,066.24	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment
	0050 0050 0060	PLACING TYPE 2 ROCK BLANKET -Total CONSTRUCTION SIGNS -Total CHANNELIZER	Overrun - T Material Material - To	Overrun - Total	2 3 3 3 3 2 2	2025 Oct 1, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 1, 2025 Sep 16, 2025 Sep 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$32,387.20) \$32,387.20 \$0.00 \$0.00 (\$1,066.24) \$1,066.24 (\$1,066.24) \$1,066.24	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.84000 - 55.84000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davidm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.



Line Item Adjustments by Estimate

Contract ID: 250516-H11

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSEM0081	0070	CHANNELIZER (TRIM-LINE)	Material			2025			Estimate Item Adjustment (0006) due to user davidm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	Material - Total				\$0.00	
	0070 -	Total						\$0.00	
	0080	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		2	Sep 16, 2025	SYSTEM	(\$5,950.00)	
					2	Sep 16, 2025	SYSTEM	\$5,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user davidm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Oct 1, 2025	SYSTEM	(\$5,950.00)	
					3	Oct 1, 2025	SYSTEM	\$5,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user davidm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total				\$0.00		
	0080 -	- Total						\$0.00	
	0110	MULCHING	Material		2	Sep 16, 2025	SYSTEM	(\$2,898.82)	
					2	Sep 16, 2025	SYSTEM	\$2,898.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user davidm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Oct 1, 2025	SYSTEM	(\$2,898.82)	
					3	Oct 1, 2025	SYSTEM	\$2,898.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user davidm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total				\$0.00		
	0110 -	Total						\$0.00	
	0120	SEEDING - COOL SEASON GRASSES	Material		2	Sep 16, 2025	SYSTEM	(\$3,672.32)	
					2	Sep 16, 2025	SYSTEM	\$3,672.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user davidm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Oct 1, 2025	SYSTEM	(\$3,672.32)	
					3	Oct 1, 2025	SYSTEM	\$3,672.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user davidm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total				\$0.00		
	0120 -	0120 - Total						\$0.00	
	0140	SILT FENCE	Material		3	Oct 1, 2025	SYSTEM	(\$2,566.00)	
				- Total				(\$2,566.00)	
			Material - Total					(\$2,566.00)	
	0140 - Total							(\$2,566.00)	
JSEM0081	- Total							(\$2,566.00)	
Overall - To	otal							(\$2,566.00)	

MoDOT

Contract Adjustments for Contract - 250516-H11

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 9 of 9