

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 3, 2025

Progress Estimate Number 8	Estimate Number Prime Contractor			•	Pay Period Start October Novem			Original Contract Amount Net Change Order Amount Current Contract Amount	\$7,962,023.8 \$0.0 \$7,962,023.8		
Approval Date									By User		
November 3, 2025			Generated a	nd Approv	ed (and sho	ould be considere	d Draf	t) at the Project Office Level by	turnep		
November 3, 2025			Reviewed and Ap	pproved (a	nd should b	e considered Dra	ıft) at t	the Resident Engineer Level by	stottt		
November 4, 2025				Review	ed and App	proved at the Cen	tral O	ffice Controllers Office Level by	ramses		
Original Completi	Il Completion Date Current Completion Date Actual Completion Date % of Current Contrac										
November 1, 2	026	Noven	nber 1, 2026					82.69%			
	Co	ontract Informa	tional Dates					Milestones			
Date Description	Original Co	mpletion Date	Current Comple	tion Date		No Milest	ones	Exist for Contract			
Acceptance Date											
Awarded Date	June 5, 202	5	June 5, 2025								
Letting Date	May 16, 202	25	May 16, 2025								
Notice to Proceed Date	July 7, 2025	5	July 7, 2025								
Work Began Date											

Contract Total Pa	ay For Estimate No. 8			
		This Estimate	Previous	To Date
250516-H5A				
	Total Posted Items Pay	\$2,084,684.24	\$4,499,042.02	\$6,583,726.26
	Gross Item Adjustments	\$15,890.94	\$107,024.48	\$122,915.42
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$4,606,066.50	\$6,706,641.68
Contract Total Pa	avable This Estimate:	\$2,100,575,18		

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount					
J9S3780	0040	2129900	MISC.SHOULDER GRADING 100F \$148.800 826									
	0070	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$70.850	230.480	\$16,329.51					
	0100	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$92.650	12,377.710	\$1,146,794.83					
	0120	4071005	TACK COAT	GAL	\$3.260	11,568	\$37,711.68					
	0180	6161005	CONSTRUCTION SIGNS	SQFT	\$6.000	1,092.500	\$6,555.00					
	0330	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$3.640	5,593.500	\$20,360.34					
	0340	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$5.200	451.600	\$2,348.32					
Project J9S	3780 - Tot	al					\$1,353,008.48					
JSE0102	0660	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$88.520	7,733.330	\$684,554.37					
	0670	4071005	TACK COAT	GAL	\$3.260	6,631	\$21,617.06					
	0680	6161005	CONSTRUCTION SIGNS	SQFT	\$6.000	838.500	\$5,031.00					
	0700	6181000	MOBILIZATION	LS	\$18,500.000	0.750	\$13,875.00					
	0740	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$10.100	653.300	\$6,598.33					
Project JSE	0102 - Tot	al					\$731,675.76					
Overall - To							\$2,084,684.24					

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	,	Annonite Extrat on Contract													
Line Item	ine Item Adjustments This Estimate														
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount							
J9S3780	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,216.14000	\$0.79	\$1,751.11							

Revision 10/17/2025 Page 1 of 15



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 3, 2025

•		Contract ID per Prime Contractor	250516-H5A Magruder Pavin		Pay Period Start Pay Period End	October 16, 2025 November 1, 2025	Original Contract An Net Change Order An Current Contract Am	mount	\$7,962,023.88 \$0.00 \$7,962,023.88
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustmen Type		Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3780		(SURFACE LEVELING)							
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	1,906.02000	\$0.79	\$1,506.06
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	1,928.53000	\$0.79	\$1,523.85
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	2,375.85000	\$0.79	\$1,877.30
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	2,892.43000	\$0.79	\$2,285.48
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	643.09000	\$0.79	\$508.14
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	415.65000	\$0.79	\$328.43
	0110	MISC.	Material				-9,043.45000	\$93.90	(\$849,179.96)
	0110	MISC.	Material		generated Mater Adjustment (000)	offsets the original syste ial Payment Estimate Ite 8) due to user turnep3 nent Estimate Exception nent Estimate.	em	\$93.90	\$849,179.96
	0580	CURB BLOCKOUT	Material				-612	\$107.00	(\$65,484.00)
	0580	CURB BLOCKOUT	Material		generated Mater Adjustment (000)	offsets the original syste ial Payment Estimate Ite 9) due to user turnep3 nent Estimate Exception nent Estimate.	em	\$107.00	\$65,484.00
	0590	CURB BLOCKOUT	Material				-695	\$101.00	(\$70,195.00)
	0590	CURB BLOCKOUT	Material		generated Mater Adjustment (001	offsets the original syste ial Payment Estimate Ite 0) due to user turnep3 nent Estimate Exception nent Estimate.	em	\$101.00	\$70,195.00
	0600	CURB BLOCKOUT	Material				-660	\$85.00	(\$56,100.00)
	0600	CURB BLOCKOUT	Material		generated Mater Adjustment (001	offsets the original systemate Items	em	\$85.00	\$56,100.00
	0610	CURB BLOCKOUT	Material				-318	\$105.00	(\$33,390.00)
	0610	CURB BLOCKOUT	Material		generated Mater Adjustment (001)	offsets the original syste ial Payment Estimate Ite 2) due to user turnep3 nent Estimate Exceptior ient Estimate.	em	\$105.00	\$33,390.00
JSE0102	0660	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	1,708.78000	\$0.79	\$1,350.21
	0660	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	855.29000	\$0.79	\$675.82
	0660	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item F Adjustment Type	Price Adjustment Index applied is FUEL	148.86000	\$0.79	\$117.62
	0660	BITUMINOUS PAVEMENT	Price		Reference Item F	Price Adjustment Index	1,975.76000	\$0.79	\$1,561.17

Revision 10/17/2025 Page 2 of 15



## Missouri Department of Transportation Contractor's Pay Estimate Summary

### Pay Estimate Created Date: November 3, 2025

Estimat	gress e Numb 8	Contract ID per Prime Contractor	250516-H5A Magruder Pavin		Pay Period Start Pay Period End	October 16, 2025 November 1, 2025	Original Contract An Net Change Order A Current Contract An	ange Order Amount		
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustmen Type		Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
JSE0102		MIXTURE PG64-22 (SURFACE LEVELING)			Adjustment Type	e applied is FUEL				
	0660	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price			Price Adjustment Inde: e applied is FUEL	x 1,635.43000	\$0.79	\$1,292.25	
	0660	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price			Price Adjustment Inde: e applied is FUEL	x 1,409.21000	\$0.79	\$1,113.50	
Total				1			,		\$15,890.94	

Revision 10/17/2025 Page 3 of 15



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Cont	ract Project Informa	ation
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9S3780	FAF 84-1(34)	Resurface	164	DUNKLIN	from Route 412 to Route 61		
JSE0102	FAS- S704 (093)	Resurface	Υ	DUNKLIN	from Route 412 to Route 164		
Totals b	y Job N	umbers					
J9S3780	Posted Item Pay Gross Item Adjustments Gross Item Pay				This Estimate \$1,353,008.48 \$9,780.37 \$1,362,788.85	Previous \$4,494,417.02 \$107,024.48 <b>\$4,601,441.50</b>	To Date \$5,847,425.50 \$116,804.85 \$5,964,230.35
	Liqui	tive centive dated Damage · Contract Adju		3	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
JSE0102		ed Item Pay s Item Adjustm		s Item Pay	This Estimate \$731,675.76 \$6,110.57 <b>\$737,786.33</b>	<b>Previous</b> \$4,625.00 \$0.00 <b>\$4,625.00</b>	<b>To Date</b> \$736,300.76 \$6,110.57 <b>\$742,411.33</b>
	Liqui	tive centive dated Damage · Contract Adju		5	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 5/29/2025 Page 4 of 15



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3780, Item 4029910, Project Item Line Number 0110, Material Set 4029910, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Awaiting submittal of Bituminous Base testing results.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3780, Item 7034600, Project Item Line Number 0580, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	PAL has been requested and awaiting submittal.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3780, Item 7034600, Project Item Line Number 0590, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	PAL has been requested and awaiting submittal.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3780, Item 7034600, Project Item Line Number 0600, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	PAL has been requested and awaiting submittal.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3780, Item 7034600, Project Item Line Number 0610, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	PAL has been requested and awaiting submittal.	turnep3	Overridden
Estimate Exception Type: Item Overrun: Contract 250516-H5A, Contract Project J9S3780, Project Item Line Number 0030, Contract Line Item Number 0030, Item 2071000, Minor Item.	Change Order to be written and submitted for approval.	turnep3	Acknowledged
Estimate Exception Type: Item Overrun: Contract 250516-H5A, Contract Project J9S3780, Project Item Line Number 0060, Contract Line Item Number 0060, Item 3049910, Minor Item.	Change Order to be written and submitted for approval.	turnep3	Acknowledged
Estimate Exception Type: Item Overrun: Contract 250516-H5A, Contract Project J9S3780, Project Item Line Number 0080, Contract Line Item Number 0080, Item 4011209, Minor Item.	Change Order to be written and submitted for approval.	turnep3	Acknowledged
Estimate Exception Type: Item Overrun: Contract 250516-H5A, Contract Project J9S3780, Project Item Line Number 0090, Contract Line Item Number 0090, Item 4013000, Minor Item.	Change Order to be written and submitted for approval.	turnep3	Acknowledged

Revision 5/29/2025 Page 5 of 15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
250516-	J9S3780	0001	0010	1081000	SIGNET DBE REPORTING	1.00	0.00	1.00	LS	0.00	\$1,000.00	\$0.00
H5A		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.30	\$75,970.00	\$22,791.00
		0001	0030	2071000	LINEAR GRADING CLASS 1	0.90	0.00	0.90	STA	1.80	\$890.89	\$1,603.60
		0001	0040	2129900	MISC.SHOULDER GRADING	2,790.00	0.00	2,790.00	100F	2,590.60	\$148.80	\$385,481.28
		0001	0050	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	225.00	0.00	225.00	SQYD	0.00	\$48.65	\$0.00
		0001	0060	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	661.50	0.00	661.50	TONS	1,586.09	\$70.85	\$112,374.48
		0001	0070	3105002	GRAVEL (A) OR CRUSHED STONE (B)	604.00	0.00	604.00	TONS	230.48	\$70.85	\$16,329.51
		0001	0800	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	2,971.40	0.00	2,971.40	TONS	3,076.14	\$95.75	\$294,540.40
		0001	0090	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	103.10	0.00	103.10	TONS	124.14	\$254.28	\$31,566.32
		0001	0100	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	26,971.50	0.00	26,971.50	TONS	26,803.00	\$92.65	\$2,483,297.95
		0001	0110	4029910	MISC.Optional Shoulder Base	15,850.10	0.00	15,850.10	TONS	15,715.22	\$93.90	\$1,475,659.16
		0001	0120	4071005	TACK COAT	36,103.00	0.00	36,103.00	GAL	30,009.00	\$3.26	\$97,829.34
		0001	0130	4091048	EMULSIFIED ASPHALT, SEAL COAT	2,570.00	0.00	2,570.00	GAL	2,570.00	\$2.85	\$7,324.50
		0001	0140	4094011	SEAL COAT AGGREGATE, GRADE B1	8,565.00	0.00	8,565.00	SQYD	8,565.00	\$10.00	\$85,650.00
		0001	0150	6083003	3 IN. CONCRETE MEDIAN STRIP	24.90	0.00	24.90	SQYD	0.00	\$461.82	\$0.00
		0001	0160	6122040	WORK ZONE CRASH CUSHION (NARROW)	8.00	0.00	8.00	EA	2.00	\$7,950.00	\$15,900.00
		0001	0170	6122041	WORK ZONE CRASH CUSHION (NARROW) (RELOCATION)	8.00	0.00	8.00	EA	8.00	\$2,200.00	\$17,600.00
		0001	0180	6161005	CONSTRUCTION SIGNS	2,817.00	0.00	2,817.00	SQFT	1,484.50	\$6.00	\$8,907.00
		0001	0190	6161025	CHANNELIZER (TRIM-LINE)	250.00	0.00	250.00	EA	38.00	\$22.00	\$836.00
		0001	0200	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	4.00	0.00	4.00	EA	4.00	\$3,500.00	\$14,000.00
		0001	0210	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$17,400.00	\$17,400.00
		0001	0220	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$368,500.00	\$368,500.00
		0001	0230	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0240	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, $ 6  \text{IN}. $ WHITE	147.00	0.00	147.00	LF	0.00	\$6.00	\$0.00
		0001	0250	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	150.00	0.00	150.00	LF	0.00	\$25.00	\$0.00
		0001	0260	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.00
		0001	0270	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	2,744.00	0.00	2,744.00	LF	2,744.00	\$3.00	\$8,232.00
		0001	0280	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	8,000.00	0.00	8,000.00	LF	1,426.00	\$3.00	\$4,278.00
		0001	0290	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	88.00	0.00	88.00	LF	44.00	\$10.00	\$440.00
		0001	0300	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	300,529.00	0.00	300,529.00	LF	0.00	\$0.14	\$0.00
		0001	0310	6206001C	4 III. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	64,597.00	0.00	64,597.00	LF	0.00	\$0.14	\$0.00
		0001	0320	6207001	PAVEMENT MARKING REMOVAL	10,832.00	0.00	10,832.00	LF	0.00	\$1.50	\$0.00
		0001	0330	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	27,352.00	0.00	27,352.00	SQYD	25,203.70	\$3.64	\$91,741.47
		0001	0340	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	8,630.00	0.00	8,630.00	SQYD	5,857.40	\$5.20	\$30,458.48
		0001	0350	6261000A		2,246.80	0.00	2,246.80	STA	0.00	\$10.34	\$0.00
		0001	0360	8025006 8051000A	MULCHING SEEDING - COOL SEASON GRASSES	105.80 70.50	0.00	105.80 70.50	ACRE	0.00	\$1,450.00	\$0.00 \$0.00
		0001	0370								\$2,250.00	\$7,848.00
		0001		8061005	ROCK DITCH CHECK  ALTERNATE DITCH CHECK	2,450.00	0.00	2,450.00	LF	654.00	\$12.00	
		0001	0390	8061006		1,480.00	0.00	1,480.00	LF	744.00	\$9.50	\$7,068.00
		0001	0400	8061016	SEDIMENT REMOVAL TEMPORARY SEEDING	360.00	0.00	360.00	CUYD	0.00	\$32.94	\$0.00
		0001	0410	8061017		35.30	0.00	35.30	ACRE	0.00	\$850.00	\$0.00
		0010	0420	8061019	SILT FENCE	3,225.00	0.00	3,225.00	LF	0.00	\$2.90	\$0.00
		0010	0430	6061060	MGS GUARDRAIL	1,745.00	0.00	1,745.00	LF	0.00	\$24.00	\$0.00
		0010	0440	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	23.00	0.00	23.00	EA	2.00	\$3,900.00	\$7,800.00
		0010	0450	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	31.00	0.00	31.00	EA	2.00	\$3,400.00	\$6,800.00
		0040	0460	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	0.00	\$28,000.00	\$0.00
		0040	0470	9031210	STRUCTURAL STEEL POSTS  BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	1,380.00 9.00	0.00	1,380.00	LB EA	0.00	\$8.00 \$400.00	\$0.00 \$0.00
		0040	0490	9031260	WOOD POST, 4 IN. BY 4 IN.	112.00	0.00	112.00	LF	0.00	\$14.00	\$0.00
		0040	0500		2 IN. PSST POST - 12 GA.	1,844.00	0.00	1,844.00	LF	0.00	\$22.00	\$0.00
		0040	0510	9031270A		174.00	0.00	174.00	EA	0.00	\$150.00	\$0.00
		0040	0520		2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	21.00	0.00	21.00	EA	0.00	\$200.00	\$0.00
			0020	0001212A	2.20 1 001 1 001 INOLINI (01 1.) - 12 0A.	21.00	0.00	∠1.00	EM	0.00	Ψ200.00	φυ.υυ

Revision 5/29/2025 Page 6 of 15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ract	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)	
16-	J9S3780	0040	0530	9031280	2.5 IN. PSST POST - 12 GA.	1,091.00	0.00	1,091.00	LF	0.00	\$24.00	\$0.0	
		0040	0540	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	93.00	0.00	93.00	EA	0.00	\$175.00	\$0.0	
		0040	0550	9035004A	SH-FLAT SHEET	1,603.00	0.00	1,603.00	SQFT	0.00	\$20.00	\$0.0	
		0040	0560	9035011A	ST-STRUCTURAL	267.00	0.00	267.00	SQFT	0.00	\$24.00	\$0.0	
		0040	0570	9035069A	SHF-FLAT SHEET FLUORESCENT	511.00	0.00	511.00	SQFT	0.00	\$24.00	\$0.0	
		0070	0580	7034600	CURB BLOCKOUT	612.00	0.00	612.00	LF	612.00	\$107.00	\$65,484.0	
		0071	0590	7034600	CURB BLOCKOUT	695.00	0.00	695.00	LF	695.00	\$101.00	\$70,195.0	
		0072	0600	7034600	CURB BLOCKOUT	1,320.00	0.00	1,320.00	LF	660.00	\$85.00	\$56,100.0	
		0073	0610	7034600	CURB BLOCKOUT	636.00	0.00	636.00	LF	318.00	\$105.00	\$33,390.0	
		0074	0620	7133000	BRIDGE GUARDRAIL (W-BEAM)	63.00	0.00	63.00	LF	0.00	\$250.00	\$0.0	
		0075	0630	7133000	BRIDGE GUARDRAIL (W-BEAM)	88.00	0.00	88.00	LF	0.00	\$250.00	\$0.0	
	Project J9S3780 - Total Value Posted to Date as of Report Generated Date												
	JSE0102	0001	0640	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	1,571.00	0.00	1,571.00	TONS	0.00	\$52.57	\$0.0	
		0001	0650	3105002	GRAVEL (A) OR CRUSHED STONE (B)	26.00	0.00	26.00	TONS	0.00	\$52.57	\$0.0	
		0001	0660	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	7,794.30	0.00	7,794.30	TONS	7,733.33	\$88.52	\$684,554.3	
		0001	0670	4071005	TACK COAT	10,107.00	0.00	10,107.00	GAL	6,631.00	\$3.26	\$21,617.0	
		0001	0680	6161005	CONSTRUCTION SIGNS	1,346.00	0.00	1,346.00	SQFT	838.50	\$6.00	\$5,031.0	
		0001	0690	6161025	CHANNELIZER (TRIM-LINE)	50.00	0.00	50.00	EA	0.00	\$20.00	\$0.0	
		0001	0700	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$18,500.00	\$18,500.0	
		0001	0710	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	23.00	0.00	23.00	LF	0.00	\$25.00	\$0.0	
		0001	0720	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	96,090.00	0.00	96,090.00	LF	0.00	\$0.15	\$0.0	
		0001	0730	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	18,407.00	0.00	18,407.00	LF	0.00	\$0.14	\$0.0	
		0001	0740	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,081.00	0.00	1,081.00	SQYD	653.30	\$10.10	\$6,598.3	
	Project JS	SE0102 - To	tal Value	Posted to D	Date as of Report Generated Date							\$736,300.7	
	EA Overel	I Total Va	luo Booto	d to Data as	of Report Generated Date							\$6,583,726.2	

Revision 5/29/2025 Page 7 of 15



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3780

Project:	J9S3780	J										
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Comments Distance
0040	2129900	MISC. SUBGRADING AND SHOULDERING	10/20/25	11/3/25	1	205.50	100F	WB shoulders, also quantities from previous days	9.850 Route 164	LOC	12.030 Route 164	LOC
			10/21/25	11/3/25	1	105.70	100F	Finish grade	9.850 Route 164	ROC	12.942 Route 164	RLC
			10/22/25	11/3/25	1	50.60	100F	Finish grade	12.942 Route 164	RLC	13.900 Route 164	RLC
			10/23/25	11/3/25	1	15.80	100F	Finish grade	13.900 Route 164	RLC	14.200 Route 164	RLC
			10/24/25	11/3/25	1	63.40	100F	Finish grade	24.100 Route 164	RLC	25.300 Route 164	RLC
			10/30/25	11/3/25	1	385.00	100F	Finish grade of aggregate edge treatment	14.200 Route 164	RLC	21.500 Route 164	RLC
0070	3105002	GRAVEL (A) OR CRUSHED STONE (B)	10/17/25	11/3/25	1	66.00	TONS	Rock entrances and driveways	7.000 Route 164	RLC	10.800 Route 164	RLC
			10/27/25	11/3/25	1	116.94	TONS	Rock entrances in and near Cardwell	0.006 Route 164	RLC	1.800 Route 164	RLC
			10/28/25	11/3/25	1	47.54	TONS	Rock entrances and side roads	1.800 Route 164	RLC	3.300 Route 164	RLC
0100	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	10/16/25	11/3/25	1	2,216.14	TONS	WB Lane	13.763 Route 164	LOC	18.007 Route 164	LOC
			10/17/25	11/3/25	1	1,906.02	TONS	EB Lane: LM 19.348 to LM 21.587 WB Lane: LM 18.007 to LM 19.983	18.007 Route 164	LOC	21.587 Route 164	ROC
			10/20/25	11/3/25	1	1,928.53	TONS	WB lane: LM 19.983 to LM 21.587, then LM 28.785 to LM 26.439	19.983 Route 164	LOC	28.785 Route 164	LOC
			10/21/25	11/3/25	1	2,375.85	TONS	WB lane	26.439 Route 164	LOC	21.663 Route 164	LOC
			10/22/25	11/3/25	1	2,892.43	TONS	EB lane	28.785 Route 164	ROC	22.679 Route 164	ROC
			10/23/25	11/3/25	1	643.09	TONS	EB lane: LM 22.679 to LM 21.587 WB lane: LM 21.663 to LM 21.587	22.679 Route 164	RLC	21.587 Route 164	RLC
			10/27/25	11/3/25	1	415.65	TONS	EB and WB lanes in Steele	28.785 Route 164	RLC	29.077 Route 164	RLC
0120	4071005	TACK COAT	10/16/25	11/3/25	1	2,178.00	GAL	2,250 GAL temperature adjusted to 2,178 GAL	13.763 Route 164	LOC	18.007 Route 164	LOC
			10/17/25	11/3/25	1	1,742.00	GAL	1,800 GAL temperature adjusted to 1,742 GAL	18.007 Route 164	LOC	21.587 Route 164	ROC
			10/20/25	11/3/25	1	1,791.00	GAL	1,850 GAL temperature adjusted to 1,791 GAL	19.983 Route 164	LOC	28.785 Route 164	LOC
			10/21/25	11/3/25	1	2,227.00	GAL	2,300 GAL temperature adjusted to 2,227 GAL	26.439 Route 164	LOC	21.663 Route 164	LOC
			10/22/25	11/3/25	1	2,856.00	GAL	2,950 GAL temperature adjusted to 2,856 GAL	28.875 Route 164	ROC	22.679 Route 164	ROC
			10/23/25	11/3/25	1	484.00	GAL	500 GAL temperature adjusted to 484 GAL	22.679 Route 164	RLC	21.587 Route 164	RLC
			10/27/25	11/3/25	1	290.00	GAL	300 GAL temperature adjusted to 290 GAL	28.785 Route 164	RLC	29.077 Route 164	RLC
0180	6161005	CONSTRUCTION SIGNS	10/23/25	11/3/25	1	1,092.50	SQFT	No Centerline x 36: 575 sqtt Uneven Lanes x 6: 96 sqtf Road Work Ahead x 6: 96 sqtf Road Work Ahead x 6: 96 sqtf One Lane Road Ahead x 6: 06 sqtf Flagger Symbol x 6: 96 sqtf Pilot Car Follow Me x 2: 9 sqtf Pilot Car Follow Me x 2: 9 sqtf Pilot Car in Use Wait and Follow x 10: 87.5 sqtf Pilot Car in Use Wait and Follow x 24: 36 sqtf Total: 1,092.5 sqtf	0.006 Route 164	RLC	29.077 Route 164	RLC
0330	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	10/27/25	11/3/25	1	5,593.50	SQYD	Mill/Fill through Steele	28.785 Route 164	RLC	29.077 route 164	RLC
0340	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	10/16/25	11/3/25	1	37.30	SQYD	Route N depth transition	14.192 Route 164	LOC		
			10/20/25	11/3/25	1	42.00	SQYD	Side road depth transition	27.246 Route 164	LOC		
			10/21/25	11/3/25	1	68.40	SQYD	Side roads and entrances	25.503 Route 164	RLC	24.118 Route 164	RLC
			10/22/25	11/3/25	1	78.60	SQYD	Side roads and entrances on EB side	28.476 Route 164	ROC	25.358 Route 164	ROC
			10/23/25	11/3/25	1	103.10	SQYD	Route NN depth transitions		RLC	-	
			10/27/25	11/3/25	1	122.20	SQYD	Depth transitions at both ends of Steele and RR tracks.	28.785 Route 164	RLC	29.077 Roue 164	RLC

### Project: JSE0102

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.		Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0660	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	10/23/25	11/3/25	1	1,708.78	TONS	NB lane	9.111 Route Y	LOC	5.099 Route Y	LOC	
			10/24/25	11/3/25	1	855.29	TONS	NB Lane	5.099 Route	LOC	3.062 Route	LOC	

Revision 6/5/2025 Page 8 of 15



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line	Item	Description	DWR	DWR	Posting	Quantity	Units	Location	From	Offset/	To	Offset/	Comments
Number	Code		Date	Approval Date	Sequence No.	Posted			Station/ Log	Distance	Station/ Log	Distance	
									Mile		Mile		
0660	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR							Υ		Υ		
			10/27/25	11/3/25	1	148.86	TONS	NB Lane	3.062 Route Y	LOC	2.777 Route Y	LOC	
			10/28/25	11/3/25	1	1,975.76	TONS	SB Lane	9.111 Route Y	ROC	4.466 Route Y	ROC	
			10/30/25	11/3/25	1	1,635.43	TONS	SB Lane: LM 4.466 to LM 2.773 NB Lane: LM 2.777 to LM 0.498	4.466 Route Y	ROC	0.498 Route Y	LOC	
			10/31/25	11/3/25	1	1,409.21	TONS	SB Lane: LM 2.773 to LM 0.021 NB Lane: LM 0.498 to LM 0.021	2.773 Route Y	ROC	0.021 Route Y	RLC	
0670	4071005	TACK COAT	10/23/25	11/3/25	1	1,568.00	GAL	1,620 GAL temperature adjusted to 1,568 GAL	9.111 Route Y	LOC	5.099 Route Y	LOC	
			10/24/25	11/3/25	1	920.00	GAL	950 Gal temperature adjusted to 920 GAL	5.099 Route Y	LOC	3.062 Route Y	LOC	
			10/27/25	11/3/25	1	77.00	GAL	80 GAL temperature adjusted to 77 GAL	3.062 Route Y	LOC	2.777 Route Y	LOC	
			10/28/25	11/3/25	1	1,355.00	GAL	1,400 GAL temperature adjusted to 1,355 GAL	9.111 Route Y	ROC	4.466 Route Y	ROC	
			10/30/25	11/3/25	1	1,404.00	GAL	1,450 GAL temperature adjusted to 1,404 GAL	4.466 Route Y	ROC	0.498 Route Y	LOC	
			10/31/25	11/3/25	1	1,307.00	GAL	1,350 GAL temperature adjusted to 1,307 GAL	2.773 Route Y	ROC	0.021 Route Y	RLC	
0680	6161005	CONSTRUCTION SIGNS	10/23/25	11/3/25	1	838.50	SQFT	Work Zone No Phone Zone x 2: 24 sqft Road Work Next 9 mi x 2: 20 sqft End Road Work x 2: 16 sqft End Road Work x 2: 16 sqft Plict Car-Follow Me: 4.5 sqft Plict Car in Use Wait and Follow x 10: 150 sqft Plict Car in Use Wait and Follow x 10: 150 sqft Plict Car in Use Wait and Follow x 10: 150 sqft Plocar in Use Wait and Follow x 10: 150 sqft One Lane Road Ahead x 6: 96 sqft Flagger Symbot x 6: 96 sqft No Centerline x 11: 176 sqft Uneven lanes x 6: 96 sqft Total: 838.5 sqft	0.000 Route Y	RLC	9.111 Route Y	RLC	
0700	6181000	MOBILIZATION	10/31/25	11/3/25	1	0.25	LS	10% Project Completion					
				11/3/25	2	0.25	LS	20% Project Completion					
				11/3/25	3	0.25	LS	30% Project Completion					
0740	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	10/23/25	11/3/25	1	33.00	SQYD	Side road and entrance depth transitions	8.347 Route Y	LOC	5.073 Route Y	LOC	
			10/24/25	11/3/25	1	130.20	SQYD	Side roads and entrances	3.837 Route Y	RLC	1.792 Route Y	RLC	
			10/27/25	11/3/25	1	339.00	SQYD	Route P and Route 412 tie ins					
			10/28/25	11/3/25	1	7.30	SQYD	Side road transition	5.978 Route Y	ROC			
			10/30/25	11/3/25	1	143.80	SQYD	Side roads and entrances depth transitions	1.657 Route Y	RLC	0.168 Route Y	RLC	

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 9 of 15



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9S3780	0030	LINEAR GRADING	Overrun	Overrun	6	Oct 1, 2025	SYSTEM	(\$801.80)					
		CLASS 1		Overrun - T	otal			(\$801.80)					
			Overrun - To	tal				(\$801.80)					
	0030 -	Total						(\$801.80)					
	0060	MISC. AGGREGATE FOR BASE	Overrun	Overrun	7	Oct 16, 2025	SYSTEM	(\$65,507.20)					
				Overrun - T	otal			(\$65,507.20)					
			Overrun - To	tal				(\$65,507.20)					
	0060 -							(\$65,507.20)					
	0800	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Overrun	Overrun	7	Oct 16, 2025	SYSTEM	(\$10,111.62)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				Overrun - T	otal			(\$10,111.62)					
			Overrun - To	tal				(\$10,111.62)					
			Price FUEL		7	Oct 16, 2025	SYSTEM	\$2,430.65	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$2,430.65					
			Price FUEL -	Total				\$2,430.65					
	0080 -	Total						(\$7,680.97)					
	0090	BITUMINOUS PAVEMENT MIXTURE	Overrun	Overrun	6	Oct 1, 2025	SYSTEM	(\$5,370.31)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
		PG64-22 (BAS		Overrun - T	otal			(\$5,370.31)					
			Overrun - To	tal				(\$5,370.31)					
			Price FUEL		6	Oct 1, 2025	SYSTEM	\$119.52	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$119.52					
			Price FUEL -	Total				\$119.52					
	0090 -	Total						(\$5,250.79)					
	0100	BITUMINOUS PAVEMENT MIXTURE	Price FUEL		6	Oct 1, 2025	SYSTEM	\$1,334.68	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
		PG64-22 (SUR			7	Oct 16, 2025	SYSTEM	\$10,302.95	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
					8	Nov 3, 2025	SYSTEM	\$9,780.37	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$21,418.00					
			Price FUEL -	Total				\$21,418.00					
								\$21,418.00					
	0110	- Total  MISC. BITUMINOUS PAVEMENT (SURF. LEVEL)	BITUMINOUS PAVEMENT	Material		6	Oct 1, 2025	SYSTEM	(\$849,179.96)				
					6	Oct 1, 2025	SYSTEM	\$849,179.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					7	Oct 16, 2025	SYSTEM	(\$849,179.96)					
					7	Oct 16, 2025	SYSTEM	\$849,179.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					8	Nov 3, 2025	SYSTEM	(\$849,179.96)					
					8	Nov 3, 2025	SYSTEM	\$849,179.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
				- Total				\$0.00					
			Material - To	tal				\$0.00					
			Other Item Adjustment	FUEL	5	Sep 16, 2025	turnep3	\$6,423.58	Fuel Index Price Adjustment: \$6,423.58				
					6	Oct 1, 2025	turnep3	\$8,707.03	Fuel Index Price Adjustment: \$8,707.03				



2025   Estimate Item Adjustment (0006) due to user turner   Estimate Exception 2 on the current Payment Estim	80 0110		Туре	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
SURF. LEVEL   Other Item Adjustment - Total   \$15,130.61		BITUMINOUS		FUEL - Tota	ı			\$15,130.61					
National			Other Item A	djustment - T	otal			\$15,130.61					
2025	0110	- Total						\$15,130.61					
6	0140	AGGREGATE,	Material		6		SYSTEM	(\$85,650.00)					
2025		GRADE BI			6		SYSTEM	\$85,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
2025   Estimate Item Adjustment (0016) due to user turner   Estimate Exception 2 on the current Payment Estim					7		SYSTEM	(\$85,650.00)					
Material - Total   \$0.00					7		SYSTEM	\$85,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
Solid   Soli				- Total				\$0.00					
D270   TEMPORARY   REMOVABLE   MARKING TAPE   4 IN.,			Material - Tot	tal				\$0.00	Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment				
REMOVABLE MARKING TAPE 4 IN.,    Solution	0140	- Total						\$0.00					
A III.,  Aug 18, 2025  SYSTEM S6,786.00  This adjustment offsets the original system-generate Estimate Exception 1 on the current Payment Estim  Total  S0.00  O270 - Total  O280 TEMPORARY REMOVABLE MARKING TAPE  MARKING TAPE  Aug 18, 2025  Aug 18, 2025  Aug 18, 2025  This adjustment offsets the original system-generate Estimate Exception 1 on the current Payment Estim  (\$4,278.00)  This adjustment offsets the original system-generate Estimate Item Adjustment (0002) due to user turner Estimate Item Adjustment (0002) due to user turner Estimate Exception 2 on the current Payment Estim  Total  S0.00  Material - Total  S0.00	0270	REMOVABLE	Material		3		SYSTEM	(\$6,786.00)					
Material - Total   \$0.00					3		SYSTEM	\$6,786.00	Estimate Item Adjustment (0001) due to user turnep3 overridding Payment				
O270 - Total   \$0.00				- Total				\$0.00					
O280 TEMPORARY REMOVABLE MARKING TAPE  Material  3 Aug 18, 2025  3 Aug 18, 2025  3 Aug 18, 2025  3 Figure 18, 2025  3 Aug 18, 2025  3 Figure 2025  3 Aug 18, 2025  5 Figure 2025  5 Figure 2025  5 Figure 2025  6 Figure			Material - Tot	tal				\$0.00	Estimate Exception 1 on the current Payment Estimate.				
REMOVABLE MARKING TAPE  3 Aug 18, 2025  3 Aug 18, 2025  This adjustment offsets the original system-generate Estimate Item Adjustment (0002) due to user turner Estimate Exception 2 on the current Payment Estimate Total  Naterial - Total  \$0.00	0270	- Total						\$0.00					
Aug 18, 2025 SYSTEM \$4,278.00 This adjustment offsets the original system-generate Estimate Item Adjustment (0002) due to user turner Estimate Exception 2 on the current Payment Estimate Total \$0.00  Material - Total \$0.00	0280	REMOVABLE	Material		3		SYSTEM	(\$4,278.00)					
Material - Total \$0.00					3		SYSTEM	\$4,278.00	Estimate Item Adjustment (0002) due to user turnep3 overridding Payment				
				- Total				\$0.00					
0280 - Total \$0.00			Material - Tot	tal				\$0.00					
	0280	- Total						\$0.00					
0290 TEMPORARY Material 3 Aug 18, 2025 (\$220.00) REMOVABLE MARKING TAPE.	0290	REMOVABLE	Material		3		SYSTEM	(\$220.00)					
24 IN. 3 Aug 18, SYSTEM \$220.00 This adjustment offsets the original system-generate Estimate Item Adjustment (0003) due to user turner					3		SYSTEM	\$220.00	Estimate Item Adjustment (0003) due to user turnep3 overridding Payment				
- Total \$0.00				- Total				\$0.00					
Material - Total \$0.00			Material - Tot	tal				\$0.00					
0290 - Total \$0.00	0290	- Total						\$0.00					
0430 MGS Construction 4 Sep 2, SYSTEM \$24,412.55 Payment Estimate Item Adjustment generated Stoc GUARDRAIL Stockpile STMI	0430		Stockpile		4		SYSTEM	\$24,412.55	Payment Estimate Item Adjustment generated Stockpile Transaction				
- Total \$24,412.55			STIVII	- Total				\$24,412.55					
Construction Stockpile STMI - Total \$24,412.55			Construction	Stockpile S1	ΓMI - Total			\$24,412.55					
0430 - Total \$24,412.55	0430	- Total						\$24,412.55					
APP TRANS Stockpile 2025	0440				4		SYSTEM	(\$4,480.00)	Payment Estimate Item Adjustment generated Stockpile Transaction				
		CURB)		- Total				(\$4,480.00)					
			Construction	Stockpile - T	otal			(\$4,480.00)					
CURB) - Total (\$4,480.00)			Construction Stockpile STMI		4	Sep 2, 2025	SYSTEM	\$51,520.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
CURB)  - Total (\$4,480.00)  Construction Stockpile - Total (\$4,480.00)  Construction Stockpile 4 Sep 2, SYSTEM \$51,520.00 Payment Estimate Item Adjustment generated Stockpile 2025			511111	- Total				\$51,520.00					
CURB)  - Total (\$4,480.00)  Construction Stockpile - Total (\$4,480.00)  Construction Stockpile STMI			Construction	Stockpile ST	MI - Total			\$51,520.00					
CURB)  - Total (\$4,480.00)  Construction Stockpile - Total (\$4,480.00)  Construction Stockpile STMI  - Total (\$4,480.00)  Stockpile STMI  - Total \$51,520.00  Stockpile STMI  - Total \$51,520.00		Total						\$47,040.00					
CURB)  - Total (\$4,480.00)  Construction Stockpile - Total (\$4,480.00)  Construction Stockpile STMI  - Total \$51,520.00  Construction Stockpile STMI - Total \$51,520.00	0440	- IOIAI											
CURB)  - Total (\$4,480.00)  Construction Stockpile - Total (\$4,480.00)  Construction Stockpile STMI - Total \$51,520.00  Construction Stockpile STMI - Total \$51,520.00  Construction Stockpile STMI - Total \$51,520.00  \$47,040.00		TYPE A CRASHWORTHY			4		SYSTEM	(\$1,193.55)	Payment Estimate Item Adjustment generated Stockpile Transaction				



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
3780	0450	TYPE A	Construction	Stockpile - 1	Γotal			(\$1,193.55)					
		CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		4	Sep 2, 2025	SYSTEM	\$18,500.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
			STMI		5	Sep 16, 2025	SYSTEM	\$37,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total				\$55,500.00					
			Construction	Stockpile S	TMI - Total			\$55,500.00					
	0450 -	Total						\$54,306.45					
	0460	TYPE C CRASHWORTHY	Construction Stockpile		4	Sep 2, 2025	SYSTEM	\$19,393.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
		END TERMINAL (MASH)	STMI	- Total				\$19,393.00					
		(**** *****)	Construction	Stockpile S	TMI - Total			\$19,393.00					
	0460 -	Total						\$19,393.00					
	0580	CURB	Material		4	Sep 2,	SYSTEM						
	0360	BLOCKOUT	iviateriai			2025		(\$32,742.00)					
					4	Sep 2, 2025	SYSTEM	\$32,742.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					5	Sep 16, 2025	SYSTEM	(\$65,484.00)					
					5	Sep 16, 2025	SYSTEM	\$65,484.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					6	Oct 1, 2025	SYSTEM	(\$65,484.00)					
					6	Oct 1, 2025	SYSTEM	\$65,484.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					7	Oct 16, 2025	SYSTEM	(\$65,484.00)					
					7	Oct 16, 2025	SYSTEM	\$65,484.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					8	Nov 3, 2025	SYSTEM	(\$65,484.00)					
					8	Nov 3, 2025	SYSTEM	\$65,484.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
				- Total				\$0.00					
			Material - To					\$0.00					
	0580 -	Total						\$0.00					
	0590	CURB BLOCKOUT	Material		4	Sep 2, 2025	SYSTEM	(\$35,097.50)					
					4	Sep 2, 2025	SYSTEM	\$35,097.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					5	Sep 16, 2025	SYSTEM	(\$70,195.00)					
					5	Sep 16, 2025	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					6	Oct 1, 2025	SYSTEM	(\$70,195.00)					
					6	Oct 1, 2025	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					7	Oct 16, 2025	SYSTEM	(\$70,195.00)					
					7	Oct 16,	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment				
					7	2025		, ,,	Estimate Item Adjustment (0018) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.				



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
3780	0590	CURB BLOCKOUT	Material		8	Nov 3, 2025	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0590 -	- Total						\$0.00					
	0600	CURB BLOCKOUT	Material		4	Sep 2, 2025	SYSTEM	(\$56,100.00)					
					4	Sep 2, 2025	SYSTEM	\$56,100.00	This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0011) due to user turnep3 overridding Pa Estimate Exception 9 on the current Payment Estimate.				
					5	Sep 16, 2025	SYSTEM	(\$56,100.00)					
					5	Sep 16, 2025	SYSTEM	\$56,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					6	Oct 1, 2025	SYSTEM	(\$56,100.00)					
					6	Oct 1, 2025	SYSTEM	\$56,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Paymen Estimate Exception 5 on the current Payment Estimate.				
					7	Oct 16, 2025	SYSTEM	(\$56,100.00)					
						7	Oct 16, 2025	SYSTEM	\$56,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user turnep3 overridding Paymen Estimate Exception 5 on the current Payment Estimate.			
					8	Nov 3, 2025	SYSTEM	(\$56,100.00)					
					8	Nov 3, 2025	SYSTEM	\$56,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Paymen Estimate Exception 4 on the current Payment Estimate.				
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0600 -	- Total						\$0.00					
	0610	CURB BLOCKOUT	Material		4	Sep 2, 2025	SYSTEM	(\$33,390.00)					
					4	Cam 1							
						Sep 2, 2025	SYSTEM	\$33,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.				
					5		SYSTEM	\$33,390.00 (\$33,390.00)	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen				
						2025 Sep 16,			Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment				
					5	2025 Sep 16, 2025 Sep 16,	SYSTEM	(\$33,390.00)	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment				
					5	2025 Sep 16, 2025 Sep 16, 2025 Oct 1,	SYSTEM SYSTEM	(\$33,390.00) \$33,390.00	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Paymen Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment				
					5 5	2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1,	SYSTEM SYSTEM SYSTEM	(\$33,390.00) \$33,390.00 (\$33,390.00)	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Paymen Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment				
					5 5 6 6	2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,390.00) \$33,390.00 (\$33,390.00) \$33,390.00	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymer Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Paymer Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Paymer Estimate Item Adjustment (0010) due to user turnep3 overridding Paymer Estimate Exception 6 on the current Payment Estimate.				
					5 5 6 6 7 7	2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,390.00) \$33,390.00 (\$33,390.00) \$33,390.00	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Paymen Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user turnep3 overridding Payment Estimate Item Adjustment (0020) due to user turnep3 overridding Payment Estimate Item Adjustment (0020) due to user turnep3 overridding Payment				
					5 5 6 6 7 7	2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,390.00) \$33,390.00 (\$33,390.00) \$33,390.00 (\$33,390.00)	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Paymen Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user turnep3 overridding Payment Estimate Item Adjustment (0020) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
				- Total	5 5 6 6 7 7	2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,390.00) \$33,390.00 (\$33,390.00) \$33,390.00 (\$33,390.00) (\$33,390.00)	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.				
			Material - To		5 5 6 6 7 7	2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,390.00) \$33,390.00 (\$33,390.00) \$33,390.00 (\$33,390.00) \$33,390.00 (\$33,390.00)	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Paymen Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user turnep3 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.				
	0610 -	-Total	Material - To		5 5 6 6 7 7	2025 Sep 16, 2025 Sep 16, 2025 Oct 1, 2025 Oct 1, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$33,390.00) \$33,390.00 (\$33,390.00) \$33,390.00 (\$33,390.00) \$33,390.00 \$33,390.00	Estimate Item Adjustment (0012) due to user turnep3 overridding Paymen Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Paymen Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user turnep3 overridding Paymen Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.				

Nov 5, 2025



## Line Item Adjustments by Estimate

			1							
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9S3780	0620	BEAM)	STMI	- Total				\$5,985.00		
			Construction	Stockpile S	ΓΜΙ - Total			\$5,985.00		
	0620 - Total							\$5,985.00		
	0630	BRIDGE GUARDRAIL (W- BEAM)	Construction Stockpile		5	Sep 16, 2025	SYSTEM	\$8,360.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$8,360.00		
			Construction	Stockpile S	ΓMI - Total			\$8,360.00		
	0630 -	- Total						\$8,360.00		
J9S3780 -	Total							\$116,804.85		
JSE0102	0660	BITUMINOUS PAVEMENT	PAVEMENT	Price FUEL		8	Nov 3, 2025	SYSTEM	\$6,110.57	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		MIXTURE PG64-22 (SUR		- Total				\$6,110.57		
			Price FUEL -	Total				\$6,110.57		
	0660 - Total							\$6,110.57		
JSE0102	- Total							\$6,110.57		
Overall -	Total							\$122,915.42		

## MoDOT

## Contract Adjustments for Contract - 250516-H5A

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 15 of 15